Model	: S650	Description	: S650 STS CORN COMBINE	Model : 2015 Year
Latest Delivery Date	: 02 May 2017	Last Reported Registration Measurement	: 400	
Machine Build Date	: 13 Mar 2015	Last Reported Claim Measurement	: 604	
Approximate Cumulative Rental Days*	: 0	JDLink Expiration Date	: 07 Sep 2020	
Machine status 1	: Used Machine			
*See John Deere Warranty System for accu	mulated rental days/detailed rental history			

Warranty Coverage

Days Remaining (may be estimate) Expiration Date Coverage term Warranty type 🖃 Hours Limit **Deductible Amount** N/A Default Warranty 120m/0h 31 Aug 2015 0 N/A Basic Warranty 12m/0h 01 Sep 2016 0 Engine Warranty 24m/2000h N/A 01 Sep 2017 0 2000 Extended Warranty 36m/1500h 01 Sep 2018 1500 USD-500.0 0 (Powertrain) N/A 467 3000 Emissions Warranty 60m/3000h 01 Sep 2020

Show / Hide

Component Serial Numbers

Component 🖃	Serial Number 🖃
GEARBOX, SINGLE SPEED	CEGBSML237444
TRANSMISSION	CE3SBAD102911
REVERSER	CEGBFHI102923
FILTER OXIDATION DOC	REXD162145031
MODULE, TRANSMISSION	CEGBLAF152391
GEAR DRIVE	CEVAAAE204576
ENGINE (DEERE MANUFACTURED)	RG6090U016555
PUMP, HYDRO VARIABLE DISPLACEMENT, FRONT	215007121
CAB	H0CBH00008945
TRANSMISSION, HYDROSTATIC	S0215008356
FRAME	100000006943
STALK CHOPPER	201020414124
STALK CHOPPER	0201020414124
PUMP, HYDRO VARIABLE DISPLACEMENT, FRONT	0215007121
GEARBOX, MULTIPLE SPEED 2	CE2SRAA130472
FINAL DRIVE, LEFT	CEFDHAL104556
FILTER EXHAUST DPF	REXF162135759
STALK CHOPPER	0201010713767
SCR AFTERTREATMENT DEVICE	REXR160002124
STALK CHOPPER	201010713767
GEAR BOX	CEGB4D4104039
FINAL DRIVE, RIGHT	CEFDHAM104447

08RAH0202	DESTINATION CODE USA	08RAH
08RAH0409	OPERATION MANUAL - ENGLISH	08RAH
08RAH0505	GEN PURP EXTENDED WEAR PKG	08RAH
08RAH1121	PREMIUM CAB	08RAH
08RAH1221	ENHANCED AIR SUSPENSION SEAT	OSRAH
08RAH1379	HID LIGHTS & EXTREMITY	08RAH
08RAH1 <mark>4</mark> 13	PREMIUM RADIO PACKAGE W/ XM	08RAH
08RAH1803	AUTOTRAC READY/HARV MONITOR	08RAH
08RAH1823	GS3 TOUCH SCRN7"COLOR DISPLY	08RAH
08RAH188F	JDLINK ULTIMATE RDA PROMO	08RAH
08RAH2012	3 SPD ELECTRICAL SHIFT TRANS	08RAH
08RAH2220	2 WHEEL DRIVE	08RAH
08RAH3025	HEAVY DUTY VAR SPEED DRIVE	08RAH
08RAH4340	ROUND BAR CONCAVE	08RAH
08RAH4814	S-SERIES CLEANING SHOE	08RAH
08RAH4883	TRISTREAM ROTOR XTD WEAR	08RAH
08RAH5220	2.2BU/SEC 250BU 6.6M LESS CV	OSRAH
08RAH5601	LESS RUST PROTECTION	08RAH
08RAH5752	MANUAL ADJUST VANE TAILBOARD	OSRAH
08RAH6638	600/70R28 R1W (FS/GY)	08RAH
08RAH6714	800/65R32 R1W 172A8	08RAH
08RAH7015	FINAL TIER 4 ENGINE	08RAH
08RAH8525	CLN GR AUG & FAN BOTM PROTEC	08RAH
08RAH8700	110V COOLANT HTR NO EXPORT	08RAH
08RAH9223	16IN (400MM)AXLE SPACER	08RAH
08RAH9522	FULL GRAIN TANK SENSOR	08RAH
08RAH9660	NO BRAND PREFERENCE	08RAH

Claim History

Dealer	Claim # 💌	Туре 👻	Fail Date 💌	Repair Date 💌	Process Date 💌	Ref # 1 💌	Ref # 2 🛒	Measurement 💌
064270	107809034	NORMAL	30 Jun 2015	06 Jul 2015	09 Jul 2015	160388-2	160388	4
064270	107809008	NORMAL	30 Jun 2015	06 Jul 2015	09 Jul 2015	160388-1	160388	4
06 <mark>4</mark> 270	108189748	NORMAL	31 Aug 2015	01 Sep 2015	15 Sep 2015	165809-1	165809	6
064270	108234813	NORMAL	16 Sep 2015	16 Sep 2015	25 Sep 2015	167133-1	167133	28
064270	108446994	NORMAL	12 Oct 2015	19 Oct 2015	04 Nov 2015	170502-1	170502	235
064270	108447436	NORMAL	21 Oct 2015	26 Oct 2015	30 Oct 2015	170873-1	170873	282
064270	109943391	PIP	15 Aug 2016	15 Aug 2016	16 Aug 2016	176147-1	176147	392
064270	110138032	NORMAL	22 Aug 2016	19 Sep 2016	28 Sep 2016	200 <mark>472</mark> -1	200472	393
064270	<u>111222766</u>	PIP	11 May 2017	11 May 2017	11 May 2017	226580-1	226580	401
064270	114118665	PIP	07 Nov 2018	07 Nov 2018	08 Nov 2018	277 <mark>4</mark> 07¬1	277407	604

PIP History

PIP Number	PIP Type	PIP Participation Type	PIP Title	PIP Status
15HX474A	Mandatory	Dealer	15HX474A - S-SERIES COMBINES MAIN ENGINE GEAR CASE SNUBBER	COMPLETE
16HX508A	Fix-as-Fail	Dealer	16HX508A - S-SERIES VACUUM FAN JACKSHAFT REPLACEMENT	COMPLETE
16HX518	Fix-as-Fail	Dealer	16HX518 - PBST PARK BRAKE PRESSURE SENSOR REPLACEMENT - FAF	TERMINATED
17HX527A	Mandatory	Dealer	17HX527A - DF3 CHAFFER FRAME IMPROVEMENT - MANDATORY	COMPLETE
17HX527B	Fix-as-Fail	Dealer	17HX527B - DF3 CHAFFER FRAME IMPROVEMENT - FIX AS FAIL	NOT_FAILED
17HX527C	Fix-as-Fail	Dealer	17HX527C - DF3 CHAFFER FRAME IMPROVEMENT - FIX AS FAIL	NOT_FAILED
17HX527D	Fix-as-Fail	Dealer	17HX527D - DF3 CHAFFER FRAME IMPROVEMENT - FIX AS FAIL	NOT_FAILED
18HX568A	Fix-as-Fail	Dealer	18HX568 A - FT4 DEF SYSTEM FILTER UPDATE - FIX AS FAIL	NOT_FAILED



75482 Road 435 Lexington, NE 68850 Phone: 308-324-4639 Fax: 308-324-6600 www.landmarkimp.com Lexington@landmarkimp.com



Invoice To Account No:	Deliver To:		SEF	RVICE INVOICE
Internal Used Stock No. 170336	Internal Used Sto	ck No. 170336	Invoice Number:	10596580
			Invoice Date:	12/11/2018
			Location:	05
			Work Order Number:	287312
			Payment Type:	Account
Bus Phone:	Bus Phone:			
Prv Phone:	Prv Phone:		Page:	1 of 1
Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE JD S650 COMBINE		1H0S650SJF0775010	MJ775010	

/S650F000009 Internal

COMPLAINT:

01 REPLACE COUPLER ON MULTI-COUPLER - PRICING PER COUPLER oil leaking from coupler

CORRECTION:

looked up parts and removed the coupler from the block and installed the new coupler

<u>Part Number</u> AXE21789	<u>Description</u> VALVE		Quantity List Price 1.00 149.22	Net PriceExtended PriceTaxed Ind149.22\$149.22N
Labor: \$99.80	Parts: \$149.22	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$249.02

		Labor:	\$99.80
Customer PO	No:	Parts:	\$149.22
Tax Exempt N	lo:		\$0.00
Advisor:	LARRY BUHLMANN	LANDWARK Misc:	\$0.00
	-	Sales Tax:	\$0.00
*** 🕻	DOCUMENT COPY * * *	Grand Total:	\$249.02

LANDMARK EXCLUSIVE WARRANTY OFFER! We're now offering a 1 year warranty on labor for all non-maintenance items only when work is completed by one of our factory trained John Deere technicians. For parts only purchase over the counter we have a 6 month warranty on John Deere parts.

TERMS AND CONDITIONS

Approved charges are due by the 10th of the month following purchase, I agree to pay a monthly periodic FINANCE CHARGE at the rate of 1.33% which is an ANNUAL PERCENTAGE CHARGE OF 16% on the unpaid balance. The purchaser agrees to pay reasonable attorney fees if collection efforts are required.

Received by:	ived by: .
--------------	------------

.....Date:

Failure Part : 17HX527A

Dante / Labon / Othen Cundite

Failure Mode :	NO FAIL MODE GIVEN
Failure Area :	
Failure Mode Comments :	
Downtime :	N/A
DTAC Case :	
DTAC Solution :	

Parts / Labor / Other Credits		
Item	Description	Quantity Approved
MPH20178	DF3 CHAFFER CLEVIS BRACKETS	1
A	124.75	7.0
		0.0

Complaint

01 17HX527A - DF3 CHAFFER FRAME IMPROVEMENT - MANDATORY

Cause

17HX527A - DF3 CHAFFER FRAME IMPROVEMENT - MANDATORY

Correction

Performed chaffer frame PIP. There were no cracks in the side sheets.

Failure Mode :	NO FAIL MODE GIVEN
Failure Area :	
Failure Mode Comments :	
Downtime :	N/A
DTAC Case :	
DTAC Solution :	

Parts / Labor / Other Credits

Item	Description	Quantity Approved
MPH20122	710416FIELD MOD: FOR DV	1
A	119.75	2.5
		0.0

Complaint

04 16HX508A S-SERIES VACUUM FAN JACKSHAFT REPLACEMENT

Cause

16HX508A S-SERIES VACUUM FAN JACKSHAFT REPLACEMENT

Correction

16HX50BA S-SERIES VACUUM FAN JACKSHAFT REPLACEMENT -- COMPLETED

Failure Mode /	: LEAKED
Failure Area :	: REVERSER
Failure Mode Comments :	:
Downtime :	: NO DOWNTIME
DTAC Case :	a
DTAC Solution :	3

Parts / Labor / Other Credits

Item	Description	Quantity Approved
TY26374	GL-5,80W140 SYNTHETIC GEAR LUBE 16G	4
TY25744	SYNTHETIC GREASE - 14.1 OZ(US)	1
PM37463	RTV CLEAR SILICONE 80ML TUBE	1
E53699	SEAL, OIL	1
AZ49370	SEAL	1
L	DIAGNOST	0.25
в	100.00	0.5
A	100.00	3.5
		0.0
Complaint		

01 REVERSER OIL LEAK

Cause

LEAKING OIL

Correction

DIAGNOSE AND FOUND TWO SEALS LEAKING. CLEANED THE UNIT OF THE LEAKED OIL, DISASSEMBLED AND REMOVED LEAKING SEALS, INSTALLED NEW SEALS AND REASSEMBLED IN REVERSE ORDER, GREASED AND FILLED WITH OIL, TEST RAN AND NO LEAKS RETURNED.

Failure Part : 15HX474A

Failure Mode :	NO FAIL MODE GIVEN
Failure Area :	
Failure Mode Comments :	
Downtime :	N/A
DTAC Case :	
DTAC Solution :	

Parts / Labor / Other Credits

Item	Description	Quantity Approved
MPH20046	PIP FOR MEG PRESSURE SWITCH	1
A	100.00	0.5
		0.0

Complaint

01 15HX474A - S-SERIES COMBINES MAIN ENGINE GEAR CASE SNUBBERPIP main engine gearcase snubber

Cause

This failure of the Main Engine Gearcase pressure switch is from repeated spikes in the hydraulic system

Correction

Removed old switch and installed snubber and new pressure switch.

Parts / Labor / Other Credits

STUCK OR SEIZED	Failure Mode :
FEEDERHOUSE	Failure Area :
	Failure Mode Comments :
NO DOWNTIME	Downtime :
	DTAC Case :
	DTAC Solution :

Item	Description	Quantity Approved
34M7255	PIN, SPRING, COILED	2
Z61818	KEY-WOODRUFF	2
H218726	V-BELT, BELT, V-BELT, HL, 4068 EL 2	1
H216332	HALF SHEAVE, INNER 26 DEGREE, HI HP	1
H172267	SPRING-COMPRESSION, FH DRIVE	1
AH230614	CAM KIT, 42 DEG CAMS KIT, BOLT IN	1
AH220892	HALF SHEAVE, ASSY, OUTER W/ZERKS, H	1
L	DIAGNOST	0.5
E	110.00	4.25
		0.0

Complaint

REVERSER GETTING HOT

Cause

inner sheave on reverser galled up making cams stick

Correction

removed lower variable drive sheaves on reverser and replaced installed new outer sheave and cams installed new belt and adjusted

Failure Part : AH167179

LEAKED	Failure Mode :
FEEDERHOUSE	Failure Area :
	Failure Mode Comments :
NO DOWNTIME	Downtime :
	DTAC Case :
	DTAC Solution :

Parts / Labor / Other Credits		
Item	Description	Quantity Approved
H218726	V-BELT, BELT, V-BELT, HL, 4068 EL 2	1
L.	DIAGNOST	0.55
E	110.00	2.0
в	110.00	0.5
		0.0

Complaint

Header not engaging

Cause

belt slipping due to oil leaking on it from breather in dipstick.

Correction

Found the feeder house variable speed belt slipping due to belt and sheaves being oil soaked. Cleaned all the leaked oil form the ar ea and from the belt and sheaves. Reinstalled the belt and it was still slipping due to being oil soaked. Removed and replaced the b elt with new and adjusted belt for proper speed ran to check operation.

Show / Hide

Failure Mode :	ELECTRICAL FAILURE
Failure Area :	AFTERTREATMENT MUFFLER
Failure Mode Comments :	
Downtime :	LESS THAN 1 DAY
DTAC Case :	14351928
DTAC Solution :	

Parts / Labor / Other Credits		
Item	Description	Quantity Approved
RE553440	CHEMICAL SENSOR, NOX, 12 V 615 MM L	1
AXE41011	GASKET, DANA, 3 LAYER	1
L :	DIAGNOST	13.0
E	110.00	3.75
		0.0

Complaint

01 SERVICE CALL - ECU code 3216.12

Darte / Labor / Other Credite

Cause

sensor was damaged during assembly

Correction

checked operation of machine problem was intermittent found DTAC solution 98064 and followed steps machine still throwing code opened up a DTAC case #14351928 went back out and did some checks on harnesses and code went away customer called up and stated machineacting up and would only idle updated DTAC case as they had forwarded it to power systems DTAC wanted me to go out and do a coupleof recordings and send it to them so i went out and got two recordings and sent it to them the next day they wanted me to go out and follow code ECU 3216.09 went out and found sensor harness damaged by cap screw replaced sensor and left the one screw out reassembled and hooked up computer and ran while watching readings for inlet sensor all working like it should

Show / Hide

Failure Part : AXE55675

SOFTWARE / REPROG	Failure Mode :
GLM SOFTWARE	Failure Area :
	Failure Mode Comments :
NO DOWNTIME	Downtime :
	DTAC Case :
102967	DTAC Solution :

Parts / Labor / Other Credits

Item	Description	Quantity Approved
		0
A	100.00	1.0
		0.0

Complaint

01 UPDATE GLM SOFTWARE GLM 001512.02 CODE PRESENT

Cause

BAD GLM SOFTWARE PER DTAC SOLUTION 102967

Correction

DOWNLOADED NEW GLM SOFTWARE FROM SDS, INSTALLED NEW SOFTWARE ON CONTROLLER, CLEARED ALL CODES, CONNECTED TO DEERE NETWORK TO CONFIRM SOFTWARE WAS UPDATED.

Failure Part : L207220

LEAKED	Failure Mode :
AC DRAIN LINE	Failure Area :
	Failure Mode Comments :
NO DOWNTIME	Downtime :
	DTAC Case :
	DTAC Solution :

Parts / Labor / Other Credits

Item	Description	Quantity Approved
		0
L	DIAGNOST	0.85
A	100.00	1.5
		0.0

Complaint

water leaking into the cab

Cause

hose not installed properly on drain

Correction

ran machine and found water runing down windshield removed trim inside of cab installed hose and checked operation

Failure Part : RE553440

Failure Mode :	ELECTRICAL FAILURE
Failure Area :	DPF/SRC SENSOR
Failure Mode Comments :	
Downtime :	NO DOWNTIME
DTAC Case :	
DTAC Solution :	

Parts / Labor / Other Credits

Item	Description	Quantity Approved
TY6341	GREASE, HI-TEMP-EP-POLY, 140Z. (397G)	1
RE553440	CHEMICAL SENSOR, NOX, 12 V 615 MM L	1
AXE41011	GASKET, DANA, 3 LAYER	1
L L	DIAGNOST	1.15
A	100.00	3.0
		0.0

Complaint

*6. DPF SENSOR FAULT CODEcode ECU 3216.12 was active

Cause

sensor was damaged during assembly

Correction

diagnosed code using service advisor found that the sensor was damaged during assembly removed all shielding to gain access to the s ensor removed sensor and replaced reinstalled shielding and ran to check operation code never came back



75482 Road 435 Lexington, NE 68850 Phone: 308-324-4639 Fax: 308-324-6600 www.landmarkimp.com Lexington@landmarkimp.com



SERVICE INVOICE

Invoice To Account No:	Deliver To:		SERVICE INVOICE			
WARRANTY			Invoice Number:	834785		
			Invoice Date:	10/30/2015		
			Location:	05		
			Work Order Number:	170873		
			Payment Type:	Account		
Bus Phone:						
Prv Phone:			Page:	1 of 2		
Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:		
JOHN DEERE S650	282	1H0S650SJF0775010	MJ775010			

/SERVCALL Warranty

COMPLAINT: REVERSER GETTING HOT

CORRECTION:

removed lower variable drive sheaves on reverser and replaced installed new outer sheave and cams installed new belt and adjusted


Part Number 34M7255	Description SPRING PIN	<u>Quantity</u> 2.00	<u>List Price</u> 1.46	<u>Net Price</u> 1.46	Extended Price \$2.92	<u>Taxed Ind</u> N
AH220892	HALF SHEAVE	1.00	657.74	657.74	\$657.74	Ν
AH230614	CAM KIT	1.00	631.21	631.21	\$631.21	Ν
H172267	COMPRESSIO	1.00	49.71	49.71	\$49.71	Ν
H216332	HALF SHEAV	1.00	568.18	568.18	\$568.18	Ν
H218726	V-BELT	1.00	371.27	371.27	\$371.27	Ν
Z61818	SHAFT KEY	2.00	6.47	6.47	\$12.94	Ν
<u>Miscellaneous</u>	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind



75482 Road 435 Lexington, NE 68850 Phone: 308-324-4639 Fax: 308-324-6600 www.landmarkimp.com Lexington@landmarkimp.com



Invoice To Account No:	Deliver To:				SERVIC	E INVO	ICE
WARRANTY				Invoice Numb	er:	834	4785
				Invoice Da	te:	10/30)/2015
				Locatio	on:		05
			1	Nork Order Numb	er:	1	70873
				Payment Typ	be:	Ac	ccount
Bus Phone:							
Prv Phone:				Pag	je:		2 of 2
Make/Model:	Meter:	Serial Number:		Eq ID:	F	leet No:	
JOHN DEERE S650	282	1H0S650SJF07750)10	MJ775010			
/SERVCALL Warranty P3750 FREIGH	г		1.00	65.00	65.00	\$65.00	N
Labor: \$522.50 Parts: \$	62,293.97 OL&M:	\$0.00	Misc:	\$65.00	Sub-Total:	\$2,881.47	



LANDMARK EXCLUSIVE WARRANTY OFFER! We're now offering a 1 year warranty on labor for all non-maintenance items only when work is completed by one of our factory trained John Deere technicians. For parts only purchase over the counter we have a 6 month warranty on John Deere parts.

TERMS AND CONDITIONS

Approved charges are due by the 10th of the month following purchase, I agree to pay a monthly periodic FINANCE CHARGE at the rate of 1.33% which is an ANNUAL PERCENTAGE CHARGE OF 16% on the unpaid balance. The purchaser agrees to pay reasonable attorney fees if collection efforts are required.

Received by: Date:



75482 Road 435 Lexington, NE 68850 Phone: 308-324-4639 Fax: 308-324-6600 www.landmarkimp.com Lexington@landmarkimp.com



SERVICE INVOICE Invoice To Account No: Deliver To: Internal Used Stock No. 71649 Internal Used Stock No. 71649 **Invoice Number:** 10148854 9/19/2016 Invoice Date: Location: 05 Work Order Number: 200472 Payment Type: Account Bus Phone: Bus Phone: 1 of 3 Prv Phone: Prv Phone: Page: Make/Model: Serial Number: Fleet No: Meter: Eq ID: JOHN DEERE JD S650 COMBINE 1H0S650SJF0775010 MJ775010

/S660G000011 Internal COMPLAINT:

02 MULTICOUPLER UPDATE

CORRECTION:

NOTE:

-Combines equipped with Closed Center Main Hydraulic Valve Block Assemble per bundle instructions HXE95346.

<u>Part Number</u> BXE10667	<u>Description</u> VALVE KIT		QuantityList Price1.0066.00	Net PriceExtended PriceTaxed Ind66.00\$66.00N
Labor: \$150.00	Parts: \$66.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$216.00

/S660SERVICE Internal

COMPLAINT:

03 SERVICE COMBINE FILTERS AND FLUIDS

CORRECTION:

Replace all filters. Drain; Engine oil. Reverser gearcase. Primary countershaft gearcase. Refill to specifications. Check the combine for; John Deere recommended tire pressures. All fluid levels are at specified levels. Remove and clean cab air pre-cleaner. Grease all lube points on the combine. Repairs/adjustments not covered on this segment. Crankcase 29 qts. HD reverser w/cooler 7.4 pts. Countersahft gearcase 2.5 pts.

<u>Part Number</u> AH128449	Description HYDRAULIC	Quantity 2.00	<u>List Price</u> 55.35	<u>Net Price</u> 55.35	Extended Price \$110.70	<u>Taxed Ind</u> N
AXE42065	Filter Element	1.00	43.28	43.28	\$43.28	Ν
AXE42066	FILTER ELE	1.00	91.24	91.24	\$91.24	Ν
HXE11090	FILTER	1.00	215.60	215.60	\$215.60	Ν



Invoice To Account No:

Landmark Implement Inc.

75482 Road 435 Lexington, NE 68850 Phone: 308-324-4639 Fax: 308-324-6600 www.landmarkimp.com Lexington@landmarkimp.com

Deliver To:



SERVICE INVOICE

Internal Used Stock No. 71649		Internal Used Stock No. 71649			Invoice Number:		10148854	
					Invoice D	ate:	9/19	9/2016
					Loca	tion:		05
				,	Work Order Num	ber:	2	00472
					Payment T	ype:	Ac	ccount
Bus Phone:		Bus Phone:						
Prv Phone:		Prv Phone:			Page:		2 of 3	
Make/Model:		Meter:	Serial Num	ber:	Eq ID:		Fleet No:	
JOHN DEERE JD S650 COMB	INE		1H0S650S	F0775010	MJ775010			
/S660SERVICE Internal								
HXE11091	FILTER			1.00	146.71	146.71	\$146.71	Ν
L214634	FILTER			1.00	15.44	15.44	\$15.44	Ν
RE284091	AIR FILTER			1.00	56.65	56.65	\$56.65	Ν
RE509672	FILTER ELE			1.00	20.41	20.41	\$20.41	Ν
RE533910	FUEL FILTER			1.00	113.48	113.48	\$113.48	Ν
RE539465	FILTER ELE			1.00	88.53	88.53	\$88.53	Ν
TY26682	Plus-50 II Oil 1	15W40 CJ4/SN		8.00	15.21	15.21	\$121.68	Ν
Labor: \$439.99	Parts: \$1,023	3.72 01	&M: \$0.00	Misc	\$0.01	Sub-Tot	al: \$1,463.72	

/S650F1138847 Internal COMPLAINT:

04 CONVEYOR DRIVE CHAIN, R&R

CORRECTION:

Remove shields. Remove and replace drive chain. Adjust chain and assemble in reverse order.

Part Number

Description



Quantity List Price

Net Price Extended Price Taxed Ind



75482 Road 435 Lexington, NE 68850 Phone: 308-324-4639 Fax: 308-324-6600 www.landmarkimp.com Lexington@landmarkimp.com



		Deliver To:				SERVICI	E INVO	DICE
Internal Used Stock No. 71649		Internal Used Stock No. 71649			Invoice Number:		10148854	
					Invoice D	ate:	9/	19/2016
					Loca	tion:		05
				1	Work Order Num			200472
					Payment T	ype:		Account
Bus Phone:		Bus Phone:			-			2 - 6 /
Prv Phone:		Prv Phone:			Pa	age:		3 of 3
/lake/Model:		Meter:	Serial Number:		Eq ID:	FI	leet No:	
IOHN DEERE JD S650 COM	BINE		1H0S650SJF07750	10	MJ775010			
S650F1138847 Internal AH232566 Labor: \$260.00	LINK CHAIN Parts: \$118		: \$0.00	1.00 Misc:	115.94 \$0.00	115.94 Sub-Total:	\$115.94 \$375.94	١
Missellanseus Channes								
Service Accessories								\$82.23
						Labor:	-	850.00
						Parts:	\$1	850.00 ,205.66
Service Accessories Customer PO No: Tax Exempt No:						Parts: OL&M:	\$1	850.00 ,205.66 \$0.00
Service Accessories Customer PO No: Tax Exempt No:	GORDON					Parts: OL&M: Misc:	\$1	\$850.00 ,205.60 \$0.00 \$82.23
Service Accessories Customer PO No: Tax Exempt No:	GORDON					Parts: OL&M:	\$1	\$850.00 ,205.66 \$0.00 \$82.23
Customer PO No: Tax Exempt No:						Parts: OL&M: Misc:	\$1	\$82.23 \$850.00 ,205.66 \$0.00 \$82.23 \$0.00 ,137.89

LANDMARK EXCLUSIVE WARRANTY OFFER! We're now offering a 1 year warranty on labor for all non-maintenance items only when work is completed by one of our factory trained John Deere technicians. For parts only purchase over the counter we have a 6 month warranty on John Deere parts.

TERMS AND CONDITIONS

Approved charges are due by the 10th of the month following purchase, I agree to pay a monthly periodic FINANCE CHARGE at the rate of 1.33% which is an ANNUAL PERCENTAGE CHARGE OF 16% on the unpaid balance. The purchaser agrees to pay reasonable attorney fees if collection efforts are required.

Received by: Date: