

Account Information	Sample Information	Other Sample Information
Lab Customer ID#: 307251 Company Name: PMC Rental Company Worksite: Company Address: 5000 Vasquez Blvd. Denver, CO, 80216	Lab No.: 201905020561 Sample Tracking #: Sample Date: May 01, 2019 Received Date: May 02, 2019 Completed Date: May 06, 2019	PO No.: PWR MOTIVE - DENVER, CO Work Order No.: Reference No.: 8292204
Unit Information	Component Information	Fluid Information
Unit ID: ECBK6-1402 Unit Mfg: Link-Miles Unit Model: Unit Serial #: ECBK6-1402 Unit Worksite:	Cpnt. Description: HYDRAULIC Cpnt. Mfg: Link-Miles Cpnt. Model: Cpnt. Serial #: ECBK6-1402 Cpnt. Type: HYDRAULIC	Fluid Manufacturer: UNKNOWN Fluid Brand/Product: UNKNOWN Fluid Grade:

Maintenance Recommendations for Lab No.: 201905020561

Evaluated By: Justin Hilt - Data Analyst

ANALYSIS INDICATES COMPONENT & LUBRICANT CONDITIONS ARE ACCEPTABLE. RESAMPLE at the next scheduled interval.

SPECTROCHEMICAL ANALYSIS IN PARTS PER MILLION

LAB NO.	SAMPLE DRAWN	Wear Metals										Contaminants			Additives							
		Iron	Chromium	Nickel	Aluminum	Lead	Copper	Tin	Silver	Titanium	Vanadium	Silicon	Sodium	Potassium	Boron	Molybdenum	Phosphorus	Zinc	Calcium	Barium	Magnesium	Antimony
0561	05/01/19	2	<1	<1	<1	1	<1	1	<0.1	<1	<1	1	<1	<1	<1	<1	146	28	3	<1	3	<1

SAMPLE INFORMATION

LAB NO.	SAMPLE DRAWN	UNIT TIME	FLUID TIME	UOM	FILTER CHG.	LUBE SERVICE
0561	05/01/19	3189		HR	-	

FLUID PROPERTIES/CONTAMINANTS








Water	D7279 Vis 100 °C
<0.1	8.2

KEY: UoM - Unit of Measure Y - Yes N - No C - Changed S - Sampled > - Greater Than < - Less Than N/R - Not Reported (M) - Modified /method

Testing performed by Bureau Veritas®, an ISO/IEC 17025:2005 accredited laboratory. L-A-B accredited Certificate Number L2264. †: Not in scope of accreditation. For further details on outsourced testing, contact the laboratory directly. ‡: This test is run based on a trigger test, in this case "<" values indicate that the trigger test was either not positive or the result was below the reportable limit. For a list of trigger tests refer to <http://www.bureauveritas.com/oil-analysis>.

Notice: This analysis is intended as an aid in predicting mechanical wear. Test results, maintenance recommendations and accuracy are affected by customer provided samples, equipment identification, maintenance history and apply only to this sample as provided. No guarantee, expressed or implied, is made against failure of this piece of equipment or a component thereof. The ultimate responsibility for the maintenance of this piece of equipment and all its components is the responsibility of the equipment owner.

Graphs



Photos



NO IMAGE
AVAILABLE

Activity

No activity