

Inspection Report Highway Tractor



IRC# B8011

CO# 201008011

Pre-Inspection

DATE: 3/31/2020

Vin #1NP5L09X8YD537726 Make- Peterbuilt Model-379 Year- 2000

Hours- 8097 Miles- 713095 Equipment Location- Thief River Falls MN

Shipping Information Length- 25' / Width- 8' 6" / Height- 11' Weight- NA Inspector- 9

Seller Info.- Bluebill Auctions

OPTIONS/SPECIFICATIONS: A/C, Air ride drivers and passenger seats, Heated mirrors, Cummins ISM Engine, 335HP@2100RPM, Spicer 10 speed manual transmission, 411 rear axle ratio, 214' wheelbase, 12000lb front axle, 40000lb rear axles, 52000 GVWR, Air ride rear suspension 11R22.5 steer tires, 11R22.5 Drive tires, Engine brake, PTO, Wet kit, Headache rack

*Please review all photos and videos along with report

Iron Ridge Co. Building A Mountain Of Integrity

1: General Condition



Operational/Average wear for type, operating hours, and age

*Heavy wear, leaks, and major damage as well as unit highlights are photographed and/or noted in comments

ITEM	<input type="checkbox"/>	COMMENT
*Start Odometer	<input type="checkbox"/>	713095, Inoperable
*Start Hour Meter	<input type="checkbox"/>	8097, Inoperable
Lights	<input checked="" type="checkbox"/>	
Paint/Main Body/Sheet Metal	<input checked="" type="checkbox"/>	
Cab External Condion	<input type="checkbox"/>	Dents in rear of cab
Steps/Ladder/Catwalks	<input checked="" type="checkbox"/>	
Handrails/Grab Irons	<input checked="" type="checkbox"/>	
Cab Door	<input checked="" type="checkbox"/>	
Fuel Tank	<input checked="" type="checkbox"/>	
Exhaust Stack/Air Inlet	<input checked="" type="checkbox"/>	
Batteries/Battery Box	<input checked="" type="checkbox"/>	

Additional Notes-

2: Operator Station

ITEM	<input type="checkbox"/>	COMMENT
Windows/Glass		Chipped windshield
Mirrors		Broken drivers convex mirror
Seat Belts		Inoperable retract
Back Up Alarm		NA/Inoperable
Horn		Electric inoperable
Dash Console	<input checked="" type="checkbox"/>	
Engine Oil Pressure	25	PSI
Warning Lights	<input checked="" type="checkbox"/>	
Gauges	<input checked="" type="checkbox"/>	
Windshield Wipers	<input checked="" type="checkbox"/>	
Steering Controls	<input checked="" type="checkbox"/>	
Engine Controls	<input checked="" type="checkbox"/>	
Drive Train Controls	<input checked="" type="checkbox"/>	
Hydraulic Controls		Not operationally checked
PTO Controls		Not operationally checked
Service/Park Brakes	<input checked="" type="checkbox"/>	
Heater	<input checked="" type="checkbox"/>	
A/C		Not operationally checked
Ceiling/Roof	<input checked="" type="checkbox"/>	
Seat/Armrests	<input checked="" type="checkbox"/>	
Floor Boards/Mats	<input checked="" type="checkbox"/>	
Doors/Latches	<input checked="" type="checkbox"/>	

Additional Notes-

3: Drive Train/Transmission

ITEM	<input type="checkbox"/>	COMMENT
Trans. Make/Model		Spicer
*Transmission Type		Manual
*Transmission Speeds		10
Transmission Forward	<input checked="" type="checkbox"/>	
Transmission Reverse	<input checked="" type="checkbox"/>	
Drive Shafts	<input checked="" type="checkbox"/>	
Steer Axle	<input checked="" type="checkbox"/>	
Middle Drive Axle	<input checked="" type="checkbox"/>	
Rear Drive Axle		Weld repair
Additional Axles	<input checked="" type="checkbox"/>	
Steering System	<input checked="" type="checkbox"/>	
PTO		Not operationally checked

Additional Notes-

4: Engine

ITEM	<input type="checkbox"/>	COMMENT
*Engine Make/Model		Cummins ISM
Emissions Control Label		See photo
Engine Operation	<input checked="" type="checkbox"/>	
Oil Leaks		None seen
Engine Blow-by Video	<input checked="" type="checkbox"/>	
Engine Run Video	<input checked="" type="checkbox"/>	
Exhaust System/Turbo		Hole in exhaust piping, lower right exhaust elbow
Fuel System	<input checked="" type="checkbox"/>	
Fuel Leaks		None seen
Radiator	<input checked="" type="checkbox"/>	
Coolant Leaks		None seen
Coolant Condition/Level	<input checked="" type="checkbox"/>	
Belts/Accessory Drive	<input checked="" type="checkbox"/>	

Additional Notes-

5: Tires/Brakes

BRAKE TYPE		Drum		
BRAKE CONDITION		Operational, see photos		
TIRE CONDITION		Recap drives, See photos		
Position	SIZE	BRAND	REMAINING TREAD-32nds.	WHEEL TYPE
LF	11R22.5	Ameristeel	7	All aluminum wheels
LMO	11R22.5	Cachland	21	
LMI	11R22.5	Cachland	20	
LRO	11R22,5	Cachland	14	
LRI	11R22.5	Cachland	12	
RF	11R22.5	Goodyear	17	
RMO	11R22.5	Cachland	18	
RMI	11R22.5	Cachland	17	
RRO	11R22.5	Cachland	14	
RRI	11r22.5	Cachland	14	
R				
L				
R				
L				

Additional Notes-

6: Hydraulics

ITEM	<input type="checkbox"/>	COMMENT
------	--------------------------	---------

Pump	Not operationally checked
Hydraulic Lines/Hoses	✓
Valves	✓
Reservoir/Tank	✓
Leaks	None seen

Additional Notes-

7: Chassis

ITEM	<input type="checkbox"/>	COMMENT
Main Frame Condition	✓	
Suspension Bushings	✓	
Suspension Springs	✓	
Suspension Air Bags	✓	
Cab Air Suspension	NA	
Fifth Wheel	✓	
Sliding Fifth Wheel	✓	
Fifth Wheel Remaining	10/32	
Sleeper	NA	
Aux. Power Unit	NA	
Start Up Video	✓	
*End Hour Meter	8097	
*End Odometer	713095	

Additional Notes-

*Notice: We CAN NOT and DO NOT offer any warranty or guarantee on the inspections from Iron Ridge Co.
We are an independent company, we do our best to represent equipment as it is.