Inspection Report Highway Tractor



IRC# B8008

_{CO#} 201008008

Pre-Inspection					DATE: March 31 2020
Vin # 472757		Make-	Peterbilt	Model- 379	_{Year-} 1998
Hours- NA Miles-	133	7159.2	Equipment l	ocation- Thief River Fall	s MN
Seller Information- Bluebill Auc	tions				
*Please review all photos and video	s along	y with report		Iron Ridge Co. Building	g A Mountain Of Integrity
1: General Condition	V			r type, operating hours, a age as well as unit highlights are	nd age photographed and/or noted in comments
ITEM				COMMENT	
*Start Odometer	1337	7159.2			
*Start Hour Meter	NA				
Lights		Clearance I	ights Inopera	ıble	
Paint/Main Body/Sheet Metal		Cracked Fe	nder		
Cab External Condtion					
Steps/Ladder/Catwalks					
Handrails/Grab Irons					
Cab Door					
Fuel Tank					
Exhaust Stack/Air Inlet					
Batteries/Battery Box					

Additional Notes-

2: Operator Station

	COMMENT
~	
~	Drivers convex cracked
~	
~	
~	Electric horn inoperable
~	
~	PSI 18
	Tack inoperable

Windshield Wipers	v	
Steering Controls		Play in tilt pivot
Engine Controls	· ·	
Drive Train Controls	~	
Hydraulic Controls		NA
PTO Controls	<u> </u>	NA
Service/Park Brakes	~	
Heater	~	
A/C	<u> </u>	Not operationally checked
Ceiling/Roof		
Seat/Armrests	v	
Floor Boards/Mats	~	
Doors/Latches	 ✓ 	

Additional Notes-

3:Drive Train/Transmission

ſ	ITEM		COMMENT
Ī	Trans. Make/Model		
	*Transmission Type	Mar	nual
	*Transmission Speeds	8	
	Transmission Forward	~	
	Transmission Reverse	~	
	Drive Shafts	~	
	Steer Axle	~	
	Middle Drive Axle	~	
	Rear Drive Axle	~	
	Additional Axles		NA
	Steering System	~	
	PTO		NA

Additional Notes-

ITEM □ COMMENT *Engine Make/Model ✓ Cummins N14 Emissions Control Label None found

Engine Operation	~	See running video
Oil Leaks		Turbo Return line
Engine Blow-by Video	~	Visible blow by
Engine Run Video	~	
Exhaust System/Turbo	~	
Fuel System	~	
Fuel Leaks	~	None found
Radiator	~	
Coolant Leaks	~	None found
Coolant Condition/Level	· ·	
Belts/Accessory Drive		

Additional Notes-

5: Tires/Brakes

BRAKE TYPE							
BRAKE CONDITION							
TIRE CO	ONDITION						
Position	SIZE		BRAND	REMAINING TREAD-32nds.	Wheel Type	Recap Y/N	
LF	11R22.5	Herc	ules	10	AI		
LMO	11R22.5	Cach	land	9	AI		
LMI	11R22.5	Cach	land	11	AI		
LRO	11R22.5	Good	lyear	17	AI		
LRI	11R22.5	Good	lyear	15	AI		
RF	11R22.5	Herc	ules	10	AI		
RMO	11R22.5	Cach	land	11	AI		
RMI	11R22.5	Cach	land	10	AI		
RRO	11R22.5	Good	lyear	17	AI		
RRI	11R22.5	Good	lyear	16	AI		
R							
L							
R							
L							

Additional Notes-

6:Hydraulic		N/A
ITEM		COMMENT
Pump		
Hydraulic Lines/Hoses		
Valves		
Reservoir/Tank		
Leaks	T -	

Additional Notes-

7: Chassis

	ITEM		COMMENT
	Main Frame Condition	~	
	Wheel Base		
	Suspension Bushings	~	
	Suspension Springs	~	
	Suspension Air Bags	~	
	Cab Air Suspension	~	
	Fifth Wheel	~	
	Sliding Fifth Wheel	~	
	Fifth Wheel Remaining	~	6mm
	Dump Box/Bed Dimensions	NA	
	Dump Box/Bed Condition		NA
	Sleeper		
	Aux. Power Unit		
	Start Up Video		
	*End Hour Meter		
	*End Odometer		
-			

Additional Notes-

*Notice: We CAN NOT and DO NOT offer any warranty or guarantee on the inspections from Iron Ridge Co.

We are an independent company, we do our best to represent equipment as it is.