

WEST-EQUIP.COM

SERVICE

Invoice To Account No: 67611		Deliver To:		Invoice Number:	
THOMAS WITTROCK THOMAS WITTROCK 2607 SUZANNE TR WEATHERFORD TX 76087		THOMAS WITTROCK 2607 SUZANNE TR WEATHERFORD TX 76087		Invoice Date:	
Bus Phone:		Bus Phone:		Location:	
Priv Phone:		Priv Phone:		Work Order Number:	
				Payment Type:	
				Page:	
Make/Model:		Meter:	Serial Number:	Eq ID:	
JOHN DEERE 6415		2344	L06415D494818	L046415D494818	

6415/1045/EG/10 Retail

COMPLAINT:

01 Diagnostics and Troubleshooting.

SPUTTERS ON START UP WILL BRING IN TOM 817-253-7924

CORRECTION:

verified engine sputter at start up. perform pinpoint tests per service manual.

Removed floor mat and fuel pickup tube access panel. Install new nut on pickup assembly. Removed hose from the fuel filter the injection pump. Installed new hose. The other hoses look fine. Reconnect all hoses, and lines after inspection, and replace the nut. Restart and check for engine sputter? No engine sputter after tractor sat all weekend after hose, and nut replacement.

NO Sputter after a couple of days of starting it up in the early mornings. Release tractor.

Checked pump pressures and scv's - all within spec.

Also inspected for any issues - none found

Part Number	Description	Quantity	List Price	Net Price
L112436	Tube Nut	1.00	21.99	21.99
RE170320	KIT	1.00	28.57	28.57
TY27047	14G BLACK WIRE	1.00	6.97	6.97
TY27049	14G WHITE WIRE	1.00	6.97	6.97
TY27158	12-10G 5/16" SHRINK RING	1.00	10.73	10.73
Labor: \$756.45		Parts: \$75.23	OL&M: \$0.00	Misc: \$0.00
				Sub

OTH/WE/H68/DIAG04 Retail

COMPLAINT:

02 Diagnostics and Troubleshooting.

STARTER ISSUES

CORRECTION: