

OWNER: WESTBURY (BERMUDA) LTD.
ADDRESS: C/O WESTBURY SERVICES INC.
 NAPLES FL 34104
PHONE: 239-643-4554
FAX:

OPERATOR: WESTBURY (BERMUDA) LTD.
ADDRESS: C/O WESTBURY SERVICES INC.
 NAPLES FL 34104
PHONE: 239-643-4554
FAX:

ANALYST: LUIS MEIRA
EMAIL: LMEIRA@CAMPSYSTEMS.COM

+1-514-636-2197 (DIRECT)
 514-636-2020 (OFFICE)
 WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
 631-980-4222 (EFAX-CARDS)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Task Type In: ('AD','ADP','SB','SBP'); Group by Profile or Bulletin: Profile Type; Mode: With Compliance or Next Due; For: Airframe,Engine,APU Etc;

AIRCRAFT SERIAL/REGNO: 9575/N813WB **MODEL:** GLOBAL 5000 GVFD **MANUFACTURER:** BOMBARDIER AVIATION

DATES	LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 27-SEP-2013	1065.5 A/C HRS	as of 14-SEP-2022	A/C HRS	as of ___/___/___
INSERVICE DATE: 30-MAY-2014	454 AFL	as of 14-SEP-2022	AFL	as of ___/___/___

APU SERIAL/PART: P-715/WE3800714-1 **MODEL:** RE220 (GX) **MANUFACTURER:** HONEYWELL

INSTALLED ON 21-SEP-2013	LAST ACTUALS		CURRENT ACTUAL	
0 APU HRS	693.9 APU HRS	as of 08-MAR-2022	APU HRS	as of ___/___/___
0 APUS	885 APUS	as of 08-MAR-2022	APUS	as of ___/___/___

ENGINE NO. 1 SERIAL/PART: 22301/DEL114 **MODEL:** BR700-710A2-20 (CIMMS) **MANUFACTURER:** ROLLS-ROYCE DERBY PLC

INSTALLED ON 11-OCT-2013	LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS 0 A/C HRS	1065.5 ENG. HRS	as of 14-SEP-2022	ENG. HRS	as of ___/___/___
0 ENC	454 ENC	as of 14-SEP-2022	ENC	as of ___/___/___

ENGINE NO. 2 SERIAL/PART: 22300/DER114 **MODEL:** BR700-710A2-20 (CIMMS) **MANUFACTURER:** ROLLS-ROYCE DERBY PLC

INSTALLED ON 11-OCT-2013	LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS 0 A/C HRS	1065.5 ENG. HRS	as of 14-SEP-2022	ENG. HRS	as of ___/___/___
0 ENC	454 ENC	as of 14-SEP-2022	ENC	as of ___/___/___



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
AIRFRAME - AD - 9575/N813WB							
EASA 2010-0067	ROCKWELL COLLINS, INC. - TDR-94, TDR-94D TRANSPONDERS - NAVIGATION - MODE S TRANSPONDER - CHECK/MODIFICATION					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED
		MOS		08-OCT-2015			
		HRS/MSC -		350.9			
		AFL		149			
EASA 2010-0186	DITTEL MESSTECHNIK GMBH, LUFTFAHRT GERATEBAU - COMMUNICATION - VERY HIGH FREQUENCY (VHF/AM) TRANSCEIVER - MODIFICATION					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED
		MOS		08-OCT-2015			
		HRS/MSC -		350.9			
		AFL		149			
EASA 2010-0204	ROCKWELL COLLINS, INC. - TDR-94, TDR-94D TRANSPONDERS - NAVIGATION SYSTEMS - MODE-S TRANSPONDER - MODIFICATION/REPLACEMENT					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED
		MOS		08-OCT-2015			
		HRS/MSC -		350.9			
		AFL		149			
EASA 2011-0090 REV 1	OXYGEN - OXYGEN MASK REGULATOR INFLATABLE HARNESS IDENTIFICATION - REPLACEMENT						NOT APPLICABLE - BY MANUFACTURER DATE
		MOS		08-OCT-2015			
		HRS/MSC -		350.9			
		AFL		149			
EASA 2013-0106	EQUIPMENT / FURNISHINGS - VARNISH ON VENEERED PANELS - INSPECTION / RE-FURBISHING					MANDATORY	NOT APPLICABLE - BY AIRCRAFT MODEL
		MOS		23-APR-2014			
		HRS/MSC -					
		AFL					
EASA 2013-0106 (1)	REWORK THE VENEERED PARTS OF THE AEROPLANE INTERIOR					MANDATORY	NOT APPLICABLE - BY AIRCRAFT MODEL
		MOS		23-APR-2014			
		HRS/MSC -					
		AFL					
EASA 2013-0106 (2)	INSPECT ALL VENEERED PARTS OF THE AEROPLANE INTERIOR					MANDATORY	NOT APPLICABLE - BY AIRCRAFT MODEL
		MOS		23-APR-2014			
		HRS/MSC -					
		AFL					
EASA 2013-0106 (3)	REPLACE OR REPAIR ALL AFFECTED VENEERED CABIN PANELS					MANDATORY	NOT APPLICABLE - BY AIRCRAFT MODEL
		MOS		23-APR-2014			
		HRS/MSC -					
		AFL					
EASA 2013-0106 (4)	INSPECTION OF AN AEROPLANE ACCOMPLISHED BEFORE EFFECTIVE DATE OF THIS AD					MANDATORY	NOT APPLICABLE - BY AIRCRAFT MODEL
		MOS		23-APR-2014			
		HRS/MSC -					
		AFL					
EASA 2013-0229R1	ENGINE FUEL AND CONTROL FUEL METERING UNIT REPLACEMENT						NOT APPLICABLE - PER ENGINE MODEL
		MOS		17-APR-2014			
		HRS/MSC -					
		AFL					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 1974-08-09 R02	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION (SUPERSEDED BY FAA AD 1974-08-09 R3)	MOS		27-SEP-2013			
29-JUL-1996		HRS/MSC -		0			
		AFL		0			
FAA 1974-08-09 R03	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION	MOS		01-NOV-2016		MANDATORY	COMPLIED WITH
39-16951		HRS/MSC 1000		541.13	1541.13	RECURRING	
		AFL		225			
FAA 2003-26-14	KIDDE AEROSPACE P/N 898052 HAND-HELD HALON FIRE EXTINGUISHERS	MOS		24-MAY-2014			NOT APPLICABLE - BY P/N 466090 INSTALLED
		HRS/MSC -					
		AFL					
FAA 2006-16-18	SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR (TAWS/RMI) UNITS APPROVED UNDER TECHNICAL STANDARD ORDER(S) C113, C151A, OR C151B - (F)INSTALL PLACARD/(G)REVISE AFM/(H)UPDATE SOFTWARE	MOS		08-OCT-2015		MANDATORY	NOT APPLICABLE - DUE TO EQUIPMENT INSTALLED
		HRS/MSC -		350.9			
		AFL		149			
FAA 2006-18-08	GOODYEAR AVIATION TIRES - PART NUMBER 217K22-1 - INSPECTION TO DETERMINE SERIAL NUMBER (S/N), AND REPLACEMENT	MOS		24-MAY-2014		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
		HRS/MSC -					
		AFL					
FAA 2006-19-04	HONEYWELL RCZ-833J/K, -851J/K, AND - 854J COMMUNICATION (COM) UNITS, EQUIPPED WITH XS-852E/F MODE S TRANSPONDERS; AND HONEYWELL XS-856A/B AND -857A MODE S TRANSPONDERS; INSTALLED ON BUT NOT LIMITED TO CERTAIN TRANSPORT CATEGORY AIRPLANES	MOS		24-MAY-2014			NOT APPLICABLE - DUE TO COMPONENTS NOT INSTALLED ON THIS A/C
		HRS/MSC -					
		AFL					
FAA 2007-26-11	INTERTECHNIQUE ZODIAC AIRCRAFT SYSTEMS, OXYGEN RESERVE CYLINDERS - REMOVE ANY AFFECTED OXYGEN RESERVE CYLINDER BEFORE FUTHER FLIGHT	MOS		08-OCT-2015		MANDATORY	NOT APPLICABLE - DUE TO EQUIPMENT INSTALLED
		HRS/MSC -		350.9			
		AFL		149			
FAA 2008-22-01	VARIOUS TRANSPORT CATEGORY AIRPLANES EQUIPPED WITH AUXILIARY FUEL TANKS INSTALLED IN ACCORDANCE WITH CERTAIN SUPPLEMENTAL TYPE CERTIFICATES	MOS		08-OCT-2015		MANDATORY	NOT APPLICABLE - DUE TO EQUIPMENT INSTALLED
		HRS/MSC -		350.9			
		AFL		149			
FAA 2009-05-08	TRIMBLE OR FREEFLIGHT SYSTEMS 2101 I/O APPROACH PLUS GLOBAL POSITIONING SYSTEM (GPS) NAVIGATION SYSTEMS	MOS		08-OCT-2015		MANDATORY	NOT APPLICABLE - DUE TO EQUIPMENT INSTALLED
		HRS/MSC -		350.9			
		AFL		149			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2009-08-01	TO PREVENT A SHIFT IN THE FMS COMPUTED POSITION					MANDATORY	NOT APPLICABLE - DUE TO EQUIPMENT INSTALLED
		MOS		08-OCT-2015			
		HRS/MSC -		350.9			
		AFL		149			
FAA 2009-13-09	MICROTURBO SA SAPHIR 2 MODEL 016 AUXILIARY POWER UNITS					MANDATORY	NOT APPLICABLE - DUE TO EQUIPMENT INSTALLED
		MOS		08-OCT-2015			
		HRS/MSC -		350.9			
		AFL		149			
FAA 2009-15-03	INSPECTION AND LUBRICATION OF ALL PART NUMBER (P/N) GT411-3800-5 AND GT411-3800-7 PCU ATTACHMENT JOINTS					MANDATORY	NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER
		MOS		24-MAY-2014			
19-AUG-2009		HRS/MSC -					
		AFL					
FAA 2009-15-03 PARA (G)(1)	FOR INSPECTION AND LUBRICATION OF ALL PART NUMBER (P/N) GT411-3800-5 AND GT411-3800-7 PCU ATTACHMENT JOINTS AIRPLANES IDENTIFIED IN PARAGRAPH (F)					MANDATORY	NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER
		MOS		24-MAY-2014			
19-AUG-2009		HRS/MSC -					
		AFL					
FAA 2009-15-03 PARA (G)(2)	FOR INSPECTION AND LUBRICATION OF ALL PART NUMBER (P/N) GT411-3800-5 AND GT411-3800-7 PCU ATTACHMENT JOINTS AIRPLANES NOT IDENTIFIED IN PARAGRAPH (F)					MANDATORY	NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER
		MOS		24-MAY-2014			
19-AUG-2009		HRS/MSC -					
		AFL					
FAA 2009-21-03	HAMILTON SUNDSTRAND POWER SYSTEMS T- 62T-46C12 AUXILIARY POWER UNITS					MANDATORY	NOT APPLICABLE - DUE TO EQUIPMENT INSTALLED
		MOS		08-OCT-2015			
		HRS/MSC -		350.9			
		AFL		149			
FAA 2009-21-10 R1	AVOX SYSTEMS AND B/E AEROSPACE OXYGEN CYLINDER ASSEMBLIES, AS INSTALLED ON VARIOUS TRANSPORT AIRPLANES						NOT APPLICABLE - PER P/N GC481-0090-5 INSTALLED AT TIME OF DELIVERY
		MOS		24-MAY-2014			
		HRS/MSC -					
		AFL					
FAA 2010-01-03	PORTABLE HALON 1211 (BCF) FIRE EXTINGUISHERS MANUFACTURED BY FIRE FIGHTING ENTERPRISES LIMITED, IDENTIFIED IN TABLE 1 OF THIS AD.						NOT APPLICABLE - BY FIRE EXTINGUISHER S/N
		MOS		24-MAY-2014			
		HRS/MSC -					
		AFL					
FAA 2010-04-16	SICLI TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS						NOT APPLICABLE - BY MANUFACTURER
		MOS		24-MAY-2014			
		HRS/MSC -					
		AFL					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2010-07-02	AIRCRAFT EQUIPPED WITH HONEYWELL PRIMUS II RNZ-850()/-851() INTEGRATED NAVIGATION UNITS					MANDATORY	NOT APPLICABLE - DUE TO EQUIPMENT INSTALLED
		MOS		09-OCT-2015			
		HRS/MSC -		350.9			
		AFL		149			
FAA 2010-07-02 PARA (H) (AMOC)	REVISE THE LIMITATIONS SECTION OF THE AFM TO INCLUDE "FLIGHT LIMITATIONS"					MANDATORY	NOT APPLICABLE - DUE TO EQUIPMENT INSTALLED
		MOS		09-OCT-2015			
		HRS/MSC -		350.9			
		AFL		149			
FAA 2010-07-02 PARA (L) (AMOC)	INSPECTION TO DETERMINE MOD LEVEL TO ENSURE THAT THE NRM IS AT MOD T CONFIGURATION					MANDATORY	NOT APPLICABLE - DUE TO EQUIPMENT INSTALLED
		MOS		09-OCT-2015			
		HRS/MSC -		350.9			
		AFL		149			
FAA 2010-09-04	HONEYWELL - TO PROVIDE THE FLIGHT CREW WITH PROCEDURES TO RECOVER FROM OR WORK AROUND SOFTWARE ANOMALIES DURING FLIGHT					MANDATORY	NOT APPLICABLE - DUE TO EQUIPMENT INSTALLED
		MOS		08-OCT-2015			
		HRS/MSC -		350.9			
		AFL		149			
FAA 2010-11-05	AVOX SYSTEMS AND B/E AEROSPACE OXYGEN CYLINDERS					MANDATORY	NOT APPLICABLE - DUE TO EQUIPMENT INSTALLED
		MOS		08-OCT-2015			
		HRS/MSC -		350.9			
		AFL		149			
FAA 2010-12-19	HONEYWELL - TO PREVENT FUEL LEAKAGE IN THE APU COMPARTMENT					MANDATORY	NOT APPLICABLE - DUE TO EQUIPMENT INSTALLED
		MOS		08-OCT-2015			
		HRS/MSC -		350.9			
		AFL		149			
FAA 2010-23-08	INSPECT TO DETERMINE THE SERIAL NUMBER OF THE INSTALLED RAM AIR TURBINE (RAT)					MANDATORY	NOT APPLICABLE - PARAGRAPHS (G), (H) AND (I) NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. PARAGRAPH (J) COMPLIED WITH
		MOS		22-SEP-2013			
14-DEC-2010		HRS/MSC -					
		AFL					
FAA 2011-01-09	B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE) PART NUMBER 119003-11 INSTALLED ON VARIOUS TRANSPORT AIRPLANES					MANDATORY	NOT APPLICABLE - NOT INSTALLED ON THIS A/C
		MOS		24-MAY-2014			
09-FEB-2011		HRS/MSC -					
		AFL					
FAA 2011-01-10	RELOCATE THE NO. 2 AND NO. 3 HYDRAULIC SYSTEM LINES IN THE WING AUXILIARY SPAR AREA ON THE LEFT SIDE OF THE AIRCRAFT, AND MODIFY THE LEFT WING RIB AND LEFT AND RIGHT DEBRIS SHIELDS					MANDATORY	NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER
		MOS		24-MAY-2014			
09-FEB-2011		HRS/MSC -					
		AFL					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2011-14-08	B/E AEROSPACE FLOW PASSENGER OXYGEN MASK ASSEMBLY P/N 174006-(), 174080-(), 174095-(), 174085-(), 174097-(), 174098-()	MOS HRS/MSC - AFL		24-MAY-2014			NOT APPLICABLE - BY MANUFACTURER
FAA 2011-21-08	SICMA AERO SEAT PASSENGER SEAT ASSEMBLIES INSTALLED ON VARIOUS TRANSPORT CATEGORY AIRPLANES	MOS HRS/MSC - AFL		08-OCT-2015 350.9 149		MANDATORY	NOT APPLICABLE - PER MANUFACTURER OF INSTALLED EQUIPMENT
FAA 2012-02-08	AVIATION COMMUNICATION & SURVEILLANCE SYSTEMS (ACSS) TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS	MOS HRS/MSC - AFL		08-OCT-2015 350.9 149	13-MAR-2012	MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED
FAA 2012-03-05	DEFORMATION AT THE NECK OF THE PRESSURE REGULATOR BODY ON CERTAIN OXYGEN CYLINDER AND REGULATOR ASSEMBLIES (CRA)	MOS HRS/MSC - AFL		24-MAY-2014	23-MAR-2012	MANDATORY	NOT APPLICABLE - BY COMPONENT S/N INSTALLED
FAA 2012-03-05 PARA (G)	INSPECTION DEFORMATION AT THE NECK OF THE PRESSURE REGULATOR BODY ON CERTAIN OXYGEN CYLINDER AND REGULATOR ASSEMBLIES (CRA) OF OXYGEN PRESSURE REGULATORS	MOS HRS/MSC - AFL		24-MAY-2014	23-MAR-2012	MANDATORY	NOT APPLICABLE - BY COMPONENT S/N INSTALLED
FAA 2012-03-05 PARA (G)(1)	REPLACE DEFORMATION AT THE NECK OF THE PRESSURE REGULATOR BODY ON CERTAIN OXYGEN CYLINDER AND REGULATOR ASSEMBLIES (CRA) THE AFFECTED OXYGEN CRA	MOS HRS/MSC - AFL		24-MAY-2014	23-MAR-2012	MANDATORY	NOT APPLICABLE - BY COMPONENT S/N INSTALLED
FAA 2012-11-09	DEACTIVATION OF CHEMICAL OXYGEN SYSTEM INSTALLED IN LAVATORIES (SUPERSEDES AD 2011-04-09)	MOS HRS/MSC - AFL		24-MAY-2014			NOT APPLICABLE - THIS AD SUPERSEDES AD 2011-04-09
FAA 2012-17-01	GOODYEAR AVIATION TIRES	MOS HRS/MSC - AFL		08-OCT-2015 350.9 149		AIRWORTHINESS DIRECTIVE	NOT APPLICABLE - PER PART NUMBERS OF INSTALLED EQUIPMENT
FAA 2014-03-05	ICE AND RAIN PROTECTION - MODIFY THE AIR DATA PROBES AND SENSORS	MOS HRS/MSC - AFL		24-MAY-2014		MANDATORY	NOT APPLICABLE - BY EFFECTIVITY



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2014-18-01	NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION					MANDATORY	NOT APPLICABLE - PER PART NUMBER OF INSTALLED EQUIPMENT
14-OCT-2014		MOS HRS/MSC - AFL		08-OCT-2015 350.9 149			
FAA 2014-20-03	FIRE PROTECTION - INSPECT TO DETERMINE THE PART NUMBER AND FOR ALL AFFECTED CHECK TEE FITTINGS MEASURE FOR CORRECT DEPTH, AND REPLACE IF NECESSARY					MANDATORY	NOT APPLICABLE - BY A/C SERIAL NUMBER
05-NOV-2014		DAYS HRS/MSC - AFL		(EFF)			
FAA 2014-21-08	OXYGEN - REPLACE LANYARDS HAVING PART NUMBERS (P/N) B431564-503 AND -505 FOR ALL PASSENGER OXYGEN DISPENSING UNITS, WITH LANYARDS HAVING P/N B431564-507					MANDATORY	NOT APPLICABLE - BY SUPPLEMENTAL TYPE CERTIFICATE STC INSTALLED
02-DEC-2014		MOS HRS/MSC - AFL		(EFF)			
FAA 2015-08-07	OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESES					MANDATORY	NOT APPLICABLE - BY A/C S/N AND OXYGEN MASK PART NUMBER
16-JUN-2015		MOS HRS/MSC - (s) AFL		09-OCT-2015 350.9 149			
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-241, REVISION 3, DATED JUNE 23, 2011					MANDATORY	NOT APPLICABLE - BY A/C S/N AND OXYGEN MASK PART NUMBER
16-JUN-2015		MOS HRS/MSC - (s) AFL		09-OCT-2015 350.9 149			
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PARAGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESES					MANDATORY	NOT APPLICABLE - BY A/C S/N AND OXYGEN MASK PART NUMBER
16-JUN-2015		MOS HRS/MSC - (s) AFL		09-OCT-2015 350.9 149			
FAA 2015-17-05	FLIGHT CONTROLS - INSPECTING FOR CORRECT CLEARANCE AND REWORK IF NECESSARY, AND, FOR CERTAIN OTHER AIRPLANES, INSTALLING A COVER FOR THE AILERON PULLEY ASSEMBLY					MANDATORY	NOT APPLICABLE - AD IS N/A BY A/C S/N
29-SEP-2015		MOS HRS/MSC - AFL		09-OCT-2015 350.9 149			
FAA 2015-17-05 PARA (G)	INSTALL A COVER FOR THE NO. 1 AILERON PULLEY, INCLUDING DOING A GVI FOR CORRECT CLEARANCE AND REWORK AS APPLICABLE					MANDATORY	NOT APPLICABLE - AD IS N/A BY A/C S/N
29-SEP-2015		MOS HRS/MSC - AFL		09-OCT-2015 350.9 149			
FAA 2015-17-05 PARA (H)	ACCOMPLISH A GVI FOR CORRECT CLEARANCE AND, REWORK, AS APPLICABLE					MANDATORY	NOT APPLICABLE - AD IS N/A BY A/C S/N
29-SEP-2015		MOS HRS/MSC - AFL		09-OCT-2015 350.9 149			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2015-17-05 PARA (I)	DO THE RE-IDENTIFICATION OF THE OVERWING PANELS					MANDATORY	NOT APPLICABLE - AD IS N/A BY A/C S/N
29-SEP-2015		MOS HRS/MSC - AFL		09-OCT-2015 350.9 149			
FAA 2016-10-06	NAVIGATION - GENERAL VISUAL INSPECTION OF THE NETWORK INTERFACE INSTALLATION BETWEEN THE IMS AND CES TO DETERMINE IF PINS ARE PRESENT AT POSITIONS 25, 27, 48, 50 AND DISCONNECT THE INSTALLATION IF ANY PINS ARE PRESENT					MANDATORY	COMPLIED WITH - 2016-10-06 WAS PREVIOUSLY COMPLETED BY INCORPORATION OF SB 700-46-5005 REV.2 DATED 6/18/15 BY JET AVIATION ON 10/9/15 ACTT 350.8 ACTC 149 REF W.O NO.15942 & 411903
23-JUN-2016		MOS HRS/MSC - (s) AFL		10-JAN-2018 707.58 297			
FAA 2016-11-20	OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE - PER PBE PN INSTALLED
15-JUL-2016		MOS HRS/MSC - AFL		01-NOV-2016 541.13 225			
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A..1 SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE
15-JUL-2016		MOS HRS/MSC - AFL		01-NOV-2016 541.13 225			
FAA 2016-11-20 PARA (H)(1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE - PER PBE PN INSTALLED
15-JUL-2016		MOS HRS/MSC - (s) AFL		01-NOV-2016 541.13 225			
FAA 2016-11-20 PARA (H)(2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE - PER PBE PN INSTALLED
15-JUL-2016		MOS HRS/MSC - AFL		01-NOV-2016 541.13 225			
FAA 2016-15-06	OXYGEN - REPLACEMENT OF FLEXIBLE RELIEF HOSES FOR THE CREW OXYGEN BOTTLES WITH NEW METAL DESIGN RELIEF HOSES					MANDATORY	COMPLIED WITH - COMPLIED WITH BY VERIFYING SERVICE BULLETIN 700-35-5001 R1 WAS PREVIOUSLY COMPLIED WITH ON 10/9/15.
08-SEP-2016		MOS HRS/MSC - (s) AFL		10-NOV-2016 541.13 225			
FAA 2016-15-06 PARA (G)	INCORPORATE BOMBARDIER MODSUM R700T400542 BY REPLACING THE OXYGEN FLEXIBLE RELIEF HOSES FOR THE CREW OXYGEN BOTTLES WITH NEW METAL DESIGN HOSES					MANDATORY	COMPLIED WITH - PCW SB 700-35-5001 REV 1 - OCT 2015
08-SEP-2016		MOS HRS/MSC - AFL		16-NOV-2016 541.13 225			
FAA 2016-17-16 PARA (G)	REVISE THE MAINTENANCE OR INSPECTION PROGRAM AS APPLICABLE					MANDATORY	COMPLIED WITH
05-OCT-2016		DAYS HRS/MSC - AFL		10-NOV-2016 541.13 225			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2017-14-15	FLIGHT CONTROLS - A REVISION TO THE MAINTENANCE OR INSPECTION PROGRAM TO INCORPORATE CERTIFICATION MAINTENANCE REQUIREMENT TASKS THAT INTRODUCE FUNCTIONAL TESTS OF THE CONTROL CABLE TENSION					MANDATORY	COMPLIED WITH
31-AUG-2017		MOS		11-JAN-2018			
		HRS/MSC	- (s)	707.58			
		AFL		297			
FAA 2017-14-15 PARA (G)	REVISE THE MAINTENANCE OR INSPECTION PROGRAM					MANDATORY	COMPLIED WITH
31-AUG-2017		DAYS		11-JAN-2018			
		HRS/MSC	-	707.58			
		AFL		297			
FAA 2017-14-15 PARA (H)	ACCOMPLISH CERTIFICATION MAINTENANCE REQUIREMENT (CMR) TASKS					MANDATORY	COMPLIED WITH - CMR TASKS CARRIED OUT NOV 2016
31-AUG-2017		DAYS		11-JAN-2018			
		HRS/MSC	-	707.58			
		AFL		297			
FAA 2017-18-12	OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES					MANDATORY	NOT APPLICABLE - S/N E1300805 INSTALLED IN WARDROBE, S/N E1302194 INSTALLED IN COCKPIT, AD DOES NOT APPLY
16-OCT-2017		MOS		19-DEC-2017			
		HRS/MSC	- (s)	684.7			
		AFL		292			
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED
16-OCT-2017		MOS		19-DEC-2017			
		HRS/MSC	- (s)	684.7			
		AFL		292			
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED
16-OCT-2017		MOS		19-DEC-2017			
		HRS/MSC	- (s)	684.7			
		AFL		292			
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED
16-OCT-2017		MOS		19-DEC-2017			
		HRS/MSC	-	684.7			
		AFL		292			
FAA 2017-19-11	FLIGHT CONTROLS - AN OPERATIONAL TEST OF THE FCU BACK-UP MODULES AND REPAIR (IF ANY FCU FAILS ANY OPERATIONAL TEST REQUIRED BY THIS AD)					MANDATORY	COMPLIED WITH
23-OCT-2017		DAYS		11-JAN-2018			
		HRS/MSC	-	707.58			
		AFL		297			
FAA 2017-22-14	NAVIGATION - INSTALLATION OF THE TSSA-4100 FLS UPGRADES ON THE ROCKWELL COLLINS, INC. TSS-4100 TRAFFIC SURVEILLANCE SYSTEM PROCESSING UNITS					MANDATORY	COMPLIED WITH - UPGRADED SOFTWARE TO P/N:810-0052-013 S/N:4DLXG7.
20-DEC-2017		MOS		23-MAR-2018			
		HRS/MSC	-	746.13			
		AFL		311			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2018-09-15	ENGINE - REAR MOUNT RETAINING BOLT FAILURE					MANDATORY	COMPLIED WITH - PCW SB 700-71-5002 & 700-71-5003
15-JUN-2018		MOS		25-MAY-2019			
		HRS/MSC - (s)		879.42			
		AFL		365			
FAA 2018-09-15 PARA (G)	INSPECTION FOR DISCREPANCIES OF THE ENGINE REAR MOUNT ASSEMBLIES (INCLUDING MISSING OR BROKEN BOLTS, MISSING NUTS, INCORRECT TORQUE VALUES, AND AN INCORRECT GAP BETWEEN THE BUSHING AND WASHER) AND REPLACE MISSING PARTS AND CORRECT NONCOMPLIANT GAPS AND BOLT TORQUE (IF ANY DISCREPANCY IS DETECTED DURING THE INSPECTION REQUIRED BY PARA (G)) (THIS PARA RESTATES THE REQUIREMENTS OF PARA (G) OF AD 2016-25-18, WITH NO CHANGES)					MANDATORY	COMPLIED WITH - PARA(N) CREDIT FOR PREVIOUS ACTION PARA (G) & (H). PCW SB 700-71-5002 & 700-71-5003
15-JUN-2018		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
FAA 2018-09-15 PARA (J)	MEASURE THE GAPS BETWEEN THE APPLICABLE SHOULDERED BUSHING FITTED ON THE MOUNT BEAM AND THE WASHER; AND BETWEEN THE APPLICABLE ENGINE RING LUG AND THE HEAD OF THE MOUNT PIN TO DETERMINE IF THE GAPS ARE WITHIN ACCEPTABLE LIMITS AND REPAIR (IF ANY GAP IS DETECTED, DURING ANY MEASUREMENT REQUIRED BY PARA (J) / (K), THAT IS NOT WITHIN THE APPLICABLE LIMITS SPECIFIED IN THE SERVICE INFORMATION SPECIFIED IN PARAS (J)(1) THRU (J)(4))					MANDATORY	NOT APPLICABLE - PART PARA(J) NOT APPLICABLE DUE TO PART A OF SB 700-71-5002 P.C.W PARA (K) SEE LOG ENTRY DATED NOV /16/2016.
15-JUN-2018		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
FAA 2018-09-15 PARA (K)	REPLACE THE NUTS HAVING P/N AS54365 AND THE BOLTS HAVING P/N AS54020 AND AS54002 IN THE ENGINE REAR MOUNT ASSEMBLY WITH NEW NUTS AND NEW BOLTS; AND DO THE GAP MEASUREMENT TO DETERMINE IF THE GAP IS WITHIN ACCEPTABLE LIMITS AND REPAIR (IF ANY GAP IS DETECTED, DURING ANY MEASUREMENT REQUIRED BY PARA (J) / (K), THAT IS NOT WITHIN THE APPLICABLE LIMITS SPECIFIED IN THE SERVICE INFORMATION SPECIFIED IN PARAS (J)(1) THRU (J)(4))					MANDATORY	COMPLIED WITH - COMPLIED WITH BY SB 700-71-5003 BASIC WAS P.C.W SEE LOG ENTRY DATED SEE LOG ENTRY DATED JAN/12/2018.
15-JUN-2018		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
FAA 2018-20-20	FLIGHT CONTROLS - ELEVATOR CONTROL SYSTEM BRACKET CRACKING					MANDATORY	COMPLIED WITH
20-NOV-2018		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
FAA 2018-22-08	FIRE PROTECTION - VISUAL INSPECTION OF CONNECTIONS BETWEEN THE FIREX SQUIB WIRE HARNESS CONNECTORS AND FIREX BOTTLE CONNECTORS, AND CORRECTIVE ACTION IF NECESSARY					MANDATORY	COMPLIED WITH
10-DEC-2018		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
FAA 2018-25-07	FUSELAGE - BELLY FAIRING - BLOCKED DRAINAGE HOLES					MANDATORY	COMPLIED WITH
15-JAN-2019		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
FAA 2019-03-22	LANDING GEAR - SAFETY DEVICE MODIFICATION AT NOSE GEAR RETRACTION ACTUATOR TO MAIN FITTING JOINT					MANDATORY	COMPLIED WITH
15-APR-2019		MOS		25-MAY-2019			
		HRS/MSC - (s)		879.42			
		AFL		365			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2019-03-22 PARA (G)	REVISE THE EXISTING MAINTENANCE OR INSPECTION PROGRAM, AS APPLICABLE AND ACCOMPLISH THE TASKS SPECIFIED IN AWL					MANDATORY	COMPLIED WITH
15-APR-2019		DAYS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
FAA 2019-03-22 PARA (H)(1)	PERFORM A GVI FOR DAMAGE OF THE COTTER PIN RETAINING THE BOLT THAT SECURES THE NLG RETRACTION ACTUATOR TO THE NLG STRUT, AND A GVI OF THE MODIFICATION NUMBER SHOWN ON THE IDENTIFICATION PLATE FOR THE NLG STRUT, AND, IF APPLICABLE, MARK THE CORRECT MODIFICATION NUMBER ON THE IDENTIFICATION PLATE OF THE NLG STRUT AND PERFORM THE MODIFICATION OF THE NLG RETRACTION ACTUATOR HARDWARE (IF DAMAGE TO THE COTTER PIN IS PRESENT)					MANDATORY	COMPLIED WITH
15-APR-2019		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
FAA 2019-12-02	ELECTRICAL POWER - VARIABLE FREQUENCY GENERATOR HARNESS LOW CLEARANCE TO HYDRAULIC/FUEL LINES					MANDATORY	COMPLIED WITH - PWC BY SB 700-24-5014 R02 AT BAS-FLL ON 25/MAY/2019 W.O# 214767
12-AUG-2019		MOS		22-APR-2020			
		HRS/MSC -		956.4			
		AFL		400			
FAA 2020-03-21	LANDING GEAR - TRAILING ARM ASSEMBLY AXLE BORE CORROSION					MANDATORY	COMPLIED WITH - PWC BY SB 700-32-5016 AT BAS-FLL ON 25/MAY/2019 W.O# 214767
12-MAR-2020		MOS		22-APR-2020			
		HRS/MSC -		956.4			
		AFL		400			
FAA 2020-03-21 PARA (H) LH	INSPECT THE LEFT HAND MLG TRAILING ARM ASSEMBLIES TO DETERMINE IF AN AFFECTED MLG TRAILING ARM ASSEMBLY IS INSTALLED					MANDATORY	COMPLIED WITH - PWC BY SB 700-32-5016 PART A AT BAS-FLL ON 25/MAY/2019 W.O# 214767
12-MAR-2020		MOS		22-APR-2020			
		HRS/MSC -		956.4			
		AFL		400			
FAA 2020-03-21 PARA (H) RH	INSPECT THE RIGHT HAND MLG TRAILING ARM ASSEMBLIES TO DETERMINE IF AN AFFECTED MLG TRAILING ARM ASSEMBLY IS INSTALLED					MANDATORY	COMPLIED WITH - PWC BY SB 700-32-5016 PART A AT BAS-FLL ON 25/MAY/2019 W.O# 214767
12-MAR-2020		MOS		22-APR-2020			
		HRS/MSC -		956.4			
		AFL		400			
FAA 2020-03-21 PARA (I)&(J) LH	ACCOMPLISH A DETAILED INSPECTION FOR SURFACE FINISH DISCREPANCIES ON THE INNER DIAMETER OF THE AFFECTED MLG TRAILING ARM ASSEMBLY AXLE BORE (IF, DURING THE INSPECTION OR REVIEW REQUIRED BY PARA (H), IT IS DETERMINED THAT AN AFFECTED MLG TRAILING ARM ASSEMBLY IS INSTALLED) AND ACCOMPLISH ALL APPLICABLE CORRECTIVE ACTIONS						NOT APPLICABLE - PER SN INSTALLED
12-MAR-2020		MOS		22-APR-2020			
		HRS/MSC -		956.4			
		AFL		400			
FAA 2020-03-21 PARA (I)&(J) RH	ACCOMPLISH A DETAILED INSPECTION FOR SURFACE FINISH DISCREPANCIES ON THE INNER DIAMETER OF THE AFFECTED MLG TRAILING ARM ASSEMBLY AXLE BORE (IF, DURING THE INSPECTION OR REVIEW REQUIRED BY PARA (H), IT IS DETERMINED THAT AN AFFECTED MLG TRAILING ARM ASSEMBLY IS INSTALLED) AND ACCOMPLISH ALL APPLICABLE CORRECTIVE ACTIONS						NOT APPLICABLE - PER SN INSTALLED
12-MAR-2020		MOS		22-APR-2020			
		HRS/MSC -		956.4			
		AFL		400			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2020-03-21 PARA (K)	REPLACE THE PRIMER AND PAINT AND APPLY THE CORROSION PREVENTIVE COMPOUND ON THE INNER DIAMETER OF THE AXLE BORE ON ALL AFFECTED MLG TRAILING ARM ASSEMBLIES					MANDATORY	NOT APPLICABLE - PER SN INSTALLED
12-MAR-2020		MOS		22-APR-2020			
		HRS/MSC	-	956.4			
		AFL		400			
FAA 2020-03-21 PARA (M)	SUBMIT A REPORT TO BOMBARDIER OF POSITIVE FINDINGS OF THE INSPECTIONS REQUIRED BY PARAGRAPHS (I) AND (J) OF THIS AD					MANDATORY	NOT APPLICABLE - PER SN INSTALLED
12-MAR-2020		DAYS		22-APR-2020			
		HRS/MSC	-(s)	956.4			
		AFL		400			
FAA 2020-05-27 PARA (G)	DETAILED VISUAL INSPECTION FOR CRACKING OF THE RUDDER QUADRANT BOX ASSEMBLY (FOR AIRPLANES THAT HAVE ACCUMULATED FEWER THAN 2,900 TOTAL FC AS OF THE EFFECTIVE DATE OF THIS AD, AND THAT HAVE NOT BEEN MODIFIED AS SPECIFIED IN PARA (I))					MANDATORY	- REF SB 700-53-5013 PCW MAY 2019 AT 365 LDGS - NEXT DUE 1365 LDGS
07-MAY-2020		MOS				RECURRING	
		HRS/MSC					
		AFL	1000		1365 M		
FAA 2020-05-27 PARA (I)	MODIFY THE RUDDER QUADRANT BOX ASSEMBLY					MANDATORY	
07-MAY-2020		MOS	60		30-MAY-2024 M		
		HRS/MSC					
		AFL	3000		3000		
FAA 2020-12-14	ELECTRICAL POWER - RAT DEPLOYMENT ACTUATOR - INSPECTION / REPLACEMENT					MANDATORY	COMPLIED WITH - SN: 0681 NOT IN TABLE 1 OF SB 700-24-5015.
08-SEP-2020		MOS		24-AUG-2020			
		HRS/MSC	-(s)	965.5			
		AFL		404			
FAA 2020-12-14 PARA (G)	INSPECTION TO DETERMINE THE SERIAL NUMBER (S/N) OF THE RAT DEPLOYMENT ACTUATOR, HAVING PART NUMBER (P/N) BZ02001-01 (GL456-1301-1)					MANDATORY	COMPLIED WITH - FOUND S/N: 0681, NOT IN TABLE 1 OF SB 700-24-5015.
08-SEP-2020		MOS		24-AUG-2020			
		HRS/MSC	-	965.5			
		AFL		404			
FAA 2020-12-14 PARA (H)	REPLACE THE RAT DEPLOYMENT ACTUATOR, HAVING P/N BZ02001-01 (GL456-1301-1), WITH AN UPGRADED PART (IF ANY RAT DEPLOYMENT ACTUATOR IS FOUND, POST PARA (G))					MANDATORY	NOT APPLICABLE - PER S/N INSTALLED IN AIRCRAFT
08-SEP-2020		MOS		24-AUG-2020			
		HRS/MSC	-(s)	965.5			
		AFL		404			
FAA 2020-12-14 PARA (I)	NO PERSON MAY INSTALL ON ANY AIRPLANE, A RAT DEPLOYMENT ACTUATOR HAVING P/N BZ02001-01 (GL456-1301-1) WITH A SERIAL NUMBER REFERRED TO IN PARAGRAPH 2.B., PART A-SPECIAL CHECK, OF THE ACCOMPLISHMENT INSTRUCTIONS, OF THE APPLICABLE BOMBARDIER SI SPECIFIED IN FIGURE 1 TO PARAS (G)(1) AND (2), (H), AND (I) OF THIS AD					MANDATORY	NOT APPLICABLE - PER S/N INSTALLED IN AIRCRAFT
08-SEP-2020		MOS		24-AUG-2020			
		HRS/MSC	-(s)	965.5			
		AFL		404			
FAA 2020-12-15	PNEUMATIC - CABIN-PRESSURE CONTROL SYSTEM - MODIFICATION/INSPECTION					MANDATORY	NOT APPLICABLE - PER S/N OF AIRCRAFT.
24-JUL-2020		MOS		29-JUL-2020			
		HRS/MSC	-(s)	960.32			
		AFL		402			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2020-12-15 PARA (G)	MEASUREMENT OF THE TRUNNION NUT TORQUE OF THE V-BAND CLAMPS					MANDATORY	NOT APPLICABLE - PER S/N OF AIRCRAFT.
24-JUL-2020		MOS		29-JUL-2020			
		HRS/MSC -		960.32			
		AFL		402			
FAA 2020-12-15 PARA (H)(1)	DO A GENERAL VISUAL INSPECTION FOR CRACKING AND DEFORMATION, FOR SAFETY VALVES WITH A V-BAND CLAMP TRUNNION NUT TORQUE OF LESS THAN 80 LBF-IN; AND PERFORM CORRECTIVE ACTIONS					MANDATORY	NOT APPLICABLE - PER S/N OF AIRCRAFT.
24-JUL-2020		MOS		29-JUL-2020			
		HRS/MSC - (s)		960.32			
		AFL		402			
FAA 2020-12-15 PARA (H)(2)	DO A MAGNIFICATION INSPECTION FOR ANY CRACKING AND DEFORMATION OF THE SAFETY VALVE AND AIRPLANE BULKHEAD FLANGE AREA, FOR SAFETY VALVES WITH A V-BAND CLAMP TRUNNION NUT TORQUE OF 80 LBF-IN OR HIGHER; PERFORM CORRECTIVE ACTIONS					MANDATORY	NOT APPLICABLE - PER S/N OF AIRCRAFT.
24-JUL-2020		MOS		29-JUL-2020			
		HRS/MSC - (s)		960.32			
		AFL		402			
FAA 2021-08-11	FLIGHT CONTROLS - ROLL CONTROL INPUT MODULES (RCIM) MAINTENANCE MANUAL / INSPECTION MANUAL INCORPORATION					MANDATORY	COMPLIED WITH - ALL MANUALS ARE UP TO DATE
27-APR-2021		DAYS		27-APR-2021			
		HRS/MSC -		994.48			
		AFL		421			
FAA 2021-10-02	FLIGHT CONTROLS - ELEVATOR CONTROL SYSTEM - VERTICAL TORQUE TUBE SEIZURE - SAND CONTAMINATION OF BEARING					MANDATORY	COMPLIED WITH
29-JUL-2021		MOS		24-NOV-2021			
		HRS/MSC - (s)		1023.57			
		AFL		435			
FAA 2021-10-02 PARA (G)	PERFORM A GENERAL VISUAL INSPECTION OF THE LEFT AND RIGHT-HAND ELEVATOR TORQUE TUBE BEARINGS FOR ANY SAND, DUST, OR CORROSION, PERFORM A FUNCTIONAL TEST OF THE ELEVATOR CONTROL SYSTEM AND ACCOMPLISH ALL APPLICABLE CORRECTIVE ACTIONS					MANDATORY	COMPLIED WITH
29-JUL-2021		MOS	63	24-NOV-2021	24-FEB-2027	RECURRING	
		HRS/MSC		1023.57			
		AFL		435			
FAA 2021-10-02 PARA (H)	SUBMIT A REPORT OF ALL FINDINGS, POSITIVE AND NEGATIVE, OF EACH OF THE FIRST THREE INSPECTIONS					MANDATORY	COMPLIED WITH
29-JUL-2021		DAYS		24-NOV-2021			
		HRS/MSC - (s)		1023.57			
		AFL		435			
FAA 2021-21-04	REDISTRIBUTION OF LOAD/STRESS ON THE MOUNT COMPONENTS					MANDATORY	COMPLIED WITH
08-DEC-2021		MOS		24-NOV-2021			
		HRS/MSC -		1023.57			
		AFL		435			
FAA 2022-11-17	FLIGHT CONTROLS - INBOARD-FLAP SUSCEPTIBILITY TO CORROSION					MANDATORY	COMPLIED WITH - AMM UPDATED 16 AUG 22, REV 43
22-JUL-2022		DAYS		16-AUG-2022			
		HRS/MSC -		1050.4			
		AFL		448			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2022-12-01 PARA (G)	DO AN INSPECTION OF THE OXYGEN HOSE ASSEMBLY TO DETERMINE IF ANY HOSE HAVING A PART NUMBER (P/N) IN THE O2C20T1 SERIES IS INSTALLED; IF P/N O2C20T1 SERIES INSTALLED OR ANY TEST FAILS, BEFORE FURTHER FLIGHT, REPLACE ALL THE OXYGEN HOSES					MANDATORY	
19-JUL-2022		MOS HRS/MSC AFL	6	(EFF)	19-JAN-2023		
FAA 2022-13-05	NAVIGATION - AIRCRAFT FLIGHT MANUAL - REVISE					MANDATORY	COMPLIED WITH - REVISION 37 POSTED 7 MARCH 2021
11-AUG-2022		DAYS HRS/MSC AFL	-	07-MAR-2021 991 418			
FAA 72-19-04	NICKEL-CADMIUM BATTERY						NOT APPLICABLE - AS PER THE EXEPTION STATEMENT WITHIN THE AD APPLICABILITY SECTION OF THE
		MOS HRS/MSC AFL		24-MAY-2014			
FAA 93-14-12	ESSEX PB&R CORPORATION PBE						NOT APPLICABLE - BY PBE MODEL
		MOS HRS/MSC AFL		24-MAY-2014			
FAA 93-24-16	PURITAN BENNET AERO SYSTEMS - PBE						NOT APPLICABLE - NOT INSTALLED ON THIS A/C
		MOS HRS/MSC AFL		24-MAY-2014			
FAA 94-06-04	EROS FULL FACE MASK						COMPLIED WITH - NOT APPLICABLE. OXYGEN MASK REGULATOR WITH DETACHABLE GOGGLES, P/N MLC20-508 /MLD20-508 INSTALLED.
		MOS HRS/MSC AFL		24-MAY-2014			
FAA 98-24-27	FIRST TECHNOLOGY FIRE AND SAFETY LTD. TOILET COMPARTMENT FIRE EXTINGUISHER. IDENTIFIED BY SERIAL AND MODEL NUMBER IN FIRST TECHNOLOGY FIRE AND SAFETY LTD. SERVICE BULLETIN (SB) NO. 26-110, REVISION 1, DATED JANUARY 1998						NOT APPLICABLE - BY INSTALLATION
		MOS HRS/MSC AFL		24-MAY-2014			
FAA 98-25-10 REV 1	AIRCRAFT BELTS INC. SEAT RESTRAINT SYSTEMS.						NOT APPLICABLE - BY SEAT BELT TYPE INSTALLED.
		MOS HRS/MSC AFL		24-MAY-2014			
TCCA CF-2008-31	ELEVATOR PCU ATTACHMENT BOLT FRACTURE - ALL PART NUMBER (P/N) GT411-3800-5 AND GT411-3800-7 PCU ATTACHMENT JOINTS						NOT APPLICABLE - DUE TO AIRCRAFT SERIAL NUMBER
		MOS HRS/MSC AFL		08-MAY-2014			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

**All Bulletins with Compliance or Due
Report Date: 01-Dec-2022**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
TCCA CF-2009-44	EMERGENCY LOCATOR TRANSMITTER						NOT APPLICABLE - BY ELT MANUFACTURER, ARTEX ELT INSTALLED.
		MOS HRS/MSC - AFL		08-MAY-2014			
TCCA CF-2010-01	RAM AIR TURBINE (RAT) - NON-CONFORMING BALANCE WASHER SCREWS						NOT APPLICABLE
16-FEB-2010		MOS HRS/MSC - AFL					
TCCA CF-2010-01 PART I	IDENTIFICATION RAM AIR TURBINE (RAT) - NON-CONFORMING BALANCE WASHER SCREWS CHECK						NOT APPLICABLE - PER AIRCRAFT SERIAL NUMBER
16-FEB-2010		MOS HRS/MSC - AFL		05-AUG-2014			
TCCA CF-2010-01 PART II	REPLACEMENT RAM AIR TURBINE (RAT) - NON-CONFORMING BALANCE WASHER SCREWS OF THE BALANCE WASHER SCREWS AND IDENTIFICATION OF THE RAT						NOT APPLICABLE - PER AIRCRAFT SERIAL NUMBER
16-FEB-2010		MOS HRS/MSC - AFL		05-AUG-2014			
TCCA CF-2010-10	HYDRAULIC SYSTEMS NUMBER 2 AND 3: DAMAGE CAUSED BY MAIN LANDING GEAR TIRE FAILURE						NOT APPLICABLE - PER AIRCRAFT SERIAL NUMBER
		MOS HRS/MSC - AFL		08-MAY-2014			
TCCA CF-2010-14	PASSENGER DOOR - TENSATOR SPRINGS FAILURE (SUPERSEDED BY TCCA AD CF-2014-39)						NOT APPLICABLE - PER AIRCRAFT SERIAL NUMBER
		MOS HRS/MSC - AFL		08-MAY-2014			
TCCA CF-2011-03 R2	SECURITY CONCERNS WITH THECHEMICAL OXYGEN GENERATORSINSTALLED IN THE LAVATORIES						NOT APPLICABLE - NO CHEMICAL OXYGEN GENERATORS INSTALLED IN LAVATORIES.
		MOS HRS/MSC - AFL		08-MAY-2014			
TCCA CF-2011-10	OXYGEN SUPPLY SYSTEM - DEFORMATION OF THE PRESSURE REGULATOR ON THE OXYGEN CYLINDER AND REGULATOR ASSEMBLY						NOT APPLICABLE - PER AIRCRAFT SERIAL NUMBER
26-MAY-2011		MOS HRS/MSC - AFL		08-MAY-2014			
TCCA CF-2012-31 R01	PASSENGER OXYGEN SYSTEM - INCORRECT LENGTH OF OXYGEN DISPENSING UNIT LANYARDS					MANDATORY	NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER
21-DEC-2012		MOS HRS/MSC - AFL		08-MAY-2014			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
TCCA CF-2012-31 REV 1	PASSENGER OXYGEN SYSTEM - INCORRECT LENGHT OF OXYGEN DISPENSING UNIT'S LANYARDS.						NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER
		MOS		08-MAY-2014			
		HRS/MSC -					
		AFL					
TCCA CF-2012-32	ICE PROTECTION SYSTEM - INABILITY TO DETECT NUMBER 2 PITOT STATIC PROBE HEATER FAILURE					MANDATORY	NOT APPLICABLE - BY A/C MODEL
		MOS		08-MAY-2014			
		HRS/MSC -					
		AFL					
TCCA CF-2013-41	FIREEX CHECK TEE FITTING - INCORRECT ASSEMBLY					MANDATORY	NOT APPLICABLE - PER AIRCRAFT SERIAL NUMBER
		MOS		08-MAY-2014			
		HRS/MSC -					
		AFL					
TCCA CF-2013-41 PART I	VERIFICATION OF THE SERIAL NUMBER					MANDATORY	NOT APPLICABLE - PER AIRCRAFT SERIAL NUMBER
		MOS		08-MAY-2014			
		HRS/MSC -					
		AFL					
TCCA CF-2013-41 PART II	INSPECTION AND REPLACEMENT OF THE CHECK TEE FITTING					MANDATORY	NOT APPLICABLE - PER AIRCRAFT SERIAL NUMBER
		MOS		08-MAY-2014			
		HRS/MSC -					
		AFL					
TCCA CF-2014-39 PART I	AMEND THE TRANSPORT CANADA APPROVED MAINTENANCE SCHEDULE BY REVISING THE REPETITIVE DISCARD TASK, TASK NUMBER 52-11-41-101					MANDATORY	COMPLIED WITH - COMPLIED WITH PART 1. PART 2 REPLACEMENT OF PASSENGER DOOR TENSATOR SPRINGS IS DUE BEFORE 650 LANDINGS.
		DAYS		10-NOV-2016			
18-NOV-2014		HRS/MSC -		541.13			
		AFL		225			
TCCA CF-2014-39 PART II	REPLACE THE PASSENGER DOOR TENSATOR SPRINGS, P/N GS321-0580-1					MANDATORY	DEFERRED - REFER TASK 52-11-41-101 - DUE AT 650 LANDINGS
		MOS		22-SEP-2016			
18-NOV-2014		HRS/MSC -					
		AFL					
TCCA CF-2015-03	DOORS - PASSENGER DOOR EXTERNAL HANDLE DETENT SEIZURE					MANDATORY	NOT APPLICABLE - BY A/C SERIAL NUMBER
		MOS		08-OCT-2015			
26-MAR-2015		HRS/MSC - (s)		350.9			
		AFL		149			
TCCA CF-2015-19	INFORMATION SYSTEMS - POTENTIAL MISLEADING NAVIGATIONAL INFORMATION					MANDATORY	COMPLIED WITH - COMPLIED WITH BY VERIFYING SERVICE BULLETIN 700-46-5005 R2 WAS PREVIOUSLY COMPLIED WITH ON 10/9/15.
		MOS		10-NOV-2016			
20-JUL-2015		HRS/MSC - (s)		541.13			
		AFL		225			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
TCCA CF-2015-25	OXYGEN - OXYGEN SYSTEM FLEXIBLE HOSE - INCORRECT BURST PRESSURE					MANDATORY	COMPLIED WITH - PCW SB 700-35-5001 R1 - OCT 2015
10-SEP-2015		MOS HRS/MSC - (s) AFL		25-MAY-2019 879.42 365			
TCCA CF-2016-06 R01	FLIGHT CONTROLS - ALERON & RUDDER CONTROL SYSTEM - CABLE TENSION RELAXATION					MANDATORY	COMPLIED WITH - COMPLIED WITH PART 1 AND PART 2
25-JUL-2016		MOS HRS/MSC - (s) AFL		10-NOV-2016 541.13 225			
TCCA CF-2016-06 R01 PART I	ACCOMPLISH TIME LIMITS / MAINTENANCE CHECKS (TLMC) - MANUAL CHANGE					MANDATORY	COMPLIED WITH - COMPLIED WITH PART 1 AND PART 2
25-JUL-2016		DAYS HRS/MSC - AFL		10-NOV-2016 541.13 225			
TCCA CF-2016-06 R01 PART II	ACCOMPLISH INSPECTION OF THE ALERON AND RUDDER CONTROL CABLE TENSION					MANDATORY	COMPLIED WITH - COMPLIED WITH PART 1 AND PART 2
25-JUL-2016		MOS HRS/MSC - AFL		10-NOV-2016 541.13 225			
TCCA CF-2016-23	ENGINE - REAR MOUNT RETAINING BOLT FAILURE					MANDATORY	COMPLIED WITH - SB 700-71-5002 REV 1
08-AUG-2016		MOS HRS/MSC - AFL		02-NOV-2016 541.13 225			
TCCA CF-2016-23 R01	ENGINE - REAR MOUNT RETAINING BOLT FAILURE					MANDATORY	COMPLIED WITH - C/W BY ACCOMPLISHMENT OF SB 700-71-5002 REV.1 AND SB 700-71-5003 BASIC.PREVIOUSLY COMPLIED WITH.
06-MAR-2017		MOS HRS/MSC - (s) AFL		23-MAR-2018 746.13 311			
TCCA CF-2016-23 R01 PART I	INSPECTION OF THE ENGINE REAR MOUNT ASSEMBLIES					MANDATORY	COMPLIED WITH - C/W BY ACCOMPLISHMENT OF SB 700-71-5002 REV.1 AND SB 700-71-5003 BASIC.PREVIOUSLY COMPLIED WITH.
06-MAR-2017		MOS HRS/MSC - AFL		23-MAR-2018 746.13 311			
TCCA CF-2016-23 R01 PART II	INSPECTION AND REPLACEMENT OF THE ENGINE REAR MOUNT ASSEMBLY HARDWARE					MANDATORY	COMPLIED WITH - C/W BY ACCOMPLISHMENT OF SB 700-71-5002 REV.1 AND SB 700-71-5003 BASIC.PREVIOUSLY COMPLIED WITH.
06-MAR-2017		MOS HRS/MSC - AFL		23-MAR-2018 746.13 311			
TCCA CF-2017-31	FUSELAGE - REPLACEMENT OF ATTACHMENTS FOR BELLY FAIRING ACCESS PANELS					MANDATORY	COMPLIED WITH - TCCA AD CF-2017-31 FOUND PREVIOUSLY COMPLIED WITH.
06-OCT-2017		MOS HRS/MSC - AFL		23-MAR-2018 746.13 311			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
TCCA CF-2017-32	FLIGHT CONTROLS - ELEVATOR CONTROL SYSTEM BRACKET CRACKING					MANDATORY	COMPLIED WITH - SB 700-27-5009 REV 1 C/W
10-OCT-2017		MOS		23-MAR-2018			
		HRS/MSC -		746.13			
		AFL		311			
TCCA CF-2018-05	LANDING GEAR - SAFETY DEVICE MODIFICATION AT NOSE GEAR RETRACTION ACTUATOR TO MAIN FITTING JOINT					MANDATORY	COMPLIED WITH - PART 1 PREVIOUSLY C/W ON 15-FEB-2018. PART II COMPLIED WITH BY SB 700-32-5011 REV.1 PERFORMED ON OCTOBER 9,2015.NO FURTHER ACTION REQUIRED
06-FEB-2018		MOS		23-MAR-2018			
		HRS/MSC - (s)		746.13			
		AFL		311			
TCCA CF-2018-05 PART I	TIME LIMITS/MAINTENANCE CHECKS (TLMC) - MANUAL CHANGE					MANDATORY	COMPLIED WITH - REQUIRED REVISIONS PREVIOUSLY INCORPORATED INTO TLMC, PART II DUE 08 AUG 2018
06-FEB-2018		DAYS		15-FEB-2018			
		HRS/MSC -		740.6			
		AFL		308			
TCCA CF-2018-05 PART II	VISUAL INSPECTION AND CONDITION-DEPENDENT MODIFICATION					MANDATORY	COMPLIED WITH - C/W BY SB 700-32-5011 REV.1
06-FEB-2018		MOS		23-MAR-2018			
		HRS/MSC -		746.13			
		AFL		311			
TCCA CF-2018-08 R01	FIRE PROTECTION - ENGINE FIRE EXTINGUISHERS' SQUIB CONNECTOR WIRING LENGTH DISCREPANCY					MANDATORY	COMPLIED WITH - C/W BY COMPLETIG SB 700-26-5003 R1.NO FURTHER ACTION REQUIRED.
12-MAR-2018		MOS		23-MAR-2018			
		HRS/MSC -		746.13			
		AFL		311			
TCCA CF-2018-14	FUSELAGE - BELLY FAIRING - BLOCKED DRAINAGE HOLES					MANDATORY	COMPLIED WITH - SB 700-53-5010 BASIC PREVIOUSLY COMPLIED WITH
15-MAY-2018		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
TCCA CF-2018-22	ELECTRICAL POWER - VARIABLE FREQUENCY GENERATOR HARNESS LOW CLEARANCE TO HYDRAULIC/FUEL LINES					MANDATORY	COMPLIED WITH - INCORPORATION OF SB 700-24-5014 REV 02
16-AUG-2018		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
TCCA CF-2019-11	AFT FUSELAGE - RUDDER QUADRANT SUPPORT CHANNEL CRACKING					MANDATORY	COMPLIED WITH
05-APR-2019		MOS		25-MAY-2019			
		HRS/MSC - (s)		879.42			
		AFL		365			
TCCA CF-2019-33	LANDING GEAR - TRAILING ARM ASSEMBLY AXLE BORE CORROSION					MANDATORY	COMPLIED WITH - COMPLIED WITH PART I ONLY, PARTS II, III & IV ARE NOT APPLICABLE PER SN INSTALLED
27-SEP-2019		MOS		05-FEB-2020			
		HRS/MSC - (s)		933.42			
		AFL		390			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
TCCA CF-2019-33 PART I	INSPECTION OF MLG TRAILING ARM ASSEMBLY P/N AND SERIAL NUMBER					MANDATORY	COMPLIED WITH - L/H P/N: 21410-107, S/N: 12HDK01192; R/H P/N: 21410-107, S/N: 12HDK01184, CURRENTLY INSTALLED S/N'S ARE NOT IN APPENDIX 4 TABLE 1 OF THIS AD.
27-SEP-2019		MOS HRS/MSC - AFL		05-FEB-2020 933.42 390			
TCCA CF-2019-33 PART II	FIRST INSPECTION OF THE MLG TRAILING ARM ASSEMBLY SURFACE FINISH						NOT APPLICABLE - PER SERIAL NUMBERS INSTALLED
27-SEP-2019		MOS HRS/MSC - (s) AFL		05-FEB-2020 933.42 390			
TCCA CF-2019-33 PART III	SECOND INSPECTION OF THE MLG TRAILING ARM ASSEMBLY SURFACE FINISH						NOT APPLICABLE - PER SERIAL NUMBERS INSTALLED
27-SEP-2019		MOS HRS/MSC - (s) AFL		05-FEB-2020 933.42 390			
TCCA CF-2019-33 PART IV	PRIMER AND PAINT REPLACEMENT ON THE MLG TRAILING ARM ASSEMBLY AXLE BORE INNER DIAMETER						NOT APPLICABLE - PER SERIAL NUMBERS INSTALLED
27-SEP-2019		MOS HRS/MSC - (s) AFL		05-FEB-2020 933.42 390			
TCCA CF-2019-33 R01	LANDING GEAR - TRAILING ARM ASSEMBLY AXLE BORE CORROSION					MANDATORY	COMPLIED WITH - COMPLIED WITH PART I ONLY, PARTS II, III & IV ARE NOT APPLICABLE PER SN INSTALLED.
06-FEB-2020		MOS HRS/MSC - (s) AFL		05-FEB-2020 933.42 390			
TCCA CF-2019-33 R01 PART I	INSPECTION OF MLG TRAILING ARM ASSEMBLY P/N AND SERIAL NUMBER					MANDATORY	COMPLIED WITH - L/H P/N: 21410-107, S/N: 12HDK01192; R/H P/N: 21410-107, S/N: 12HDK01184, CURRENTLY INSTALLED S/N'S ARE NOT IN APPENDIX 4 TABLE 1 OF THIS AD.
06-FEB-2020		MOS HRS/MSC - AFL		05-FEB-2020 933.42 390			
TCCA CF-2019-33 R01 PART II	FIRST INSPECTION OF THE MLG TRAILING ARM ASSEMBLY SURFACE FINISH					MANDATORY	NOT APPLICABLE - PER SERIAL NUMBERS INSTALLED
06-FEB-2020		MOS HRS/MSC - (s) AFL		05-FEB-2020 933.42 390			
TCCA CF-2019-33 R01 PART III	SECOND INSPECTION OF THE MLG TRAILING ARM ASSEMBLY SURFACE FINISH					MANDATORY	NOT APPLICABLE - PER SERIAL NUMBERS INSTALLED
06-FEB-2020		MOS HRS/MSC - (s) AFL		05-FEB-2020 933.42 390			
TCCA CF-2019-33 R01 PART IV	PRIMER AND PAINT REPLACEMENT ON THE MLG TRAILING ARM ASSEMBLY AXLE BORE INNER DIAMETER					MANDATORY	NOT APPLICABLE - PER SERIAL NUMBERS INSTALLED
06-FEB-2020		MOS HRS/MSC - (s) AFL		05-FEB-2020 933.42 390			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
TCCA CF-2019-38	ELECTRICAL POWER - RAM AIR TURBINE (RAT) DEPLOYMENT ACTUATOR GALLING					MANDATORY	COMPLIED WITH - SB PART A - VERIFIED RAT DEPLOYMENT ACTUATOR SN 0681 INSTALLED - NO FURTHER ACTION REQUIRED
13-NOV-2019		MOS HRS/MSC - (s) AFL		17-AUG-2020 964.77 403			
TCCA CF-2019-38 PART I	CHECK THE AEROPLANE MAINTENANCE RECORDS TO DETERMINE THE SERIAL NUMBER OF THE RAT DEPLOYMENT ACTUATOR, PART NUMBER (P/N) BZ02001-01 (GL456-1301-1), INSTALLED ON THE AEROPLANE					MANDATORY	COMPLIED WITH - SB PART A - VERIFIED RAT DEPLOYMENT ACTUATOR SN 0681 INSTALLED - NO FURTHER ACTION REQUIRED
13-NOV-2019		MOS HRS/MSC - AFL		17-AUG-2020 964.77 403			
TCCA CF-2019-38 PART II	VERIFY THE SERIAL NUMBER OF THE RAT DEPLOYMENT ACTUATOR, P/N BZ02001-01 (GL456-1301-1)					MANDATORY	COMPLIED WITH - SB PART A - VERIFIED RAT DEPLOYMENT ACTUATOR SN 0681 INSTALLED - NO FURTHER ACTION REQUIRED
13-NOV-2019		MOS HRS/MSC - (s) AFL		17-AUG-2020 964.77 403			
TCCA CF-2019-38 PART III	REMOVE AND REPLACE THE RAT DEPLOYMENT ACTUATOR P/N BZ02001-01 (GL456-1301-1)					MANDATORY	NOT APPLICABLE - VERIFIED RAT DEPLOYMENT ACTUATOR SN 0681 INSTALLED - NO FURTHER ACTION REQUIRED
13-NOV-2019		MOS HRS/MSC - (s) AFL		17-AUG-2020 964.77 403			
TCCA CF-2020-16	PNEUMATICS - CABIN PRESSURE CONTROL SYSTEM - SAFETY VALVE - OVERTORQUE					MANDATORY	NOT APPLICABLE - PER S/N OF AIRCRAFT.
29-MAY-2020		MOS HRS/MSC - (s) AFL		29-JUL-2020 960.32 402			
TCCA CF-2020-16 PARA A	INSPECT THE V-BAND CLAMP TRUNNION NUT TORQUE ON BOTH CABIN PRESSURE CONTROL SYSTEM SAFETY VALVES (P/N GG435-3006-3)					MANDATORY	NOT APPLICABLE - PER S/N OF AIRCRAFT.
29-MAY-2020		MOS HRS/MSC - (s) AFL		29-JUL-2020 960.32 402			
TCCA CF-2020-16 PARA B	PERFORM A VISUAL INSPECTION AND COMPLETE THE REMAINDER / REPLACE THE SAFETY VALVE (FOR SAFETY VALVES WITH A V-BAND CLAMP TRUNNION NUT TORQUE OF LESS THAN 80 LBF-IN)					MANDATORY	NOT APPLICABLE - PER S/N OF AIRCRAFT.
29-MAY-2020		MOS HRS/MSC - (s) AFL		29-JUL-2020 960.32 402			
TCCA CF-2020-16 PARA C	PERFORM A MAGNIFICATION INSPECTION AND COMPLETE THE REMAINDER / REPLACE THE SAFETY VALVE (FOR SAFETY VALVES WITH A V-BAND CLAMP TRUNNION NUT TORQUE OF 80 LBF-IN OR HIGHER)					MANDATORY	NOT APPLICABLE - PER S/N OF AIRCRAFT.
29-MAY-2020		MOS HRS/MSC - (s) AFL		29-JUL-2020 960.32 402			
TCCA CF-2020-35	FLIGHT CONTROLS - ROLL CONTROL INPUT-MODULES (RCIMS) INCORRECT INSTALLATION					MANDATORY	COMPLIED WITH - UTILIZING AMM TASK ISSUE DATES OF 21 FEBRUARY 2020 OR LATER
21-OCT-2020		DAYS HRS/MSC - AFL		29-OCT-2020 972.5 408			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
TCCA CF-2022-25	LANDING GEAR - INTRODUCTION OF NEW BRAKE ACCUMULATOR LIFE LIMIT					MANDATORY	COMPLIED WITH - UPDATED BY CAMP SYSTEMS. REPLACEMENT DUE @8366 AIRCRAFT HOURS
17-MAY-2022		DAYS HRS/MSC - AFL		12-JUL-2022 1050.4 448			
TCCA CF-96-21	NICKEL-CADMIUM BATTERY						NOT APPLICABLE - CANCELS THE APPLICABILITY OF FAA AD 72-19-04 FOR CANADIAN AIRCRAFT.
		MOS HRS/MSC - AFL		08-MAY-2014			
AD CF-2011-03 R2	SECURITY CONCERNS WITH THE CHEMICAL OXYGEN GENERATORS INSTALLED IN THE LAVATORIES						NOT APPLICABLE - NO CHEMICAL OXYGEN GENERATORS INSTALLED IN LAVATORIES
		MOS HRS/MSC N/A AFL		08-MAY-2014			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
APPLIANCE - 9575/N813WB							
EASA 2007-0156	APPLIANCE AD - COMMUNICATION - COMM UNITS & TRANSPONDERS - MODIFICATION / REPLACEMENT						NOT APPLICABLE - DUE TO COMPONENT P/N NOT INSTALLED ON THIS A/C
		MOS HRS/MSC - AFL		24-MAY-2014			
EASA 2009-0251-E	APPLIANCE/EMERGENCY AD - FIRE EXTINGUISHER - PORTABLE FIRE EXTINGUISHERS IDENTIFICATION/REPLACEMENT						NOT APPLICABLE - THIS AD IS N/A BY FIRE EXTINGUISHER SERIAL NUMBERS INSTALLED 086486 & 086488
		MOS HRS/MSC - AFL		24-MAY-2014			
EASA 2009-0262 R1	APPLIANCE AD - FIRE PROTECTION - HALON 1211 FIRE EXTINGUISHERS - IDENTIFICATION / REPLACEMENT						NOT APPLICABLE - BY FIRE EXTINGUISHER SERIAL NUMBER INSTALLED
		MOS HRS/MSC - AFL		24-MAY-2014			
EASA 2009-0262 REV 1	APPLIANCE AD - FIRE EXTINGUISHER - PORTABLE FIRE EXTINGUISHERS IDENTIFICATION/REPLACEMENT						NOT APPLICABLE - BY EXTINGUISHER SERIAL NUMBERS INSTALLED 086486 & 086488
		MOS HRS/MSC - AFL		24-MAY-2014			
EASA 2009-0278	APPLIANCE AD - FIRE EXTINGUISHER - PORTABLE FIRE EXTINGUISHERS IDENTIFICATION/REPLACEMENT						NOT APPLICABLE - NOT INSTALLED ON THIS A/C
		MOS HRS/MSC - AFL		24-MAY-2014			
EASA 2010-0003 R02	APPLIANCE AD - NAVIGATION - MODE S TRANSPONDER AIRCRAFT TYPE MODE STRAPPING - CHECK / MODIFICATION					MANDATORY	NOT APPLICABLE - BY PART NUMBER OF INSTALLED EQUIPMENT
14-OCT-2014		MOS HRS/MSC - (s) AFL		08-OCT-2015 350.9 149			
EASA 2010-0003 R02 PARA (1)	VERIFY AIRCRAFT TYPE MODE STRAPPING CODE S SET TO '0' (ZERO) OR '1', AS DEFINED IN ROCKWELL-COLLINS SERVICE LETTER TDR-94() SIL 07-2.					MANDATORY	NOT APPLICABLE - BY PART NUMBER OF INSTALLED EQUIPMENT
14-OCT-2014		MOS HRS/MSC - (s) AFL		08-OCT-2015 350.9 149			
EASA 2010-0003 R02 PARA (2)	EXEMPTIONS: DASSAULT AEROPLANES					MANDATORY	NOT APPLICABLE - BY PART NUMBER OF INSTALLED EQUIPMENT
14-OCT-2014		MOS HRS/MSC - (s) AFL		08-OCT-2015 350.9 149			
EASA 2010-0003 R02 PARA (3)	EXEMPTIONS: ATR 42 AND ATR 72 AEROPLANES					MANDATORY	NOT APPLICABLE - BY PART NUMBER OF INSTALLED EQUIPMENT
14-OCT-2014		MOS HRS/MSC - (s) AFL		08-OCT-2015 350.9 149			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2010-0003 R02 PARA (4)	EXEMPTIONS: SAAB 2000 AEROPLANES					MANDATORY	NOT APPLICABLE - BY PART NUMBER OF INSTALLED EQUIPMENT
14-OCT-2014		MOS		08-OCT-2015			
		HRS/MSC - (s)		350.9			
		AFL		149			
EASA 2010-0003 R02 PARA (5)	EXEMPTIONS: BOMBARDIER AEROSPACE (CANADAIR) AEROPLANES: CL-600-2B16 (604 VARIANT) AND CL-600-2B19 (RJ100 AND RJ200)					MANDATORY	NOT APPLICABLE - BY PART NUMBER OF INSTALLED EQUIPMENT
14-OCT-2014		MOS		08-OCT-2015			
		HRS/MSC - (s)		350.9			
		AFL		149			
EASA 2010-0003 R02 PARA (6)	EXEMPTIONS: CESSNA AIRCRAFT COMPANY AEROPLANES: CESSNA MODEL 525, 525A, 525B; AND CESSNA MODEL 525, 525A, 525B, 560; 560XL					MANDATORY	NOT APPLICABLE - BY PART NUMBER OF INSTALLED EQUIPMENT
14-OCT-2014		MOS		08-OCT-2015			
		HRS/MSC - (s)		350.9			
		AFL		149			
EASA 2010-0003 R02 PARA (7)	EXEMPTIONS: PIAGGIO AERO INDUSTRIES AEROPLANES: P.180 (AVANTI) AND P.180 (AVANTI II)					MANDATORY	NOT APPLICABLE - BY PART NUMBER OF INSTALLED EQUIPMENT
14-OCT-2014		MOS		08-OCT-2015			
		HRS/MSC - (s)		350.9			
		AFL		149			
EASA 2010-0062 R1	APPLIANCE AD - FIRE PROTECTION - HALON 1211 FIRE EXTINGUISHERS - IDENTIFICATION / REPLACEMENT - FIRE FIGHTING ENTERPRISES LIMITED						NOT APPLICABLE - BY EXTINGUISHER SERIAL NUMBERS INSTALLED 086486 & 086488
		MOS		24-MAY-2014			
		HRS/MSC -					
		AFL					
EASA 2010-0062 REV 1	APPLIANCE AD - PORTABLE HALON 1211 FIRE EXTINGUISHER - IDENTIFICATION/REPLACEMENT						NOT APPLICABLE - BY FIRE EXTINGUISHER SERIAL NUMBER INSTALLED
		MOS		24-MAY-2014			
		HRS/MSC -					
		AFL					
EASA 2010-0152	APPLIANCE AD - OXYGEN MASK REGULATOR - MODIFICATION						NOT APPLICABLE - BY P/N MLD20-508 INSTALLED
		MOS		24-MAY-2014			
		HRS/MSC -					
		AFL					
EASA 2011-0090 R1	APPLIANCE AD - OXYGEN MASK REGULATOR INFLATABLE HARNESS - IDENTIFICATION / REPLACEMENT						NOT APPLICABLE - BY MANUFACTURER DATE
		MOS		08-OCT-2015			
		HRS/MSC -		350.9			
		AFL		149			
EASA 2011-0103	APPLIANCE AD - EQUIPMENT / FURNISHINGS - EMERGENCY LOCATOR TRANSMITTER (ELT) ANTENNA - MODIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - BY PART NUMBER OF INSTALLED EQUIPMENT
03-JUN-2011		MOS		08-OCT-2015			
		HRS/MSC - (s)		350.9			
		AFL		149			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2011-0103 PARA (1)	PERFORM A SELF-TEST OF THE ELT UNIT INTERCONNECTED WITH THE P/N 21-41 SERIES ANTENNA					MANDATORY	NOT APPLICABLE - BY PART NUMBER OF INSTALLED EQUIPMENT
03-JUN-2011		MOS HRS/MSC - (s) AFL		08-OCT-2015 350.9 149			
EASA 2011-0103 PARA (2)	MODIFY THE P/N 21-41 SERIES ANTENNA IN ACCORDANCE WITH THE INSTRUCTIONS OF CHELTON LTD SB 02/2011 ISSUE 1, OR REPLACE THE ANTENNA WITH A MODIFIED P/N 21-41 SERIES ANTENNA, OR WITH A P/N 21-41 SERIES ANTENNA WITH A S/N OF 13000 OR HIGHER					MANDATORY	NOT APPLICABLE - BY PART NUMBER OF INSTALLED EQUIPMENT
03-JUN-2011		MOS HRS/MSC - (s) AFL		08-OCT-2015 350.9 149			
EASA 2011-0103 PARA (3)	MODIFY THE P/N 21-41 SERIES ANTENNA IN ACCORDANCE WITH THE INSTRUCTIONS OF CHELTON LTD SB 02/2011 ISSUE 1, OR REPLACE THE ANTENNA WITH A MODIFIED P/N 21-41 SERIES ANTENNA, OR WITH A P/N 21-41 SERIES ANTENNA WITH A S/N OF 13000 OR HIGHER					MANDATORY	NOT APPLICABLE - BY PART NUMBER OF INSTALLED EQUIPMENT
03-JUN-2011		MOS HRS/MSC - (s) AFL		08-OCT-2015 350.9 149			
EASA 2011-0103 PARA (4)	PERFORM A SELF-TEST OF THE ELT UNIT INTERCONNECTED WITH THE P/N 21-41 SERIES ANTENNA					MANDATORY	NOT APPLICABLE - BY PART NUMBER OF INSTALLED EQUIPMENT
03-JUN-2011		MOS HRS/MSC - (s) AFL		08-OCT-2015 350.9 149			
EASA 2011-0103 PARA (5)	TERMINATING ACTION FOR THE REPETITIVE SELF-TESTS AS REQUIRED BY PARAGRAPH (1) OF THIS AD FOR THAT AIRCRAFT, WHEN AN INSTALLATION ON AN AIRCRAFT PASSES THE SELF-TEST AS REQUIRED BY PARAGRAPH (4) OF THIS AD					MANDATORY	NOT APPLICABLE - BY PART NUMBER OF INSTALLED EQUIPMENT
03-JUN-2011		MOS HRS/MSC - (s) AFL		08-OCT-2015 350.9 149			
EASA 2011-0103 PARA (6)	DO NOT INSTALL AN AFFECTED P/N 21-41 SERIES ANTENNA WITH A S/N BELOW 13000 ON AN AIRCRAFT, UNLESS IT HAS BEEN MODIFIED IN ACCORDANCE WITH THE INSTRUCTIONS OF CHELTON LTD SB 02/2011 ISSUE 1					MANDATORY	NOT APPLICABLE - BY PART NUMBER OF INSTALLED EQUIPMENT
03-JUN-2011		MOS HRS/MSC - (s) AFL		08-OCT-2015 350.9 149			
EASA 2012-0037	APPLIANCE AD - FIRE PROTECTION – HAND OPERATED FIRE EXTINGUISHER – MODIFICATION						NOT APPLICABLE - PART NUMBER OF INSTALLED EQUIPMENT
		MOS HRS/MSC - AFL		08-OCT-2015 350.9 149			
EASA 2012-0038	APPLIANCE AD - EQUIPMENT & FURNISHINGS – PASSENGER SEAT BACKREST LINK – INSPECTION / REPLACEMENT						NOT APPLICABLE - PER MANUFACTURER OF INSTALLED EQUIPMENT
		MOS HRS/MSC - AFL		08-OCT-2015 350.9 149			
EASA 2012-0254 R01	APPLIANCE AD - OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT					MANDATORY	NOT APPLICABLE - BY P/N MLD20-508 INSTALLED
21-DEC-2012		MOS HRS/MSC - AFL		24-MAY-2014			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2012-0254 R01 PARA (1)	INSPECT OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT EACH FLIGHT CREW OXYGEN MASK REGULATOR TO IDENTIFY THE P/N AND S/N	MOS		24-MAY-2014		MANDATORY	NOT APPLICABLE - BY P/N MLD20-508 INSTALLED
21-DEC-2012		HRS/MSC - AFL					
EASA 2012-0254 R01 PARA (2.1)	REPLACE OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT EACH AFFECTED FLIGHT CREW OXYGEN MASK REGULATOR WITH A SERVICEABLE PART	MOS		24-MAY-2014		MANDATORY	NOT APPLICABLE - BY P/N MLD20-508 INSTALLED
21-DEC-2012		HRS/MSC - AFL					
EASA 2012-0254 R01 PARA (2.2)	AMEND OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT THE AIRCRAFT FLIGHT MANUAL (AFM) AND INSTALL A PLACARD	MOS		24-MAY-2014		MANDATORY	NOT APPLICABLE - BY P/N MLD20-508 INSTALLED
21-DEC-2012		HRS/MSC - AFL					
EASA 2012-0254 R01 PARA (3)	REPLACE OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT EACH AFFECTED FLIGHT CREW OXYGEN MASK REGULATOR	MOS		24-MAY-2014		MANDATORY	NOT APPLICABLE - BY P/N MLD20-508 INSTALLED
21-DEC-2012		HRS/MSC - AFL					
EASA 2013-0020 R02	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT	MOS		22-SEP-2013		MANDATORY	COMPLIED WITH - NEW PARTS INSTALLED DURING AIRCRAFT MANUFACTURE
11-JUL-2013		HRS/MSC - AFL					
EASA 2013-0020 R02 PARA (1)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT INSPECT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN THE DESIGN APPROVAL HOLDER	MOS		23-APR-2014		MANDATORY	COMPLIED WITH
11-JUL-2013		HRS/MSC - AFL					
EASA 2013-0020 R02 PARA (2)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT VERIFY IF THE ORGANISATION IS LISTED AMONG THE AUTHORIZED MAINTENANCE OR REPAIR ORGANISATION REFERENCE DOCUMENTS QUOTED IN THE REF. PUBLICATIONS SECTION OF THIS AD	MOS		23-APR-2014		MANDATORY	COMPLIED WITH
11-JUL-2013		HRS/MSC - (s) AFL					
EASA 2013-0020 R02 PARA (3)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT REMOVE AND REPLACE BELTS NOT MEETING THE CERTIFICATION REQUIREMENTS OR MAKE RELEVANT SEAT INOPERATIVE	MOS		23-APR-2014		MANDATORY	COMPLIED WITH
11-JUL-2013		HRS/MSC - (s) AFL					
EASA 2013-0020 R02 PARA (4)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT AFTER 14 FEBRUARY 2013 [THE EFFECTIVE DATE OF THE ORIGINAL ISSUE OF THIS AD], DO NOT INSTALL SAFETY BELTS OR TORSO RESTRAINT SYSTEMS ON ANY AIRCRAFT, UNLESS INSPECTED AND CORRECTED IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD	MOS		23-APR-2014		MANDATORY	COMPLIED WITH
11-JUL-2013		HRS/MSC - AFL					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2013-0020 R03	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - NEW PARTS INSTALLED DURING AIRCRAFT MANUFACTURE
28-MAR-2014		MOS HRS/MSC - AFL		24-MAY-2014			
EASA 2013-0020 R03 PARA (1)	INSPECT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN THE DESIGN APPROVAL HOLDER					MANDATORY	NOT APPLICABLE - NEW PARTS INSTALLED DURING AIRCRAFT MANUFACTURE
28-MAR-2014		MOS HRS/MSC - AFL		24-MAY-2014			
EASA 2013-0020 R03 PARA (2)	VERIFY IF THE ORGANISATION IS LISTED AMONG THE AUTHORIZED MAINTENANCE OR REPAIR ORGANISATION REFERENCE DOCUMENTS QUOTED IN THE REF. PUBLICATIONS SECTION OF THIS AD					MANDATORY	NOT APPLICABLE - NEW PARTS INSTALLED DURING AIRCRAFT MANUFACTURE
28-MAR-2014		MOS HRS/MSC - AFL		24-MAY-2014			
EASA 2013-0020 R03 PARA (3)	REMOVE AND REPLACE BELTS NOT MEETING THE CERTIFICATION REQUIREMENTS OR MAKE RELEVANT SEAT INOPERATIVE					MANDATORY	NOT APPLICABLE - NEW PARTS INSTALLED DURING AIRCRAFT MANUFACTURE
28-MAR-2014		MOS HRS/MSC - AFL		24-MAY-2014			
EASA 2013-0020 R03 PARA (4)	AFTER 14 FEBRUARY 2013 [THE EFFECTIVE DATE OF THE ORIGINAL ISSUE OF THIS AD], DO NOT INSTALL SAFETY BELTS OR TORSO RESTRAINT SYSTEMS ON ANY AIRCRAFT, UNLESS INSPECTED AND CORRECTED IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD					MANDATORY	NOT APPLICABLE - NEW PARTS INSTALLED DURING AIRCRAFT MANUFACTURE
28-MAR-2014		MOS HRS/MSC - AFL		24-MAY-2014			
EASA 2014-0088	APPLIANCE AD - COMMUNICATIONS - COCKPIT VOICE RECORDER - REPLACEMENT					MANDATORY	NOT APPLICABLE - PART NUMBER OF INSTALLED EQUIPMENT
29-APR-2014		MOS HRS/MSC - (s) AFL		08-OCT-2015 350.9 149			
EASA 2014-0142 R01	APPLIANCE AD - OXYGEN – OXYGEN MASK REGULATOR INFLATABLE HARNESS / INFLATION HOSE – IDENTIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - PART NUMBER OF INSTALLED EQUIPMENT
18-JUN-2014		MOS HRS/MSC - AFL		08-OCT-2015 350.9 149			
FAA 2006-19-04 PART (F)	APPLIANCE AD - HONEYWELL - COMMUNICATION (COM) UNIT / MODE S TRANSPONDER ERRONEOUSLY GOING INTO STANDBY MODE - REVISE AIRPLANE FLIGHT MANUAL (AFM)					MANDATORY	NOT APPLICABLE - DUE TO COMPONENTS NOT INSTALLED ON THIS A/C
		MOS HRS/MSC - AFL		24-MAY-2014			
FAA 2006-19-04 PART (G)	APPLIANCE AD - HONEYWELL - COMMUNICATION (COM) UNIT / MODE S TRANSPONDER ERRONEOUSLY GOING INTO STANDBY MODE - REPLACEMENT OF IDENTIFICATION PLATES FOR CERTAIN COM UNITS					MANDATORY	NOT APPLICABLE - DUE TO COMPONENTS NOT INSTALLED ON THIS A/C
		MOS HRS/MSC - AFL		24-MAY-2014			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2006-19-04 PART (H)	APPLIANCE AD - HONEYWELL - COMMUNICATION (COM) UNIT / MODE S TRANSPONDER ERRONEOUSLY GOING INTO STANDBY MODE - REPLACEMENT OF CERTAIN TRANSPONDERS	MOS		24-MAY-2014		MANDATORY	NOT APPLICABLE - DUE TO COMPONENTS NOT INSTALLED ON THIS A/C
		HRS/MSC -					
		AFL					
FAA 2015-16-04	APPLIANCE AD - FIRE PROTECTION - MODIFY ALL KIDDE GRAVINER HAND-OPERATED FIRE EXTINGUISHERS HAVING PART NUMBERS 56412-001 (34H), 56411-001 (35H), AND 56412-002 (38H)	MOS		08-OCT-2015		MANDATORY	NOT APPLICABLE - PER PART NUMBERS OF INSTALLED EQUIPMENT
15-SEP-2015		HRS/MSC - (s)		350.9			
		AFL		149			
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS	MOS		19-DEC-2017		MANDATORY	NOT APPLICABLE - DOES NOT APPLY ACR ELECTRONICS, INSTALLED
24-OCT-2017		HRS/MSC - (s)		684.7			
		AFL		292			
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	MOS		19-DEC-2017			NOT APPLICABLE - DOES NOT APPLY ACR ELECTRONICS, INSTALLED
24-OCT-2017		HRS/MSC -		684.7			
		AFL		292			
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT	MOS		19-DEC-2017		MANDATORY	NOT APPLICABLE - DOES NOT APPLY ACR ELECTRONICS, INSTALLED
24-OCT-2017		HRS/MSC - (s)		684.7			
		AFL		292			
FAA 2021-07-13	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT	MOS		12-MAY-2021		MANDATORY	NOT APPLICABLE - PER PN INSTALLED ON AIRCRAFT.
11-MAY-2021		HRS/MSC -		994.48			
		AFL		421			
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE	MOS		12-MAY-2021		MANDATORY	NOT APPLICABLE - PER PN INSTALLED
11-MAY-2021		HRS/MSC -		994.48			
		AFL		421			
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE	MOS		12-MAY-2021		MANDATORY	NOT APPLICABLE - PER PN INSTALLED
11-MAY-2021		HRS/MSC -		994.48			
		AFL		421			
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER	MOS		12-MAY-2021		MANDATORY	NOT APPLICABLE - PER PN INSTALLED
11-MAY-2021		HRS/MSC -		994.48			
		AFL		421			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2021-08-07	APPLIANCE AD - ROCKWELL COLLINS - GLOBAL POSITIONING SYSTEM GPS-4000S - UPGRADE					MANDATORY	NOT APPLICABLE - PER PN INSTALLED
12-MAY-2021		MOS		12-MAY-2021			
		HRS/MSC -		994.48			
		AFL		421			
FAA 2021-08-07 PARA (G)(1)	REPLACE EACH GPS-4000S GPS P/N 822-2189-100 WITH A GPS THAT DOES NOT HAVE P/N 822-2189-100					MANDATORY	NOT APPLICABLE - PER PN INSTALLED
12-MAY-2021		MOS		12-MAY-2021			
		HRS/MSC -		994.48			
		AFL		421			
FAA 2021-08-07 PARA (G)(2)	DO NOT INSTALL GPS-4000S GPS P/N 822-2189-100 ON ANY AIRPLANE					MANDATORY	NOT APPLICABLE - PER PN INSTALLED
12-MAY-2021		MOS		12-MAY-2021			
		HRS/MSC - (s)		994.48			
		AFL		421			
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS					MANDATORY	COMPLIED WITH - AMOC
09-DEC-2021		MOS		28-DEC-2021			
		HRS/MSC -		1030.92			
		AFL		438			
TCCA 2012-31 REV1	APPLIANCE AD - PASSENGER OXYGEN SYSTEM - INCORRECT LENGTH OF OXYGEN DISPENSING UNIT LANYARDS						NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER
		MOS		08-MAY-2014			
		HRS/MSC -					
		AFL					
TCCA CF-2013-25	APPLIANCE AD - EMERGENCY LOCATOR TRANSMITTER - BATTERY WIRING INSTALLATION DISCREPANCIES					MANDATORY	NOT APPLICABLE - PART NUMBER OF INSTALLED EQUIPMENT
26-AUG-2013		DAYS		08-OCT-2015			
		HRS/MSC - (s)		350.9			
		AFL		149			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
AIRFRAME - SB - 9575/N813WB							
ASB A700-26-5002	SPECIAL CHECK/REPLACEMENT - FIRE EXTINGUISHING SYSTEM - INSPECTION OF CHECK TEE, PART NO. 446651, ALERT SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
18-APR-2013		MOS HRS/MSC - AFL					
ASB A700-26-5002 PART A	- SPECIAL CHECK/REPLACEMENT - FIRE EXTINGUISHING SYSTEM - INSPECTION OF CHECK TEE, PART NO. 446651, ALERT SERVICE BULLETIN SERIAL NUMBER VERIFICATION					RECOMMENDED	NOT APPLICABLE
18-APR-2013		MOS HRS/MSC - AFL					
ASB A700-26-5002 PART B	INSPECTION SPECIAL CHECK/REPLACEMENT - FIRE EXTINGUISHING SYSTEM - INSPECTION OF CHECK TEE, PART NO. 446651, ALERT SERVICE BULLETIN AND/OR REPLACEMENT OF CHECK TEE FITTING(S)					RECOMMENDED	NOT APPLICABLE
18-APR-2013		MOS HRS/MSC - AFL					
ASB A700-53-5005	SPECIAL CHECK/REWORK - BELLY FAIRINGS - BELLY FAIRINGS FASTENERS ENGAGEMENT CHECK, ALERT SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
22-FEB-2012		MOS HRS/MSC - AFL					
ASB A700-53-5005 PART A	INSPECTION SPECIAL CHECK/REWORK - BELLY FAIRINGS - BELLY FAIRINGS FASTENERS ENGAGEMENT CHECK, ALERT SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
22-FEB-2012		DAYS HRS/MSC - AFL					
ASB A700-53-5005 PART B	REWORK SPECIAL CHECK/REWORK - BELLY FAIRINGS - BELLY FAIRINGS FASTENERS ENGAGEMENT CHECK, ALERT SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
22-FEB-2012		DAYS HRS/MSC - AFL					
ASB A700-53-5005 PART C	REPLACE SPECIAL CHECK/REWORK - BELLY FAIRINGS - BELLY FAIRINGS FASTENERS ENGAGEMENT CHECK, ALERT SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
22-FEB-2012		MOS HRS/MSC - AFL					
ASB A700-72-5001 REV 02	ICA - REWORK - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL-PUMP SPLINED COUPLING, ALERT SERVICE BULLETIN					RECOMMENDED	
28-MAR-2017		MOS HRS/MSC - AFL			27-SEP-2013		
MODSUM REV A	IS700-53-0023 FUSELAGE FAIRINGS AND LANDING GEAR WHEEL WELL - CORROSION PREVENTION, MODIFICATION SUMMARY						COMPLIED WITH - MODSUM IS700-53-0023 REV A-1 TO FLL-USA BAS FACILITY
		MOS HRS/MSC - AFL			25-MAY-2019 879.42 365		



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
MODSUM IS700-54-0002 REV A	ADDITION OF DRAIN HOLES IN PYLON LOWER SKIN / ACCESS PANELS, MODIFICATION SUMMARY						COMPLIED WITH - MODSUM IS700-54-0002 REV A-1
		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
REO 700-53-53-358	REPAIR TO TAIL CONE END CAP R/H SIDE, REPAIR ENGINEERING ORDER						COMPLIED WITH
		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
SB 700-11-5001 REV 01	OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
		MOS		23-APR-2014			
22-MAR-2013		HRS/MSC -		15.4			
		AFL		7			
SB 700-11-5001 REV 01 PART A	ACCOMPLISH OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS, SERVICE BULLETIN AIRCRAFT OPERATING AT AIRPORTS WITH A 74,955 LB (33,999 KG) MAXIMUM WEIGHT LIMITATION					OPTIONAL	COMPLIED WITH
		MOS		23-APR-2014			
22-MAR-2013		HRS/MSC -		15.4			
		AFL		7			
SB 700-11-5001 REV 01 PART B	ACCOMPLISH OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS, SERVICE BULLETIN AIRCRAFT OPERATING AT AIRPORTS WITH A 75,000 LB (34,019 KG) MAXIMUM WEIGHT LIMITATION					OPTIONAL	COMPLIED WITH
		MOS		23-APR-2014			
22-MAR-2013		HRS/MSC -		15.4			
		AFL		7			
SB 700-11-5002 REV 01	MODIFICATION - EXTERIOR PLACARDS AND MARKINGS AND FLIGHT COMPARTMENT PLACARDS - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 89,700 LBS (40,687 KG), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS					
08-JAN-2016		HRS/MSC -					
		AFL					
SB 700-11-5002 REV 02	MODIFICATION - EXTERIOR PLACARDS AND MARKINGS AND FLIGHT COMPARTMENT PLACARDS - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 89,700 LBS (40,687 KG), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS					
19-JUN-2017		HRS/MSC -					
		AFL					
SB 700-11-5002 REV 03	MODIFICATION - EXTERIOR PLACARDS AND MARKINGS AND FLIGHT COMPARTMENT PLACARDS - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 89,700 LBS (40,687 KG), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS					
23-DEC-2021		HRS/MSC -					
		AFL					
SB 700-11-5003 REV 01	MODIFICATION - INTERIOR AND EXTERIOR PLACARDS AND MARKINGS - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 88,700 LBS (40,233 KG), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS					
08-JAN-2016		HRS/MSC -					
		AFL					
SB 700-11-5003 REV 02	MODIFICATION - INTERIOR AND EXTERIOR PLACARDS AND MARKINGS - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 88,700 LBS (40,233 KG), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS					
19-JUN-2017		HRS/MSC -					
		AFL					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-11-5003 REV 03	MODIFICATION - INTERIOR AND EXTERIOR PLACARDS AND MARKINGS - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 88,700 LBS (40,233 KG), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
23-DEC-2021		MOS					
		HRS/MSC	-				
		AFL					
SB 700-11-5004 REV 01	MODIFICATION - INTERIOR PLACARDS AND MARKINGS - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 92,500 LBS (41,957 KG) FOR INCREASED RANGE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
08-JAN-2016		MOS					
		HRS/MSC	-				
		AFL					
SB 700-11-5004 REV 02	MODIFICATION - INTERIOR PLACARDS AND MARKINGS - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 92,500 LBS (41,957 KG) FOR INCREASED RANGE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
19-JUN-2017		MOS					
		HRS/MSC	-				
		AFL					
SB 700-11-5004 REV 03	MODIFICATION - INTERIOR PLACARDS AND MARKINGS - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 92,500 LBS (41,957 KG) FOR INCREASED RANGE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
23-DEC-2021		MOS					
		HRS/MSC	-				
		AFL					
SB 700-21-5003	MODIFICATION - TEMPERATURE CONTROL - REPLACE SUSPECT PACKINGS AT HOT-AIR CHECK VALVE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
29-FEB-2012		MOS					
		HRS/MSC	-				
		AFL					
SB 700-21-5005	MODIFICATION - PASSENGER COMPARTMENT AND AIR DISTRIBUTION SYSTEM - MODIFICATION OF AIR GASPERS FOR NOISE REDUCTION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
29-JUN-2015		MOS		(EFF)			
		HRS/MSC	-				
		AFL					
SB 700-21-5008 REV 01	MODIFICATION - TEMPERATURE CONTROL - REPLACEMENT OF THE AIR-CONDITIONING SYSTEM CONTROLLER (ACSC), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
25-SEP-2018		MOS		25-MAY-2019			
		HRS/MSC	-	879.42			
		AFL		365			
SB 700-21-5009	SPECIAL CHECK/MODIFICATION - CABIN-PRESSURE CONTROL SYSTEM - SAFETY VALVE OVERTORQUE (SUPERSEDED BY 700-21-5009 REV 01), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
23-JAN-2020		MOS					
		HRS/MSC	-				
		AFL					
SB 700-21-5009 PART A	ACCOMPLISH SPECIAL CHECK/MODIFICATION - CABIN-PRESSURE CONTROL SYSTEM - SAFETY VALVE OVERTORQUE (SUPERSEDED BY 700-21-5009 REV 01), SERVICE BULLETIN INSPECTION / TORQUE CHECK OF LH AND RH SAFETY VALVES					RECOMMENDED	NOT APPLICABLE
23-JAN-2020		MOS		(EFF)			
		HRS/MSC	-				
		AFL					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-21-5009 PART B	ACCOMPLISH SPECIAL CHECK/MODIFICATION - CABIN-PRESSURE CONTROL SYSTEM - SAFETY VALVE OVERTORQUE (SUPERSEDED BY 700-21-5009 REV 01), SERVICE BULLETIN REPLACEMENT OF LH AND RH SAFETY VALVES					RECOMMENDED	NOT APPLICABLE
23-JAN-2020		MOS		(EFF)			
		HRS/MSC -					
		AFL					
SB 700-21-5009 REV 01	SPECIAL CHECK/MODIFICATION - CABIN-PRESSURE CONTROL SYSTEM - SAFETY VALVE OVERTORQUE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
19-MAR-2020		MOS					
		HRS/MSC -					
		AFL					
SB 700-21-5009 REV 01 PART A	ACCOMPLISH, SERVICE BULLETIN INSPECTION / TORQUE CHECK OF LH AND RH SAFETY VALVES					RECOMMENDED	NOT APPLICABLE
19-MAR-2020		MOS					
		HRS/MSC -					
		AFL					
SB 700-21-5009 REV 01 PART B	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF LH AND RH SAFETY VALVES					RECOMMENDED	NOT APPLICABLE
19-MAR-2020		MOS					
		HRS/MSC - (s)					
		AFL					
SB 700-21-5009 REV 02	SPECIAL CHECK/MODIFICATION - CABIN-PRESSURE CONTROL SYSTEM - SAFETY VALVE OVERTORQUE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
31-MAR-2020		MOS		29-JUL-2020			
		HRS/MSC -		960.3			
		AFL		402			
SB 700-21-5009 REV 02 PART A	ACCOMPLISH, SERVICE BULLETIN INSPECTION / TORQUE CHECK OF LH AND RH SAFETY VALVES					RECOMMENDED	NOT APPLICABLE
31-MAR-2020		MOS		29-JUL-2020			
		HRS/MSC -		960.3			
		AFL		402			
SB 700-21-5009 REV 02 PART B	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF LH AND RH SAFETY VALVES					RECOMMENDED	NOT APPLICABLE
31-MAR-2020		MOS		29-JUL-2020			
		HRS/MSC - (s)		960.3			
		AFL		402			
SB 700-22-5001	SPECIAL CHECK/MODIFICATION - AUTOPILOT SYSTEM - AILERON AND ELEVATOR AUTOPILOT SERVO CABLE KEEPER WEAR, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
09-JAN-2013		MOS					
		HRS/MSC -					
		AFL					
SB 700-22-5001 PART A	INSPECTION SPECIAL CHECK/MODIFICATION - AUTOPILOT SYSTEM - AILERON AND ELEVATOR AUTOPILOT SERVO CABLE KEEPER WEAR, SERVICE BULLETIN OF THE CABLE KEEPERS AND MODIFICATION OF THE AILERON SERVO CABLE TENSION					RECOMMENDED	NOT APPLICABLE
09-JAN-2013		MOS					
		HRS/MSC -					
		AFL					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-22-5001 PART B	INSPECTION SPECIAL CHECK/MODIFICATION - AUTOPILOT SYSTEM - AILERON AND ELEVATOR AUTOPILOT SERVO CABLE KEEPER WEAR, SERVICE BULLETIN OF THE CABLE KEEPERS AND MODIFICATION OF THE ELEVATOR SERVO CABLE TENSION					RECOMMENDED	NOT APPLICABLE
09-JAN-2013		MOS					
		HRS/MSC -					
		AFL					
SB 700-23-5001	MODIFICATION - AIRBORNE DATA-LINK SYSTEM - INSTALLATION OF A SECOND DATA-LINK SYSTEM., SERVICE BULLETIN						COMPLIED WITH
		MOS		23-APR-2014			
		HRS/MSC -					
		AFL					
SB 700-23-5002 REV 01	MODIFICATION - PRINTER SYSTEM - INSTALLATION OF A FLIGHT COMPARTMENT PRINTER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
		MOS		23-APR-2014			
17-JAN-2013		HRS/MSC -		15.4			
		AFL		7			
SB 700-23-5008	MODIFICATION - RADIO MANAGEMENT SYSTEM - INTRODUCTION OF A NEW RADIO INTERFACE UNIT (RIU) PART NUMBER TO SUPPORT FANS/CPDLC CONNECTION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
17-APR-2012		HRS/MSC -					
		AFL					
SB 700-23-5010 REV 03	MODIFICATION - AUDIO INTEGRATING SYSTEM - INTRODUCTION OF NEW AUDIO CONTROL PANEL ACP-6000 PART NO. 822-2928-500 (MOD 1) INSTEAD OF ACP-4120 PART NO. 822-1950-503, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
05-MAY-2014		HRS/MSC -					
		AFL					
SB 700-23-5010 REV 04	ICA - MODIFICATION - AUDIO INTEGRATING SYSTEM - INTRODUCTION OF NEW AUDIO CONTROL PANEL ACP-6000 PART NO. 822-2928-500 (MOD 1) INSTEAD OF ACP-4120 PART NO. 822-1950-503, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
09-JUL-2014		HRS/MSC -					
		AFL					
SB 700-23-5011 REV 01	MODIFICATION - VOICE RECORDER SYSTEM - COCKPIT VOICE RECORDER (CVR) - FA2100 CVR P/N 2100-1025-22 CHANGE TO P/N 2100-1025-24, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
10-DEC-2012		HRS/MSC -					
		AFL					
SB 700-23-5012	MODIFICATION - VOICE RECORDER SYSTEM - REPLACEMENT OF COCKPIT VOICE RECORDER CVR IMPACT SWITCH, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
04-MAR-2013		HRS/MSC -					
		AFL					
SB 700-23-5012 REV 01	ICA - MODIFICATION - VOICE RECORDER SYSTEM - REPLACEMENT OF COCKPIT VOICE RECORDER CVR IMPACT SWITCH, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
01-OCT-2014		HRS/MSC -					
		AFL					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-23-5013 REV 01	MODIFICATION - GENERAL - UPDATE TO SUPPORT IMPLEMENTATION OF ATN CPDLC CAPABILITY, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
15-AUG-2014		MOS HRS/MSC - AFL					
SB 700-23-5013 REV 02	MODIFICATION - GENERAL - UPDATE TO SUPPORT IMPLEMENTATION OF ATN CPDLC CAPABILITY, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
13-NOV-2014		MOS HRS/MSC - AFL					
SB 700-23-5014	ICA - SPECIAL CHECK/MODIFICATION - RADIO MANAGEMENT SYSTEM (RMS) - INSPECTION OF IMPROPERLY CRIMPED TERMINAL FORK CONTACTS ON RADIO INTERFACE UNIT (RIU) NO. 1 AND NO. 2, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS HRS/MSC - AFL					
SB 700-23-5014 PART A	REMOVE/INSPECT ICA - SPECIAL CHECK/MODIFICATION - RADIO MANAGEMENT SYSTEM (RMS) - INSPECTION OF IMPROPERLY CRIMPED TERMINAL FORK CONTACTS ON RADIO INTERFACE UNIT (RIU) NO. 1 AND NO. 2, SERVICE BULLETIN AND REPLACE THE FORK CONTACTS P87 AND P88 ON RIU NO. 1 (A411P1 AND A411P2) AND RIU NO. 2 (A412P1 AND A412P2)					RECOMMENDED	NOT APPLICABLE
		MOS HRS/MSC - AFL					
SB 700-23-5014 PART B	REMOVE/INSPECT ICA - SPECIAL CHECK/MODIFICATION - RADIO MANAGEMENT SYSTEM (RMS) - INSPECTION OF IMPROPERLY CRIMPED TERMINAL FORK CONTACTS ON RADIO INTERFACE UNIT (RIU) NO. 1 AND NO. 2, SERVICE BULLETIN AND INSTALL ALL OTHER CONTACTS (NOT P87 AND P88) ON RIU NO. 1 (A411P1 AND A411P2) AND RIU NO. 2 (A412P1 AND A412P2)					RECOMMENDED	NOT APPLICABLE
		MOS HRS/MSC - AFL					
SB 700-23-5016	MODIFICATION - RADIO MANAGEMENT SYSTEM - REPLACE CTP-6000 PART NUMBER 822-2493-003 TO REDUCE OCCURANCE OF UN-COMMANDED BEHAVIOR, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
17-FEB-2014		MOS HRS/MSC - AFL		23-APR-2014 15.4 7			
SB 700-23-5016 REV 01	ICA - MODIFICATION - RADIO MANAGEMENT SYSTEM - REPLACE CTP-6000 PART NUMBER 822-2493-003 TO REDUCE OCCURENCE OF UN-COMMANDED BEHAVIOR, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - CTP-6000-23-1 REV 1
17-APR-2014		MOS HRS/MSC - AFL		23-APR-2014			
SB 700-23-5017	MODIFICATION - CABIN COMMUNICATIONS SYSTEM-REPLACEMENT OF CORDLESS HANDSET ASSEMBLY, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
27-MAR-2015		MOS HRS/MSC - AFL					
SB 700-23-5017 REV 01	MODIFICATION - CABIN COMMUNICATIONS SYSTEM-REPLACEMENT OF CORDLESS HANDSET ASSEMBLY, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
12-JUL-2016		MOS HRS/MSC - AFL					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-23-5017 REV 02	MODIFICATION - CABIN COMMUNICATION SYSTEM - REPLACEMENT OF CORDLESS HANDSET ASSEMBLY, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
28-MAY-2018		MOS HRS/MSC - AFL					
SB 700-23-5020	MODIFICATION - CABIN COMMUNICATION SYSTEM - REPLACEMENT OF ICS 100/200 SERIES IRIDIUM TRANSCEIVER WITH ICS 120/220 A/AF/B/BF SERIES IRIDIUM TRANSCEIVER, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
07-JUL-2017		MOS HRS/MSC - AFL					
SB 700-23-5021	SPECIAL CHECK/REWORK - SATELLITE COMMUNICATIONS SYSTEM - INSPECTION OF SATCOM RF COAX CABLE FOR MINIMUM BEND RADIUS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
20-MAR-2017		MOS HRS/MSC - AFL					
SB 700-23-5021 PART A	ACCOMPLISH SPECIAL CHECK/REWORK - SATELLITE COMMUNICATIONS SYSTEM - INSPECTION OF SATCOM RF COAX CABLE FOR MINIMUM BEND RADIUS, SERVICE BULLETIN VISUAL INSPECTION					RECOMMENDED	NOT APPLICABLE
20-MAR-2017		MOS HRS/MSC - AFL					
SB 700-23-5021 PART B	ACCOMPLISH SPECIAL CHECK/REWORK - SATELLITE COMMUNICATIONS SYSTEM - INSPECTION OF SATCOM RF COAX CABLE FOR MINIMUM BEND RADIUS, SERVICE BULLETIN COAXIAL CABLE BEND RADIUS REWORK					RECOMMENDED	NOT APPLICABLE
20-MAR-2017		MOS HRS/MSC - AFL					
SB 700-23-5022	SPECIAL CHECK/REWORK - SATELLITE COMMUNICATIONS SYSTEM - INSPECTION OF SATCOM RF COAX CABLE FOR MINIMUM BEND RADIUS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
29-JUN-2017		MOS HRS/MSC - AFL					
SB 700-23-5022 PART A	ACCOMPLISH, SERVICE BULLETIN VISUAL INSPECTION OF THE COAXIAL CABLE BEND RADIUS			(EFF)		RECOMMENDED	NOT APPLICABLE
29-JUN-2017		MOS HRS/MSC - AFL					
SB 700-23-5022 PART B	ACCOMPLISH, SERVICE BULLETIN COAXIAL CABLE INSTALLATION REWORK			(EFF)		RECOMMENDED	NOT APPLICABLE
29-JUN-2017		MOS HRS/MSC - AFL					
SB 700-23-5024	MODIFICATION - CABIN COMMUNICATION SYSTEM - SIGMA 7 HANDSETS REPLACEMENT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
23-DEC-2019		MOS HRS/MSC - AFL					
SB 700-23-5026	MODIFICATION - CABIN COMMUNICATION SYSTEM - ASPIRE-100 HANDSET REMOVAL IF NOT REQUIRED WITH VENUE CABIN MANAGEMENT SYSTEM (CMS), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
12-OCT-2020		MOS HRS/MSC - AFL					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-24-5003	MODIFICATION - MAIN GENERATOR OIL SYSTEM - ADDITION OF HIGH CONDUCTIVITY OIL TO DISSIPATE ELECTRO STATIC DISCHARGE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
20-FEB-2012		MOS					
		HRS/MSC	-				
		AFL					
SB 700-24-5004	MODIFICATION - MAIN GENERATOR OIL SYSTEM - INTRODUCTION OF NEW VARIABLE FREQUENCY GENERATOR (VFG) FILTER ELEMENT, SERVICE BULLETIN					RECOMMENDED	
20-FEB-2012		MOS					
		HRS/MSC	3000		3000		
		AFL					
SB 700-24-5005	MODIFICATION - MAIN GENERATOR OIL SYSTEM - REPLACEMENT OF THE VARIABLE FREQUENCY GENERATOR, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
30-APR-2012		MOS					
		HRS/MSC	-				
		AFL					
SB 700-24-5005 PART A	CHECK MODIFICATION - MAIN GENERATOR OIL SYSTEM - REPLACEMENT OF THE VARIABLE FREQUENCY GENERATOR, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
30-APR-2012		MOS					
		HRS/MSC	-				
		AFL					
SB 700-24-5005 PART B	INSPECTION MODIFICATION - MAIN GENERATOR OIL SYSTEM - REPLACEMENT OF THE VARIABLE FREQUENCY GENERATOR, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
30-APR-2012		MOS					
		HRS/MSC	-				
		AFL					
SB 700-24-5005 PART C	REPLACEMENT MODIFICATION - MAIN GENERATOR OIL SYSTEM - REPLACEMENT OF THE VARIABLE FREQUENCY GENERATOR, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
30-APR-2012		MOS					
		HRS/MSC	-				
		AFL					
SB 700-24-5006 REV 01	SPECIAL CHECK - PRIMARY AC-POWER SUPPLY - VFG VIBRATION GROUND TEST, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
05-NOV-2013		MOS					
		HRS/MSC	-				
		AFL					
SB 700-24-5007	MODIFICATION - ELECTRICAL POWER - BUS BAR HARNESS CLAMP REPLACEMENT IN THE LEFT HAND SIDE CIRCUIT BREAKER PANEL, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
09-OCT-2012		MOS					
		HRS/MSC	-				
		AFL					
SB 700-24-5008	MODIFICATION - MAIN GENERATOR OIL SYSTEM - REPLACEMENT OF THE VARIABLE FREQUENCY GENERATOR, SERVICE BULLETIN						COMPLIED WITH
17-JAN-2014		MOS		23-APR-2014			
		HRS/MSC	-	15.4			
		AFL		7			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-24-5009	SPECIAL CHECK - PRIMARY AC-POWER SUPPLY - REBALANCE OF VARIABLE FREQUENCY GENERATOR (VFG), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
28-MAY-2015		MOS HRS/MSC - AFL					
SB 700-24-5009 PART A	SPECIAL CHECK - PRIMARY AC-POWER SUPPLY - REBALANCE OF VARIABLE FREQUENCY GENERATOR (VFG), SERVICE BULLETIN SPECIAL CHECK					RECOMMENDED	NOT APPLICABLE
28-MAY-2015		MOS HRS/MSC - AFL		(EFF)			
SB 700-24-5009 PART B	SPECIAL CHECK - PRIMARY AC-POWER SUPPLY - REBALANCE OF VARIABLE FREQUENCY GENERATOR (VFG), SERVICE BULLETIN REPLACEMENT OF VFG(S)					RECOMMENDED	NOT APPLICABLE
28-MAY-2015		MOS HRS/MSC - AFL		(EFF)			
SB 700-24-5011	SPECIAL CHECK/MODIFICATION - ELECTRICAL GENERAL- REPLACEMENT OF ELECTRICAL OUTLETS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - COMPLETED PART A AND B
27-JAN-2017		MOS HRS/MSC - AFL		23-MAR-2018 746.13 311			
SB 700-24-5011 PART A	ACCOMPLISH SPECIAL CHECK/MODIFICATION - ELECTRICAL GENERAL- REPLACEMENT OF ELECTRICAL OUTLETS, SERVICE BULLETIN VISUAL INSPECTION OF THE UNIVERSAL ELECTRICAL OUTLETS					RECOMMENDED	COMPLIED WITH - COMPLETED PART A AND B
27-JAN-2017		MOS HRS/MSC - AFL		23-MAR-2018 746.13 311			
SB 700-24-5011 PART B	ACCOMPLISH SPECIAL CHECK/MODIFICATION - ELECTRICAL GENERAL- REPLACEMENT OF ELECTRICAL OUTLETS, SERVICE BULLETIN REPLACEMENT OF THE UNIVERSAL ELECTRICAL OUTLETS					RECOMMENDED	COMPLIED WITH - COMPLETED PART A AND B
27-JAN-2017		MOS HRS/MSC - AFL		23-MAR-2018 746.13 311			
SB 700-24-5012	SPECIAL CHECK/MODIFICATION - PRIMARY AC-POWER SUPPLY - INSPECTION OF THE VARIABLE FREQUENCY GENERATOR (VFG) HOUSING WALL THICKNESS AND IF NECESSARY REPLACEMENT OF VFG, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - COMPLIED WITH PART A AND PART B ON VFGS NO.1-S/N 4464,NO.2 S/N 4500,NO.3-S/N 4520 AND NO.4-S/N 4526.PART C NOT APPLICABLE.
04-OCT-2017		MOS HRS/MSC - AFL		23-MAR-2018 746.13 311			
SB 700-24-5012 PART A	ACCOMPLISH, SERVICE BULLETIN VFG TORQUE AND SERIAL NUMBER CHECK					RECOMMENDED	COMPLIED WITH - COMPLIED WITH PART A AND PART B ON VFGS NO.1-S/N 4464,NO.2 S/N 4500,NO.3-S/N 4520 AND NO.4-S/N 4526.PART C NOT APPLICABLE.
04-OCT-2017		MOS HRS/MSC - AFL		23-MAR-2018 746.13 311			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-24-5012 PART B	ACCOMPLISH, SERVICE BULLETIN INSPECT VFG HOUSING WALL THICKNESS					RECOMMENDED	COMPLIED WITH - COMPLIED WITH PART A AND PART B ON VFGS NO.1-S/N 4464,NO.2 S/N 4500,NO.3-S/N 4520 AND NO.4-S/N 4526.PART C NOT APPLICABLE.
04-OCT-2017		MOS		23-MAR-2018			
		HRS/MSC -		746.13			
		AFL		311			
SB 700-24-5012 PART C	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - REPLACEMENT OF VFG					RECOMMENDED	NOT APPLICABLE - COMPLIED WITH PART A AND PART B ON VFGS NO.1-S/N 4464,NO.2 S/N 4500,NO.3-S/N 4520 AND NO.4-S/N 4526.PART C NOT APPLICABLE.
04-OCT-2017		MOS		23-MAR-2018			
		HRS/MSC - (s)		746.13			
		AFL		311			
SB 700-24-5013 REV 01	MODIFICATION - CIRCUIT BREAKER - CABIN FIXED FREQUENCY MAIN CIRCUIT BREAKER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
22-NOV-2018		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
SB 700-24-5013 REV 02	MODIFICATION - CIRCUIT BREAKER - CABIN FIXED FREQUENCY MAIN CIRCUIT BREAKER, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - PCW REVISION 1 ON 05/25/2019 AT BAS-FLL.
19-JAN-2021		MOS		12-MAY-2021			
		HRS/MSC -		994.48			
		AFL		421			
SB 700-24-5014 REV 02	MODIFICATION - VARIABLE FREQUENCY GENERATOR (VFG) - MODIFICATION TO THE VFG CABLES INSTALLATION, REAR FUSELAGE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
27-SEP-2018		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
SB 700-24-5014 REV 02 PART A	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - INSTALLATION OF ADDITIONAL CLAMPS					RECOMMENDED	COMPLIED WITH
27-SEP-2018		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
SB 700-24-5014 REV 02 PART B	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - CUTTING THE ELECTRICAL WIRES TO MEET INSTALLATION REQUIREMENTS (IF NECESSARY)					RECOMMENDED	NOT APPLICABLE
27-SEP-2018		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
SB 700-24-5015	SPECIAL CHECK/MODIFICATION - EMERGENCY AC-POWER SUPPLY - REPLACEMENT OF THE RAM AIR TURBINE (RAT) DEPLOYMENT ACTUATOR PART NO. BZ02001-01 (GL456-1301-1), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - PART A - VERIFIED RAT DEPLOYMENT ACTUATOR SN 0681 INSTALLED - NO FURTHER ACTION REQUIRED
22-FEB-2019		MOS		17-AUG-2020			
		HRS/MSC -		964.77			
		AFL		403			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-24-5015 PART A	ACCOMPLISH, SERVICE BULLETIN SPECIAL CHECK					RECOMMENDED	COMPLIED WITH - VERIFIED RAT DEPLOYMENT ACTUATOR SN 0681 INSTALLED - NO FURTHER ACTION REQUIRED
22-FEB-2019		MOS HRS/MSC - AFL		17-AUG-2020 964.77 403			
SB 700-24-5015 PART B	ACCOMPLISH, SERVICE BULLETIN MODIFICATION					RECOMMENDED	NOT APPLICABLE - VERIFIED RAT DEPLOYMENT ACTUATOR SN 0681 INSTALLED - NO FURTHER ACTION REQUIRED
22-FEB-2019		MOS HRS/MSC - AFL		17-AUG-2020 964.77 403			
SB 700-25-5009	MODIFICATION - BUFFET/GALLEY - MODIFICATION OF MICROWAVE OVEN PART NO. 400-1409-01-L OR 400-1409-01-R, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
24-JUL-2013		MOS HRS/MSC - AFL					
SB 700-25-5010	SPECIAL CHECK/REWORK - GALLEY - REWORK OF THE COFFEE BREWER, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
05-SEP-2012		MOS HRS/MSC - AFL					
SB 700-25-5013	MODIFICATION - ENTRY AREA CURTAINS - REPLACEMENT OF COCKPIT CURTAIN ASSEMBLY PART NO. B6018GNTT-103 WITH CURTAIN ASSEMBLY PART NO. B6018GNTT-111, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
05-FEB-2014		MOS HRS/MSC - AFL					
SB 700-25-5016 REV 01	ICA - SPECIAL CHECK/REWORK - PASSENGER COMPARTMENT - INSPECTION AND REPLACEMENT OF EJECTOR BASE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
21-APR-2015		MOS HRS/MSC - AFL		09-OCT-2015 350.9 149			
SB 700-25-5016 REV 01 PART A	VERIFICATION ICA - SPECIAL CHECK/REWORK - PASSENGER COMPARTMENT - INSPECTION AND REPLACEMENT OF EJECTOR BASE, SERVICE BULLETIN OF INSTALLED PARTS					RECOMMENDED	COMPLIED WITH
21-APR-2015		MOS HRS/MSC - AFL		09-OCT-2015 350.9 149			
SB 700-25-5016 REV 01 PART B	REPLACEMENT ICA - SPECIAL CHECK/REWORK - PASSENGER COMPARTMENT - INSPECTION AND REPLACEMENT OF EJECTOR BASE, SERVICE BULLETIN OF THE EJECTOR BASE					RECOMMENDED	COMPLIED WITH
21-APR-2015		MOS HRS/MSC - AFL		09-OCT-2015 350.9 149			
SB 700-25-5016 REV 02	ICA - SPECIAL CHECK/REWORK - PASSENGER COMPARTMENT - REPLACEMENT OF EJECTOR BASE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
21-DEC-2015		MOS HRS/MSC - AFL		08-NOV-2016 541.13 225			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-25-5016 REV 02 PART A	VERIFICATION ICA - SPECIAL CHECK/REWORK - PASSENGER COMPARTMENT - REPLACEMENT OF EJECTOR BASE, SERVICE BULLETIN OF INSTALLED PARTS					RECOMMENDED	COMPLIED WITH
21-DEC-2015		MOS		08-NOV-2016			
		HRS/MSC	-	541.13			
		AFL		225			
SB 700-25-5016 REV 02 PART B	REPLACEMENT ICA - SPECIAL CHECK/REWORK - PASSENGER COMPARTMENT - REPLACEMENT OF EJECTOR BASE, SERVICE BULLETIN OF THE EJECTOR BASE					RECOMMENDED	COMPLIED WITH
21-DEC-2015		MOS		08-NOV-2016			
		HRS/MSC	-	541.13			
		AFL		225			
SB 700-25-5020 REV 01	SPECIAL CHECK/REWORK - EQUIPMENT RACKS - REWORK ON AFT AND FWD DECOMPRESSION PANEL ASSEMBLY SPRING PLUNGERS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
12-JAN-2018		MOS		23-MAR-2018			
		HRS/MSC	-	746.13			
		AFL		311			
SB 700-25-5024	MODIFICATION - BUFFET/GALLEY - MODIFICATION OF THE GALLEY MICROWAVE COMPARTMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - COMPLIED WITH WITH STPES 2B, 1-16 IN SB 700-25-5024
28-MAR-2018		MOS		10-MAY-2019			
		HRS/MSC	-	879.42			
		AFL		365			
SB 700-25-5024 REV 02	MODIFICATION - ANNEX/PANTRY - MODIFICATION OF THE MICROWAVE COMPARTMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
17-JAN-2019		MOS		25-MAY-2019			
		HRS/MSC	-	879.42			
		AFL		365			
SB 700-25-5025	SPECIAL CHECK/REWORK - PASSENGER COMPARTMENT - REPLACEMENT OF THE SEAT BELT EJECTOR BASE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - PART A & B ONLY
18-DEC-2018		MOS		25-MAY-2019			
		HRS/MSC	-	879.42			
		AFL		365			
SB 700-25-5025 PART A	ACCOMPLISH, SERVICE BULLETIN VERIFICATION OF INSTALLED SEAT BELTS					RECOMMENDED	COMPLIED WITH
18-DEC-2018		MOS		25-MAY-2019			
		HRS/MSC	-	879.42			
		AFL		365			
SB 700-25-5025 PART B	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF THE SEAT BELTS WITH THE TEMPORARY PARTS /MODIFIED SEAT BELTS					RECOMMENDED	COMPLIED WITH
18-DEC-2018		MOS		25-MAY-2019			
		HRS/MSC	-	879.42			
		AFL		365			
SB 700-25-5025 PART C	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF THE TEMPORARY PART WITH THE MODIFIED SEAT BELTS					RECOMMENDED	NOT APPLICABLE - LOANER BELTS NEVER INSTALLED.
18-DEC-2018		MOS		25-MAY-2019			
		HRS/MSC	-	879.42			
		AFL		365			
SB 700-25-5027	MODIFICATION - ELECTRONIC FLIGHT BAG (EFB) DISPLAY UNITS (DU) - MOD DOT 7: INTRODUCTION OF REPLACEMENT BATTERY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - PART A AND B FOR EFB'S LH SN:000874790 AND RH SN: 001025505.
11-OCT-2019		MOS		24-OCT-2019			
		HRS/MSC	-	908			
		AFL		379			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-26-5001	MODIFICATION - FIRE EXTINGUISHING SYSTEM - REPLACEMENT OF FIRE EXTINGUISHISHER CONTAINER PART NO. 473776-2, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
13-MAR-2012		MOS					
		HRS/MSC -					
		AFL					
SB 700-26-5003	SPECIAL CHECK/MODIFICATION - FIRE EXTINGUISHING SYSTEM - SQUIB CONNECTORS A111P2, A112P1 AND A111P3 WIRE LENGTHS (SUPERSEDED BY 700-26-5003 REV 01), SERVICE BULLETIN					RECOMMENDED	- SUPERSEDED - REFER REV 1
28-DEC-2017		MOS		(EFF)			
		HRS/MSC -					
		AFL					
SB 700-26-5003 REV 01	SPECIAL CHECK/MODIFICATION - FIRE EXTINGUISHING SYSTEM - SQUIB CONNECTORS A111P2, A112P1 AND A111P3 WIRE LENGTHS (SUPERSEDED BY 700-26-5003 REV 02), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
15-FEB-2018		MOS		23-MAR-2018			
		HRS/MSC -		746.13			
		AFL		311			
SB 700-26-5003 REV 02	SPECIAL CHECK/MODIFICATION - FIRE EXTINGUISHING SYSTEM - SQUIB CONNECTORS A111P2, A112P1 AND A111P3 WIRE LENGTHS (SUPERSEDED BY 700-26-5003 REV 03), SERVICE BULLETIN					RECOMMENDED	- SUPERSEDED
27-JUL-2018		MOS					
		HRS/MSC -					
		AFL					
SB 700-26-5003 REV 03	SPECIAL CHECK/MODIFICATION - FIRE EXTINGUISHING SYSTEM - SQUIB CONNECTORS A111P2, A112P1 AND A111P3 WIRE LENGTHS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - SB REV 01 WAS PCW ON MARCH 23 2018 WO-208915
24-AUG-2018		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
SB 700-27-5002	REWORK - AILERON CONTROL SYSTEM - REPLACEMENT OF THE FLANGED BUSHINGS AND HINGE BOLT ASSEMBLY ON THE INBOARD AND OUTBOARD SIDES OF THE AILERON, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
07-MAY-2012		MOS					
		HRS/MSC -					
		AFL					
SB 700-27-5003	CHECK/MODIFICATION - FLAPS AND SLATS - CHECK SLAT/FLAP ASYMMETRY BRAKE DECAL COVER FOR CORRECT INSTALLATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
28-FEB-2012		MOS					
		HRS/MSC -					
		AFL					
SB 700-27-5004 REV 01	ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO.1 AILERON PULLEY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
16-JUL-2012		MOS					
		HRS/MSC -					
		AFL					
SB 700-27-5004 REV 01 PART A	INSPECTION ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO.1 AILERON PULLEY, SERVICE BULLETIN AND REWORK					RECOMMENDED	NOT APPLICABLE
16-JUL-2012		MOS					
		HRS/MSC -					
		AFL					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-27-5004 REV 01 PART B	MODIFICATION ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO.1 AILERON PULLEY, SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE
16-JUL-2012		HRS/MSC - AFL					
SB 700-27-5004 REV 02	ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO. 1 AILERON PULLEY, SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE
17-JUN-2014		HRS/MSC - AFL					
SB 700-27-5004 REV 02 PART A	INSPECTION ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO. 1 AILERON PULLEY, SERVICE BULLETIN AND REWORK	MOS		(EFF)		RECOMMENDED	NOT APPLICABLE
17-JUN-2014		HRS/MSC - AFL					
SB 700-27-5004 REV 02 PART B	MODIFICATION ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO. 1 AILERON PULLEY, SERVICE BULLETIN	MOS		(EFF)		RECOMMENDED	NOT APPLICABLE
17-JUN-2014		HRS/MSC - AFL					
SB 700-27-5004 REV 03	ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO. 1 AILERON PULLEY, SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE
28-JUL-2014		HRS/MSC - AFL					
SB 700-27-5004 REV 03 PART A	INSPECTION ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO. 1 AILERON PULLEY, SERVICE BULLETIN AND REWORK	MOS				RECOMMENDED	NOT APPLICABLE
28-JUL-2014		HRS/MSC - AFL					
SB 700-27-5004 REV 03 PART B	MODIFICATION ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO. 1 AILERON PULLEY, SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE
28-JUL-2014		HRS/MSC - AFL					
SB 700-27-5004 REV 04	ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO.1 AILERON PULLEY, SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE
04-SEP-2014		HRS/MSC - AFL					
SB 700-27-5004 REV 04 PART A	INSPECTION ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO.1 AILERON PULLEY, SERVICE BULLETIN AND REWORK	MOS		(EFF)		RECOMMENDED	NOT APPLICABLE
04-SEP-2014		HRS/MSC - AFL					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-27-5004 REV 04 PART B	MODIFICATION ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO.1 AILERON PULLEY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
04-SEP-2014		MOS HRS/MSC - AFL		(EFF)			
SB 700-27-5009 REV 01	SPECIAL CHECK/MODIFICATION - ELEVATOR CONTROL SYSTEM - INSPECT AND REPLACE (IF NECESSARY) ELEVATOR BRACKETS, PART NO. GD248-8750-3 AND GD248-8750-4, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - C/W PART A, PART B NOT REQUIRED.
18-JUL-2017		MOS HRS/MSC - AFL		23-MAR-2018 746.13 311			
SB 700-27-5009 REV 01 PART A	ACCOMPLISH SPECIAL CHECK/MODIFICATION - ELEVATOR CONTROL SYSTEM - INSPECT AND REPLACE (IF NECESSARY) ELEVATOR BRACKETS, PART NO. GD248-8750-3 AND GD248-8750-4, SERVICE BULLETIN INSPECTION / NDT OF THE ELEVATOR BRACKETS					RECOMMENDED	COMPLIED WITH - C/W PART A, PART B NOT REQUIRED.
18-JUL-2017		MOS HRS/MSC - AFL		23-MAR-2018 746.13 311			
SB 700-27-5009 REV 01 PART B	ACCOMPLISH SPECIAL CHECK/MODIFICATION - ELEVATOR CONTROL SYSTEM - INSPECT AND REPLACE (IF NECESSARY) ELEVATOR BRACKETS, PART NO. GD248-8750-3 AND GD248-8750-4, SERVICE BULLETIN REPLACEMENT OF THE ELEVATOR BRACKET					RECOMMENDED	NOT APPLICABLE - C/W PART A, PART B NOT REQUIRED.
18-JUL-2017		MOS HRS/MSC - AFL		23-MAR-2018 746.13 311			
SB 700-27-5009 REV 02	SPECIAL CHECK/MODIFICATION - ELEVATOR CONTROL SYSTEM - INSPECT AND REPLACE (IF NECESSARY) ELEVATOR BRACKETS, PART NO. GD248-8750-3 AND GD248-8750-4, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - PCW REV 1 - MARCH 2018
15-JUN-2018		MOS HRS/MSC - AFL		25-MAY-2019 879.42 365			
SB 700-27-5009 REV 02 PART A	ACCOMPLISH, SERVICE BULLETIN INSPECTION / NDT OF THE ELEVATOR BRACKETS					RECOMMENDED	NOT APPLICABLE - PCW REV 1 - MARCH 2018
15-JUN-2018		MOS HRS/MSC - AFL		25-MAY-2019 879.42 365			
SB 700-27-5009 REV 02 PART B	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF THE ELEVATOR BRACKET					RECOMMENDED	NOT APPLICABLE - PCW REV 1 - MARCH 2018
15-JUN-2018		MOS HRS/MSC - AFL		25-MAY-2019 879.42 365			
SB 700-27-5010	MODIFICATION - STALL PROTECTION SYSTEM - ENABLE THE STICK PUSHER OVERRIDE FUNCTION OF THE MASTER DISCONNECT SWITCH FOR CONFIGURATIONS OTHER THAN JAA, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
17-MAR-2020		MOS HRS/MSC - AFL					
SB 700-27-5012	SPECIAL CHECK - ELEVATOR CONTROL SYSTEM - INSPECTION OF TORQUE TUBE BEARINGS, SERVICE BULLETIN					RECOMMENDED	
23-JUL-2020		MOS HRS/MSC - AFL		(EFF)			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-27-5012 REV 01	SPECIAL CHECK - ELEVATOR CONTROL SYSTEM - INSPECTION OF TORQUE TUBE BEARINGS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
07-DEC-2020		MOS HRS/MSC - AFL		24-NOV-2021 1023.57 435			
SB 700-27-5012 REV 01 PART A	ACCOMPLISH, SERVICE BULLETIN BEARINGS INSPECTION					RECOMMENDED	COMPLIED WITH
07-DEC-2020		MOS HRS/MSC - AFL		24-NOV-2021 1023.57 435			
SB 700-27-5012 REV 01 PART B	ACCOMPLISH, SERVICE BULLETIN BEARINGS REPLACEMENT					RECOMMENDED	NOT APPLICABLE
07-DEC-2020		MOS HRS/MSC - AFL		24-NOV-2021 1023.57 435			
SB 700-27-5014	SPECIAL CHECK - FLAP SYSTEM - INSPECTION OF FORWARD AND AFT INBOARD FLAP SPIGOT TUBES FOR CORROSION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
31-MAR-2021		MOS HRS/MSC - AFL		24-NOV-2021 1023.57 435			
SB 700-28-5001 REV 01	MODIFICATION - FUEL TRANSFER SYSTEM - DESIGN IMPROVEMENT TO THE CENTER TRANSFER PUMP, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
14-SEP-2012		MOS HRS/MSC - AFL					
SB 700-29-5002 PART A	INSPECTION SPECIAL CHECK/REWORK - NO. 1, NO. 2 AND NO. 3 HYDRAULIC SYSTEM - ADDITION OF CLAMPS TO HYDRAULIC TUBES IN MLG BAY AND UNDER ACCESS PANEL 185BL, SERVICE BULLETIN OF HYDRAULIC TUBES					RECOMMENDED	NOT APPLICABLE
19-MAR-2012		MOS HRS/MSC - AFL					
SB 700-29-5002 PART B	ADJUSTMENT SPECIAL CHECK/REWORK - NO. 1, NO. 2 AND NO. 3 HYDRAULIC SYSTEM - ADDITION OF CLAMPS TO HYDRAULIC TUBES IN MLG BAY AND UNDER ACCESS PANEL 185BL, SERVICE BULLETIN OF HYDRAULIC TUBES LOCATION					RECOMMENDED	NOT APPLICABLE
19-MAR-2012		MOS HRS/MSC - AFL					
SB 700-29-5003 PART A	ACCOMPLISH MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - REPLACEMENT OF ENGINE DRIVEN PUMP (EDP) V-BAND COUPLING CLAMP, SERVICE BULLETIN INSPECTION					RECOMMENDED	NOT APPLICABLE
06-OCT-2011		MOS HRS/MSC - AFL					
SB 700-29-5003 PART B	ACCOMPLISH MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - REPLACEMENT OF ENGINE DRIVEN PUMP (EDP) V-BAND COUPLING CLAMP, SERVICE BULLETIN EDP V-BAND COUPLING CLAMP REPLACEMENT					RECOMMENDED	NOT APPLICABLE
06-OCT-2011		MOS HRS/MSC - AFL					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-29-5005	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - HYDRAULIC FIREWALL SHUT-OFF VALVES (HF5OV) INTRODUCTION OF IMPROVED ACTUATOR AS A SEPARATE LRU PART NO. 975237-501 (GX473-0126-1), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
15-JUL-2013		MOS		23-APR-2014			
		HRS/MSC -		15.4			
		AFL		7			
SB 700-29-5006	MODIFICATION - NO. 3 HYDRAULIC SYSTEM - REPLACEMENT OF RAT ACCUMULATOR, PART NO. GX473-0100-5 WITH RAT ACCUMULATOR, PART NO. GX473-0100-7, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - INSTALLED NEW ACCUMULATOR P/N GX473-0100-7, S/N 60190-3040
27-JUN-2014		MOS		16-AUG-2014			
		HRS/MSC -		114.5			
		AFL		45			
SB 700-29-5007	MODIFICATION - NO. 3 HYDRAULIC SYSTEM - INSPECTION OF RAT ACCUMULATOR END CAPS, PART NO. 900094-5 (GX473-0100-5), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
18-JUL-2014		MOS					
		HRS/MSC -					
		AFL					
SB 700-29-5007 PART A	MODIFICATION MODIFICATION - NO. 3 HYDRAULIC SYSTEM - INSPECTION OF RAT ACCUMULATOR END CAPS, PART NO. 900094-5 (GX473-0100-5), SERVICE BULLETIN - MARKING OF SUFFIX "E" AT THE END OF ACCUMULATOR SERIAL NO.					RECOMMENDED	NOT APPLICABLE
18-JUL-2014		MOS		(EFF)			
		HRS/MSC -					
		AFL					
SB 700-29-5007 PART B	MODIFICATION MODIFICATION - NO. 3 HYDRAULIC SYSTEM - INSPECTION OF RAT ACCUMULATOR END CAPS, PART NO. 900094-5 (GX473-0100-5), SERVICE BULLETIN - REMOVAL - INSTALLATION OF NEW ACCUMULATOR (FOR ALL ACCUMULATORS, PART NO. 900094-5 NOT LISTED IN PART A AND WITHOUT "E" OR "ENA" SUFFIX)					RECOMMENDED	NOT APPLICABLE
18-JUL-2014		MOS		(EFF)			
		HRS/MSC -					
		AFL					
SB 700-29-5008	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - NEW PRESSURE LINE AND BRACKET IN AFT EQUIPMENT BAY HYDRAULIC SYSTEM NO. 1, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - C/W SB 700-29-5008
15-JUL-2016		MOS		23-MAR-2018			
		HRS/MSC -		746.13			
		AFL		311			
SB 700-29-5008 REV 02	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - NEW PRESSURE LINE AND BRACKET IN AFT EQUIPMENT BAY HYDRAULIC SYSTEM NO. 1, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - PART B - RETROACTIVE ACTION - PCW PART A BASIC ISSUE
		MOS		17-AUG-2020			
		HRS/MSC -		964.77			
		AFL		403			
SB 700-29-5008 REV 02 PART A	ACCOMPLISH, SERVICE BULLETIN MODIFICATION APPLICABLE TO AIRCRAFT ON WHICH BASIC ISSUE OF THIS SERVICE BULLETIN IS NOT INCORPORATED					RECOMMENDED	NOT APPLICABLE - PCW PART A BASIC ISSUE
08-JUN-2020		MOS		17-AUG-2020			
		HRS/MSC -		964.77			
		AFL		403			
SB 700-29-5008 REV 02 PART B	ACCOMPLISH, SERVICE BULLETIN RETROACTIVE ACTION OF THIS SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - PART B - RETROACTIVE ACTION - PCW PART A BASIC ISSUE
08-JUN-2020		MOS		17-AUG-2020			
		HRS/MSC -		964.77			
		AFL		403			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-29-5008 REV 04	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - NEW PRESSURE LINE AND BRACKET IN AFT EQUIPMENT BAY HYDRAULIC SYSTEM NO. 1, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - PREVIOUSLY COMPLIED WITH NO WORK PERFORMED DUE TO RETROACTIVE ACTION.
26-APR-2021		MOS		24-NOV-2021			
		HRS/MSC -		1023.57			
		AFL		435			
SB 700-29-5008 REV 04 PART A	ACCOMPLISH, SERVICE BULLETIN MODIFICATION APPLICABLE TO AIRCRAFT ON WHICH BASIC ISSUE OF THIS SERVICE BULLETIN IS NOT INCORPORATED					RECOMMENDED	NOT APPLICABLE - PREVIOUSLY COMPLIED WITH NO WORK PERFORMED DUE TO RETROACTIVE ACTION.
26-APR-2021		MOS		24-NOV-2021			
		HRS/MSC -		1023.57			
		AFL		435			
SB 700-29-5008 REV 04 PART B	ACCOMPLISH, SERVICE BULLETIN RETROACTIVE ACTION OF THIS SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - PREVIOUSLY COMPLIED WITH NO WORK PERFORMED DUE TO RETROACTIVE ACTION.
26-APR-2021		MOS		24-NOV-2021			
		HRS/MSC -		1023.57			
		AFL		435			
SB 700-29-5008 REV 04 PART C	ACCOMPLISH, SERVICE BULLETIN INSPECTION IN PYLON					RECOMMENDED	NOT APPLICABLE - PREVIOUSLY COMPLIED WITH NO WORK PERFORMED DUE TO RETROACTIVE ACTION.
26-APR-2021		MOS		24-NOV-2021			
		HRS/MSC -		1023.57			
		AFL		435			
SB 700-29-5009 REV 02	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - ADDITION OF SUPPORT BRACKET ON THE CASE DRAIN LINE (SUPERSEDED BY 700-29-5009 REV 03), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - C/W SB 700-29-5009 R02
22-JAN-2019		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
SB 700-30-5001	MODIFICATION - ANTI-ICING SYSTEM - PART NO. CHANGE OF THE WING ANTI-ICE VALVE (WAIV) TO GG436-4001-13, SERVICE BULLETIN						COMPLIED WITH
11-DEC-2013		MOS		23-APR-2014			
		HRS/MSC -		15.4			
		AFL		7			
SB 700-31-5001	MODIFICATION - QUICK ACCESS RECORDER SYSTEM - INTRODUCTION OF A QUICK ACCESS RECORDER (QAR), SERVICE BULLETIN						COMPLIED WITH
		MOS		23-APR-2014			
		HRS/MSC -		15.4			
		AFL		7			
SB 700-31-5002 REV 01	MODIFICATION - FLIGHT DATA RECORDING (FDR) SYSTEM - INSTALLATION OF THE FORCE TRANSDUCER UNITS (FTU) AND ACTIVATION OF THE CREW FORCE MEASURING SYSTEM (CFMS) 2002, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
04-NOV-2016		MOS					
		HRS/MSC -					
		AFL					
SB 700-32-5004	ICA - SPECIAL CHECK/MODIFICATION - BRAKE CONTROL UNIT (BCU) - INSPECTION AND REPLACEMENT OF PART NUMBER 42-965-2 WITH INCORRECT ZENER DIODES INSTALLED, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
29-APR-2013		MOS					
		HRS/MSC -					
		AFL					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-32-5004 PART A	INSPECTION ICA - SPECIAL CHECK/MODIFICATION - BRAKE CONTROL UNIT (BCU) - INSPECTION AND REPLACEMENT OF PART NUMBER 42-965-2 WITH INCORRECT ZENER DIODES INSTALLED, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
29-APR-2013		MOS					
		HRS/MSC -					
		AFL					
SB 700-32-5004 PART B	REMOVE ICA - SPECIAL CHECK/MODIFICATION - BRAKE CONTROL UNIT (BCU) - INSPECTION AND REPLACEMENT OF PART NUMBER 42-965-2 WITH INCORRECT ZENER DIODES INSTALLED, SERVICE BULLETIN AND REPLACE THE BCU					RECOMMENDED	NOT APPLICABLE
29-APR-2013		MOS					
		HRS/MSC -					
		AFL					
SB 700-32-5005	MODIFICATION - BRAKE CONTROL SYSTEM - INSPECTION OF HYDRAULIC SYSTEM NO. 2 OUTBOARD BRAKE ACCUMULATOR, PART NO. GW415-1250-1 (24550-101), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
08-OCT-2014		MOS					
		HRS/MSC -					
		AFL					
SB 700-32-5005 PART A	INSPECTION MODIFICATION - BRAKE CONTROL SYSTEM - INSPECTION OF HYDRAULIC SYSTEM NO. 2 OUTBOARD BRAKE ACCUMULATOR, PART NO. GW415-1250-1 (24550-101), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
08-OCT-2014		MOS		(EFF)			
		HRS/MSC -					
		AFL					
SB 700-32-5005 PART B	MODIFICATION MODIFICATION - BRAKE CONTROL SYSTEM - INSPECTION OF HYDRAULIC SYSTEM NO. 2 OUTBOARD BRAKE ACCUMULATOR, PART NO. GW415-1250-1 (24550-101), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
08-OCT-2014		MOS		(EFF)			
		HRS/MSC -					
		AFL					
SB 700-32-5006	MODIFICATION - BRAKE CONTROL SYSTEM - INSPECTION OF HYDRAULIC SYSTEM NO. 3 INBOARD BRAKE ACCUMULATOR, PART NO. GW415-1200-1 (33-119500), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
09-OCT-2014		MOS					
		HRS/MSC -					
		AFL					
SB 700-32-5006 PART A	MODIFICATION - BRAKE CONTROL SYSTEM - INSPECTION OF HYDRAULIC SYSTEM NO. 3 INBOARD BRAKE ACCUMULATOR, PART NO. GW415-1200-1 (33-119500), SERVICE BULLETIN MODIFICATION - MARKING OF SUFFIX "E" AT THE END OF ACCUMULATOR SERIAL NO.					RECOMMENDED	NOT APPLICABLE
09-OCT-2014		MOS		(EFF)			
		HRS/MSC -					
		AFL					
SB 700-32-5006 PART B	MODIFICATION - BRAKE CONTROL SYSTEM - INSPECTION OF HYDRAULIC SYSTEM NO. 3 INBOARD BRAKE ACCUMULATOR, PART NO. GW415-1200-1 (33-119500), SERVICE BULLETIN MODIFICATION - REMOVAL - INSTALLATION OF NEW ACCUMULATOR					RECOMMENDED	NOT APPLICABLE
09-OCT-2014		MOS		(EFF)			
		HRS/MSC -					
		AFL					
SB 700-32-5010	REWORK - BRAKE CONTROL SYSTEM - APPLICATION OF SEALANT AT THE AXLE TRAILING ARM AND WHEEL SPEED TRANSDUCER-HARNESS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
01-APR-2015		MOS		09-OCT-2015			
		HRS/MSC -		350.9			
		AFL		149			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-32-5010 REV 01	REWORK - BRAKE CONTROL SYSTEM - APPLICATION OF SEALANT AT THE AXLE TRAILING ARM AND WHEEL SPEED TRANSDUCER-HARNESS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
15-OCT-2015		MOS		11-NOV-2016			
		HRS/MSC -		541.13			
		AFL		225			
SB 700-32-5011 REV 01	ICA - SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
26-AUG-2015		MOS		09-OCT-2015			
		HRS/MSC -		350.9			
		AFL		149			
SB 700-32-5011 REV 01 PART A	VISUAL INSPECTION ICA - SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN OF THE BOLT THAT SECURES THE RETRACTION ACTUATOR TO THE NLG STRUT					RECOMMENDED	COMPLIED WITH
26-AUG-2015		MOS		09-OCT-2015			
		HRS/MSC -		350.9			
		AFL		149			
SB 700-32-5011 REV 01 PART B	ICA - SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN NLG STRUT IDENTIFICATION PLATE MODIFICATION NUMBER CHECK					RECOMMENDED	NOT APPLICABLE - PER SERIAL NUMBER
26-AUG-2015		MOS		09-OCT-2015			
		HRS/MSC -		350.9			
		AFL		149			
SB 700-32-5011 REV 01 PART C	INSTALLATION ICA - SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN OF THE NEW ATTACHMENT HARDWARE SECURING THE RETRACTION ACTUATOR TO NLG STRUT					RECOMMENDED	COMPLIED WITH
26-AUG-2015		MOS		09-OCT-2015			
		HRS/MSC -		350.9			
		AFL		149			
SB 700-32-5011 REV 02	SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - REVISION 1 PREVIOUSLY COMPLIED WITH ON LOG ENTRY DATED OCT 9,2015 @ 350.9 HRS AND 149 CYC.PER SB 700-32-5011 REV.2 REVISION 2 PART A,B AND C IS N/A.
06-NOV-2017		MOS		23-MAR-2018			
		HRS/MSC -		746.13			
		AFL		311			
SB 700-32-5011 REV 02 PART A	ACCOMPLISH SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN VISUAL INSPECTION OF THE BOLT THAT SECURES THE RETRACTION ACTUATOR TO THE NLG STRUT					RECOMMENDED	NOT APPLICABLE - REVISION 2 PART A,B AND C IS N/A
06-NOV-2017		MOS		23-MAR-2018			
		HRS/MSC -		746.13			
		AFL		311			
SB 700-32-5011 REV 02 PART B	ACCOMPLISH SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN NLG STRUT IDENTIFICATION PLATE MODIFICATION NUMBER CHECK					RECOMMENDED	NOT APPLICABLE - REVISION 2 PART A,B AND C IS N/A
06-NOV-2017		MOS		23-MAR-2018			
		HRS/MSC -		746.13			
		AFL		311			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-32-5011 REV 02 PART C	ACCOMPLISH SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN INSTALLATION OF THE NEW ATTACHMENT HARDWARE SECURING THE RETRACTION ACTUATOR TO NLG STRUT					RECOMMENDED	NOT APPLICABLE - REVISION 2 PART A,B AND C IS N/A
06-NOV-2017		MOS HRS/MSC - AFL		23-MAR-2018 746.13 311			
SB 700-32-5015	SPECIAL CHECK/REWORK - MAIN LANDING GEAR (MLG) - INSPECTION OF SEALANT AT THE AXLE END CAP, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
16-JUN-2017		MOS HRS/MSC - AFL					
SB 700-32-5015 PART A	ACCOMPLISH SPECIAL CHECK/REWORK - MAIN LANDING GEAR (MLG) - INSPECTION OF SEALANT AT THE AXLE END CAP, SERVICE BULLETIN VISUAL CHECK OF THE SEALANT AT THE AXLE END CAP					RECOMMENDED	NOT APPLICABLE
16-JUN-2017		MOS HRS/MSC - AFL		(EFF)			
SB 700-32-5015 PART B	ACCOMPLISH SPECIAL CHECK/REWORK - MAIN LANDING GEAR (MLG) - INSPECTION OF SEALANT AT THE AXLE END CAP, SERVICE BULLETIN SEALANT APPLICATION					RECOMMENDED	NOT APPLICABLE
16-JUN-2017		MOS HRS/MSC - AFL		(EFF)			
SB 700-32-5016	SPECIAL CHECK - MAIN LANDING GEAR - TRAILING ARM ASSEMBLY INSPECTION OF THE PAINT IN THE AXLE BORE (SUPERSEDED BY 700-32-5016 REV 01), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
03-MAY-2019		MOS HRS/MSC - AFL		25-MAY-2019 879.42 365			
SB 700-32-5016 PART A	ACCOMPLISH SPECIAL CHECK - MAIN LANDING GEAR - TRAILING ARM ASSEMBLY INSPECTION OF THE PAINT IN THE AXLE BORE (SUPERSEDED BY 700-32-5016 REV 01), SERVICE BULLETIN INSPECTION OF PART NUMBER AND SERIAL NUMBER					RECOMMENDED	COMPLIED WITH
03-MAY-2019		MOS HRS/MSC - AFL		25-MAY-2019 879.42 365			
SB 700-32-5016 PART B	ACCOMPLISH SPECIAL CHECK - MAIN LANDING GEAR - TRAILING ARM ASSEMBLY INSPECTION OF THE PAINT IN THE AXLE BORE (SUPERSEDED BY 700-32-5016 REV 01), SERVICE BULLETIN FIRST INSPECTION					RECOMMENDED	NOT APPLICABLE - PER S/N INSTALLED
03-MAY-2019		MOS HRS/MSC - AFL		25-MAY-2019 879.42 365			
SB 700-32-5016 PART C	ACCOMPLISH SPECIAL CHECK - MAIN LANDING GEAR - TRAILING ARM ASSEMBLY INSPECTION OF THE PAINT IN THE AXLE BORE (SUPERSEDED BY 700-32-5016 REV 01), SERVICE BULLETIN SECOND INSPECTION					RECOMMENDED	NOT APPLICABLE - PER S/N INSTALLED
03-MAY-2019		MOS HRS/MSC - (s) AFL		25-MAY-2019 879.42 365			
SB 700-32-5016 PART D	ACCOMPLISH SPECIAL CHECK - MAIN LANDING GEAR - TRAILING ARM ASSEMBLY INSPECTION OF THE PAINT IN THE AXLE BORE (SUPERSEDED BY 700-32-5016 REV 01), SERVICE BULLETIN PRIMER AND PAINT REPLACEMENT					RECOMMENDED	NOT APPLICABLE - PER S/N INSTALLED
03-MAY-2019		MOS HRS/MSC - (s) AFL		25-MAY-2019 879.42 365			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-32-5016 REV 01	SPECIAL CHECK - MAIN LANDING GEAR - TRAILING ARM ASSEMBLY INSPECTION OF THE PAINT IN THE AXLE BORE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - PCW SB 700-32-5016 BASIC AT BAS-FLL ON 13 MAY 2019: W/O: 214767
27-NOV-2019		MOS		05-FEB-2020			
		HRS/MSC -		933.42			
		AFL		390			
SB 700-32-5016 REV 01 PART A	ACCOMPLISH, SERVICE BULLETIN INSPECTION OF PART NUMBER AND SERIAL NUMBER					RECOMMENDED	NOT APPLICABLE - PCW SB 700-32-5016 BASIC AT BAS-FLL ON 13 MAY 2019: W/O: 214767
27-NOV-2019		MOS		05-FEB-2020			
		HRS/MSC -		933.42			
		AFL		390			
SB 700-32-5016 REV 01 PART B	ACCOMPLISH, SERVICE BULLETIN FIRST INSPECTION						NOT APPLICABLE - PCW SB 700-32-5016 BASIC AT BAS-FLL ON 13 MAY 2019: W/O: 214767
27-NOV-2019		MOS		05-FEB-2020			
		HRS/MSC -		933.42			
		AFL		390			
SB 700-32-5016 REV 01 PART C	ACCOMPLISH, SERVICE BULLETIN SECOND INSPECTION					RECOMMENDED	NOT APPLICABLE - PCW SB 700-32-5016 BASIC AT BAS-FLL ON 13 MAY 2019: W/O: 214767
27-NOV-2019		MOS		05-FEB-2020			
		HRS/MSC - (s)		933.42			
		AFL		390			
SB 700-32-5016 REV 01 PART D	ACCOMPLISH, SERVICE BULLETIN PRIMER AND PAINT REPLACEMENT					RECOMMENDED	NOT APPLICABLE - PCW SB 700-32-5016 BASIC AT BAS-FLL ON 13 MAY 2019: W/O: 214767
27-NOV-2019		MOS		05-FEB-2020			
		HRS/MSC -		933.42			
		AFL		390			
SB 700-32-5017	MODIFICATION - BRAKE CONTROL SYSTEM - LH AND RH ASSEMBLY REPLACEMENT OF THE SWIVEL JOINT ASSEMBLIES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
31-JAN-2019		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
SB 700-32-5019 REV 01	MODIFICATION - MLG - MAIN LANDING GEAR ASSEMBLY IMPROVED RESISTANCE TO WATER INGRESS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
11-FEB-2021		MOS		24-NOV-2021			
		HRS/MSC -		1023.57			
		AFL		435			
SB 700-32-5021	MODIFICATION - NOSEWHEEL-STEERING CONTROL SYSTEM - REPLACEMENT OF THE STEERING SOLENOID VALVE, SERVICE BULLETIN					RECOMMENDED	
24-NOV-2022		MOS	60	(EBT)	24-NOV-2027		
		HRS/MSC					
		AFL					
	NEW REQUIREMENT ADDED ON 25-NOV-2022 (EFFECTIVE: 24-NOV-2022). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.						
SB 700-32-5022	MODIFICATION - BRAKE CONTROL SYSTEM - REPLACEMENT OF BRAKE CONTROL UNIT (BCU), SERVICE BULLETIN					RECOMMENDED	
25-MAY-2022		MOS	48	(EFF)	25-MAY-2026		
		HRS/MSC					
		AFL					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-33-5002	SPECIAL CHECK - SERVICE COMPARTMENT LIGHTING - TORQUE CHECK OF TOGGLE SWITCHES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - PER SB
	30-JUN-2021	MOS		27-AUG-2021			
		HRS/MSC -		1012.88			
		AFL		430			
SB 700-34-5002	MODIFICATION - TRAFFIC COLLISION AVOIDANCE SYSTEM (TCAS)INSTALLATION OF LOWER DIRECTIONAL TRAFFIC SURVEILLANCE SYSTEM (TSS) ANTENNA, SERVICE BULLETIN						COMPLIED WITH
		MOS		23-APR-2014			
		HRS/MSC -		15.4			
		AFL		7			
SB 700-34-5002 REV 01	MODIFICATION - TRAFFIC COLLISION AVOIDANCE SYSTEM (TCAS) - INSTALLATION OF LOWER DIRECTIONAL TRAFFIC SURVEILLANCE SYSTEM (TSS) ANTENNA, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
	14-MAY-2013	MOS					
		HRS/MSC -					
		AFL					
SB 700-34-5003 REV 01	MODIFICATION - SYNTHETIC VISION SYSTEM - INSTALLATION OF A SECOND SYNTHETIC VISION SYSTEM, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
	24-NOV-2015	MOS					
		HRS/MSC -					
		AFL					
SB 700-34-5004	MODIFICATION - HEAD-UP DISPLAY (SVS) - INSTALLATION OF HEAD-UP DISPLAY (HUD) SYSTEM., SERVICE BULLETIN						COMPLIED WITH
		MOS		23-APR-2014			
		HRS/MSC -		15.4			
		AFL		7			
SB 700-34-5005 REV 01	MODIFICATION - ENHANCED VISION SYSTEM (EVS) - INSTALLATION OF EVS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
	21-DEC-2012	MOS		23-APR-2014			
		HRS/MSC -		12.8			
		AFL		6			
SB 700-34-5005 REV 01 PART A	RETROFIT MODIFICATION - ENHANCED VISION SYSTEM (EVS) - INSTALLATION OF EVS, SERVICE BULLETIN OF ISU					RECOMMENDED	COMPLIED WITH
	21-DEC-2012	MOS		23-APR-2014			
		HRS/MSC -		12.8			
		AFL		6			
SB 700-34-5005 REV 01 PART B	INSTALLATION MODIFICATION - ENHANCED VISION SYSTEM (EVS) - INSTALLATION OF EVS, SERVICE BULLETIN OF EVS					RECOMMENDED	COMPLIED WITH
	21-DEC-2012	MOS		23-APR-2014			
		HRS/MSC -		12.8			
		AFL		6			
SB 700-34-5006	MODIFICATION - FLIGHT MANAGEMENT SYSTEM - INTRODUCTION OF HARDWARE/SOFTWARE UPDATES TO SUPPORT VNAV FUNCTIONALITY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
	16-APR-2012	MOS					
		HRS/MSC -					
		AFL					
SB 700-34-5008 REV 01	MODIFICATION - TERRAIN AWARENESS WARNING SYSTEM (TAWS) - ACTIVATION OF WINDSHEAR DETECTION ALERT AND WINDSHEAR ESCAPE GUIDANCE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
	20-AUG-2012	MOS					
		HRS/MSC -					
		AFL					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-34-5010 REV 01	MODIFICATION - GENERAL - AVIONIC SYSTEM UPDATES TO SUPPORT INTRODUCTION OF FMS 3, TOLD, ECL, FMS SPEED CONTROL AND RNP AR (SUPERSEDED BY SB 700-34-5017 REV 3), SERVICE BULLETIN					INFORMATIONAL	NOT APPLICABLE - SUPERSEDED BY SB 700-34-5017
13-SEP-2013		MOS		23-APR-2014			
		HRS/MSC -		12.8			
		AFL		6			
SB 700-34-5012	SPECIAL CHECK/MODIFICATION - DISTANCE MEASURING EQUIPMENT (DME) SYSTEM - INSPECTION OF IMPROPERLY CRIMPED TERMINAL FORK CONTACTS ON DME NO. 1 AND NO. 2, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
05-JUN-2013		MOS					
		HRS/MSC -					
		AFL					
SB 700-34-5013	SPECIAL CHECK/MODIFICATION - VHF COMMUNICATION AND VHF NAVIGATION SYSTEMS - INSPECTION OF IMPROPERLY CRIMPED TERMINAL FORK CONTACTS ON VHF COMMUNICATION UNITS NO. 1 AND NO. 3 AND VHF NAVIGATION UNIT NO. 1, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
12-JUN-2013		MOS					
		HRS/MSC -					
		AFL					
SB 700-34-5014	SPECIAL CHECK/MODIFICATION - VHF COMMUNICATION AND VHF NAVIGATION SYSTEMS - INSPECTION OF IMPROPERLY CRIMPED TERMINAL FORK CONTACTS ON VHF COMMUNICATION UNIT NO. 2, VHF NAVIGATION UNIT NO. 2 AND AIR TRAFFIC CONTROL (ATC) TRANSPONDER (TDR), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
17-JUN-2013		MOS					
		HRS/MSC -					
		AFL					
SB 700-34-5015	SPECIAL CHECK/MODIFICATION - RADIO ALTIMETER SYSTEM - INSPECTION OF IMPROPERLY CRIMPED TERMINAL FORK CONTACTS ON RADIO ALTIMETER TRANSCEIVERS NO. 1 AND NO. 2, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
17-JUN-2013		MOS					
		HRS/MSC -					
		AFL					
SB 700-34-5016	MODIFICATION - GENERAL - ACTIVATION OF THE STEEP APPROACH OPTION - GLIDEPATH ANGLES FROM 4.5 TO 5.5 DEGREES (SUPERSEDED BY 700-34-5016 REV 01), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
17-FEB-2014		MOS					
		HRS/MSC -					
		AFL					
SB 700-34-5016 REV 01	MODIFICATION - GENERAL - ACTIVATION OF THE STEEP APPROACH OPTION - GLIDEPATH ANGLES FROM 4.5 TO 5.5 DEGREES (SUPERSEDED BY 700-34-5016 REV 02), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
24-JUL-2014		MOS					
		HRS/MSC -					
		AFL					
SB 700-34-5016 REV 02	MODIFICATION - GENERAL - ACTIVATION OF THE STEEP APPROACH OPTION - GLIDEPATH ANGLES FROM 4.5 TO 5.5 DEGREES (SUPERSEDED BY 700-34-5016 REV 03), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
22-OCT-2015		MOS					
		HRS/MSC -					
		AFL					
SB 700-34-5016 REV 03	MODIFICATION - GENERAL - ACTIVATION OF THE STEEP APPROACH OPTION GLIDEPATH ANGLES FROM 4.5 TO 5.5 DEGREES, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
12-FEB-2020		MOS					
		HRS/MSC -					
		AFL					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-34-5017 REV 03	MODIFICATION - GENERAL - AVIONIC SYSTEM UPDATES AND REMOVAL OF SVS LIMITATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
19-NOV-2013		MOS		23-APR-2014			
		HRS/MSC -		12.8			
		AFL		6			
SB 700-34-5017 REV 03 PART A	MODIFICATION - GENERAL - AVIONIC SYSTEM UPDATES AND REMOVAL OF SVS LIMITATION, SERVICE BULLETIN CTP REPLACEMENT					RECOMMENDED	COMPLIED WITH
19-NOV-2013		MOS		23-APR-2014			
		HRS/MSC -		12.8			
		AFL		6			
SB 700-34-5017 REV 03 PART B	MODIFICATION - GENERAL - AVIONIC SYSTEM UPDATES AND REMOVAL OF SVS LIMITATION, SERVICE BULLETIN SOFTWARE LOADING					RECOMMENDED	COMPLIED WITH
19-NOV-2013		MOS		23-APR-2014			
		HRS/MSC -		12.8			
		AFL		6			
SB 700-34-5018 REV 03	MODIFICATION - GENERAL - IMPLEMENTATION OF AUTOMATIC DEPENDENT SURVEILLANCE - BROADCAST OUT (ADS-B OUT) (DO-260B) AND AERONAUTICAL TELECOMMUNICATIONS NETWORK (ATN) CONTROLLER PILOT DATA-LINK COMMUNICATIONS (CPDLC) CAPABILITY (LINK2000+) (SUPERSEDED BY 700-34-5018 REV 04), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
14-FEB-2019		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
SB 700-34-5020 REV 01	MODIFICATION - TERRAIN AWARENESS AND WARNING SYSTEM (TAWS) - CCM CSO DATABASE CHANGE FOR MODE 6 AURAL WARNINGS +6DB VOLUME INCREASE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
07-NOV-2016		MOS					
		HRS/MSC -					
		AFL					
SB 700-34-5021 REV 03	MODIFICATION - GENERAL - IMPLEMENTATION OF GLOBAL VISION FLIGHT DECK AVIONICS SOFTWARE VERSION 5, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
05-JAN-2018		MOS		23-MAR-2018			
		HRS/MSC -		746.13			
		AFL		311			
SB 700-34-5022	SPECIAL CHECK/MODIFICATION - STANDBY COMPASS SYSTEM - INSPECTION AND REPLACEMENT OF ELECTRICAL LEAD ASSEMBLY FOR STANDBY COMPASS PART NO. WL1001KCA1, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
27-JUN-2016		MOS					
		HRS/MSC -					
		AFL					
SB 700-34-5022 PART A	ACCOMPLISH SPECIAL CHECK/MODIFICATION - STANDBY COMPASS SYSTEM - INSPECTION AND REPLACEMENT OF ELECTRICAL LEAD ASSEMBLY FOR STANDBY COMPASS PART NO. WL1001KCA1, SERVICE BULLETIN INSPECTION ON THE STANDBY COMPASS AND LEAD ASSEMBLY					RECOMMENDED	NOT APPLICABLE
27-JUN-2016		MOS					
		HRS/MSC -					
		AFL					
SB 700-34-5022 PART B	ACCOMPLISH SPECIAL CHECK/MODIFICATION - STANDBY COMPASS SYSTEM - INSPECTION AND REPLACEMENT OF ELECTRICAL LEAD ASSEMBLY FOR STANDBY COMPASS PART NO. WL1001KCA1, SERVICE BULLETIN VISUAL CHECK OF THE "Y" SOCKET END OF THE WIRE AND INSULATION RESISTANCE TEST					RECOMMENDED	NOT APPLICABLE
27-JUN-2016		MOS					
		HRS/MSC -					
		AFL					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-34-5022 PART C	ACCOMPLISH SPECIAL CHECK/MODIFICATION - STANDBY COMPASS SYSTEM - INSPECTION AND REPLACEMENT OF ELECTRICAL LEAD ASSEMBLY FOR STANDBY COMPASS PART NO. WL1001KCA1, SERVICE BULLETIN REMOVAL / INSTALLATION OF THE NEW LEAD ASSEMBLY	MOS				RECOMMENDED	NOT APPLICABLE
27-JUN-2016		HRS/MSC -					
		AFL					
SB 700-34-5023 REV 01	MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INTRODUCTION OF NEW GPS-4000S PART NUMBER, SERVICE BULLETIN	MOS		23-MAR-2018		RECOMMENDED	COMPLIED WITH - C/W PART A AND PART B.
13-DEC-2017		HRS/MSC -		746.13			
		AFL		311			
SB 700-34-5023 REV 01 PART A	ACCOMPLISH, SERVICE BULLETIN INSPECTION	MOS		23-MAR-2018		RECOMMENDED	COMPLIED WITH - C/W PART A AND PART B.
13-DEC-2017		HRS/MSC -		746.13			
		AFL		311			
SB 700-34-5023 REV 01 PART B	ACCOMPLISH, SERVICE BULLETIN MODIFICATION	MOS		23-MAR-2018		RECOMMENDED	COMPLIED WITH - C/W PART A AND PART B.
13-DEC-2017		HRS/MSC -		746.13			
		AFL		311			
SB 700-34-5025 REV 01	MODIFICATION - SYNTHETIC VISION SYSTEM (SVS) - REPLACEMENT OF SYNTHETIC VISION MODULE FOR RELIABILITY ENHANCEMENT, SERVICE BULLETIN	MOS		25-MAY-2019		RECOMMENDED	COMPLIED WITH
16-MAY-2018		HRS/MSC -		879.42			
		AFL		365			
SB 700-34-5025 REV 01 PART A	ACCOMPLISH, SERVICE BULLETIN INSPECTION OF THE SERIAL NO. FOR THE SVM-6110(H) MODULE	MOS		25-MAY-2019		RECOMMENDED	COMPLIED WITH
16-MAY-2018		HRS/MSC -		879.42			
		AFL		365			
SB 700-34-5025 REV 01 PART B	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF THE SVM-6110(H) MODULE	MOS		25-MAY-2019		RECOMMENDED	COMPLIED WITH
16-MAY-2018		HRS/MSC -		879.42			
		AFL		365			
SB 700-34-5026	MODIFICATION - TRAFFIC COLLISION AVOIDANCE SYSTEM (TCAS) - TSSA-4100 TSS COASTING ERROR FIX FOR DO-260A, SERVICE BULLETIN	MOS		23-MAR-2018		RECOMMENDED	COMPLIED WITH - UPGRADED SOFTWARE TO P/N: 810-0052-013 S/N 4DLXG7.
15-DEC-2017		HRS/MSC -		746.13			
		AFL		311			
SB 700-34-5028	SPECIAL CHECK/MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INTRODUCTION OF NEW GPS-4000S PART NUMBER 822-2189-101, SERVICE BULLETIN	MOS		29-JUL-2020		RECOMMENDED	NOT APPLICABLE - PER P/N INSTALLED.
		HRS/MSC -		960.32			
		AFL		402			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-34-5028 PART A	ACCOMPLISH, SERVICE BULLETIN INSPECTION					RECOMMENDED	NOT APPLICABLE - PER P/N INSTALLED.
13-JUL-2020		MOS HRS/MSC - AFL		29-JUL-2020 960.32 402			
SB 700-34-5028 PART B	ACCOMPLISH, SERVICE BULLETIN MODIFICATION					RECOMMENDED	NOT APPLICABLE - PER P/N'S INSTALLED.
13-JUL-2020		MOS HRS/MSC - AFL		29-JUL-2020 960.32 402			
SB 700-34-5029	MODIFICATION - WEATHER RADAR SYSTEM - RTA-4118 - DIGITAL SIGNAL PROCESSOR (DSP) COMMUNICATION (COM) FAULT RELIABILITY IMPROVEMENT COLLINS SB RTA-41XX-34-8, SERVICE BULLETIN					RECOMMENDED	
		MOS HRS/MSC AFL	48	(EFF)	31-JUL-2024		
SB 700-35-5001 REV 01	ICA - MODIFICATION - OXYGEN CREW - REPLACEMENT OF FLEXIBLE RELIEF HOSES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
20-FEB-2015		MOS HRS/MSC - AFL		09-OCT-2015 350.9 149			
SB 700-35-5002	ICA - MODIFICATION - PASSENGER OXYGEN SYSTEM - OXYGEN BOX - MANIFOLD REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - C/W SB 700-35-5002
30-APR-2015		MOS HRS/MSC - AFL		09-OCT-2015 350.9 149			
SB 700-35-5003	MODIFICATION - PORTABLE OXYGEN PROVISION - REPLACEMENT OF THE BRACKET OF THE OXYGEN BOTTLE BRACKET, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
03-JUL-2018		MOS HRS/MSC - AFL					
SB 700-35-5003 REV 01	MODIFICATION - PORTABLE OXYGEN PROVISION - REPLACEMENT OF THE BRACKET OF THE OXYGEN BOTTLE BRACKET, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
23-NOV-2018		MOS HRS/MSC - AFL					
SB 700-35-5004	MODIFICATION - OXYGEN SUPPLY SYSTEM - OXYGEN BOX MANIFOLD REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
10-DEC-2018		MOS HRS/MSC - AFL					
SB 700-35-5004 REV 01	MODIFICATION - OXYGEN SUPPLY SYSTEM - OXYGEN BOX MANIFOLD REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
29-NOV-2019		MOS HRS/MSC - AFL					
SB 700-35-5004 REV 02	SPECIAL CHECK/MODIFICATION - OXYGEN SUPPLY SYSTEM - OXYGEN BOX MANIFOLD REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
27-AUG-2021		MOS HRS/MSC - AFL					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-35-5005	MODIFICATION - OXYGEN SUPPLY SYSTEM - FLEXIBLE OXYGEN HOSE REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	- SUPERSEDED
28-SEP-2020		MOS HRS/MSC - AFL					
SB 700-35-5005 REV 01	MODIFICATION - OXYGEN SUPPLY SYSTEM - FLEXIBLE OXYGEN HOSE REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - PART B COMPLIED WITH, LEAK CHECKED OK
12-FEB-2021		MOS HRS/MSC - AFL		15-AUG-2022 1050.4 448			
SB 700-35-5005 REV 01 PART A	ACCOMPLISH, SERVICE BULLETIN PART NUMBER INSPECTION ON EXISTING OXYGEN SYSTEM					RECOMMENDED	COMPLIED WITH
12-FEB-2021		MOS HRS/MSC - AFL		28-MAR-2021 994.17 420			
SB 700-35-5005 REV 01 PART B	ACCOMPLISH, SERVICE BULLETIN SCHEDULED TESTING					RECOMMENDED	COMPLIED WITH - LEAK CHECKED OK
12-FEB-2021		MOS HRS/MSC AFL	15 +3m/-3m	15-AUG-2022 1050.4 448	15-NOV-2023	15-FEB-2024 RECURRING	
SB 700-35-5005 REV 01 PART C	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - FLEXIBLE OXYGEN HOSE REPLACEMENT					RECOMMENDED	
12-FEB-2021		MOS HRS/MSC AFL	120		30-MAY-2024 M		
SB 700-36-5001	MODIFICATION - BLEED AIR SYSTEM - REPLACEMENT OF THE BLEED-PRESSURE REGULATING-AND-SHUTOFF VALVE (PRSOV), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
03-JUL-2018		MOS HRS/MSC - AFL		25-MAY-2019 879.42 365			
SB 700-38-5002	MODIFICATION - WASTE SYSTEM - ADDITION OF HEATER AND INSULATION BLANKET TO THE DELTA PRESSURE (DP) SENSOR OF THE WATER TANK ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
21-JAN-2013		MOS HRS/MSC - AFL					
SB 700-38-5003	MODIFICATION - WASTE DISPOSAL - INTRODUCTION OF IMPROVED RINSE VALVE TO PREVENT RINSE VALVE LEAKAGE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
28-MAR-2013		MOS HRS/MSC - AFL					
SB 700-44-5004	MODIFICATION - SATELLITE COMMUNICATIONS SYSTEM - INSTALLATION OF MODMAN POWER RELAY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
08-DEC-2017		MOS HRS/MSC - AFL					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-44-5006	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INSTALLATION OF A HONEYWELL JETWAVE™ KA BAND SATELLITE DATA SYSTEM WITH VENUE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
10-OCT-2018		MOS	HRS/MSC -	AFL			
SB 700-44-5006 REV 01	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INSTALLATION OF A HONEYWELL JETWAVE™ KA BAND SATELLITE DATA SYSTEM WITH VENUE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
10-OCT-2018		MOS	HRS/MSC -	AFL			
SB 700-44-5006 REV 02	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INSTALLATION OF A HONEYWELL JETWAVE™ KA BAND SATELLITE DATA SYSTEM WITH VENUE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
03-MAY-2019		MOS	HRS/MSC -	AFL			
SB 700-44-5006 REV 03	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INSTALLATION OF A HONEYWELL JETWAVE KA BAND SATELLITE DATA SYSTEM WITH VENUE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
03-JUL-2019		MOS	HRS/MSC -	AFL			
SB 700-44-5007	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - HONEYWELL JETWAVE KA-BAND RADIO FREQUENCY UNIT (KRFU) REPLACEMENT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
23-OCT-2018		MOS	HRS/MSC -	AFL			
SB 700-44-5007 REV 01	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - HONEYWELL JETWAVE KA-BAND RADIO FREQUENCY UNIT (KRFU) REPLACEMENT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
23-OCT-2018		MOS	HRS/MSC -	AFL			
SB 700-44-5007 REV 02	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - HONEYWELL JETWAVE KA-BAND RADIO FREQUENCY UNIT (KRFU) REPLACEMENT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
15-JAN-2019		MOS	HRS/MSC -	AFL			
SB 700-44-5008	MODIFICATION - CABIN SYSTEMS - JETWAVE SYSTEMS - BLV7.1 SOFTWARE UPDATE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
03-DEC-2018		MOS	HRS/MSC -	AFL			
SB 700-44-5008 REV 01	MODIFICATION - CABIN SYSTEMS - JETWAVE SYSTEMS - BLV7.1 SOFTWARE UPDATE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
28-FEB-2019		MOS	HRS/MSC -	AFL			
SB 700-44-5009	MODIFICATION - CABIN SYSTEMS - POWER SUPPLY 200 MS HOLDUP CAPACITOR IMPROVEMENT - MOD 7, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
25-JUN-2019		MOS	HRS/MSC -	AFL			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-45-5001	MODIFICATION - ONBOARD MAINTENANCE SYSTEM (OMS) - INTRODUCTION OF UPGRADED PMAT, PART NO. G700-454501-5, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
08-AUG-2014		MOS HRS/MSC - AFL		05-DEC-2014 185.42 76			
SB 700-45-5001 PART A	MODIFICATION MODIFICATION - ONBOARD MAINTENANCE SYSTEM (OMS) - INTRODUCTION OF UPGRADED PMAT, PART NO. G700-454501-5, SERVICE BULLETIN - REMOVAL/INSTALLATION OF HARD DRIVE FOR PMAT E6420					OPTIONAL	COMPLIED WITH
08-AUG-2014		MOS HRS/MSC - AFL		05-DEC-2014 185.42 76			
SB 700-45-5001 PART B	MODIFICATION MODIFICATION - ONBOARD MAINTENANCE SYSTEM (OMS) - INTRODUCTION OF UPGRADED PMAT, PART NO. G700-454501-5, SERVICE BULLETIN - REMOVAL/INSTALLATION OF HARD DRIVE FOR PMAT E6430					OPTIONAL	NOT APPLICABLE - PER LAPTOP MODEL
08-AUG-2014		MOS HRS/MSC - AFL		05-DEC-2014 185.42 76			
SB 700-45-5001 PART C	MODIFICATION MODIFICATION - ONBOARD MAINTENANCE SYSTEM (OMS) - INTRODUCTION OF UPGRADED PMAT, PART NO. G700-454501-5, SERVICE BULLETIN - REMOVAL/INSTALLATION OF HARD DRIVE FOR PMAT E5440					OPTIONAL	NOT APPLICABLE - PER LAPTOP MODEL
08-AUG-2014		MOS HRS/MSC - AFL		05-DEC-2014 185.42 76			
SB 700-46-5001 REV 01	MODIFICATION - INTEGRATED FLIGHT INFORMATION SYSTEM (IFIS) - INSTALLATION OF XM GRAPHICAL WEATHER RADAR, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
23-DEC-2013		MOS HRS/MSC - AFL					
SB 700-46-5001 REV 02	MODIFICATION - INTEGRATED FLIGHT INFORMATION SYSTEM (IFIS) - INSTALLATION OF XM GRAPHICAL WEATHER RADAR, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
23-DEC-2015		MOS HRS/MSC - AFL					
SB 700-46-5002 REV 01	MODIFICATION - INTEGRATED FLIGHT INFORMATION SYSTEM (IFIS) - INTRODUCTION OF DATALINK GRAPHICAL WEATHER SYSTEM, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
02-MAR-2016		MOS HRS/MSC - AFL					
SB 700-46-5003 REV 01	MODIFICATION - INTEGRATED FLIGHT INFORMATION SYSTEM (IFIS) - INTRODUCTION OF A THIRD INTEGRATED FLIGHT INFORMATION SYSTEM, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
21-MAR-2013		MOS HRS/MSC - AFL					
SB 700-46-5003 REV 02	MODIFICATION - INTEGRATED FLIGHT INFORMATION SYSTEM (IFIS) - INTRODUCTION OF A THIRD INTEGRATED FLIGHT INFORMATION SYSTEM, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
03-DEC-2014		MOS HRS/MSC - AFL					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-46-5003 REV 03	MODIFICATION - INTEGRATED FLIGHT INFORMATION SYSTEM (IFIS) - INTRODUCTION OF A THIRD INTEGRATED FLIGHT INFORMATION SYSTEM, SERVICE BULLETIN	MOS				OPTIONAL	NOT APPLICABLE
01-FEB-2016		HRS/MSC -					
		AFL					
SB 700-46-5005 REV 02	ICA - MODIFICATION - INFORMATION MANAGEMENT SYSTEM -DEACTIVATION OF CES ETHERNET INTERFACE TO CABIN PRINTER, SERVICE BULLETIN	MOS		09-OCT-2015		RECOMMENDED	COMPLIED WITH
18-JUN-2015		HRS/MSC -		350.9			
		AFL		149			
SB 700-46-5005 REV 02 PART A	VERIFY ICA - MODIFICATION - INFORMATION MANAGEMENT SYSTEM -DEACTIVATION OF CES ETHERNET INTERFACE TO CABIN PRINTER, SERVICE BULLETIN CONNECTOR PINS ARE PRESENT	MOS		09-OCT-2015		RECOMMENDED	COMPLIED WITH
18-JUN-2015		HRS/MSC -		350.9			
		AFL		149			
SB 700-46-5005 REV 02 PART B	ICA - MODIFICATION - INFORMATION MANAGEMENT SYSTEM -DEACTIVATION OF CES ETHERNET INTERFACE TO CABIN PRINTER, SERVICE BULLETIN MODIFICATION	MOS		09-OCT-2015		RECOMMENDED	COMPLIED WITH
18-JUN-2015		HRS/MSC -		350.9			
		AFL		149			
SB 700-46-5008	MODIFICATION - INFORMATION MANAGEMENT SYSTEM (IMS), SERVICE BULLETIN	MOS	18	(EFF)	20-JAN-2024	RECOMMENDED	
20-JUL-2022		HRS/MSC					
		AFL					
SB 700-49-5002	MODIFICATION - INDICATING - AUXILIARY POWER UNIT (APU) EXHAUST-GAS TEMPERATURE SENSOR UPGRADE TO PART NUMBER WE3876352-2 WITH SERIAL NUMBER 50413-1000204 OR ABOVE, SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE
08-MAR-2012		HRS/MSC -					
		AFL					
SB 700-49-5002 PART A	ACCOMPLISH MODIFICATION - INDICATING - AUXILIARY POWER UNIT (APU) EXHAUST-GAS TEMPERATURE SENSOR UPGRADE TO PART NUMBER WE3876352-2 WITH SERIAL NUMBER 50413-1000204 OR ABOVE, SERVICE BULLETIN APU EGT SENSOR PART AND SERIAL NUMBER INSPECTION	MOS				RECOMMENDED	NOT APPLICABLE
08-MAR-2012		HRS/MSC -					
		AFL					
SB 700-49-5002 PART B	ACCOMPLISH MODIFICATION - INDICATING - AUXILIARY POWER UNIT (APU) EXHAUST-GAS TEMPERATURE SENSOR UPGRADE TO PART NUMBER WE3876352-2 WITH SERIAL NUMBER 50413-1000204 OR ABOVE, SERVICE BULLETIN UPGRADE OF THE APU EGT SENSOR(S)	MOS				RECOMMENDED	NOT APPLICABLE
08-MAR-2012		HRS/MSC -					
		AFL					
SB 700-49-5003	SPECIAL CHECK/MODIFICATION - AUTOMATIC CONTROL SYSTEM - VISUAL INSPECTION AND SEALANT APPLICATION METHOD FOR THE EXHAUST GAS TEMPERATURE (EGT) SENSOR, PART NUMBER WE3876352-1 AND WE3876352-2, SERVICE BULLETIN	MOS		23-MAR-2018		RECOMMENDED	COMPLIED WITH
29-JUN-2017		HRS/MSC -		746.13			
		AFL		311			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-52-5001 REV 01	MODIFICATION - PASSENGER DOOR - INSTALLATION OF AESTHETIC SIDE COVERS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
06-JUN-2013		MOS HRS/MSC - AFL		23-APR-2014 12.8 6			
SB 700-52-5007	ICA - MODIFICATION - AFT EQUIPMENT-COMPARTMENT DOOR - MODIFICATION TO PREVENT FUEL INGRESS INTO THE AFT EQUIPMENT BAY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
29-MAR-2012		MOS HRS/MSC - AFL					
SB 700-52-5008	MODIFICATION - PASSENGER DOOR - RECONFIGURATION OF THE PASSENGER DOOR EXTERNAL HANDLE DETENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
09-NOV-2012		MOS HRS/MSC - AFL					
SB 700-52-5008 REV 02	ICA - MODIFICATION - PASSENGER DOOR - RECONFIGURATION OF THE PASSENGER DOOR EXTERNAL HANDLE DETENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
11-MAR-2016		MOS HRS/MSC - AFL					
SB 700-52-5011 PART A	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - TENSATOR SPRINGS TENSION RELEASE					RECOMMENDED	
20-MAY-2022		MOS HRS/MSC AFL	36	(EFF)	20-MAY-2025		
SB 700-52-5011 PART B	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - TENSATOR SPRINGS PRE-TENSIONING AND TENSION SET FOR DOOR IN OPEN POSITION					RECOMMENDED	
20-MAY-2022		MOS HRS/MSC AFL	36	(EFF)	20-MAY-2025		
SB 700-52-5011 PART C	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - CABLES CONNECTION					RECOMMENDED	
20-MAY-2022		MOS HRS/MSC AFL	36	(EFF)	20-MAY-2025		
SB 700-53-5006	SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLY FOR CORROSION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
16-DEC-2015		MOS HRS/MSC - AFL		(EFF)			
SB 700-53-5008	SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLY AND APU DOORS FOR CORROSION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
16-DEC-2015		MOS HRS/MSC - AFL		(EFF)			
SB 700-53-5008 PART A	DETAILED VISUAL INSPECTION SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLY AND APU DOORS FOR CORROSION, SERVICE BULLETIN (DVI) OF THE TAILCONE ASSEMBLY					RECOMMENDED	NOT APPLICABLE
16-DEC-2015		MOS HRS/MSC - AFL					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-53-5008 PART B	SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLY AND APU DOORS FOR CORROSION, SERVICE BULLETIN LOCAL REWORK OF THE TAILCONE ASSEMBLY					RECOMMENDED	NOT APPLICABLE
16-DEC-2015		MOS	HRS/MSC -	AFL			
SB 700-53-5008 PART C	SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLY AND APU DOORS FOR CORROSION, SERVICE BULLETIN MAJOR REWORK OF THE FORWARD/AFT TAILCONE AND END CAP SKINS					RECOMMENDED	NOT APPLICABLE
16-DEC-2015		MOS	HRS/MSC -	AFL			
SB 700-53-5008 PART D	SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLY AND APU DOORS FOR CORROSION, SERVICE BULLETIN MAJOR REWORK OF THE APU DOOR SKINS					RECOMMENDED	NOT APPLICABLE
16-DEC-2015		MOS	HRS/MSC -	AFL			
SB 700-53-5008 REV 01	SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLY AND APU DOORS FOR CORROSION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
13-JAN-2017		MOS	HRS/MSC -	AFL			
SB 700-53-5008 REV 01 PART A	ACCOMPLISH SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLY AND APU DOORS FOR CORROSION, SERVICE BULLETIN DETAILED VISUAL INSPECTION (DVI) OF THE TAILCONE ASSEMBLY					RECOMMENDED	NOT APPLICABLE
13-JAN-2017		MOS	HRS/MSC -	AFL			
SB 700-53-5008 REV 01 PART B	ACCOMPLISH SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLY AND APU DOORS FOR CORROSION, SERVICE BULLETIN LOCAL REWORK OF THE TAILCONE ASSEMBLY					RECOMMENDED	NOT APPLICABLE
13-JAN-2017		MOS	HRS/MSC -	AFL			
SB 700-53-5008 REV 01 PART C	ACCOMPLISH SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLY AND APU DOORS FOR CORROSION, SERVICE BULLETIN MAJOR REWORK OF THE FORWARD/AFT TAILCONE AND END CAP SKINS					RECOMMENDED	NOT APPLICABLE
13-JAN-2017		MOS	HRS/MSC -	AFL			
SB 700-53-5008 REV 01 PART D	ACCOMPLISH SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLY AND APU DOORS FOR CORROSION, SERVICE BULLETIN MAJOR REWORK OF THE APU DOOR SKINS					RECOMMENDED	NOT APPLICABLE
13-JAN-2017		MOS	HRS/MSC -	AFL			
SB 700-53-5008 REV 02	SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLY AND APU DOORS FOR CORROSION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
07-SEP-2018		MOS	HRS/MSC -	AFL			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-53-5008 REV 02 PART A	ACCOMPLISH, SERVICE BULLETIN DETAILED VISUAL INSPECTION (DVI) OF THE TAILCONE ASSEMBLY					RECOMMENDED	NOT APPLICABLE
07-SEP-2018		MOS HRS/MSC - AFL					
SB 700-53-5008 REV 02 PART B	ACCOMPLISH, SERVICE BULLETIN LOCAL REWORK OF THE TAILCONE ASSEMBLY					RECOMMENDED	NOT APPLICABLE
07-SEP-2018		MOS HRS/MSC - AFL					
SB 700-53-5008 REV 02 PART C	ACCOMPLISH, SERVICE BULLETIN MAJOR REWORK OF THE FORWARD/AFT TAILCONE AND END CAP SKINS					RECOMMENDED	NOT APPLICABLE
07-SEP-2018		MOS HRS/MSC - AFL					
SB 700-53-5008 REV 02 PART D	ACCOMPLISH, SERVICE BULLETIN MAJOR REWORK OF THE APU DOOR SKINS					RECOMMENDED	NOT APPLICABLE
07-SEP-2018		MOS HRS/MSC - AFL					
SB 700-53-5009 REV 01	MODIFICATION - BELLY FAIRINGS - REPLACEMENT OF ATTACHMENTS FOR THE ACCESS PANELS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
16-DEC-2016		MOS HRS/MSC - AFL		11-JAN-2018 707.58 297			
SB 700-53-5010	SPECIAL CHECK/REWORK - BELLY FAIRINGS - INSPECT FORWARD AND MIDDLE ACCESS PANEL (181BB) AND (183BB) FOR DRAINAGE HOLE BLOCKAGE, AND IF NECESSARY REMOVE SEALANT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - C/W PARTS A & B
17-MAY-2017		MOS HRS/MSC - AFL		23-MAR-2018 746.13 311			
SB 700-53-5010 PART A	ACCOMPLISH SPECIAL CHECK/REWORK - BELLY FAIRINGS - INSPECT FORWARD AND MIDDLE ACCESS PANEL (181BB) AND (183BB) FOR DRAINAGE HOLE BLOCKAGE, AND IF NECESSARY REMOVE SEALANT, SERVICE BULLETIN INSPECTION OF SEALANT					RECOMMENDED	COMPLIED WITH - C/W PARTS A & B
17-MAY-2017		MOS HRS/MSC - AFL		23-MAR-2018 746.13 311			
SB 700-53-5010 PART B	ACCOMPLISH SPECIAL CHECK/REWORK - BELLY FAIRINGS - INSPECT FORWARD AND MIDDLE ACCESS PANEL (181BB) AND (183BB) FOR DRAINAGE HOLE BLOCKAGE, AND IF NECESSARY REMOVE SEALANT, SERVICE BULLETIN REWORK - REMOVAL OF AERODYNAMIC SEALANT					RECOMMENDED	COMPLIED WITH - C/W PARTS A & B
17-MAY-2017		MOS HRS/MSC - AFL		23-MAR-2018 746.13 311			
SB 700-53-5011	MODIFICATION - AFT FUSELAGE - REPLACEMENT AND REINFORCEMENT OF THE RUDDER QUADRANT BOX ASSEMBLY HALF RIBS, SERVICE BULLETIN					RECOMMENDED	
01-OCT-2018		MOS HRS/MSC AFL	60	(EFF)	01-OCT-2023 3000 M		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-53-5013	SPECIAL CHECK - AFT FUSELAGE - INSPECTION OF THE RUDDER QUADRANT BOX ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
01-OCT-2018		MOS		25-MAY-2019		RECURRING	
		HRS/MSC		879.42			
		AFL	1000	365	1365	1365	
SB 700-53-5014 REV 01	MODIFICATION - AUXILIARY POWER UNIT (APU) ACCESS DOORS - MODIFICATION OF APU ACCESS DOORS AND FORWARD/AFT TAILCONE TO IMPROVE DRAINAGE AND PREVENT CORROSION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
08-APR-2019		MOS		25-MAY-2019			
		HRS/MSC	-	879.42			
		AFL		365			
SB 700-53-5014 REV 01 PART A	ACCOMPLISH, SERVICE BULLETIN LEFT AND RIGHT AFT TAILCONE SKIN MODIFICATION (APPLICABLE TO AIRCRAFT SERIAL NO. 9386, 9401 AND 9445 TO 9663)					RECOMMENDED	COMPLIED WITH
08-APR-2019		MOS		25-MAY-2019			
		HRS/MSC	-	879.42			
		AFL		365			
SB 700-53-5014 REV 01 PART B	ACCOMPLISH, SERVICE BULLETIN APPLY THE CORROSION INHIBITING COMPOUND (CIC) ON FORWARD AND AFT TAILCONE STRUCTURES					RECOMMENDED	COMPLIED WITH
08-APR-2019		MOS		25-MAY-2019			
		HRS/MSC	-	879.42			
		AFL		365			
SB 700-53-5014 REV 01 PART C	ACCOMPLISH, SERVICE BULLETIN APU ACCESS DOOR MODIFICATION AND APPLICATION OF CIC					RECOMMENDED	COMPLIED WITH
08-APR-2019		MOS		25-MAY-2019			
		HRS/MSC	-	879.42			
		AFL		365			
SB 700-55-5001	MODIFICATION - HORIZONTAL STABILIZER - ADDITION OF DRAINAGE HOLES TO ELIMINATE WATER ACCUMULATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
11-OCT-2012		MOS					
		HRS/MSC	-				
		AFL					
SB 700-55-5002 REV 02	MODIFICATION - VERTICAL STABILIZER - MODIFICATION OF BULLET AND DORSAL FAIRINGS TO IMPROVE DRAINAGE AND PREVENT CORROSION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
27-APR-2018		MOS		25-MAY-2019			
		HRS/MSC	-	879.42			
		AFL		365			
SB 700-55-5002 REV 02 PART A	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF THE NUTPLATE RETAINERS					RECOMMENDED	COMPLIED WITH
27-APR-2018		MOS		25-MAY-2019			
		HRS/MSC	-	879.42			
		AFL		365			
SB 700-55-5002 REV 02 PART B	ACCOMPLISH, SERVICE BULLETIN VERTICAL STAB BULLET FAIRINGS MODIFICATION					RECOMMENDED	COMPLIED WITH
27-APR-2018		MOS		25-MAY-2019			
		HRS/MSC	-	879.42			
		AFL		365			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-55-5002 REV 02 PART C	ACCOMPLISH, SERVICE BULLETIN DORSAL FAIRING MODIFICATION					RECOMMENDED	COMPLIED WITH
27-APR-2018		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
SB 700-56-5001	SPECIAL CHECK/REWORK - FLIGHT COMPARTMENT - INSPECT THE WINDSHIELD/SIDE WINDOW AND IF NECESSARY REPAIR SEAL, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
28-MAR-2013		MOS					
		HRS/MSC -					
		AFL					
SB 700-57-5001	MODIFICATION - GENERAL - APPLICATION OF ADDITIONAL SEALANT AND ADD WATER DRAINAGE IN THE COLLECTOR BOX, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
07-MAY-2012		MOS					
		HRS/MSC -					
		AFL					
SB 700-57-5002	SPECIAL CHECK/MODIFICATION - LEADING EDGES - REPLACEMENT OF ATTACHMENT ANGLES AND MODIFICATION OF SHROUD PANEL MOUNTING HOLES, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - N/A PER S/N.
08-NOV-2012		MOS		10-JAN-2018			
		HRS/MSC -		707.58			
		AFL		297			
SB 700-57-5003 REV 02	MODIFICATION - FLAPS - INSPECTION AND REPLACEMENT OF THE INNER FLAPS AUXILIARY-RIB BUSHING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - PART A - PART B IS N/A NO MIGRATION OF THE BUSHINGS
13-JUL-2018		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
SB 700-57-5003 REV 02 PART A	ACCOMPLISH, SERVICE BULLETIN INSPECTION OF THE SPIGOT TUBE BUSHING FOR MIGRATION					RECOMMENDED	COMPLIED WITH - PART A - PART B IS N/A NO MIGRATION OF THE BUSHINGS
13-JUL-2018		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
SB 700-57-5003 REV 02 PART B	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF THE SPIGOT TUBE BUSHING(S)					RECOMMENDED	NOT APPLICABLE - C/W PART A - PART B IS N/A
13-JUL-2018		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
SB 700-57-5005 REV 01	SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INNER FLAPS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - PART A - PART C IS APPLICABLE
26-APR-2018		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
SB 700-57-5005 REV 01 PART A	ACCOMPLISH, SERVICE BULLETIN INSPECTION OF INNER FLAP FOR CORROSION					RECOMMENDED	COMPLIED WITH
26-APR-2018		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-57-5005 REV 01 PART B	ACCOMPLISH, SERVICE BULLETIN INNER FLAP CORROSION PREVENTION					RECOMMENDED	NOT APPLICABLE - CORROSION FOUND - REFER PART C
26-APR-2018		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
SB 700-57-5005 REV 01 PART C	ACCOMPLISH, SERVICE BULLETIN INNER FLAP - CORROSION REMOVAL REWORK					RECOMMENDED	COMPLIED WITH - MOD / REPAIR C/W BY INNODYNE SEE WO 33624/33623
26-APR-2018		MOS		25-MAY-2019			
		HRS/MSC -		879.42			
		AFL		365			
SB 700-57-5005 REV 03	SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INBOARD FLAPS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
11-DEC-2020		MOS		24-NOV-2021			
		HRS/MSC -		1023.57			
		AFL		435			
SB 700-57-5005 REV 03 PART A	ACCOMPLISH, SERVICE BULLETIN INSPECTION OF INBOARD FLAP FOR CORROSION					RECOMMENDED	COMPLIED WITH
11-DEC-2020		MOS		24-NOV-2021			
		HRS/MSC -		1023.57			
		AFL		435			
SB 700-57-5005 REV 03 PART B	ACCOMPLISH, SERVICE BULLETIN INBOARD FLAP DRAINAGE IMPROVEMENT					RECOMMENDED	COMPLIED WITH
11-DEC-2020		MOS		24-NOV-2021			
		HRS/MSC -		1023.57			
		AFL		435			
SB 700-57-5005 REV 03 PART C	ACCOMPLISH, SERVICE BULLETIN INBOARD FLAP CORROSION PREVENTION					RECOMMENDED	COMPLIED WITH
11-DEC-2020		MOS		24-NOV-2021			
		HRS/MSC -		1023.57			
		AFL		435			
SB 700-57-5005 REV 03 PART E	ACCOMPLISH, SERVICE BULLETIN INBOARD FLAP DRAIN HOLE COVERS INSTALLATION					RECOMMENDED	COMPLIED WITH
11-DEC-2020		MOS		24-NOV-2021			
		HRS/MSC -		1023.57			
		AFL		435			
SB 700-57-5008 REV 01	SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - MIDDLE FLAP, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
28-SEP-2021		MOS		24-NOV-2021			
		HRS/MSC -		1023.57			
		AFL		435			
SB 700-57-5008 REV 01 PART A	ACCOMPLISH, SERVICE BULLETIN MIDDLE FLAP DRAINAGE IMPROVEMENT					RECOMMENDED	COMPLIED WITH
28-SEP-2021		MOS		24-NOV-2021			
		HRS/MSC -		1023.57			
		AFL		435			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-57-5008 REV 01 PART B	ACCOMPLISH, SERVICE BULLETIN INSPECTION OF MIDDLE FLAP FOR CORROSION					RECOMMENDED	COMPLIED WITH
28-SEP-2021		MOS HRS/MSC - AFL		24-NOV-2021 1023.57 435			
SB 700-57-5008 REV 01 PART C	ACCOMPLISH, SERVICE BULLETIN MIDDLE FLAP CORROSION PREVENTION					RECOMMENDED	COMPLIED WITH
28-SEP-2021		MOS HRS/MSC - AFL		24-NOV-2021 1023.57 435			
SB 700-57-5009 REV 01	SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - OUTER FLAPS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
28-SEP-2021		MOS HRS/MSC - AFL		24-NOV-2021 1023.57 435			
SB 700-57-5009 REV 01 PART A	ACCOMPLISH, SERVICE BULLETIN OUTER FLAP DRAINAGE IMPROVEMENT					RECOMMENDED	COMPLIED WITH
28-SEP-2021		MOS HRS/MSC - AFL		24-NOV-2021 1023.57 435			
SB 700-57-5009 REV 01 PART B	ACCOMPLISH, SERVICE BULLETIN INSPECTION OF OUTER FLAP FOR CORROSION					RECOMMENDED	COMPLIED WITH
28-SEP-2021		MOS HRS/MSC - AFL		24-NOV-2021 1023.57 435			
SB 700-57-5009 REV 01 PART C	ACCOMPLISH, SERVICE BULLETIN OUTER FLAP CORROSION PREVENTION					RECOMMENDED	COMPLIED WITH
28-SEP-2021		MOS HRS/MSC - AFL		24-NOV-2021 1023.57 435			
SB 700-71-5001	MODIFICATION - FIXED COWLS - INTRODUCTION OF A DRAINAGE HOLE IN THE FRONT MOUNT ACCESS PANEL ON THE FIXED COWL, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
06-MAY-2013		MOS HRS/MSC - AFL		23-APR-2014 12.8 6			
SB 700-71-5002	SPECIAL CHECK/REWORK - REAR MOUNT - INSPECT THE RETAINING BOLT AND NUT ON THE LOWER/UPPER ENGINE REAR MOUNT ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
31-MAY-2016		MOS HRS/MSC - AFL		(EFF)			
SB 700-71-5002 PART A	ACCOMPLISH SPECIAL CHECK/REWORK - REAR MOUNT - INSPECT THE RETAINING BOLT AND NUT ON THE LOWER/UPPER ENGINE REAR MOUNT ASSEMBLY, SERVICE BULLETIN INSPECTION OF THE ENGINE REAR MOUNT ASSEMBLIES					RECOMMENDED	NOT APPLICABLE
31-MAY-2016		MOS HRS/MSC - AFL		(EFF)			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-71-5002 PART B	ACCOMPLISH SPECIAL CHECK/REWORK - REAR MOUNT - INSPECT THE RETAINING BOLT AND NUT ON THE LOWER/UPPER ENGINE REAR MOUNT ASSEMBLY, SERVICE BULLETIN REPLACEMENT OF THE HARDWARE					RECOMMENDED	NOT APPLICABLE
31-MAY-2016		MOS		(EFF)			
		HRS/MSC -					
		AFL					
SB 700-71-5002 REV 01	SPECIAL CHECK/REWORK - REAR MOUNT - INSPECT THE RETAINING BOLT AND NUT ON THE LOWER/UPPER ENGINE REAR MOUNT ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
30-JUN-2016		MOS		02-NOV-2016			
		HRS/MSC -		541.13			
		AFL		225			
SB 700-71-5002 REV 01 PART A	ACCOMPLISH SPECIAL CHECK/REWORK - REAR MOUNT - INSPECT THE RETAINING BOLT AND NUT ON THE LOWER/UPPER ENGINE REAR MOUNT ASSEMBLY, SERVICE BULLETIN INSPECTION OF THE ENGINE REAR MOUNT ASSEMBLIES					RECOMMENDED	COMPLIED WITH
30-JUN-2016		MOS		02-NOV-2016			
		HRS/MSC -		541.13			
		AFL		225			
SB 700-71-5002 REV 01 PART B	ACCOMPLISH SPECIAL CHECK/REWORK - REAR MOUNT - INSPECT THE RETAINING BOLT AND NUT ON THE LOWER/UPPER ENGINE REAR MOUNT ASSEMBLY, SERVICE BULLETIN REPLACEMENT OF THE HARDWARE					RECOMMENDED	NOT APPLICABLE - NO DEFECTS NOTED IN PART A
30-JUN-2016		MOS		02-NOV-2016			
		HRS/MSC -		541.13			
		AFL		225			
SB 700-71-5003	MODIFICATION - REAR MOUNT - REPLACEMENT OF RETAINING BOLT AND NUT ON THE LOWER/UPPER ENGINE REAR MOUNT ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
05-DEC-2016		MOS		09-JAN-2018			
		HRS/MSC -		707.58			
		AFL		297			
SB 700-71-5003 PART A	ACCOMPLISH MODIFICATION - REAR MOUNT - REPLACEMENT OF RETAINING BOLT AND NUT ON THE LOWER/UPPER ENGINE REAR MOUNT ASSEMBLY, SERVICE BULLETIN MEASUREMENT OF THE GAPS ON THE ENGINE REAR MOUNT ASSEMBLY HARDWARE					RECOMMENDED	NOT APPLICABLE - N/A DUE TO SB 700-71-5002 PREVIOUSLY INCORPORATED
05-DEC-2016		MOS		09-JAN-2018			
		HRS/MSC -		707.58			
		AFL		297			
SB 700-71-5003 PART B	ACCOMPLISH MODIFICATION - REAR MOUNT - REPLACEMENT OF RETAINING BOLT AND NUT ON THE LOWER/UPPER ENGINE REAR MOUNT ASSEMBLY, SERVICE BULLETIN REPLACEMENT OF THE ENGINE REAR MOUNT ASSEMBLY HARDWARE					RECOMMENDED	COMPLIED WITH
05-DEC-2016		MOS		09-JAN-2018			
		HRS/MSC -		707.58			
		AFL		297			
SB 700-71-5005	SPECIAL CHECK - FRONT AND REAR ENGINE MOUNT ASSEMBLIES - INSPECTION OF BUSHINGS ON THE ENGINE MOUNT SYSTEM, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS		24-NOV-2021			
		HRS/MSC -		1023.57			
		AFL		435			
SB 700-71-5005 PART A	ACCOMPLISH, SERVICE BULLETIN INSPECTION OF SLIDING BUSHING (BRR15811) AT THE UPPER AND LOWER SIDE OF FRONT MOUNT BEAM					RECOMMENDED	COMPLIED WITH
14-DEC-2020		MOS		24-NOV-2021			
		HRS/MSC -		1023.57			
		AFL		435			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-71-5005 PART B	ACCOMPLISH, SERVICE BULLETIN INSPECTION OF SLIDING BUSHING (BRR15808) AT THE THRUST STRUT FRONT LOCATION					RECOMMENDED	COMPLIED WITH
14-DEC-2020		MOS HRS/MSC - AFL		24-NOV-2021 1023.57 435			
SB 700-71-5005 PART C	ACCOMPLISH, SERVICE BULLETIN INSPECTION OF SLIDING BUSHING (BRR15823) AT THE THRUST STRUT AIRCRAFT PYLON INTERFACE					RECOMMENDED	COMPLIED WITH
14-DEC-2020		MOS HRS/MSC - AFL		24-NOV-2021 1023.57 435			
SB 700-71-5005 PART D	ACCOMPLISH, SERVICE BULLETIN INSPECTION OF SLIDING BUSHING (BRR15804) AT THE FRONT MOUNT BEAM INTERFACE WITH THE AIRCRAFT PYLON UPPER AND LOWER INSTALLATION					RECOMMENDED	COMPLIED WITH
14-DEC-2020		MOS HRS/MSC - AFL		24-NOV-2021 1023.57 435			
SB 700-71-5005 PART E	ACCOMPLISH, SERVICE BULLETIN INSPECTION OF SLIDING BUSHING (BRR15841) AT THE REAR MOUNT BEAM INTERFACE WITH THE AIRCRAFT PYLON UPPER AND LOWER INSTALLATION					RECOMMENDED	COMPLIED WITH
14-DEC-2020		MOS HRS/MSC - AFL		24-NOV-2021 1023.57 435			
SB 700-73-5002	MODIFICATION - FULL-AUTHORITY DIGITAL ENGINE-CONTROL (FADEC) SYSTEM - EEC SOFTWARE UPGRADE OF VERSION X2.0, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
04-OCT-2016		MOS HRS/MSC - AFL		24-MAY-2019 879.42 365			
SB 700-73-5002 PART A	ACCOMPLISH MODIFICATION - FULL-AUTHORITY DIGITAL ENGINE-CONTROL (FADEC) SYSTEM - EEC SOFTWARE UPGRADE OF VERSION X2.0, SERVICE BULLETIN INSPECT THE EEC TYPE NO. AND AIRCRAFT SETUP					RECOMMENDED	COMPLIED WITH
04-OCT-2016		MOS HRS/MSC - AFL		24-MAY-2019 879.42 365			
SB 700-73-5002 PART B	ACCOMPLISH MODIFICATION - FULL-AUTHORITY DIGITAL ENGINE-CONTROL (FADEC) SYSTEM - EEC SOFTWARE UPGRADE OF VERSION X2.0, SERVICE BULLETIN MODIFICATION - UPGRADE OF THE EEC					RECOMMENDED	COMPLIED WITH
04-OCT-2016		MOS HRS/MSC - AFL		24-MAY-2019 879.42 365			
SB 700D21-5001	MODIFICATION - INTERNAL DISTRIBUTION - INSTALLATION OF ENVIRONMENTAL CONTROL SYSTEM (ECS) DUCTING AND SYSTEM COMPONENTS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
28-MAR-2012		MOS HRS/MSC - AFL		23-APR-2014 12.8 6			
SB 700D25-5002 REV 02	MODIFICATION - CARGO COMPARTMENT - MODIFICATION TO FACILITATE INSTALLATION OF THE BAGGAGE COMPARTMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
21-MAY-2013		MOS HRS/MSC - AFL		23-APR-2014 12.8 6			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700D25-5003	MODIFICATION - PROVISIONS - CARGO COMPARTMENT - INSTALLATION OF NET AND SHELF IN THE BAGGAGE COMPARTMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
30-MAR-2012		MOS		23-APR-2014			
		HRS/MSC -		12.8			
		AFL		6			
SB 700D25-5004	MODIFICATION - PROVISIONS - PASSENGER COMPARTMENT - INTRODUCTION OF NEW SUPPORT BRACKETS AND MODIFICATION OF INTERCOSTALS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
18-APR-2012		MOS		23-APR-2014			
		HRS/MSC -		12.8			
		AFL		6			
SB 700D25-5005	MODIFICATION - PROVISIONS - LAVATORIES - INSTALL PROVISIONS FOR 29 INCH FORWARD LAVATORY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
28-MAR-2012		MOS		23-APR-2014			
		HRS/MSC -		12.8			
		AFL		6			
SB 700D53-5001	MODIFICATION - PROVISIONS - CENTER FUSELAGE - BRACKET INSTALLATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
29-MAR-2012		MOS		23-APR-2014			
		HRS/MSC -		12.8			
		AFL		6			
SB 975237-29-434 REV 3	MOD #1 AND #2 HYDRAULIC SYSTEMS - HYDRAULIC FIRE SHUT-OFF VALVES. INTRODUCTION OF IMPROVED ACTUATORS AS SEPARATE URL P/N:975237-501 (GX473-0126-1), SERVICE BULLETIN						COMPLIED WITH
		MOS		23-APR-2014			
		HRS/MSC -		12.8			
		AFL		6			
STC SA12-16 REV 2	MANUFACTURE AND INSTALLATION OF A PASSENGER COMPLETE AIRCRAFT INTERIOR CONFIGURATION., SUPPLEMENTAL TYPE CERTIFICATE						COMPLIED WITH
		MOS		23-APR-2014			
		HRS/MSC -					
		AFL					
STC SA12-24	INSTALLATION OF CLASS II ELECTRONIC FLIGHT BAG (SINGLE L3 COMMUNICATIONS CREWMATE 840)., SUPPLEMENTAL TYPE CERTIFICATE						COMPLIED WITH
		MOS		23-APR-2014			
		HRS/MSC -					
		AFL					
STC SA12-24 REV 3	INSTALLATION OF CLASS II ELECTRONIC FLIGHT BAG (SINGLE L3 COMMUNICATIONS CREWMATE 840)., SUPPLEMENTAL TYPE CERTIFICATE						COMPLIED WITH
		MOS		23-APR-2014			
		HRS/MSC -					
		AFL					
STC ST03088NY	MANUFACTURE AND INSTALLATION OF A PASSENGER COMPLETE AIRCRAFT INTERIOR CONFIGURATION., SUPPLEMENTAL TYPE CERTIFICATE						COMPLIED WITH
		MOS		24-MAY-2014			
		HRS/MSC -					
		AFL					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
STC ST03108NY	INSTALLATION OF CLASS II ELECTRONIC FLIGHT BAG (SINGLE L3 COMMUNICATIONS CREWMATE 840). , SUPPLEMENTAL TYPE CERTIFICATE					STC-SUPPLEMEN TAL TYPE CERTIFICATE	COMPLIED WITH
		MOS		24-MAY-2014			
		HRS/MSC -		23.6			
		AFL		9			
VSB 06-15	SAFT - REPLACE EXISTING AVIONICS BATTERY HARNESS ASSEMBLY, VENDOR SERVICE BULLETIN						COMPLIED WITH
		MOS		09-JAN-2018			
		HRS/MSC -		707.58			
		AFL		297			
VSB 3ACF0107-25-46 REV A	BOTTOM CUSHION REPLACEMENT, VENDOR SERVICE BULLETIN					VENDOR RECOMMENDATIO N	COMPLIED WITH
		MOS		23-APR-2014			
		HRS/MSC -					
		AFL					
VSB 90401226 REV B	ASPIRE-100 (1492-A-3200-202) -ASPIRE-100 SOFTWARE UPGRADE, VENDOR SERVICE BULLETIN					VENDOR RECOMMENDATIO N	COMPLIED WITH
		MOS		23-APR-2014			
		HRS/MSC -					
		AFL					
VSB 90401268	ASPIRE HANDSET SOFTWAREUPGARDE INCORPORATED(1492-F0203-01, 149-F-0204-01 & 1492-F0202-01), VENDOR SERVICE BULLETIN					VENDOR RECOMMENDATIO N	COMPLIED WITH
		MOS		23-APR-2014			
		HRS/MSC -					
		AFL					
VSB 90403825 REV A	EMS TECHNOLOGIES - ASPIRE HANDSET SOFTWARE UPDATE, VENDOR SERVICE BULLETIN					VSB	COMPLIED WITH
		MOS		08-OCT-2015			
		HRS/MSC -		350.9			
		AFL		149			
VSB 90404347 REV A	EMS TECHNOLOGIES - ASPIRE -100 SOFTWARE UPDATE, VENDOR SERVICE BULLETIN					VSB	COMPLIED WITH
		MOS		08-OCT-2015			
		HRS/MSC -		350.9			
		AFL		149			
VSB ACP-6000-23-1 REV IR	COMMUNICATIONS ACP-6000 AUDIO CONTROL PANEL, VENDOR SERVICE BULLETIN						COMPLIED WITH
		MOS		23-APR-2014			
		HRS/MSC -		12.8			
		AFL		6			
VSB BA05801-24-28 REV 2	ELECTRICAL POWER - VARIABLE FREQUENCY GENERATOR INTRODUCTION OF THE BA05801-07 MODSTRIKE 1, VENDOR SERVICE BULLETIN					VENDOR RECOMMENDATIO N	COMPLIED WITH
		MOS		23-APR-2014			
		HRS/MSC -		12.8			
		AFL		6			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
VSB BR710-NAC-71-0051 REV II	NACELLE - POWER PLANT - FIXED COWL - FRONT MOUNT ACCESS PANEL - INTRODUCTION OF A DRAIN HOLE., VENDOR SERVICE BULLETIN					VENDOR RECOMMENDATIO N	COMPLIED WITH
		MOS		23-APR-2014			
		HRS/MSC -		12.8			
		AFL		6			
VSB CTP-6000-23-1 REV 1	COMMUNICATIONS - CTP-6000 CONTROL TUNING PANEL (CPN 822-2493-003) - 1/0 CIRCUIT CARD A2A3 (CPN 828-2653-004/005) - REDUCE OCCURRENCE OF UNCOMMANDED BEHAVIOR., VENDOR SERVICE BULLETIN						COMPLIED WITH - FOUND EMBODIED
		MOS		23-APR-2014			
		HRS/MSC -		12.8			
		AFL		6			
VSB WLU-2100-23-502	COMMUNICATIONS - WLU-2100 MULTI-MODE WIRELESS LAN UNIT (CPN 822-2210-501) WLU-2100 CONVERSION FOR COMPATIBILITY WITH BRS CES V10 PLATFORMS (CONVERTS BLACK LABEL CPN 822-2210-501 TO BLACK LABEL CPN 822-2210-502), VENDOR SERVICE BULLETIN					VENDOR RECOMMENDATIO N	COMPLIED WITH
		MOS		23-APR-2014			
		HRS/MSC -					
		AFL					
VSB ZDE-6000-44-502 REV 2	CABIN ELECTRONICS SYSTEM - ZDE-6000 ZONE DISTRIBUTION EQUIPMENT (CPN 1308523-101). NOTE: C/O ON UNIT S/N 4JJWJ, 4JJTB, 41244C, 42DGM, 4CT1N., VENDOR SERVICE BULLETIN					VENDOR RECOMMENDATIO N	COMPLIED WITH - FOUND EMBODIED
		MOS		23-APR-2014			
		HRS/MSC -		12.8			
		AFL		6			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
APU - AD - P-715/WE3800714-1							
EASA 2010-0079	APU - MICROTURBO - SAPHIR 20 MODEL 095 AUXILIARY POWER UNIT - AIRBORNE AUXILIARY POWER - AUXILIARY POWER UNIT TURBINE WHEEL LIFE LIMIT - REDUCTION					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED
		MOS HRS/MSC - AFL		08-OCT-2015			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
APU - SB - P-715/WE3800714-1							
SB 49-7759 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - INSPECTION OF SPECIFIC FADEC CONTROLLER, PART NO. 2118990-3, SERVICE BULLETIN					RECOMMENDED	
		MOS		26-SEP-2013			
		HRS/MSC -		0			
		APUS		0			
SB 49-7933 R05	APU - AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
	23-OCT-2014	HRS/MSC -					
		APUS					
SB RE220-49-8169 R03	APU - GAS TURBINE ENGINE - VISUAL INSPECTION AND SEALANT APPLICATION METHOD FOR THE EXHAUST GAS TEMPERATURE (EGT) SENSOR, PN WE3876352-1, -2, ON RE220 AUXILIARY POWER UNITS (APUS), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - PARTS A & B , PT C N/A
		MOS		23-MAR-2018			
	26-JUN-2017	HRS/MSC -					
		APUS					
SIL APU-87 REV 4	APU - APU - AUTO SHUT DOWN IN HEAVY RAIN, SERVICE INFORMATION LETTER					SERVICE LETTER	COMPLIED WITH
		MOS		08-OCT-2015			
		HRS/MSC -					
		APUS					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 1 - AD - 22301/DEL114							
EASA 2010-0075	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE DISCS STAGE 1 AND 2 ASSEMBLY LIFE LIMITS - MODIFICATION					MANDATORY	COMPLIED WITH - AT MANUFACTURE
04-MAY-2010		MOS HRS/MSC - APUS ENC		23-SEP-2013 0 0			
EASA 2010-0077	NO. 1 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT					MANDATORY	COMPLIED WITH - AT MANUFACTURE
04-MAY-2010		MOS HRS/MSC - ENC		23-SEP-2013 0 0			
EASA 2012-0161	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING					MANDATORY	COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC - ENC		23-SEP-2013 0 0			
EASA 2012-0166	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR DISC STAGE 1 AND STAGE 2 LIFE LIMITATION - IMPLEMENTATION					MANDATORY	COMPLIED WITH - AT MANUFACTURE
13-SEP-2012		MOS HRS/MSC - ENC		23-SEP-2013 0 0			
EASA 2013-0296	NO. 1 ENGINE - ENGINE - HIGH PRESSURE COMPRESSOR AND COMBUSTION FAIRINGS - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - BY ENGINE SERIAL NUMBER
25-DEC-2013		MOS HRS/MSC - ENC		17-APR-2014			
EASA 2013-0296 PARA (1)	NO. 1 ENGINE - INSPECT THE UPPER LEFT HPC FAIRING					MANDATORY	NOT APPLICABLE - BY ENGINE SERIAL NUMBER
25-DEC-2013		MOS HRS/MSC - ENC		17-APR-2014			
EASA 2013-0296 PARA (2)	NO. 1 ENGINE - REPLACE THE UPPER LEFT HPC FAIRING					MANDATORY	NOT APPLICABLE - BY ENGINE SERIAL NUMBER
25-DEC-2013		MOS HRS/MSC - ENC		17-APR-2014			
EASA 2013-0296 PARA (3)	NO. 1 ENGINE - REPLACE AN UPPER LEFT, UPPER RIGHT AND LOWER RIGHT COMBUSTION SECTION FAIRING					MANDATORY	NOT APPLICABLE - BY ENGINE SERIAL NUMBER
25-DEC-2013		MOS HRS/MSC - ENC		17-APR-2014			
EASA 2013-0296-CN	NO. 1 ENGINE - CANCELLED: ENGINE - HIGH PRESSURE COMPRESSOR AND COMBUSTION FAIRINGS - INSPECTION / REPLACEMENT					CANCELLED	NOT APPLICABLE
26-JUN-2014		MOS HRS/MSC - ENC		(EFF)			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2017-0198	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER FIREBOX ASSEMBLY - REPLACEMENT (CANCELLED BY EASA AD 2017-0198-CN)					MANDATORY	COMPLIED WITH - SB BR700-73-A101977 REV 3
10-OCT-2017		MOS		24-MAY-2019			
		HRS/MSC	-	879.42			
		ENC		365			
EASA 2018-0268	NO. 1 ENGINE - ENGINE - LIFE-LIMITED CRITICAL PARTS - SERVICE LIFE CALCULATION / REPLACEMENT					MANDATORY	COMPLIED WITH - VERIFIED SB BR700-72-A900584 R02 PCW 3/23/18
01-JAN-2019		MOS		24-MAY-2019			
		HRS/MSC	-(s)	879.42			
		ENC		365			
EASA 2018-0268 PARA (1)	NO. 1 ENGINE - DETERMINE THE OPERATIONAL HISTORY OF THE LPC DISC AND, BASED ON THAT DETERMINATION, RE-CALCULATE THE CONSUMED (AND REMAINING) SERVICE LIFE OF THE LPC DISC (FOR EACH AFFECTED ENGINE)					MANDATORY	COMPLIED WITH - VERIFIED SB BR700-72-A900584 R02 PCW 3/23/18
01-JAN-2019		MOS		24-MAY-2019			
		HRS/MSC	DUE	879.42			
		ENC		365			
EASA 2018-0268 PARA (2)	NO. 1 ENGINE - ACCOMPLISH A ONE-TIME RE-CALCULATION OF THE SERVICE LIFE ACCUMULATED BY THE LPC DISC ON THAT AFFECTED ENGINE (FOR EACH AFFECTED ENGINE)					MANDATORY	NOT APPLICABLE - DUE TO ENGINE WITHIN 250 CYCLES AND 12 MONTHS OF EFFECTIVE DATE
01-JAN-2019		MOS		24-MAY-2019			
		HRS/MSC	-	879.42			
		ENC		365			
EASA 2018-0268 PARA (3)	NO. 1 ENGINE - RE-CALCULATE THE CONSUMED (AND REMAINING) SERVICE LIFE OF EACH AFFECTED LLP (FOLLOWING THE RE-CALCULATION OF THE SERVICE LIFE ACCUMULATED BY THE LPC DISC ON AN AFFECTED ENGINE, AS REQUIRED BY PARAGRAPH (2) OF THIS AD)					MANDATORY	NOT APPLICABLE - DUE TO ENGINE WITHIN 250 CYCLES AND 12 MONTHS OF EFFECTIVE DATE
01-JAN-2019		MOS		24-MAY-2019			
		HRS/MSC	DUE (s)	879.42			
		ENC		365			
EASA 2018-0268 PARA (4)	NO. 1 ENGINE - REPLACE THAT AFFECTED LLP WITH A SERVICEABLE PART					MANDATORY	NOT APPLICABLE - N/A DUE TO LIFELIMIT NOT REACHED
01-JAN-2019		DAYS		24-MAY-2019			
		HRS/MSC	-(s)	879.42			
		ENC		365			
EASA 2018-0268 PARA (6)	NO. 1 ENGINE - TERMINATING ACTION: RE-CALCULATION OF THE CONSUMED (AND REMAINING) SERVICE LIFE OF EACH AFFECTED LLP ON AN AFFECTED ENGINE IN ACCORDANCE WITH THE INSTRUCTIONS OF PART B "REQUIREMENT 2" OF THE NMSB, AS REQUIRED BY PARAGRAPH (3) OF THIS AD. CONSTITUTES TERMINATING ACTION FOR THE REPETITIVE RE-CALCULATIONS OF THE LPC DISC LIFE AS REQUIRED BY PARAGRAPH (1) OF THIS AD FOR THAT AFFECTED ENGINE					MANDATORY	NOT APPLICABLE - DUE TO ENG INSTALLED ON POST MOD AIRCRAFT
01-JAN-2019		MOS		24-MAY-2019			
		HRS/MSC	-(s)	879.42			
		ENC		365			
EASA 2018-0268 PARA (7)	NO. 1 ENGINE - TERMINATING ACTION: INSTALLATION OF AN AFFECTED ENGINE ON A POST-MOD AEROPLANE, AS DEFINED IN THIS AD, CONSTITUTES TERMINATING ACTION FOR THE REPETITIVE RE-CALCULATION REQUIREMENTS OF PARAGRAPH (3) OF THIS AD FOR THAT ENGINE, EXCEPT AS SPECIFIED IN PARAGRAPH (8) OF THIS AD					MANDATORY	COMPLIED WITH - VERIFIED ENGINE IS INSTALLED ON A POST MOD AIRCRAFT SINCE COMPLETION OF SB BR 700-72-A900584 R2 ON 3/23/18
01-JAN-2019		MOS		24-MAY-2019			
		HRS/MSC	-(s)	879.42			
		ENC		365			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2019-0299	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE STAGE 1 DISCS - LIFE LIMIT REDUCTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - BY S/N PER PARA 1.A(2) OF ASB -BR-700-A900659 R01
24-DEC-2019		MOS		05-JAN-2020			
		HRS/MSC - (s)		928.37			
		ENC		388			
EASA 2019-0299 PARA (1)	NO. 1 ENGINE - DETERMINE WHETHER AN AFFECTED PART, AS DEFINED IN THIS AD, IS INSTALLED ON THE ENGINE					MANDATORY	NOT APPLICABLE - BY S/N PER PARA 1.A(2) OF ASB -BR-700-A900659 R01
24-DEC-2019		MOS		05-JAN-2020			
		HRS/MSC -		928.37			
		ENC		388			
EASA 2019-0299 PARA (2)	NO. 1 ENGINE - REMOVE THE ENGINE FROM SERVICE AND, BEFORE RELEASE TO SERVICE OF THAT ENGINE, REPLACE THE AFFECTED PART WITH A SERVICEABLE PART (FOR EACH ENGINE FOR WHICH IT HAS BEEN DETERMINED, AS REQUIRED BY PARAGRAPH (1) OF THIS AD, THAT AN AFFECTED PART IS INSTALLED)					MANDATORY	NOT APPLICABLE - BY S/N PER PARA 1.A(2) OF ASB -BR-700-A900659 R01
24-DEC-2019		MOS		05-JAN-2020			
		HRS/MSC - (s)		928.37			
		ENC		388			
FAA 1998-24-03 R01	NO. 1 ENGINE - VISUAL INSPECTION OF ENGINE CORE FAIRING FASTENERS.						COMPLIED WITH - AT MANUFACTURE
27-DEC-1999		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
FAA 2001-01-01	NO. 1 ENGINE - ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH - REPLACE						NOT APPLICABLE
31-JAN-2001		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
FAA 2001-05-06 ULTRASONIC INSP	NO. 1 ENGINE - ULTRASONIC INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS					SUPERSEDED	NOT APPLICABLE - SUPERSEDED BY 2003-07-11
39-12142		MOS		23-SEP-2013			
14-MAR-2001		HRS/MSC N/A		0			
		ENC					
FAA 2001-05-06 VISUAL INSP	NO. 1 ENGINE - VISUAL INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS					SUPERSEDED	NOT APPLICABLE - SUPERSEDED BY 2003-07-11
39-12142		MOS		23-SEP-2013			
14-MAR-2001		HRS/MSC N/A		0			
		ENC		0			
FAA 2003-07-11 PART B	NO. 1 ENGINE - VISUAL OR ULTRASONIC INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS					SUPERSEDED	NOT APPLICABLE - SUPERSEDED BY 2005-21-05
39-13107		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
FAA 2003-07-11 PART F	NO. 1 ENGINE - VISUAL AND ULTRASONIC INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS					SUPERSEDED	NOT APPLICABLE - SUPERSEDED BY 2005-21-05
		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
FAA 2005-21-05 PART 1	NO. 1 ENGINE - VISUAL OR ULTRASONIC INSPECTION OF THE FAN DISC					MANDATORY	NOT APPLICABLE
		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2005-21-05 PART 2	NO. 1 ENGINE - ULTRASONIC AND VISUAL INSPECTION OF THE FAN DISC					MANDATORY	NOT APPLICABLE
		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
FAA 2005-21-05 PART L	NO. 1 ENGINE - VISUAL AND ULTRASONIC INSPECTION AS MANDATED IN RRD TIME LIMITS MANUAL T-710-2BR, CHAPTER 05-10-01 (BR700-710A2-20).					MANDATORY	NOT APPLICABLE
		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
FAA 2010-25-05	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE DISCS STAGE 1 AND 2 ASSEMBLY LIFE LIMITS - MODIFICATION					MANDATORY	COMPLIED WITH
39-16538		MOS		24-MAY-2014			
13-JAN-2011		HRS/MSC -					
		ENC					
FAA 2011-22-01	NO. 1 ENGINE - ROLLS-ROYCE DEUTSCHLAND LTD & CO KG (RRD) BR700-710 SERIES TURBOFAN ENGINES - LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT					MANDATORY	COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2013			
23-NOV-2011		HRS/MSC -		0			
		ENC		0			
FAA 2011-22-01 (E) (1), (2)	NO. 1 ENGINE - REVISE ROLLS-ROYCE DEUTSCHLAND LTD & CO KG (RRD) BR700-710 SERIES TURBOFAN ENGINES - LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT THE AIRWORTHINESS LIMITATIONS SECTION (ALS) OF THE OPERATORS' APPROVED MAINTENANCE PROGRAM (REFERENCE THE TIME LIMITS MANUAL (TLM), CHAPTERS 05-00-01 AND 05-00-02 OF THE APPLICABLE ENGINE MANUALS (EMS))					MANDATORY	COMPLIED WITH
		DAYS		23-SEP-2013			
23-NOV-2011		HRS/MSC -					
		ENC					
FAA 2011-22-01 PARA (E)(3)	NO. 1 ENGINE - DETERMINE ROLLS-ROYCE DEUTSCHLAND LTD & CO KG (RRD) BR700-710 SERIES TURBOFAN ENGINES - LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT THE NUMBER OF TOUCH-AND-GO'S AND OVERSHOOT THAT EACH INDIVIDUAL CRITICAL PART EXCEPT THE FAN SHAFT AND LP TURBINE ROTOR SHAFT HAS EXPERIENCED SINCE ENTRY INTO SERVICE FOR PILOT TRAINING					MANDATORY	COMPLIED WITH
		DAYS		23-SEP-2013			
23-NOV-2011		HRS/MSC -					
		ENC					
FAA 2013-03-17	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR DISC STAGE 1 AND STAGE 2 LIFE LIMITATION - IMPLEMENTATION					MANDATORY	COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2013			
39-17351		HRS/MSC -		0			
21-MAR-2013		ENC		0			
FAA 2013-05-13	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING					MANDATORY	COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2013		RECURRING	
24-APR-2013		HRS/MSC	4000	0	4000		
		ENC		0			
FAA 2016-13-12	NO. 1 ENGINE - ENGINE - PAWL CARRIER PIVOT PINS, PART NUMBER (P/N) BRR17117, - REMOVE FROM SERVICE / REPLACE					MANDATORY	COMPLIED WITH - NOT APPLICABLE BY ENGINE SERIAL NUMBER
		MOS		10-NOV-2016			
05-AUG-2016		HRS/MSC -		541.13			
		ENC		225			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2018-18-14	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER FIREBOX ASSEMBLY - REPLACEMENT					MANDATORY	COMPLIED WITH - SB BR700-73-A101977 REV 3
12-OCT-2018		MOS HRS/MSC - ENC		25-MAY-2019 879.42 365			
FAA 2021-12-07	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE (HPT) STAGE 1 DISK - REPLACE					MANDATORY	NOT APPLICABLE - PER SB
12-AUG-2021		DAYS HRS/MSC - ENC		27-AUG-2021 1012.88 430			
FAA 2021-21-12	NO. 1 ENGINE - TURBINE ENGINE COMPRESSOR SECTION - LIFE-LIMITED CRITICAL PARTS - SERVICE LIFE CALCULATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - BOMBARDIER SB 700-34-5021 WAS C/W 23 MAR 2018
13-DEC-2021		MOS HRS/MSC - ENC		25-FEB-2022 1035.25 441			
FAA 2021-21-12 PARA (G)(1)	NO. 1 ENGINE - RECALCULATE THE CONSUMED AND REMAINING SERVICE LIFE OF EACH AFFECTED LLP					MANDATORY	NOT APPLICABLE - BOMBARDIER SB 700-34-5021 WAS C/W 23 MAR 2018
13-DEC-2021		DAYS HRS/MSC - ENC		25-FEB-2022 1035.25 441			
FAA 2021-21-12 PARA (G)(2)	NO. 1 ENGINE - CALCULATE THE CONSUMED AND REMAINING SERVICE LIFE OF EACH AFFECTED LLP (FOR ENGINES INSTALLED AND OPERATED ON A PRE-MOD AIRPLANE, AFTER PERFORMING THE INITIAL RECALCULATIONS REQUIRED BY PARA (G)(1))					MANDATORY	NOT APPLICABLE - BOMBARDIER SB 700-34-5021 WAS C/W 23 MAR 2018
13-DEC-2021		MOS HRS/MSC - (s) ENC		25-FEB-2022 1035.25 441			
FAA 2021-21-12 PARA (G)(3)	NO. 1 ENGINE - REMOVE EACH AFFECTED LLP					MANDATORY	NOT APPLICABLE - BOMBARDIER SB 700-34-5021 WAS C/W 23 MAR 2018
13-DEC-2021		DAYS HRS/MSC - ENC		25-FEB-2022 1035.25 441			
LBA D-1998-467	NO. 1 ENGINE - ENGINE - SEPARATION OF THE ENGINE CORE FAIRINGS DUE TO INCORRECT INSTALLATION					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 1998-467/2
04-NOV-1998		MOS HRS/MSC - ENC		23-SEP-2013 0 0			
LBA D-1998-467 R02	NO. 1 ENGINE - ENGINE - SEPARATION OF THE ENGINE CORE FAIRINGS DUE TO INCORRECT INSTALLATION					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 1998-467/3
26-MAR-1999		MOS HRS/MSC - ENC		23-SEP-2013 0 0			
LBA D-1998-467 R03	NO. 1 ENGINE - ENGINE - SEPARATION OF THE ENGINE CORE FAIRINGS DUE TO INCORRECT INSTALLATION					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 1998-467/4
15-SEP-1999		MOS HRS/MSC - ENC		23-SEP-2013 0 0			
LBA D-1998-467 R04	NO. 1 ENGINE - ENGINE - SEPARATION OF THE ENGINE CORE FAIRINGS DUE TO INCORRECT INSTALLATION					MANDATORY	COMPLIED WITH - NOT AFFECTED BY ENGINE SERIAL NUMBER 22301 AND 22300 INSTALLED AT TIME OF DELIVERY.
19-SEP-2002		MOS HRS/MSC - ENC		24-MAY-2014			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
LBA D-2000-257	NO. 1 ENGINE - ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-257/2
25-JUL-2000		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2000-257 PART 1	NO. 1 ENGINE - PERFORM ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431 INSPECTION TO DETERMINE THE SERIAL NUMBER					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-257/2
25-JUL-2000		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2000-257 PART 2 & 3	NO. 1 ENGINE - PERFORM ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431 REPLACE THE OIL FILTER DIFFERENTIAL PRESSURE SWITCH UNIT OR MARK THE OIL FILTER DIFFERENTIAL PRESSURE SWITCH UNIT WITH A STRIP OF A HIGH TEMPERATURE YELLOW PAINT.					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-257/2
25-JUL-2000		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2000-257 R02	NO. 1 ENGINE - ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431					MANDATORY	NOT APPLICABLE
24-AUG-2000		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2000-257 R02 PART 1	NO. 1 ENGINE - PERFORM ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431 INSPECTION TO DETERMINE THE SERIAL NUMBER					MANDATORY	NOT APPLICABLE
24-AUG-2000		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2000-257 R02 PART 2	NO. 1 ENGINE - REPLACE ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431 THE OIL FILTER DIFFERENTIAL PRESSURE SWITCH UNIT					MANDATORY	NOT APPLICABLE
24-AUG-2000		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2000-348	NO. 1 ENGINE - ENGINE - LP COMPRESSOR - FAN DISC CRACKS (ATA 72)					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-348/2
02-OCT-2000		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2000-348 R02	NO. 1 ENGINE - ENGINE - LP COMPRESSOR - FAN DISC CRACKS (ATA 72)					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-348/3
24-NOV-2000		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2000-348 R03	NO. 1 ENGINE - ENGINE - LP COMPRESSOR - FAN DISC CRACKS (ATA 72)					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-348/4
		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2000-348 R04	NO. 1 ENGINE - ENGINE - LP COMPRESSOR - FAN DISC CRACKS (ATA 72)					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-348/5
		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
LBA D-2000-348 R05	NO. 1 ENGINE - ENGINE - LP COMPRESSOR - FAN DISC CRACKS (ATA 72)					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-348/6
		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2000-348 R06	NO. 1 ENGINE - ENGINE - LP COMPRESSOR - FAN DISC CRACKS (ATA 72)						NOT APPLICABLE
		MOS		23-SEP-2013			
31-MAR-2005		HRS/MSC -		0			
		ENC		0			
LBA D-2000-348 REV 6 PART 4	NO. 1 ENGINE - VISUAL OR ULTRASONIC INSP FAN DISC, P/N BRR20791						NOT APPLICABLE
		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2000-348 REV 6 PART 5	NO. 1 ENGINE - VISUAL AND ULTRASONIC INSP OF FAN DISC, ALL P/NS						NOT APPLICABLE
		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2007-352	NO. 1 ENGINE - REVERSE WIRED INDEPENDENT OVERSPEED PROTECTION COILS IN BR700 SERIES ENGINES					MANDATORY	NOT APPLICABLE
		MOS		23-SEP-2013			
21-DEC-2007		HRS/MSC -		0			
		ENC		0			
LBA D-2008-222	NO. 1 ENGINE - BR700-710 - RE-USE OF POTENTIALLY DAMAGED ENGINE MATERIAL					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2008-222 R1
		MOS		23-SEP-2013			
23-JUN-2008		HRS/MSC -		0			
		ENC		0			
LBA D-2008-222 R01	NO. 1 ENGINE - BR700-710 - RE-USE OF POTENTIALLY DAMAGED ENGINE MATERIAL					MANDATORY	NOT APPLICABLE
		MOS		23-SEP-2013			
25-SEP-2008		HRS/MSC -		0			
		ENC		0			
LBA D-2010-126	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE DISCS STAGE 1 AND 2 ASSEMBLY LIFE LIMITS - MODIFICATION					MANDATORY	COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2013			
03-MAY-2010		HRS/MSC -		0			
		ENC		0			
LBA D-2010-130	NO. 1 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT					MANDATORY	COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2013			
03-MAY-2010		HRS/MSC -		0			
		ENC		0			
LBA D-2012-340	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING					MANDATORY	COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
LBA D-2012-346	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR DISC STAGE 1 AND STAGE 2 LIFE LIMITATION - IMPLEMENTATION	MOS HRS/MSC - ENC		24-MAY-2014		MANDATORY	NOT APPLICABLE - DUE TO HPT S/N INSTALLED
LBA D-2013-366	NO. 1 ENGINE - ENGINE - HIGH PRESSURE COMPRESSOR AND COMBUSTION FAIRINGS - INSPECTION / REPLACEMENT	MOS HRS/MSC - ENC		24-MAY-2014		MANDATORY	NOT APPLICABLE - BY ENGINE SERIAL NUMBER



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 2 - AD - 22300/DER114							
EASA 2010-0075	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE DISCS STAGE 1 AND 2 ASSEMBLY LIFE LIMITS - MODIFICATION					MANDATORY	COMPLIED WITH - AT MANUFACTURE
04-MAY-2010		MOS HRS/MSC - ENC		19-AUG-2013 0 0			
EASA 2010-0077	NO. 2 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT					MANDATORY	COMPLIED WITH - AT MANUFACTURE
04-MAY-2010		MOS HRS/MSC - ENC		19-AUG-2013 0 0			
EASA 2012-0161	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING					MANDATORY	COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC - ENC		19-AUG-2013 0 0			
EASA 2012-0166	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR DISC STAGE 1 AND STAGE 2 LIFE LIMITATION - IMPLEMENTATION					MANDATORY	COMPLIED WITH - AT MANUFACTURE
13-SEP-2012		MOS HRS/MSC - ENC		19-AUG-2013 0 0			
EASA 2013-0296	NO. 2 ENGINE - ENGINE - HIGH PRESSURE COMPRESSOR AND COMBUSTION FAIRINGS - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - BY ENGINE SERIAL NUMBER
25-DEC-2013		MOS HRS/MSC - ENC		17-APR-2014			
EASA 2013-0296 PARA (1)	NO. 2 ENGINE - INSPECT THE UPPER LEFT HPC FAIRING					MANDATORY	NOT APPLICABLE - BY ENGINE SERIAL NUMBER
25-DEC-2013		MOS HRS/MSC - ENC		17-APR-2014			
EASA 2013-0296 PARA (2)	NO. 2 ENGINE - REPLACE THE UPPER LEFT HPC FAIRING					MANDATORY	NOT APPLICABLE - BY ENGINE SERIAL NUMBER
25-DEC-2013		MOS HRS/MSC - ENC		17-APR-2014			
EASA 2013-0296 PARA (3)	NO. 2 ENGINE - REPLACE AN UPPER LEFT, UPPER RIGHT AND LOWER RIGHT COMBUSTION SECTION FAIRING					MANDATORY	NOT APPLICABLE - BY ENGINE SERIAL NUMBER
25-DEC-2013		MOS HRS/MSC - ENC		17-APR-2014			
EASA 2013-0296-CN	NO. 2 ENGINE - CANCELLED: ENGINE - HIGH PRESSURE COMPRESSOR AND COMBUSTION FAIRINGS - INSPECTION / REPLACEMENT					CANCELLED	NOT APPLICABLE
26-JUN-2014		MOS HRS/MSC - ENC		(EFF)			
EASA 2017-0198	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER FIREBOX ASSEMBLY - REPLACEMENT (CANCELLED BY EASA AD 2017-0198-CN)					MANDATORY	COMPLIED WITH - SB BR700-73-A101977 REV 3
10-OCT-2017		MOS HRS/MSC - ENC		01-MAY-2019 879.42 365			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2018-0268	NO. 2 ENGINE - ENGINE - LIFE-LIMITED CRITICAL PARTS - SERVICE LIFE CALCULATION / REPLACEMENT					MANDATORY	COMPLIED WITH - VERIFIED SB BR700-72-A900584 R02 PCW 3/23/18
01-JAN-2019		MOS HRS/MSC - (s) ENC		10-APR-2019 879.42 365			
EASA 2018-0268 PARA (1)	NO. 2 ENGINE - DETERMINE THE OPERATIONAL HISTORY OF THE LPC DISC AND, BASED ON THAT DETERMINATION, RE-CALCULATE THE CONSUMED (AND REMAINING) SERVICE LIFE OF THE LPC DISC (FOR EACH AFFECTED ENGINE)					MANDATORY	COMPLIED WITH - VERIFIED SB BR700-72-A900584 R02 PCW 3/23/18
01-JAN-2019		MOS HRS/MSC DUE ENC		10-APR-2019 879.42 365			
EASA 2018-0268 PARA (2)	NO. 2 ENGINE - ACCOMPLISH A ONE-TIME RE-CALCULATION OF THE SERVICE LIFE ACCUMULATED BY THE LPC DISC ON THAT AFFECTED ENGINE (FOR EACH AFFECTED ENGINE)					MANDATORY	NOT APPLICABLE - DUE TO ENGINE WITHIN 250 CYCLES AND 12 MONTHS OF EFFECTIVE DATE
01-JAN-2019		MOS HRS/MSC - ENC		10-APR-2019 879.42 365			
EASA 2018-0268 PARA (3)	NO. 2 ENGINE - RE-CALCULATE THE CONSUMED (AND REMAINING) SERVICE LIFE OF EACH AFFECTED LLP (FOLLOWING THE RE-CALCULATION OF THE SERVICE LIFE ACCUMULATED BY THE LPC DISC ON AN AFFECTED ENGINE, AS REQUIRED BY PARAGRAPH (2) OF THIS AD)					MANDATORY	NOT APPLICABLE - DUE TO ENGINE BEING INSTALLED ON POST-MOD AIRCRAFT
01-JAN-2019		MOS HRS/MSC DUE (s) ENC		10-APR-2019 879.42 365			
EASA 2018-0268 PARA (4)	NO. 2 ENGINE - REPLACE THAT AFFECTED LLP WITH A SERVICEABLE PART					MANDATORY	NOT APPLICABLE - DUE TO LIFE LIMIT NOT REACHED
01-JAN-2019		DAYS HRS/MSC - (s) ENC		10-APR-2019 879.42 365			
EASA 2018-0268 PARA (6)	NO. 2 ENGINE - TERMINATING ACTION: RE-CALCULATION OF THE CONSUMED (AND REMAINING) SERVICE LIFE OF EACH AFFECTED LLP ON AN AFFECTED ENGINE IN ACCORDANCE WITH THE INSTRUCTIONS OF PART B "REQUIREMENT 2" OF THE NMSB, AS REQUIRED BY PARAGRAPH (3) OF THIS AD, CONSTITUTES TERMINATING ACTION FOR THE REPETITIVE RE-CALCULATIONS OF THE LPC DISC LIFE AS REQUIRED BY PARAGRAPH (1) OF THIS AD FOR THAT AFFECTED ENGINE					MANDATORY	NOT APPLICABLE - DUE TO ENGINE BEING INSTALLED ON POST-MOD AIRCRAFT
01-JAN-2019		MOS HRS/MSC - (s) ENC		10-APR-2019 879.42 365			
EASA 2018-0268 PARA (7)	NO. 2 ENGINE - TERMINATING ACTION: INSTALLATION OF AN AFFECTED ENGINE ON A POST-MOD AEROPLANE, AS DEFINED IN THIS AD, CONSTITUTES TERMINATING ACTION FOR THE REPETITIVE RE-CALCULATION REQUIREMENTS OF PARAGRAPH (3) OF THIS AD FOR THAT ENGINE, EXCEPT AS SPECIFIED IN PARAGRAPH (8) OF THIS AD					MANDATORY	COMPLIED WITH - VERIFIED ENGINE IS INSTALLED ON A POST MOD AIRCRAFT SINCE COMPLETION OF SB BR 700-72-A900584 R2 ON 3/23/18
01-JAN-2019		MOS HRS/MSC - (s) ENC		10-APR-2019 879.42 365			
EASA 2019-0299	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE STAGE 1 DISCS - LIFE LIMIT REDUCTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - BY S/N PER PARA 1.A(2) OF ASB -BR-700-A900659 R01
24-DEC-2019		MOS HRS/MSC - (s) ENC		05-JAN-2020 928.37 388			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2019-0299 PARA (1)	NO. 2 ENGINE - DETERMINE WHETHER AN AFFECTED PART, AS DEFINED IN THIS AD, IS INSTALLED ON THE ENGINE					MANDATORY	NOT APPLICABLE - BY S/N PER PARA 1.A(2) OF ASB -BR-700-A900659 R01
24-DEC-2019		MOS		05-JAN-2020			
		HRS/MSC -		928.37			
		ENC		388			
EASA 2019-0299 PARA (2)	NO. 2 ENGINE - REMOVE THE ENGINE FROM SERVICE AND, BEFORE RELEASE TO SERVICE OF THAT ENGINE, REPLACE THE AFFECTED PART WITH A SERVICEABLE PART (FOR EACH ENGINE FOR WHICH IT HAS BEEN DETERMINED, AS REQUIRED BY PARAGRAPH (1) OF THIS AD, THAT AN AFFECTED PART IS INSTALLED)						NOT APPLICABLE - BY S/N PER PARA 1.A(2) OF ASB -BR-700-A900659 R01
24-DEC-2019		MOS		05-JAN-2020			
		HRS/MSC - (s)		928.37			
		ENC		388			
FAA 1998-24-03 R01	NO. 2 ENGINE - VISUAL INSPECTION OF ENGINE CORE FAIRING FASTENERS.						COMPLIED WITH - AT MANUFACTURE
27-DEC-1999		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
FAA 2001-01-01	NO. 2 ENGINE - ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH - REPLACE						NOT APPLICABLE
31-JAN-2001		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
FAA 2001-05-06 ULTRASONIC INSP	NO. 2 ENGINE - ULTRASONIC INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS					SUPERSEDED	NOT APPLICABLE - SUPERSEDED BY 2003-07-11
39-12142		MOS		19-AUG-2013			
14-MAR-2001		HRS/MSC N/A		0			
		ENC		0			
FAA 2001-05-06 VISUAL INSP	NO. 2 ENGINE - VISUAL INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS					SUPERSEDED	NOT APPLICABLE - SUPERSEDED BY 2003-07-11
39-12142		MOS		19-AUG-2013			
14-MAR-2001		HRS/MSC N/A		0			
		ENC		0			
FAA 2003-07-11 PART B	NO. 2 ENGINE - VISUAL OR ULTRASONIC INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS					SUPERSEDED	NOT APPLICABLE - SUPERSEDED BY 2005-21-05
39-13107		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
FAA 2003-07-11 PART F	NO. 2 ENGINE - VISUAL AND ULTRASONIC INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS					SUPERSEDED	NOT APPLICABLE - SUPERSEDED BY 2005-21-05
		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
FAA 2005-21-05 PART 1	NO. 2 ENGINE - VISUAL OR ULTRASONIC INSPECTION OF THE FAN DISC					MANDATORY	NOT APPLICABLE
		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
FAA 2005-21-05 PART 2	NO. 2 ENGINE - ULTRASONIC AND VISUAL INSPECTION OF THE FAN DISC					MANDATORY	NOT APPLICABLE
		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2005-21-05 PART L	NO. 2 ENGINE - VISUAL AND ULTRASONIC INSPECTION AS MANDATED IN RRD TIME LIMITS MANUAL T-710-2BR, CHAPTER 05-10-01 (BR700-710A2-20).					MANDATORY	NOT APPLICABLE
		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
FAA 2010-25-05	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE DISCS STAGE 1 AND 2 ASSEMBLY LIFE LIMITS - MODIFICATION					MANDATORY	COMPLIED WITH
39-16538		MOS		24-MAY-2014			
13-JAN-2011		HRS/MSC -					
		ENC					
FAA 2011-22-01	NO. 2 ENGINE - ROLLS-ROYCE DEUTSCHLAND LTD & CO KG (RRD) BR700-710 SERIES TURBOFAN ENGINES - LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT					MANDATORY	COMPLIED WITH - AT MANUFACTURE
		MOS		19-AUG-2013			
23-NOV-2011		HRS/MSC -		0			
		ENC		0			
FAA 2011-22-01 (E) (1), (2)	NO. 2 ENGINE - REVISE ROLLS-ROYCE DEUTSCHLAND LTD & CO KG (RRD) BR700-710 SERIES TURBOFAN ENGINES - LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT THE AIRWORTHINESS LIMITATIONS SECTION (ALS) OF THE OPERATORS' APPROVED MAINTENANCE PROGRAM (REFERENCE THE TIME LIMITS MANUAL (TLM), CHAPTERS 05-00-01 AND 05-00-02 OF THE APPLICABLE ENGINE MANUALS (EMS))					MANDATORY	COMPLIED WITH
		DAYS		19-AUG-2013			
23-NOV-2011		HRS/MSC -					
		ENC					
FAA 2011-22-01 PARA (E)(3)	NO. 2 ENGINE - DETERMINE ROLLS-ROYCE DEUTSCHLAND LTD & CO KG (RRD) BR700-710 SERIES TURBOFAN ENGINES - LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT THE NUMBER OF TOUCH-AND-GO'S AND OVERSHOOTS THAT EACH INDIVIDUAL CRITICAL PART EXCEPT THE FAN SHAFT AND LP TURBINE ROTOR SHAFT HAS EXPERIENCED SINCE ENTRY INTO SERVICE FOR PILOT TRAINING					MANDATORY	COMPLIED WITH
		DAYS		23-SEP-2013			
23-NOV-2011		HRS/MSC -					
		ENC					
FAA 2013-03-17	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR DISC STAGE 1 AND STAGE 2 LIFE LIMITATION - IMPLEMENTATION					MANDATORY	COMPLIED WITH - AT MANUFACTURE
		MOS		19-AUG-2013			
39-17351		HRS/MSC -		0			
21-MAR-2013		ENC		0			
FAA 2013-05-13	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING					MANDATORY	COMPLIED WITH - AT MANUFACTURE
		MOS		19-AUG-2013		RECURRING	
24-APR-2013		HRS/MSC 4000		0	4000		
		ENC		0			
FAA 2016-13-12	NO. 2 ENGINE - ENGINE - PAWL CARRIER PIVOT PINS, PART NUMBER (P/N) BRR17117, - REMOVE FROM SERVICE / REPLACE					MANDATORY	NOT APPLICABLE - NOT APPLICABLE BY ENGINE SERIAL NUMBER
		MOS		10-NOV-2016			
05-AUG-2016		HRS/MSC -		541.13			
		ENC		225			
FAA 2018-18-14	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER FIREBOX ASSEMBLY - REPLACEMENT					MANDATORY	COMPLIED WITH - SB BR700-73-A101977 REV 3
		MOS		25-MAY-2019			
12-OCT-2018		HRS/MSC -		879.42			
		ENC		365			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2021-12-07	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE (HPT) STAGE 1 DISK - REPLACE					MANDATORY	NOT APPLICABLE - PER SB
12-AUG-2021		DAYS		27-AUG-2021			
		HRS/MSC	-	1012.88			
		ENC		430			
FAA 2021-21-12	NO. 2 ENGINE - TURBINE ENGINE COMPRESSOR SECTION - LIFE-LIMITED CRITICAL PARTS - SERVICE LIFE CALCULATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - BOMBARDIER SB 700-34-5021 WAS C/W 23 MAR 2018
13-DEC-2021		MOS		25-FEB-2022			
		HRS/MSC	-	1035.25			
		ENC		441			
FAA 2021-21-12 PARA (G)(1)	NO. 2 ENGINE - RECALCULATE THE CONSUMED AND REMAINING SERVICE LIFE OF EACH AFFECTED LLP					MANDATORY	NOT APPLICABLE - BOMBARDIER SB 700-34-5021 WAS C/W 23 MAR 2018
13-DEC-2021		DAYS		25-FEB-2022			
		HRS/MSC	-	1035.25			
		ENC		441			
FAA 2021-21-12 PARA (G)(2)	NO. 2 ENGINE - CALCULATE THE CONSUMED AND REMAINING SERVICE LIFE OF EACH AFFECTED LLP (FOR ENGINES INSTALLED AND OPERATED ON A PRE-MOD AIRPLANE, AFTER PERFORMING THE INITIAL RECALCULATIONS REQUIRED BY PARA (G)(1))					MANDATORY	NOT APPLICABLE - BOMBARDIER SB 700-34-5021 WAS C/W 23 MAR 2018
13-DEC-2021		MOS		25-FEB-2022			
		HRS/MSC	-(s)	1035.25			
		ENC		441			
FAA 2021-21-12 PARA (G)(3)	NO. 2 ENGINE - REMOVE EACH AFFECTED LLP					MANDATORY	NOT APPLICABLE - BOMBARDIER SB 700-34-5021 WAS C/W 23 MAR 2018
13-DEC-2021		DAYS		25-FEB-2022			
		HRS/MSC	-	1035.25			
		ENC		441			
LBA D-1998-467	NO. 2 ENGINE - ENGINE - SEPARATION OF THE ENGINE CORE FAIRINGS DUE TO INCORRECT INSTALLATION					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 1998-467/2
04-NOV-1998		MOS		19-AUG-2013			
		HRS/MSC	-	0			
		ENC		0			
LBA D-1998-467 R02	NO. 2 ENGINE - ENGINE - SEPARATION OF THE ENGINE CORE FAIRINGS DUE TO INCORRECT INSTALLATION					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 1998-467/3
26-MAR-1999		MOS		19-AUG-2013			
		HRS/MSC	-	0			
		ENC		0			
LBA D-1998-467 R03	NO. 2 ENGINE - ENGINE - SEPARATION OF THE ENGINE CORE FAIRINGS DUE TO INCORRECT INSTALLATION					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 1998-467/4
15-SEP-1999		MOS		19-AUG-2013			
		HRS/MSC	-	0			
		ENC		0			
LBA D-1998-467 R04	NO. 2 ENGINE - ENGINE - SEPARATION OF THE ENGINE CORE FAIRINGS DUE TO INCORRECT INSTALLATION					MANDATORY	COMPLIED WITH - NOT AFFECTED BY ENGINE SERIAL NUMBER 22301 AND 22300 INSTALLED AT TIME OF DELIVERY.
19-SEP-2002		MOS		24-MAY-2014			
		HRS/MSC	-				
		ENC					
LBA D-2000-257	NO. 2 ENGINE - ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-257/2
25-JUL-2000		MOS		19-AUG-2013			
		HRS/MSC	-	0			
		ENC		0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
LBA D-2000-257 PART 1	NO. 2 ENGINE - PERFORM ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431 INSPECTION TO DETERMINE THE SERIAL NUMBER					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-257/2
25-JUL-2000		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2000-257 PART 2 & 3	NO. 2 ENGINE - PERFORM ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431 REPLACE THE OIL FILTER DIFFERENTIAL PRESSURE SWITCH UNIT OR MARK THE OIL FILTER DIFFERENTIAL PRESSURE SWITCH UNIT WITH A STRIP OF A HIGH TEMPERATURE YELLOW PAINT.					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-257/2
25-JUL-2000		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2000-257 R02	NO. 2 ENGINE - ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431					MANDATORY	NOT APPLICABLE
24-AUG-2000		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2000-257 R02 PART 1	NO. 2 ENGINE - PERFORM ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431 INSPECTION TO DETERMINE THE SERIAL NUMBER					MANDATORY	NOT APPLICABLE
24-AUG-2000		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2000-257 R02 PART 2	NO. 2 ENGINE - REPLACE ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431 THE OIL FILTER DIFFERENTIAL PRESSURE SWITCH UNIT					MANDATORY	NOT APPLICABLE
24-AUG-2000		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2000-348	NO. 2 ENGINE - ENGINE - LP COMPRESSOR - FAN DISC CRACKS (ATA 72)					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-348/2
02-OCT-2000		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2000-348 R02	NO. 2 ENGINE - ENGINE - LP COMPRESSOR - FAN DISC CRACKS (ATA 72)					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-348/3
24-NOV-2000		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2000-348 R03	NO. 2 ENGINE - ENGINE - LP COMPRESSOR - FAN DISC CRACKS (ATA 72)					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-348/4
		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2000-348 R04	NO. 2 ENGINE - ENGINE - LP COMPRESSOR - FAN DISC CRACKS (ATA 72)					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-348/5
		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2000-348 R05	NO. 2 ENGINE - ENGINE - LP COMPRESSOR - FAN DISC CRACKS (ATA 72)					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-348/6
		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
LBA D-2000-348 R06	NO. 2 ENGINE - ENGINE - LP COMPRESSOR - FAN DISC CRACKS (ATA 72)						NOT APPLICABLE
31-MAR-2005		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2000-348 REV 6 PART 4	NO. 2 ENGINE - VISUAL OR ULTRASONIC INSP FAN DISC, P/N BRR20791						NOT APPLICABLE
		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2000-348 REV 6 PART 5	NO. 2 ENGINE - VISUAL AND ULTRASONIC INSP OF FAN DISC, ALL P/NS						NOT APPLICABLE
		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2007-352	NO. 2 ENGINE - REVERSE WIRED INDEPENDENT OVERSPEED PROTECTION COILS IN BR700 SERIES ENGINES					MANDATORY	NOT APPLICABLE
21-DEC-2007		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2008-222	NO. 2 ENGINE - BR700-710 - RE-USE OF POTENTIALLY DAMAGED ENGINE MATERIAL					MANDATORY	NOT APPLICABLE - SUPERSEDED BY D-2008-222R1
23-JUN-2008		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2008-222 R01	NO. 2 ENGINE - BR700-710 - RE-USE OF POTENTIALLY DAMAGED ENGINE MATERIAL					MANDATORY	NOT APPLICABLE
25-SEP-2008		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2010-126	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE DISCS STAGE 1 AND 2 ASSEMBLY LIFE LIMITS - MODIFICATION					MANDATORY	COMPLIED WITH - AT MANUFACTURE
03-MAY-2010		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2010-130	NO. 2 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT					MANDATORY	COMPLIED WITH - AT MANUFACTURE
03-MAY-2010		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2012-340	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING					MANDATORY	COMPLIED WITH - AT MANUFACTURE
		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
LBA D-2012-346	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR DISC STAGE 1 AND STAGE 2 LIFE LIMITATION - IMPLEMENTATION					MANDATORY	NOT APPLICABLE - DUE TO HPT S/N INSTALLED
		MOS		24-MAY-2014			
		HRS/MSC -					
		ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
LBA D-2013-366	NO. 2 ENGINE - ENGINE - HIGH PRESSURE COMPRESSOR AND COMBUSTION FAIRINGS - INSPECTION / REPLACEMENT	MOS HRS/MSC - ENC		24-MAY-2014		MANDATORY	NOT APPLICABLE - BY ENGINE SERIAL NUMBER



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 1 - SB - 22301/DEL114							
ASB R03	BR700-72-A101523	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUT-OFF PAWL CARRIER PIVOT PINS MADE FROM A DIFFERENT MATERIAL WITH IMPROVED CORROSION PROTECTION PROPERTIES, ALERT SERVICE BULLETIN				ALERT	NOT APPLICABLE
	10-DEC-2015		MOS HRS/MSC - ENC				
ASB	BR700-72-A900297	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR FAIRINGS - INSPECTION OF THE UPPER LEFT HP COMPRESSOR FAIRING FOR POTENTIAL PROFILE NON-CONFORMANCE AND REPLACEMENT OF NON-CONFORMING UPPER LEFT HP COMPRESSOR FAIRING - NON-MODIFICATION, ALERT SERVICE BULLETIN				ALERT	NOT APPLICABLE
	02-SEP-2013		MOS HRS/MSC - ENC				
ASB	BR700-72-A900298	NO. 1 ENGINE - ENGINE - ENGINE COMBUSTION FAIRINGS - REPLACEMENT OF NON-CONFORMING UPPER LEFT, UPPER RIGHT AND LOWER RIGHT COMBUSTION SECTION FAIRINGS - NON-MODIFICATION, ALERT SERVICE BULLETIN				ALERT	NOT APPLICABLE
			MOS HRS/MSC - ENC				
ASB R01	BR700-72-A900298	NO. 1 ENGINE - ENGINE COMBUSTION FAIRINGS - REPLACEMENT OF NON-CONFORMING UPPER LEFT, UPPER RIGHT AND LOWER RIGHT COMBUSTION SECTION FAIRINGS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN				OPTIONAL	NOT APPLICABLE
	21-MAY-2014		MOS HRS/MSC - ENC				
ASB	BR700-72-A900497	NO. 1 ENGINE - HPT ROTOR DISCS - DECREASE OF TIME LIMITS MANUAL MAXIMUM APPROVED LIVES OF STG 1 & 2 DISCS, ALERT SERVICE BULLETIN				ALERT	COMPLIED WITH - AT MANUFACTURE
	12-FEB-2010		MOS HRS/MSC - ENC	23-SEP-2013 0 0			
ASB R01	BR700-72-A900504	NO. 1 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT, ALERT SERVICE BULLETIN				ALERT	COMPLIED WITH - AT MANUFACTURE
			MOS HRS/MSC - ENC	23-SEP-2013 0 0			
ASB	BR700-72-A900508	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 AND 2 DISCS DUE TO POTENTIAL STEEL INCLUSION - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN					COMPLIED WITH - AT MANUFACTURE
	26-JUL-2012		MOS HRS/MSC - ENC	23-SEP-2013 0 0			
ASB R01	BR700-72-A900508	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 AND 2 DISCS DUE TO POTENTIAL STEEL INCLUSION - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN					NOT APPLICABLE
			MOS HRS/MSC - ENC				



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASB R03	BR700-72-A900509 NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN	MOS HRS/MSC - ENC		23-SEP-2013 0 0			NOT APPLICABLE - AT MANUFACTURE
ASB R02	BR700-72-A900556 NO. 1 ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR SPECIAL FLIGHT PROFILE - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN	MOS HRS/MSC - ENC			16-DEC-2014		NOT APPLICABLE
ASB	BR700-72-A900584 NO. 1 ENGINE - GENERAL - ENGINE INSTALLATION RESTRICTION AND CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN	MOS HRS/MSC - ENC			31-JAN-2017	(EFF)	- SUPERSEDED
ASB R01	BR700-72-A900584 NO. 1 ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN	MOS HRS/MSC - ENC		06-DEC-2017 683.8 291	05-OCT-2017		COMPLIED WITH - BAS - FLL - COMPLIED WITH PART A.
ASB R01 PART A	BR700-72-A900584 NO. 1 ENGINE - ACCOMPLISH GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN INSTRUCTIONS TO DETERMINE THE EFFECTIVE ENGINE POPULATION	DAYS HRS/MSC - ENC		06-DEC-2017 683.8 291	05-OCT-2017		COMPLIED WITH - BAS - FLL - COMPLIED WITH PART A.
ASB R01 PART B	BR700-72-A900584 NO. 1 ENGINE - ACCOMPLISH GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN INSTRUCTIONS ON HOW TO CALCULATE THE LIVES FOR AFFECTED PARTS ON ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT HAVING BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 STANDARD INCORPORATED	MOS HRS/MSC - ENC			05-OCT-2017	(EFF)	- SUPERSEDED
ASB R02	BR700-72-A900584 NO. 1 ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SB, ALERT SERVICE BULLETIN	MOS HRS/MSC - ENC		23-MAR-2018 746.25 311	22-NOV-2017		COMPLIED WITH - PTS A & B - PENALTY CALCULATION OF 139.8 (140) CYCLES FOR NEW LP DISC CSN = 451 CYC



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASB BR700-72-A900584 R02 PART A	NO. 1 ENGINE - ACCOMPLISH GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SB, ALERT SERVICE BULLETIN INSTRUCTIONS TO DETERMINE THE EFFECTIVE ENGINE POPULATION						COMPLIED WITH - PCW REV 1 PART A DEC 2017 ON BOMBARDIER W.O.206054.
22-NOV-2017		DAYS		10-JAN-2018			
		HRS/MSC	-	707.58			
		ENC		297			
ASB BR700-72-A900584 R02 PART B	NO. 1 ENGINE - ACCOMPLISH GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SB, ALERT SERVICE BULLETIN INSTRUCTIONS ON HOW TO CALCULATE THE LIVES FOR AFFECTED PARTS ON ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT HAVING BOMBARDIER SB700-34-5021 OR SB700-34-6021 STANDARD INCORPORATED						COMPLIED WITH - PTS A & B - PENALTY CALCULATION OF 139.8 (140) CYCLES FOR NEW LP DISC CSN = 451 CYC
22-NOV-2017		MOS		23-MAR-2018			
		HRS/MSC	-	746.25			
		ENC		311			
ASB BR700-72-A900659	NO. 1 ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN						NOT APPLICABLE
22-JUL-2019		MOS					
		HRS/MSC	-				
		ENC					
ASB BR700-72-A900659 PART A	NO. 1 ENGINE - ACCOMPLISH HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN REMOVAL OF THE ENGINE FOR INCORPORATION OF PART B OF THIS NON-MODIFICATION SERVICE BULLETIN						NOT APPLICABLE
22-JUL-2019		MOS					
		HRS/MSC	-				
		ENC					
ASB BR700-72-A900659 PART B	NO. 1 ENGINE - ACCOMPLISH HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN REPLACEMENT OF HIGH PRESSURE (HP) TURBINE STAGE 1 DISCS						NOT APPLICABLE
22-JUL-2019		MOS					
		HRS/MSC	-				
		ENC					
ASB BR700-72-A900659 R01	NO. 1 ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN					ALERT	NOT APPLICABLE
05-NOV-2019		MOS					
		HRS/MSC	-				
		ENC					
ASB BR700-72-A900659 R01 PART A	NO. 1 ENGINE - ACCOMPLISH HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN REMOVAL OF THE ENGINE FOR INCORPORATION OF PART B OF THIS NON-MODIFICATION SERVICE BULLETIN						NOT APPLICABLE
05-NOV-2019		MOS		27-AUG-2021			
		HRS/MSC	-	1012.88			
		ENC		430			
ASB BR700-72-A900659 R01 PART B	NO. 1 ENGINE - ACCOMPLISH HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN REPLACEMENT OF HIGH PRESSURE (HP) TURBINE STAGE 1 DISCS						NOT APPLICABLE
05-NOV-2019		MOS		27-AUG-2021			
		HRS/MSC	-	1012.88			
		ENC		430			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASB R02	BR700-73-A101977 NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW EEC FIREBOX ASSEMBLY WITH A REVISED PAINT SYSTEM, ALERT SERVICE BULLETIN	MOS				ALERT	- SUPERSEDED
	27-MAR-2017	HRS/MSC -					
		ENC					
ASB R03	BR700-73-A101977 NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW EEC FIREBOX ASSEMBLY WITH A REVISED PAINT SYSTEM, ALERT SERVICE BULLETIN	MOS		24-MAY-2019			COMPLIED WITH
	10-JUL-2017	HRS/MSC -		879.42			
		ENC		365			
ASB	BR700-73-A900083 NO. 1 ENGINE - ENGINE FUEL AND CONTROL ENGINE ELECTRONIC CONTROLLER (EEC) - REPLACEMENT OF NON-CONFORMING PARTS OF THE EEC FIREBOX ASSEMBLY - NON-MODIFICATION, ALERT SERVICE BULLETIN	MOS				ALERT	NOT APPLICABLE
	09-MAR-2015	HRS/MSC -					
		ENC					
ASB R01	BR700-73-A900083 NO. 1 ENGINE - ENGINE FUEL AND CONTROL ENGINE ELECTRONIC CONTROLLER (EEC) - REPLACEMENT OF NON-CONFORMING PARTS OF THE EEC FIREBOX ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN	MOS				ALERT	NOT APPLICABLE
	22-MAR-2017	HRS/MSC -					
		ENC					
ASB R02	BR700-73-A900083 NO. 1 ENGINE - ENGINE FUEL AND CONTROL ENGINE ELECTRONIC CONTROLLER (EEC) - REPLACEMENT OF NON-CONFORMING PARTS OF THE EEC FIREBOX ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN	MOS				ALERT	NOT APPLICABLE
	14-DEC-2018	HRS/MSC -					
		ENC					
ASB	BR700-73-A900451 NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL METERING UNIT (FMU) - COMBINED OVERSPEED SHUTOFF SOLENOID (COSS) SCREENING FOR REVERSE WIRED INDEPENDENT OVERSPEED PROTECTION (IOP) COILS, ALERT SERVICE BULLETIN	MOS		23-SEP-2013		ALERT	NOT APPLICABLE
		HRS/MSC -		0			
		ENC		0			
SB	BR700-24-100166 R01 NO. 1 ENGINE - ELECTRICAL POWER - VARIABLE FREQUENCY GENERATOR OIL TRANSFER TUBES AND FITTINGS - REVISED OIL TRANSFER TUBE SELF LOCKING NUT TIGHTENING TORQUE, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
	01-DEC-2000	HRS/MSC -					
		ENC					
SB	BR700-24-100378 NO. 1 ENGINE - ELECTRICAL POWER - ENGINE GENERATOR OIL COOLER - DELETION OF FIRE PROTECTION COVER PLATES, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
	26-APR-1999	HRS/MSC -					
		ENC					
SB	BR700-24-100384 NO. 1 ENGINE - POWER - ENGINE GENERATOR OIL TRANSFER TUBES AND FITTINGS -INTRODUCTION OF MODIFIED OIL COOLER TO VFG TUBE ASSEMBLY, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
	21-MAY-1999	HRS/MSC -					
		ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-24-100384 R01	NO. 1 ENGINE - ELECTRICAL POWER - ENGINE GENERATOR SURFACE AIR COOLED OIL COOLER (SACOC) TRANSFER TUBES AND FITTINGS - INTRODUCTION OF A MODIFIED SACOC TO VARIABLE FREQUENCY GENERATOR (VFG) OIL TUBE, SERVICE BULLETIN	MOS				OPTIONAL	NOT APPLICABLE
08-JUL-2014		HRS/MSC -					
		ENC					
SB BR700-24-100472	NO. 1 ENGINE - POWER - ENGINE GENERATOR OIL COOLER - DELETION OF THE THERMOSTATIC CONTROL VALVE OF THE SURFACE AIR COOLED OIL COOLER AND ASSOCIATED DRESSINGS CHANGES, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
24-JAN-2002		HRS/MSC -					
		ENC					
SB BR700-24-100961 R01	NO. 1 ENGINE - ELECTRICAL POWER - ENGINE GENERATOR OIL COOLER - INTRODUCTION OF A NEW BUILD INSTRUCTION FOR THE FIRE SHIELDS OF THE OIL COOLER, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-APR-2001		HRS/MSC -					
		ENC					
SB BR700-24-101483	NO. 1 ENGINE - ELECTRICAL POWER - ENGINE GENERATOR OIL COOLER - INTRODUCTION OF NEW SURFACE AIR COOLED OIL COOLERS (SACOC), SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-FEB-2005		HRS/MSC -					
		ENC					
SB BR700-26-100396	NO. 1 ENGINE - FIRE PROTECTION - CORE ENGINE FIRE DETECTION SENSORS - INTRODUCTION OF REVISED CORE FIRE WIRE MOUNTING BRACKETS, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-APR-1999		HRS/MSC -					
		ENC					
SB BR700-26-100434 R02	NO. 1 ENGINE - FIRE - PROTECTION - CORE ENGINE NOZZLE, TUBES AND FITTINGS - INTRODUCTION OF MODIFIED ZONE 2 TUBES AND ADDITIONAL CLIPPING, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
31-JUL-2002		HRS/MSC -					
		ENC					
SB BR700-26-100466	NO. 1 ENGINE - FIRE PROTECTION - ELECTRICAL HARNESSSES - INTRODUCTION OF CLIPPING POSITION CHANGES TO SUIT MODIFIED FIRE EXTINGUISHER SYSTEM, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
03-SEP-1998		HRS/MSC -					
		ENC					
SB BR700-36-100142 R01	NO. 1 ENGINE - PNEUMATIC - CABIN AIR DUCTS - INTRODUCTION OF A REVISED HP5 CABIN AIR DUCT ASSEMBLY, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
25-JAN-2001		HRS/MSC -					
		ENC					
SB BR700-71-100058	NO. 1 ENGINE - POWER PLANT - THRUST REVERSER UNIT (TRU) AND GENERAL SERVICES HARNESS ATTACHMENT FITTINGS - INTRODUCTION OF REVISED CLIPPING POINTS, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
29-APR-1998		HRS/MSC -					
		ENC					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-71-100160	NO. 1 ENGINE - POWER PLANT - LEFT ENGINE HARNESS ATTACH FITTINGS - INTRODUCTION OF RE-ROUTED HARNESSES AND REPLACEMENT OF RELATED CLIPPING POINTS, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
31-JAN-1998		HRS/MSC - ENC					
SB BR700-71-100177	NO. 1 ENGINE - POWER PLANT - ELECTRICAL HARNESSES - INTRODUCTION OF ENGINE BUILD UP (EBU) EXTENSION CLIPS, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
20-SEP-1997		HRS/MSC - ENC					
SB BR700-71-100179	NO. 1 ENGINE - POWER PLANT - LEFT ENGINE HARNESS ATTACH FITTINGS - INTRODUCTION OF RE-ROUTED TRU HARNESS AND RELATED CLIPPING POINTS, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
19-JUN-1998		HRS/MSC - ENC					
SB BR700-71-100211	NO. 1 ENGINE - POWER PLANT - DRAINS TANK EJECTOR - INTRODUCTION OF REVISED MATERIAL, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		HRS/MSC - ENC					
SB BR700-71-100242 R01	NO. 1 ENGINE - POWER PLANT - MINOR PODDING MODIFICATIONS, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
22-OCT-1999		HRS/MSC - ENC					
SB BR700-71-100259	NO. 1 ENGINE - POWER PLANT - ADDITIONAL ACOC DELETION DRESSING MODIFICATIONS, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
24-JAN-1998		HRS/MSC - ENC					
SB BR700-71-100298 R02	NO. 1 ENGINE - POWER PLANT - ADDITIONAL PRODUCTION ACOC DELETION DRESSING MODIFICATIONS, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		HRS/MSC - ENC					
SB BR700-71-100307	NO. 1 ENGINE - POWER PLANT - EEC HARNESS - MINOR CONFIGURATION AMENDMENTS TO CLIPPING POINTS CP10733 AND CP10734, SERVICE BULLETIN	MOS		19-SEP-2013		INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
26-APR-1999		HRS/MSC - ENC					
SB BR700-71-100340	NO. 1 ENGINE - POWER PLANT - GEARBOX MOUNTED EBU BRACKETS - TRANSFER OF OWNERSHIP, SERVICE BULLETIN	MOS		19-SEP-2013		INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		HRS/MSC - ENC					
SB BR700-71-100341	NO. 1 ENGINE - POWER PLANT - VARIOUS - ADDITIONAL HARNESS CLIPPING MODIFICATIONS (NEUTRAL AND RIGHT HAND), SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-MAR-1998		HRS/MSC - ENC					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-71-100351	NO. 1 ENGINE - POWER PLANT - GEARBOX MOUNTED EBU BRACKETS - INTRODUCTION OF SHORTER BOLTS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-MAR-1998		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-71-100426 R01	NO. 1 ENGINE - POWER PLANT - CORE/EXTERNAL DRAINS TUBES AND FITTINGS - INTRODUCTION OF REVISED CLEARANCES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-OCT-1999		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-71-100427 R01	NO. 1 ENGINE - POWER PLANT - EEC LANE A HARNESS 1A - RE-ORIENTATION OF HARNESS CONNECTOR BACKSHELLS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
26-APR-1999		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-71-100428 R01	NO. 1 ENGINE - POWER PLANT - EEC LANE B HARNESS 1D - RE-ORIENTATION OF HARNESS CONNECTOR BACKSHELLS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
26-APR-1999		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-71-100429 R01	NO. 1 ENGINE - POWER PLANT - EEC LANE B HARNESS 1E - RE-ORIENTATION OF HARNESS CONNECTOR BACKSHELLS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
26-APR-1999		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-71-100476	NO. 1 ENGINE - POWER PLANT - ELECTRICAL HARNESSES - REROUTING OF HARNESS LOOMS TO CLEAR BYPASS DUCT ACCESS PANEL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
17-SEP-1999		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-71-100488	NO. 1 ENGINE - POWER PLANT - EEC LANES A AND B HARNESSES - INTRODUCTION OF REVISED CLIPPING POINTS CP10022 AND CP10029, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-APR-1999		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-71-100500	NO. 1 ENGINE - POWER PLANT - ELECTRICAL HARNESSES - INTRODUCTION OF MINOR ASSOCIATED DRESSING CHANGES FOR THE EEC TROUGH DELETION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
25-SEP-1998		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-71-100530	NO. 1 ENGINE - POWER PLANT - EXTERNAL DRAIN TUBES AND FITTINGS - INTRODUCTION OF A CHANGE OF OWNERSHIP (INSTALLATION RESPONSIBILITY) FOR THE WET DRAINS BRACKETS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
26-APR-1999		MOS HRS/MSC - ENC		19-SEP-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-71-100585 R01	NO. 1 ENGINE - POWER PLANT - EEC LANE A HARNESS 1C - INTRODUCTION OF MODIFIED CLIPPING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-71-100595 R01	NO. 1 ENGINE - POWER PLANT - GEARBOX MOUNTED EBU BRACKETS - INTRODUCTION OF REVISED LENGTH BOLTS TO ACCOMMODATE NEW STANDARD OF ACCESSORY GEARBOX MAIN HOUSING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-JUN-2005		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-71-100602	NO. 1 ENGINE - POWER PLANT - FRONT SUSPENSION-ENGINE MOUNTED - INTRODUCTION OF THRUST TRUNNION FLANGE BOLTS WITH A THINNER HEAD, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
03-AUG-2016		MOS HRS/MSC - ENC					
SB BR700-71-100680 R02	NO. 1 ENGINE - POWER PLANT - GEARBOX MOUNTED ENGINE BUILD UNIT (EBU) BRACKETS - INTRODUCTION OF REVISED FIRERAIL SUPPORT BRACKET, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
15-NOV-2000		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-71-100892	NO. 1 ENGINE - POWER PLANT - LEFT AND RIGHT ENGINE EEC LANE A HARNESS 1C AND LANE B HARNESS 1F - INTRODUCTION OF ELECTRONIC ENGINE CONTROLLER (EEC) HARNESSSES WITH A RESISTOR IN THE ELECTRICAL SUPPLY LINE TO THE STARTER AIR VALVE (SAV) SOLENOID, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
13-OCT-1999		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-71-101465	NO. 1 ENGINE - POWER PLANT - GENERAL - INTRODUCTION OF A NEW EXTENSION CLIP WITH A SIMPLIFIED DESIGN, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
27-JAN-2006		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-71-101581	NO. 1 ENGINE - INTRODUCTION OF AN OIL DRAIN TUBE SUPPORT BRACKET WITH A SLOTTED HOLE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
13-SEP-2007		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-71-101603	NO. 1 ENGINE - POWER PLANT - ENGINE ELECTRONIC CONTROLLER (EEC) LANE A HARNESS 1A - CLIP POSITION CHANGES FOR THE OIL LEVEL SENSOR CABLE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-FEB-2008		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-71-101830 R01	NO. 1 ENGINE - POWER PLANT - LEFT AND RIGHT FIXED COWL - INTRODUCTION OF A DRAINAGE HOLE WITHIN THE FRONT MOUNT ACCESS PANEL AND THE FIXED COWL ASSEMBLIES TO PREVENT CORROSION OF THE ENGINE FRONT MOUNT ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
06-SEP-2013		MOS HRS/MSC - ENC		23-APR-2014 6.4			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-71-900675	NO. 1 ENGINE - POWER PLANT - GENERAL - ENGINE CONVERSION FROM A FLIGHT-TEST STANDARD ENGINE TO A PRODUCTION STANDARD ENGINE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
30-JAN-2020		MOS HRS/MSC - ENC					
SB BR700-72-100025 R02	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF HPC FRONT SPLIT CASING WITH INCREASED CAST BOSS DIAMETERS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100044 R03	NO. 1 ENGINE - ENGINE - HP COMPRESSOR (HPC) - INTRODUCTION OF VARIABLE STATOR VANES SOLID TIE RODS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-JAN-2012		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100109	NO. 1 ENGINE - ENGINE - HP COMPRESSOR (HPC) - INTRODUCTION OF VARIABLE STATOR VANES SOLID TIE RODS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-AUG-1997		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100110 R02	NO. 1 ENGINE - ENGINE - HP TURBINE - INTRODUCTION OF SILVER PLATING TREATMENT TO THREAD AND FLANK OF INTRASCOPE HOUSING BLANKING PLUG, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
06-JUL-1998		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100138	NO. 1 ENGINE - ENGINE - LPC STATOR VANES - INTRODUCTION OF NEW LP COMPRESSOR STATOR VANE ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-OCT-1997		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100149	NO. 1 ENGINE - ENGINE - DRESSING AND NON DRESSING - MINOR ALTERATIONS, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
05-JUN-1998		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100150	NO. 1 ENGINE - ENGINE - FAIRING, INTAKE ROTATING - LP COMPRESSOR - INTRODUCTION OF A LIGHTWEIGHT LP COMPRESSOR NOSECONE FAIRING ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-SEP-1997		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100152 R01	NO. 1 ENGINE - ENGINE - ENGINE MOUNTING SUPPORT - INTRODUCTION OF A NEW REAR MOUNT RING ASSEMBLY WITH REDUCED WEIGHT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-NOV-1997		MOS HRS/MSC - ENC		19-SEP-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100157	NO. 1 ENGINE - ENGINE - LP COMPRESSOR BLADES - INTRODUCTION OF LIGHTWEIGHT LP COMPRESSOR DISK SEALING PLATE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-SEP-1997		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100158 R01	NO. 1 ENGINE - ENGINE - VANES, STATOR, EXIT GUIDE - LP COMPRESSOR - INTRODUCTION OF CAST ALUMINUM OUTLET GUIDE VANE ASSEMBLY WITH POTTED OUTER END AND DAMPED INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
14-SEP-2000		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100159 R01	NO. 1 ENGINE - ENGINE - HP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED HP 1 NOZZLE GUIDE VANES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-JUL-1998		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100162	NO. 1 ENGINE - ENGINE - DISC, ROTOR - LP COMPRESSOR - INTRODUCTION OF A REDUCED WEIGHT ROTOR DISC WITH RE-PROFILED DOVETAIL SLOT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-OCT-1999		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100164 R01	NO. 1 ENGINE - ENGINE - CASE AND FITTINGS - COMPRESSOR INTERMEDIATE (LP TO IP/HP) - INTRODUCTION OF ENGINE VIBRATION MONITOR TRANSDUCER MOUNTING PLATE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100172 R02	NO. 1 ENGINE - ENGINE - HPC REAR INNER CASE - INTRODUCTION OF A NEW ABRADABLE LINING MATERIAL ON THE ROTOR PATH LINERS OF HPC STAGE 5, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-AUG-2003		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100178	NO. 1 ENGINE - ENGINE - ATTACHING PARTS AND FITTINGS - BYPASS DUCT MODULE - REVISED ENGINE BUILD-UP (EBU) FLANGE BRACKETS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-JUL-1998		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100186	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF VARIOUS IMPROVEMENTS TO THE GEARBOX ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
05-MAR-1998		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100194 R01	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF REDUCED STAGE 4 TO 10 PLATFORM GAPS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
16-JUL-1998		MOS HRS/MSC - ENC		19-SEP-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100195	NO. 1 ENGINE - ENGINE - COMBUSTION AND HP TURBINE - FIRE DETECTOR AND OVERHEAT PROBE PROTECTOR TUBES - REVISED LOCATION FEATURE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
31-MAY-1997		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100200 R02	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - FRONT BEARING AND SUPPORT - INTRODUCTION OF AN ALTERNATIVE NO. 3 BEARING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100202 R01	NO. 1 ENGINE - ENGINE - EXTERNALS - MINOR ENGINEERING MODIFICATIONS, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
21-JUN-2000		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100205	NO. 1 ENGINE - ENGINE - HP COMPRESSOR (HPC) - INTRODUCTION OF STAGE 7/8 HEATSHIELD WITH REDUCED CIRCUMFERENTIAL GAP, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
17-MAY-1997		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100207 R02	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF A TUBED VORTEX REDUCER AND A MODIFIED STAGE 7 TO 10 ROTOR ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100207 R03	NO. 1 ENGINE - HP COMPRESSOR - INTRODUCTION OF A TUBED VORTEX REDUCER AND A MODIFIED STAGE 7 TO 10 ROTOR ASSEMBLY, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
17-SEP-2015		MOS HRS/MSC - ENC					
SB BR700-72-100226	NO. 1 ENGINE - ENGINE - REPLACEMENT, DELETION OR INTRODUCTION OF NEW INSTRUCTIONS AND ARRANGEMENTS TO AMEND THE DIS10005., SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100229	NO. 1 ENGINE - ENGINE - SHAFT, ROTOR - LP TURBINE - INTRODUCTION OF LP TURBINE SHAFT IN SUPER S/CMV MATERIAL WITH REPROFILED INTERNAL BORE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-APR-1998		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100233	NO. 1 ENGINE - ENGINE - RING, BLADE RETAINING - LP COMPRESSOR - INTRODUCTION OF A LIGHTWIGHT RETAINING RING ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-SEP-1997		MOS HRS/MSC - ENC		19-SEP-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100241	NO. 1 ENGINE - ENGINE - BYPASS DUCT - INTRODUCTION OF INTRASCOPE BLANK EXTRACTION FEATURE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
19-MAR-1998		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100263	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF A SLEEVE IN THE PRESSURE RELIEF VALVE BORE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-AUG-1997		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100263 R01	NO. 1 ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF A SLEEVE IN THE PRESSURE RELIEF VALVE (PRV) HOUSING BORE OF THE ACCESSORY GEARBOX MAIN HOUSING ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
19-JAN-2016		MOS HRS/MSC - ENC					
SB BR700-72-100265 R03	NO. 1 ENGINE - ENGINE - TURBINE AND REAR SUPPORT - INTRODUCTION OF REVISED FUEL SHUT OFF CABLE SETTING INSTRUCTION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100266	NO. 1 ENGINE - ENGINE - TURBINE AND REAR SUPPORT - INTRODUCTION OF REVISED LPT EXHAUST CASE FUEL SHUT OFF EXIT RADIUS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
06-JUN-1997		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100266 R01	NO. 1 ENGINE - TURBINE AND REAR SUPPORT - INTRODUCTION OF REVISED LOW PRESSURE (LP) TURBINE EXHAUST CASE FUEL SHUT-OFF EXIT RADIUS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
08-DEC-2014		MOS HRS/MSC - ENC					
SB BR700-72-100267	NO. 1 ENGINE - ENGINE - INTRODUCTION OF ADDITIONAL CLIPPING AMENDMENTS DUE TO PODDING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
06-APR-1998		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100268	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF SILVER COATED STAGE 1, 3 AND 5 INTRASCOPE PLUGS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
07-FEB-1998		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100280	NO. 1 ENGINE - ENGINE - EXHAUST CASE - INTRODUCTION OF WEIGHT REDUCED LP TURBINE OUTLET GUIDE VANE (OGV) AND DOUBLE ENDED UNIONS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS HRS/MSC - ENC		19-SEP-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100281	NO. 1 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED COMBUSTION CHAMBER INNER CASE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		MOS		19-SEP-2013			
		HRS/MSC -					
		ENC					
SB BR700-72-100284 R01	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF REDUCED WEIGHT HP COMPRESSOR REAR OUTER CASE AND REVISED INTRASCOPE HOUSINGS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
19-DEC-2000		MOS		19-SEP-2013			
		HRS/MSC -					
		ENC					
SB BR700-72-100290	NO. 1 ENGINE - ENGINE - BYPASS SERVICES FAIRING - MINOR CONFIGURATION AMENDMENTS, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
16-JUL-1998		MOS		19-SEP-2013			
		HRS/MSC -					
		ENC					
SB BR700-72-100291	NO. 1 ENGINE - ENGINE - VARIOUS - ADDITIONAL DRESSING MODIFICATIONS RELATING TO THE DELETION OF THE AIR COOLED OIL COOLER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
02-JUN-1998		MOS		19-SEP-2013			
		HRS/MSC -					
		ENC					
SB BR700-72-100296 R01	NO. 1 ENGINE - ENGINE - SUPPORT, BEARING FRONT - LOW PRESSURE (LP) COMPRESSOR/DRIVEN ASSEMBLY - INTERNAL GEARBOX DRIVE - INTRODUCTION OF REVISED NO.1 AND NO.2 BEARING SUPPORT HOUSINGS AND ASSOCIATED COMPONENTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-JAN-2009		MOS		19-SEP-2013			
		HRS/MSC -					
		ENC					
SB BR700-72-100299 R01	NO. 1 ENGINE - ENGINE - BYPASS DUCT, ELECTRICAL HARNESSES AND ELECTRONIC ENGINE CONTROLLER (EEC) - DELETION OF EEC TROUGH AND INTRODUCTION OF EEC FIRE BOX AND ASSOCIATED MODIFICATIONS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		19-SEP-2013			
		HRS/MSC -					
		ENC					
SB BR700-72-100301	NO. 1 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED STAGE 1 DISC, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		MOS		19-SEP-2013			
		HRS/MSC -					
		ENC					
SB BR700-72-100302 R01	NO. 1 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED STAGE 2 DISC, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		19-SEP-2013			
		HRS/MSC -					
		ENC					
SB BR700-72-100303	NO. 1 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED REAR HEATSHIELD ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-JAN-1999		MOS		19-SEP-2013			
		HRS/MSC -					
		ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100304	NO. 1 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED HP TURBINE CASE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-MAR-1998		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100311	NO. 1 ENGINE - ENGINE - CASE LP COMPRESSOR - INTRODUCTION OF LP COMPRESSOR CASE ASSEMBLY WITH INCREASED THICKNESS FAN TRACK LINER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
06-APR-1998		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100319	NO. 1 ENGINE - ENGINE - HP COMPRESSOR (HPC) - INTRODUCTION OF STAGE 6 BLADES WHICH INCORPORATE A FORGED PLATFORM RAMP, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
03-DEC-1998		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100320	NO. 1 ENGINE - ENGINE - LP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED LP 1 BLADE DAMPERS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
02-JUN-1998		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100322	NO. 1 ENGINE - ENGINE - MANIFOLD, IMPINGEMENT COOLING - HP TURBINE - ADDITIONAL LOAD SPREADING STRIPS ON THE FRONT AND REAR MOUNTING BRACKET SECURING FEATURES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
18-DEC-1998		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100333	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF STAGE 10 BLADES WITH INCREASED PLATFORM WIDTH, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100336	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF STAGE 9 BLADES WITH INCREASED PLATFORM WIDTH AND ROOT DEPTH, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-JUN-1998		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100337	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF STAGE 8 BLADES WITH INCREASED PLATFORM WIDTH AND ROOT DEPTH, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-MAR-1998		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100346	NO. 1 ENGINE - ENGINE -HIGH PRESSURE (HP) COMPRESSOR - INTRODUCTION OF VARIABLE VANE INNER SHROUD BUSHES WITH REVISED TOLERANCES ON INNER AND OUTER DIAMETERS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
02-JUN-1998		MOS HRS/MSC - ENC		19-SEP-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100347	NO. 1 ENGINE - ENGINE - EXHAUST CASE - INTRODUCTION OF AN LP TURBINE OUTLET GUIDE VANE (OGV) ASSEMBLY WITH MODIFIED STAGE 2 SHROUD RETENTION, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		HRS/MSC - ENC					
SB BR700-72-100353	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF ALUMINUM ALLOY UNISON RING CENTRALIZERS FOR WEIGHT REDUCTION, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		HRS/MSC - ENC					
SB BR700-72-100362	NO. 1 ENGINE - ENGINE - INTERMEDIATE CASE MODULE - INTRODUCTION OF A NEW LOW PRESSURE SHAFT SPEED PROBE WITHOUT FUSE WIRES, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-MAR-1999		HRS/MSC - ENC					
SB BR700-72-100373	NO. 1 ENGINE - ENGINE - COMBUSTION AND HP TURBINE - INTRODUCTION OF A REAR BEARING SUPPORT STRUCTURE (RBSS) BEARING BORE OFFSET, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-NOV-1998		HRS/MSC - ENC					
SB BR700-72-100380 R01	NO. 1 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - INTRODUCTION OF A WEIGHT REDUCED COMBUSTION CHAMBER, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-SEP-2005		HRS/MSC - ENC					
SB BR700-72-100381	NO. 1 ENGINE - ENGINE - EEC LANE A HARNESS 2A - INTRODUCTION OF A REVISED HARNESS LENGTH, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		HRS/MSC - ENC					
SB BR700-72-100382 R01	NO. 1 ENGINE - ENGINE - LP TURBINE - INTRODUCTION OF WEIGHT REDUCED LP TURBINE STAGE 1 SHROUD SEGMENTS AND WEIGHT REDUCED LP TURBINE CASE WITH IMPROVED SURFACE PROTECTION, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		HRS/MSC - ENC					
SB BR700-72-100383	NO. 1 ENGINE - ENGINE - HP TURBINE - INTRODUCTION OF WEIGHT-REDUCED HP TURBINE STAGE 2 NOZZLE GUIDE VANES WITH REVISED COOLING AIR FLOW CHARACTERISTICS, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
25-NOV-1998		HRS/MSC - ENC					
SB BR700-72-100387	NO. 1 ENGINE - ENGINE - HP COMPRESSOR MODULE - DELETION OF WASHERS ON FLANGE CB, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-JUN-1998		HRS/MSC - ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100393	NO. 1 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE ATTACHING PARTS AND FITTINGS - INTRODUCTION OF BRACKETS MADE OF INCO 718 MATERIAL, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		HRS/MSC - ENC					
SB BR700-72-100401	NO. 1 ENGINE - ENGINE - LP COMPRESSOR (FAN) MODULE - ATTACH PARTS AND FITTINGS - INTRODUCTION OF A REVISED LP COMPRESSOR ANTI-SCORE RING IN CORROSION RESISTANT STEEL, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-JUN-1998		HRS/MSC - ENC					
SB BR700-72-100405	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE AND ENGINE MOUNTING SUPPORT - MINOR AMENDMENTS TO BRING THE CONFIGURATION DATABASE IN LINE WITH THE ENGINES AS BUILT, SERVICE BULLETIN	MOS		19-SEP-2013		INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		HRS/MSC - ENC					
SB BR700-72-100408	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF A NEW VANE TIP GRINDING AND ROTOR PATH MACHINING INSTRUCTION, SERVICE BULLETIN	MOS		19-SEP-2013		INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		HRS/MSC - ENC					
SB BR700-72-100411	NO. 1 ENGINE - ENGINE - ATTACHING PARTS AND FITTINGS - INTRODUCTION OF WEIGHT REDUCED EBU BRACKETS, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-MAR-2000		HRS/MSC - ENC					
SB BR700-72-100419 R01	NO. 1 ENGINE - ENGINE - LP COMPRESSOR BLADES - INTRODUCTION OF FAN ANNULUS FILLERS WITH POSITIVE BUSH LOCATION AND REVISED SEALING STRIPS, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-DEC-2001		HRS/MSC - ENC					
SB BR700-72-100433 R02	NO. 1 ENGINE - ENGINE - CASE AND FITTINGS - COMPRESSOR INTERMEDIATE (LP TO IP/HP) - INTRODUCTION OF REVISED CASE WITH MODIFIED EARTHING BRACKETS, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
11-JAN-1999		HRS/MSC - ENC					
SB BR700-72-100461 R01	NO. 1 ENGINE - ENGINE - LP COMPRESSOR - INTRODUCTION OF LP COMPRESSOR BLADES WITH REVISED TRAILING EDGE, MOMENT LIMITS AND DEFINITION OF FREQUENCY LIMITS, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-DEC-2001		HRS/MSC - ENC					
SB BR700-72-100463	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF OIL-FILLING INSTRUCTION LABELS, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		HRS/MSC - ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100475 R02	NO. 1 ENGINE - ENGINE - HP COMPRESSOR MODULE - INTRODUCTION OF NEW VANES ON THE HPC STAGES 6 TO 9, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS		19-SEP-2013			
	03-APR-2003	HRS/MSC -					
		ENC					
SB BR700-72-100494	NO. 1 ENGINE - ENGINE - BYPASS DUCT - INTRODUCTION OF A PRESSURE RECOVERY DEVICE IN THE PRECOOLER FAN AIR FLOW LINE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS		19-SEP-2013			
	09-SEP-1998	HRS/MSC -					
		ENC					
SB BR700-72-100506	NO. 1 ENGINE - ENGINE - LP COMPRESSOR CASE - INTRODUCTION OF A REVISED STARTER EFFLUX SHIELD WITH EDGE PROTECTION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS		19-SEP-2013			
	25-JAN-2000	HRS/MSC -					
		ENC					
SB BR700-72-100544 R01	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF A MOUNT KIT WITH IMPROVED PROTECTION AND DELETION OF THE BREATHER COVER INSTRUMENTATION BOSS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS		19-SEP-2013			
	05-AUG-1999	HRS/MSC -					
		ENC					
SB BR700-72-100563	NO. 1 ENGINE - ENGINE - LP/HP TURBINE SUPPORT AND OUTER BEARINGS - INTRODUCTION OF STAGE 4 AIR TUBES AND REAR BEARING SUPPORT STRUCTURE WITH INCREASED CONTACT AREA, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS		19-SEP-2013			
		HRS/MSC -					
		ENC					
SB BR700-72-100563 R01	NO. 1 ENGINE - LP/HP TURBINE SUPPORT AND OUTER BEARINGS - INTRODUCTION OF STAGE 4 AIR TUBES AND REAR BEARING SUPPORT STRUCTURE (RBSS) WITH INCREASED CONTACT AREA, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
		HRS/MSC -					
		ENC					
SB BR700-72-100564 R01	NO. 1 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - REMOVAL OF INSULATION STRIPS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		19-SEP-2013			
	10-MAY-2001	HRS/MSC -					
		ENC					
SB BR700-72-100566 R02	NO. 1 ENGINE - ENGINE - HPC REAR INNER CASE - INTRODUCTION OF A NEW ABRADABLE LINING MATERIAL ON THE ROTOR PATH LINERS OF HPC STAGE 6, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		19-SEP-2013			
	22-AUG-2003	HRS/MSC -					
		ENC					
SB BR700-72-100600 R01	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF A NEW STANDARD OF MAIN HOUSING AND ASSOCIATED ASSEMBLY IMPROVEMENTS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS		19-SEP-2013			
	21-JUN-2005	HRS/MSC -					
		ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100621	NO. 1 ENGINE - ENGINE - HP COMPRESSOR VARIABLE INLET GUIDE VANE ACTUATING MECHANISM - INTRODUCTION OF REDUCED LENGTH VARIABLE STATOR VANE ACTUATOR (VSVA) BRACKET CONNECTING DOWELS, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		HRS/MSC - ENC					
SB BR700-72-100623	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF REDUCED WEIGHT HP COMPRESSOR STAGE 1 TO 6 ROTOR DISKS ASSEMBLY, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		HRS/MSC - ENC					
SB BR700-72-100635	NO. 1 ENGINE - ENGINE - HP COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) RINGS AND SEALS - INTRODUCTION OF A NEW VIGV INNER SHROUD, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-DEC-1999		HRS/MSC - ENC					
SB BR700-72-100643	NO. 1 ENGINE - ENGINE - INTERMEDIATE CASE MODULE ATTACHING PARTS AND FITTINGS - INTRODUCTION OF REVISED FASTENERS, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		HRS/MSC - ENC					
SB BR700-72-100671	NO. 1 ENGINE - ENGINE - HPT BLADES - INTRODUCTION OF HP TURBINE STAGE 2 BLADE DAMPERS WHICH ARE MANUFACTURED AS A PRECISION CASTING, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-OCT-2000		HRS/MSC - ENC					
SB BR700-72-100681 R01	NO. 1 ENGINE - ENGINE - LP COMPRESSOR INTAKE ROTATING FAIRING - INTRODUCTION OF REVISED NOSE CONE ASSEMBLY, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-OCT-2001		HRS/MSC - ENC					
SB BR700-72-100686	NO. 1 ENGINE - ENGINE - NL SPEED PROBE HARNESS AND ACCESSORIES - REDUCED NUMBER OF SPEED PROBE WASHERS, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-1999		HRS/MSC - ENC					
SB BR700-72-100704	NO. 1 ENGINE - ENGINE - COMBUSTION INNER CASE AND VANES - INTRODUCTION OF COMPRESSOR OUTLET GUIDE VANES (OGV)/DIFFUSER CASE WITH IMPROVED AIR FLOW CHARACTERISTICS, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-1999		HRS/MSC - ENC					
SB BR700-72-100712	NO. 1 ENGINE - ENGINE - HPC VIGV ACTUATING MECHANISM - INTRODUCTION OF NEW HP COMPRESSOR VSV SYSTEM DRIVE BRACKETS, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
16-DEC-1999		HRS/MSC - ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100720 R01	NO. 1 ENGINE - ENGINE - HP COMPRESSOR BLADES - INTRODUCTION OF REVISED STAGES 6 TO 10 BLADE PLATFORM GAPS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-MAY-2001		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100733	NO. 1 ENGINE - ENGINE - LPC FRONT AND REAR (NO. 1, 2 AND 3) BEARING AND SUPPORT - INTRODUCTION OF ALTERNATIVE SQUEEZE FILM PISTON RINGS., SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
16-DEC-1999		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100770 R01	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF SHOT PEENED GEARS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-AUG-2003		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100785	NO. 1 ENGINE - ENGINE - HP TURBINE - INTRODUCTION OF DECREASED COLD BUILD CLEARANCE ON STAGE 1 HP TURBINE AND DELETION OF DRY FILM LUBRICANT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-MAR-2000		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100805 R01	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF NEW PROCEDURE FOR TIP GRINDING OF HP COMPRESSOR VANES AND IN-SERVICE ROTOR BLADE NUMBERING PROCEDURE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100812	NO. 1 ENGINE - ENGINE - HPC VIGV ACTUATING MECHANISM - INTRODUCTION OF A VIGV UNISON RING WITH IMPROVED CORROSION RESISTANCE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-JAN-2000		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100813	NO. 1 ENGINE - ENGINE - HPC VIGV ACTUATING MECHANISM - INTRODUCTION OF A VSV STAGE 1 UNISON RING WITH IMPROVED CORROSION RESISTANCE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-MAR-2000		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100814	NO. 1 ENGINE - ENGINE - HPC VIGV ACTUATING MECHANISM - INTRODUCTION OF A VSV STAGE 2 UNISON RING WITH IMPROVED CORROSION RESISTANCE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-JAN-2000		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100815	NO. 1 ENGINE - ENGINE - HPC VIGV ACTUATING MECHANISM - INTRODUCTION OF A VSV STAGE 3 UNISON RING WITH IMPROVED CORROSION RESISTANCE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-MAR-2000		MOS HRS/MSC - ENC		19-SEP-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100818	NO. 1 ENGINE - ENGINE - LP COMPRESSOR ROTOR SHAFT - INTRODUCTION OF FAN SHAFT ASSEMBLY WITH REVISED MATERIAL PHONIC WHEEL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-OCT-2000		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100840	NO. 1 ENGINE - ENGINE - HP TURBINE ROTOR DISKS - INTRODUCTION OF A REVISED MANUFACTURING PROCESS FOR HPT STAGE 1 DISKS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100845 R02	NO. 1 ENGINE - ENGINE - NL SPEED PROBE HARNESS AND ACCESSORIES - INTRODUCTION OF A NEW HARNESS ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
16-MAY-2001		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100848	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF AN ACCESSORY GEARBOX WITH ALL GEARS SHOT PEENED ON THE EXTERNAL SURFACES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-JUN-2000		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100851 R02	NO. 1 ENGINE - ENGINE - LP COMPRESSOR (FAN) MODULE - INTRODUCTION OF A COMMON MASTER PART, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
15-FEB-2001		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100852 R02	NO. 1 ENGINE - ENGINE - LP COMPRESSOR CASE MODULE - INTRODUCTION OF A COMMON MASTER PART, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
19-DEC-2000		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100853 R01	NO. 1 ENGINE - ENGINE - LP TURBINE MODULE - INTRODUCTION OF A COMMON MASTER PART, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
09-NOV-2000		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100859	NO. 1 ENGINE - ENGINE - LPC REAR (NO.2) BEARING ASSEMBLY FRONT PANEL - INTRODUCTION OF REVISED MATERIAL SPEED PROBE SUPPORT BRACKET, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
16-DEC-1999		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100865	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF A NEW STANDARD OF INSERT IN THE HAND CRANK FLANGE OF THE BREATHER COVER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-DEC-1999		MOS HRS/MSC - ENC		19-SEP-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100867	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX - CHANGES TO THE CONTOUR OF THE GEARBOX MAIN HOUSING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-NOV-1999		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100879	NO. 1 ENGINE - ENGINE - LP/HP TURBINE STATOR RETAINERS/SEALS - INTRODUCTION OF ABRADABLE LININGS WITH INCREASED CORROSION RESISTANCE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
22-SEP-2000		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100879 R01	NO. 1 ENGINE - LP/HP TURBINE STATOR RETAINERS/SEALS - INTRODUCTION OF ABRADABLE LININGS WITH INCREASED CORROSION RESISTANCE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS HRS/MSC - ENC					
SB BR700-72-100899 R01	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF THINNER ADJUSTING SHIMS AT BEVEL GEAR LINE 1 AND 2, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-JUN-2003		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100900 R01	NO. 1 ENGINE - HP COMPRESSOR AND COMBUSTION FAIRINGS-INTRODUCTION OF NEW FAIRINGS WITH NEW ATTACHMENT FEATURES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC - ENC		23-SEP-2013 0 0			
SB BR700-72-100901	NO. 1 ENGINE - ENGINE - HPC ROTOR HYDRAULIC SEAL - INTRODUCTION OF AN HP COMPRESSOR HYDRAULIC SEAL ASSEMBLY WITH INCREASED CLEARANCE BETWEEN THE SEAL AND THE LP TURBINE SHAFT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-FEB-2001		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100902	NO. 1 ENGINE - ENGINE - LPC PHONIC WHEEL - INTRODUCTION OF A REAR INNER BEARING ASSEMBLY WITH INCREASED CLEARANCE BETWEEN THE BEARING INNER RACE AND THE LP TURBINE SHAFT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-OCT-2000		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100903	NO. 1 ENGINE - ENGINE - HP TURBINE ROTOR SHAFT AND (NO 4) BEARING - INTRODUCTION OF ABRADABLE LINING WITH INCREASED CORROSION RESISTANCE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
28-APR-2000		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-100913	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF ALTERNATIVE MOUNT WASHERS MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-APR-2000		MOS HRS/MSC - ENC		19-SEP-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100944 R03 18-JAN-2000	NO. 1 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE ATTACH PARTS AND FITTINGS - DRESSING CHANGES FOR THE NEW HP COMPRESSOR AND COMBUSTION FAIRINGS, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
SB BR700-72-100952 R01 30-JUL-2002	NO. 1 ENGINE - ENGINE - LP TURBINE FAIRINGS - INTRODUCTION OF LP TURBINE FAIRINGS WITH INCREASED WIDTH RELIEF SLOTS, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
SB BR700-72-100976 R03 13-SEP-2000	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX - INCREASED CLEARANCE BETWEEN THE GENERATOR MAGNETIC SEALS AND THEIR RELATED AIR BLOWN SEALS AND BETWEEN THE ACCESSORY GEARBOX GEAR LINE 6 AND THE HYDRAULIC PUMP SPLINE, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
SB BR700-72-100978 R01 12-JUL-2001	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF DECREASED COLD BUILD TIP CLEARANCES FOR THE HP COMPRESSOR STAGES 5, 6, 7 AND 9 STATOR VANES, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
SB BR700-72-100981 R01 20-JAN-2004	NO. 1 ENGINE - ENGINE - LP COMPRESSOR - CASE - INTRODUCTION OF REVISED FAN TRACK LINER AND ICE IMPACT PANEL ADHESIVE AND FILLER, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
SB BR700-72-100985 22-SEP-2000	NO. 1 ENGINE - ENGINE - HP COMPRESSOR BLADES - REMOVAL OF THE HP COMPRESSOR STAGES 1, 2 AND 3 ROTOR BLADE UNDERPLATFORM STRIP SEALS, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
SB BR700-72-101006 19-OCT-2001	NO. 1 ENGINE - ENGINE - COMBUSTION FAIRINGS - INTRODUCTION OF NEW FASTENERS FOR COMBUSTION CENTRE CORE FAIRINGS AND LP TURBINE DIAPHRAGMS, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
SB BR700-72-101007 12-JUL-2000	NO. 1 ENGINE - ENGINE - HPC FRONT (NO. 3) BEARING SUPPORT - INCREASED CLEARANCE BETWEEN THE NUMBER 2 BEARING HOUSING AND THE NUMBER 3 BEARING RETAINER, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
SB BR700-72-101019 22-MAR-2000	NO. 1 ENGINE - ENGINE - LPC BEARING SEALS - INTRODUCTION OF NEW INTERNAL GEARBOX FORWARD AIR SEAL PISTON RING SEAL MANUFACTURED BY A NEW SUPPLIER, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101020	NO. 1 ENGINE - ENGINE - LPC INTAKE ROTATING FAIRING - INTRODUCTION OF A NEW NOSE CONE FAIRING ASSEMBLY., SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
23-NOV-2001		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101032	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE ATTACH PARTS AND FITTINGS - INTRODUCTION OF A NEW MATERIAL FOR MOUNT BUSHES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
24-JAN-2000		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101037 R01	NO. 1 ENGINE - ENGINE - HPC REAR OUTER CASE - INTRODUCTION OF NEW HP COMPRESSOR STAGE 9 INTRASCOPE PLUG ASSEMBLIES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
04-SEP-2003		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101038	NO. 1 ENGINE - ENGINE - HPC REAR OUTER CASE - INTRODUCTION OF HP COMPRESSOR STAGE 5 INTRASCOPE PLUGS MADE FROM A DIFFERENT MATERIAL AND WITH A DECREASED THREAD DIAMETER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
12-FEB-2001		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101057 R01	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF CHANGES BECAUSE OF A SUPPLIER TRANSFER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
13-JUL-2001		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101060 R01	NO. 1 ENGINE - ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF A NEW ENGINE NAME PLATE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-SEP-2000		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101068	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF DECREASED COLD BUILD TIP CLEARANCES FOR HP COMPRESSOR ROTOR BLADES AND STATOR VANES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-FEB-2002		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101069	NO. 1 ENGINE - ENGINE - HPC VARIABLE INLET GUIDE VANE (VIGV) ACTUATING MECHANISM - INTRODUCTION OF NUT RETAINERS WITH IMPROVED FEATURES FOR EASIER ASSEMBLY OF THE UNISON RINGS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-JUN-2000		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101084 R01	NO. 1 ENGINE - ENGINE - LPC FRONT (NO. 1) BEARING AND SUPPORT - INTRODUCTION OF A NO. 1 BEARING WITH A NEW DIAMETRAL CLEARANCE AND A RADIUSED INNER SPLIT LINE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
26-NOV-2005		MOS HRS/MSC - ENC		19-SEP-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101088	NO. 1 ENGINE - ENGINE - LPC STATOR VANES - INTRODUCTION OF AN ENGINE SECTION STATOR (ESS) WITH A NEW FILLER MATERIAL FOR THE PLATFORM, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-FEB-2002		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101090 R01	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW IDENTIFICATION PLATE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUN-2003		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101091	NO. 1 ENGINE - ENGINE - HPT 1 NGV - INTRODUCTION OF HP TURBINE STAGE 1 NOZZLE GUIDE VANES WITH NEW FILM COOLING HOLE CONFIGURATION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-2000		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101100 R02	NO. 1 ENGINE - ENGINE - HPC ROTOR SHAFT - INTRODUCTION OF A NEW HP COMPRESSOR STUB SHAFT WITH AN IMPROVED BALANCING PROCEDURE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-SEP-2004		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101102	NO. 1 ENGINE - ENGINE - HPC ROTOR REAR DISKS - INTRODUCTION OF A NEW HP COMPRESSOR STAGE 7 TO 10 ROTOR ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
13-JUL-2001		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101103	NO. 1 ENGINE - ENGINE - HPC ROTOR FRONT DISKS - INTRODUCTION OF A NEW HP COMPRESSOR STAGE 1 TO 6 ROTOR ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-JAN-2002		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101107 R01	NO. 1 ENGINE - ENGINE - INTERMEDIATE CASE MODULE - DELETION OF JOINTING COMPOUND ON ENGINE SECTION STATOR (ESS) AND THE INTERNAL GEARBOX (IGB) MATING FACES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101114 R04	NO. 1 ENGINE - ENGINE - BYPASS DUCT - INTRODUCTION OF A BYPASS DUCT WITH NEW INSERTS FOR INSTALLATION OF A FUEL RETURN TO TANK VALVE AND FOR A REPOSITIONED LP FUEL SWITCH, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
14-NOV-2000		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101116	NO. 1 ENGINE - ENGINE - LPC REAR NO.2 BEARING ASSY FRONT PANEL - INTRODUCTION OF NEW O-RINGS WITH A DECREASED INTERNAL DIAMETER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
24-JAN-2001		MOS HRS/MSC - ENC		19-SEP-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101117	NO. 1 ENGINE - ENGINE - HPT BLADES - INTRODUCTION OF HP TURBINE STAGE 1 BLADES WITH A NEW FILM COOLING HOLE CONFIGURATION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-NOV-2001		MOS		19-SEP-2013			
		HRS/MSC -					
		ENC					
SB BR700-72-101117 R01	NO. 1 ENGINE - HIGH PRESSURE (HP) TURBINE BLADES - INTRODUCTION OF HP TURBINE STAGE 1 BLADES WITH A NEW FILM COOLING HOLE CONFIGURATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
26-SEP-2018		MOS					
		HRS/MSC -					
		ENC					
SB BR700-72-101128 R01	NO. 1 ENGINE - ENGINE - HPT ROTOR SHAFT AND NO. 4 BEARING - INTRODUCTION OF AN HP TURBINE NO. 4 STUB SHAFT WITH IDENTITY MARKINGS PERMITTED ONLY ON THE REAR FACE OF THE SHAFT, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
25-MAR-2008		MOS		19-SEP-2013			
		HRS/MSC -					
		ENC					
SB BR700-72-101139 R01	NO. 1 ENGINE - HPC ROTOR SHAFT-INTRODUCTION OF A NEW FITTING INSTRUCTION FOR THE HP COMPRESSOR STUB SHAFT TO ALIGN WITH THE HP COMPRESSOR ROTOR, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
18-DEC-2006		MOS		19-SEP-2013			
		HRS/MSC -					
		ENC					
SB BR700-72-101144	NO. 1 ENGINE - ENGINE - COMBUSTION INNER CASE AND VANES - INTRODUCTION OF A NEW COMBUSTION INNER FRONT CASING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
24-JUN-2003		MOS		19-SEP-2013			
		HRS/MSC -					
		ENC					
SB BR700-72-101150	NO. 1 ENGINE - ENGINE - NL SPEED PROBES - INTRODUCTION OF LP COMPRESSOR TRIM BALANCE AND SPEED PROBES WHICH ARE MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-DEC-2003		MOS		19-SEP-2013			
		HRS/MSC -					
		ENC					
SB BR700-72-101157	NO. 1 ENGINE - ENGINE - TURBINE EXHAUST SUPPORTS - INTRODUCTION OF NEW REAR MOUNT SUPPORT STRUTS WITH A DIFFERENT COATING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-MAR-2008		MOS		19-SEP-2013			
		HRS/MSC -					
		ENC					
SB BR700-72-101167	NO. 1 ENGINE - ENGINE - LPC ROTOR SHAFT - INTRODUCTION OF FAN SHAFT BOLTS WITH INCREASED HEAD THICKNESS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-AUG-2001		MOS		19-SEP-2013			
		HRS/MSC -					
		ENC					
SB BR700-72-101173	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP)/HIGH PRESSURE (HP) TURBINE STATOR RETAINERS/SEALS - INTRODUCTION OF A NEW REAR BEARING SUPPORT STRUCTURE (RBSS) VENT DUCT, REAR HEAT SHIELD AND LP TURBINE SEAL CARRIER WHICH ARE DECREASED IN WEIGHT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-MAR-2007		MOS		19-SEP-2013			
		HRS/MSC -					
		ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101174	NO. 1 ENGINE - ENGINE - COMBUSTION FAIRINGS - INTRODUCTION OF A LEFT HAND LOWER COMBUSTION FAIRING WITH A STRENGTHENED PRESSURE RELIEF DOOR, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-FEB-2003		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101175	NO. 1 ENGINE - ENGINE - LPC EXIT GUIDE STATOR VANES - INTRODUCTION OF A NEW PART NUMBER FOR THE ALUMINIUM OUTLET GUIDE VANE (OGV) ASSEMBLY WITH CHANGED CLASSIFICATION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
25-JAN-2002		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101177 R01	NO. 1 ENGINE - ENGINE - COMBUSTION OUTER CASE - INTRODUCTION OF A NEW COMBUSTION CHAMBER OUTER CASING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-AUG-2002		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101179 R01	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - CHANGES TO OIL DISTRIBUTORS, PLUGS, O-RINGS, INSERTS AND RETAINING RINGS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-MAY-2004		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101180	NO. 1 ENGINE - ENGINE - HPC VIGV AND STAGES 1-4 STATOR VANES - INTRODUCTION OF A NEW VARIABLE INLET GUIDE VANE (VIGV) ASSEMBLY WHICH IS DECREASED IN WEIGHT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-AUG-2002		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101181	NO. 1 ENGINE - ENGINE - HPC VIGV AND STAGES 1 - 4 STATOR VANES - INTRODUCTION OF A NEW STAGE 1 VANE ASSEMBLY WHICH IS DECREASED IN WEIGHT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-AUG-2002		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101190	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF NEW ACCESSORY GEARBOX LINE 1 AND LINE 2 BEVEL GEARS WHICH ARE MANUFACTURED BY A NEW SUPPLIER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-FEB-2001		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101193 R01	NO. 1 ENGINE - ENGINE - HIGH PRESSURE COMPRESSOR (HPC) FRONT CASE - INTRODUCTION OF A NEW HPC FRONT CASE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
19-JUN-2002		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101197	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - DELETION OF THE FIRE SHIELD ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-MAR-2001		MOS HRS/MSC - ENC		19-SEP-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101197 R01	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - DELETION OF THE FIRE SHIELD ASSEMBLY, SERVICE BULLETIN	MOS				OPTIONAL	NOT APPLICABLE
17-OCT-2014		HRS/MSC -					
		ENC					
SB BR700-72-101203 R01	NO. 1 ENGINE - ENGINE - HIGH PRESSURE COMPRESSOR (HPC) VARIABLE INLET GUIDE VANES (VIGV) ACTUATING MECHANISM - INTRODUCTION OF NEW HPC LEVERS WITH CHANGED TOLERANCES, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAR-2003		HRS/MSC -					
		ENC					
SB BR700-72-101204	NO. 1 ENGINE - ENGINE - COMBUSTION REAR INNER CASE - INTRODUCTION OF NEW FRONT AND REAR COMBUSTION INNER CASINGS WHICH ARE DECREASED IN WEIGHT, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-JUN-2002		HRS/MSC -					
		ENC					
SB BR700-72-101205	NO. 1 ENGINE - ENGINE - HPT1 NOZZLE GUIDE SEALS - INTRODUCTION OF A NEW PRESWIRL NOZZLE WITH A DECREASED COOLING AIR FLOW TO THE HP 1 TURBINE ROTOR DISC AND BLADES, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
14-MAR-2002		HRS/MSC -					
		ENC					
SB BR700-72-101216	NO. 1 ENGINE - ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF A NEW ENGINE NAME PLATE, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-FEB-2001		HRS/MSC -					
		ENC					
SB BR700-72-101218	NO. 1 ENGINE - ENGINE - LPT FUEL SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUT-OFF MECHANISM PAWLS WHICH HAVE A LARGER SURFACE CONTACT AREA WITH THE FUEL SHUT-OFF REFERENCE TUBE, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
12-APR-2002		HRS/MSC -					
		ENC					
SB BR700-72-101218 R01	NO. 1 ENGINE - LOW PRESSURE (LP) TURBINE FUEL SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUT-OFF MECHANISM PAWLS WHICH HAVE A LARGER SURFACE CONTACT AREA WITH THE FUEL SHUT-OFF REFERENCE TUBE, SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE
03-DEC-2020		HRS/MSC -					
		ENC					
SB BR700-72-101222	NO. 1 ENGINE - ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF NEW BUILD INSTRUCTIONS TO DECREASE HIGH PRESSURE (HP) VIBRATION LEVELS, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-JAN-2009		HRS/MSC -					
		ENC					
SB BR700-72-101223 R02	NO. 1 ENGINE - ENGINE - LPT FUEL SHUT-OFF CABLE AND FITTINGS - INTRODUCTION OF INCREASED CLEARANCES BETWEEN THE FUEL SHUT-OFF CABLE AND ADJACENT DRESSINGS, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
07-MAY-2004		HRS/MSC -					
		ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101234 R02	NO. 1 ENGINE - LOW PRESSURE/HIGH PRESSURE (LP/HP) TURBINE SUPPORT AND OUTER BEARINGS - INTRODUCTION OF REWORKED REAR BEARING SUPPORT STRUCTURES (RBSS) OF EARLIER STANDARDS, REWORKED HP AND LP TURBINE BEARING RETAINERS AND NEW STAGE 4 AIR TUBES, SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE
27-MAY-2014		HRS/MSC -					
		ENC					
SB BR700-72-101246	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR DISC - INTRODUCTION OF A NEW FAN DISC DESIGN FOR LIFE ENHANCEMENT, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		HRS/MSC -					
		ENC					
SB BR700-72-101246 R01	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSOR DISC - INTRODUCTION OF A NEW FAN DISC DESIGN FOR LIFE ENHANCEMENT, SERVICE BULLETIN	MOS				OPTIONAL	NOT APPLICABLE
28-OCT-2016		HRS/MSC -					
		ENC					
SB BR700-72-101252	NO. 1 ENGINE - ENGINE - COMBUSTION LINER - INTRODUCTION OF A NEW COMBUSTOR HEAT SHIELD, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-APR-2002		HRS/MSC -					
		ENC					
SB BR700-72-101254	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF CHANGES TO THE MANUFACTURING PROCEDURE FOR THE ACCESSORY GEARBOX LINE 1 AND LINE 2 BEVEL GEARS, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-JUL-2003		HRS/MSC -					
		ENC					
SB BR700-72-101258 R01	NO. 1 ENGINE - ENGINE - LP COMPRESSOR CASE - INTRODUCTION OF A LP COMPRESSOR CASE WHICH IS MADE FROM A FORGING, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-OCT-2008		HRS/MSC -					
		ENC					
SB BR700-72-101260	NO. 1 ENGINE - ENGINE - HPT ROTOR SHAFT AND (NO. 4) BEARING - INTRODUCTION OF AN HP TURBINE STUB SHAFT WHICH IS DECREASED IN WEIGHT, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		HRS/MSC -					
		ENC					
SB BR700-72-101260 R01	NO. 1 ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR SHAFT AND (NO. 4) BEARING - INTRODUCTION OF AN HP TURBINE STUB SHAFT WHICH IS DECREASED IN WEIGHT, SERVICE BULLETIN	MOS				OPTIONAL	NOT APPLICABLE
15-JAN-2015		HRS/MSC -					
		ENC					
SB BR700-72-101270	NO. 1 ENGINE - ENGINE - LP/HP TURBINE SUPPORT AND OUTER BEARINGS - INTRODUCTION OF FRONT AND REAR BEARING CHAMBER PISTON RINGS WITH A SPECIFIED ROUNDNESS VALUE, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
25-JAN-2002		HRS/MSC -					
		ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101271	NO. 1 ENGINE - ENGINE - HPC FRONT (NO 3) BEARING SUPPORT - INTRODUCTION OF NEW BOLTS TO ATTACH THE REAR LABYRINTH SEAL, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
28-JUN-2002		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101275	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF AN ACCESSORY GEARBOX MAIN HOUSING WITH AN IMPROVED MANUFACTURING PROCEDURE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-NOV-2001		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101285	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW ACCESSORY GEARBOX INPUT HOUSING AND ADJUSTING SHIMS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
16-JUN-2003		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101286	NO. 1 ENGINE - ENGINE - BYPASS DUCT - INTRODUCTION OF BYPASS DUCT ACCESS COVERS WITH TITANIUM OUTER SKINS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-MAR-2004		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101293	NO. 1 ENGINE - ENGINE - BYPASS DUCT - INTRODUCTION OF A BYPASS DUCT (BPD) WHICH IS MANUFACTURED BY A NEW SUPPLIER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-JUN-2002		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101326 R01	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW SELF LOCKING NUT FOR THE ACCESSORY GEARBOX LINE NUMBER 9 BREATHER SHAFT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
17-NOV-2008		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101328	NO. 1 ENGINE - ENGINE - HPT 2 LINERS - INTRODUCTION OF NEW HP TURBINE STAGE 2 LINERS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-MAR-2004		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101331	NO. 1 ENGINE - ENGINE - LPT CASE - INTRODUCTION OF DECREASED SHROUD TIP CLEARANCES BETWEEN THE LP TURBINE STAGE 1 AND 2 ROTOR BLADES AND THEIR RELATED SHROUD SEGMENTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-MAY-2003		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101333	NO. 1 ENGINE - ENGINE - HPT ROTOR DISCS - INTRODUCTION OF A NEW STANDARD OF CURVIC RING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-JUN-2002		MOS HRS/MSC - ENC		19-SEP-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101349	NO. 1 ENGINE - ENGINE - LPT FUEL SHUT-OFF CABLE AND FITTINGS - INTRODUCTION OF A NEW FUEL SHUT-OFF (FSO) CABLE WITH BRAZED-ON CLIPS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
24-JUN-2003		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101351 R01	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF AN ALTERNATIVE LINE 9 IMPELLER SHAFT WITH A NEW EXTERNAL THREAD DIAMETER TOLERANCE, NEW IDENTITY MARKINGS AND AN ALTERNATIVE MATERIAL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-JUL-2003		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101369	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR BLADES - INTRODUCTION OF NEW HP COMPRESSOR STAGE 5 AND 6 BLADES MADE FROM A NEW MATERIAL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-JAN-2006		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101395	NO. 1 ENGINE - ENGINE - LP COMPRESSOR BLADES - INTRODUCTION OF A METCO 58 COATING ON THE LP COMPRESSOR BLADES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-MAY-2004		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101414	NO. 1 ENGINE - ENGINE - HPC FRONT CASE - INTRODUCTION OF NEW COATED BUSHES FOR IMPROVED CORROSION PROTECTION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-SEP-2003		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101416 R01	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW ACCESSORY GEARBOX LINE 12 SPACER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-AUG-2003		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101417	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW ACCESSORY GEARBOX LINE 12 GEAR SHAFT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
27-FEB-2004		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101419 R02	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) VARIABLE INLET GUIDE VANE (VIGV) ACTUATING MECHANISM - INTRODUCTION OF A NEW BUILD INSTRUCTION TO INCREASE END FLOAT AND CENTRALISER GAP, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-MAR-2012		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101420	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE CASE - APPLICATION OF ANTI-SEIZURE COMPOUND ON DESIGNATED PLUGS OF COMBUSTOR AND TURBINE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
07-MAY-2004		MOS HRS/MSC - ENC		19-SEP-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101421	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE STAGE 1 NOZZLE GUIDE SEALS - INTRODUCTION OF A NEW REAR BEARING SUPPORT STRUCTURE (RBSS) VENT DUCT MADE FROM A FORGING, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-MAR-2007		HRS/MSC - ENC					
SB BR700-72-101431	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 1 NOZZLE GUIDE SEALS - INTRODUCTION OF A NEW ONE PIECE PRESWIRL NOZZLE AND WEB SEAL ASSEMBLY, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-MAY-2006		HRS/MSC - ENC					
SB BR700-72-101436 R01	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) EXIT GUIDE STATOR VANES - FAN OUTLET GUIDE VANE (OGV) RE-SOURCING, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
03-MAR-2010		HRS/MSC - ENC					
SB BR700-72-101436 R02	NO. 1 ENGINE - RE-SOURCING LOW PRESSURE (LP) EXIT GUIDE STATOR VANES - FAN OUTLET GUIDE VANE (OGV), SERVICE BULLETIN	MOS				OPTIONAL	NOT APPLICABLE
01-OCT-2015		HRS/MSC - ENC					
SB BR700-72-101440	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE AND GEARBOX RADIAL DRIVE - INTRODUCTION OF REVISED INSTALLATION PROCEDURE, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-MAR-2009		HRS/MSC - ENC					
SB BR700-72-101453 R01	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR STATOR VANES - INTRODUCTION OF A FULLY MACHINED ENGINE SECTION STATOR (ESS) BLADE INTEGRATED RING (BLING), SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-APR-2013		HRS/MSC - ENC					
SB BR700-72-101454	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 2 NOZZLE GUIDE SEALS - INTRODUCTION OF A NEW MATERIAL FOR THE HP TURBINE SUPPORT RING, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-JAN-2005		HRS/MSC - ENC					
SB BR700-72-101456	NO. 1 ENGINE - ENGINE LOW PRESSURE (LP) TURBINE SHUT OFF PAWL CARRIER - DELETION OF AN UNUSED TRIM BALANCE FEATURE ON THE PAWL CARRIER, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
09-SEP-2004		HRS/MSC - ENC					
SB BR700-72-101457	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 2 NOZZLE GUIDE SEALS - INTRODUCTION OF A NEW MATERIAL FOR THE HP TURBINE RIM SEAL, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-JAN-2005		HRS/MSC - ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101461	NO. 1 ENGINE - ENGINE - COMBUSTION FAIRINGS - INTRODUCTION OF A NEW CORE FAIRING WITH BLOW OPEN DOOR REMOVED, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
01-JUN-2005		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101463	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR INNER CASE - INTRODUCTION OF A NEW STAGE 5 TO 10 REAR INNER CASE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-APR-2006		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101469	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR VORTEX REDUCER - INTRODUCTION OF A NEW FORGING MATERIAL FOR THE HP COMPRESSOR VORTEX REDUCER RING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
01-MAR-2006		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101469 R01	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VORTEX REDUCER - INTRODUCTION OF A NEW FORGING MATERIAL FOR THE HP COMPRESSOR VORTEX REDUCER RING, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
29-AUG-2014		MOS HRS/MSC - ENC					
SB BR700-72-101471 R02	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - INTRODUCTION OF METCO 58 COATED LP COMPRESSOR BLADES WITH A TRANSITION STRIP, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
28-JUL-2005		MOS HRS/MSC A/R ENC		19-SEP-2013			
SB BR700-72-101474	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF A LASER SHOCK PEENED (LSP) LP COMPRESSOR ROTOR DISC WITH A NEW PART NUMBER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101474 R01	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF A LASER SHOCK PEENED (LSP) LP COMPRESSOR ROTOR DISC WITH A NEW PART NUMBER, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS HRS/MSC - ENC					
SB BR700-72-101474 R01 PART 1	NO. 1 ENGINE - REIDENTIFICATION LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF A LASER SHOCK PEENED (LSP) LP COMPRESSOR ROTOR DISC WITH A NEW PART NUMBER, SERVICE BULLETIN OF A NON-FLOWN LP COMPRESSOR ROTOR DISC					RECOMMENDED	NOT APPLICABLE
		MOS HRS/MSC - ENC					
SB BR700-72-101474 R01 PART 2	NO. 1 ENGINE - REMOVAL LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF A LASER SHOCK PEENED (LSP) LP COMPRESSOR ROTOR DISC WITH A NEW PART NUMBER, SERVICE BULLETIN AND INSTALLATION OF THE LP COMPRESSOR ROTOR DISC					RECOMMENDED	NOT APPLICABLE
		MOS HRS/MSC - ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101476	NO. 1 ENGINE - ENGINE - COMBUSTION LINER - INTRODUCTION OF A NEW COMBUSTION CHAMBER WITHOUT COOLING RIBS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-SEP-2005		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101476 R01	NO. 1 ENGINE - COMBUSTION LINER - INTRODUCTION OF A NEW COMBUSTION CHAMBER WITHOUT COOLING RIBS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
29-AUG-2014		MOS HRS/MSC - ENC					
SB BR700-72-101476 R02	NO. 1 ENGINE - COMBUSTION LINER - INTRODUCTION OF A NEW COMBUSTION CHAMBER WITHOUT COOLING RIBS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
01-OCT-2015		MOS HRS/MSC - ENC					
SB BR700-72-101490	NO. 1 ENGINE - ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - INTRODUCTION OF A NEW RADIAL DRIVE SHAFT (RDS) LOWER SUPPORT HOUSING (LSH), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
14-JUL-2006		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101492	NO. 1 ENGINE - ENGINE - BYPASS DUCT - INTRODUCTION OF NEW INTRASCOPE BLANKS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-NOV-2005		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101493	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR INNER CASE - DELETION OF THE HP VCOMPRESSOR STAGE 5 AND STAGE 7 TO 8 HEAT-SHIELDS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-NOV-2005		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101498	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF METAL TRANSPORTATION BLANKS WITH PLASTIC TRANSPORTATION BLANKS AND INTRODUCTION OF ALTERNATIVE ORIGINAL SUPPLIER PART NUMBERS FOR CERTAIN ACCESSORY GEARBOX COMPONENTS, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAR-2012		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101500	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW ACCESSORY GEARBOX MAIN HOUSING ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101522	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW METHOD OF MANUFACTURE FOR ACCESSORY GEARBOX COMPONENTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-FEB-2008		MOS HRS/MSC - ENC		19-SEP-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101523 R01	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUT-OFF PAWL CARRIER PIVOT PINS MADE FROM A DIFFERENT MATERIAL WITH IMPROVED CORROSION PROTECTION PROPERTIES, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
SB BR700-72-101523 R02	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUT-OFF PAWL CARRIER PIVOT PINS MADE FROM A DIFFERENT MATERIAL WITH IMPROVED CORROSION PROTECTION PROPERTIES, SERVICE BULLETIN	MOS HRS/MSC - ENC			19-DEC-2013	RECOMMENDED	NOT APPLICABLE
SB BR700-72-101525	NO. 1 ENGINE - INTERMEDIATE CASE MODULE - INTRODUCTION OF NEW AND RE-IDENTIFIED INTERNAL GEARBOX COMPONENTS BECAUSE OF DESIGN RESPONSIBILITY CHANGE (SUPERSEDED BY SB BR700-72-101939), SERVICE BULLETIN	MOS HRS/MSC - ENC		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
					11-SEP-2006		
SB BR700-72-101526	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE MODULE ATTACH PARTS AND FITTINGS - INTRODUCTION OF A NEW LP TURBINE AXIAL SETTING PROCEDURE WITH AN INCREASED RANGE OF ADJUSTING RINGS, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
					11-NOV-2008		
SB BR700-72-101527	NO. 1 ENGINE - INTERMEDIATE CASE MODULE ATTACH PARTS AND FITTINGS - INTRODUCTION OF A NEW AIR TURBINE STARTER BRACKET ASSEMBLY, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
					22-AUG-2007		
SB BR700-72-101531	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF NEW MANUFACTURING PROCEDURES FOR ACCESSORY GEARBOX COMPONENTS, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
					07-FEB-2008		
SB BR700-72-101540 R01	NO. 1 ENGINE - ENGINE - EXHAUST CASE - INTRODUCTION OF AN OUTLET GUIDE VANE (OGV) HOUSING ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
					26-NOV-2009		
SB BR700-72-101540 R02	NO. 1 ENGINE - ENGINE - EXHAUST CASE - INTRODUCTION OF AN OUTLET GUIDE VANE (OGV) HOUSING ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN	MOS HRS/MSC - ENC				OPTIONAL	NOT APPLICABLE
					25-SEP-2013		
SB BR700-72-101540 R03	NO. 1 ENGINE - EXHAUST CASE - INTRODUCTION OF AN OUTLET GUIDE VANE (OGV) HOUSING ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN	MOS HRS/MSC - ENC				OPTIONAL	NOT APPLICABLE
					28-JAN-2014		



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101540 R04	NO. 1 ENGINE - EXHAUST CASE - INTRODUCTION OF AN OUTLET GUIDE VANE (OGV) HOUSING ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
29-AUG-2014		MOS HRS/MSC - ENC					
SB BR700-72-101548	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR CASE - INTRODUCTION OF A NEW LP COMPRESSOR CASE WITH NEW IMPROVED SEALING OF THE REAR PANEL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101551	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - DELETION OF BREATHER FILTER AND CHANGES TO BREATHER COVER, TANK COVERS AND OBTURATOR PLATE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
24-MAY-2007		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101573	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR - INCREASED TIP CLEARANCE FOR HP COMPRESSOR STAGE 4 STATOR VANES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-SEP-2006		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101577	NO. 1 ENGINE - ENGINE - BYPASS DUCT ATTACHING PARTS AND FITTINGS - INTRODUCTION OF NEW BYPASS DUCT FRONT AND REAR LOAD SPREADER PLATE ASSEMBLIES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-JUL-2008		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101580	NO. 1 ENGINE - ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF A NEW ENGINE NAME PLATE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
24-SEP-2008		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101589	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF AN ACCESSORY GEARBOX MAIN HOUSING MADE FROM ALUMINUM, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-FEB-2008		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101604 R01	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR BLADES - INTRODUCTION OF HP COMPRESSOR STAGE 1 BLADES WITH A THICKER LEADING EDGE CONTOUR, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
03-MAR-2010		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101618	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF AN ACCESSORY GEARBOX OIL TANK OIL FILL INSTRUCTION LABEL SUITABLE FOR USE WITH AN ALUMINUM ACCESSORY GEARBOX MAIN HOUSING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-NOV-2007		MOS HRS/MSC - ENC		19-SEP-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101623	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW LUBRICLONE FOR THE ACCESSORY GEARBOX, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
19-SEP-2007		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101663	NO. 1 ENGINE - ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY AND LOW PRESSURE (LP) COMPRESSOR/INTERNAL GEARBOX OIL DISTRIBUTION TUBES - INTRODUCTION OF REVISED OIL JET HOUSINGS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
19-FEB-2010		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101664 R02	NO. 1 ENGINE - ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - INTRODUCTION OF A NEW NO.2 BEARING SUPPORT HOUSING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
02-SEP-2010		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101669	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF NUTS WITH SILVER COATED THREAD ONLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-JAN-2010		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101699	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - INTRODUCTION OF A NEW LP COMPRESSOR ANNULUS FILLER WITH AN INTEGRAL HOOK DESIGN, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101705	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR ROTOR AND SHAFT DISCS - INTRODUCTION OF A NEW HP COMPRESSOR FRONT ROTOR ASSEMBLY WITH SHANK NUTS HAVING SILVER COATED THREADS ONLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
14-JAN-2011		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101722	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 2 ONWARD NOZZLE GUIDE SEALS - INTRODUCTION OF A DIFFERENT STANDARD HP TURBINE RIM SEAL ASSEMBLY AND HP TURBINE SUPPORT RING ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101728	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) ACTUATING RINGS AND LEVERS - INTRODUCTION OF A NEW MOUNTING BRACKET ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-72-101734	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) ACTUATING RINGS AND LEVERS - INTRODUCTION OF CHANGES TO THE HP COMPRESSOR VARIABLE STATOR VANE (VSV) SYSTEM COMPONENTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-JAN-2014		MOS HRS/MSC - ENC		19-SEP-2013			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101757	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR FRONT BEARING AND SUPPORT - INTRODUCTION OF A NEW ALTERNATIVE HP COMPRESSOR NO.3 BEARING ASSEMBLY WITH A MORE ROBUST DESIGN, SERVICE BULLETIN	MOS HRS/MSC - ENC				RECOMMENDED	NOT APPLICABLE
SB BR700-72-101774	NO. 1 ENGINE - ENGINE - CORE ENGINE FAIRINGS - INTRODUCTION OF A NEW STANDARD OF CORE ENGINE FAIRINGS, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
SB BR700-72-101794	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) RINGS AND SEALS - INTRODUCTION OF NUTS WITH SILVER COATED THREADS ONLY, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
SB BR700-72-101805 R03	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW STANDARD OF PRESSURE RELIEF VALVE (PRV), SERVICE BULLETIN	MOS HRS/MSC - ENC	18-APR-2013	19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
SB BR700-72-101805 R04	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW STANDARD OF PRESSURE RELIEF VALVE (PRV), SERVICE BULLETIN	MOS HRS/MSC - ENC				OPTIONAL	NOT APPLICABLE
SB BR700-72-101813	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 1 LINER - INTRODUCTION OF NEW HP TURBINE STAGE 1 LINER SEGMENTS WITH AN INCREASED HONEYCOMB AREA (SUPERSEDED BY SB BR700-72-101971), SERVICE BULLETIN	MOS HRS/MSC - ENC		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
SB BR700-72-101953	NO. 1 ENGINE - HIGH PRESSURE (HP) TURBINE BLADES - INTRODUCTION OF AN INSTRUCTION FOR MATCHED TIP GRINDING OF THE HP TURBINE STAGE 2 BLADES DURING NEW PRODUCTION OF THE ENGINE, SERVICE BULLETIN	MOS HRS/MSC - ENC	11-MAR-2016			OPTIONAL	NOT APPLICABLE
SB BR700-72-900062 R02	NO. 1 ENGINE - ENGINE - INSTALLATION CHECK OF THE FASTENERS ON THE ENGINE COMPRESSOR AND COMBUSTION SECTION CORE FAIRINGS NON-MODIFICATION, SERVICE BULLETIN	MOS HRS/MSC - ENC		23-SEP-2013 0 0		INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
SB BR700-72-900062 R03	NO. 1 ENGINE - ENGINE - INSTALLATION CHECK OF THE FASTENERS ON THE ENGINE COMPRESSOR AND COMBUSTION SECTION CORE FAIRINGS NON-MODIFICATION, SERVICE BULLETIN	MOS HRS/MSC - ENC	22-APR-1999	23-SEP-2013 0 0		INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-900062 R04	NO. 1 ENGINE - ENGINE - INSTALLATION CHECK OF THE FASTENERS ON THE ENGINE COMPRESSOR AND COMBUSTION SECTION CORE FAIRINGS NON-MODIFICATION, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
06-MAR-2002		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900229 R01	NO. 1 ENGINE - LP COMPRESSOR INSPECTION OF FAN DISC, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900229 R02	NO. 1 ENGINE - LP COMPRESSOR INSPECTION OF FAN DISC, SERVICE BULLETIN						NOT APPLICABLE
		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900229 R03	NO. 1 ENGINE - LP COMPRESSOR - INSPECTION OF FAN DISC, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900229 R04	NO. 1 ENGINE - LP COMPRESSOR - INSPECTION OF FAN DISC, SERVICE BULLETIN						NOT APPLICABLE
		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900229 R05	NO. 1 ENGINE - LP COMPRESSOR - INSPECTION OF FAN DISC, SERVICE BULLETIN						NOT APPLICABLE
		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900229 R06	NO. 1 ENGINE - LP COMPRESSOR - INSPECTION OF FAN DISC, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
23-FEB-2005		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900229 R06	NO. 1 ENGINE - VISUAL OR ULTRASONIC INSP OF THE FAN DISC, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
PART 1		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900229 R06	NO. 1 ENGINE - ULTRASONIC AND VISUAL INSPECTION OF THE FAN DISC, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
PART 2		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900307 R03	NO. 1 ENGINE - INSPECTION OF TIGHT CLEARANCE ON ENGINE DRESSING, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
21-FEB-2012		MOS					
		HRS/MSC -					
		ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-900392 R02	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSOR CASE - INSPECTION OF THE LP COMPRESSOR CASE FOR INSTALLATION OF CUT ICE IMPACT TRAY BOX ASSEMBLIES BY INCORPORATION OF THE ORIGINAL REPAIR BRG1431 - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
06-OCT-2014		MOS					
		HRS/MSC -					
		ENC					
SB BR700-72-900409 R01	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR CASE - INSPECTION OF THE LP COMPRESSOR CASE FOR INCORPORATION OF THE REPAIR BRG1299 NON-MODIFICATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
30-MAR-2012		MOS					
		HRS/MSC -					
		ENC					
SB BR700-72-900455 R02 PART A	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - VISUAL INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - SUPERSEDED BY ROLLS-ROYCE SB BR700-72-101699 ON 19,AUGUST 2013 AT MANUFACTURE
		MOS		11-OCT-2013			
		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900455 R02 PART B	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - SUPERSEDED BY ROLLS-ROYCE SB BR700-72-101699 ON 19,AUGUST 2013 AT MANUFACTURE
		MOS		11-OCT-2013			
		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900456	NO. 1 ENGINE - ENGINE CONVERSION FROM A FLIGHT-TEST STANDARD ENGINE TO A PRODUCTION STANDARD ENGINE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
26-JUL-2012		MOS					
		HRS/MSC -					
		ENC					
SB BR700-72-900510 R01	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP)/HIGH PRESSURE (HP) TURBINE SUPPORT AND OUTER BEARINGS - INSPECTION AND REPAIR OF REAR BEARING SUPPORT STRUCTURES (RBSS) THAT HAVE BEEN MACHINED BY ELECTRICAL DISCHARGE MACHINING (EDM) - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
18-SEP-2013		MOS					
		HRS/MSC -					
		ENC					
SB BR700-72-900521 R04	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, SERVICE BULLETIN						NOT APPLICABLE
		MOS		09-OCT-2015			
		HRS/MSC -		350.9			
		ENC		149			
SB BR700-72-900521 R04 PART A	NO. 1 ENGINE - VERIFICATION ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, SERVICE BULLETIN OF THE SERIAL NUMBERS OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS					RECOMMENDED	NOT APPLICABLE
		MOS		09-OCT-2015			
		HRS/MSC - (s)		350.9			
		ENC		149			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-900521 R04 PART B	NO. 1 ENGINE - EDDY CURRENT INSPECTION ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, SERVICE BULLETIN OF THE AFFECTED LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS	MOS		09-OCT-2015		RECOMMENDED	NOT APPLICABLE
		HRS/MSC - (s)		350.9			
		ENC		149			
SB BR700-72-900525	NO. 1 ENGINE - INSPECTION OF THE INTERMEDIATE CASE FOR CORROSION DUE TO WATER ACCUMULATION IN THE ENGINE FRONT MOUNT FIREBOX, SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE
10-AUG-2012		HRS/MSC -					
		ENC					
SB BR700-72-900525 R01	NO. 1 ENGINE - ENGINE - INTERMEDIATE CASE MODULE - INSPECTION OF THE INTERMEDIATE CASE FOR CORROSION DUE TO WATER ACCUMULATION IN THE ENGINE FRONT MOUNT FIREBOX - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE
24-JAN-2013		HRS/MSC -					
		ENC					
SB BR700-72-900571	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VIGV AND STAGES 1 TO 4 STATOR VANES - REPLACEMENT OF UNWANTED PARTS TO RECTIFY THE ENGINE CONFIGURATION IN LINE WITH THE REQUIREMENTS OF SB SB-BR700-72-101901 - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE
20-NOV-2015		HRS/MSC -					
		ENC					
SB BR700-72-900580	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE OIL FILLER ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	MOS				OPTIONAL	NOT APPLICABLE
30-NOV-2015		HRS/MSC -					
		ENC					
SB BR700-72-900580 R01	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE OIL FILLER ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	MOS				OPTIONAL	NOT APPLICABLE
04-APR-2016		HRS/MSC -					
		ENC					
SB BR700-72-900637	NO. 1 ENGINE - INTERMEDIATE CASE MODULE - INSPECTION OF THE RETENTION BOLTS OF THE NO.2/NO.3 BEARING HOUSINGS TO THE INTERMEDIATE CASE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE
15-FEB-2018		HRS/MSC -					
		ENC					
SB BR700-72-A900297 R01	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR FAIRINGS - INSPECTION OF THE UPPER LEFT HP COMPRESSOR FAIRING FOR POTENTIAL PROFILE NON CONFORMANCE AND REPLACEMENT OF NON-CONFORMING UPPER LEFT HP COMPRESSOR FAIRING - NON MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	MOS				OPTIONAL	NOT APPLICABLE
21-MAY-2014		HRS/MSC -					
		ENC					
SB BR700-73-100148 R02	NO. 1 ENGINE - FUEL AND CONTROL - DRAINS EJECTOR FUEL FILTER - INTRODUCTION OF A FILTER IN THE LINE TO THE FUEL DRAINS EJECTOR PUMP AND RELATED DRESSINGS CHANGES, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
06-JUL-1998		HRS/MSC -					
		ENC					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-100190	NO. 1 ENGINE - FUEL AND CONTROL - ELECTRONIC ENGINE CONTROL (EEC) - INTRODUCTION OF REVISED HARDWARE STANDARD, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
22-MAR-1997		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-73-100206	NO. 1 ENGINE - ENGINE FUEL AND CONTROL-TUBES AND FITTINGS, AIR-ENGINE FUEL CONTROL SYSTEM (EXTERNAL)-INTRODUCTION OF A REVISED P30 TUBE ASSEMBLY WITH BLEED HOLE IN MOISTURE TRAP, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
11-OCT-1997		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-73-100219	NO. 1 ENGINE - FUEL AND CONTROL - ELECTRONIC ENGINE CONTROLLER (EEC) - INTRODUCTION OF C3.1.1. SOFTWARE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-SEP-1998		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-73-100247	NO. 1 ENGINE - FUEL AND CONTROL - OVERSPEED SPLITTER UNIT - INTRODUCTION OF A NEW UNIT FEATURING AN IMPROVED SAFETY LOCK FEATURE BASED ON RING LOCKED FITTINGS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
07-FEB-1998		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-73-100271 R01	NO. 1 ENGINE - FUEL AND CONTROL - TUBES AND FITTINGS - INTRODUCTION OF MODIFIED TUBE ASSEMBLY END FITTINGS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-73-100283 R02	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH - INTRODUCTION OF UNITS INCORPORATING A HERMETICALLY SEALED MICRO-SWITCH, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-73-100352	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - CORE FUEL SYSTEM TUBES AND FITTINGS - INTRODUCTION OF REVISED BOLT LENGTH (CONFIGURATION SCHEME), SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-73-100357	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INTRODUCTION OF AN REVISED MOTIVE FUEL FILTER TUBE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
29-APR-1998		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-73-100363	NO. 1 ENGINE - FUEL AND CONTROL - FUEL METERING UNIT (FMU) - INTRODUCTION OF A NEW OPTIMISED FUEL METERING UNIT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-JUL-1998		MOS HRS/MSC - ENC		19-SEP-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-100371 R02	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL LOW PRESSURE SWITCH - INTRODUCTION OF UNITS INCORPORATING A HERMETICALLY SEALED MICRO-SWITCH, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-73-100414	NO. 1 ENGINE - FUEL AND CONTROL - ELECTRONIC ENGINE CONTROLLER (EEC) - INTRODUCTION OF C4.0 SOFTWARE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
03-JUL-1998		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-73-100440	NO. 1 ENGINE - FUEL AND CONTROL - ELECTRONIC ENGINE CONTROLLER (EEC) - INTRODUCTION OF SOFTWARE VERSION C5.1.1, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
18-AUG-1998		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-73-100459 R01	NO. 1 ENGINE - FUEL AND CONTROL - FUEL SPRAY NOZZLES - INTRODUCTION OF A FUEL SPRAY NOZZLE ASSEMBLY WITH MODIFIED INTERNAL PARTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-SEP-2005		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-73-100497	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INTRODUCTION OF DRESSING CHANGES TO SUIT MODIFIED THERMAL ANTI-ICING VALVE AND MUSCLE LINE (NEUTRAL ENGINES), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
25-SEP-1998		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-73-100596	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROL (EEC) - INTRODUCTION OF IMPROVED EEC FIREBOX HANDLING ACCESS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-73-100689	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - HP FUEL FILTER - INTRODUCTION OF IMPROVED REMOVAL / INSTALLATION FEATURES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-73-100709	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC ENGINE CONTROLLER (EEC) - INTRODUCTION OF AN EEC WITH C5.2.1 SOFTWARE STANDARD, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-73-100732	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF AN AIR FEED RESTRICTOR TO THE CONFIGURATION DATABASE AND THE ENGINE DOCUMENTATION, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS HRS/MSC - ENC		19-SEP-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-100827 R01	NO. 1 ENGINE - FUEL FLOW TRANSMITTER - INTRODUCTION OF A NEW UNIT WITH A MORE ACCURATE CALIBRATION, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		HRS/MSC	A/R				
		ENC					
SB BR700-73-100835 R02	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - DATA ENTRY PLUG - INTRODUCTION OF A RE-TRIMMED DATA ENTRY PLUG TO INCREASE THE PERMITTED STATOR OUTLET TEMPERATURE, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
10-APR-2001		HRS/MSC	-				
		ENC					
SB BR700-73-100927 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC ENGINE CONTROLLER (EEC) - INTRODUCTION OF AN EEC WITH 05 OR 05R HARDWARE STANDARD, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-2000		HRS/MSC	-				
		ENC					
SB BR700-73-100938	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC ENGINE CONTROLLER (EEC) - INTRODUCTION OF SOFTWARE C5.2.3. INTO AN EEC WITH 04 STANDARD HARDWARE, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
20-OCT-1999		HRS/MSC	-				
		ENC					
SB BR700-73-100964 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL MANIFOLD - INSTALLATION OF A DAMPER WIRE BETWEEN THE LEFT HAND (LH) AND RIGHT HAND (RH) FUEL MANIFOLD, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-OCT-1999		HRS/MSC	-				
		ENC					
SB BR700-73-100970	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - INTRODUCTION OF NEW FITTING INSTRUCTIONS FOR ACCESSORY GEARBOX MOUNTED ACCESSORIES, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
24-JAN-2002		HRS/MSC	-				
		ENC					
SB BR700-73-101085 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL RETURN TO TANK VALVE - INTRODUCTION OF A FUEL RETURN TO TANK VALVE WITH RELATED DRESSING CHANGES, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-OCT-2000		HRS/MSC	-				
		ENC					
SB BR700-73-101094	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INTRODUCTION OF A NEW FUEL TUBE WITH INCREASED CLEARANCE TO THE BUFFER AIR TUBE, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-AUG-2001		HRS/MSC	-				
		ENC					
SB BR700-73-101106 R01	NO. 1 ENGINE - ENGINE AND FUEL CONTROL - FUEL METERING UNIT - INTRODUCTION OF A NEW FUEL METERING UNIT WITH CHANGES TO THE COMBINED OVERSPEED AND SHUT-OFF SOLENOID, THE PRESSURE RAISING VALVE AND ELECTRO HYDRAULIC SERVO VALVE, SERVICE BULLETIN	MOS		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
07-MAR-2001		HRS/MSC	A/R				
		ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-101145 R03	NO. 1 ENGINE - ENGINE AND FUEL CONTROL-ENGINE ELECTRIC CONTROLLER-INTRODUCTION OF C6.0 SOFTWARE STANDARD INTO AN EEC WITH 05 OR 05B HARDWARE, SERVICE BULLETIN	MOS HRS/MSC A/R ENC		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
SB BR700-73-101359	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INTRODUCTION OF A FUEL TUBE WITH A NEW ROUTING TO INCREASE THE CLEARANCE BETWEEN THE TUBE AND THE V-BAND CLAMP FOR THE HP STAGE 5 BLEED, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
17-DEC-2002							
SB BR700-73-101362	NO. 1 ENGINE - ENGINE - FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW EEC HARDWARE STANDARD, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
02-OCT-2002							
SB BR700-73-101367	NO. 1 ENGINE - INTRODUCTION OF AN EEC WITH A NEW HARDWARE STANDARD (08), SERVICE BULLETIN	MOS HRS/MSC A/R ENC		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
SB BR700-73-101386	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL MANIFOLD - CHANGE OF SUPPLIER SOURCE FOR THE FUEL MANIFOLD DAMPER WIRE, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-JUL-2005							
SB BR700-73-101396	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INTRODUCTION OF NEW PART NUMBERS FOR TWO FUEL TUBE ASSEMBLIES, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-MAR-2004							
SB BR700-73-101415	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - CHANGE OF SUPPLIER SOURCE FOR THE FUEL SYSTEM P20, P30 AND P50 FLEXIBLE AIR TUBES, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-MAY-2006							
SB BR700-73-101429	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - DEDICATED GENERATOR - INTRODUCTION OF A NEW DEDICATED GENERATOR ROTOR WITH REDUCED OUT-OF-BALANCE (OOB) LIMITS, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
20-JAN-2004							
SB BR700-73-101443	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - DATA ENTRY PLUG (DEP) - INTRODUCTION OF A NEW DEP, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-MAY-2006							



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-101451	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW LOCATION OF THE EEC CONNECT MODULE CAPACITOR, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-JUN-2004		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-73-101472 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C7.0.2, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-NOV-2004		MOS HRS/MSC A/R ENC		19-SEP-2013			
SB BR700-73-101477	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - T30 THERMOCOUPLES - INTRODUCTION OF A NEW T30 THERMOCOUPLE PROBE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-APR-2005		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-73-101504	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW STANDARD OF EEC HARDWARE AND SOFTWARE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
19-NOV-2007		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-73-101504 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW STANDARD OF EEC HARDWARE AND SOFTWARE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
10-JUL-2017		MOS HRS/MSC - ENC					
SB BR700-73-101505	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW TRANSMITTER (FFT) - INTRODUCTION OF A NEW FFT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-SEP-2005		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-73-101509	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF AN EEC WITH PRINTED CIRCUIT BOARDS FROM A NEW SOURCE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC A/R ENC		19-SEP-2013			
SB BR700-73-101558 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW TRANSMITTER (FFT) - INTRODUCTION OF A NEW FFT WITH IMPROVED ACCURACY LIMITS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
09-NOV-2007		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-73-101559 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
27-FEB-2012		MOS HRS/MSC - ENC		19-SEP-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-101559 R02	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN	MOS				OPTIONAL	NOT APPLICABLE
10-JUL-2017		HRS/MSC -					
		ENC					
SB BR700-73-101559 R03	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN	MOS				OPTIONAL	NOT APPLICABLE
10-MAR-2021		HRS/MSC -					
		ENC					
SB BR700-73-101617	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW TRANSMITTER (FFT) - INTRODUCTION OF A FFT WITH A NEW CALIBRATION, SERVICE BULLETIN	MOS				OPTIONAL	COMPLIED WITH - AT MANUFACTURE
27-JUN-2007		HRS/MSC -		19-SEP-2013			
		ENC					
SB BR700-73-101617 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW TRANSMITTER (FFT) - INTRODUCTION OF A FFT WITH A NEW CALIBRATION, SERVICE BULLETIN	MOS				OPTIONAL	NOT APPLICABLE
		HRS/MSC -					
		ENC					
SB BR700-73-101628 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF AN EEC WITH X1.1 SOFTWARE STANDARD, SERVICE BULLETIN	MOS				OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		HRS/MSC -		19-SEP-2013			
		ENC					
SB BR700-73-101634	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN	MOS				OPTIONAL	NOT APPLICABLE
26-JUN-2008		HRS/MSC -					
		ENC					
SB BR700-73-101634 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN	MOS				OPTIONAL	NOT APPLICABLE
10-JUL-2017		HRS/MSC -					
		ENC					
SB BR700-73-101634 R02	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN	MOS				OPTIONAL	NOT APPLICABLE
10-MAR-2021		HRS/MSC -					
		ENC					
SB BR700-73-101806 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF X1.2 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01, SERVICE BULLETIN	MOS				OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		HRS/MSC -		19-SEP-2013			
		ENC					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-101966 R02	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF X2.0 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01, SERVICE BULLETIN	MOS		24-MAY-2019		OPTIONAL	COMPLIED WITH
21-DEC-2016		HRS/MSC -		879.42			
		ENC		365			
SB BR700-73-900423 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE
09-SEP-2014		HRS/MSC -					
		ENC					
SB BR700-73-900423 R02	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE
09-MAR-2015		HRS/MSC -					
		ENC					
SB BR700-73-900423 R03	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE
22-DEC-2016		HRS/MSC -					
		ENC					
SB BR700-73-900423 R04	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN (THIS NON-MODIFICATION SB-BR700-73-9000423 IS NO LONGER VALID AND CAN BE CLOSED), SERVICE BULLETIN	MOS				OPTIONAL	NOT APPLICABLE
25-FEB-2021		HRS/MSC -					
		ENC					
SB BR700-73-900539	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - HIGH PRESSURE (HP) FUEL FILTER ASSEMBLY - INSPECTION OF THE HP FUEL FILTER HOUSING CAP FOR CORRECT INSTALLATION OF ITS SEAL RING AND BACKUP RING - NON-MODIFICATION, SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE
		HRS/MSC A/R					
		ENC					
SB BR700-73-900539 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - HIGH PRESSURE (HP) FUEL FILTER ASSEMBLY - INSPECTION OF THE HP FUEL FILTER HOUSING CAP FOR CORRECT INSTALLATION OF ITS SEAL RING AND BACKUP RING - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE
06-JUN-2013		HRS/MSC -					
		ENC					
SB R03 BR700-73-A900083	NO. 1 ENGINE - ENGINE FUEL AND CONTROL ENGINE ELECTRONIC CONTROLLER (EEC) - REPLACEMENT OF NON-CONFORMING PARTS OF THE EEC FIREBOX ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN (THIS SB IS NO LONGER VALID AND CAN BE CLOSED), SERVICE BULLETIN	MOS				OPTIONAL	NOT APPLICABLE
28-JAN-2021		HRS/MSC -					
		ENC					
SB BR700-74-100199	NO. 1 ENGINE - IGNITION - IGNITION UNIT - HIGH ENERGY - REVISED IGNITER BOX ATTACHING PARTS, SERVICE BULLETIN	MOS		23-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-FEB-1998		HRS/MSC -					
		ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-74-100248	NO. 1 ENGINE - IGNITION - IGNITION LEADS - INTRODUCTION OF REVISED CLIPPING, SERVICE BULLETIN	MOS		23-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		HRS/MSC - ENC					
SB BR700-74-100316	NO. 1 ENGINE - IGNITION - IGNITER LEAD - INTRODUCTION OF SILVER PLATING ON CONNECTING NUT THREADS, SERVICE BULLETIN	MOS		23-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
28-APR-2000		HRS/MSC - ENC					
SB BR700-74-100355	NO. 1 ENGINE - IGNITION - IGNITER PLUG - INTRODUCTION OF A SECOND SOURCE IGNITER PLUG, SERVICE BULLETIN	MOS		23-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-APR-1998		HRS/MSC - ENC					
SB BR700-74-100550	NO. 1 ENGINE - IGNITION - RIGHT ENGINE IGNITION LEAD ATTACHING FITTINGS - INTRODUCTION OF DRESSING CHANGES TO SUIT MODIFIED THERMAL ANTI-ICING VALVE AND MUSCLE LINE (RIGHT HAND ENGINES), SERVICE BULLETIN	MOS		23-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
25-SEP-1998		HRS/MSC - ENC					
SB BR700-74-100551	NO. 1 ENGINE - IGNITION - LEFT ENGINE IGNITION LEAD ATTACHING FITTINGS - INTRODUCTION OF TWO ADDITIONAL CLIPPING POINTS AND TRANSFER OF A BRACKET TO A LEFT ENGINE SECTION, SERVICE BULLETIN	MOS		23-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-SEP-1998		HRS/MSC - ENC					
SB BR700-74-101073 R01	NO. 1 ENGINE - IGNITION - IGNITER PLUG - INTRODUCTION OF A STANDARD LENGTH IGNITER PLUG ADAPTOR AND RELATED ADJUSTING WASHERS, SERVICE BULLETIN	MOS		23-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-OCT-2001		HRS/MSC - ENC					
SB BR700-74-101280	NO. 1 ENGINE - IGNITION - HIGH ENERGY IGNITION UNITS - INTRODUCTION OF A NEW IGNITION UNIT WITH CHANGES TO THE PRINTED CIRCUIT BOARD, SERVICE BULLETIN	MOS		23-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
04-OCT-2001		HRS/MSC - ENC					
SB BR700-74-101378	NO. 1 ENGINE - IGNITION - LEFT ENGINE IGNITION LEAD ATTACHING FITTINGS - INCREASED CLEARANCE BETWEEN CLIPPING POINT CP10373 AND AN ADJACENT OIL PIPE, SERVICE BULLETIN	MOS		23-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
25-FEB-2003		HRS/MSC - ENC					
SB BR700-75-100212 R01	NO. 1 ENGINE - AIR - BLEED VALVES - INTRODUCTION OF HIGH PRESSURE COMPRESSOR (HPC) BLEED VALVES WITH STEEL BUSHES, SERVICE BULLETIN	MOS		23-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
11-APR-2003		HRS/MSC - ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-75-100228 R01	NO. 1 ENGINE - AIR - VSV ACTUATOR - INTRODUCTION OF ONE HANDED 'ROSAN' LOCKING FEATURE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-75-100270	NO. 1 ENGINE - AIR - AIR TUBES AND FITTINGS - MINOR CONFIGURATION AMENDMENTS, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-75-100297 R01	NO. 1 ENGINE - AIR - VALVE CONTROL AIR BLEED - INTRODUCTION OF REVISED TORQUE TIGHTENING VALUES FOR BLEED VALVE BOLTS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-75-100332 R01	NO. 1 ENGINE - AIR - SOLENOID CONTROL - AIR BLEED - INTRODUCTION OF REVISED BLEED VALVE SOLENOID CONTROL BLOCK MOUNTING BRACKETS AND ASSOCIATED AIR TUBES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-75-100366 R01	NO. 1 ENGINE - AIR - SOLENOID CONTROL - AIR BLEED - INTRODUCTION OF A REVISED BLEED VALVE SOLENOID CONTROL BLOCK, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-75-100385 R01	NO. 1 ENGINE - AIR-BLEED VALVES AND SOLENOID CONTROL BLOCK - INTRODUCTION OF AN IMPROVED DESIGN OF BLEED VALVE AND SOLENOID CONTROL BLOCK, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-OCT-1999		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-75-100392	NO. 1 ENGINE - AIR - VSV ACTUATOR - INTRODUCTION OF A VARIABLE STATOR VANE ACTUATOR MANUFACTURED BY A NEW SUPPLIER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
14-SEP-1998		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-75-100465 R01	NO. 1 ENGINE - AIR - BUFFER AIR VALVE - INTRODUCTION OF A NEW BUFFER AIR VALVE FROM A DIFFERENT SUPPLIER AND WITH IMPROVED CORROSION PROTECTION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
19-JUL-2002		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-75-101096	NO. 1 ENGINE - AIR - BLEED VALVE SOLENOID CONTROL BLOCK - INTRODUCTION OF TRANSFER TUBES BETWEEN THE BLEED VALVE SOLENOID BLOCK VENT VALVE BODY AND THE SOLENOID CAPS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
12-JUL-2000		MOS HRS/MSC - ENC		23-SEP-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-75-101097	NO. 1 ENGINE - AIR - CORE AIR TUBES AND FITTINGS - INTRODUCTION OF A NEW AIR TUBE WITH A DIFFERENT ROUTING FROM THE BUFFER AIR VALVE TO THE ACCESSORY GEARBOX AND AN ADDITIONAL CLIP POINT CP40402, SERVICE BULLETIN	MOS		19-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
03-FEB-2004		HRS/MSC - ENC					
SB BR700-75-101130 R01	NO. 1 ENGINE - AIR - BLEED VALVES - INTRODUCTION OF NEW HP 8 HANDLING BLEED VALVE INNER AND OUTER ATTENUATORS TO PREVENT DAMAGE TO BYPASS DUCT, SERVICE BULLETIN	MOS		23-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
22-JUN-2001		HRS/MSC A/R ENC					
SB BR700-75-101161 R01	NO. 1 ENGINE - AIR - BLEED VALVE SOLENOID CONTROL BLOCK-INTRODUCTION OF HANDLING BLEED VALVE SOLENOID WITH SOLENOID SERVO VALVES WHICH OPERATE AT LOWER CURRENT FLOWS, SERVICE BULLETIN	MOS		23-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
07-FEB-2001		HRS/MSC - ENC					
SB BR700-75-101161 R02	NO. 1 ENGINE - AIR - BLEED VALVE SOLENOID CONTROL BLOCK - INTRODUCTION OF A HANDLING BLEED VALVE SOLENOID WITH SOLENOID SERVO VALVES WHICH OPERATE AT LOWER CURRENT FLOWS, SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE
07-OCT-2017		HRS/MSC - ENC					
SB BR700-75-101161 R03	NO. 1 ENGINE - AIR - BLEED VALVE SOLENOID CONTROL BLOCK - INTRODUCTION OF A HANDLING BLEED VALVE SOLENOID WITH SOLENOID SERVO VALVES WHICH OPERATE AT LOWER CURRENT FLOWS, SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE
07-SEP-2018		HRS/MSC - ENC					
SB BR700-75-101207	NO. 1 ENGINE - AIR - AIR TUBES AND FITTINGS - INTRODUCTION OF A P30 AIR TUBE WITH A NEW ROUTING TO INCREASE THE CLEARANCE BETWEEN THE TUBE AND THE FUEL MANIFOLD, SERVICE BULLETIN	MOS		23-SEP-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
20-JUN-2002		HRS/MSC - ENC					
SB BR700-75-101228	NO. 1 ENGINE - AIR - CORE AIR TUBES AND FITTINGS - INTRODUCTION OF NEW HP2/HP4 AIR SYSTEM TUBE ASSEMBLIES WHICH ARE DECREASED IN WEIGHT, SERVICE BULLETIN	MOS		23-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
24-APR-2002		HRS/MSC - ENC					
SB BR700-75-101381 R01	NO. 1 ENGINE - AIR - BLEED VALVES - INTRODUCTION OF NEW TRIPLE SEALS AND A CARBON BUSH TO REPLACE THE EXISTING STEEL COMPONENTS, SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE
09-OCT-2018		HRS/MSC - ENC					
SB BR700-75-101447 R01	NO. 1 ENGINE - AIR - VSV ACTUATOR - INTRODUCTION OF A MODIFIED VARIABLE STATOR VANE (VSV) ACTUATOR, SERVICE BULLETIN	MOS		23-SEP-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-AUG-2013		HRS/MSC - ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-75-101447 R02	NO. 1 ENGINE - AIR - VSV ACTUATOR - INTRODUCTION OF A MODIFIED VARIABLE STATOR VANE (VSV) ACTUATOR, SERVICE BULLETIN	MOS HRS/MSC - ENC				OPTIONAL	NOT APPLICABLE
SB BR700-75-101694	NO. 1 ENGINE - AIR - AIR BLEED CONTROL SOLENOID - INTRODUCTION OF WASHERS WITH A SMALLER OUTER DIAMETER FOR THE INSTALLATION OF THE HANDLING BLEED VALVE SOLENOID CONTROL BLOCK, SERVICE BULLETIN	MOS HRS/MSC - ENC				OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-APR-2010				23-SEP-2013			
SB BR700-75-900633	NO. 1 ENGINE - AIR - VSV ACTUATOR - REPLACEMENT OF LUCAS VARIABLE STATOR VANE (VSV) ACTUATORS, SERVICE BULLETIN	MOS HRS/MSC - ENC				RECOMMENDED	NOT APPLICABLE
19-JUN-2018							
SB BR700-75-900633 R01	NO. 1 ENGINE - AIR - VSV ACTUATOR - REPLACEMENT OF LUCAS VARIABLE STATOR VANE (VSV) ACTUATORS - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	MOS HRS/MSC - ENC				RECOMMENDED	NOT APPLICABLE
11-DEC-2018							
SB BR700-75-900693	NO. 1 ENGINE - AIR - VSV ACTUATOR - REPLACEMENT OF VARIABLE STATOR VANE (VSV) ACTUATORS - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	MOS HRS/MSC - ENC				RECOMMENDED	NOT APPLICABLE
25-MAR-2021							
SB BR700-77-100556	NO. 1 ENGINE - ENGINE INDICATING - TURBINE OVERHEAT/OIL FIRE DETECTION THERMOCOUPLE - INTRODUCTION OF STRENGTHENED TERMINALS, SERVICE BULLETIN	MOS HRS/MSC - ENC				OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-NOV-1998				23-SEP-2013			
SB BR700-77-101105	NO. 1 ENGINE - ENGINE INDICATING - TGT HARNESS - INTRODUCTION OF TORQUE TIGHTENING VALUES FOR THE NUTS WHICH ATTACH THE TURBINE GAS TEMPERATURE (TGT) HARNESS TO THE TGT PROBES, SERVICE BULLETIN	MOS HRS/MSC - ENC				RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
10-APR-2001				23-SEP-2013			
SB BR700-77-101534	NO. 1 ENGINE - ENGINE INDICATING - TURBINE GAS TEMPERATURE (TGT) THERMOCOUPLE - INTRODUCTION OF NEW TGT PROBES, SERVICE BULLETIN	MOS HRS/MSC - ENC				OPTIONAL	COMPLIED WITH - AT MANUFACTURE
14-SEP-2006				23-SEP-2013			
SB BR700-77-101536	NO. 1 ENGINE - ENGINE INDICATING - TURBINE GAS TEMPERATURE (TGT) HARNESS - INTRODUCTION OF A NEW TGT HARNESS, SERVICE BULLETIN	MOS HRS/MSC - ENC				OPTIONAL	COMPLIED WITH - AT MANUFACTURE
14-JUL-2006				23-SEP-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-77-101544	NO. 1 ENGINE - ENGINE INDICATING - VIBRATION TRANSDUCER AND CABLE - INTRODUCTION OF A NEW ENGINE VIBRATION MONITORING SYSTEM (EVMS) ACCELEROMETER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
02-NOV-2007		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-77-101553	NO. 1 ENGINE - ENGINE INDICATING - VIBRATION TRANSDUCER AND CABLE - INTRODUCTION OF A NEW ENGINE VIBRATION MONITORING SYSTEM (EVMS) CABLE ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
24-MAR-2009		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-77-900329 R01	NO. 1 ENGINE - ENGINE INDICATING - N2 SPEED PROBES - INSULATION RESISTANCE TEST ON N2 SPEED PROBES FOR POTENTIAL ELECTRICAL DEFECTS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - PER SPEED PROBES INSTALLED
29-OCT-2003		MOS HRS/MSC - ENC		02-NOV-2016 541.13 225			
SB BR700-78-100165 R01	NO. 1 ENGINE - THRUST REVERSER - LH AND RH ENGINES - INTRODUCTION OF BEARINGS WITH A TEFLON LINER FOR THE LINEAR VARIABLE TRANSDUCER (LVT) ROD ENDS, THE PRIMARY DOOR LOCK AND THE INHIBITION BOLT RECEPTACLE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-100196 R02	NO. 1 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - LH AND RH ENGINES - INTRODUCTION ON THE LH AND RH ENGINE OF SPHERICAL BEARINGS WITH A HIGH TEMPERATURE TEFLON LINER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
22-MAR-2000		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-100224 R01	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF A CHANGE OF OWNERSHIP (INSTALLATION RESPONSIBILITY) FOR THE WET DRAINS BRACKETS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-100225	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - REPLACEMENT OF THE FIRE PROTECTION ABLATIVE COATING ON THE THRUST REVERSER FRONT FRAME TORQUE BOX WITH FIRE BLANKETS (HUREL DUBOIS SB 04MOD0077), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
05-JUN-1998		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-100236 R01	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF REVISED PIVOT DOOR ACTUATORS AND DYNAMIC SEALS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-100252 R01	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - DELETION OF 'NEXTEL' FROM PIVOT DOORS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		09-SEP-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-78-100358	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - DELETION OF THE THRUST REVERSER STOW SWITCH ACCESS PANELS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-100359	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - DELETION OF UPPER DOOR HOISTING POINTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-MAR-2002		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-100360	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - DELETION OF THE NEXTEL LAYER ON THE FAN DUCT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-100361	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - DELETION OF THE NEXTEL LAYER ON FRAME 1, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-100389 R01	NO. 1 ENGINE - EXHAUST - THRUST REVERSER UNIT (TRU) - CHANGE OF THE LINEAR VARIABLE TRANSFORMER (LVT) TO ENSURE IMPROVED PERFORMANCE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-100390	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF SIMPLIFIED TORQUE BOX AND LATERAL BEAM JOINT FOR WEIGHT REDUCTION PURPOSES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-100417	NO. 1 ENGINE - EXHAUST - LEFT ENGINE THRUST REVERSER - INTRODUCTION OF LONGER HYDRAULIC HOSES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-DEC-1998		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-100502	NO. 1 ENGINE - EXHAUST - ISOLATION CONTROL UNIT (ICU) - INTRODUCTION OF A NEW ICU WHICH HAVE A RETARDED THRUST REVERSER UNIT (TRU) PRESSURISATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
25-SEP-2008		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-100593 R01	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - CHANGE OF THRUST REVERSER PIVOT DOOR HONEYCOMB MATERIAL AND INTRODUCTION OF WEIGHT REDUCTION FEATURES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-2000		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-100599	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF A WEIGHT REDUCED GEARBOX AIR BREATHER PIPE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		09-SEP-2013			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-78-100641	NO. 1 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - INTRODUCTION OF A NEW MATERIAL FOR THE JUNCTION SPLICE BETWEEN THE NOZZLE AND BEAM, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
17-MAY-2001		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-100642 R01	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - IMPROVED ELECTRICAL BONDING OF THE THRUST REVERSER MAIN DOOR, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-100783 R05	NO. 1 ENGINE - EXHAUST - LEFT AND RIGHT ENGINE THRUST REVERSER - MATERIAL CHANGE OF THE PIVOTING DOOR SEAL DEPRESSOR AND CARRIER SEGMENTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-NOV-2009		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-100898	NO. 1 ENGINE - EXHAUST - EXHAUST CONE - INTRODUCTION OF A ONE PIECE EXHAUST CONE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
13-JUL-2001		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-78-100935 R01	NO. 1 ENGINE - EXHAUST - TERTIARY LOCK - INTRODUCTION OF TERTIARY LOCKS WITH A BETTER MANUAL RELEASE MECHANISM AND INCREASED SOLENOID FORCE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
04-JUL-2002		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-100987 R01	NO. 1 ENGINE - EXHAUST - LEFT AND RIGHT THRUST REVERSER HYDRAULIC TUBES - CHANGES TO THE MAIN-DOOR-ACTUATOR HOSES (THE ACTUATOR HOSES) OF THE THRUST REVERSER UNIT (TRU), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-SEP-2000		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-101009	NO. 1 ENGINE - EXHAUST - LEFT AND RIGHT ENGINE THRUST REVERSER - INTRODUCTION OF NEW SHIMS FOR THE SEAL LANDS ON THE INTERFACE OF THE THRUST REVERSER AND THE UPPER AND LOWER COWL DOOR, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
16-OCT-2000		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-101061 R04	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF THRUST REVERSER FLOW DISCOURAGER SEALS BETWEEN THE PIVOT DOORS AND THE FIXED STRUCTURE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
03-MAY-2001		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-101129 R01	NO. 1 ENGINE - EXHAUST - LEFT AND RIGHT ENGINE THRUST REVERSER FIXED STRUCTURE - REORIENTATION OF THE FASTENERS AT THE THRUST REVERSER FRONT FRAME TO INCREASE THE CLEARANCE TO THE S-HOOK, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
16-OCT-2000		MOS HRS/MSC - ENC		09-SEP-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-78-101387	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF STOW SWITCHES MANUFACTURED BY A NEW SUPPLIER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-MAR-2003		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-101442	NO. 1 ENGINE - EXHAUST - EXHAUST NOZZLE - INTRODUCTION OF A NEW EXHAUST NOZZLE ASSEMBLY WITHOUT SPACERS BETWEEN THE FRONT SUPPORT BRACKETS AND THE NOZZLE SKIN, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
29-OCT-2004		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-78-101501	NO. 1 ENGINE - EXHAUST - ISOLATION CONTROL UNIT (ICU) - INTRODUCTION OF AN ISOLATION CONTROL UNIT WITH IMPROVED BONDING RESISTANCE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-JUL-2005		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-101512	NO. 1 ENGINE - EXHAUST - THRUST REVERSER PIVOTING DOORS - INSTRUCTION OF VARIOUS IMPROVEMENTS TO THE THRUST REVERSER PIVOTING DOORS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
27-APR-2006		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-101514	NO. 1 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - INTRODUCTION OF A NEW UPPER INHIBITION BOLT FITTING MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
27-APR-2006		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-101515	NO. 1 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - INTRODUCTION OF A NEW 'Y' STOP FITTING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-JAN-2007		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-101607	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF A NEW THRUST REVERSER UNIT (TRU), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-AUG-2007		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-101635	NO. 1 ENGINE - EXHAUST - THRUST REVERSER DOOR STOW SWITCH - INTRODUCTION OF A DOOR STOW SWITCH WITH IMPROVED SEALING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
01-AUG-2008		MOS HRS/MSC - ENC		09-SEP-2013			
SB BR700-78-102008 R01	NO. 1 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - INTRODUCTION OF A DRAINAGE HOLE WITHIN THE THRUST REVERSER FIXED STRUCTURE TO PREVENT CORROSION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - SB BR700-78-102008 R1 IAW SAFRAN NACELLES SB 04MOD132 ON LEFT ENGINE AT BAS FLL-USA FACILITY
19-JAN-2018		MOS HRS/MSC - ENC		25-MAY-2019 879.42 365			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-79-100118 R01	NO. 1 ENGINE - OIL - COOLER - ENGINE LUBRICATING OIL (AIR COOLED) DELETION OF AIR COOLED OIL COOLER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
29-SEP-2000		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-79-100221	NO. 1 ENGINE - OIL - OIL TANK AND EXTERNAL OIL TUBES - INTRODUCTION OF A SCUPPER DRAIN TUBE AND A MODIFIED OIL FILLER ASSEMBLY AND THE DELETION OF BLANKING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
19-JUN-1998		MOS HRS/MSC - ENC		19-SEP-2013			
SB BR700-79-100294	NO. 1 ENGINE - OIL - FUEL COOLED OIL COOLER - REMOVAL OF LIFE LIMITATION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
25-FEB-1998		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-79-100323	NO. 1 ENGINE - OIL - TUBES AND FITTINGS - ENGINE LUBRICATING OIL - EXTERNAL - INTRODUCTION OF A REVISED ANTI - SYPHON TUBE ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
29-APR-1998		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-79-100323 R01	NO. 1 ENGINE - OIL - EXTERNAL OIL TUBES AND FITTINGS - INTRODUCTION OF A REVISED ANTI-SYPHON OIL TUBE ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
14-MAR-2014		MOS HRS/MSC - ENC					
SB BR700-79-100403	NO. 1 ENGINE - OIL - OIL DIFFERENTIAL PRESSURE TRANSDUCER- INTRODUCTION OF A NEW OIL DIFFERENTIAL PRESSURE TRANSDUCER UNIT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-79-100406 R01	NO. 1 ENGINE - OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH - INTRODUCTION OF A UNIT INCORPORATING A HERMETICALLY SEALED MICRO-SWITCH, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
09-DEC-1998		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-79-100413	NO. 1 ENGINE - OIL - FUEL COOLED OIL COOLER - INTRODUCTION OF A NEW UNIT FEATURING A CAST VERSION OF THE OIL FILTER HOUSING COVER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-79-100478	NO. 1 ENGINE - OIL - EXTERNAL OIL TUBES AND FITTINGS - INTRODUCTION OF REVISED CLIPPING POINTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		23-SEP-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-79-100798 R01	NO. 1 ENGINE - OIL - FUEL COOLED OIL COOLER - INTRODUCTION OF NEW ELECTRICAL BONDING LEAD FITTING INSTRUCTIONS, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
22-SEP-2000		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-79-101083	NO. 1 ENGINE - OIL - EXTERNAL OIL TUBES AND FITTINGS - INTRODUCTION OF A NEW OIL VENT TUBE WITH BETTER SEALING PROPERTIES BETWEEN THE OIL VENT PIPE AND THE ACCESSORY GEARBOX, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
01-DEC-2000		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-79-101188 R01	NO. 1 ENGINE - OIL - OIL DIFFERENTIAL PRESURE SWITCH - INTRODUCTION OF A NEW OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH A THICKER COVER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-JUL-2002		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-79-101287	NO. 1 ENGINE - OIL - OIL PUMPS - INTRODUCTION OF A NEW OIL PUMP WITH A SMALLER SPILL RETURN ORIFICE WHICH INCREASES THE PUMP DISCHARGE OIL FLOW, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-FEB-2002		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-79-101292	NO. 1 ENGINE - OIL - EXTERNAL OIL TUBES AND FITTINGS - INTRODUCTION OF A NEW OIL TUBE BETWEEN THE GEARBOX OIL PUMP AND THE FUEL COOLED OIL COOLER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-NOV-2002		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-79-101445	NO. 1 ENGINE - OIL - OIL PUMP - INTRODUCTION OF A NEW STATIC ANTI LEAK VALVE (SALV) INTO THE OIL PUMP UNIT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
16-APR-2004		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-79-101449	NO. 1 ENGINE - OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH - INTRODUCTION OF A NEW OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH A CHANGE TO THE SWITCH SET POINT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-MAY-2004		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-79-101458	NO. 1 ENGINE - OIL - PRESSURE FILTER ELEMENT - INTRODUCTION OF A NEW OIL FILTER ELEMENT WITH INCREASED DIRT HOLDING CAPACITY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
17-MAY-2004		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-79-101470	NO. 1 ENGINE - OIL - FUEL COOLED OIL COOLER (FCOC) - INTRODUCTION OF A NEW FRONT SUPPORT BRACKET, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-NOV-2005		MOS HRS/MSC - ENC		23-SEP-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-79-101482	NO. 1 ENGINE - OIL - FUEL COOLED OIL COOLER (FCOC) - INTRODUCTION OF A NEW FUEL COOLED OIL COOLER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-MAR-2005		MOS		23-SEP-2013			
		HRS/MSC -					
		ENC					
SB BR700-79-101739	NO. 1 ENGINE - OIL - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF A NEW SEALING PLATE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-FEB-2011		MOS		23-SEP-2013			
		HRS/MSC -					
		ENC					
SB BR700-79-101744	NO. 1 ENGINE - FUEL COOLED OIL COOLER (FCOC) - INTRODUCTION OF A NEW FCOC WITH IMPROVED ICING PROTECTION CAPABILITY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
29-AUG-2012		MOS					
		HRS/MSC -					
		ENC					
SB BR700-79-101744 R01	NO. 1 ENGINE - OIL - FUEL COOLED OIL COOLER (FCOC) - INTRODUCTION OF A NEW FCOC WITH IMPROVED ICING PROTECTION CAPABILITY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2013			
		HRS/MSC -					
		ENC					
SB BR700-79-101803	NO. 1 ENGINE - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF A NEW OIL PUMP UNIT WITH IMPROVED GEARS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
09-AUG-2012		MOS		23-SEP-2013			
		HRS/MSC -					
		ENC					
SB BR700-79-101803 R01	NO. 1 ENGINE - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF A NEW OIL PUMP UNIT WITH IMPROVED GEARS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
29-AUG-2014		MOS					
		HRS/MSC -					
		ENC					
SB BR700-79-900215 R01	NO. 1 ENGINE - OIL - EXCHANGE OF OIL FILTER DIFFERENTIAL PRESSURE SWITCH, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
SB BR700-79-900215 R02	NO. 1 ENGINE - OIL - EXCHANGE OF OIL FILTER DIFFERENTIAL PRESSURE SWITCH, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS		23-SEP-2013			
		HRS/MSC -		0			
		ENC		0			
SB BR700-79-900448	NO. 1 ENGINE - OIL - MAGNETIC CHIP DETECTORS (MCD) - REVISED INSPECTION SCHEDULE OF THE FRONT BEARING CHAMBER (FBC) MCD AND MANAGEMENT OF POTENTIAL NON-CONFORMING HIGH PRESSURE (HP) COMPRESSOR NO.3 BEARING ASSEMBLIES - NON-MODIFICATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
05-AUG-2013		MOS					
		HRS/MSC -					
		ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-79-900448 PART A	NO. 1 ENGINE - INTRODUCTION OIL - MAGNETIC CHIP DETECTORS (MCD) - REVISED INSPECTION SCHEDULE OF THE FRONT BEARING CHAMBER (FBC) MCD AND MANAGEMENT OF POTENTIAL NON-CONFORMING HIGH PRESSURE (HP) COMPRESSOR NO.3 BEARING ASSEMBLIES - NON-MODIFICATION, SERVICE BULLETIN OF A REVISED FRONT BEARING CHAMBER (FBC) MAGNETIC CHIP DETECTOR (MCD) INSPECTION INTERVAL FOR ALL POTENTIALLY AFFECTED ENGINES					RECOMMENDED	NOT APPLICABLE
05-AUG-2013		MOS HRS/MSC - ENC					
SB BR700-79-900448 PART B	NO. 1 ENGINE - INSTRUCTIONS OIL - MAGNETIC CHIP DETECTORS (MCD) - REVISED INSPECTION SCHEDULE OF THE FRONT BEARING CHAMBER (FBC) MCD AND MANAGEMENT OF POTENTIAL NON-CONFORMING HIGH PRESSURE (HP) COMPRESSOR NO.3 BEARING ASSEMBLIES - NON-MODIFICATION, SERVICE BULLETIN FOR THE REMOVAL OF POTENTIALLY AFFECTED HIGH PRESSURE (HP) COMPRESSOR NO.3 BEARING ASSEMBLIES FROM SERVICE					RECOMMENDED	NOT APPLICABLE
05-AUG-2013		MOS HRS/MSC - ENC					
SB BR700-79-900541 R01	NO. 1 ENGINE - OIL - GENERAL - SAMPLING OF THE ENGINE OIL SYSTEM, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - DUE TO NO LOSS OF OIL AT PRV
11-JAN-2012		MOS HRS/MSC - ENC		24-APR-2014 4.7 5			
SB BR700-80-100077	NO. 1 ENGINE - STARTING - AIR TURBINE STARTER - REPLACEMENT OF OUTPUT SHAFT ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
19-FEB-1998		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-80-100470	NO. 1 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A DUAL-PLANE BALANCED TURBINE WHEEL AND A REVISED METHOD OF MAGNETIC CHIP DETECTOR ATTACHMENT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
29-SEP-1998		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-80-100640	NO. 1 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW STANDARD OF AIR TURBINE STARTER UNIT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
11-MAR-1999		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-80-101018 R03	NO. 1 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
05-SEP-2005		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-80-101729	NO. 1 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH MODIFIED TURBINE THRUST BEARING, SEAL AND RETAINING RING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC - ENC		23-SEP-2013			
SB BR700-80-101741	NO. 1 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH MODIFIED OIL FILL PORTS TO IMPROVE THE MAINTENANCE OIL FILL PROCEDURE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC - ENC		23-SEP-2013			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 2 - SB - 22300/DER114							
ASB R03	BR700-72-A101523	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUT-OFF PAWL CARRIER PIVOT PINS MADE FROM A DIFFERENT MATERIAL WITH IMPROVED CORROSION PROTECTION PROPERTIES, ALERT SERVICE BULLETIN				ALERT	NOT APPLICABLE
	10-DEC-2015		MOS HRS/MSC - ENC				
ASB	BR700-72-A900297	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR FAIRINGS - INSPECTION OF THE UPPER LEFT HP COMPRESSOR FAIRING FOR POTENTIAL PROFILE NON-CONFORMANCE AND REPLACEMENT OF NON-CONFORMING UPPER LEFT HP COMPRESSOR FAIRING - NON-MODIFICATION, ALERT SERVICE BULLETIN				ALERT	NOT APPLICABLE
	02-SEP-2013		MOS HRS/MSC - ENC				
ASB	BR700-72-A900298	NO. 2 ENGINE - ENGINE - ENGINE COMBUSTION FAIRINGS - REPLACEMENT OF NON-CONFORMING UPPER LEFT, UPPER RIGHT AND LOWER RIGHT COMBUSTION SECTION FAIRINGS - NON-MODIFICATION, ALERT SERVICE BULLETIN				ALERT	NOT APPLICABLE
			MOS HRS/MSC - ENC				
ASB R01	BR700-72-A900298	NO. 2 ENGINE - ENGINE COMBUSTION FAIRINGS - REPLACEMENT OF NON-CONFORMING UPPER LEFT, UPPER RIGHT AND LOWER RIGHT COMBUSTION SECTION FAIRINGS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN				OPTIONAL	NOT APPLICABLE
	21-MAY-2014		MOS HRS/MSC - ENC				
ASB	BR700-72-A900497	NO. 2 ENGINE - HPT ROTOR DISCS - DECREASE OF TIME LIMITS MANUAL MAXIMUM APPROVED LIVES OF STG 1 & 2 DISCS, ALERT SERVICE BULLETIN				ALERT	COMPLIED WITH - AT MANUFACTURE
	12-FEB-2010		MOS HRS/MSC - ENC	19-AUG-2013 0 0			
ASB R01	BR700-72-A900504	NO. 2 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT, ALERT SERVICE BULLETIN				ALERT	COMPLIED WITH - AT MANUFACTURE
			MOS HRS/MSC - ENC	19-AUG-2013 0 0			
ASB	BR700-72-A900508	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 AND 2 DISCS DUE TO POTENTIAL STEEL INCLUSION - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN					COMPLIED WITH - AT MANUFACTURE
	26-JUL-2012		MOS HRS/MSC - ENC	19-AUG-2013 0 0			
ASB R01	BR700-72-A900508	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 AND 2 DISCS DUE TO POTENTIAL STEEL INCLUSION - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN					NOT APPLICABLE
			MOS HRS/MSC - ENC				



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASB R03 BR700-72-A900509	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN	MOS HRS/MSC - ENC		19-AUG-2013 0 0			NOT APPLICABLE - AT MANUFACTURE
ASB R02 BR700-72-A900556	NO. 2 ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR SPECIAL FLIGHT PROFILE - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN	MOS HRS/MSC - ENC			16-DEC-2014		NOT APPLICABLE
ASB BR700-72-A900584	NO. 2 ENGINE - GENERAL - ENGINE INSTALLATION RESTRICTION AND CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN	MOS HRS/MSC - ENC			31-JAN-2017	(EFF)	- SUPERSEDED
ASB R01 BR700-72-A900584	NO. 2 ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN	MOS HRS/MSC - ENC		06-DEC-2017 683.8 291	05-OCT-2017		COMPLIED WITH - BAS - FLL - COMPLIED WITH PART A.
ASB BR700-72-A900584 R01 PART A	NO. 2 ENGINE - ACCOMPLISH GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN INSTRUCTIONS TO DETERMINE THE EFFECTIVE ENGINE POPULATION	DAYS HRS/MSC - ENC		06-DEC-2017 683.8 291	05-OCT-2017		COMPLIED WITH - BAS - FLL - COMPLIED WITH PART A.
ASB BR700-72-A900584 R01 PART B	NO. 2 ENGINE - ACCOMPLISH GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN INSTRUCTIONS ON HOW TO CALCULATE THE LIVES FOR AFFECTED PARTS ON ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT HAVING BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 STANDARD INCORPORATED	MOS HRS/MSC - ENC			05-OCT-2017	(EFF)	- SUPERSEDED
ASB R02 BR700-72-A900584	NO. 2 ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SB, ALERT SERVICE BULLETIN	MOS HRS/MSC - ENC		23-MAR-2018 746.25 311	22-NOV-2017		COMPLIED WITH - PTS A & B - PENALTY CALCULATION OF 139.8 (140) CYCLES FOR NEW LP DISC CSN = 451 CYC



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASB BR700-72-A900584 R02 PART A	NO. 2 ENGINE - ACCOMPLISH GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SB, ALERT SERVICE BULLETIN INSTRUCTIONS TO DETERMINE THE EFFECTIVE ENGINE POPULATION						COMPLIED WITH - PCW REV 1 PART A DEC 2017 ON BOMBARDIER W.O.206054.
22-NOV-2017		DAYS		10-JAN-2018			
		HRS/MSC	-	707.58			
		ENC		297			
ASB BR700-72-A900584 R02 PART B	NO. 2 ENGINE - ACCOMPLISH GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SB, ALERT SERVICE BULLETIN INSTRUCTIONS ON HOW TO CALCULATE THE LIVES FOR AFFECTED PARTS ON ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT HAVING BOMBARDIER SB700-34-5021 OR SB700-34-6021 STANDARD INCORPORATED						COMPLIED WITH - PTS A & B - PENALTY CALCULATION OF 139.8 (140) CYCLES FOR NEW LP DISC CSN = 451 CYC
22-NOV-2017		MOS		23-MAR-2018			
		HRS/MSC	-	746.25			
		ENC		311			
ASB BR700-72-A900659	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN						NOT APPLICABLE
22-JUL-2019		MOS					
		HRS/MSC	-				
		ENC					
ASB BR700-72-A900659 PART A	NO. 2 ENGINE - ACCOMPLISH HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN REMOVAL OF THE ENGINE FOR INCORPORATION OF PART B OF THIS NON-MODIFICATION SERVICE BULLETIN						NOT APPLICABLE
22-JUL-2019		MOS					
		HRS/MSC	-				
		ENC					
ASB BR700-72-A900659 PART B	NO. 2 ENGINE - ACCOMPLISH HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN REPLACEMENT OF HIGH PRESSURE (HP) TURBINE STAGE 1 DISCS						NOT APPLICABLE
22-JUL-2019		MOS					
		HRS/MSC	-				
		ENC					
ASB BR700-72-A900659 R01	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN					ALERT	NOT APPLICABLE
05-NOV-2019		MOS					
		HRS/MSC	-				
		ENC					
ASB BR700-72-A900659 R01 PART A	NO. 2 ENGINE - ACCOMPLISH HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN REMOVAL OF THE ENGINE FOR INCORPORATION OF PART B OF THIS NON-MODIFICATION SERVICE BULLETIN						NOT APPLICABLE
05-NOV-2019		MOS		27-AUG-2021			
		HRS/MSC	-	1012.88			
		ENC		430			
ASB BR700-72-A900659 R01 PART B	NO. 2 ENGINE - ACCOMPLISH HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN REPLACEMENT OF HIGH PRESSURE (HP) TURBINE STAGE 1 DISCS						NOT APPLICABLE
05-NOV-2019		MOS		27-AUG-2021			
		HRS/MSC	-	1012.88			
		ENC		430			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASB R02	BR700-73-A101977 NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW EEC FIREBOX ASSEMBLY WITH A REVISED PAINT SYSTEM, ALERT SERVICE BULLETIN	MOS				ALERT	- SUPERSEDED
	27-MAR-2017	HRS/MSC -					
		ENC					
ASB R03	BR700-73-A101977 NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW EEC FIREBOX ASSEMBLY WITH A REVISED PAINT SYSTEM, ALERT SERVICE BULLETIN	MOS		01-MAY-2019			COMPLIED WITH
	10-JUL-2017	HRS/MSC -		879.42			
		ENC		365			
ASB	BR700-73-A900083 NO. 2 ENGINE - ENGINE FUEL AND CONTROL ENGINE ELECTRONIC CONTROLLER (EEC) - REPLACEMENT OF NON-CONFORMING PARTS OF THE EEC FIREBOX ASSEMBLY - NON-MODIFICATION, ALERT SERVICE BULLETIN	MOS				ALERT	NOT APPLICABLE
	09-MAR-2015	HRS/MSC -					
		ENC					
ASB R01	BR700-73-A900083 NO. 2 ENGINE - ENGINE FUEL AND CONTROL ENGINE ELECTRONIC CONTROLLER (EEC) - REPLACEMENT OF NON-CONFORMING PARTS OF THE EEC FIREBOX ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN	MOS				ALERT	NOT APPLICABLE
	22-MAR-2017	HRS/MSC -					
		ENC					
ASB R02	BR700-73-A900083 NO. 2 ENGINE - ENGINE FUEL AND CONTROL ENGINE ELECTRONIC CONTROLLER (EEC) - REPLACEMENT OF NON-CONFORMING PARTS OF THE EEC FIREBOX ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN	MOS				ALERT	NOT APPLICABLE
	14-DEC-2018	HRS/MSC -					
		ENC					
ASB	BR700-73-A900451 NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL METERING UNIT (FMU) - COMBINED OVERSPEED SHUTOFF SOLENOID (COSS) SCREENING FOR REVERSE WIRED INDEPENDENT OVERSPEED PROTECTION (IOP) COILS, ALERT SERVICE BULLETIN	MOS		19-AUG-2013		ALERT	NOT APPLICABLE
		HRS/MSC -		0			
		ENC		0			
SB	BR700-24-100166 R01 NO. 2 ENGINE - ELECTRICAL POWER - VARIABLE FREQUENCY GENERATOR OIL TRANSFER TUBES AND FITTINGS - REVISED OIL TRANSFER TUBE SELF LOCKING NUT TIGHTENING TORQUE, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
	01-DEC-2000	HRS/MSC -					
		ENC					
SB	BR700-24-100378 NO. 2 ENGINE - ELECTRICAL POWER - ENGINE GENERATOR OIL COOLER - DELETION OF FIRE PROTECTION COVER PLATES, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
	26-APR-1999	HRS/MSC -					
		ENC					
SB	BR700-24-100384 NO. 2 ENGINE - POWER - ENGINE GENERATOR OIL TRANSFER TUBES AND FITTINGS -INTRODUCTION OF MODIFIED OIL COOLER TO VFG TUBE ASSEMBLY, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
	21-MAY-1999	HRS/MSC -					
		ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-24-100384 R01	NO. 2 ENGINE - ELECTRICAL POWER - ENGINE GENERATOR SURFACE AIR COOLED OIL COOLER (SACOC) TRANSFER TUBES AND FITTINGS - INTRODUCTION OF A MODIFIED SACOC TO VARIABLE FREQUENCY GENERATOR (VFG) OIL TUBE, SERVICE BULLETIN	MOS				OPTIONAL	NOT APPLICABLE
08-JUL-2014		HRS/MSC -					
		ENC					
SB BR700-24-100472	NO. 2 ENGINE - POWER - ENGINE GENERATOR OIL COOLER - DELETION OF THE THERMOSTATIC CONTROL VALVE OF THE SURFACE AIR COOLED OIL COOLER AND ASSOCIATED DRESSINGS CHANGES, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
24-JAN-2002		HRS/MSC -					
		ENC					
SB BR700-24-100961 R01	NO. 2 ENGINE - ELECTRICAL POWER - ENGINE GENERATOR OIL COOLER - INTRODUCTION OF A NEW BUILD INSTRUCTION FOR THE FIRE SHIELDS OF THE OIL COOLER, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-APR-2001		HRS/MSC -					
		ENC					
SB BR700-24-101483	NO. 2 ENGINE - ELECTRICAL POWER - ENGINE GENERATOR OIL COOLER - INTRODUCTION OF NEW SURFACE AIR COOLED OIL COOLERS (SACOC), SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-FEB-2005		HRS/MSC -					
		ENC					
SB BR700-26-100396	NO. 2 ENGINE - FIRE PROTECTION - CORE ENGINE FIRE DETECTION SENSORS - INTRODUCTION OF REVISED CORE FIRE WIRE MOUNTING BRACKETS, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-APR-1999		HRS/MSC -					
		ENC					
SB BR700-26-100434 R02	NO. 2 ENGINE - FIRE - PROTECTION - CORE ENGINE NOZZLE, TUBES AND FITTINGS - INTRODUCTION OF MODIFIED ZONE 2 TUBES AND ADDITIONAL CLIPPING, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
31-JUL-2002		HRS/MSC -					
		ENC					
SB BR700-26-100466	NO. 2 ENGINE - FIRE PROTECTION - ELECTRICAL HARNESSSES - INTRODUCTION OF CLIPPING POSITION CHANGES TO SUIT MODIFIED FIRE EXTINGUISHER SYSTEM, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
03-SEP-1998		HRS/MSC -					
		ENC					
SB BR700-36-100142 R01	NO. 2 ENGINE - PNEUMATIC - CABIN AIR DUCTS - INTRODUCTION OF A REVISED HP5 CABIN AIR DUCT ASSEMBLY, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
25-JAN-2001		HRS/MSC -					
		ENC					
SB BR700-71-100058	NO. 2 ENGINE - POWER PLANT - THRUST REVERSER UNIT (TRU) AND GENERAL SERVICES HARNESS ATTACHMENT FITTINGS - INTRODUCTION OF REVISED CLIPPING POINTS, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
29-APR-1998		HRS/MSC -					
		ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-71-100161	NO. 2 ENGINE - POWER PLANT - RIGHT ENGINE HARNESS ATTACH FITTINGS - INTRODUCTION OF RE-ROUTED HARNESSES AND REPLACEMENT OF RELATED CLIPPING POINTS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
24-JAN-1998		MOS		19-AUG-2013			
		HRS/MSC	-				
		ENC					
SB BR700-71-100177	NO. 2 ENGINE - POWER PLANT - ELECTRICAL HARNESSES - INTRODUCTION OF ENGINE BUILD UP (EBU) EXTENSION CLIPS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
20-SEP-1997		MOS		19-AUG-2013			
		HRS/MSC	-				
		ENC					
SB BR700-71-100180	NO. 2 ENGINE - POWER PLANT - RIGHT ENGINE HARNESS ATTACH FITTINGS - INTRODUCTION OF RE-ROUTED TRU HARNESS AND RELATED CLIPPING POINTS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		MOS		19-AUG-2013			
		HRS/MSC	-				
		ENC					
SB BR700-71-100211	NO. 2 ENGINE - POWER PLANT - DRAINS TANK EJECTOR - INTRODUCTION OF REVISED MATERIAL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		MOS		19-AUG-2013			
		HRS/MSC	-				
		ENC					
SB BR700-71-100242 R01	NO. 2 ENGINE - POWER PLANT - MINOR PODDING MODIFICATIONS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
22-OCT-1999		MOS		19-AUG-2013			
		HRS/MSC	-				
		ENC					
SB BR700-71-100259	NO. 2 ENGINE - POWER PLANT - ADDITIONAL ACOC DELETION DRESSING MODIFICATIONS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
24-JAN-1998		MOS		19-AUG-2013			
		HRS/MSC	-				
		ENC					
SB BR700-71-100298 R02	NO. 2 ENGINE - POWER PLANT - ADDITIONAL PRODUCTION ACOC DELETION DRESSING MODIFICATIONS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS		19-AUG-2013			
		HRS/MSC	-				
		ENC					
SB BR700-71-100340	NO. 2 ENGINE - POWER PLANT - GEARBOX MOUNTED EBU BRACKETS - TRANSFER OF OWNERSHIP, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		MOS		19-AUG-2013			
		HRS/MSC	-				
		ENC					
SB BR700-71-100341	NO. 2 ENGINE - POWER PLANT - VARIOUS - ADDITIONAL HARNESS CLIPPING MODIFICATIONS (NEUTRAL AND RIGHT HAND), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-MAR-1998		MOS		19-AUG-2013			
		HRS/MSC	-				
		ENC					
SB BR700-71-100351	NO. 2 ENGINE - POWER PLANT - GEARBOX MOUNTED EBU BRACKETS - INTRODUCTION OF SHORTER BOLTS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-MAR-1998		MOS		19-AUG-2013			
		HRS/MSC	-				
		ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-71-100426 R01	NO. 2 ENGINE - POWER PLANT - CORE/EXTERNAL DRAINS TUBES AND FITTINGS - INTRODUCTION OF REVISED CLEARANCES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-OCT-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-71-100427 R01	NO. 2 ENGINE - POWER PLANT - EEC LANE A HARNESS 1A - RE-ORIENTATION OF HARNESS CONNECTOR BACKSHELLS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
26-APR-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-71-100428 R01	NO. 2 ENGINE - POWER PLANT - EEC LANE B HARNESS 1D - RE-ORIENTATION OF HARNESS CONNECTOR BACKSHELLS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
26-APR-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-71-100429 R01	NO. 2 ENGINE - POWER PLANT - EEC LANE B HARNESS 1E - RE-ORIENTATION OF HARNESS CONNECTOR BACKSHELLS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
26-APR-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-71-100476	NO. 2 ENGINE - POWER PLANT - ELECTRICAL HARNESSES - REROUTING OF HARNESS LOOMS TO CLEAR BYPASS DUCT ACCESS PANEL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
17-SEP-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-71-100488	NO. 2 ENGINE - POWER PLANT - EEC LANES A AND B HARNESSES - INTRODUCTION OF REVISED CLIPPING POINTS CP10022 AND CP10029, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-APR-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-71-100500	NO. 2 ENGINE - POWER PLANT - ELECTRICAL HARNESSES - INTRODUCTION OF MINOR ASSOCIATED DRESSING CHANGES FOR THE EEC TROUGH DELETION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
25-SEP-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-71-100530	NO. 2 ENGINE - POWER PLANT - EXTERNAL DRAIN TUBES AND FITTINGS - INTRODUCTION OF A CHANGE OF OWNERSHIP (INSTALLATION RESPONSIBILITY) FOR THE WET DRAINS BRACKETS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
26-APR-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-71-100585 R01	NO. 2 ENGINE - POWER PLANT - EEC LANE A HARNESS 1C - INTRODUCTION OF MODIFIED CLIPPING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS HRS/MSC - ENC		19-AUG-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-71-100595 R01	NO. 2 ENGINE - POWER PLANT - GEARBOX MOUNTED EBU BRACKETS - INTRODUCTION OF REVISED LENGTH BOLTS TO ACCOMMODATE NEW STANDARD OF ACCESSORY GEARBOX MAIN HOUSING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-JUN-2005		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-71-100602	NO. 2 ENGINE - POWER PLANT - FRONT SUSPENSION-ENGINE MOUNTED - INTRODUCTION OF THRUST TRUNNION FLANGE BOLTS WITH A THINNER HEAD, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
03-AUG-2016		MOS					
		HRS/MSC -					
		ENC					
SB BR700-71-100680 R02	NO. 2 ENGINE - POWER PLANT - GEARBOX MOUNTED ENGINE BUILD UNIT (EBU) BRACKETS - INTRODUCTION OF REVISED FIRERAIL SUPPORT BRACKET, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
15-NOV-2000		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-71-100892	NO. 2 ENGINE - POWER PLANT - LEFT AND RIGHT ENGINE EEC LANE A HARNESS 1C AND LANE B HARNESS 1F - INTRODUCTION OF ELECTRONIC ENGINE CONTROLLER (EEC) HARNESSES WITH A RESISTOR IN THE ELECTRICAL SUPPLY LINE TO THE STARTER AIR VALVE (SAV) SOLENOID, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
13-OCT-1999		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-71-101465	NO. 2 ENGINE - POWER PLANT - GENERAL - INTRODUCTION OF A NEW EXTENSION CLIP WITH A SIMPLIFIED DESIGN, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
27-JAN-2006		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-71-101581	NO. 2 ENGINE - INTRODUCTION OF AN OIL DRAIN TUBE SUPPORT BRACKET WITH A SLOTTED HOLE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
13-SEP-2007		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-71-101603	NO. 2 ENGINE - POWER PLANT - ENGINE ELECTRONIC CONTROLLER (EEC) LANE A HARNESS 1A - CLIP POSITION CHANGES FOR THE OIL LEVEL SENSOR CABLE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-FEB-2008		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-71-101830 R01	NO. 2 ENGINE - POWER PLANT - LEFT AND RIGHT FIXED COWL - INTRODUCTION OF A DRAINAGE HOLE WITHIN THE FRONT MOUNT ACCESS PANEL AND THE FIXED COWL ASSEMBLIES TO PREVENT CORROSION OF THE ENGINE FRONT MOUNT ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
06-SEP-2013		MOS		23-APR-2014			
		HRS/MSC -		6.4			
		ENC					
SB BR700-71-900675	NO. 2 ENGINE - POWER PLANT - GENERAL - ENGINE CONVERSION FROM A FLIGHT-TEST STANDARD ENGINE TO A PRODUCTION STANDARD ENGINE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
30-JAN-2020		MOS					
		HRS/MSC -					
		ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100025 R02	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF HPC FRONT SPLIT CASING WITH INCREASED CAST BOSS DIAMETERS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100044 R03	NO. 2 ENGINE - ENGINE - HP COMPRESSOR (HPC) - INTRODUCTION OF VARIABLE STATOR VANES SOLID TIE RODS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-JAN-2012		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100109	NO. 2 ENGINE - ENGINE - HP COMPRESSOR (HPC) - INTRODUCTION OF VARIABLE STATOR VANES SOLID TIE RODS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-AUG-1997		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100110 R02	NO. 2 ENGINE - ENGINE - HP TURBINE - INTRODUCTION OF SILVER PLATING TREATMENT TO THREAD AND FLANK OF INTRASCOPE HOUSING BLANKING PLUG, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
06-JUL-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100138	NO. 2 ENGINE - ENGINE - LPC STATOR VANES - INTRODUCTION OF NEW LP COMPRESSOR STATOR VANE ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-OCT-1997		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100149	NO. 2 ENGINE - ENGINE - DRESSING AND NON DRESSING - MINOR ALTERATIONS, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
05-JUN-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100150	NO. 2 ENGINE - ENGINE - FAIRING, INTAKE ROTATING - LP COMPRESSOR - INTRODUCTION OF A LIGHTWEIGHT LP COMPRESSOR NOSECONE FAIRING ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-SEP-1997		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100152 R01	NO. 2 ENGINE - ENGINE - ENGINE MOUNTING SUPPORT - INTRODUCTION OF A NEW REAR MOUNT RING ASSEMBLY WITH REDUCED WEIGHT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-NOV-1997		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100157	NO. 2 ENGINE - ENGINE - LP COMPRESSOR BLADES - INTRODUCTION OF LIGHTWEIGHT LP COMPRESSOR DISK SEALING PLATE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-SEP-1997		MOS HRS/MSC - ENC		19-AUG-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100158 R01	NO. 2 ENGINE - ENGINE - VANES, STATOR, EXIT GUIDE - LP COMPRESSOR - INTRODUCTION OF CAST ALUMINUM OUTLET GUIDE VANE ASSEMBLY WITH POTTED OUTER END AND DAMPED INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
14-SEP-2000		HRS/MSC - ENC					
SB BR700-72-100159 R01	NO. 2 ENGINE - ENGINE - HP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED HP 1 NOZZLE GUIDE VANES, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-JUL-1998		HRS/MSC - ENC					
SB BR700-72-100162	NO. 2 ENGINE - ENGINE - DISC, ROTOR - LP COMPRESSOR - INTRODUCTION OF A REDUCED WEIGHT ROTOR DISC WITH RE-PROFILED DOVETAIL SLOT, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-OCT-1999		HRS/MSC - ENC					
SB BR700-72-100164 R01	NO. 2 ENGINE - ENGINE - CASE AND FITTINGS - COMPRESSOR INTERMEDIATE (LP TO IP/HP) - INTRODUCTION OF ENGINE VIBRATION MONITOR TRANSDUCER MOUNTING PLATE, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		HRS/MSC - ENC					
SB BR700-72-100172 R02	NO. 2 ENGINE - ENGINE - HPC REAR INNER CASE - INTRODUCTION OF A NEW ABRADABLE LINING MATERIAL ON THE ROTOR PATH LINERS OF HPC STAGE 5, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-AUG-2003		HRS/MSC - ENC					
SB BR700-72-100178	NO. 2 ENGINE - ENGINE - ATTACHING PARTS AND FITTINGS - BYPASS DUCT MODULE - REVISED ENGINE BUILD-UP (EBU) FLANGE BRACKETS, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-JUL-1998		HRS/MSC - ENC					
SB BR700-72-100186	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF VARIOUS IMPROVEMENTS TO THE GEARBOX ASSEMBLY, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
05-MAR-1998		HRS/MSC - ENC					
SB BR700-72-100194 R01	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF REDUCED STAGE 4 TO 10 PLATFORM GAPS, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
16-JUL-1998		HRS/MSC - ENC					
SB BR700-72-100195	NO. 2 ENGINE - ENGINE - COMBUSTION AND HP TURBINE - FIRE DETECTOR AND OVERHEAT PROBE PROTECTOR TUBES - REVISED LOCATION FEATURE, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
31-MAY-1997		HRS/MSC - ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100200 R02	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - FRONT BEARING AND SUPPORT - INTRODUCTION OF AN ALTERNATIVE NO. 3 BEARING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100202 R01	NO. 2 ENGINE - ENGINE - EXTERNALS - MINOR ENGINEERING MODIFICATIONS, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
21-JUN-2000		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100205	NO. 2 ENGINE - ENGINE - HP COMPRESSOR (HPC) - INTRODUCTION OF STAGE 7/8 HEATSHIELD WITH REDUCED CIRCUMFERENTIAL GAP, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
17-MAY-1997		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100207 R02	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF A TUBED VORTEX REDUCER AND A MODIFIED STAGE 7 TO 10 ROTOR ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100207 R03	NO. 2 ENGINE - HP COMPRESSOR - INTRODUCTION OF A TUBED VORTEX REDUCER AND A MODIFIED STAGE 7 TO 10 ROTOR ASSEMBLY, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
17-SEP-2015		MOS HRS/MSC - ENC					
SB BR700-72-100226	NO. 2 ENGINE - ENGINE - REPLACEMENT, DELETION OR INTRODUCTION OF NEW INSTRUCTIONS AND ARRANGEMENTS TO AMEND THE DIS10005., SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100229	NO. 2 ENGINE - ENGINE - SHAFT, ROTOR - LP TURBINE - INTRODUCTION OF LP TURBINE SHAFT IN SUPER S/CMV MATERIAL WITH REPROFILED INTERNAL BORE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-APR-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100233	NO. 2 ENGINE - ENGINE - RING, BLADE RETAINING - LP COMPRESSOR - INTRODUCTION OF A LIGHTWIGHT RETAINING RING ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-SEP-1997		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100241	NO. 2 ENGINE - ENGINE - BYPASS DUCT - INTRODUCTION OF INTRASCOPE BLANK EXTRACTION FEATURE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
19-MAR-1998		MOS HRS/MSC - ENC		19-AUG-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100263	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF A SLEEVE IN THE PRESSURE RELIEF VALVE BORE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-AUG-1997		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100263 R01	NO. 2 ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF A SLEEVE IN THE PRESSURE RELIEF VALVE (PRV) HOUSING BORE OF THE ACCESSORY GEARBOX MAIN HOUSING ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
19-JAN-2016		MOS HRS/MSC - ENC					
SB BR700-72-100265 R03	NO. 2 ENGINE - ENGINE - TURBINE AND REAR SUPPORT - INTRODUCTION OF REVISED FUEL SHUT OFF CABLE SETTING INSTRUCTION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100266	NO. 2 ENGINE - ENGINE - TURBINE AND REAR SUPPORT - INTRODUCTION OF REVISED LPT EXHAUST CASE FUEL SHUT OFF EXIT RADIUS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
06-JUN-1997		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100266 R01	NO. 2 ENGINE - TURBINE AND REAR SUPPORT - INTRODUCTION OF REVISED LOW PRESSURE (LP) TURBINE EXHAUST CASE FUEL SHUT-OFF EXIT RADIUS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
08-DEC-2014		MOS HRS/MSC - ENC					
SB BR700-72-100267	NO. 2 ENGINE - ENGINE - INTRODUCTION OF ADDITIONAL CLIPPING AMENDMENTS DUE TO PODDING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
06-APR-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100268	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF SILVER COATED STAGE 1, 3 AND 5 INTRASCOPE PLUGS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
07-FEB-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100280	NO. 2 ENGINE - ENGINE - EXHAUST CASE - INTRODUCTION OF WEIGHT REDUCED LP TURBINE OUTLET GUIDE VANE (OGV) AND DOUBLE ENDED UNIONS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100281	NO. 2 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED COMBUSTION CHAMBER INNER CASE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		MOS HRS/MSC - ENC		19-AUG-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100284 R01	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF REDUCED WEIGHT HP COMPRESSOR REAR OUTER CASE AND REVISED INTRASCOPE HOUSINGS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
19-DEC-2000		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100290	NO. 2 ENGINE - ENGINE - BYPASS SERVICES FAIRING - MINOR CONFIGURATION AMENDMENTS, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
16-JUL-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100291	NO. 2 ENGINE - ENGINE - VARIOUS - ADDITIONAL DRESSING MODIFICATIONS RELATING TO THE DELETION OF THE AIR COOLED OIL COOLER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
02-JUN-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100296 R01	NO. 2 ENGINE - ENGINE - SUPPORT, BEARING FRONT - LOW PRESSURE (LP) COMPRESSOR/DRIVEN ASSEMBLY - INTERNAL GEARBOX DRIVE - INTRODUCTION OF REVISED NO.1 AND NO.2 BEARING SUPPORT HOUSINGS AND ASSOCIATED COMPONENTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-JAN-2009		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100299 R01	NO. 2 ENGINE - ENGINE - BYPASS DUCT, ELECTRICAL HARNESSSES AND ELECTRONIC ENGINE CONTROLLER (EEC) - DELETION OF EEC TROUGH AND INTRODUCTION OF EEC FIRE BOX AND ASSOCIATED MODIFICATIONS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100301	NO. 2 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED STAGE 1 DISC, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100302 R01	NO. 2 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED STAGE 2 DISC, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100303	NO. 2 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED REAR HEATSHIELD ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-JAN-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100304	NO. 2 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED HP TURBINE CASE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-MAR-1998		MOS HRS/MSC - ENC		19-AUG-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100311	NO. 2 ENGINE - ENGINE - CASE LP COMPRESSOR - INTRODUCTION OF LP COMPRESSOR CASE ASSEMBLY WITH INCREASED THICKNESS FAN TRACK LINER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
06-APR-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100319	NO. 2 ENGINE - ENGINE - HP COMPRESSOR (HPC) - INTRODUCTION OF STAGE 6 BLADES WHICH INCORPORATE A FORGED PLATFORM RAMP, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
03-DEC-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100320	NO. 2 ENGINE - ENGINE - LP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED LP 1 BLADE DAMPERS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
02-JUN-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100322	NO. 2 ENGINE - ENGINE - MANIFOLD, IMPINGEMENT COOLING - HP TURBINE - ADDITIONAL LOAD SPREADING STRIPS ON THE FRONT AND REAR MOUNTING BRACKET SECURING FEATURES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
18-DEC-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100333	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF STAGE 10 BLADES WITH INCREASED PLATFORM WIDTH, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100336	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF STAGE 9 BLADES WITH INCREASED PLATFORM WIDTH AND ROOT DEPTH, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-JUN-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100337	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF STAGE 8 BLADES WITH INCREASED PLATFORM WIDTH AND ROOT DEPTH, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-MAR-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100346	NO. 2 ENGINE - ENGINE -HIGH PRESSURE (HP) COMPRESSOR - INTRODUCTION OF VARIABLE VANE INNER SHROUD BUSHES WITH REVISED TOLERANCES ON INNER AND OUTER DIAMETERS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
02-JUN-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100347	NO. 2 ENGINE - ENGINE - EXHAUST CASE - INTRODUCTION OF AN LP TURBINE OUTLET GUIDE VANE (OGV) ASSEMBLY WITH MODIFIED STAGE 2 SHROUD RETENTION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS HRS/MSC - ENC		19-AUG-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100353	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF ALUMINUM ALLOY UNISON RING CENTRALIZERS FOR WEIGHT REDUCTION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100362	NO. 2 ENGINE - ENGINE - INTERMEDIATE CASE MODULE - INTRODUCTION OF A NEW LOW PRESSURE SHAFT SPEED PROBE WITHOUT FUSE WIRES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-MAR-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100373	NO. 2 ENGINE - ENGINE - COMBUSTION AND HP TURBINE - INTRODUCTION OF A REAR BEARING SUPPORT STRUCTURE (RBSS) BEARING BORE OFFSET, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-NOV-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100380 R01	NO. 2 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - INTRODUCTION OF A WEIGHT REDUCED COMBUSTION CHAMBER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-SEP-2005		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100381	NO. 2 ENGINE - ENGINE - EEC LANE A HARNESS 2A - INTRODUCTION OF A REVISED HARNESS LENGTH, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100382 R01	NO. 2 ENGINE - ENGINE - LP TURBINE - INTRODUCTION OF WEIGHT REDUCED LP TURBINE STAGE 1 SHROUD SEGMENTS AND WEIGHT REDUCED LP TURBINE CASE WITH IMPROVED SURFACE PROTECTION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100383	NO. 2 ENGINE - ENGINE - HP TURBINE - INTRODUCTION OF WEIGHT-REDUCED HP TURBINE STAGE 2 NOZZLE GUIDE VANES WITH REVISED COOLING AIR FLOW CHARACTERISTICS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
25-NOV-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100387	NO. 2 ENGINE - ENGINE - HP COMPRESSOR MODULE - DELETION OF WASHERS ON FLANGE CB, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-JUN-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100393	NO. 2 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE ATTACHING PARTS AND FITTINGS - INTRODUCTION OF BRACKETS MADE OF INCO 718 MATERIAL, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS HRS/MSC - ENC		19-AUG-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100401	NO. 2 ENGINE - ENGINE - LP COMPRESSOR (FAN) MODULE - ATTACH PARTS AND FITTINGS - INTRODUCTION OF A REVISED LP COMPRESSOR ANTI-SCORE RING IN CORROSION RESISTANT STEEL, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-JUN-1998		HRS/MSC - ENC					
SB BR700-72-100405	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE AND ENGINE MOUNTING SUPPORT - MINOR AMENDMENTS TO BRING THE CONFIGURATION DATABASE IN LINE WITH THE ENGINES AS BUILT, SERVICE BULLETIN	MOS		19-AUG-2013		INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		HRS/MSC - ENC					
SB BR700-72-100408	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF A NEW VANE TIP GRINDING AND ROTOR PATH MACHINING INSTRUCTION, SERVICE BULLETIN	MOS		19-AUG-2013		INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		HRS/MSC - ENC					
SB BR700-72-100411	NO. 2 ENGINE - ENGINE - ATTACHING PARTS AND FITTINGS - INTRODUCTION OF WEIGHT REDUCED EBU BRACKETS, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-MAR-2000		HRS/MSC - ENC					
SB BR700-72-100419 R01	NO. 2 ENGINE - ENGINE - LP COMPRESSOR BLADES - INTRODUCTION OF FAN ANNULUS FILLERS WITH POSITIVE BUSH LOCATION AND REVISED SEALING STRIPS, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-DEC-2001		HRS/MSC - ENC					
SB BR700-72-100433 R02	NO. 2 ENGINE - ENGINE - CASE AND FITTINGS - COMPRESSOR INTERMEDIATE (LP TO IP/HP) - INTRODUCTION OF REVISED CASE WITH MODIFIED EARTHING BRACKETS, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
11-JAN-1999		HRS/MSC - ENC					
SB BR700-72-100461 R01	NO. 2 ENGINE - ENGINE - LP COMPRESSOR - INTRODUCTION OF LP COMPRESSOR BLADES WITH REVISED TRAILING EDGE, MOMENT LIMITS AND DEFINITION OF FREQUENCY LIMITS, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-DEC-2001		HRS/MSC - ENC					
SB BR700-72-100463	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF OIL-FILLING INSTRUCTION LABELS, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		HRS/MSC - ENC					
SB BR700-72-100475 R02	NO. 2 ENGINE - ENGINE - HP COMPRESSOR MODULE - INTRODUCTION OF NEW VANES ON THE HPC STAGES 6 TO 9, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
03-APR-2003		HRS/MSC - ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100494	NO. 2 ENGINE - ENGINE - BYPASS DUCT - INTRODUCTION OF A PRESSURE RECOVERY DEVICE IN THE PRECOOLER FAN AIR FLOW LINE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
09-SEP-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100506	NO. 2 ENGINE - ENGINE - LP COMPRESSOR CASE - INTRODUCTION OF A REVISED STARTER EFFLUX SHIELD WITH EDGE PROTECTION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
25-JAN-2000		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100544 R01	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF A MOUNT KIT WITH IMPROVED PROTECTION AND DELETION OF THE BREATHER COVER INSTRUMENTATION BOSS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
05-AUG-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100563	NO. 2 ENGINE - ENGINE - LP/HP TURBINE SUPPORT AND OUTER BEARINGS - INTRODUCTION OF STAGE 4 AIR TUBES AND REAR BEARING SUPPORT STRUCTURE WITH INCREASED CONTACT AREA, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100563 R01	NO. 2 ENGINE - LP/HP TURBINE SUPPORT AND OUTER BEARINGS - INTRODUCTION OF STAGE 4 AIR TUBES AND REAR BEARING SUPPORT STRUCTURE (RBSS) WITH INCREASED CONTACT AREA, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS HRS/MSC - ENC					
SB BR700-72-100564 R01	NO. 2 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - REMOVAL OF INSULATION STRIPS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-MAY-2001		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100566 R02	NO. 2 ENGINE - ENGINE - HPC REAR INNER CASE - INTRODUCTION OF A NEW ABRADABLE LINING MATERIAL ON THE ROTOR PATH LINERS OF HPC STAGE 6, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-AUG-2003		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100600 R01	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF A NEW STANDARD OF MAIN HOUSING AND ASSOCIATED ASSEMBLY IMPROVEMENTS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-JUN-2005		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100621	NO. 2 ENGINE - ENGINE - HP COMPRESSOR VARIABLE INLET GUIDE VANE ACTUATING MECHANISM - INTRODUCTION OF REDUCED LENGTH VARIABLE STATOR VANE ACTUATOR (VSVA) BRACKET CONNECTING DOWELS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS HRS/MSC - ENC		19-AUG-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100623	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF REDUCED WEIGHT HP COMPRESSOR STAGE 1 TO 6 ROTOR DISKS ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100635	NO. 2 ENGINE - ENGINE - HP COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) RINGS AND SEALS - INTRODUCTION OF A NEW VIGV INNER SHROUD, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-DEC-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100643	NO. 2 ENGINE - ENGINE - INTERMEDIATE CASE MODULE ATTACHING PARTS AND FITTINGS - INTRODUCTION OF REVISED FASTENERS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100671	NO. 2 ENGINE - ENGINE - HPT BLADES - INTRODUCTION OF HP TURBINE STAGE 2 BLADE DAMPERS WHICH ARE MANUFACTURED AS A PRECISION CASTING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-OCT-2000		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100681 R01	NO. 2 ENGINE - ENGINE - LP COMPRESSOR INTAKE ROTATING FAIRING - INTRODUCTION OF REVISED NOSE CONE ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-OCT-2001		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100686	NO. 2 ENGINE - ENGINE - NL SPEED PROBE HARNESS AND ACCESSORIES - REDUCED NUMBER OF SPEED PROBE WASHERS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100704	NO. 2 ENGINE - ENGINE - COMBUSTION INNER CASE AND VANES - INTRODUCTION OF COMPRESSOR OUTLET GUIDE VANES (OGV)/DIFFUSER CASE WITH IMPROVED AIR FLOW CHARACTERISTICS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100712	NO. 2 ENGINE - ENGINE - HPC VIGV ACTUATING MECHANISM - INTRODUCTION OF NEW HP COMPRESSOR VSV SYSTEM DRIVE BRACKETS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
16-DEC-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100720 R01	NO. 2 ENGINE - ENGINE - HP COMPRESSOR BLADES - INTRODUCTION OF REVISED STAGES 6 TO 10 BLADE PLATFORM GAPS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-MAY-2001		MOS HRS/MSC - ENC		19-AUG-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100733	NO. 2 ENGINE - ENGINE - LPC FRONT AND REAR (NO. 1, 2 AND 3) BEARING AND SUPPORT - INTRODUCTION OF ALTERNATIVE SQUEEZE FILM PISTON RINGS., SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
16-DEC-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100770 R01	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF SHOT PEENED GEARS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-AUG-2003		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100785	NO. 2 ENGINE - ENGINE - HP TURBINE - INTRODUCTION OF DECREASED COLD BUILD CLEARANCE ON STAGE 1 HP TURBINE AND DELETION OF DRY FILM LUBRICANT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-MAR-2000		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100805 R01	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF NEW PROCEDURE FOR TIP GRINDING OF HP COMPRESSOR VANES AND IN-SERVICE ROTOR BLADE NUMBERING PROCEDURE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100812	NO. 2 ENGINE - ENGINE - HPC VIGV ACTUATING MECHANISM - INTRODUCTION OF A VIGV UNISON RING WITH IMPROVED CORROSION RESISTANCE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-JAN-2000		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100813	NO. 2 ENGINE - ENGINE - HPC VIGV ACTUATING MECHANISM - INTRODUCTION OF A VSV STAGE 1 UNISON RING WITH IMPROVED CORROSION RESISTANCE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-MAR-2000		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100814	NO. 2 ENGINE - ENGINE - HPC VIGV ACTUATING MECHANISM - INTRODUCTION OF A VSV STAGE 2 UNISON RING WITH IMPROVED CORROSION RESISTANCE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-JAN-2000		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100815	NO. 2 ENGINE - ENGINE - HPC VIGV ACTUATING MECHANISM - INTRODUCTION OF A VSV STAGE 3 UNISON RING WITH IMPROVED CORROSION RESISTANCE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-MAR-2000		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100818	NO. 2 ENGINE - ENGINE - LP COMPRESSOR ROTOR SHAFT - INTRODUCTION OF FAN SHAFT ASSEMBLY WITH REVISED MATERIAL PHONIC WHEEL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-OCT-2000		MOS HRS/MSC - ENC		19-AUG-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100840	NO. 2 ENGINE - ENGINE - HP TURBINE ROTOR DISKS - INTRODUCTION OF A REVISED MANUFACTURING PROCESS FOR HPT STAGE 1 DISKS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100845 R02	NO. 2 ENGINE - ENGINE - NL SPEED PROBE HARNESS AND ACCESSORIES - INTRODUCTION OF A NEW HARNESS ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
16-MAY-2001		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100848	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF AN ACCESSORY GEARBOX WITH ALL GEARS SHOT PEENED ON THE EXTERNAL SURFACES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-JUN-2000		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100851 R02	NO. 2 ENGINE - ENGINE - LP COMPRESSOR (FAN) MODULE - INTRODUCTION OF A COMMON MASTER PART, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
15-FEB-2001		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100852 R02	NO. 2 ENGINE - ENGINE - LP COMPRESSOR CASE MODULE - INTRODUCTION OF A COMMON MASTER PART, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
19-DEC-2000		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100853 R01	NO. 2 ENGINE - ENGINE - LP TURBINE MODULE - INTRODUCTION OF A COMMON MASTER PART, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
09-NOV-2000		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100859	NO. 2 ENGINE - ENGINE - LPC REAR (NO.2) BEARING ASSEMBLY FRONT PANEL - INTRODUCTION OF REVISED MATERIAL SPEED PROBE SUPPORT BRACKET, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
16-DEC-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100865	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF A NEW STANDARD OF INSERT IN THE HAND CRANK FLANGE OF THE BREATHER COVER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-DEC-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100867	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX - CHANGES TO THE CONTOUR OF THE GEARBOX MAIN HOUSING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-NOV-1999		MOS HRS/MSC - ENC		19-AUG-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100879	NO. 2 ENGINE - ENGINE - LP/HP TURBINE STATOR RETAINERS/SEALS - INTRODUCTION OF ABRADABLE LININGS WITH INCREASED CORROSION RESISTANCE, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
22-SEP-2000		HRS/MSC - ENC					
SB BR700-72-100879 R01	NO. 2 ENGINE - LP/HP TURBINE STATOR RETAINERS/SEALS - INTRODUCTION OF ABRADABLE LININGS WITH INCREASED CORROSION RESISTANCE, SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE
		HRS/MSC - ENC					
SB BR700-72-100899 R01	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF THINNER ADJUSTING SHIMS AT BEVEL GEAR LINE 1 AND 2, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-JUN-2003		HRS/MSC - ENC					
SB BR700-72-100900 R01	NO. 2 ENGINE - HP COMPRESSOR AND COMBUSTION FAIRINGS-INTRODUCTION OF NEW FAIRINGS WITH NEW ATTACHMENT FEATURES, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		HRS/MSC - ENC		0 0			
SB BR700-72-100901	NO. 2 ENGINE - ENGINE - HPC ROTOR HYDRAULIC SEAL - INTRODUCTION OF AN HP COMPRESSOR HYDRAULIC SEAL ASSEMBLY WITH INCREASED CLEARANCE BETWEEN THE SEAL AND THE LP TURBINE SHAFT, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-FEB-2001		HRS/MSC - ENC					
SB BR700-72-100902	NO. 2 ENGINE - ENGINE - LPC PHONIC WHEEL - INTRODUCTION OF A REAR INNER BEARING ASSEMBLY WITH INCREASED CLEARANCE BETWEEN THE BEARING INNER RACE AND THE LP TURBINE SHAFT, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-OCT-2000		HRS/MSC - ENC					
SB BR700-72-100903	NO. 2 ENGINE - ENGINE - HP TURBINE ROTOR SHAFT AND (NO 4) BEARING - INTRODUCTION OF ABRADABLE LINING WITH INCREASED CORROSION RESISTANCE, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
28-APR-2000		HRS/MSC - ENC					
SB BR700-72-100913	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF ALTERNATIVE MOUNT WASHERS MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-APR-2000		HRS/MSC - ENC					
SB BR700-72-100944 R03	NO. 2 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE ATTACH PARTS AND FITTINGS - DRESSING CHANGES FOR THE NEW HP COMPRESSOR AND COMBUSTION FAIRINGS, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
18-JAN-2000		HRS/MSC - ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100952 R01	NO. 2 ENGINE - ENGINE - LP TURBINE FAIRINGS - INTRODUCTION OF LP TURBINE FAIRINGS WITH INCREASED WIDTH RELIEF SLOTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-JUL-2002		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100976 R03	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX - INCREASED CLEARANCE BETWEEN THE GENERATOR MAGNETIC SEALS AND THEIR RELATED AIR BLOWN SEALS AND BETWEEN THE ACCESSORY GEARBOX GEAR LINE 6 AND THE HYDRAULIC PUMP SPLINE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
13-SEP-2000		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100978 R01	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF DECREASED COLD BUILD TIP CLEARANCES FOR THE HP COMPRESSOR STAGES 5, 6, 7 AND 9 STATOR VANES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100981 R01	NO. 2 ENGINE - ENGINE - LP COMPRESSOR - CASE - INTRODUCTION OF REVISED FAN TRACK LINER AND ICE IMPACT PANEL ADHESIVE AND FILLER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-JAN-2004		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-100985	NO. 2 ENGINE - ENGINE - HP COMPRESSOR BLADES - REMOVAL OF THE HP COMPRESSOR STAGES 1, 2 AND 3 ROTOR BLADE UNDERPLATFORM STRIP SEALS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-SEP-2000		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101006	NO. 2 ENGINE - ENGINE - COMBUSTION FAIRINGS - INTRODUCTION OF NEW FASTENERS FOR COMBUSTION CENTRE CORE FAIRINGS AND LP TURBINE DIAPHRAGMS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
19-OCT-2001		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101007	NO. 2 ENGINE - ENGINE - HPC FRONT (NO. 3) BEARING SUPPORT - INCREASED CLEARANCE BETWEEN THE NUMBER 2 BEARING HOUSING AND THE NUMBER 3 BEARING RETAINER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
12-JUL-2000		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101019	NO. 2 ENGINE - ENGINE - LPC BEARING SEALS - INTRODUCTION OF NEW INTERNAL GEARBOX FORWARD AIR SEAL PISTON RING SEAL MANUFACTURED BY A NEW SUPPLIER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-MAR-2000		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101020	NO. 2 ENGINE - ENGINE - LPC INTAKE ROTATING FAIRING - INTRODUCTION OF A NEW NOSE CONE FAIRING ASSEMBLY., SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
23-NOV-2001		MOS HRS/MSC - ENC		19-AUG-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101032	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE ATTACH PARTS AND FITTINGS - INTRODUCTION OF A NEW MATERIAL FOR MOUNT BUSHES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
24-JAN-2000		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101037 R01	NO. 2 ENGINE - ENGINE - HPC REAR OUTER CASE - INTRODUCTION OF NEW HP COMPRESSOR STAGE 9 INTRASCOPE PLUG ASSEMBLIES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
04-SEP-2003		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101038	NO. 2 ENGINE - ENGINE - HPC REAR OUTER CASE - INTRODUCTION OF HP COMPRESSOR STAGE 5 INTRASCOPE PLUGS MADE FROM A DIFFERENT MATERIAL AND WITH A DECREASED THREAD DIAMETER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
12-FEB-2001		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101057 R01	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF CHANGES BECAUSE OF A SUPPLIER TRANSFER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
13-JUL-2001		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101060 R01	NO. 2 ENGINE - ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF A NEW ENGINE NAME PLATE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-SEP-2000		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101068	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF DECREASED COLD BUILD TIP CLEARANCES FOR HP COMPRESSOR ROTOR BLADES AND STATOR VANES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-FEB-2002		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101069	NO. 2 ENGINE - ENGINE - HPC VARIABLE INLET GUIDE VANE (VIGV) ACTUATING MECHANISM - INTRODUCTION OF NUT RETAINERS WITH IMPROVED FEATURES FOR EASIER ASSEMBLY OF THE UNISON RINGS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-JUN-2000		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101084 R01	NO. 2 ENGINE - ENGINE - LPC FRONT (NO. 1) BEARING AND SUPPORT - INTRODUCTION OF A NO. 1 BEARING WITH A NEW DIAMETRAL CLEARANCE AND A RADIUSED INNER SPLIT LINE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
26-NOV-2005		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101088	NO. 2 ENGINE - ENGINE - LPC STATOR VANES - INTRODUCTION OF AN ENGINE SECTION STATOR (ESS) WITH A NEW FILLER MATERIAL FOR THE PLATFORM, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-FEB-2002		MOS HRS/MSC - ENC		19-AUG-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101090 R01	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW IDENTIFICATION PLATE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUN-2003		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-72-101091	NO. 2 ENGINE - ENGINE - HPT 1 NGV - INTRODUCTION OF HP TURBINE STAGE 1 NOZZLE GUIDE VANES WITH NEW FILM COOLING HOLE CONFIGURATION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-2000		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-72-101100 R02	NO. 2 ENGINE - ENGINE - HPC ROTOR SHAFT - INTRODUCTION OF A NEW HP COMPRESSOR STUB SHAFT WITH AN IMPROVED BALANCING PROCEDURE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-SEP-2004		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-72-101102	NO. 2 ENGINE - ENGINE - HPC ROTOR REAR DISKS - INTRODUCTION OF A NEW HP COMPRESSOR STAGE 7 TO 10 ROTOR ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
13-JUL-2001		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-72-101103	NO. 2 ENGINE - ENGINE - HPC ROTOR FRONT DISKS - INTRODUCTION OF A NEW HP COMPRESSOR STAGE 1 TO 6 ROTOR ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-JAN-2002		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-72-101107 R01	NO. 2 ENGINE - ENGINE - INTERMEDIATE CASE MODULE - DELETION OF JOINTING COMPOUND ON ENGINE SECTION STATOR (ESS) AND THE INTERNAL GEARBOX (IGB) MATING FACES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-72-101114 R04	NO. 2 ENGINE - ENGINE - BYPASS DUCT - INTRODUCTION OF A BYPASS DUCT WITH NEW INSERTS FOR INSTALLATION OF A FUEL RETURN TO TANK VALVE AND FOR A REPOSITIONED LP FUEL SWITCH, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
14-NOV-2000		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-72-101116	NO. 2 ENGINE - ENGINE - LPC REAR NO.2 BEARING ASSY FRONT PANEL - INTRODUCTION OF NEW O-RINGS WITH A DECREASED INTERNAL DIAMETER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
24-JAN-2001		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-72-101117	NO. 2 ENGINE - ENGINE - HPT BLADES - INTRODUCTION OF HP TURBINE STAGE 1 BLADES WITH A NEW FILM COOLING HOLE CONFIGURATION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-NOV-2001		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101117 R01	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE BLADES - INTRODUCTION OF HP TURBINE STAGE 1 BLADES WITH A NEW FILM COOLING HOLE CONFIGURATION, SERVICE BULLETIN	MOS				OPTIONAL	NOT APPLICABLE
26-SEP-2018		HRS/MSC -					
		ENC					
SB BR700-72-101128 R01	NO. 2 ENGINE - ENGINE - HPT ROTOR SHAFT AND NO. 4 BEARING - INTRODUCTION OF AN HP TURBINE NO. 4 STUB SHAFT WITH IDENTITY MARKINGS PERMITTED ONLY ON THE REAR FACE OF THE SHAFT, SERVICE BULLETIN	MOS		19-AUG-2013		INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
25-MAR-2008		HRS/MSC -					
		ENC					
SB BR700-72-101139 R01	NO. 2 ENGINE - HPC ROTOR SHAFT-INTRODUCTION OF A NEW FITTING INSTRUCTION FOR THE HP COMPRESSOR STUB SHAFT TO ALIGN WITH THE HP COMPRESSOR ROTOR, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
18-DEC-2006		HRS/MSC -					
		ENC					
SB BR700-72-101144	NO. 2 ENGINE - ENGINE - COMBUSTION INNER CASE AND VANES - INTRODUCTION OF A NEW COMBUSTION INNER FRONT CASING, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
24-JUN-2003		HRS/MSC -					
		ENC					
SB BR700-72-101150	NO. 2 ENGINE - ENGINE - NL SPEED PROBES - INTRODUCTION OF LP COMPRESSOR TRIM BALANCE AND SPEED PROBES WHICH ARE MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-DEC-2003		HRS/MSC -					
		ENC					
SB BR700-72-101157	NO. 2 ENGINE - ENGINE - TURBINE EXHAUST SUPPORTS - INTRODUCTION OF NEW REAR MOUNT SUPPORT STRUTS WITH A DIFFERENT COATING, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-MAR-2008		HRS/MSC -					
		ENC					
SB BR700-72-101167	NO. 2 ENGINE - ENGINE - LPC ROTOR SHAFT - INTRODUCTION OF FAN SHAFT BOLTS WITH INCREASED HEAD THICKNESS, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-AUG-2001		HRS/MSC -					
		ENC					
SB BR700-72-101173	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP)/HIGH PRESSURE (HP) TURBINE STATOR RETAINERS/SEALS - INTRODUCTION OF A NEW REAR BEARING SUPPORT STRUCTURE (RBSS) VENT DUCT, REAR HEAT SHIELD AND LP TURBINE SEAL CARRIER WHICH ARE DECREASED IN WEIGHT, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-MAR-2007		HRS/MSC -					
		ENC					
SB BR700-72-101174	NO. 2 ENGINE - ENGINE - COMBUSTION FAIRINGS - INTRODUCTION OF A LEFT HAND LOWER COMBUSTION FAIRING WITH A STRENGTHENED PRESSURE RELIEF DOOR, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-FEB-2003		HRS/MSC -					
		ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101175	NO. 2 ENGINE - ENGINE - LPC EXIT GUIDE STATOR VANES - INTRODUCTION OF A NEW PART NUMBER FOR THE ALUMINIUM OUTLET GUIDE VANE (OGV) ASSEMBLY WITH CHANGED CLASSIFICATION, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
25-JAN-2002		HRS/MSC - ENC					
SB BR700-72-101177 R01	NO. 2 ENGINE - ENGINE - COMBUSTION OUTER CASE - INTRODUCTION OF A NEW COMBUSTION CHAMBER OUTER CASING, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-AUG-2002		HRS/MSC - ENC					
SB BR700-72-101179 R01	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - CHANGES TO OIL DISTRIBUTORS, PLUGS, O-RINGS, INSERTS AND RETAINING RINGS, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-MAY-2004		HRS/MSC - ENC					
SB BR700-72-101180	NO. 2 ENGINE - ENGINE - HPC VIGV AND STAGES 1-4 STATOR VANES - INTRODUCTION OF A NEW VARIABLE INLET GUIDE VANE (VIGV) ASSEMBLY WHICH IS DECREASED IN WEIGHT, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-AUG-2002		HRS/MSC - ENC					
SB BR700-72-101181	NO. 2 ENGINE - ENGINE - HPC VIGV AND STAGES 1 - 4 STATOR VANES - INTRODUCTION OF A NEW STAGE 1 VANE ASSEMBLY WHICH IS DECREASED IN WEIGHT, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-AUG-2002		HRS/MSC - ENC					
SB BR700-72-101190	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF NEW ACCESSORY GEARBOX LINE 1 AND LINE 2 BEVEL GEARS WHICH ARE MANUFACTURED BY A NEW SUPPLIER, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-FEB-2001		HRS/MSC - ENC					
SB BR700-72-101193 R01	NO. 2 ENGINE - ENGINE - HIGH PRESSURE COMPRESSOR (HPC) FRONT CASE - INTRODUCTION OF A NEW HPC FRONT CASE, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
19-JUN-2002		HRS/MSC - ENC					
SB BR700-72-101197	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - DELETION OF THE FIRE SHIELD ASSEMBLY, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-MAR-2001		HRS/MSC - ENC					
SB BR700-72-101197 R01	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - DELETION OF THE FIRE SHIELD ASSEMBLY, SERVICE BULLETIN	MOS				OPTIONAL	NOT APPLICABLE
17-OCT-2014		HRS/MSC - ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101203 R01	NO. 2 ENGINE - ENGINE - HIGH PRESSURE COMPRESSOR (HPC) VARIABLE INLET GUIDE VANES (VIGV) ACTUATING MECHANISM - INTRODUCTION OF NEW HPC LEVERS WITH CHANGED TOLERANCES, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAR-2003		HRS/MSC - ENC					
SB BR700-72-101204	NO. 2 ENGINE - ENGINE - COMBUSTION REAR INNER CASE - INTRODUCTION OF NEW FRONT AND REAR COMBUSTION INNER CASINGS WHICH ARE DECREASED IN WEIGHT, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-JUN-2002		HRS/MSC - ENC					
SB BR700-72-101205	NO. 2 ENGINE - ENGINE - HPT1 NOZZLE GUIDE SEALS - INTRODUCTION OF A NEW PRESWIRL NOZZLE WITH A DECREASED COOLING AIR FLOW TO THE HP 1 TURBINE ROTOR DISC AND BLADES, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
14-MAR-2002		HRS/MSC - ENC					
SB BR700-72-101216	NO. 2 ENGINE - ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF A NEW ENGINE NAME PLATE, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-FEB-2001		HRS/MSC - ENC					
SB BR700-72-101218	NO. 2 ENGINE - ENGINE - LPT FUEL SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUT-OFF MECHANISM PAWLS WHICH HAVE A LARGER SURFACE CONTACT AREA WITH THE FUEL SHUT-OFF REFERENCE TUBE, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
12-APR-2002		HRS/MSC - ENC					
SB BR700-72-101218 R01	NO. 2 ENGINE - LOW PRESSURE (LP) TURBINE FUEL SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUT-OFF MECHANISM PAWLS WHICH HAVE A LARGER SURFACE CONTACT AREA WITH THE FUEL SHUT-OFF REFERENCE TUBE, SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE
03-DEC-2020		HRS/MSC - ENC					
SB BR700-72-101222	NO. 2 ENGINE - ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF NEW BUILD INSTRUCTIONS TO DECREASE HIGH PRESSURE (HP) VIBRATION LEVELS, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-JAN-2009		HRS/MSC - ENC					
SB BR700-72-101223 R02	NO. 2 ENGINE - ENGINE - LPT FUEL SHUT-OFF CABLE AND FITTINGS - INTRODUCTION OF INCREASED CLEARANCES BETWEEN THE FUEL SHUT-OFF CABLE AND ADJACENT DRESSINGS, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
07-MAY-2004		HRS/MSC - ENC					
SB BR700-72-101234 R02	NO. 2 ENGINE - LOW PRESSURE/HIGH PRESSURE (LP/HP) TURBINE SUPPORT AND OUTER BEARINGS - INTRODUCTION OF REWORKED REAR BEARING SUPPORT STRUCTURES (RBSS) OF EARLIER STANDARDS, REWORKED HP AND LP TURBINE BEARING RETAINERS AND NEW STAGE 4 AIR TUBES, SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE
27-MAY-2014		HRS/MSC - ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101246	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR DISC - INTRODUCTION OF A NEW FAN DISC DESIGN FOR LIFE ENHANCEMENT, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
SB BR700-72-101246 R01	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR DISC - INTRODUCTION OF A NEW FAN DISC DESIGN FOR LIFE ENHANCEMENT, SERVICE BULLETIN	MOS HRS/MSC - ENC	28-OCT-2016			OPTIONAL	NOT APPLICABLE
SB BR700-72-101252	NO. 2 ENGINE - ENGINE - COMBUSTION LINER - INTRODUCTION OF A NEW COMBUSTOR HEAT SHIELD, SERVICE BULLETIN	MOS HRS/MSC - ENC	12-APR-2002	19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
SB BR700-72-101254	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF CHANGES TO THE MANUFACTURING PROCEDURE FOR THE ACCESSORY GEARBOX LINE 1 AND LINE 2 BEVEL GEARS, SERVICE BULLETIN	MOS HRS/MSC - ENC	08-JUL-2003	19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
SB BR700-72-101258 R01	NO. 2 ENGINE - ENGINE - LP COMPRESSOR CASE - INTRODUCTION OF A LP COMPRESSOR CASE WHICH IS MADE FROM A FORGING, SERVICE BULLETIN	MOS HRS/MSC - ENC	22-OCT-2008	19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
SB BR700-72-101260	NO. 2 ENGINE - ENGINE - HPT ROTOR SHAFT AND (NO. 4) BEARING - INTRODUCTION OF AN HP TURBINE STUB SHAFT WHICH IS DECREASED IN WEIGHT, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
SB BR700-72-101260 R01	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR SHAFT AND (NO. 4) BEARING - INTRODUCTION OF AN HP TURBINE STUB SHAFT WHICH IS DECREASED IN WEIGHT, SERVICE BULLETIN	MOS HRS/MSC - ENC	15-JAN-2015			OPTIONAL	NOT APPLICABLE
SB BR700-72-101270	NO. 2 ENGINE - ENGINE - LP/HP TURBINE SUPPORT AND OUTER BEARINGS - INTRODUCTION OF FRONT AND REAR BEARING CHAMBER PISTON RINGS WITH A SPECIFIED ROUNDNESS VALUE, SERVICE BULLETIN	MOS HRS/MSC - ENC	25-JAN-2002	19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
SB BR700-72-101271	NO. 2 ENGINE - ENGINE - HPC FRONT (NO 3) BEARING SUPPORT - INTRODUCTION OF NEW BOLTS TO ATTACH THE REAR LABYRINTH SEAL, SERVICE BULLETIN	MOS HRS/MSC - ENC	28-JUN-2002	19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101275	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF AN ACCESSORY GEARBOX MAIN HOUSING WITH AN IMPROVED MANUFACTURING PROCEDURE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-NOV-2001		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101285	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW ACCESSORY GEARBOX INPUT HOUSING AND ADJUSTING SHIMS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
16-JUN-2003		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101286	NO. 2 ENGINE - ENGINE - BYPASS DUCT - INTRODUCTION OF BYPASS DUCT ACCESS COVERS WITH TITANIUM OUTER SKINS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-MAR-2004		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101293	NO. 2 ENGINE - ENGINE - BYPASS DUCT - INTRODUCTION OF A BYPASS DUCT (BPD) WHICH IS MANUFACTURED BY A NEW SUPPLIER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-JUN-2002		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101326 R01	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW SELF LOCKING NUT FOR THE ACCESSORY GEARBOX LINE NUMBER 9 BREATHER SHAFT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
17-NOV-2008		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101328	NO. 2 ENGINE - ENGINE - HPT 2 LINERS - INTRODUCTION OF NEW HP TURBINE STAGE 2 LINERS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-MAR-2004		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101331	NO. 2 ENGINE - ENGINE - LPT CASE - INTRODUCTION OF DECREASED SHROUD TIP CLEARANCES BETWEEN THE LP TURBINE STAGE 1 AND 2 ROTOR BLADES AND THEIR RELATED SHROUD SEGMENTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-MAY-2003		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101333	NO. 2 ENGINE - ENGINE - HPT ROTOR DISCS - INTRODUCTION OF A NEW STANDARD OF CURVIC RING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-JUN-2002		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101349	NO. 2 ENGINE - ENGINE - LPT FUEL SHUT-OFF CABLE AND FITTINGS - INTRODUCTION OF A NEW FUEL SHUT-OFF (FSO) CABLE WITH BRAZED-ON CLIPS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
24-JUN-2003		MOS HRS/MSC - ENC		19-AUG-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101351 R01	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF AN ALTERNATIVE LINE 9 IMPELLER SHAFT WITH A NEW EXTERNAL THREAD DIAMETER TOLERANCE, NEW IDENTITY MARKINGS AND AN ALTERNATIVE MATERIAL, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-JUL-2003		HRS/MSC - ENC					
SB BR700-72-101369	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR BLADES - INTRODUCTION OF NEW HP COMPRESSOR STAGE 5 AND 6 BLADES MADE FROM A NEW MATERIAL, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-JAN-2006		HRS/MSC - ENC					
SB BR700-72-101395	NO. 2 ENGINE - ENGINE - LP COMPRESSOR BLADES - INTRODUCTION OF A METCO 58 COATING ON THE LP COMPRESSOR BLADES, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-MAY-2004		HRS/MSC - ENC					
SB BR700-72-101414	NO. 2 ENGINE - ENGINE - HPC FRONT CASE - INTRODUCTION OF NEW COATED BUSHES FOR IMPROVED CORROSION PROTECTION, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-SEP-2003		HRS/MSC - ENC					
SB BR700-72-101416 R01	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW ACCESSORY GEARBOX LINE 12 SPACER, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-AUG-2003		HRS/MSC - ENC					
SB BR700-72-101417	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW ACCESSORY GEARBOX LINE 12 GEAR SHAFT, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
27-FEB-2004		HRS/MSC - ENC					
SB BR700-72-101419 R02	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) VARIABLE INLET GUIDE VANE (VIGV) ACTUATING MECHANISM - INTRODUCTION OF A NEW BUILD INSTRUCTION TO INCREASE END FLOAT AND CENTRALISER GAP, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-MAR-2012		HRS/MSC - ENC					
SB BR700-72-101420	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE CASE - APPLICATION OF ANTI-SEIZURE COMPOUND ON DESIGNATED PLUGS OF COMBUSTOR AND TURBINE, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
07-MAY-2004		HRS/MSC - ENC					
SB BR700-72-101421	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE STAGE 1 NOZZLE GUIDE SEALS - INTRODUCTION OF A NEW REAR BEARING SUPPORT STRUCTURE (RBSS) VENT DUCT MADE FROM A FORGING, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-MAR-2007		HRS/MSC - ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101431	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 1 NOZZLE GUIDE SEALS - INTRODUCTION OF A NEW ONE PIECE PRESWIRL NOZZLE AND WEB SEAL ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-MAY-2006		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101436 R01	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) EXIT GUIDE STATOR VANES - FAN OUTLET GUIDE VANE (OGV) RE-SOURCING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
03-MAR-2010		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101436 R02	NO. 2 ENGINE - RE-SOURCING LOW PRESSURE (LP) EXIT GUIDE STATOR VANES - FAN OUTLET GUIDE VANE (OGV), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
01-OCT-2015		MOS HRS/MSC - ENC					
SB BR700-72-101440	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE AND GEARBOX RADIAL DRIVE - INTRODUCTION OF REVISED INSTALLATION PROCEDURE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-MAR-2009		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101453 R01	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR STATOR VANES - INTRODUCTION OF A FULLY MACHINED ENGINE SECTION STATOR (ESS) BLADE INTEGRATED RING (BLING), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-APR-2013		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101454	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 2 NOZZLE GUIDE SEALS - INTRODUCTION OF A NEW MATERIAL FOR THE HP TURBINE SUPPORT RING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-JAN-2005		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101456	NO. 2 ENGINE - ENGINE LOW PRESSURE (LP) TURBINE SHUT OFF PAWL CARRIER - DELETION OF AN UNUSED TRIM BALANCE FEATURE ON THE PAWL CARRIER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
09-SEP-2004		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101457	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 2 NOZZLE GUIDE SEALS - INTRODUCTION OF A NEW MATERIAL FOR THE HP TURBINE RIM SEAL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-JAN-2005		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101461	NO. 2 ENGINE - ENGINE - COMBUSTION FAIRINGS - INTRODUCTION OF A NEW CORE FAIRING WITH BLOW OPEN DOOR REMOVED, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
01-JUN-2005		MOS HRS/MSC - ENC		19-AUG-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101463	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR INNER CASE - INTRODUCTION OF A NEW STAGE 5 TO 10 REAR INNER CASE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-APR-2006		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101469	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR VORTEX REDUCER - INTRODUCTION OF A NEW FORGING MATERIAL FOR THE HP COMPRESSOR VORTEX REDUCER RING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
01-MAR-2006		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101469 R01	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VORTEX REDUCER - INTRODUCTION OF A NEW FORGING MATERIAL FOR THE HP COMPRESSOR VORTEX REDUCER RING, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
29-AUG-2014		MOS HRS/MSC - ENC					
SB BR700-72-101471 R02	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - INTRODUCTION OF METCO 58 COATED LP COMPRESSOR BLADES WITH A TRANSITION STRIP, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
28-JUL-2005		MOS HRS/MSC A/R ENC		19-AUG-2013			
SB BR700-72-101474	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF A LASER SHOCK PEENED (LSP) LP COMPRESSOR ROTOR DISC WITH A NEW PART NUMBER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-72-101474 R01	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF A LASER SHOCK PEENED (LSP) LP COMPRESSOR ROTOR DISC WITH A NEW PART NUMBER, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS HRS/MSC - ENC					
SB BR700-72-101474 R01 PART 1	NO. 2 ENGINE - REIDENTIFICATION LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF A LASER SHOCK PEENED (LSP) LP COMPRESSOR ROTOR DISC WITH A NEW PART NUMBER, SERVICE BULLETIN OF A NON-FLOWN LP COMPRESSOR ROTOR DISC					RECOMMENDED	NOT APPLICABLE
		MOS HRS/MSC - ENC					
SB BR700-72-101474 R01 PART 2	NO. 2 ENGINE - REMOVAL LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF A LASER SHOCK PEENED (LSP) LP COMPRESSOR ROTOR DISC WITH A NEW PART NUMBER, SERVICE BULLETIN AND INSTALLATION OF THE LP COMPRESSOR ROTOR DISC					RECOMMENDED	NOT APPLICABLE
		MOS HRS/MSC - ENC					
SB BR700-72-101476	NO. 2 ENGINE - ENGINE - COMBUSTION LINER - INTRODUCTION OF A NEW COMBUSTION CHAMBER WITHOUT COOLING RIBS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-SEP-2005		MOS HRS/MSC - ENC		19-AUG-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101476 R01	NO. 2 ENGINE - COMBUSTION LINER - INTRODUCTION OF A NEW COMBUSTION CHAMBER WITHOUT COOLING RIBS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
29-AUG-2014		MOS					
		HRS/MSC	-				
		ENC					
SB BR700-72-101476 R02	NO. 2 ENGINE - COMBUSTION LINER - INTRODUCTION OF A NEW COMBUSTION CHAMBER WITHOUT COOLING RIBS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
01-OCT-2015		MOS					
		HRS/MSC	-				
		ENC					
SB BR700-72-101490	NO. 2 ENGINE - ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - INTRODUCTION OF A NEW RADIAL DRIVE SHAFT (RDS) LOWER SUPPORT HOUSING (LSH), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
14-JUL-2006		MOS		19-AUG-2013			
		HRS/MSC	-				
		ENC					
SB BR700-72-101492	NO. 2 ENGINE - ENGINE - BYPASS DUCT - INTRODUCTION OF NEW INTRASCOPE BLANKS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-NOV-2005		MOS		19-AUG-2013			
		HRS/MSC	-				
		ENC					
SB BR700-72-101493	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR INNER CASE - DELETION OF THE HP VCOMPRESSOR STAGE 5 AND STAGE 7 TO 8 HEAT-SHIELDS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-NOV-2005		MOS		19-AUG-2013			
		HRS/MSC	-				
		ENC					
SB BR700-72-101498	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF METAL TRANSPORTATION BLANKS WITH PLASTIC TRANSPORTATION BLANKS AND INTRODUCTION OF ALTERNATIVE ORIGINAL SUPPLIER PART NUMBERS FOR CERTAIN ACCESSORY GEARBOX COMPONENTS, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAR-2012		MOS		19-AUG-2013			
		HRS/MSC	-				
		ENC					
SB BR700-72-101500	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW ACCESSORY GEARBOX MAIN HOUSING ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		19-AUG-2013			
		HRS/MSC	-				
		ENC					
SB BR700-72-101522	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW METHOD OF MANUFACTURE FOR ACCESSORY GEARBOX COMPONENTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-FEB-2008		MOS		19-AUG-2013			
		HRS/MSC	-				
		ENC					
SB BR700-72-101523 R01	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUT-OFF PAWL CARRIER PIVOT PINS MADE FROM A DIFFERENT MATERIAL WITH IMPROVED CORROSION PROTECTION PROPERTIES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS		19-AUG-2013			
		HRS/MSC	-				
		ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101523 R02	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUT-OFF PAWL CARRIER PIVOT PINS MADE FROM A DIFFERENT MATERIAL WITH IMPROVED CORROSION PROTECTION PROPERTIES, SERVICE BULLETIN	MOS HRS/MSC - ENC				RECOMMENDED	NOT APPLICABLE
19-DEC-2013							
SB BR700-72-101525	NO. 2 ENGINE - INTERMEDIATE CASE MODULE - INTRODUCTION OF NEW AND RE-IDENTIFIED INTERNAL GEARBOX COMPONENTS BECAUSE OF DESIGN RESPONSIBILITY CHANGE (SUPERSEDED BY SB BR700-72-101939), SERVICE BULLETIN	MOS HRS/MSC - ENC		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-SEP-2006							
SB BR700-72-101526	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE MODULE ATTACH PARTS AND FITTINGS - INTRODUCTION OF A NEW LP TURBINE AXIAL SETTING PROCEDURE WITH AN INCREASED RANGE OF ADJUSTING RINGS, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-NOV-2008							
SB BR700-72-101527	NO. 2 ENGINE - INTERMEDIATE CASE MODULE ATTACH PARTS AND FITTINGS - INTRODUCTION OF A NEW AIR TURBINE STARTER BRACKET ASSEMBLY, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-AUG-2007							
SB BR700-72-101531	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF NEW MANUFACTURING PROCEDURES FOR ACCESSORY GEARBOX COMPONENTS, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-FEB-2008							
SB BR700-72-101540 R01	NO. 2 ENGINE - ENGINE - EXHAUST CASE - INTRODUCTION OF AN OUTLET GUIDE VANE (OGV) HOUSING ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN	MOS HRS/MSC - ENC		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-NOV-2009							
SB BR700-72-101540 R02	NO. 2 ENGINE - ENGINE - EXHAUST CASE - INTRODUCTION OF AN OUTLET GUIDE VANE (OGV) HOUSING ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN	MOS HRS/MSC - ENC				OPTIONAL	NOT APPLICABLE
25-SEP-2013							
SB BR700-72-101540 R03	NO. 2 ENGINE - EXHAUST CASE - INTRODUCTION OF AN OUTLET GUIDE VANE (OGV) HOUSING ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN	MOS HRS/MSC - ENC				OPTIONAL	NOT APPLICABLE
28-JAN-2014							
SB BR700-72-101540 R04	NO. 2 ENGINE - EXHAUST CASE - INTRODUCTION OF AN OUTLET GUIDE VANE (OGV) HOUSING ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN	MOS HRS/MSC - ENC				OPTIONAL	NOT APPLICABLE
29-AUG-2014							



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101548	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR CASE - INTRODUCTION OF A NEW LP COMPRESSOR CASE WITH NEW IMPROVED SEALING OF THE REAR PANEL, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		HRS/MSC -					
		ENC					
SB BR700-72-101551	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - DELETION OF BREATHER FILTER AND CHANGES TO BREATHER COVER, TANK COVERS AND OBTURATOR PLATE, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		HRS/MSC -					
		ENC					
	24-MAY-2007						
SB BR700-72-101573	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR - INCREASED TIP CLEARANCE FOR HP COMPRESSOR STAGE 4 STATOR VANES, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		HRS/MSC -					
		ENC					
	11-SEP-2006						
SB BR700-72-101577	NO. 2 ENGINE - ENGINE - BYPASS DUCT ATTACHING PARTS AND FITTINGS - INTRODUCTION OF NEW BYPASS DUCT FRONT AND REAR LOAD SPREADER PLATE ASSEMBLIES, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		HRS/MSC -					
		ENC					
	30-JUL-2008						
SB BR700-72-101580	NO. 2 ENGINE - ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF A NEW ENGINE NAME PLATE, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		HRS/MSC -					
		ENC					
	24-SEP-2008						
SB BR700-72-101589	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF AN ACCESSORY GEARBOX MAIN HOUSING MADE FROM ALUMINUM, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		HRS/MSC -					
		ENC					
	05-FEB-2008						
SB BR700-72-101604 R01	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR BLADES - INTRODUCTION OF HP COMPRESSOR STAGE 1 BLADES WITH A THICKER LEADING EDGE CONTOUR, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		HRS/MSC -					
		ENC					
	03-MAR-2010						
SB BR700-72-101618	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF AN ACCESSORY GEARBOX OIL TANK OIL FILL INSTRUCTION LABEL SUITABLE FOR USE WITH AN ALUMINUM ACCESSORY GEARBOX MAIN HOUSING, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		HRS/MSC -					
		ENC					
	30-NOV-2007						
SB BR700-72-101623	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW LUBRICLONE FOR THE ACCESSORY GEARBOX, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		HRS/MSC -					
		ENC					
	19-SEP-2007						



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101663	NO. 2 ENGINE - ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY AND LOW PRESSURE (LP) COMPRESSOR/INTERNAL GEARBOX OIL DISTRIBUTION TUBES - INTRODUCTION OF REVISED OIL JET HOUSINGS, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
19-FEB-2010		HRS/MSC - ENC					
SB BR700-72-101664 R02	NO. 2 ENGINE - ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - INTRODUCTION OF A NEW NO.2 BEARING SUPPORT HOUSING, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
02-SEP-2010		HRS/MSC - ENC					
SB BR700-72-101669	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF NUTS WITH SILVER COATED THREAD ONLY, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-JAN-2010		HRS/MSC - ENC					
SB BR700-72-101699	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - INTRODUCTION OF A NEW LP COMPRESSOR ANNULUS FILLER WITH AN INTEGRAL HOOK DESIGN, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		HRS/MSC - ENC					
SB BR700-72-101705	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR ROTOR AND SHAFT DISCS - INTRODUCTION OF A NEW HP COMPRESSOR FRONT ROTOR ASSEMBLY WITH SHANK NUTS HAVING SILVER COATED THREADS ONLY, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
14-JAN-2011		HRS/MSC - ENC					
SB BR700-72-101722	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 2 ONWARD NOZZLE GUIDE SEALS - INTRODUCTION OF A DIFFERENT STANDARD HP TURBINE RIM SEAL ASSEMBLY AND HP TURBINE SUPPORT RING ASSEMBLY, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		HRS/MSC - ENC					
SB BR700-72-101728	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) ACTUATING RINGS AND LEVERS - INTRODUCTION OF A NEW MOUNTING BRACKET ASSEMBLY, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		HRS/MSC - ENC					
SB BR700-72-101734	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) ACTUATING RINGS AND LEVERS - INTRODUCTION OF CHANGES TO THE HP COMPRESSOR VARIABLE STATOR VANE (VSV) SYSTEM COMPONENTS, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-JAN-2014		HRS/MSC - ENC					
SB BR700-72-101757	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR FRONT BEARING AND SUPPORT - INTRODUCTION OF A NEW ALTERNATIVE HP COMPRESSOR NO.3 BEARING ASSEMBLY WITH A MORE ROBUST DESIGN, SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE
		HRS/MSC - ENC					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101774	NO. 2 ENGINE - ENGINE - CORE ENGINE FAIRINGS - INTRODUCTION OF A NEW STANDARD OF CORE ENGINE FAIRINGS, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		HRS/MSC -					
		ENC					
SB BR700-72-101794	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) RINGS AND SEALS - INTRODUCTION OF NUTS WITH SILVER COATED THREADS ONLY, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		HRS/MSC -					
		ENC					
SB BR700-72-101805 R03	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW STANDARD OF PRESSURE RELIEF VALVE (PRV), SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-APR-2013		HRS/MSC -					
		ENC					
SB BR700-72-101805 R04	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW STANDARD OF PRESSURE RELIEF VALVE (PRV), SERVICE BULLETIN	MOS				OPTIONAL	NOT APPLICABLE
		HRS/MSC -					
		ENC					
SB BR700-72-101813	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 1 LINER - INTRODUCTION OF NEW HP TURBINE STAGE 1 LINER SEGMENTS WITH AN INCREASED HONEYCOMB AREA (SUPERSEDED BY SB BR700-72-101971), SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		HRS/MSC -					
		ENC					
SB BR700-72-101953	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE BLADES - INTRODUCTION OF AN INSTRUCTION FOR MATCHED TIP GRINDING OF THE HP TURBINE STAGE 2 BLADES DURING NEW PRODUCTION OF THE ENGINE, SERVICE BULLETIN	MOS				OPTIONAL	NOT APPLICABLE
11-MAR-2016		HRS/MSC -					
		ENC					
SB BR700-72-900062 R02	NO. 2 ENGINE - ENGINE - INSTALLATION CHECK OF THE FASTENERS ON THE ENGINE COMPRESSOR AND COMBUSTION SECTION CORE FAIRINGS NON-MODIFICATION, SERVICE BULLETIN	MOS		19-AUG-2013		INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900062 R03	NO. 2 ENGINE - ENGINE - INSTALLATION CHECK OF THE FASTENERS ON THE ENGINE COMPRESSOR AND COMBUSTION SECTION CORE FAIRINGS NON-MODIFICATION, SERVICE BULLETIN	MOS		19-AUG-2013		INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
22-APR-1999		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900062 R04	NO. 2 ENGINE - ENGINE - INSTALLATION CHECK OF THE FASTENERS ON THE ENGINE COMPRESSOR AND COMBUSTION SECTION CORE FAIRINGS NON-MODIFICATION, SERVICE BULLETIN	MOS		19-AUG-2013		INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
06-MAR-2002		HRS/MSC -		0			
		ENC		0			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-900229 R01	NO. 2 ENGINE - LP COMPRESSOR INSPECTION OF FAN DISC, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900229 R02	NO. 2 ENGINE - LP COMPRESSOR INSPECTION OF FAN DISC, SERVICE BULLETIN						NOT APPLICABLE
		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900229 R03	NO. 2 ENGINE - LP COMPRESSOR - INSPECTION OF FAN DISC, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900229 R04	NO. 2 ENGINE - LP COMPRESSOR - INSPECTION OF FAN DISC, SERVICE BULLETIN						NOT APPLICABLE
		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900229 R05	NO. 2 ENGINE - LP COMPRESSOR - INSPECTION OF FAN DISC, SERVICE BULLETIN						NOT APPLICABLE
		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900229 R06	NO. 2 ENGINE - LP COMPRESSOR - INSPECTION OF FAN DISC, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		19-AUG-2013			
23-FEB-2005		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900229 R06	NO. 2 ENGINE - VISUAL OR ULTRASONIC INSP OF THE FAN DISC, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
PART 1		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900229 R06	NO. 2 ENGINE - ULTRASONIC AND VISUAL INSPECTION OF THE FAN DISC, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
PART 2		MOS		19-AUG-2013			
		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900307 R03	NO. 2 ENGINE - INSPECTION OF TIGHT CLEARANCE ON ENGINE DRESSING, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
21-FEB-2012		HRS/MSC -					
		ENC					
SB BR700-72-900392 R02	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR CASE - INSPECTION OF THE LP COMPRESSOR CASE FOR INSTALLATION OF CUT ICE IMPACT TRAY BOX ASSEMBLIES BY INCORPORATION OF THE ORIGINAL REPAIR BRG1431 - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS					
06-OCT-2014		HRS/MSC -					
		ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-900409 R01	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR CASE - INSPECTION OF THE LP COMPRESSOR CASE FOR INCORPORATION OF THE REPAIR BRG1299 NON-MODIFICATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
30-MAR-2012		MOS					
		HRS/MSC -					
		ENC					
SB BR700-72-900455 R02 PART A	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - VISUAL INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - SUPERSEDED BY ROLLS-ROYCE SB BR700-101699 ON 19 AUGUST 2013 AT MANUFACTURE
		MOS		11-OCT-2013			
		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900455 R02 PART B	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - SUPERSEDED BY ROLLS-ROYCE SB BR700-72-101699 ON 19,AUGUST 2013 AT MANUFACTURE
		MOS		11-OCT-2013			
		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900456	NO. 2 ENGINE - ENGINE CONVERSION FROM A FLIGHT-TEST STANDARD ENGINE TO A PRODUCTION STANDARD ENGINE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
26-JUL-2012		MOS					
		HRS/MSC -					
		ENC					
SB BR700-72-900510 R01	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP)/HIGH PRESSURE (HP) TURBINE SUPPORT AND OUTER BEARINGS - INSPECTION AND REPAIR OF REAR BEARING SUPPORT STRUCTURES (RBSS) THAT HAVE BEEN MACHINED BY ELECTRICAL DISCHARGE MACHINING (EDM) - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
18-SEP-2013		MOS					
		HRS/MSC -					
		ENC					
SB BR700-72-900521 R04	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, SERVICE BULLETIN						NOT APPLICABLE
		MOS		09-OCT-2015			
		HRS/MSC -		350.9			
		ENC		149			
SB BR700-72-900521 R04 PART A	NO. 2 ENGINE - VERIFICATION ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, SERVICE BULLETIN OF THE SERIAL NUMBERS OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS					RECOMMENDED	NOT APPLICABLE
		MOS		09-OCT-2015			
		HRS/MSC - (s)		350.9			
		ENC		149			
SB BR700-72-900521 R04 PART B	NO. 2 ENGINE - EDDY CURRENT INSPECTION ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, SERVICE BULLETIN OF THE AFFECTED LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS					RECOMMENDED	NOT APPLICABLE
		MOS		09-OCT-2015			
		HRS/MSC - (s)		350.9			
		ENC		149			
SB BR700-72-900525	NO. 2 ENGINE - INSPECTION OF THE INTERMEDIATE CASE FOR CORROSION DUE TO WATER ACCUMULATION IN THE ENGINE FRONT MOUNT FIREBOX, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
10-AUG-2012		MOS					
		HRS/MSC -					
		ENC					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-900525 R01	NO. 2 ENGINE - ENGINE - INTERMEDIATE CASE MODULE - INSPECTION OF THE INTERMEDIATE CASE FOR CORROSION DUE TO WATER ACCUMULATION IN THE ENGINE FRONT MOUNT FIREBOX - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
24-JAN-2013		MOS HRS/MSC - ENC					
SB BR700-72-900571	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VIGV AND STAGES 1 TO 4 STATOR VANES - REPLACEMENT OF UNWANTED PARTS TO RECTIFY THE ENGINE CONFIGURATION IN LINE WITH THE REQUIREMENTS OF SB SB-BR700-72-101901 - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
20-NOV-2015		MOS HRS/MSC - ENC					
SB BR700-72-900580	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE OIL FILLER ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
30-NOV-2015		MOS HRS/MSC - ENC					
SB BR700-72-900580 R01	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE OIL FILLER ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
04-APR-2016		MOS HRS/MSC - ENC					
SB BR700-72-900637	NO. 2 ENGINE - INTERMEDIATE CASE MODULE - INSPECTION OF THE RETENTION BOLTS OF THE NO.2/NO.3 BEARING HOUSINGS TO THE INTERMEDIATE CASE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
15-FEB-2018		MOS HRS/MSC - ENC					
SB R01 BR700-72-A900297	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR FAIRINGS - INSPECTION OF THE UPPER LEFT HP COMPRESSOR FAIRING FOR POTENTIAL PROFILE NON CONFORMANCE AND REPLACEMENT OF NON-CONFORMING UPPER LEFT HP COMPRESSOR FAIRING - NON MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
21-MAY-2014		MOS HRS/MSC - ENC					
SB BR700-73-100148 R02	NO. 2 ENGINE - FUEL AND CONTROL - DRAINS EJECTOR FUEL FILTER - INTRODUCTION OF A FILTER IN THE LINE TO THE FUEL DRAINS EJECTOR PUMP AND RELATED DRESSINGS CHANGES, SERVICE BULLETIN				19-AUG-2013	RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
06-JUL-1998		MOS HRS/MSC - ENC					
SB BR700-73-100190	NO. 2 ENGINE - FUEL AND CONTROL - ELECTRONIC ENGINE CONTROL (EEC) - INTRODUCTION OF REVISED HARDWARE STANDARD, SERVICE BULLETIN				19-AUG-2013	RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
22-MAR-1997		MOS HRS/MSC - ENC					
SB BR700-73-100206	NO. 2 ENGINE - ENGINE FUEL AND CONTROL-TUBES AND FITTINGS, AIR-ENGINE FUEL CONTROL SYSTEM (EXTERNAL)-INTRODUCTION OF A REVISED P30 TUBE ASSEMBLY WITH BLEED HOLE IN MOISTURE TRAP, SERVICE BULLETIN				19-AUG-2013	RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
11-OCT-1997		MOS HRS/MSC - ENC					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-100219	NO. 2 ENGINE - FUEL AND CONTROL - ELECTRONIC ENGINE CONTROLLER (EEC) - INTRODUCTION OF C3.1.1. SOFTWARE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-SEP-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-73-100247	NO. 2 ENGINE - FUEL AND CONTROL - OVERSPEED SPLITTER UNIT - INTRODUCTION OF A NEW UNIT FEATURING AN IMPROVED SAFETY LOCK FEATURE BASED ON RING LOCKED FITTINGS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
07-FEB-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-73-100271 R01	NO. 2 ENGINE - FUEL AND CONTROL - TUBES AND FITTINGS - INTRODUCTION OF MODIFIED TUBE ASSEMBLY END FITTINGS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-73-100283 R02	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH - INTRODUCTION OF UNITS INCORPORATING A HERMETICALLY SEALED MICRO-SWITCH, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-73-100352	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - CORE FUEL SYSTEM TUBES AND FITTINGS - INTRODUCTION OF REVISED BOLT LENGTH (CONFIGURATION SCHEME), SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-73-100357	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INTRODUCTION OF AN REVISED MOTIVE FUEL FILTER TUBE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
29-APR-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-73-100363	NO. 2 ENGINE - FUEL AND CONTROL - FUEL METERING UNIT (FMU) - INTRODUCTION OF A NEW OPTIMISED FUEL METERING UNIT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-JUL-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-73-100371 R02	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL LOW PRESSURE SWITCH - INTRODUCTION OF UNITS INCORPORATING A HERMETICALLY SEALED MICRO-SWITCH, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-73-100414	NO. 2 ENGINE - FUEL AND CONTROL - ELECTRONIC ENGINE CONTROLLER (EEC) - INTRODUCTION OF C4.0 SOFTWARE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
03-JUL-1998		MOS HRS/MSC - ENC		19-AUG-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-100440	NO. 2 ENGINE - FUEL AND CONTROL - ELECTRONIC ENGINE CONTROLLER (EEC) - INTRODUCTION OF SOFTWARE VERSION C5.1.1, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
18-AUG-1998		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-73-100459 R01	NO. 2 ENGINE - FUEL AND CONTROL - FUEL SPRAY NOZZLES - INTRODUCTION OF A FUEL SPRAY NOZZLE ASSEMBLY WITH MODIFIED INTERNAL PARTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-SEP-2005		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-73-100497	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INTRODUCTION OF DRESSING CHANGES TO SUIT MODIFIED THERMAL ANTI-ICING VALVE AND MUSCLE LINE (NEUTRAL ENGINES), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
25-SEP-1998		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-73-100596	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROL (EEC) - INTRODUCTION OF IMPROVED EEC FIREBOX HANDLING ACCESS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-73-100689	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - HP FUEL FILTER - INTRODUCTION OF IMPROVED REMOVAL / INSTALLATION FEATURES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-73-100709	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC ENGINE CONTROLLER (EEC) - INTRODUCTION OF AN EEC WITH C5.2.1 SOFTWARE STANDARD, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-73-100732	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF AN AIR FEED RESTRICTOR TO THE CONFIGURATION DATABASE AND THE ENGINE DOCUMENTATION, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-73-100827 R01	NO. 2 ENGINE - FUEL FLOW TRANSMITTER - INTRODUCTION OF A NEW UNIT WITH A MORE ACCURATE CALIBRATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS		19-AUG-2013			
		HRS/MSC A/R					
		ENC					
SB BR700-73-100835 R02	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - DATA ENTRY PLUG - INTRODUCTION OF A RE-TRIMMED DATA ENTRY PLUG TO INCREASE THE PERMITTED STATOR OUTLET TEMPERATURE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
10-APR-2001		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-100927 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC ENGINE CONTROLLER (EEC) - INTRODUCTION OF AN EEC WITH 05 OR 05R HARDWARE STANDARD, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-2000		HRS/MSC - ENC					
SB BR700-73-100938	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC ENGINE CONTROLLER (EEC) - INTRODUCTION OF SOFTWARE C5.2.3. INTO AN EEC WITH 04 STANDARD HARDWARE, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
20-OCT-1999		HRS/MSC - ENC					
SB BR700-73-100964 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL MANIFOLD - INSTALLATION OF A DAMPER WIRE BETWEEN THE LEFT HAND (LH) AND RIGHT HAND (RH) FUEL MANIFOLD, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-OCT-1999		HRS/MSC - ENC					
SB BR700-73-100970	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - INTRODUCTION OF NEW FITTING INSTRUCTIONS FOR ACCESSORY GEARBOX MOUNTED ACCESSORIES, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
24-JAN-2002		HRS/MSC - ENC					
SB BR700-73-101085 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL RETURN TO TANK VALVE - INTRODUCTION OF A FUEL RETURN TO TANK VALVE WITH RELATED DRESSING CHANGES, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-OCT-2000		HRS/MSC - ENC					
SB BR700-73-101094	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INTRODUCTION OF A NEW FUEL TUBE WITH INCREASED CLEARANCE TO THE BUFFER AIR TUBE, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-AUG-2001		HRS/MSC - ENC					
SB BR700-73-101106 R01	NO. 2 ENGINE - ENGINE AND FUEL CONTROL - FUEL METERING UNIT - INTRODUCTION OF A NEW FUEL METERING UNIT WITH CHANGES TO THE COMBINED OVERSPEED AND SHUT-OFF SOLENOID, THE PRESSURE RAISING VALVE AND ELECTRO HYDRAULIC SERVO VALVE, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
07-MAR-2001		HRS/MSC A/R ENC					
SB BR700-73-101145 R03	NO. 2 ENGINE - ENGINE AND FUEL CONTROL-ENGINE ELECTRIC CONTROLLER-INTRODUCTION OF C6.0 SOFTWARE STANDARD INTO AN EEC WITH 05 OR 05B HARDWARE, SERVICE BULLETIN	MOS		19-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		HRS/MSC A/R ENC					
SB BR700-73-101359	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INTRODUCTION OF A FUEL TUBE WITH A NEW ROUTING TO INCREASE THE CLEARANCE BETWEEN THE TUBE AND THE V-BAND CLAMP FOR THE HP STAGE 5 BLEED, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
17-DEC-2002		HRS/MSC - ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-101362	NO. 2 ENGINE - ENGINE - FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW EEC HARDWARE STANDARD, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
02-OCT-2002		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-73-101367	NO. 2 ENGINE - INTRODUCTION OF AN EEC WITH A NEW HARDWARE STANDARD (08), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC A/R ENC		19-AUG-2013			
SB BR700-73-101386	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL MANIFOLD - CHANGE OF SUPPLIER SOURCE FOR THE FUEL MANIFOLD DAMPER WIRE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-JUL-2005		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-73-101396	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INTRODUCTION OF NEW PART NUMBERS FOR TWO FUEL TUBE ASSEMBLIES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-MAR-2004		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-73-101415	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - CHANGE OF SUPPLIER SOURCE FOR THE FUEL SYSTEM P20, P30 AND P50 FLEXIBLE AIR TUBES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-MAY-2006		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-73-101429	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - DEDICATED GENERATOR - INTRODUCTION OF A NEW DEDICATED GENERATOR ROTOR WITH REDUCED OUT-OF-BALANCE (OOB) LIMITS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
20-JAN-2004		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-73-101443	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - DATA ENTRY PLUG (DEP) - INTRODUCTION OF A NEW DEP, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-MAY-2006		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-73-101451	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW LOCATION OF THE EEC CONNECT MODULE CAPACITOR, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-JUN-2004		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-73-101472 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C7.0.2, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-NOV-2004		MOS HRS/MSC A/R ENC		19-AUG-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-101477	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - T30 THERMOCOUPLES - INTRODUCTION OF A NEW T30 THERMOCOUPLE PROBE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-APR-2005		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-73-101504	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW STANDARD OF EEC HARDWARE AND SOFTWARE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
19-NOV-2007		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-73-101504 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW STANDARD OF EEC HARDWARE AND SOFTWARE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
10-JUL-2017		MOS HRS/MSC - ENC					
SB BR700-73-101505	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW TRANSMITTER (FFT) - INTRODUCTION OF A NEW FFT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-SEP-2005		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-73-101509	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF AN EEC WITH PRINTED CIRCUIT BOARDS FROM A NEW SOURCE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC A/R ENC		19-AUG-2013			
SB BR700-73-101558 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW TRANSMITTER (FFT) - INTRODUCTION OF A NEW FFT WITH IMPROVED ACCURACY LIMITS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
09-NOV-2007		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-73-101559 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
27-FEB-2012		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-73-101559 R02	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
10-JUL-2017		MOS HRS/MSC - ENC					
SB BR700-73-101559 R03	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
10-MAR-2021		MOS HRS/MSC - ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-101617	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW TRANSMITTER (FFT) - INTRODUCTION OF A FFT WITH A NEW CALIBRATION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
27-JUN-2007		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-73-101617 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW TRANSMITTER (FFT) - INTRODUCTION OF A FFT WITH A NEW CALIBRATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS					
		HRS/MSC -					
		ENC					
SB BR700-73-101628 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF AN EEC WITH X1.1 SOFTWARE STANDARD, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-73-101634	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
26-JUN-2008		MOS					
		HRS/MSC -					
		ENC					
SB BR700-73-101634 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
10-JUL-2017		MOS					
		HRS/MSC -					
		ENC					
SB BR700-73-101634 R02	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
10-MAR-2021		MOS					
		HRS/MSC -					
		ENC					
SB BR700-73-101806 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF X1.2 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-73-101966 R02	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF X2.0 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
21-DEC-2016		MOS		01-MAY-2019			
		HRS/MSC -		879.42			
		ENC		365			
SB BR700-73-900423 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
09-SEP-2014		MOS					
		HRS/MSC -					
		ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-900423 R02	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
09-MAR-2015		MOS	HRS/MSC -				
ENC							
SB BR700-73-900423 R03	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
22-DEC-2016		MOS	HRS/MSC -				
ENC							
SB BR700-73-900423 R04	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN (THIS NON-MODIFICATION SB-BR700-73-9000423 IS NO LONGER VALID AND CAN BE CLOSED), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
25-FEB-2021		MOS	HRS/MSC -				
ENC							
SB BR700-73-900539	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - HIGH PRESSURE (HP) FUEL FILTER ASSEMBLY - INSPECTION OF THE HP FUEL FILTER HOUSING CAP FOR CORRECT INSTALLATION OF ITS SEAL RING AND BACKUP RING - NON-MODIFICATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS	HRS/MSC A/R				
ENC							
SB BR700-73-900539 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - HIGH PRESSURE (HP) FUEL FILTER ASSEMBLY - INSPECTION OF THE HP FUEL FILTER HOUSING CAP FOR CORRECT INSTALLATION OF ITS SEAL RING AND BACKUP RING - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
06-JUN-2013		MOS	HRS/MSC -				
ENC							
SB R03 BR700-73-A900083	NO. 2 ENGINE - ENGINE FUEL AND CONTROL ENGINE ELECTRONIC CONTROLLER (EEC) - REPLACEMENT OF NON-CONFORMING PARTS OF THE EEC FIREBOX ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN (THIS SB IS NO LONGER VALID AND CAN BE CLOSED), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
28-JAN-2021		MOS	HRS/MSC -				
ENC							
SB BR700-74-100199	NO. 2 ENGINE - IGNITION - IGNITION UNIT - HIGH ENERGY - REVISED IGNITER BOX ATTACHING PARTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-FEB-1998		MOS	HRS/MSC -		19-AUG-2013		
ENC							
SB BR700-74-100248	NO. 2 ENGINE - IGNITION - IGNITION LEADS - INTRODUCTION OF REVISED CLIPPING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		MOS	HRS/MSC -		19-AUG-2013		
ENC							
SB BR700-74-100316	NO. 2 ENGINE - IGNITION - IGNITER LEAD - INTRODUCTION OF SILVER PLATING ON CONNECTING NUT THREADS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
28-APR-2000		MOS	HRS/MSC -		19-AUG-2013		
ENC							



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-74-100355	NO. 2 ENGINE - IGNITION - IGNITER PLUG - INTRODUCTION OF A SECOND SOURCE IGNITER PLUG, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-APR-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-74-100550	NO. 2 ENGINE - IGNITION - RIGHT ENGINE IGNITION LEAD ATTACHING FITTINGS - INTRODUCTION OF DRESSING CHANGES TO SUIT MODIFIED THERMAL ANTI-ICING VALVE AND MUSCLE LINE (RIGHT HAND ENGINES), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
25-SEP-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-74-100551	NO. 2 ENGINE - IGNITION - LEFT ENGINE IGNITION LEAD ATTACHING FITTINGS - INTRODUCTION OF TWO ADDITIONAL CLIPPING POINTS AND TRANSFER OF A BRACKET TO A LEFT ENGINE SECTION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-SEP-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-74-101073 R01	NO. 2 ENGINE - IGNITION - IGNITER PLUG - INTRODUCTION OF A STANDARD LENGTH IGNITER PLUG ADAPTOR AND RELATED ADJUSTING WASHERS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-OCT-2001		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-74-101280	NO. 2 ENGINE - IGNITION - HIGH ENERGY IGNITION UNITS - INTRODUCTION OF A NEW IGNITION UNIT WITH CHANGES TO THE PRINTED CIRCUIT BOARD, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
04-OCT-2001		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-75-100212 R01	NO. 2 ENGINE - AIR - BLEED VALVES - INTRODUCTION OF HIGH PRESSURE COMPRESSOR (HPC) BLEED VALVES WITH STEEL BUSHES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
11-APR-2003		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-75-100228 R01	NO. 2 ENGINE - AIR - VSV ACTUATOR - INTRODUCTION OF ONE HANDED 'ROSAN' LOCKING FEATURE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-75-100270	NO. 2 ENGINE - AIR - AIR TUBES AND FITTINGS - MINOR CONFIGURATION AMENDMENTS, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-75-100297 R01	NO. 2 ENGINE - AIR - VALVE CONTROL AIR BLEED - INTRODUCTION OF REVISED TORQUE TIGHTENING VALUES FOR BLEED VALVE BOLTS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS HRS/MSC - ENC		19-AUG-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-75-100332 R01	NO. 2 ENGINE - AIR - SOLENOID CONTROL - AIR BLEED - INTRODUCTION OF REVISED BLEED VALVE SOLENOID CONTROL BLOCK MOUNTING BRACKETS AND ASSOCIATED AIR TUBES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-75-100366 R01	NO. 2 ENGINE - AIR - SOLENOID CONTROL - AIR BLEED - INTRODUCTION OF A REVISED BLEED VALVE SOLENOID CONTROL BLOCK, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-75-100385 R01	NO. 2 ENGINE - AIR-BLEED VALVES AND SOLENOID CONTROL BLOCK - INTRODUCTION OF AN IMPROVED DESIGN OF BLEED VALVE AND SOLENOID CONTROL BLOCK, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-OCT-1999		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-75-100392	NO. 2 ENGINE - AIR - VSV ACTUATOR - INTRODUCTION OF A VARIABLE STATOR VANE ACTUATOR MANUFACTURED BY A NEW SUPPLIER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
14-SEP-1998		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-75-100465 R01	NO. 2 ENGINE - AIR - BUFFER AIR VALVE - INTRODUCTION OF A NEW BUFFER AIR VALVE FROM A DIFFERENT SUPPLIER AND WITH IMPROVED CORROSION PROTECTION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
19-JUL-2002		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-75-101096	NO. 2 ENGINE - AIR - BLEED VALVE SOLENOID CONTROL BLOCK - INTRODUCTION OF TRANSFER TUBES BETWEEN THE BLEED VALVE SOLENOID BLOCK VENT VALVE BODY AND THE SOLENOID CAPS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
12-JUL-2000		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-75-101097	NO. 2 ENGINE - AIR - CORE AIR TUBES AND FITTINGS - INTRODUCTION OF A NEW AIR TUBE WITH A DIFFERENT ROUTING FROM THE BUFFER AIR VALVE TO THE ACCESSORY GEARBOX AND AN ADDITIONAL CLIP POINT CP40402, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
03-FEB-2004		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-75-101130 R01	NO. 2 ENGINE - AIR - BLEED VALVES - INTRODUCTION OF NEW HP 8 HANDLING BLEED VALVE INNER AND OUTER ATTENUATORS TO PREVENT DAMAGE TO BYPASS DUCT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
22-JUN-2001		MOS		19-AUG-2013			
		HRS/MSC A/R					
		ENC					
SB BR700-75-101161 R01	NO. 2 ENGINE - AIR - BLEED VALVE SOLENOID CONTROL BLOCK-INTRODUCTION OF HANDLING BLEED VALVE SOLENOID WITH SOLENOID SERVO VALVES WHICH OPERATE AT LOWER CURRENT FLOWS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
07-FEB-2001		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-75-101161 R02	NO. 2 ENGINE - AIR - BLEED VALVE SOLENOID CONTROL BLOCK - INTRODUCTION OF A HANDLING BLEED VALVE SOLENOID WITH SOLENOID SERVO VALVES WHICH OPERATE AT LOWER CURRENT FLOWS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
07-OCT-2017		MOS	HRS/MSC -				
		ENC					
SB BR700-75-101161 R03	NO. 2 ENGINE - AIR - BLEED VALVE SOLENOID CONTROL BLOCK - INTRODUCTION OF A HANDLING BLEED VALVE SOLENOID WITH SOLENOID SERVO VALVES WHICH OPERATE AT LOWER CURRENT FLOWS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
07-SEP-2018		MOS	HRS/MSC -				
		ENC					
SB BR700-75-101207	NO. 2 ENGINE - AIR - AIR TUBES AND FITTINGS - INTRODUCTION OF A P30 AIR TUBE WITH A NEW ROUTING TO INCREASE THE CLEARANCE BETWEEN THE TUBE AND THE FUEL MANIFOLD, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
20-JUN-2002		MOS	HRS/MSC -	19-AUG-2013			
		ENC					
SB BR700-75-101228	NO. 2 ENGINE - AIR - CORE AIR TUBES AND FITTINGS - INTRODUCTION OF NEW HP2/HP4 AIR SYSTEM TUBE ASSEMBLIES WHICH ARE DECREASED IN WEIGHT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
24-APR-2002		MOS	HRS/MSC -	19-AUG-2013			
		ENC					
SB BR700-75-101381 R01	NO. 2 ENGINE - AIR - BLEED VALVES - INTRODUCTION OF NEW TRIPLE SEALS AND A CARBON BUSH TO REPLACE THE EXISTING STEEL COMPONENTS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
09-OCT-2018		MOS	HRS/MSC -				
		ENC					
SB BR700-75-101447 R01	NO. 2 ENGINE - AIR - VSV ACTUATOR - INTRODUCTION OF A MODIFIED VARIABLE STATOR VANE (VSV) ACTUATOR, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-AUG-2013		MOS	HRS/MSC -	19-AUG-2013			
		ENC					
SB BR700-75-101447 R02	NO. 2 ENGINE - AIR - VSV ACTUATOR - INTRODUCTION OF A MODIFIED VARIABLE STATOR VANE (VSV) ACTUATOR, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS	HRS/MSC -				
		ENC					
SB BR700-75-101694	NO. 2 ENGINE - AIR - AIR BLEED CONTROL SOLENOID - INTRODUCTION OF WASHERS WITH A SMALLER OUTER DIAMETER FOR THE INSTALLATION OF THE HANDLING BLEED VALVE SOLENOID CONTROL BLOCK, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-APR-2010		MOS	HRS/MSC -	19-AUG-2013			
		ENC					
SB BR700-75-900633	NO. 2 ENGINE - AIR - VSV ACTUATOR - REPLACEMENT OF LUCAS VARIABLE STATOR VANE (VSV) ACTUATORS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
19-JUN-2018		MOS	HRS/MSC -				
		ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-75-900633 R01	NO. 2 ENGINE - AIR - VSV ACTUATOR - REPLACEMENT OF LUCAS VARIABLE STATOR VANE (VSV) ACTUATORS - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
11-DEC-2018		MOS					
		HRS/MSC -					
		ENC					
SB BR700-75-900693	NO. 2 ENGINE - AIR - VSV ACTUATOR - REPLACEMENT OF VARIABLE STATOR VANE (VSV) ACTUATORS - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
25-MAR-2021		MOS					
		HRS/MSC -					
		ENC					
SB BR700-77-100556	NO. 2 ENGINE - ENGINE INDICATING - TURBINE OVERHEAT/OIL FIRE DETECTION THERMOCOUPLE - INTRODUCTION OF STRENGTHENED TERMINALS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-NOV-1998		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-77-101105	NO. 2 ENGINE - ENGINE INDICATING - TGT HARNESS - INTRODUCTION OF TORQUE TIGHTENING VALUES FOR THE NUTS WHICH ATTACH THE TURBINE GAS TEMPERATURE (TGT) HARNESS TO THE TGT PROBES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
10-APR-2001		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-77-101534	NO. 2 ENGINE - ENGINE INDICATING - TURBINE GAS TEMPERATURE (TGT) THERMOCOUPLE - INTRODUCTION OF NEW TGT PROBES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
14-SEP-2006		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-77-101536	NO. 2 ENGINE - ENGINE INDICATING - TURBINE GAS TEMPERATURE (TGT) HARNESS - INTRODUCTION OF A NEW TGT HARNESS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
14-JUL-2006		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-77-101544	NO. 2 ENGINE - ENGINE INDICATING - VIBRATION TRANSDUCER AND CABLE - INTRODUCTION OF A NEW ENGINE VIBRATION MONITORING SYSTEM (EVMS) ACCELEROMETER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
02-NOV-2007		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-77-101553	NO. 2 ENGINE - ENGINE INDICATING - VIBRATION TRANSDUCER AND CABLE - INTRODUCTION OF A NEW ENGINE VIBRATION MONITORING SYSTEM (EVMS) CABLE ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
24-MAR-2009		MOS		19-AUG-2013			
		HRS/MSC -					
		ENC					
SB BR700-77-900329 R01	NO. 2 ENGINE - ENGINE INDICATING - N2 SPEED PROBES - INSULATION RESISTANCE TEST ON N2 SPEED PROBES FOR POTENTIAL ELECTRICAL DEFECTS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - PER SPEED PROBES INSTALLED
29-OCT-2003		MOS		02-NOV-2016			
		HRS/MSC -		541.13			
		ENC		225			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-78-100165 R01	NO. 2 ENGINE - THRUST REVERSER - LH AND RH ENGINES - INTRODUCTION OF BEARINGS WITH A TEFLON LINER FOR THE LINEAR VARIABLE TRANSDUCER (LVT) ROD ENDS, THE PRIMARY DOOR LOCK AND THE INHIBITION BOLT RECEPTACLE, SERVICE BULLETIN	MOS		16-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		HRS/MSC - ENC					
SB BR700-78-100196 R02	NO. 2 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - LH AND RH ENGINES - INTRODUCTION ON THE LH AND RH ENGINE OF SPHERICAL BEARINGS WITH A HIGH TEMPERATURE TEFLON LINER, SERVICE BULLETIN	MOS		16-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
22-MAR-2000		HRS/MSC - ENC					
SB BR700-78-100224 R01	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF A CHANGE OF OWNERSHIP (INSTALLATION RESPONSIBILITY) FOR THE WET DRAINS BRACKETS, SERVICE BULLETIN	MOS		16-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		HRS/MSC - ENC					
SB BR700-78-100225	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - REPLACEMENT OF THE FIRE PROTECTION ABLATIVE COATING ON THE THRUST REVERSER FRONT FRAME TORQUE BOX WITH FIRE BLANKETS (HUREL DUBOIS SB 04MOD0077), SERVICE BULLETIN	MOS		16-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
05-JUN-1998		HRS/MSC - ENC					
SB BR700-78-100236 R01	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF REVISED PIVOT DOOR ACTUATORS AND DYNAMIC SEALS, SERVICE BULLETIN	MOS		16-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		HRS/MSC - ENC					
SB BR700-78-100252 R01	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - DELETION OF 'NEXTEL' FROM PIVOT DOORS, SERVICE BULLETIN	MOS		16-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		HRS/MSC - ENC					
SB BR700-78-100358	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - DELETION OF THE THRUST REVERSER STOW SWITCH ACCESS PANELS, SERVICE BULLETIN	MOS		16-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		HRS/MSC - ENC					
SB BR700-78-100359	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - DELETION OF UPPER DOOR HOISTING POINTS, SERVICE BULLETIN	MOS		16-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-MAR-2002		HRS/MSC - ENC					
SB BR700-78-100360	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - DELETION OF THE NEXTEL LAYER ON THE FAN DUCT, SERVICE BULLETIN	MOS		16-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		HRS/MSC - ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-78-100361	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - DELETION OF THE NEXTEL LAYER ON FRAME 1, SERVICE BULLETIN	MOS		16-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		HRS/MSC - ENC					
SB BR700-78-100389 R01	NO. 2 ENGINE - EXHAUST - THRUST REVERSER UNIT (TRU) - CHANGE OF THE LINEAR VARIABLE TRANSFORMER (LVT) TO ENSURE IMPROVED PERFORMANCE, SERVICE BULLETIN	MOS		16-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		HRS/MSC - ENC					
SB BR700-78-100390	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF SIMPLIFIED TORQUE BOX AND LATERAL BEAM JOINT FOR WEIGHT REDUCTION PURPOSES, SERVICE BULLETIN	MOS		16-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		HRS/MSC - ENC					
SB BR700-78-100502	NO. 2 ENGINE - EXHAUST - ISOLATION CONTROL UNIT (ICU) - INTRODUCTION OF A NEW ICU WHICH HAVE A RETARDED THRUST REVERSER UNIT (TRU) PRESSURISATION, SERVICE BULLETIN	MOS		16-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
25-SEP-2008		HRS/MSC - ENC					
SB BR700-78-100593 R01	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - CHANGE OF THRUST REVERSER PIVOT DOOR HONEYCOMB MATERIAL AND INTRODUCTION OF WEIGHT REDUCTION FEATURES, SERVICE BULLETIN	MOS		16-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-2000		HRS/MSC - ENC					
SB BR700-78-100599	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF A WEIGHT REDUCED GEARBOX AIR BREATHER PIPE, SERVICE BULLETIN	MOS		16-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		HRS/MSC - ENC					
SB BR700-78-100641	NO. 2 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - INTRODUCTION OF A NEW MATERIAL FOR THE JUNCTION SPLICE BETWEEN THE NOZZLE AND BEAM, SERVICE BULLETIN	MOS		16-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
17-MAY-2001		HRS/MSC - ENC					
SB BR700-78-100642 R01	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - IMPROVED ELECTRICAL BONDING OF THE THRUST REVERSER MAIN DOOR, SERVICE BULLETIN	MOS		16-AUG-2013		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		HRS/MSC - ENC					
SB BR700-78-100783 R05	NO. 2 ENGINE - EXHAUST - LEFT AND RIGHT ENGINE THRUST REVERSER - MATERIAL CHANGE OF THE PIVOTING DOOR SEAL DEPRESSOR AND CARRIER SEGMENTS, SERVICE BULLETIN	MOS		16-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-NOV-2009		HRS/MSC - ENC					
SB BR700-78-100898	NO. 2 ENGINE - EXHAUST - EXHAUST CONE - INTRODUCTION OF A ONE PIECE EXHAUST CONE, SERVICE BULLETIN	MOS		19-AUG-2013		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
13-JUL-2001		HRS/MSC - ENC					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-78-100935 R01	NO. 2 ENGINE - EXHAUST - TERTIARY LOCK - INTRODUCTION OF TERTIARY LOCKS WITH A BETTER MANUAL RELEASE MECHANISM AND INCREASED SOLENOID FORCE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
04-JUL-2002		MOS		16-AUG-2013			
		HRS/MSC	-				
		ENC					
SB BR700-78-100987 R01	NO. 2 ENGINE - EXHAUST - LEFT AND RIGHT THRUST REVERSER HYDRAULIC TUBES - CHANGES TO THE MAIN-DOOR-ACTUATOR HOSES (THE ACTUATOR HOSES) OF THE THRUST REVERSER UNIT (TRU), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-SEP-2000		MOS		16-AUG-2013			
		HRS/MSC	-				
		ENC					
SB BR700-78-101009	NO. 2 ENGINE - EXHAUST - LEFT AND RIGHT ENGINE THRUST REVERSER - INTRODUCTION OF NEW SHIMS FOR THE SEAL LANDS ON THE INTERFACE OF THE THRUST REVERSER AND THE UPPER AND LOWER COWL DOOR, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
16-OCT-2000		MOS		16-AUG-2013			
		HRS/MSC	-				
		ENC					
SB BR700-78-101061 R04	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF THRUST REVERSER FLOW DISCOURAGER SEALS BETWEEN THE PIVOT DOORS AND THE FIXED STRUCTURE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
03-MAY-2001		MOS		16-AUG-2013			
		HRS/MSC	-				
		ENC					
SB BR700-78-101129 R01	NO. 2 ENGINE - EXHAUST - LEFT AND RIGHT ENGINE THRUST REVERSER FIXED STRUCTURE - REORIENTATION OF THE FASTENERS AT THE THRUST REVERSER FRONT FRAME TO INCREASE THE CLEARANCE TO THE S-HOOK, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
16-OCT-2000		MOS		16-AUG-2013			
		HRS/MSC	-				
		ENC					
SB BR700-78-101387	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF STOW SWITCHES MANUFACTURED BY A NEW SUPPLIER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-MAR-2003		MOS		16-AUG-2013			
		HRS/MSC	-				
		ENC					
SB BR700-78-101442	NO. 2 ENGINE - EXHAUST - EXHAUST NOZZLE - INTRODUCTION OF A NEW EXHAUST NOZZLE ASSEMBLY WITHOUT SPACERS BETWEEN THE FRONT SUPPORT BRACKETS AND THE NOZZLE SKIN, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
29-OCT-2004		MOS		19-AUG-2013			
		HRS/MSC	-				
		ENC					
SB BR700-78-101501	NO. 2 ENGINE - EXHAUST - ISOLATION CONTROL UNIT (ICU) - INTRODUCTION OF AN ISOLATION CONTROL UNIT WITH IMPROVED BONDING RESISTANCE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-JUL-2005		MOS		16-AUG-2013			
		HRS/MSC	-				
		ENC					
SB BR700-78-101512	NO. 2 ENGINE - EXHAUST - THRUST REVERSER PIVOTING DOORS - INSTRUCTION OF VARIOUS IMPROVEMENTS TO THE THRUST REVERSER PIVOTING DOORS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
27-APR-2006		MOS		16-AUG-2013			
		HRS/MSC	-				
		ENC					



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-78-101514	NO. 2 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - INTRODUCTION OF A NEW UPPER INHIBITION BOLT FITTING MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
27-APR-2006		MOS HRS/MSC - ENC		16-AUG-2013			
SB BR700-78-101515	NO. 2 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - INTRODUCTION OF A NEW 'Y' STOP FITTING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-JAN-2007		MOS HRS/MSC - ENC		16-AUG-2013			
SB BR700-78-101607	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF A NEW THRUST REVERSER UNIT (TRU), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-AUG-2007		MOS HRS/MSC - ENC		16-AUG-2013			
SB BR700-78-101635	NO. 2 ENGINE - EXHAUST - THRUST REVERSER DOOR STOW SWITCH - INTRODUCTION OF A DOOR STOW SWITCH WITH IMPROVED SEALING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
01-AUG-2008		MOS HRS/MSC - ENC		16-AUG-2013			
SB BR700-78-102008 R01	NO. 2 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - INTRODUCTION OF A DRAINAGE HOLE WITHIN THE THRUST REVERSER FIXED STRUCTURE TO PREVENT CORROSION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - SB BR700-78-102008 R1 IAW SAFRAN NACELLES SB 04MOD132 ON RIGHT ENGINE AT BAS FLL-USA FACILITY
19-JAN-2018		MOS HRS/MSC - ENC		25-MAY-2019 879.42 365			
SB BR700-79-100118 R01	NO. 2 ENGINE - OIL - COOLER - ENGINE LUBRICATING OIL (AIR COOLED) DELETION OF AIR COOLED OIL COOLER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
29-SEP-2000		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-79-100221	NO. 2 ENGINE - OIL - OIL TANK AND EXTERNAL OIL TUBES - INTRODUCTION OF A SCUPPER DRAIN TUBE AND A MODIFIED OIL FILLER ASSEMBLY AND THE DELETION OF BLANKING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
19-JUN-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-79-100294	NO. 2 ENGINE - OIL - FUEL COOLED OIL COOLER - REMOVAL OF LIFE LIMITATION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
25-FEB-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-79-100323	NO. 2 ENGINE - OIL - TUBES AND FITTINGS - ENGINE LUBRICATING OIL - EXTERNAL - INTRODUCTION OF A REVISED ANTI - SYPHON TUBE ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
29-APR-1998		MOS HRS/MSC - ENC		19-AUG-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-79-100323 R01	NO. 2 ENGINE - OIL - EXTERNAL OIL TUBES AND FITTINGS - INTRODUCTION OF A REVISED ANTI-SYPHON OIL TUBE ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
14-MAR-2014		MOS HRS/MSC - ENC					
SB BR700-79-100403	NO. 2 ENGINE - OIL - OIL DIFFERENTIAL PRESSURE TRANSDUCER- INTRODUCTION OF A NEW OIL DIFFERENTIAL PRESSURE TRANSDUCER UNIT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-79-100406 R01	NO. 2 ENGINE - OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH - INTRODUCTION OF A UNIT INCORPORATING A HERMETICALLY SEALED MICRO-SWITCH, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
09-DEC-1998		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-79-100413	NO. 2 ENGINE - OIL - FUEL COOLED OIL COOLER - INTRODUCTION OF A NEW UNIT FEATURING A CAST VERSION OF THE OIL FILTER HOUSING COVER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-79-100478	NO. 2 ENGINE - OIL - EXTERNAL OIL TUBES AND FITTINGS - INTRODUCTION OF REVISED CLIPPING POINTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-79-100798 R01	NO. 2 ENGINE - OIL - FUEL COOLED OIL COOLER - INTRODUCTION OF NEW ELECTRICAL BONDING LEAD FITTING INSTRUCTIONS, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
22-SEP-2000		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-79-101083	NO. 2 ENGINE - OIL - EXTERNAL OIL TUBES AND FITTINGS - INTRODUCTION OF A NEW OIL VENT TUBE WITH BETTER SEALING PROPERTIES BETWEEN THE OIL VENT PIPE AND THE ACCESSORY GEARBOX, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
01-DEC-2000		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-79-101188 R01	NO. 2 ENGINE - OIL - OIL DIFFERENTIAL PRESURE SWITCH - INTRODUCTION OF A NEW OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH A THICKER COVER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-JUL-2002		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-79-101287	NO. 2 ENGINE - OIL - OIL PUMPS - INTRODUCTION OF A NEW OIL PUMP WITH A SMALLER SPILL RETURN ORIFICE WHICH INCREASES THE PUMP DISCHARGE OIL FLOW, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-FEB-2002		MOS HRS/MSC - ENC		19-AUG-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-79-101292	NO. 2 ENGINE - OIL - EXTERNAL OIL TUBES AND FITTINGS - INTRODUCTION OF A NEW OIL TUBE BETWEEN THE GEARBOX OIL PUMP AND THE FUEL COOLED OIL COOLER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-NOV-2002		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-79-101445	NO. 2 ENGINE - OIL - OIL PUMP - INTRODUCTION OF A NEW STATIC ANTI LEAK VALVE (SALV) INTO THE OIL PUMP UNIT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
16-APR-2004		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-79-101449	NO. 2 ENGINE - OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH - INTRODUCTION OF A NEW OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH A CHANGE TO THE SWITCH SET POINT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-MAY-2004		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-79-101458	NO. 2 ENGINE - OIL - PRESSURE FILTER ELEMENT - INTRODUCTION OF A NEW OIL FILTER ELEMENT WITH INCREASED DIRT HOLDING CAPACITY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
17-MAY-2004		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-79-101470	NO. 2 ENGINE - OIL - FUEL COOLED OIL COOLER (FCOC) - INTRODUCTION OF A NEW FRONT SUPPORT BRACKET, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-NOV-2005		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-79-101482	NO. 2 ENGINE - OIL - FUEL COOLED OIL COOLER (FCOC) - INTRODUCTION OF A NEW FUEL COOLED OIL COOLER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-MAR-2005		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-79-101739	NO. 2 ENGINE - OIL - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF A NEW SEALING PLATE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-FEB-2011		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-79-101744	NO. 2 ENGINE - FUEL COOLED OIL COOLER (FCOC) - INTRODUCTION OF A NEW FCOC WITH IMPROVED ICING PROTECTION CAPABILITY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
29-AUG-2012		MOS HRS/MSC - ENC					
SB BR700-79-101744 R01	NO. 2 ENGINE - OIL - FUEL COOLED OIL COOLER (FCOC) - INTRODUCTION OF A NEW FCOC WITH IMPROVED ICING PROTECTION CAPABILITY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC - ENC		19-AUG-2013			



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-79-101803	NO. 2 ENGINE - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF A NEW OIL PUMP UNIT WITH IMPROVED GEARS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
09-AUG-2012		MOS HRS/MSC - ENC		19-AUG-2013			
SB BR700-79-101803 R01	NO. 2 ENGINE - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF A NEW OIL PUMP UNIT WITH IMPROVED GEARS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
29-AUG-2014		MOS HRS/MSC - ENC					
SB BR700-79-900215 R01	NO. 2 ENGINE - OIL - EXCHANGE OF OIL FILTER DIFFERENTIAL PRESSURE SWITCH, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS HRS/MSC - ENC		19-AUG-2013 0 0			
SB BR700-79-900215 R02	NO. 2 ENGINE - OIL - EXCHANGE OF OIL FILTER DIFFERENTIAL PRESSURE SWITCH, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS HRS/MSC - ENC		19-AUG-2013 0 0			
SB BR700-79-900448	NO. 2 ENGINE - OIL - MAGNETIC CHIP DETECTORS (MCD) - REVISED INSPECTION SCHEDULE OF THE FRONT BEARING CHAMBER (FBC) MCD AND MANAGEMENT OF POTENTIAL NON-CONFORMING HIGH PRESSURE (HP) COMPRESSOR NO.3 BEARING ASSEMBLIES - NON-MODIFICATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
05-AUG-2013		MOS HRS/MSC - ENC					
SB BR700-79-900448 PART A	NO. 2 ENGINE - INTRODUCTION OIL - MAGNETIC CHIP DETECTORS (MCD) - REVISED INSPECTION SCHEDULE OF THE FRONT BEARING CHAMBER (FBC) MCD AND MANAGEMENT OF POTENTIAL NON-CONFORMING HIGH PRESSURE (HP) COMPRESSOR NO.3 BEARING ASSEMBLIES - NON-MODIFICATION, SERVICE BULLETIN OF A REVISED FRONT BEARING CHAMBER (FBC) MAGNETIC CHIP DETECTOR (MCD) INSPECTION INTERVAL FOR ALL POTENTIALLY AFFECTED ENGINES					RECOMMENDED	NOT APPLICABLE
05-AUG-2013		MOS HRS/MSC - ENC					
SB BR700-79-900448 PART B	NO. 2 ENGINE - INSTRUCTIONS OIL - MAGNETIC CHIP DETECTORS (MCD) - REVISED INSPECTION SCHEDULE OF THE FRONT BEARING CHAMBER (FBC) MCD AND MANAGEMENT OF POTENTIAL NON-CONFORMING HIGH PRESSURE (HP) COMPRESSOR NO.3 BEARING ASSEMBLIES - NON-MODIFICATION, SERVICE BULLETIN FOR THE REMOVAL OF POTENTIALLY AFFECTED HIGH PRESSURE (HP) COMPRESSOR NO.3 BEARING ASSEMBLIES FROM SERVICE					RECOMMENDED	NOT APPLICABLE
05-AUG-2013		MOS HRS/MSC - ENC					
SB BR700-79-900541 R01	NO. 2 ENGINE - OIL - GENERAL - SAMPLING OF THE ENGINE OIL SYSTEM, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - NO ACTION REQUIRED DUE TO NO LOSS OF OIL AT PRV
11-JAN-2012		MOS HRS/MSC - ENC		24-APR-2014 4.7 5			
SB BR700-80-100077	NO. 2 ENGINE - STARTING - AIR TURBINE STARTER - REPLACEMENT OF OUTPUT SHAFT ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
19-FEB-1998		MOS HRS/MSC - ENC		19-AUG-2013			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

GLOBAL 5000 GVFD S/N 9575 (N813WB): 1065.5HRS, 454 AFL as of 14-Sep-2022

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 01-Dec-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-80-100470	NO. 2 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A DUAL-PLANE BALANCED TURBINE WHEEL AND A REVISED METHOD OF MAGNETIC CHIP DETECTOR ATTACHMENT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
29-SEP-1998		MOS HRS/MSC - ENC			19-AUG-2013		
SB BR700-80-100640	NO. 2 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW STANDARD OF AIR TURBINE STARTER UNIT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
11-MAR-1999		MOS HRS/MSC - ENC			19-AUG-2013		
SB BR700-80-101018 R03	NO. 2 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
05-SEP-2005		MOS HRS/MSC - ENC			19-AUG-2013		
SB BR700-80-101729	NO. 2 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH MODIFIED TURBINE THRUST BEARING, SEAL AND RETAINING RING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC - ENC			19-AUG-2013		
SB BR700-80-101741	NO. 2 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH MODIFIED OIL FILL PORTS TO IMPROVE THE MAINTENANCE OIL FILL PROCEDURE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC - ENC			19-AUG-2013		