

Unit ID	Meter Amt	Complete Date	WO Complaint	WO Correction
24600001	16099	8/21/2018	WASH AND STEAM	WASHED AND STEAMED
24600001	15998	8/6/2018	LEFT FRONT & LEFT REAR TIRES ARE LOOSING 40 PSI PER DAY 29.5R25	REPLACED LF & LR TIRES W/SPARE 29.5R25
24600001	15895	7/11/2018	HAS ACTIVE PAYLOAD MEMORY LOW CODE THAT CANNOT BE CLEARED	INSTALLED NEW FUEL TEMPERATURE SENSOR
24600001	15886	7/9/2018	HAS SEVERAL FAULT CODES THAT NEED CHECKED. SEE LIST OF CODES	CLEARED AND TESTED
24600001	15886	7/9/2018	STILL NO CRANK/NO START STILL HAVE TO BEAT ON STARTER	INSTALLED NEW STARTER
24600001	15878	7/6/2018	NO CRANK NO START	TIGHTENED WIRING
24600001	15480	5/1/2018	HARD TO STEER TO THE RIGHT	INSTALLED NEW STEERING SHAFT
24600001	15480	4/16/2018	NO CRANK/ NO START	REPLACED BATTERIES
24600001	15389	3/30/2018	MAIN GREASE LINE AT BOTTOM OF GREASER IS BROKEN	REPLACED MAIN FEED LINE WITH HYDRAULIC HOSE
24600001	15043	1/2/2018	ENGINE DIED AND WONT RESTART	REPLACED BOTH FUEL FILTERS AND TEST RAN
24600001	14803	11/29/2017	ACTIVE CODE FOR TILT POSITION SENSOR	INSTALLED NEW HARNESS
24600001	14803	11/29/2017	PARKING BRAKE LIGHT STAYING ON	INSTALLED NEW PARKING BRAKE SWITCH
24600001	14621	10/17/2017	PM2 Inspection - Decision Machine	PERFORMED PM2 INSPECTION
24600001	14030	8/23/2017	CHECK PARKING BRAKE OPERATION	CHECKED PARKING BRAKE OPERATION, CHECKED OK
24600001	14244	8/21/2017	BUCKET LINER CRACKED	ARC AIRED CRACKS AND RE-WELDED
24600001	14123	8/8/2017	DRIVE TRAIN NOISE ON 3-2 DOWNSHIFT, POPS LOUD BUT NOT ON 2-1 DOWNSHIFT	INSTALLED NEW DRIVE SHAFT USING NEW BOLTS
24600001	14030	7/25/2017	NO CRANK/NO START	INSTALLED NEW STARTER
24600001	14021	7/24/2017	WELD ON BUCKET SIDES WEAR PLATES?	RE-WELDED OUTSIDE WEAR LINES
24600001	13584	5/23/2017	FRONT WIPER WORKS INTERMITTENTLY	REPLACED MOTOR
24600001	13613	5/30/2017	INSTALL USED TIRE TO MATCH ON RIGHT FRONT 29.5R25	INSTALLED USED TIRE ON RF 29.5R25
24600001	15576	5/4/2018	ENGINE STILL SHUTTING DOWN	REPLACED STARTER
24600001	13386	4/21/2017	ENGINE DIED AND WOULD NOT RESTART FOR 10-15 MINUTES	NO PROBLEM FOUND NO CORRECTION MADE
24600001	13287	4/4/2017	Repair leaking tilt cylinder	INSTALLED TILT CYLINDER AND INSTALLED TWO NEW HYDRAULIC HOSES
24600001	13287	4/4/2017	Repair leak @ transmission	INSTALLED NEW HOSE AND CLAMPS
24600001	13287	4/4/2017	Adjust valves on engine & tune up	ADJUSTED VALVES ON ENGINE & PERFORMED ENGINE TUNE UP
24600001	13287	4/4/2017	Misc minor hydraulic repairs	Misc minor hydraulic repairs
24600001	13287	4/4/2017	Repair prelube system - motor not working	INSTALLED NEW SWITCH
24600001	13287	4/4/2017	Repair leak @ exhaust manifold	INSTALLED NEW EXHAUST MANIFOLD AND INSTALLED NEW SEALS
24600001	13287	4/4/2017	Repair burnt out dash lights	REPLACED ALL BLOWN BULBS AND REPLACED THE GAUGE CLUSTER
24600001	13287	4/4/2017	Repair leak @ steering orbital	INSTALLED NEW PILOT VALVE
24600001	13287	4/4/2017	Repair parking brake	INSTALLED NEW PIN IN THE ACTUATOR
24600001	13287	4/4/2017	Repair left rear step	REPLACED LEFT FRONT BOTTOM STEP
24600001	13287	4/4/2017	REPLACE NEEDED GREASE LINES	REPLACED NEEDED GREASE LINES
24600001	13287	4/4/2017	Replace cutting edges - JRJ supplied	REPLACED CUTTING EDGES
24600001	12821	11/22/2016	BUCKET LEVELER AND RETURN TO DIG INOP THROWING CODES	PLUGGED IN LEVEL SENSOR
24600001	12776	11/9/2016	BLOWER MOTOR INOPERATIVE	REPLACED MOTOR
24600001	13287	4/4/2017	Misc minor PM repairs - Cincy Cat Shop	Misc minor PM repairs - Cincy Cat Shop
24600001	12224	9/30/2016	PARKING BRAKE WILL NOT HOLD	ADJUSTED PARKING BRAKE
24600001	12339	9/2/2016	PM2 Inspection - Decision Machine	PERFORMED PM2 INSPECTION
24600001	12135	8/8/2016	REPLACE BOTH FRONT TIRES W/NEW AND MOVE CURRENT FRONT TIRES TO REARS	REPLACED BOTH FRONT TIRES AND MOVED CURRENT FRONT TIRES TO REARS
24600001	11805	6/20/2016	TORE UP - REPLACE BLOWN LR TIRE	REPLACED LR TIRE W/USED 29.5R25
24600001	11591	5/12/2016	Repair antifreeze leak @ turbo	REPLACED COOLANT HOSE FOR THE TURBO

24600001	11038	5/5/2016	Repair leaks @ transmission cooler	CLEANED DEBRIS OUTSIDE OF COOLER, RESEALED COOLER AND REPLACED HOSE
24600001	11038	5/5/2016	Repair leak @ top of radiator	REPLACED UPPER RADIATOR HOSE AND CLAMP AND RADIATOR CAP
24600001	11038	5/5/2016	Front differential pinion seal leaking	INSTALLED NEW PINION SEAL
24600001	11038	5/5/2016	Replace bucket pivot pins & bushings - will not take grease	REPLACED BUCKET PIVOT PINS AND BUSHINGS
24600001	11038	5/5/2016	Misc minor hydraulic repairs	Misc minor hydraulic repairs
24600001	11038	5/5/2016	Adjust valves on engine	ADJUSTED VALVES ON ENGINE
24600001	11038	5/5/2016	Replace center Z bar pin & bushing	INSTALLED NEW BUSHINGS AND SEALS
24600001	11038	5/5/2016	Repair operator seat - will not recline	REPLACED OPERATOR SEAT
24600001	11038	5/5/2016	Replace missing seals on engine door panels	INSTALLED NEW SEALS
24600001	0	3/28/2016	250 hour PM Service	
24600001	11038	5/5/2016	Misc minor PM repairs - Cincy Cat Field	Misc minor PM repairs - Cincy Cat Field
24600001	0	12/8/2015	SCALE SYSTEM IS OPERATING ERRATICALLY -AGAIN	
24600001	0	11/20/2015	TRANSMISSION TEMPERATURE GAUGE FLUCTUATING-AGAIN	ADMINISTRATIVELY CLOSED
24600001	10527	11/20/2015	TRANSMISSION TEMPERATURE GAUGE FLUCTUATING	INSTALLED NEW TRANSMISSION TEMPERATURE SENSOR
24600001	10285	11/4/2015	Scale system not working	TROUBLESHOT DECK SCALE
24600001	10291	10/19/2015	PREVENTATIVE- UPGRADE TIRES: NEW FRONTS & NEW CAPS ON REAR 29.5R25	REPLACED BOTH FRONT & REAR TIRES W/NEW 29.5R25
24600001	10250	10/12/2015	LEFT FRONT TIRE FLAT 29.5R25	REPLACED LEFT FRONT TIRE 29.5R25
24600001	10672	12/15/2015	PM2 Inspection	PERFORMED PM2 INSPECTION
24600001	10892	10/2/2015	WILL NOT SHIFT FROM FORWARD TO REVERSE	INSTALLED NEW SWITCH
24600001	10069	9/15/2015	RIGHT REAR VALVE STEM IS LEAKING	REPAIRED RR TIRE & REPLACED R-520 VALVE STEM
24600001	9935	8/25/2015	SCALE SYSTEM IS OPERATING ERRATICALLY	RE-CALIBRATED DECK SCALE
24600001	9609	7/7/2015	AIR CONDITIONING INOPERATIVE	REPLACED HOSE & SEAL O-RINGS
24600001	9308	5/12/2015	FLUID LEAK UNDER CAB	INSTALLED TEST PORT LINE
24600001	9222	4/29/2015	DEBRIS ROCK CUT - 20/32 LEFT - RIGHT FRONT TIRE FLAT 29.5R25	REPLACED RIGHT FRONT TIRE 29.5R25
24600001	9108	4/15/2015	GREASER INOP	REPLACED WIPER AND RESERVOIR
24600001	9088	4/8/2015	WILL NOT TILT, CURL OR LIFT THE BUCKET	REPLACED BAD PILOT PRESSURE KICK OUT VALVE AND SOLENOID
24600001	9044	4/2/2015	FRONT WINDSHIELD WIPER INOP	REPLACED FRONT WINDSHIELD WIPER MOTOR
24600001	8990	3/27/2015	seat won't hold adjustment	replace broken seat pan
24600001	8980	3/31/2015	PRE-LUBE SYSTEM WILL NOT SHUT OFF INTERMITTENTLY	REPLACED PRE-LUBE SYSTEM PRESSURE SWITCH
24600001	8808	2/27/2015	Engine block heater not working	INSTALLED NEW BLOCKER HEATER AND DRAIN VALVE
24600001	8808	2/27/2015	Hydraulic oil sample reported high sodium - check & advise	REPLACED FILTER AND ADDED HYDRAULIC OIL
24600001	8808	2/27/2015	Ride control not working	REPAIRED RIDE CONTROL
24600001	8808	2/27/2015	Harsh downshifting from 4th to 3rd gear	CALIBRATED THE TRANSMISSION
24600001	8808	2/27/2015	Adjust valves on engine	ADJUSTED VALVES ON ENGINE
24600001	8808	2/27/2015	Repair exhaust leak @ manifold & turbo	INSTALLED NEW GASKET, STUDS SPACERS AND NUTS.
24600001	8808	2/27/2015	Replace seat belt	REPLACED SEAT BELT
24600001	8808	2/27/2015	Misc minor PM repairs - Cincy Cat Field	misc/ minor pm repairs completed
24600001	0	2/19/2015	PARK BRAKE WILL NOT DISENGAGE, LOADER WILL NOT RAISE	ADMINISTRATIVELY CLOSED
24600001	8180	10/24/2014	PM2 Inspection	PM2 Inspection
24600001	8055	9/3/2014	PLASTIC TEST PORT HOSE LEAKING (FOR STEERING?)	replaced hose
24600001	0	7/19/2014	Batteries are boiling over	NEW BATTERIES & ALTERNATOR
24600001	6989	4/25/2014	Re-calibrate transmission	CALIBRATED TRANSMISSION
24600001	6970	3/27/2014	2000 hr service due	perform 2000 hr service
24600001	6989	4/25/2014	VLError EID49 - Coasting in neutral warning again	FLASHED SOFTWARE AND PERFORMED NEEDED CALIBRATIONS

24600001	6989	3/31/2014	VLError EID49 - Coasting in neutral warning	FLASHED SOFTWARE AND PERFORMED NEEDED CALIBRATIONS
24600001	6664	3/4/2014	Right bucket pivot pin will not take grease	REPAIRED GREASE LINE TO RIGHT BUCKET PIN & TIGHTENED LINES
24600001	6625	2/26/2014	LEFT FRONT TIRE IS LOW 29.5R25	REPLACED O-RING
24600001	0	2/7/2014	Re-seal windshield	ADMINISTRATIVELY CLOSED
24600001	0	2/5/2014	Interlube grease system not working	ADMINISTRATIVELY CLOSED
24600001	6376	1/16/2014	Cab heat cooling valves leaking	INSTALLED NEW VALVES
24600001	6376	1/16/2014	Repair exhaust leak @ turbo & manifold	INSTALLED NEW CLAMP ON TURBO
24600001	6376	1/16/2014	Replace seat belt	INSTALLED NEW SEAT BELT
24600001	6376	1/16/2014	Weight scales not reading correctly	CLEANED BUCKET AND CALIBRATED SCALES
24600001	6376	1/16/2014	Misc/minor PM repairs - Cat Field	INSTALLED NEW HEATER CORD, TIGHTENED RADIATOR CLAMPS
24600001	6235	11/26/2013	trans and diff service	
24600001	6288	11/26/2013	PM2 INSPECTION	PM2 INSPECTION
24600001	6102	10/10/2013	ALTERNATOR BELT CAME OFF	REPLACED ALTERNATOR BELT AND TENSIONER
24600001	5988	9/6/2013	45/32 -RIGHT FRONT TIRE IS LEAKING 20 PSI EVERY 3 DAYS 29.5R25	*KEEP WO 50 TILL TREADSTAT SHOWS TIRE OFF TRANSACTION COMPLETE HV7MNA229*
24600001	4783	12/11/2012	ENGINE VALVE ADJUSTMENT	TIMED THE ENGINE, CHECKED VALVE ADJUSTMENT
24600001	4783	12/11/2012	REPAIR MUFFLER	REPLACED MUFFLER
24600001	4783	12/11/2012	MISC/MINOR PM REPAIRS	INSTALLED NEW RUBBER ON STEP, ADJUSTED DOOR STRIKER, CALIBRATED SCALES
24600001	4676	11/15/2012	PM2 INSPECTION	PM2 INSPECTION
24600001	4292	8/22/2012	ENGINE DIED WHILE RUNNING	REPLACED FUEL TRANSFER PUMP
24600001	0	5/25/2012	ALL 4 TIRES ARE WORE OUT	REPLACED ALL 4 TIRES WITH NEW
24600001	3808	4/12/2012	LOADER SCALE SYSTEM IS NOT READING 1/2 BUCKETS CORRECTLY	CALIBRATED POSITION SENSORS AND RESET TEST WEIGHT IN THE ECM SUMMARY
24600001	3414	2/13/2012	REPAIR HYDRAULIC LEAK @ FAN MOTOR	INSTALLED A NEW HOSE AND SEALS
24600001	3414	2/13/2012	CHECK TRANSMISSION FOR DEBRIS / PARTICLE COUNT ELEVATED	CHANGED TRANS FLUID AND FILTER, CHECKED FOR DEBRIS & EVERYTHING WAS OK
24600001	3414	2/13/2012	REPAIR EXHAUST LEAK @ MANIFOLD	RESEALED THE EXHAUST MANIFOLD
24600001	3414	2/13/2012	MISC/MINOR PM REPAIRS	INSTALLED LADDER, REPLACED MISC LIGHTS, TROUBLE SHOT FUEL SYSTEM
24600001	3353	1/20/2012	PM2 INSPECTION	PM2 INSPECTION, INSPECTED BUCKET
24600001	2614	8/16/2011	FAN MOTOR STOPPED WORKING	REMOVED DEBRIS FROM FAN MOTOR
24600001	1619	3/15/2011	KIDNEY LOOP HYDRAULIC SYSTEM	OIL SAMPLE AND CHECKED PARTICLE LEVEL
24600001	1619	3/15/2011	CALIBRATE TRANSMISSION	CALIBRATED TRANS, AND CLUTCH FILL CALIBRATIONS
24600001	1619	3/15/2011	EXHAUST MANIFOLD LEAKING	NEW EXHAUST GASKETS AND HARDWARE
24600001	1619	3/15/2011	CODE 036-0094 FUEL DELIVERY PRESSURE	ADMINISTRATIVELY CLOSED
24600001	1619	3/14/2011	MISC/MINOR PM REPAIRS	INSTALLED NEW LEFT ARMREST, CLEANED RADIATOR, NEW FILTERS
24600001	1413	1/25/2011	PM2 INSPECTION	PERFORM PM 2 INSPECTION
24600001	0	11/19/2010	CHECK INTERLUBE SYSTEM-NOT PUTTING OUT ANY GREASE AGAIN / STILL	FLAT SPOT ON WIPER ARM ROUNDED OUT
24600001	0	10/12/2010	CHECK INTERLUBE SYSTEM-NOT PUTTING OUT ANY GREASE	INSTALLED NEW PUMP CARTRIDGE & TESTED
24600001	142	7/20/2010	CAT 125 HOUR SERVICE	PERFORMED CAT 125 HOUR SERVICE
24600001	0	8/15/2011	ROTATE TIRES @ 45% RTD REARS - FRONTS TO BACK, BACKS TO FRONT	
24600001	100	6/17/2010	ENGINE KNOCK / TICK NOISE ABOVE IDLE	RREPLACED ENGINE
24600001	0	6/1/2010	INSTALL RFID FUEL RINGS	INSTALLED RFID FUEL RINGS
24600001	0	6/7/2010	INSTALL INTERLUBE LUBE SYSTEM	INSTALLED INTERLUBE LUBE SYSTEM
24600001	0	6/3/2010	NEW EQUIPMENT SETUP	NEW EQUIPMENT SETUP
24600001	10	6/7/2010	INSTALL BUCKET BOTTOM LINER & WEAR PROTECTION	WELDED ¼" HARDOX ON SIDES, ½" ROLLED HARDOX ON FLOOR & CRONAPLATE ON MOLDBOARD E