

Unit Job History

Michels Corporation
Report Printed: 03-Jan-2020 08:33:09 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: E1028 - 2008 TOYOTA 426FCU20										
03-Jun-2013 11:18:35	6,748	0	118829	03-017-001	Replace Tire - Pneumatic		BTIRE	F	CAN	0.00
03-Jun-2013 11:18:35	6,748	0	118829	03-017-005	Replace Tire - Solid	03-Jun-2013 11:19:52	BTIRE	F	DON	140.63
29-Oct-2013 09:18:12	7,013	0	135238	03-033-003	Replace Spark Plugs	21-Jan-2014 06:40:41	NBYARD	I	DON	282.67
08-Apr-2019 06:00:00	8,865	0	380089	06-100-PMB	Inspect B PMI	08-Apr-2019 16:00:00	NBSHP	P	DON	0.00
08-Apr-2019 06:00:00	8,865	0	380089	38-100-PMB	Service B PMI	08-Apr-2019 16:00:00	NBSHP	P	DON	140.92
27-Jan-2016 07:56:55	7,780	0	230899	03-033-004	Replace Spark Plug Wires	31-Mar-2016 07:00:00	NBSHP	O	DON	247.99
27-Jan-2016 07:56:55	7,780	0	230899	03-042-004	Replace Water Pump	31-Mar-2016 07:00:00	NBSHP	O	DON	262.97
27-Jan-2016 07:56:55	7,780	0	230899	03-065-007	Replace Hoses & Fittings	31-Mar-2016 07:00:00	NBSHP	O	DON	831.77
27-Jan-2016 07:56:55	7,780	0	230899	24-042-002	Repair Radiator	31-Mar-2016 07:00:00	NBSHP	O	DON	1,163.83
27-Jan-2016 07:56:55	7,780	0	230899	38-045	Service Power Plant	31-Mar-2016 07:00:00	NBSHP	P	DON	148.49
26-Aug-2013 10:58:55	6,948	0	128562	38-040	Service Engine / Motor Systems Group	19-Sep-2013 16:09:46	NBYARD	P	DON	128.71
13-Sep-2018 06:00:00	8,756	0	352046	03-017-005	Replace Tire - Solid	07-Dec-2018 16:00:00	NBSHP	O	DON	766.19
13-Sep-2018 06:00:00	8,756	0	352046	03-032-001	Replace Battery	07-Dec-2018 16:00:00	NBSHP	O	DON	131.70
13-Sep-2018 06:00:00	8,756	0	352046	03-506-003	Replace Propane Tank	07-Dec-2018 16:00:00	NBSHP	O	DON	19.30
18-Apr-2018 07:00:00	8,549	0	334964	06-266	Inspect Forklift	10-May-2018 16:00:00	NBSHP	O	DON	432.96
16-Jan-2017 07:00:00	8,456	0	273679	01-266-003	Adjust Mast	05-Jan-2018 16:00:00	NBSHP	O	DON	44.79
16-Jan-2017 07:00:00	8,456	0	273679	03-033-003	Replace Spark Plugs	05-Jan-2018 16:00:00	NBSHP	O	DON	14.93
16-Jan-2017 07:00:00	8,456	0	273679	03-033-004	Replace Spark Plug Wires	05-Jan-2018 16:00:00	NBSHP	O	DON	219.07
16-Jan-2017 07:00:00	8,456	0	273679	03-033-005	Replace Cap / Rotor	05-Jan-2018 16:00:00	NBSHP	O	DON	29.86
16-Jan-2017 07:00:00	8,456	0	273679	03-042-004	Replace Water Pump	05-Jan-2018 16:00:00	NBSHP	O	DON	875.28
16-Jan-2017 07:00:00	8,456	0	273679	03-042-006	Replace Thermostat	05-Jan-2018 16:00:00	NBSHP	O	DON	38.49
16-Jan-2017 07:00:00	8,456	0	273679	03-054-001	Replace Horn & Mounting	05-Jan-2018 16:00:00	NBSHP	O	DON	183.48
16-Jan-2017 07:00:00	8,456	0	273679	03-268-002	Replace Cables and Pulleys (Sheaves)	05-Jan-2018 16:00:00	NBSHP	O	DON	151.75
16-Jan-2017 07:00:00	8,456	0	273679	06-100-PMB	Inspect B PMI	05-Jan-2018 16:00:00	NBSHP	P	DON	118.67
16-Jan-2017 07:00:00	8,456	0	273679	24-002-061	Repair Seat Cushion	05-Jan-2018 16:00:00	NBSHP	O	DON	314.99
17-Mar-2014 06:22:33	7,311	0	150402	06-003-009	Inspect Fuel Gauge	26-Nov-2014 10:40:52	NBYARD	O	DON	0.00
17-Mar-2014 06:22:33	7,311	0	150402	06-032-002	Inspect Starter	26-Nov-2014 10:40:52	NBYARD	O	DON	350.28
17-Mar-2014 06:22:33	7,311	0	150402	06-042-004	Inspect Water Pump	26-Nov-2014 10:40:52	NBYARD	O	DON	385.00
17-Mar-2014 06:22:33	7,311	0	150402	06-054-001	Inspect Horn & Mounting	26-Nov-2014 10:40:52	NBYARD	O	DON	267.76

Unit Job History

Michels Corporation
Report Printed: 03-Jan-2020 08:33:09 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: E1028 - 2008 TOYOTA 426FCU20										
17-Mar-2014 06:22:3	7,311	0	150402	06-100-PMA	Inspect A PMI	26-Nov-2014 10:40:52	NBYARD	P	DON	387.81
17-Mar-2014 06:22:3	7,311	0	150402	06-266-002	Inspect Fork Assembly	26-Nov-2014 10:40:52	NBYARD	O	DON	19.39
17-Mar-2014 06:22:3	7,311	0	150402	06-266-003	Inspect Mast	26-Nov-2014 10:40:52	NBYARD	O	DON	405.53
16-Dec-2014 11:59:0	7,571	0	184834	06-042	Inspect Cooling System	27-May-2015 09:02:38	NBYARD	O	DON	235.95
16-Dec-2014 11:59:0	7,571	0	184834	06-100-PMA	Inspect A PMI	27-May-2015 09:02:38	NBYARD	P	DON	154.16
16-Dec-2014 11:59:0	7,571	0	184834	06-268-002	Inspect Cables and Pulleys (Sheaves)	27-May-2015 09:02:38	NBYARD	O	DON	152.87
19-Nov-2012 11:16:0	6,748	0	100976	38-040	Service Engine / Motor Systems Group	19-Nov-2012 14:30:00	NBYARD	J	DON	109.28
19-Nov-2014 14:23:1	7,013	0	181626	38-017-011	Service Tire - Foam Filled	19-Nov-2014 14:23:31	BTIRE	F	DON	243.53
05-Dec-2019 08:21:5	9,087	0	415343	02-266	Clean Forklift	10-Dec-2019 17:00:40	BWASH	N	DON	86.55
05-Dec-2019 08:21:5	9,087	0	415343	06-100-FRK	Inspect Forklift Inspection	16-Dec-2019 13:02:15	BSMEQP	P	DON	88.69
05-Dec-2019 08:21:5	9,087	0	415343	06-100-PMA	Inspect A PMI	16-Dec-2019 10:19:22	BSMEQP	P	DON	201.73
05-Dec-2019 08:21:5	9,087	0	415343	38-266	Service Forklift		BSMEQP	P	CAN	0.00
01-Dec-2016 07:00:0	8,139	0	268236	06-100-PMB	Inspect B PMI	09-Dec-2016 07:00:00	NBSHP	P	DON	87.78
31-May-2016 07:00:0	7,950	0	246437	03-032-002	Replace Starter	01-Jun-2016 16:00:00	NBSHP	O	DON	293.65
08-Oct-2015 15:20:21	7,762	0	217721	14-034-014	Install Auxiliary Work / Flood Light	29-Oct-2015 10:56:05	NBYARD	O	DON	233.46
11-Jul-2019 06:00:00	8,865	0	402373	03-033-003	Replace Spark Plugs	10-Sep-2019 14:43:54	NBSHP	O	DON	224.09
16-Aug-2019 00:00:0	8,865	0	399255	11-065-004	Rebuild Cylinder	27-Aug-2019 00:00:00	BVLOFC	B	DON	914.39
20-Jul-2018 06:00:00	8,628	0	344659	06-100-PMB	Inspect B PMI	31-Jul-2018 16:00:00	NBSHP	P	DON	112.29
22-Sep-2014 10:41:44	7,013	0	173112	24-017-001	Repair Tire - Pneumatic	22-Sep-2014 10:42:06	BTIRE	E	DON	43.49

Unit No: E1028

Count: 48

11,687.12