



Maintenance Items

16-Mar-2022

N393BV

Make & Model (Serial)
BOMBARDIER GLOBAL EXPRESS XRS (9385)

Operator
IAC Expedia Global LLC

Reported Date
15-Mar-2022

Hours
4455.80

Landings
1495

- Major Components

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 000-1000H Airframe INSPECTION #2267	1000 HOUR CHECK	10-MAR-2022 H: 4455.80 L: 1495	H: 1000.00			H: 5455.80	H: 1000.00
05 000-1500H Airframe INSPECTION #658	1500 HOUR CHECK	08-FEB-2022 H: 4399.80 L: 1478	H: 1500.00	H: 50.00		H: 5899.80	H: 1444.00
05 000-1800L Airframe INSPECTION #4944	1800 LANDING CHECK	10-MAR-2022 H: 4455.80 L: 1495	L: 1800			L: 3295	L: 1800
05 000-2250H Airframe INSPECTION #1027	2250 HOUR CHECK	31-MAR-2020 H: 3741.10 L: 1233	H: 2250.00	H: 50.00		H: 5991.10	H: 1535.30
05 000-24M Airframe INSPECTION #4947	24 MONTH CHECK	09-MAR-2022 H: 4455.80 L: 1495	M: 24			09-MAR-2024	M: 23 D: 22
05 000-250H Airframe INSPECTION #4943	250 HOUR CHECK	08-FEB-2022 H: 4399.80 L: 1478	H: 250.00	H: 25.00		H: 4649.80	H: 194.00
05 000-3000H Airframe INSPECTION #1578	3000 HOUR CHECK	01-DEC-2018 H: 3011.20 L: 1025	H: 3000.00	H: 50.00		H: 6011.20	H: 1555.40





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 000-3750L Airframe INSPECTION #4945	3750 LANDING CHECK	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
05 000-4500H Airframe INSPECTION #2403	4500 HOUR CHECK	21-MAR-2010 H: 0.00	H: 4500.00	H: 50.00		H: 4500.00	H: 44.20
		Work Order Number FLL BAS 9385	Scheduled 19-Mar- 2022	Man Hours 0.00			
05 000-450L Airframe INSPECTION #1140	450 LANDING CHECK	10-MAR-2022 H: 4455.80 L: 1495	L: 450	L: 50		L: 1945	L: 450
05 000-5000H Engine 1 INSPECTION #4846	NO. 1 ENGINE 5000 HOUR CHECK		H: 5000.00			H: 5000.00	H: 544.20
05 000-5000H Engine 2 INSPECTION #4868	NO. 2 ENGINE 5000 HOUR CHECK		H: 5000.00			H: 5000.00	H: 544.20
05 000-500H Airframe INSPECTION #294	500 HOUR CHECK	10-MAR-2022 H: 4455.80 L: 1495	H: 500.00	H: 50.00		H: 4955.80	H: 500.00
05 000-7500L Airframe INSPECTION #4946	7500 LANDING CHECK	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
05 000-750H Airframe INSPECTION #2300	750 HOUR CHECK	08-FEB-2022 H: 4399.80 L: 1478	H: 750.00	H: 50.00		H: 5149.80	H: 694.00
05 000-900L Airframe INSPECTION #226	900 LANDING CHECK	29-SEP-2017 H: 2431.70 L: 854	L: 900	L: 50		L: 1754	L: 259





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 001-1000 Engine 1 INSPECTION #4848	ENGINE 1 - 1000 HOUR INSPECTION PACKAGE	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00			H: 4741.10	H: 285.30
05 001-120M Airframe INSPECTION #1442	120 MONTH CHECK	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
05 001-15M Airframe INSPECTION #673	15 MONTH CHECK	19-APR-2021 H: 3992.00 L: 1324	M: 15	M: 3		19-JUL-2022	M: 4 D: 3
05 001-180M Airframe INSPECTION #1569	180 MONTH CHECK	15-FEB-2011 H: 0.00	M: 180	M: 3		15-FEB-2026	M: 46 D: 30
05 001-2000H Engine 1 INSPECTION #4847	ENGINE 1 - 2000 HOUR CHECK	01-DEC-2018 H: 3011.20 C: 1025	H: 2000.00			H: 5011.20	H: 555.40
05 001-240M Airframe INSPECTION #2545	240 MONTH / 120 MONTH CHECK	21-MAR-2010 H: 0.00	M: 240	M: 3		21-MAR-2030	M: 96 D: 5
05 001-30M Airframe INSPECTION #1645	30 MONTH CHECK	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
05 001-60M Airframe INSPECTION #1507	60 MONTH CHECK	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
05 002-1000 Engine 2 INSPECTION #4870	ENGINE 2 - 1000 HOUR INSPECTION PACKAGE		H: 1000.00			H: 4741.10	H: 285.30
05 002-2000H Engine 2 INSPECTION #4869	ENGINE 2 - 2000 HOUR CHECK	01-DEC-2018 H: 3011.20 C: 1025	H: 2000.00			H: 5011.20	H: 555.40



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 1000APU APU INSPECTION #4739	APU - 1000 HOUR APU	17-JUL-2021 H: 3565.00 C: 3059	H: 1000.00	H: 50.00		H: 4565.00	H: 777.00
05 1500APU APU INSPECTION #1240	APU - 1500 HOUR APU	08-DEC-2019 H: 3204.00 C: 2674	H: 1500.00	H: 50.00		H: 4704.00	H: 916.00
05 750APU APU INSPECTION #2915	APU - 750 HOUR APU	10-MAR-2022 H: 3788.00 C: 3274	H: 750.00	H: 50.00		H: 4538.00	H: 750.00
05 BR710-05-10-01-860-002 Engine 1 INSPECTION #2348	NO. 1 ENGINE - VISUAL AND ULTRASONIC INSPECTION OF THE LP COMPRESSOR DISK	21-MAR-2010 H: 0.00					
05 BR710-05-10-01-860-002 Engine 2 INSPECTION #832	NO. 2 ENGINE - VISUAL AND ULTRASONIC INSPECTION OF THE LP COMPRESSOR DISK	21-MAR-2010 H: 0.00					
11 30-50-601 Airframe INSPECTION 30M #868	GENERAL VISUAL INSPECTION OF CABIN PLACARDS-INTERNAL Reference Number 11-30-50-210-801 Notes NO DEFECTS NOTED	19-APR-2021 H: 3992.00 L: 1324	M: 30			19-OCT-2023	M: 19 D: 3
12 Airframe INSPECTION #5043	POST FLIGHT / PRE-FLIGHT TURN AROUND Work Order Number E.O.M. MAR 22	Scheduled 28-Feb- 2022	Man Hours 0.00			11-MAR-2022 H: 4455.80 L: 1495	
21 -51-25-45 Airframe PART #4862	LH PACK CONTROL VALVE SENSE LINE Part Number GD438-1405-5 Serial Number J/C M689349					26-JUL-2018 H: 2817.20 L: 966	





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 21-00-201 Airframe INSPECTION 1000 H #2074	OPERATIONAL TEST OF THE RECIRC SWITCH	10-MAR-2022 H: 4455.80 L: 1495	H: 1000.00	H: 50.00		H: 5455.80	H: 1000.00
21 21-17-201 Airframe INSPECTION 3000H #796	OPERATIONAL TEST OF THE BULKHEAD CHECK VALVES	01-DEC-2018 H: 3011.20 L: 1025	H: 3000.00	H: 50.00		H: 6011.20	H: 1555.40
21 21-25-201 Airframe INSPECTION #69	DISCARD THE RECIRCULATION FILTERS	08-OCT-2019 H: 3516.60 L: 1170	H: 1000.00	H: 50.00		H: 4516.60	H: 60.80
		Work Order Number	Scheduled	Man Hours			
		FLL BAS 9385	19-Mar- 2022	0.00			
21 2105-001 Airframe PART #1830	LH TRIM DUCT				21-MAR-2010 H: 0.00		
	Part Number	Serial Number					
	GG438-2066-1	1162					
21 2105-002 Airframe PART #1633	RH TRIM DUCT				21-MAR-2010 H: 0.00		
	Part Number	Serial Number					
	GG438-2066-1	1080					
21 2105-003 Airframe PART #2202	CENTER TRIM DUCT				21-MAR-2010 H: 0.00		
	Part Number	Serial Number					
	GG438-2066-1	1092					
21 2105-004 Airframe PART #468	MIX MANIFOLD				21-MAR-2010 H: 0.00		
	Part Number	Serial Number					
	PN	SN- UNKNOWN					
21 2109-001 Airframe PART #456	LH (MIX MANIFOLD) TEMPERATURE SENSOR				21-MAR-2010 H: 0.00		
	Part Number	Serial Number					
	PN	SN- UNKNOWN					
21 2109-002 Airframe PART #986	RH (MIX MANIFOLD) TEMPERATURE SENSOR				21-MAR-2010 H: 0.00		
	Part Number	Serial Number					
	PN	SN- UNKNOWN					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 2117-001 Airframe PART #2824	LH BULKHEAD CHECK VALVE Part Number PN	21-MAR-2010 H: 0.00	Serial Number SN- UNKNOWN				
21 2117-002 Airframe PART #137	RH BULKHEAD CHECK VALVE Part Number PN	21-MAR-2010 H: 0.00	Serial Number SN- UNKNOWN				
21 2121-001 Airframe PART #2330	LH RECIRCULATION FAN Part Number GG433-2030-9	21-MAR-2010 H: 0.00	Serial Number 882				
21 2121-002 Airframe PART #1769	RH RECIRCULATION FAN Part Number GG433-2030-9	21-MAR-2010 H: 0.00	Serial Number 942				
21 2125-001 Airframe PART FILTERS #2575	LH RECIRCULATION FILTER Part Number GG431-2031-1	08-OCT-2019 H: 3516.60 L: 1170	Serial Number 8319	Work Order Number FLL BAS 9385	Scheduled 19-Mar- 2022	Man Hours 0.00	
21 2125-002 Airframe PART FILTERS #934	RH RECIRCULATION FILTER Part Number GG431-2031-1	08-OCT-2019 H: 3516.60 L: 1170	Serial Number 8312	Work Order Number FLL BAS 9385	Scheduled 19-Mar- 2022	Man Hours 0.00	
21 2300-701 Airframe PART #2992	(RH GALLEY) EXHAUST FAN Part Number 11835	15-FEB-2011 H: 25.00 L: 11	Serial Number 109305347				
21 2300-702 Airframe PART #919	(AFT LAVATORY) EXHAUST FAN Part Number 11836000	15-FEB-2011 H: 25.00 L: 11	Serial Number 110398371				
21 2300-703 Airframe PART #2613	(FWD LAVATORY) EXHAUST FAN Part Number 11836000	15-FEB-2011 H: 25.00 L: 11	Serial Number 110341436				





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 31-00-101 Airframe INSPECTION 1500H #1049	OPERATIONAL TEST OF THE EMERGENCY DEPRESSURIZATION FUNCTION	08-FEB-2022 H: 4399.80 L: 1478	H: 1500.00			H: 5899.80	H: 1444.00
21 31-00-103 Airframe INSPECTION 120M #4	FUNCTIONAL TEST OF THE CABIN-PRESSURE LEAKAGE RATE	19-APR-2021 H: 3992.00 L: 1324	M: 120			19-APR-2031	M: 109 D: 3
	Notes NO DEFECTS NOTED						
21 31-00-201 Airframe INSPECTION 2250H #2438	OPERATIONAL TEST OF THE MANUAL MODE	31-MAR-2020 H: 3741.10 L: 1233	H: 2250.00	H: 50.00		H: 5991.10	H: 1535.30
21 31-00-203 Airframe INSPECTION 3000H #2090	OPERATIONAL TEST OF THE DITCHING FUNCTION	01-DEC-2018 H: 3011.20 L: 1025	H: 3000.00	H: 50.00		H: 6011.20	H: 1555.40
21 31-09-101 Airframe INSPECTION 3000H #2748	FUNCTIONAL TEST OF THE SAFETY VALVES	01-DEC-2018 H: 3011.20 L: 1025	H: 3000.00			H: 6011.20	H: 1555.40
21 31-11-201 Airframe PART - Life Limited 3000H #197	DISCARD THE SAFETY VALVE FILTERS	01-DEC-2018 H: 3011.20 L: 1025	H: 3000.00	H: 50.00		H: 6011.20	H: 1555.40
21 3101-001 Airframe PART #1546	LH CABIN PRESSURE CONTROLLER				21-MAR-2010 H: 0.00		
	Part Number	Serial Number					
	GG546-3001-11	937					
21 3101-002 Airframe PART #2122	RH CABIN PRESSURE CONTROLLER				21-MAR-2010 H: 0.00		
	Part Number	Serial Number					
	GG546-3001-11	940					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 3105-001 Airframe PART #439	FWD OUTFLOW VALVE Part Number GG435-3002-21 Serial Number 00515	12-OCT-2014 H: 1015.50 L: 386					
21 3105-002 Airframe PART #2894	AFT OUTFLOW VALVE Part Number GG435-3002-21 Serial Number 939	21-MAR-2010 H: 0.00					
21 3109-001 Airframe PART #2291	LH SAFETY VALVE Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
21 3109-002 Airframe PART #570	RH SAFETY VALVE Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
21 41-50-601 Airframe INSPECTION 30M #1733	OPERATIONAL TEST OF THE ENTRY AREA HEAT Reference Number 21-41-50-710-801 Notes NO DEFECTS NOTED	19-APR-2021 H: 3992.00 L: 1324	M: 30			19-OCT-2023	M: 19 D: 3
21 51-09-201 Airframe INSPECTION 3000H #2678	RESTORATION OF THE OZONE CONVERTER	01-DEC-2018 H: 3011.20 L: 1025	H: 3000.00	H: 50.00		H: 6011.20	H: 1555.40
21 5102-001 Airframe PART #77	LH VENTURI FLOW SENSOR Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
21 5102-002 Airframe PART #2865	RH VENTURI FLOW SENSOR Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
21 5105-003 Airframe PART #776	LH BLEED FILTER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 5105-004 Airframe PART #2630	RH BLEED FILTER Part Number PN	21-MAR-2010 H: 0.00	Serial Number SN- UNKNOWN				
21 5109-001 Airframe PART #126	LH OZONE CONVERTER Part Number GG431-2001-3	01-DEC-2018 H: 3011.20 L: 1025	Serial Number 6739				
21 5109-002 Airframe PART #1489	RH OZONE CONVERTER Part Number GG431-2001-3	01-DEC-2018 H: 3011.20 L: 1025	Serial Number 6748				
21 5113-001 Airframe PART #2778	LH PACK INLET FLOW SENSOR Part Number GG436-2003-1	21-MAR-2010 H: 0.00	Serial Number 2483				
21 5113-002 Airframe PART #2900	RH PACK INLET FLOW SENSOR Part Number GG436-2003-1	21-MAR-2010 H: 0.00	Serial Number 2487				
21 5117-001 Airframe PART #1998	LH PACK INLET PRESSURE SENSOR Part Number GG436-2004-1	21-MAR-2010 H: 0.00	Serial Number 2394				
21 5117-002 Airframe PART #1212	RH PACK INLET PRESSURE SENSOR Part Number GG436-2004-1	21-MAR-2010 H: 0.00	Serial Number 2398				
21 5121-001 Airframe PART #87	LH PACK INLET TEMPERATURE SENSOR. Part Number GG436-2005-3	22-JUN-2021 H: 4104.00 L: 1369	Serial Number 14977				
	Notes S/N 14977 REMOVED IN SERVICABLE CONDITION FROM N826BN S/N 9826 ON 28FEB2019.						
21 5121-002 Airframe PART #43	RH PACK INLET TEMPERATURE (INLET) SENSOR Part Number GG436-2005-3	19-DEC-2012 H: 426.50 L: 209	Serial Number 11088R				





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 5125-003 Airframe PART #118	LH SUPPLY DUCT Part Number GG468-4042-3 Serial Number 610	21-MAR-2010 H: 0.00					
21 5125-004 Airframe PART #2490	RH SUPPLY DUCT Part Number GG468-4042-3 Serial Number 622	21-MAR-2010 H: 0.00					
21 5125-006 Airframe PART #2962	LH SUPPLY DUCT ASSY Part Number GG468-4043-3 Serial Number 403	21-MAR-2010 H: 0.00					
21 5125-010 Airframe PART #2654	RH SUPPLY DUCT ASSY Part Number GG468-4056-3 Serial Number 429	21-MAR-2010 H: 0.00					
21 5125-011 Airframe PART #257	SENSE LINE Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
21 5125-012 Airframe PART #544	LH FLOW CONTROL VALVE Part Number GG436-2006-11 Serial Number 01274	26-FEB-2022 H: 4428.00 L: 1487					
21 5125-013 Airframe PART #812	RH FLOW CONTROL VALVE Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
21 52-00-101 Airframe INSPECTION 1500H #489	OPERATIONAL TEST OF THE MANUAL MODE OF THE AIR CONDITIONING SYSTEM	08-FEB-2022 H: 4399.80 L: 1478	H: 1500.00			H: 5899.80	H: 1444.00
21 5200-001 Airframe PART #707	LH COOLING PACK Part Number GG431-2007-7 Serial Number 894	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 5200-002 Airframe PART #48	RH COOLING PACK Part Number GG431-2007-7	Serial Number 918	21-MAR-2010 H: 0.00				
21 5201-001 Airframe PART #1440	LH PLENUM Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
21 5201-002 Airframe PART #2668	RH PLENUM Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
21 5205-001 Airframe PART #2479	LH DUAL HEAT EXCHANGER Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
21 5205-002 Airframe PART #98	RH DUAL HEAT EXCHANGER Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
21 5209-001 Airframe PART #2189	LH AIR CYCLE MACHINE ACM Part Number GG431-2010-3	Serial Number 01099	09-DEC-2021 H: 4382.30 L: 1470				
21 5209-002 Airframe PART #305	RH AIR CYCLE MACHINE ACM Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
21 5213-001 Airframe PART #575	LH PACK INLET TEMPERATURE (DISCHARGE) SENSOR Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
21 5213-002 Airframe PART #2088	RH PACK INLET TEMPERATURE (DISCHARGE) SENSOR Part Number GG436-2005-3	Serial Number 11060R	06-DEC-2012 H: 426.50 L: 209				





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 5217-001 Airframe PART #2128	LH COMPRESSOR PNEUMATIC OVERHEAT SENSOR Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
21 5217-002 Airframe PART #2015	RH COMPRESSOR PNEUMATIC OVERHEAT SENSOR Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
21 5221-001 Airframe PART #1840	LH REHEATER CONDENSER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
21 5221-002 Airframe PART #2345	RH REHEATER CONDENSER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
21 5225-001 Airframe PART #517	LH (PACK) TEMPERATURE SENSOR Part Number GG436-20015-3 Serial Number 20995	26-JUL-2018 H: 2817.20 L: 966					
21 5225-002 Airframe PART #1242	RH (PACK) TEMPERATURE SENSOR Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
21 5229-001 Airframe PART #846	LH WATER EXTRACTOR Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
21 5229-002 Airframe PART #1695	RH WATER EXTRACTOR Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
21 5233-001 Airframe PART #2896	LH TEMPERATURE CONTROL VALVE Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 5233-002 Airframe PART #2336	RH TEMPERATURE CONTROL VALVE Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
21 5237-001 Airframe PART #1510	LH (PACK DISCHARGE) TEMPERATURE SENSOR Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
21 5237-002 Airframe PART #535	RH (PACK DISCHARGE) TEMPERATURE SENSOR Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
21 5241-001 Airframe PART #1083	LH ANTI-ICING PRESSURE SENSOR Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
21 5241-002 Airframe PART #1696	RH ANTI-ICING PRESSURE SENSOR Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
21 5249-001 Airframe PART #2629	LH PACK DISCHARGE DUCT Part Number GG438-2050-9 Serial Number 1052	04-MAR-2016 H: 1753.70 L: 622					
21 5253-001 Airframe PART #522	RH PACK DISCHARGE DUCT Part Number GG438-2049-9 Serial Number 393	21-MAR-2010 H: 0.00					
21 53-05-101 Airframe INSPECTION 1500H #2427	OPERATIONAL TEST OF THE RAM AIR VALVE	08-FEB-2022 H: 4399.80 L: 1478	H: 1500.00			H: 5899.80	H: 1444.00
21 5300-001 Airframe PART #1102	LH RAM AIR FLEXIBLE DUCT Part Number GG438-2056-3 Serial Number 558	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 5300-002 Airframe PART #2655	RH RAM AIR FLEXIBLE DUCT Part Number GG438-2056-3	Serial Number 164	21-MAR-2010 H: 0.00				
21 5301-001 Airframe PART #2955	LH WATER SPRAYER Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
21 5301-002 Airframe PART #2917	RH WATER SPRAYER Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
21 5305-001 Airframe PART #2234	EMERGENCY RAM AIR VALVE Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
21 5317-001 Airframe PART #365	LH MAIN HEAT EXCHANGER DIFFUSER Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
21 5317-002 Airframe PART #1127	RH MAIN HEAT EXCHANGER DIFFUSER Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
21 5321-001 Airframe PART #2465	SPLITTER RAM AIR DUCT Part Number GG438-2055-1	Serial Number 2964	21-MAR-2010 H: 0.00				
21 5333-001 Airframe PART #1029	RAM-AIR CHECK VALVE Part Number GG436-2068-3	Serial Number 01214	16-FEB-2021 H: 3992.00 L: 1324				
21 5333-002 Airframe PART #1682	RAM-AIR INTAKE Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 5401-001 Airframe PART #2739	NO. 1 COOLING IRS FAN Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
21 5401-002 Airframe PART #686	NO. 2 COOLING IRS FAN Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
21 5401-003 Airframe PART #2878	NO. 3 COOLING IRS FAN Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
21 5410-701 Airframe PART #2607	AVIONICS COOLING DUCT Part Number GS438-0034-5	Serial Number 432	23-JAN-2011 H: 0.00				
21 5437-001 Airframe PART #3044	NO. 1 AVIONICS EXHAUST FAN Part Number GG433-2047-1	Serial Number 1114	29-SEP-2017 H: 2431.70 L: 854				
21 5437-002 Airframe PART #1408	NO. 2 AVIONICS EXHAUST FAN Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
21 5441-001 Airframe PART #1107	NO. 1 AVIONIC FAN CONVERTER Part Number UNK	Serial Number UNK	29-SEP-2017 H: 2431.70 L: 854				
21 5441-002 Airframe PART #3012	NO. 2 AVIONIC FAN CONVERTER Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
21 60-00-101 Airframe INSPECTION 1500H #2528	OPERATIONAL TEST OF THE AUXILIARY PRESSURIZATION FUNCTION		08-FEB-2022 H: 4399.80 L: 1478	H: 1500.00		H: 5899.80	H: 1444.00





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 6001-001 Airframe PART #1329	EMERGENCY CHECK VALVE Part Number PN	21-MAR-2010 H: 0.00					Serial Number SN- UNKNOWN
21 6005-001 Airframe PART #1088	LH TRIM AIR CHECK VALVE Part Number PN	21-MAR-2010 H: 0.00					Serial Number SN- UNKNOWN
21 6005-002 Airframe PART #1609	RH TRIM AIR CHECK VALVE Part Number PN	21-MAR-2010 H: 0.00					Serial Number SN- UNKNOWN
21 6009-001 Airframe PART #2622	LH HOT AIR SHUT-OFF VALVE Part Number PN	21-MAR-2010 H: 0.00					Serial Number SN- UNKNOWN
21 6009-002 Airframe PART #2311	RH HOT AIR SHUT-OFF VALVE Part Number PN	21-MAR-2010 H: 0.00					Serial Number SN- UNKNOWN
21 6013-001 Airframe PART #51	LH TRIM AIR VALVE Part Number GG436-2038-7	16-OCT-2015 H: 1597.40					Serial Number 01100
21 6013-002 Airframe PART #1449	RH TRIM AIR VALVE Part Number GG436-2038-7	31-MAY-2017 H: 2294.40 L: 807					Serial Number 01218
21 6013-003 Airframe PART #1795	CENTER TRIM AIR VALVE Part Number GG436-2038-5	22-JUL-2014 H: 923.10 L: 359					Serial Number 00346
21 6017-001 Airframe PART #1065	LH (DUCT AFT CABIN) TEMPERATURE SENSOR Part Number PN	21-MAR-2010 H: 0.00					Serial Number SN- UNKNOWN



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 6017-002 Airframe PART #2686	RH (DUCT FWD CABIN) TEMPERATURE SENSOR Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
21 6017-003 Airframe PART #2378	CENTER (DUCT FLT COMPARTMENT) TEMPERATURE SENSOR Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
21 6021-001 Airframe PART #1652	LH AIR CONDITIONING SYSTEM CONTROLLER Part Number Serial Number GG546-2040-15 01652	22-JUN-2021 H: 4104.00 L: 1369					
21 6021-002 Airframe PART #597	RH AIR CONDITIONING SYSTEM CONTROLLER Part Number Serial Number GG546-2040-15 01642	22-JUN-2021 H: 4104.00 L: 1369					
21 6025-001 Airframe PART #139	AFT VENTILATED TEMPERATURE SENSOR Part Number Serial Number GG436-2041-3 4706	21-MAR-2010 H: 0.00					
21 6025-002 Airframe PART #1812	LH VENTILATED TEMPERATURE SENSOR Part Number Serial Number GG436-2041-3 4782	21-MAR-2010 H: 0.00					
21 6025-003 Airframe PART #2586	FWD VENTILATED TEMPERATURE SENSOR Part Number Serial Number GG436-2041-3 4820	21-MAR-2010 H: 0.00					
21 7108-001 Airframe PART #2560	HUMIDIFIER CONTROL UNIT Part Number Serial Number GG546-2125-1 SN- UNKNOWN	21-MAR-2010 H: 0.00					
21 7108-002 Airframe PART #2924	HUMIDIFIER LEVEL SENSOR Part Number Serial Number GG436-2126-1 SN- UNKNOWN	21-MAR-2010 H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 7149-001 Airframe PART #2492	HUMIDIFIER CABIN SENSOR Part Number PN	21-MAR-2010 H: 0.00	Serial Number SN- UNKNOWN				
21 7149-002 Airframe PART #5098	TRU COOLING DUCT Part Number GC439-0020-1	04-FEB-2021 H: 3992.00 L: 1324	Serial Number 864				
22 1101-001 Airframe PART #2826	GUIDANCE PANEL Part Number 7022010-905	04-MAY-2021 H: 4016.40 L: 1333	Serial Number 05010421				
22 1201-001 Airframe PART #2683	AILERON PARALLEL SERVO Part Number 4015373-823	21-MAR-2010 H: 0.00	Serial Number 0902H287				
22 1205-001 Airframe PART #2236	LEFT MLG WHEEL WELL AILERON SERVO BRACKET Part Number 4015374-813	21-MAR-2010 H: 0.00	Serial Number 0903H302				
22 1209-001 Airframe PART #2043	ELEVATOR PARALLEL SERVO Part Number 4015373-834	21-MAR-2010 H: 0.00	Serial Number 0812H275				
22 1213-001 Airframe PART #2615	FS1076.0 WL203.8 ELEVATOR SERVO BRACKET Part Number 4015374-906	21-MAR-2010 H: 0.00	Serial Number 0903H299				
23 000025 Airframe PART #5116	DUAL BLU-RAY PLAYER (L/H CREWREST SIDELEDGE) Part Number 441-0089-100	03-APR-2021	Serial Number 1644-1727				
	Notes VENUE MODIFICATION						
23 000026 Airframe PART #5117	DUAL BLU-RAY PLAYER (L/H FWD SIDELEDGE) Part Number 441-0089-100	03-APR-2021	Serial Number 1644-1715				
	Notes VENUE MODIFICATION						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
23 00027 Airframe PART #5118	DUAL BLU-RAY PLAYER (L/H 650 DESK AREA) Part Number: 441-0089-100 Serial Number: 1924-0139	03-APR-2021					
	Notes VENUE MODIFICATION						
23 00012 Airframe PART #5112	DUAL USB CHARGING PORT (R/H AFT CABIN DIVAN CABINET) Part Number: 6430202-1 Serial Number: K20-11096	03-APR-2021					
	Notes VENUE MODIFICATION						
23 00013 Airframe PART #5113	DUAL USB CHARGING PORT (L/H #1 SEAT FWD CABIN DADO PANEL) Part Number: 6430202-1 Serial Number: K20-11097	03-APR-2021					
	Notes VENUE MODIFICATION						
23 00014 Airframe PART #5114	DUAL USB CHARGING PORT (R/H FWD CABIN DIVAN CABINET) Part Number: 6430202-1 Serial Number: K20-11093	03-APR-2021					
	Notes VENUE MODIFICATION						
23 00015 Airframe PART #5115	DUAL USB CHARGING PORT (R/H #1 SEAT FWD DADO PANEL) Part Number: 6430202-1 Serial Number: K20-11103	03-APR-2021					
	Notes VENUE MODIFICATION						
23 00016 Airframe PART #5105	DUAL USB CHARGING PORT (L/H #3 SEAT AFT DADO PANEL) IN CABIN Part Number: 6430202-1 Serial Number: K20-11099	03-APR-2021					
	Notes VENUE MODIFICATION						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
23 00017 Airframe PART #5106	DUAL USB CHARGING PORT (R/H #1 SEAT FWD DADO PANEL) IN CABIN Part Number: 6430202-1 Serial Number: K20-11104 Notes VENUE MODIFICATION	03-APR-2021					
23 00018 Airframe PART #5107	DUAL USB CHARGING PORT (L/H CREWREST) Part Number: 6430202-1 Serial Number: K20-11095 Notes VENUE MODIFICATION	03-APR-2021					
23 00019 Airframe PART #5108	DUAL USB CHARGING PORT (L/H #5 DESK AFT DADO PANEL) IN STATEROOM Part Number: 6430202-1 Serial Number: K20-11101 Notes VENUE MODIFICATION	03-APR-2021					
23 00020 Airframe PART #5109	DUAL USB CHARGING PORT (L/H #6 SEAT AFT DADO PANEL) IN STATEROOM Part Number: 6430202-1 Serial Number: K20-11102 Notes VENUE MODIFICATION	03-APR-2021					
23 00021 Airframe PART #5110	DUAL USB CHARGING PORT (L/H #4 SEAT AFT DADO PANEL) IN CABIN Part Number: 6430202-1 Serial Number: K20-11100 Notes VENUE MODIFICATION	03-APR-2021					
23 00022 Airframe PART #5111	DUAL USB CHARGING PORT (L/H #2 SEAT FWD DADO PANEL) IN CABIN Part Number: 6430202-1 Serial Number: K20-11098 Notes VENUE MODIFICATION	03-APR-2021					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
23 00023 Airframe PART #5104	DUAL USB CHARGING PORT (R/H MID CABIN DIVAN CABINET) Part Number: 6430202-1 Serial Number: K20-11094	03-APR-2021					
	Notes VENUE MODIFICATION						
23 0101-002A Airframe PART #1882	RECERTIFY NO. 2 VHF COMMUNICATION RECEIVER PER 04 CFR 91.413 Part Number: 7510733-666 Serial Number: 080C117	09-MAR-2022 H: 4455.80 L: 1495	M: 24			09-MAR-2024	M: 23 D: 22
23 0320-701A Airframe INSPECTION #676	PERFORM PORTABLE SAT PHONE OPERATIONAL / BATTERY CHECK Notes TOP CHARGED BATTERY. OPS CHECKED GOOD	05-MAR-2022 H: 4446.70 L: 1492	D: 30			30-APR-2022	M: 1 D: 14
23 1098 Airframe PART #4835	XM DATA RECEIVER Part Number: 4092743-901 Serial Number: 35633549	29-JAN-2018 H: 2586.20 L: 898					
23 1101-001A Airframe PART #2354	RECERTIFY NO. 1 VHF COMMUNICATION RECEIVER PER 14 CFR 91.413 Part Number: 7510733-666 Serial Number: 0904C536	09-MAR-2022 H: 4455.80 L: 1495	M: 24			09-MAR-2024	M: 23 D: 22
23 1101-701 Airframe PART #2365	#3 VHF COMMUNICATION UNIT Part Number: 7510700-833 Serial Number: 0912C645	15-FEB-2011 H: 25.00 L: 11					
23 1105-001 Airframe PART #1362	NO. 1 COMM VHF TOP ANTENNA Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
23 1105-002 Airframe PART #2540	NO. 2 COMM VHF BOTTOM ANTENNA Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
23 1201-001 Airframe PART #133	LH HF (HF9031A) RECEIVER Part Number: 822-0101-002 Serial Number: 4657	23-NOV-2016 H: 2064.80 L: 722					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
23 1201-002 Airframe PART #476	RH HF (HF9031A) RECEIVER Part Number: 822-0101-002 Serial Number: 4157	21-MAR-2010 H: 0.00					
23 1201-002 Airframe PART #4780	RH HF RECEIVER Part Number: 822-0101-002 Serial Number: 4639	23-NOV-2016 H: 2064.80 L: 722					
23 1205-001 Airframe PART #2771	NO. 1 VERTICAL STABILIZER ANTENNA (HF9041A) COUPLER Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
23 1205-002 Airframe PART #1161	NO. 2 VERTICAL STABILIZER ANTENNA (HF9041A) COUPLER Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
23 1230005 Airframe PART #5129	HDMI INPUT PANEL (RH FWD DIVAN END CABINET IN CABIN) Part Number: 441-0056-101 Serial Number: 4L9KYN	03-APR-2021					
	Notes VENUE MODIFICATION						
23 1230006 Airframe PART #5130	HDMI INPUT PANEL (RH FWD DIVAN END CABINET IN CABIN) Part Number: 441-0056-101 Serial Number: L49KYP	03-APR-2021					
	Notes VENUE MODIFICATION						
23 13-13-700 Airframe INSPECTION #4645	EDDY CURRENT INSPECTION IRIDIUM ANTENNA						
23 13-13-702 Airframe INSPECTION #4646	LIFE LIMIT - IRIDIUM ANTENNA						
23 13-50-650 Airframe INSPECTION #4647	GENERAL VISUAL INSPECTION OF ELECTRICAL WIRING INTERCONNECTION SYSTEM (EWIS) XM WEATHER SYSTEM	29-JAN-2018 H: 2586.20 L: 898	M: 60			29-JAN-2023	M: 10 D: 13





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
23 13-50-700 Airframe INSPECTION #4644	FUNCTIONAL CHECK OF XM RECEIVER	29-JAN-2018 H: 2586.20 L: 898					
	<p>Notes</p> <p>ITEM HAS BEEN REMOVED FROM AIRCRAFT AND THERE FOR REQUIRES NO MORE FUNCTIONAL TEST. THERE IS NO CHANGE IN WB FROM THE REMOVAL OF THESE ITEMS. REFERENCE STANDARD AERO WORK ORDER NUMBER 338758 DATED 29 JAN 18 ITEM 34 "AIRCRAFT IS NOT EQUIPPED WITH WM WEATHER".</p>						
23 13-52-700 Airframe INSPECTION #4648	EDDY CURRENT INSPECTION XM ANTENNA						
23 13-52-702 Airframe INSPECTION #4649	LIFE LIMIT - XM ANTENNA						
23 13-90-01 Airframe INSPECTION #1368	VISUAL INSPECTION - SATCOM DIRECT ROUTER INSTALLATION	03-SEP-2021 H: 4258.30 L: 1423	M: 24 H: 1000.00			03-SEP-2023 H: 5258.30	M: 17 D: 18 H: 802.50
	<p>Notes</p> <p>PER ICA NO. 140828002 REV A SECTION 5</p>						
23 1300-701 Airframe PART #2572	HST 2110 (#1) HIGH SPEED TRANSCEIVER	31-MAY-2016 H: 1865.90 L: 657					
	Part Number	Serial Number					
	822-2231-020	977					
23 1300-702 Airframe PART #263	HST 2110 (#2) HIGH SPEED TRANSCEIVER	31-MAY-2016 H: 1865.90 L: 657					
	Part Number	Serial Number					
	822-2231-020	972					
23 1301-701 Airframe PART #831	SATCOM SRT-2100 TRANSCEIVER	28-JUN-2016 H: 1899.20 L: 668					
	Part Number	Serial Number					
	822-1785-001	146712					
23 1302-701 Airframe PART #1460	ANTENNA DRIVER UNIT	15-FEB-2011 H: 25.00 L: 11					
	Part Number	Serial Number					
	0811-A-0001	1831					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
23 1303-701 Airframe PART #180	DIPLEXER/LNA UNIT Part Number 1242-A-0006 Serial Number 906	02-AUG-2013 H: 432.80 L: 211					
23 1304-701 Airframe PART #155	SATCOM HCM-2100B CONFIGURATION MODULE Part Number 822-2248-001 Serial Number 40KH2K	09-AUG-2013 H: 432.80 L: 211					
23 1306-701 Airframe PART #1528	SATCOM DIRECT ROUTER Part Number 1233-F-2191-10 Serial Number 820	25-OCT-2016 H: 2025.80 L: 705					
23 1310-701 Airframe PART #777	AMT- 50 SATCOM ANTENNA Part Number 0476-A-00377 Serial Number 1857	15-FEB-2011 H: 25.00 L: 11					
23 1313-701 Airframe PART #639	IRIDIUM/GPS ANTENNA Part Number CI 490-1 Serial Number 419284	02-AUG-2013 H: 432.80 L: 211					
23 1320-701 Airframe PART #3235	PORTABLE SAT PHONE Part Number 9555 Serial Number B03Y06	H: 0.00					
23 1350-701 Airframe PART #1803	LH COCKPIT XM RECEIVER Part Number XMD075-01 Serial Number 805000890	09-AUG-2013 H: 432.80 L: 211					
23 1350-702 Airframe PART #2749	RH COCKPIT XM RECEIVER Part Number XMD075-01 Serial Number 805000891	09-AUG-2013 H: 432.80 L: 211					
23 1352-701 Airframe PART #1307	TOP FUSELAGE XM ANTENNA Part Number CI 420-1 Serial Number 408134	09-AUG-2013 H: 432.80 L: 211					
23 1412-701 Airframe PART #2818	FWD AIRCELL BROADBAND ANTENNA Part Number P12949 Serial Number 406980	09-AUG-2013 H: 432.80 L: 211					



Maintenance Items

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Page 24 of 653



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
23 1412-702 Airframe PART #1597	AFT AIRCELL BROADBAND ANTENNA Part Number Serial Number P12949 408370	09-AUG-2013 H: 432.80 L: 211					
23 1502-701 Airframe PART #2098	ATG CONFIGURATION (AIRCELL) MODULE Part Number Serial Number P14126 1412612174	02-AUG-2013 H: 432.80 L: 211					
23 1504-701 Airframe PART #176	ATG 5000 (AIRCELL) UNIT Part Number Serial Number P15864-001 1586412410	02-AUG-2013 H: 432.80 L: 211					
23 1510-701 Airframe PART #1519	CABIN TELECOMMUNICATIONS (AIRCELL) ROUTER Part Number Serial Number P12083 1208371856	16-OCT-2017 H: 2490.40 L: 873					
23 1520-701 Airframe PART #1537	AIRCELL WIFI ANTENNA Part Number Serial Number S65-5366-315 235-2443	09-AUG-2013 H: 432.80 L: 211					
23 1520-702 Airframe PART #921	AIRCELL WIFI ANTENNA Part Number Serial Number S65-5366-315 235-2444	09-AUG-2013 H: 432.80 L: 211					
23 1620-701 Airframe PART #1188	TRUE NORTH CABIN NETWORK DISTRIBUTION UNIT Part Number Serial Number TN1002-100 871	02-AUG-2013 H: 432.80 L: 211					
23 1620-702 Airframe PART #1221	TRUE NORTH CABIN NETWORK DISTRIBUTION UNIT Part Number Serial Number TN1002-100 872	02-AUG-2013 H: 432.80 L: 211					
23 1620-703 Airframe PART #2954	TRUE NORTH CABIN NETWORK DISTRIBUTION UNIT Part Number Serial Number TN1002-100 286	12-SEP-2014 H: 992.50 L: 375					
23 1630-701 Airframe PART #2284	TRUE NORTH WIFI ANTENNA Part Number Serial Number TN1008-100 300	02-AUG-2013 H: 432.80 L: 211					



Maintenance Items

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Page 25 of 653



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
23 1640-701 Airframe PART #458	COCKPIT TRUE NORTH HANDSET Part Number TN2003-101 Serial Number 143	02-AUG-2013 H: 432.80 L: 211					
23 1640-702 Airframe PART #1573	CABIN TRUE NORTH HANDSET Part Number TN2003-101 Serial Number 128	02-AUG-2013 H: 432.80 L: 211					
23 1650-701 Airframe PART #649	TRUE NORTH IRIDIUM BANDPASS FILTER Part Number TN1011-100 Serial Number 222	02-AUG-2013 H: 432.80 L: 211					
23 1977 Airframe PART #4833	DATA LOADER Part Number - Serial Number -	26-JAN-2018					
23 2100-701 Airframe PART #582	COCKPIT PRINTER UNIT Part Number 706300-1111 Serial Number 48403733	15-FEB-2011 H: 25.00 L: 11					
23 2100-702 Airframe PART #2192	PRINTER FAX SCANNER KIT (CABIN DESK) MACHINE Part Number Q5801A Serial Number CN57SEG3 31	15-FEB-2011 H: 25.00 L: 11					
23 2101-702 Airframe PART #2543	PRINT (CREW REST) SERVER Part Number ADI23900-000 Serial Number 197	15-FEB-2011 H: 25.00 L: 11					
23 2201-001 Airframe PART #1166	SELCAL DECODER Part Number 1200008-002 Serial Number 6166	12-FEB-2013 H: 430.70 L: 211					
23 2300-701 Airframe PART #2707	TELELINK (ADLU) UNIT Part Number 8400021-03 Serial Number 10510	25-JAN-2014 H: 649.70 L: 284					
23 2301-701 Airframe PART #108	AIRBORNE DATA-LINK CONFIGURATION MODULE Part Number 2243262-1 Serial Number 381	15-FEB-2011 H: 25.00 L: 11					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
23 3000-701 Airframe PART #399	SPEAKER, PA (A571) AMPLIFIER Part Number 251-003 Serial Number 60445	15-FEB-2011 H: 25.00 L: 11					
23 4556 Airframe PART #4834	#1 CCP Part Number G7280-703 Serial Number 29437	29-JAN-2018 H: 2586.20 L: 898					
23 4556 Airframe PART #4836	#2CCP Part Number G7280-703 Serial Number 29440	29-JAN-2018 H: 2586.20 L: 898					
23 5105-001 Airframe PART #1284	NO. 1 AUDIO CONTROL PANEL Part Number 7511001-985 Serial Number 7511001-985	23-OCT-2020 H: 3913.60 L: 1297					
Notes PILOT REPORTED VHF1 BLEEDS INTO HEADSET. COULD NOT DUPLICATE ON THE GROUND.							
23 5105-002 Airframe PART #2582	NO. 2 AUDIO CONTROL PANEL Part Number 7511001-985 Serial Number 0909D685	16-AUG-2021 H: 4227.30 L: 1412					
Notes HEADSET AUDIO REPORTED WAY TOO LOUD.							
23 5105-003 Airframe PART #849	NO. 3 AUDIO CONTROL PANEL Part Number 7511001-985 Serial Number 0609B363	09-APR-2021 H: 3992.00 L: 1324					
23 5121-001 Airframe PART #92	RH CREW INTERPHONE UNIT Part Number 600-59146-3 Serial Number 7406	21-MAR-2010 H: 0.00					
23 5125-001 Airframe PART #766	LH CREW INTERPHONE UNIT Part Number PN Serial Number SN-UNKNOWN	21-MAR-2010 H: 0.00					
23 60-14 Airframe INSPECTION #4643	FUNCTIONAL CHECK OF TRUENORTH SIMPHONE INSTALLATION	03-JAN-2022 H: 4399.80 L: 1478	M: 24			03-JAN-2024	M: 21 D: 18



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
23 6015-701 Airframe PART #271	TRUE NORTH SIMPHONE TRANSCEIVER Part Number: TN1000-305 Serial Number: 198	01-JUN-2020 H: 3757.80 L: 1239					
23 6016-701 Airframe PART #1772	TRUE NORTH SIMPHONE WIFI ANTENNA Part Number: TN1008-100 Serial Number: 300	09-AUG-2013 H: 432.80 L: 211					
23 6017-701 Airframe PART #1724	TRUE NORTH SIMPHONE CABIN NETWORK DISTRIBUTION UNIT Part Number: TN1002-100 Serial Number: 871	09-AUG-2013 H: 432.80 L: 211					
23 6017-702 Airframe PART #30	TRUE NORTH SIMPHONE CABIN NETWORK DISTRIBUTION UNIT Part Number: TN1002-100 Serial Number: 872	09-AUG-2013 H: 432.80 L: 211					
23 6017-703 Airframe PART #1164	TRUE NORTH SIMPHONE CABIN NETWORK DISTRIBUTION UNIT Part Number: TN1002-100 Serial Number: 873	09-AUG-2013 H: 432.80 L: 211					
23 6018-701 Airframe PART #2178	TRUE NORTH SIMPHONE TRANSCEIVER PERSONALITY MODULE Part Number: TN1001-200 Serial Number: SN-UNKNOWN	09-AUG-2013 H: 432.80 L: 211					
23 6019-701 Airframe PART #2709	TRUE NORTH SIMPHONE IRIDIUM BANDPASS FILTER Part Number: TN1011-100 Serial Number: 222	09-AUG-2013 H: 432.80 L: 211					
23 6020-701 Airframe PART #1924	COCKPIT TRUE NORTH SIMPHONE HANDSET Part Number: TN2003-101 Serial Number: 143	09-AUG-2013 H: 432.80 L: 211					
23 6020-702 Airframe PART #532	CABIN TRUE NORTH SIMPHONE HANDSET Part Number: TN2003-101 Serial Number: 128	09-AUG-2013 H: 432.80 L: 211					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
23 61-01-201 Airframe INSPECTION 60M #1717	FUNCTIONAL TEST OF THE STATIC DISCHARGERS	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
23 7000-701 Airframe PART #1649	VIDEO CONTROL (VCU-05) - AV. BAY UNIT Part Number: 100-2415-01 Serial Number: 1187	13-DEC-2012 H: 424.50 L: 208					
23 7001-701 Airframe PART #635	QUAD - AFT BELLY CAMERA Part Number: 100-1051-01 Serial Number: 0617	04-MAR-2016 H: 1753.70 L: 622					
23 7001-702 Airframe PART #2638	CMZ-01-2 - FWD BELLY CAMERA Part Number: 100-1053-02 Serial Number: 1018278	15-FEB-2011 H: 25.00 L: 11					
23 7001-703 Airframe PART #1096	CMX-01-2 - VERT STAB CAMERA Part Number: 100105402 Serial Number: 0601315	04-MAY-2017 H: 2259.40 L: 796					
23 71-00-201 Airframe INSPECTION 3000H #1372	OPERATIONAL TEST OF THE VOICE RECORDER SYSTEM	04-MAR-2016 H: 1753.70 L: 622	H: 3000.00	H: 50.00		H: 4753.70	H: 297.90
23 71-21-201 Airframe PART - Expiration #1494	DISCARD CVR (ULB) UNDERWATER LOCATOR BEACON BATTERY Part Number: DK120/90 Serial Number: AT131727	27-NOV-2019 H: 3575.60 L: 1184				27-NOV-2024	M: 32 D: 11
23 71-21-202 Airframe INSPECTION 30M #2723	OPERATIONAL TEST CVR (ULB) UNDERWATER LOCATOR BEACON Notes NO DEFECTS NOTED	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
23 7101-001 Airframe PART #1791	(CVR) COCKPIT VOICE RECORDER Part Number: 980-6032-040 Serial Number: CVR-02451	26-JAN-2014 H: 649.70 L: 284					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
23 7105-001 Airframe PART #1776	MICROPHONE Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
23 7117-001 Airframe PART #1080	IMPACT SWITCH Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
23 7121-002 Airframe PART #792	CVR - CONTROL PANEL Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
23 8101-001 Airframe PART #1121	LH RADIO MANAGEMENT UNIT Part Number 7013270-977	Serial Number 03124134	11-OCT-2014 H: 1015.50 L: 386				
23 8101-002 Airframe PART #1060	RH RADIO MANAGEMENT UNIT Part Number 7013270-977	Serial Number 08106529	13-OCT-2014 H: 1015.50 L: 386				
23 DOC 1024904 RA Airframe INSPECTION #5021	INSTRUCTIONS FOR CONTINUED AIRWORTHINESS TRUENORTH SIMPHONE CHORUS IRIDIUM PHONE SYSTEM		04-MAR-2016 H: 1753.70 L: 622				
23 DOC 1024904 RA Airframe INSPECTION #5023	INSTRUCTIONS FOR CONTINUED AIRWORTHINESS TRUENORTH SIMPHONE CHORUS IRIDIUM PHONE SYSTEM- 24 MONTH INSPECTION		15-JUN-2020 H: 3778.50 L: 1252	M: 24		15-JUN-2022	M: 2 D: 30
23 DOC 1024904 RA Airframe INSPECTION #5022	INSTRUCTIONS FOR CONTINUED AIRWORTHINESS TRUENORTH SIMPHONE CHORUS IRIDIUM PHONE SYSTEM- ELECTRICAL WIRING INTERCONNECTION SYSTEM INSPECTION		15-APR-2021 H: 3992.00 L: 1324	M: 60		15-APR-2026	M: 48 D: 30
24 Airframe PART #4892	24-51-17-001 APCP EXTERNAL AC-to-DC CONVERTER Reference Number 24-51-17	Part Number 1707580B	Serial Number PR1205002				
			08-DEC-2018 H: 3033.70 L: 1035				





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 Airframe PART #5127	TRIP SETTING MODULE (DCPM) Part Number 10720B01E00 Serial Number 19065218	02-MAR-2021 H: 3992.00 L: 1324					
	Notes DCPDE #1						
24 00-00-301 Airframe INSPECTION 15M #2331	OPERATIONAL TEST (CYCLING) OF THERMAL CIRCUIT BREAKERS	19-APR-2021 H: 3992.00 L: 1324	M: 15	M: 3		19-JUL-2022	M: 4 D: 3
	Notes NO DEFECTS NOTED						
24 00-50-601 Airframe INSPECTION 30M #736	OPERATIONAL TEST OF THE CABIN POWER SHUT-OFF SWITCH Reference Number 24-03-50-710-802	19-APR-2021 H: 3992.00 L: 1324	M: 30			19-OCT-2023	M: 19 D: 3
	Notes NO DEFECTS NOTED						
24 0001-001 Airframe PART #2472	JB3 JUNCTION BOX Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
24 0001-002 Airframe PART #784	JB4 JUNCTION BOX Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
24 0009-001 Airframe PART #419	JB5 JUNCTION BOX Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
24 0013-001 Airframe PART #208	JB6 JUNCTION BOX Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
24 1201-001 Airframe PART #801	NO. 1 VFG OIL PIPE Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 1201-002 Airframe PART #1793	NO. 2 VFG OIL PIPE Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
24 1202-001 Engine 1 PART #2753	NO. 1 ENGINE - VFG OIL AIR COOLED COOLER Part Number Serial Number 50043001-11 50043-1454	21-MAR-2010 H: 0.00					
24 1202-001 Engine 2 PART #2211	NO. 2 ENGINE - VFG OIL AIR COOLED COOLER Part Number Serial Number 50043001-11 50043-1456	21-MAR-2010 H: 0.00					
24 1202-002 Engine 1 PART #196	NO. 1 ENGINE - VFG OIL AIR COOLED COOLER Part Number Serial Number 50042001-11 50042-1448	21-MAR-2010 H: 0.00					
24 1202-002 Engine 2 PART #1266	NO. 2 ENGINE - VFG OIL AIR COOLED COOLER Part Number Serial Number 50042001-11 50042-1456	21-MAR-2010 H: 0.00					
24 21-01-201 Airframe INSPECTION 1000 H #628	DETAILED INSPECTION OF THE VARIABLE FREQUENCY GENERATOR (VFG) OIL SUPPLY Reference Number AMM 24-12-00-220 -801	10-MAR-2022 H: 4455.80 L: 1495	H: 1000.00	H: 50.00		H: 5455.80	H: 1000.00
24 2101-001 Airframe PART #1277	LOB (NO. 1) VARIABLE FREQUENCY AC (40KVA) GENERATOR Part Number Serial Number GL511-1103-9 6462 Notes NOTE: SB BA05801-24-34 MOD STRIKE 2 INSPECTION OF THE WALL THICKNESS C/W	08-DEC-2018 H: 3033.70 L: 1035					
24 2101-002 Airframe PART #354	LIB (NO. 2) VARIABLE FREQUENCY AC (40KVA) GENERATOR Part Number Serial Number GL511-1103-9 2594	04-MAR-2016 H: 1753.70 L: 622					
24 2101-003 Airframe PART #907	ROB (NO. 3) VARIABLE FREQUENCY AC (40KVA) GENERATOR Part Number Serial Number GL511-1103-9 6235	29-JAN-2018 H: 2586.20 L: 898					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 2101-004 Airframe PART #371	RIB (NO. 4) VARIABLE FREQUENCY AC (40KVA) GENERATOR Part Number Serial Number GL511-1103-9 2027	31-AUG-2020 H: 3844.20 L: 1271					
24 2201-001 Airframe PART #1294	NO.5 APU AC (40/45 KVA) GENERATOR Part Number Serial Number GL511-1204-5 2265	23-JAN-2011 H: 11.80 L: 6					
24 23-01-101 Airframe INSPECTION 24M, RAT #1035	OPERATIONAL TEST OF THE RAM AIR TURBINE (RAT) Part Number Serial Number GL456-1101-9 0250	09-MAR-2022 H: 4455.80 L: 1495	M: 24			09-MAR-2024	M: 23 D: 22
24 23-01-102 Airframe INSPECTION 24M, RAT #2682	FUNCTIONAL TEST RAM AIR TURBINE (RAT) HEATER Part Number Serial Number GL456-1101-9 0250	18-APR-2020 H: 3741.10 L: 1233	M: 24			18-APR-2022	M: 1 D: 2
24 2301-001 Airframe PART #2366	RAM AIR TURBINE Part Number Serial Number GL456-1101-9 0250	18-APR-2020 H: 3741.10 L: 1233					
24 2301-003 Airframe PART #2620	GENERATOR- RAT CONTROL Part Number Serial Number GL456-1201-9 491	21-MAR-2010 H: 0.00					
24 2309-001 Airframe PART #1498	DEPLOY RAT ACTUATOR Part Number Serial Number GL456-1301-1 497	21-MAR-2010 H: 0.00					
24 2313-001 Airframe PART #78	RAT MANUAL RELEASE CABLE Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
24 2317-001 Airframe PART #2970	DOOR RAT LINK Part Number Serial Number GL456-1501-1 499	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 2321-001 Airframe PART #2681	RAT RETRACTION PUMP Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
24 2325-001 Airframe PART #1023	RAT UPLOCK Part Number Serial Number GL456-1601-3 484	21-MAR-2010 H: 0.00					
24 2401-001 Airframe PART #1855	NO.1 LH ENGINE GENERATOR CONTROL UNIT GCU Part Number Serial Number GL511-3104-1 2444	21-MAR-2010 H: 0.00					
24 2401-002 Airframe PART #3033	NO.2 LH ENGINE GENERATOR CONTROL UNIT GCU Part Number Serial Number GL511-3104-1 2441	21-MAR-2010 H: 0.00					
24 2401-003 Airframe PART #2594	NO.3 RH ENGINE GENERATOR CONTROL UNIT GCU Part Number Serial Number GL511-3105-1 5145	05-APR-2015 H: 1364.00 L: 487					
24 2401-004 Airframe PART #2243	NO.4 RH ENGINE GENERATOR CONTROL UNIT GCU Part Number Serial Number GL511-3104-1 2442	03-APR-2015 H: 1359.10 L: 484					
24 2401-005 Airframe PART #1962	NO.5 APU GENERATOR CONTROL UNIT GCU Part Number Serial Number GL511-3104-1 2609	23-JAN-2011 H: 11.80 L: 6					
24 25-00-201 Airframe PART - Life Limited 3000H #2932	DISCARD OF THE VFG OIL FILTER (NO. 1) Reference Number AMM 24-12-03-961 -801	01-DEC-2018 H: 3011.20 L: 1025	H: 3000.00	H: 50.00		H: 6011.20	H: 1555.40
24 25-00-201 Airframe PART - Life Limited 3000H #2433	DISCARD OF THE VFG OIL FILTER (NO. 2) Reference Number AMM 24-12-03-961 -801	01-DEC-2018 H: 3011.20 L: 1025	H: 3000.00	H: 50.00		H: 6011.20	H: 1555.40





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 25-00-201 Airframe PART - Life Limited 3000H #629	DISCARD OF THE VFG OIL FILTER (NO. 3) Reference Number AMM 24-12-03-961 -801	01-DEC-2018 H: 3011.20 L: 1025	H: 3000.00	H: 50.00		H: 6011.20	H: 1555.40
24 25-00-201 Airframe PART - Life Limited 3000H #2602	DISCARD OF THE VFG OIL FILTER (NO. 4) Reference Number AMM 24-12-03-961 -801	01-DEC-2018 H: 3011.20 L: 1025	H: 3000.00	H: 50.00		H: 6011.20	H: 1555.40
24 25-00-202 Airframe INSPECTION 1000 H #28	VISUAL CHECK OF THE DIFFERENTIAL PRESSURE INDICATOR Reference Number AMM 24-12-00-210 -801	10-MAR-2022 H: 4455.80 L: 1495	H: 1000.00	H: 50.00		H: 5455.80	H: 1000.00
24 26-58-601 Airframe INSPECTION #5083	OPERATIONAL TEST OF RESIDUAL CURRENT DEVICES. STLMC 05-21-11 (CH 5 TASK 24-26-58-601). SMM TASK 24-26-58-710-801. Notes C/W	13-APR-2021 H: 3992.00 L: 1324	M: 15			13-JUL-2022	M: 3 D: 27
24 3101-001 Airframe PART #144	NO. 1 TRANSFORMER RECTIFIER UNIT TRU Part Number GL511-2102-1 Serial Number B1651	21-MAR-2010 H: 0.00					
24 3101-002 Airframe PART #79	NO. 2 TRANSFORMER RECTIFIER UNIT TRU Part Number GL511-2102-1 Serial Number B1652	21-MAR-2010 H: 0.00					
24 3101-003 Airframe PART #844	NO. 3 TRANSFORMER RECTIFIER UNIT TRU Part Number GL511-2102-1 Serial Number B1653	21-MAR-2010 H: 0.00					
24 3101-004 Airframe PART #20	NO. 4 TRANSFORMER RECTIFIER UNIT TRU Part Number GL511-2102-1 Serial Number B1654	21-MAR-2010 H: 0.00					
24 32-01-203 Airframe PART #340	RESTORATION AVIONICS BATTERY Part Number GL511-2201-5 / 257CH- 9 Serial Number 09052000E 05FB	09-MAR-2022 H: 4455.80 L: 1495	M: 8	D: 24		30-NOV-2022	M: 8 D: 14





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 32-09-203 Airframe PART #2173	RESTORATION APU BATTERY Part Number Serial Number GL511-2301-5 / 427CK-1 090520015 BACB	09-MAR-2022 H: 4455.80 L: 1495	M: 8	D: 24		30-NOV-2022	M: 8 D: 14
24 32-440-801 Airframe PART #1503	AVIONICS BATTERY Part Number Serial Number GL511-2201-5 120839	07-MAY-2020 H: 3745.30 L: 1235					
24 32-440-801 Airframe PART #4785	AVIONICS BATTERY CONNECTOR Part Number MS25182-2						
24 32-440-802 Airframe PART #4771	APU BATTERY Part Number Serial Number GL511-2301-5 121730	07-MAY-2020 H: 3745.30 L: 1235					
24 32-440-802 Airframe PART #4786	APU BATTERY CONNECTOR Part Number MS25182-2	H: 0.00					
24 3205-001 Airframe PART #2641	AVIONIC BATTERY CHARGER Part Number Serial Number GL511-2401-9 E959	21-MAR-2010 H: 0.00					
24 3205-002 Airframe PART #129	APU BATTERY CHARGER Part Number Serial Number GL511-2401-9 E978	21-MAR-2010 H: 0.00					
24 4101-001 Airframe PART #1098	CTA CURRENT TRANSFORMER Part Number Serial Number GL516-1101-1 1905	21-MAR-2010 H: 0.00					
24 51-00-01 Airframe INSPECTION #4650	GENERAL VISUAL INSPECTION OF ELECTRICAL WIRING INTERCONNECTION SYSTEM (EWIS) GFI OUTLETS	18-OCT-2018 H: 2955.40 L: 1006	M: 60			18-OCT-2023	M: 19 D: 2
24 51-00-02 Airframe INSPECTION #4651	SYSTEM TEST GROUND FAULT INTERRUPTER (GFI) AND OUTLET SYSTEM TO ENSURE PROPER OPERATION	04-MAR-2016 H: 1753.70 L: 622					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 5117-001 Airframe PART #1203	AC TO DC CONVERTER Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
24 5117-002 Airframe PART #638	FREQUENCY CONVERTER Part Number 1-002-0102-2335	Serial Number HT004036	02-JUN-2019 H: 3322.60 L: 1112				
24 5121-001 Airframe PART #2270	EPQM CARD Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
24 5137-001 Airframe PART #2419	K2 ACPC L - SERIES CONTACTOR Part Number 1714157	Serial Number 06518	03-DEC-2014 H: 1111.80 L: 414				
24 5137-002 Airframe PART #2184	K3 ACPC ZC-SERIES CONTACTOR Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
24 5137-003 Airframe PART #2408	K5 ACPC ZC-SERIES CONTACTOR Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
24 5137-004 Airframe PART #258	K7 ACPC ZC-SERIES CONTACTOR Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
24 5137-005 Airframe PART #2871	K8 ACPC ZC-SERIES CONTACTOR Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
24 5137-006 Airframe PART #1984	K10 ACPC ZC-SERIES CONTACTOR Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 5137-007 Airframe PART #80	K11 ACPC ZC-SERIES CONTACTOR Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
24 5137-008 Airframe PART #970	K13 ACPC ZC-SERIES CONTACTOR Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
24 5141-001 Airframe PART #2691	K4 CONTACTOR Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
24 5141-002 Airframe PART #2953	K6 CONTACTOR Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
24 5141-003 Airframe PART #211	K9 CONTACTOR Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
24 5141-004 Airframe PART #21	K12 CONTACTOR Part Number 1714139	Serial Number 03618	17-JUL-2014 H: 914.90 L: 357				
24 5141-005 Airframe PART #355	K1 ACPC L−SERIES CONTACTOR Part Number 1714137 / ZJCB9N015	Serial Number 00875	14-MAR-2018 H: 2677.70 L: 923				
24 5141-018 Airframe PART #2733	ACPC K18 CONTACTOR Part Number 5911737-1	Serial Number NSN	24-JUN-2015 H: 1493.00 L: 523				
24 5153-001 Airframe PART #1400	AC POWER CENTER Part Number GL512-1101-19	Serial Number 6132	21-MAR-2010 H: 0.00				





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 5201-001 Airframe PART #1823	CIRCUIT BREAKER PANEL Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
24 5205-001 Airframe PART #2253	CCBP H-SERIES CONTACTOR Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
24 6100-001 Airframe PART #613	DCPC DC POWER CENTER Part Number GL512-3101-15	Serial Number 619	21-MAR-2010 H: 0.00				
24 6100-002 Airframe PART #1282	DCPC DC POWER CENTER Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
24 6109-001 Airframe PART #362	NO. 1 DCPC CARD Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
24 6109-002 Airframe PART #2118	NO. 2 DCPC CARD Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
24 6109-003 Airframe PART #225	NO. 3 DCPC CARD Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
24 6113-001 Airframe PART #2837	NO. 1 DCPC DCPQM CARD Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
24 6113-002 Airframe PART #1109	NO. 2 DCPC DCPQM CARD Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 6133-001 Airframe PART #1596	DCPC BATTERY/RAT IF CARD Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
24 6137-001 Airframe PART #2020	DCPC SPDA FEEDER CARD Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
24 6153-001 Airframe PART #2670	K1 DCPC L-SERIES CONTACTOR Part Number 5911746-1	Serial Number 04946	01-JUN-2018 H: 2748.10 L: 940				
24 6153-002 Airframe PART #491	K2 DCPC L-SERIES CONTACTOR Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
24 6153-003 Airframe PART #3014	K3 DCPC L-SERIES CONTACTOR Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
24 6153-004 Airframe PART #2754	K4 DCPC L-SERIES CONTACTOR Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
24 6153-005 Airframe PART #2684	K5 DCPC L-SERIES CONTACTOR Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
24 6201-001 Airframe PART #1635	NO. 1 SPDA SECONDARY POWER DISTRIBUTION Part Number GL511-2301-13	Serial Number 2070	28-JAN-2011 H: 18.00 L: 8				
24 6201-002 Airframe PART #569	NO. 2 SPDA SECONDARY POWER DISTRIBUTION Part Number GL512-3201-13	Serial Number 0609	30-OCT-2013 H: 513.50 L: 241				



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 6201-003 Airframe PART #802	NO. 3 SPDA SECONDARY POWER DISTRIBUTION Part Number Serial Number GL512-3201-13 2023	21-MAR-2010 H: 0.00					
24 6201-004 Airframe PART #601	NO. 4 SPDA SECONDARY POWER DISTRIBUTION Part Number Serial Number GL512-3201-13 2025	21-MAR-2010 H: 0.00					
24 6205-001 Airframe PART #2755	APU START (ASCA) CONTACTOR Part Number Serial Number GL512-3301-11 572	21-MAR-2010 H: 0.00					
24 64-00-201 Airframe INSPECTION 500H #2290	OPERATIONAL TEST OF THE DC OVERRIDE SYSTEM	10-MAR-2022 H: 4455.80 L: 1495	H: 500.00	H: 50.00		H: 4955.80	H: 500.00
24 7000-701 Airframe PART #1761	NO.1 AC POWER DISTRIBUTION EQUIPMENT Part Number Serial Number 10719B01E01 08081133C D	02-AUG-2013 H: 432.80 L: 211					
24 7000-702 Airframe PART #2875	NO.2 AC POWER DISTRIBUTION EQUIPMENT Part Number Serial Number 10719B01E01 10031579C	15-FEB-2011 H: 25.00 L: 11					
24 7000-703 Airframe PART #2010	NO.3 AC POWER DISTRIBUTION EQUIPMENT Part Number Serial Number 10719B01E01 08091160C	15-FEB-2011 H: 25.00 L: 11					
24 7000-704 Airframe PART #2710	NO.4 AC POWER DISTRIBUTION EQUIPMENT Part Number Serial Number 10719B01E01 10031570C	15-FEB-2011 H: 25.00 L: 11					
24 7000-705 Airframe PART #1014	NO.5 AC POWER DISTRIBUTION EQUIPMENT Part Number Serial Number 10719B01E01 10031582C	15-FEB-2011 H: 25.00 L: 11					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 7001-001 Airframe PART #2340	LH EMS ELECTRICAL MANAGEMENT SYSTEM CONTROL DISPLAY UNIT Part Number Serial Number GL542-3101-19 1564	23-JAN-2011 H: 11.80 L: 6					
24 7001-002 Airframe PART #951	RH EMS ELECTRICAL MANAGEMENT SYSTEM CONTROL DISPLAY UNIT Part Number Serial Number GL542-3101-19 1534	21-MAR-2010 H: 0.00					
24 7001-701 Airframe PART #2001	NO.1 ACPDE PERSONALITY MODULE Part Number Serial Number 10722B01E00 10021325	15-FEB-2011 H: 25.00 L: 11					
24 7001-702 Airframe PART #1445	NO.2 ACPDE PERSONALITY MODULE Part Number Serial Number 10722B01E00 10021327	15-FEB-2011 H: 25.00 L: 11					
24 7001-703 Airframe PART #2768	NO.3 ACPDE PERSONALITY MODULE Part Number Serial Number 10722B01E00 10021330	15-FEB-2011 H: 25.00 L: 11					
24 7001-704 Airframe PART #1138	NO.4 ACPDE PERSONALITY MODULE Part Number Serial Number 10722B01E00 10021331	15-FEB-2011 H: 25.00 L: 11					
24 7001-705 Airframe PART #2230	NO.5 ACPDE PERSONALITY MODULE Part Number Serial Number 10722B01E00 10021332	15-FEB-2011 H: 25.00 L: 11					
24 7002-701 Airframe PART #1311	NO.1 DC POWER DISTRIBUTION EQUIPMENT Part Number Serial Number 10718B01E01 09011231B	10-SEP-2013 H: 467.20 L: 222					
24 7002-702 Airframe PART #1622	NO.2 DC POWER DISTRIBUTION EQUIPMENT Part Number Serial Number 10718B01E01 05010132B	20-OCT-2017 H: 2498.70 L: 877					
24 7002-703 Airframe PART #262	NO. 3 DC POWER DISTRIBUTION EQUIPMENT Part Number Serial Number 10718B01E01 09111393A	10-SEP-2013 H: 467.20 L: 222					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 7002-704 Airframe PART #1132	NO.4 DC POWER DISTRIBUTION EQUIPMENT Part Number Serial Number 10718B01E01 10081597B	20-JAN-2017 H: 2120.50 L: 749					
	Notes UNIT REPLACED BY DUNCAN AVIATION - VNY W.O. #4Y5EA						
24 7002-705 Airframe PART #1152	NO.5 DC POWER DISTRIBUTION EQUIPMENT Part Number Serial Number 10718B01E01 10021471A	15-FEB-2011 H: 25.00 L: 11					
24 7002-706 Airframe PART #1192	NO.6 DC POWER DISTRIBUTION EQUIPMENT Part Number Serial Number 10718B01E01 10121728A	15-FEB-2011 H: 25.00 L: 11					
24 7003-701 Airframe PART #2714	NO.1 DCPDE PERSONALITY MODULE Part Number Serial Number 10720B01E00 13022656	24-SEP-2013 H: 477.60 L: 225					
24 7003-702 Airframe PART #2519	NO.2 DCPDE PERSONALITY MODULE Part Number Serial Number 10720B01E00 17094461	20-OCT-2017 H: 2498.70 L: 877					
24 7003-703 Airframe PART #906	NO.3 DCPDE PERSONALITY MODULE Part Number Serial Number 10720B01E00 11122200	15-DEC-2012 H: 424.50 L: 208					
24 7003-704 Airframe PART #1150	NO.4 DCPDE PERSONALITY MODULE Part Number Serial Number 10720B01E00 10021514	15-FEB-2011 H: 25.00 L: 11					
24 7003-705 Airframe PART #1306	NO.5 DCPDE PERSONALITY MODULE Part Number Serial Number 10720B01E00 10021515	15-FEB-2011 H: 25.00 L: 11					
24 7003-706 Airframe PART #618	NO.6 DCPDE PERSONALITY MODULE Part Number Serial Number 10720B01E00 10021511	15-FEB-2011 H: 25.00 L: 11					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 7003-707 Airframe PART #5096	HIGH DEF A/V 6000 (HDAV-6) NO. 2 Part Number 441-0102-100 Serial Number 4LD988	08-FEB-2021 H: 3992.00 L: 1324					
24 7003-708 Airframe PART #5097	HIGH DEF AVV 6000 (HDAV-6) NO. 1 Part Number 441-0102-100 Serial Number 4LD7TY	17-FEB-2021 H: 3992.00 L: 1324					
25 Airframe PART - Life Limited #5074	AFT LAV WARDROBE FIREBANE EXTINGUISHING AGENT KIT Part Number SPECTRUM EX Serial Number 202531	25-NOV-2020 H: 3947.80 L: 1309				30-NOV-2022	M: 8 D: 14
25 Airframe INSPECTION #5139	DAVID CLARKS HEADSET BATTERIES REPLACMENT / INSPECTION	09-FEB-2022 H: 4399.80 L: 1478	M: 3			09-MAY-2022	M: 1 D: 23
25 Airframe PART - Expiration #5075	MEDAIRE BIOHAZARD KIT Part Number 500094 Serial Number 101220023	25-NOV-2020 H: 3947.80 L: 1309				31-AUG-2022	M: 5 D: 15
25 000025 Airframe PART #5103	AMT-700 HGA Part Number 1428-A-0010-02 Serial Number 199	18-FEB-2021 H: 3992.00 L: 1324					
25 01-52-602 Airframe INSPECTION #296	DISCARD PADDLE LATCH STRIKERS Reference Number 25-01-52-961-801	21-MAR-2010 H: 0.00	L: 6000			L: 6000	L: 4505
25 11-05-201 Airframe INSPECTION 1000 H #1728	OPERATIONAL TEST OF THE INERTIA REELS AND THE INERTIA REELS CONTROL	10-MAR-2022 H: 4455.80 L: 1495	H: 1000.00	H: 50.00		H: 5455.80	H: 1000.00
25 11-09-201 Airframe INSPECTION 1000 H #1766	GENERAL VISUAL INSPECTION OF THE SAFETY STRAPS	10-MAR-2022 H: 4455.80 L: 1495	H: 1000.00	H: 50.00		H: 5455.80	H: 1000.00





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 1100-001 Airframe PART #1673	PILOT SEAT Part Number GC721-1001-1 Serial Number 180-1400	21-MAR-2010 H: 0.00					
25 1100-002 Airframe PART #1176	COPILOT SEAT Part Number GC721-1001-2 Serial Number 176-1400	21-MAR-2010 H: 0.00					
25 13-50-601 Airframe INSPECTION 750H/30M #466	OPERATIONAL TEST OF JUMPSEAT INERTIA REELS Reference Number 25-13-50-710-801 Notes TASK INTERVAL IN ACCORDANCE WITH TLMC TASK ATA 25-11 FOR SEATS, REF TLMC SECTION 5-21-10.	08-FEB-2022 H: 4399.80 L: 1478	H: 750.00			H: 5149.80	H: 694.00
25 13-50-602 Airframe INSPECTION 750H/30M #113	GENERAL VISUAL INSPECTION OF JUMPSEAT SAFETY STRAPS Reference Number 25-13-50-210-801 Notes TASK INTERVAL IN ACCORDANCE WITH TLMC TASK ATA 25-11 FOR SEATS, REF TLMC SECTION 5-21-10.	08-FEB-2022 H: 4399.80 L: 1478	H: 750.00			H: 5149.80	H: 694.00
25 13-50-603 Airframe INSPECTION 15M #101	OPERATIONAL TEST OF THE JUMPSEAT TRACKING AND LOCKING MECHANISMS Reference Number 25-13-50-710-802 Notes TASK INTERVAL IN ACCORDANCE WITH TLMC TASK ATA 25-11 FOR SEATS, REF TLMC SECTION 5-21-10. JUMP START LOOKING HARD WHEN EXTENDED JUMP START ARM REST ARE TOO LOSE	19-APR-2021 H: 3992.00 L: 1324	M: 15			19-JUL-2022	M: 4 D: 3
25 1301-001 Airframe PART #149	LH PILOT FLOOR MAT HEATER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
25 1301-002 Airframe PART #1797	RH PILOT FLOOR MAT HEATER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 1301-003 Airframe PART #765	LH COPILOT FLOOR MAT HEATER Part Number PN	21-MAR-2010 H: 0.00	Serial Number SN- UNKNOWN				
25 1301-004 Airframe PART #1179	RH COPILOT FLOOR MAT HEATER Part Number PN	21-MAR-2010 H: 0.00	Serial Number SN- UNKNOWN				
25 1301-005 Airframe PART #4667	ENTRYWAY HEATER Part Number 2831-49	04-MAR-2016 H: 1753.70 L: 622	Serial Number 078				
25 2000-701 Airframe PART #835	JUMP SEAT (TSO C127) ASSEMBLY Part Number 1513000-3	15-FEB-2011 H: 25.00 L: 11	Serial Number 47291				
25 2000-703 Airframe PART #46	SINGLE - CREW REST - FWD FACING SEAT ASSEMBLY Part Number 3ACF1107133BCAD	15-FEB-2011 H: 25.00 L: 11	Serial Number 100303-01				
25 2000-703A Airframe PART #5061	CREW REST SEAT RETRACTABLE ARM REST ASSEMBLY. Part Number 3AAA1559501	11-SEP-2020 H: 3852.30 L: 1275	Serial Number N/A				
	Notes CREATED FD CARD 11 SEPT 2020.						
25 2000-704 Airframe PART #922	#1 LH - SINGLE - AFT FACING SEAT ASSEMBLY Part Number 3ACF1107160BCAD	15-FEB-2011 H: 25.00 L: 11	Serial Number 100303-08				
25 2000-705 Airframe PART #647	#1 RH - SINGLE - AFT FACING SEAT ASSEMBLY Part Number 3ACF1107159BCAD	15-FEB-2011 H: 25.00 L: 11	Serial Number 100303-07				
25 2000-706 Airframe PART #2843	#2 LH - SINGLE - FWD FACING SEAT ASSEMBLY Part Number 3ACF1107031BCAD	15-FEB-2011 H: 25.00 L: 11	Serial Number 100303-02				





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 2000-707 Airframe PART #1592	#2 RH - SINGLE - FWD FACING SEAT ASSEMBLY Part Number: 3ACF1107032BCAD Serial Number: 100303-03	15-FEB-2011 H: 25.00 L: 11					
25 2000-708 Airframe PART #749	#3 LH - DOUBLE - AFT FACING SEAT ASSEMBLY Part Number: 3ACF1207020BCAD Serial Number: 100303-10	15-FEB-2011 H: 25.00 L: 11					
25 2000-710 Airframe PART #2549	#4 LH - DOUBLE - FWD FACING SEAT ASSEMBLY Part Number: 3ACF1207019BCAD Serial Number: 100303-09	15-FEB-2011 H: 25.00 L: 11					
25 2000-712 Airframe PART #573	#5 LH - SINGLE - AFT FACING SEAT ASSEMBLY Part Number: 3ACF1107034BCAD Serial Number: 100303-06	15-FEB-2011 H: 25.00 L: 11					
25 2001-701 Airframe PART #370	3-PLACE AFT RH (16G) DIVAN Part Number: 41539001-209 Serial Number: 5590311S & D	15-FEB-2011 H: 25.00 L: 11					
25 21-00-601 Airframe INSPECTION 30M #2614	DETAILED INSPECTION OF PASSENGER SEATS (INCLUDING DIVANS) FOR ATTACHMENT AND LOCKING Reference Number: 25-21-50-280-801 Notes: TASK INTERVAL IN ACCORDANCE WITH TLMC TASK ATA 25-11 FOR SEATS, REF TLMC SECTION 5-21-10. L/H #1 SEAT IS NOT FULLY TRACKING L/H #2 SEAT IS NOT FULLY TRACKING R/H #1 SEAT IS NOT FULLY TRACKING	19-APR-2021 H: 3992.00 L: 1324	M: 30			19-OCT-2023	M: 19 D: 3
25 21-00-602 Airframe INSPECTION 30M #1704	DETAILED INSPECTION OF PASSENGER SEATS RESTRAINTS Reference Number: 25-21-50-280-802 Notes: TASK INTERVAL IN ACCORDANCE WITH TLMC TASK ATA 25-11 FOR SEATS, REF TLMC SECTION 5-21-10.	19-APR-2021 H: 3992.00 L: 1324	M: 30			19-OCT-2023	M: 19 D: 3





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 21-00-603 Airframe INSPECTION 30M #2672	OPERATIONAL CHECK OF PASSENGER SEAT INERTIA REELS (INCLUDING DIVANS) Reference Number 25-21-50-710-801 Notes TASK INTERVAL IN ACCORDANCE WITH TLMC TASK ATA 25-11 FOR SEATS, REF TLMC SECTION 5-21-10.	19-APR-2021 H: 3992.00 L: 1324	M: 30			19-OCT-2023	M: 19 D: 3
25 21-00-604 Airframe INSPECTION 30M #4639	INSPECT HEATED FLOOR MATS (CABIN) FOR WIRE DAMAGE AND MAT DAMAGE Notes THIS TASK SHOULD BE ACCOMPLISHED IN CONJUNCTION WITH 25-21-00-601 NO DEFECTS NOTED	19-APR-2021 H: 3992.00 L: 1324	M: 30			19-OCT-2023	M: 19 D: 3
25 21-00-605 Airframe INSPECTION 30M #4640	INSPECT CABINET DOORS/DRAWERS HINGES, LATCHES AND FASTENERS THAT ATTACH THE CABINETS TO THE AIRFRAME Notes NO DEFECTS NOTED	19-APR-2021 H: 3992.00 L: 1324	M: 30			19-OCT-2023	M: 19 D: 3
25 21-00-606 Airframe INSPECTION #4641	INSPECT ELECTRICAL WIRING INTERCONNECTION SYSTEM (EWIS) INSTALLED AS PART OF INTERIOR ALTERATIONS	29-JAN-2018 H: 2586.20 L: 898	M: 60			29-JAN-2023	M: 10 D: 13
25 21-00-607 Airframe INSPECTION #4642	GENERAL VISUAL INSPECTION ELECTRICAL WIRING INTERCONNECTION SYSTEM (EWIS) TRUENORTH SIMPHONE Notes NO DEFECTS NOTED	01-APR-2021 H: 3992.00 L: 1324	M: 60			01-APR-2026	M: 48 D: 16
25 25 6070-501 Airframe PART #4878	STATEROOM CABIN SEAT FORE/AFT FLOOR TRACK ADJUST MICROSWITCH Part Number 3AAD0207501 Serial Number NA	11-OCT-2018 H: 2919.10 L: 1001					
25 25-61-03-201 Airframe PART #5120	GALLEY TOUCHSCREEN Part Number 822-2647-103 Serial Number 3360-2321 Notes VENUE MODIFICATION				03-APR-2021		





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 25-61-04-201 Airframe PART #5121	L/H 650 MONITOR Part Number 441-0133-100 Serial Number 92240807	03-APR-2021					
	Notes VENUE MODIFICATION						
25 25-61-05-201 Airframe PART #5122	L/H 650 COOLING FAN Part Number 009-0287 Serial Number 001638	03-APR-2021					
	Notes VENUE MODIFICATION						
25 25-61-06-201 Airframe PART #5123	R/H 420 MONITOR Part Number 441-0133-100 Serial Number 92240806	03-APR-2021					
	Notes VENUE MODIFICATION						
25 30-02 Airframe INSPECTION #4638	INSPECTION OF CONVECTION OVEN	03-JAN-2022 H: 4399.80 L: 1478	M: 24			03-JAN-2024	M: 21 D: 18
25 30-50-601 Airframe INSPECTION 1500H #1781	GENERAL VISUAL INSPECTION OF GALLEY WASTE CONTAINER Reference Number 25-30-50-210-801	08-FEB-2022 H: 4399.80 L: 1478	H: 1500.00			H: 5899.80	H: 1444.00
25 30-50-602 Airframe INSPECTION 30M #1975	GENERAL VISUAL INSPECTION OF GALLEY APPLIANCES Reference Number 25-30-50-210-802	19-APR-2021 H: 3992.00 L: 1324	M: 30			19-OCT-2023	M: 19 D: 3
	Notes COMPLIED WITH GVI OF GALLERY APPLIANCES. NO DEFECTS NOTED						
25 30-50-605 Airframe INSPECTION 500H #1642	REPLACEMENT OF THE GALLEY CHILLER AIR FILTER Reference Number 25-30-50-960-801	10-MAR-2022 H: 4455.80 L: 1495	H: 500.00			H: 4955.80	H: 500.00
	Notes INTERVAL TO BE DETERMINED BY OPERATOR BASED ON THEIR EXPERIENCE, OPERATIONAL REQUIREMENTS, AND/OR ENVIRONMENTAL CONDITIONS.						





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 3000 Airframe PART #4832	THIRD CREW MEMBER OXYGEN STORAGE BOX Part Number: MXP411-3 Serial Number: 15362	22-JAN-2018 H: 2586.20 L: 898					
25 3000-701 Airframe PART #2786	TIA HYBRID CONVECTION OVEN Part Number: 400-2286-01 Serial Number: 13-04-51925	09-AUG-2013 H: 432.80 L: 211					
25 3002-701 Airframe PART #1509	MICROWAVE OVEN AND MOUNT UNIT Part Number: NN-SN661S Serial Number: 6833140541	09-AUG-2013 H: 432.80 L: 211					
25 3003-701 Airframe PART #596	AIR CHILLER UNIT Part Number: 319-4 Serial Number: 629	15-FEB-2011 H: 25.00 L: 11					
25 3006-701 Airframe PART #903	L/H ROLLERSHADE ASSY Part Number: 7002510364-001 Serial Number: 376	21-OCT-2020 H: 3913.60 L: 1297					
25 3006-702 Airframe PART #2784	R/H ROLLERSHADE ASSY Part Number: 7002510364-002 Serial Number: 362	03-JAN-2020 H: 3618.70 L: 1196					
25 40-50-601 Airframe INSPECTION LAV INSP #1856	GENERAL VISUAL INSPECTION OF LAVATORY WASTE CONTAINER Reference Number: 25-40-50-210-801	05-MAR-2022 H: 4446.70 L: 1492	H: 1000.00			H: 5446.70	H: 990.90
25 60-00-201 Airframe PART #2864	RESTORATION COPILOT LIFE VEST Part Number: P01074-201WC Serial Number: 2005107001 1	15-APR-2021 H: 3992.00 L: 1324	M: 60			31-MAY-2030	M: 98 D: 15
	Notes DOE: 05-31-2030						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 60-00-201 Airframe PART #331	RESTORATION PILOT LIFE VEST Part Number 901074-201WC Serial Number 2005107001 0	15-APR-2021 H: 3992.00 L: 1324	M: 60			31-MAY-2030	M: 98 D: 15
Notes DOE: 05-31-2030							
25 60-00-202 Airframe PART CREW PBE #2117	RESTORATION FLIGHT COMPARTMENT PROTECTIVE BREATHING EQUIPMENT - CREW PBE Part Number 119003-21 Serial Number 004- 04682M	18-AUG-2016 H: 1948.40 L: 681	M: 120			18-MAR-2025	M: 36 D: 2
Notes LOCATED FORWARD CREW CLOSET.							
25 60-00-203 Airframe PART CREW PBE #1820	DISCARD FLIGHT COMPARTMENT PROTECTIVE BREATHING EQUIPMENT - CREW PBE Part Number 119003-21 Serial Number 004- 04682M	18-AUG-2016 H: 1948.40 L: 681	M: 240			18-MAR-2025	M: 36 D: 2
Notes LOCATED FORWARD CREW CLOSET							
25 60-00-204 Airframe PART - Life Limited #3291	RESTORE PROTECTIVE BREATHING EQUIPMENT (PBE) Part Number DP3113AMR-10037N Serial Number E0904548	28-FEB-2019 H: 0.00	M: 126		M: 0 H: 0.00 L: 0	28-AUG-2029	M: 89 D: 12
Notes LOCATED AFT WARDROBE CLOSET.							
25 60-00-208 Airframe INSPECTION 1000 H, COPILOT LV #2152	DETAILED INSPECTION COPILOT LIFE VEST Part Number P01074-201WC Serial Number 2005107001 1	10-MAR-2022 H: 4455.80 L: 1495	H: 1000.00	H: 50.00		H: 5455.80	H: 1000.00
25 60-00-208 Airframe INSPECTION 1000 H, PILOT LV #480	DETAILED INSPECTION PILOT LIFE VEST Part Number 901074-201WC Serial Number 2005107001 0	10-MAR-2022 H: 4455.80 L: 1495	H: 1000.00	H: 50.00		H: 5455.80	H: 1000.00
25 60-00-209 Airframe INSPECTION 1000 H #1713	DETAILED INSPECTION FLIGHT COMPARTMENT PROTECTIVE BREATHING EQUIPMENT - CREW PBE	10-MAR-2022 H: 4455.80 L: 1495	H: 1000.00	H: 50.00		H: 5455.80	H: 1000.00





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 60-00-210 Airframe INSPECTION 30M #2024	RESTORATION OF THE CREW FLASHLIGHTS	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
25 60-00-211 Airframe PART #5038	FLASHLIGHT, PILOT Part Number Serial Number P2-07-0022-001 N/A	15-JUL-2020 H: 3806.80 L: 1260					
25 60-00-212 Airframe PART #5039	FLASHLIGHT, COPILOT Part Number Serial Number P2-07-0022-001 N/A	15-JUL-2020 H: 3806.80 L: 1260					
25 60-00-213 Airframe PART #5040	FLASHLIGHT, CREW CLOSET Part Number Serial Number P2-07-0022-001 N/A	15-JUL-2020 H: 3806.80 L: 1260					
	Notes CREATED WORK CARD 7/15/2020. RON GIANNINI						
25 60-00-214 Airframe PART #5041	FLASHLIGHT, BAGGAGE COMPARTMENT Part Number Serial Number P2-07-0022-001 N/A	15-JUL-2020 H: 3806.80 L: 1260					
25 60-00-602 Airframe INSPECTION 15M #1563	DETAILED INSPECTION OF THE LIFE VESTS Reference Number 25-60-52-220-801	19-APR-2021 H: 3992.00 L: 1324	M: 15			19-JUL-2022	M: 4 D: 3
	Notes TASK INTERVAL IN ACCORDANCE WITH EQUIVALENT TLMC TASK ATA 25-60, REF TLMC SECTION 5-21-10. NEXT INSPECTION IS 9/2021/ NO DEFECTS NOTED						
25 60-00-603 Airframe PART #2661	RESTORE CABIN LIFE VEST - AFT DIVAN 2 Reference Number Part Number Serial Number 25-62-50-610-801; 63600-191 CMM 25-64-02 Rev. 31, 01/08/2016 L5154439	03-SEP-2021 H: 4258.30 L: 1423	M: 60			03-SEP-2026	M: 53 D: 18
	Notes INTERVAL IS PER VENDOR'S RECOMMENDATION AS OF PUBLICATION DATE OF THIS STLMC. REFER TO THE TABLE BELOW FOR VENDOR RECOMMENDATION. THE TASK DUE TIME IS CALCULATED FROM THE DATE NOTED IN THE CERTIFICATION DOCUMENTATION.						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 60-00-603 Airframe PART #2764	RESTORE CABIN LIFE VEST - AFT DIVAN 3 Reference Number Part Number Serial Number 25-62-50-610-801; 63600-191 L5154439 CMM 25-64-02 Rev. 31, 01/08/2016 Notes INTERVAL IS PER VENDOR'S RECOMMENDATION AS OF PUBLICATION DATE OF THIS STLMC. REFER TO THE TABLE BELOW FOR VENDOR RECOMMENDATION. THE TASK DUE TIME IS CALCULATED FROM THE DATE NOTED IN THE CERTIFICATION DOCUMENTATION. DOE: 10-01-2030 DOE: 10-01-2030	14-APR-2021 H: 3992.00 L: 1324	M: 60			01-OCT-2030	M: 102 D: 15
25 60-00-603 Airframe PART #1779	RESTORE CABIN LIFE VEST - CONF AFT IB Reference Number Part Number Serial Number 25-62-50-610-801; 63600-191 L5154424 CMM 25-64-02 Rev. 31, 01/08/2016 Notes INTERVAL IS PER VENDOR'S RECOMMENDATION AS OF PUBLICATION DATE OF THIS STLMC. REFER TO THE TABLE BELOW FOR VENDOR RECOMMENDATION. THE TASK DUE TIME IS CALCULATED FROM THE DATE NOTED IN THE CERTIFICATION DOCUMENTATION. DOE: 10-01-2030	14-APR-2021 H: 3992.00 L: 1324	M: 60			01-OCT-2030	M: 102 D: 15
25 60-00-603 Airframe PART #1866	RESTORE CABIN LIFE VEST - CONF AFT OB Reference Number Part Number Serial Number 25-62-50-610-801; 63600-191 L5154426 CMM 25-64-02 Rev. 31, 01/08/2016 Notes INTERVAL IS PER VENDOR'S RECOMMENDATION AS OF PUBLICATION DATE OF THIS STLMC. REFER TO THE TABLE BELOW FOR VENDOR RECOMMENDATION. THE TASK DUE TIME IS CALCULATED FROM THE DATE NOTED IN THE CERTIFICATION DOCUMENTATION. DOE: 10-01-2030	14-APR-2021 H: 3992.00 L: 1324	M: 60			01-OCT-2030	M: 102 D: 15



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 60-00-603 Airframe PART #1167	RESTORE CABIN LIFE VEST - CONF FWD INBRD Reference Number Part Number Serial Number 25-62-50-610-801; 63600-191 L5154429 CMM 25-64-02 Rev. 31, 01/08/2016 Notes INTERVAL IS PER VENDOR'S RECOMMENDATION AS OF PUBLICATION DATE OF THIS STLMC. REFER TO THE TABLE BELOW FOR VENDOR RECOMMENDATION. THE TASK DUE TIME IS CALCULATED FROM THE DATE NOTED IN THE CERTIFICATION DOCUMENTATION. DOE: 10-01-2030	14-APR-2021 H: 3992.00 L: 1324	M: 60			01-OCT-2030	M: 102 D: 15
25 60-00-603 Airframe PART #879	RESTORE CABIN LIFE VEST - CONF FWD OB Reference Number Part Number Serial Number 25-62-50-610-801; 63600-191 L5154430 CMM 25-64-02 Rev. 31, 01/08/2016 Notes INTERVAL IS PER VENDOR'S RECOMMENDATION AS OF PUBLICATION DATE OF THIS STLMC. REFER TO THE TABLE BELOW FOR VENDOR RECOMMENDATION. THE TASK DUE TIME IS CALCULATED FROM THE DATE NOTED IN THE CERTIFICATION DOCUMENTATION. DOE: 10-01-2030	14-APR-2021 H: 3992.00 L: 1324	M: 60			01-OCT-2030	M: 102 D: 15
25 60-00-603 Airframe PART #2064	RESTORE CABIN LIFE VEST - FWD DIVAN 2 Reference Number Part Number Serial Number 25-62-50-610-801; 63600-191 L5154436 CMM 25-64-02 Rev. 31, 01/08/2016 Notes INTERVAL IS PER VENDOR'S RECOMMENDATION AS OF PUBLICATION DATE OF THIS STLMC. REFER TO THE TABLE BELOW FOR VENDOR RECOMMENDATION. THE TASK DUE TIME IS CALCULATED FROM THE DATE NOTED IN THE CERTIFICATION DOCUMENTATION. DOE: 10-01-2030	14-APR-2021 H: 3992.00 L: 1324	M: 60			01-OCT-2030	M: 102 D: 15
25 60-00-603 Airframe PART #2382	RESTORE CABIN LIFE VEST - FWD DIVAN 3 Reference Number Part Number Serial Number 25-62-50-610-801; 63600-191 L5154437 CMM 25-64-02 Rev. 31, 01/08/2016 Notes INTERVAL IS PER VENDOR'S RECOMMENDATION AS OF PUBLICATION DATE OF THIS STLMC. REFER TO THE TABLE BELOW FOR VENDOR RECOMMENDATION. THE TASK DUE TIME IS CALCULATED FROM THE DATE NOTED IN THE CERTIFICATION DOCUMENTATION. DOE: 10-01-2030	14-APR-2021 H: 3992.00 L: 1324	M: 60			01-OCT-2031	M: 114 D: 15





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 60-00-603 Airframe PART #617	RESTORE CABIN LIFE VEST - LH #1 Reference Number Part Number Serial Number 25-62-50-610-801; 63600-191 L5154422 CMM 25-64-02 Rev. 31, 01/08/2016 Notes	14-APR-2021 H: 3992.00 L: 1324	M: 60			01-OCT-2030	M: 102 D: 15
<p>INTERVAL IS PER VENDOR'S RECOMMENDATION AS OF PUBLICATION DATE OF THIS STLMC. REFER TO THE TABLE BELOW FOR VENDOR RECOMMENDATION. THE TASK DUE TIME IS CALCULATED FROM THE DATE NOTED IN THE CERTIFICATION DOCUMENTATION.</p> <p>DOE: 10-01-2030</p>							
25 60-00-603 Airframe PART #817	RESTORE CABIN LIFE VEST - LH #2 Reference Number Part Number Serial Number 25-62-50-610-801; 63600-191 L5154423 CMM 25-64-02 Rev. 31, 01/08/2016 Notes	16-APR-2021 H: 3992.00 L: 1324	M: 60			01-OCT-2030	M: 102 D: 15
<p>INTERVAL IS PER VENDOR'S RECOMMENDATION AS OF PUBLICATION DATE OF THIS STLMC. REFER TO THE TABLE BELOW FOR VENDOR RECOMMENDATION. THE TASK DUE TIME IS CALCULATED FROM THE DATE NOTED IN THE CERTIFICATION DOCUMENTATION.</p> <p>DOE: 10-01-2030</p>							
25 60-00-603 Airframe PART #685	RESTORE CABIN LIFE VEST - RH #1 Reference Number Part Number Serial Number 25-62-50-610-801; 63600-191 L5154420 CMM 25-64-02 Rev. 31, 01/08/2016 Notes	14-APR-2021 H: 3992.00 L: 1324	M: 60			01-OCT-2030	M: 102 D: 15
<p>INTERVAL IS PER VENDOR'S RECOMMENDATION AS OF PUBLICATION DATE OF THIS STLMC. REFER TO THE TABLE BELOW FOR VENDOR RECOMMENDATION. THE TASK DUE TIME IS CALCULATED FROM THE DATE NOTED IN THE CERTIFICATION DOCUMENTATION.</p> <p>DOE: 10-01-2030</p>							
25 60-00-603 Airframe PART #825	RESTORE CABIN LIFE VEST - RH #2 Reference Number Part Number Serial Number 25-62-50-610-801; 63600-191 L5154421 CMM 25-64-02 Rev. 31, 01/08/2016 Notes	14-APR-2021 H: 3992.00 L: 1324	M: 60			01-OCT-2030	M: 102 D: 15
<p>INTERVAL IS PER VENDOR'S RECOMMENDATION AS OF PUBLICATION DATE OF THIS STLMC. REFER TO THE TABLE BELOW FOR VENDOR RECOMMENDATION. THE TASK DUE TIME IS CALCULATED FROM THE DATE NOTED IN THE CERTIFICATION DOCUMENTATION.</p> <p>DOE: 10-01-2030</p>							





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 60-00-603 Airframe PART #2846	RESTORE CABIN LIFE VEST - AFT DESK Reference Number Part Number Serial Number 25-62-50-610-801; 63600-191 L5154431 CMM 25-64-02 Rev. 31, 01/08/2016 Notes INTERVAL IS PER VENDOR'S RECOMMENDATION AS OF PUBLICATION DATE OF THIS STLMC. REFER TO THE TABLE BELOW FOR VENDOR RECOMMENDATION. THE TASK DUE TIME IS CALCULATED FROM THE DATE NOTED IN THE CERTIFICATION DOCUMENTATION. DOE: 10-01-2030	14-APR-2021	M: 60			01-OCT-2030	M: 102 D: 15
25 60-00-603 Airframe PART #2631	RESTORE CABIN LIFE VEST - AFT DIVAN 1 Reference Number Part Number Serial Number 25-62-50-610-801; 63600-191 L5154432 CMM 25-64-02 Rev. 31, 01/08/2016 Notes INTERVAL IS PER VENDOR'S RECOMMENDATION AS OF PUBLICATION DATE OF THIS STLMC. REFER TO THE TABLE BELOW FOR VENDOR RECOMMENDATION. THE TASK DUE TIME IS CALCULATED FROM THE DATE NOTED IN THE CERTIFICATION DOCUMENTATION. DOE: 10-01-2030	14-APR-2021	M: 60			01-OCT-2030	M: 102 D: 15
25 60-00-603 Airframe PART #1884	RESTORE CABIN LIFE VEST - FWD DIVAN 1 Reference Number Part Number Serial Number 25-62-50-610-801; 63600-191 L5154435 CMM 25-64-02 Rev. 31, 01/08/2016 Notes INTERVAL IS PER VENDOR'S RECOMMENDATION AS OF PUBLICATION DATE OF THIS STLMC. REFER TO THE TABLE BELOW FOR VENDOR RECOMMENDATION. THE TASK DUE TIME IS CALCULATED FROM THE DATE NOTED IN THE CERTIFICATION DOCUMENTATION. DOE: 10-01-2030	14-APR-2021	M: 60			01-OCT-2030	M: 102 D: 15
25 60-00-604 Airframe INSPECTION #1989	DETAILED INSPECTION OF THE LIFE RAFTS Reference Number 25-62-50-280-802 Notes NEXT SERVICE DUE 07/2023 FOR BOTH RAFTS/ NO DEFECTS NOTED	07-NOV-2021	M: 30			07-MAY-2024	M: 25 D: 21



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 60-00-606 Airframe PART - Life Limited MED KIT #2222	DETAILED INSPECTION ADVANCED AVIATION MEDICAL KIT Reference Number Part Number Serial Number 25-60-50-280-802 573848 AMK-001	18-NOV-2021 H: 4368.30 L: 1464	M: 12		M: 24	18-NOV-2022	M: 8 D: 2
	Notes NEW UNIT FROM AIRCAREACCESS ASSISTANCE DIRECT REPLACEMENT FROM MEDAIRE. EXPIRES NOV 2022/ NO DEFECTS NOTED						
25 60-52-601 Airframe INSPECTION #2477	DETAILED INSPECTION OF THE CREW FLASHLIGHTS Reference Number 25-60-52-220-801; 25-60-14 Rev. C, 12/16/2014	14-APR-2021 H: 3992.00 L: 1324	M: 12			14-APR-2022	M: 0 D: 29
	Notes INTERVAL IS PER VENDOR'S RECOMMENDATION AS OF PUBLICATION DATE OF THIS STLMC. REFER TO THE TABLE BELOW FOR VENDOR RECOMMENDATION.						
25 6000-003B Airframe PART #562	RESTORATION JUMPSEAT LIFE VEST Part Number Serial Number 63600-591 L5146135	14-APR-2021 H: 3992.00 L: 1324				01-OCT-2030	M: 102 D: 15
	Notes DOE: 10-01-2030						
25 6000-004B Airframe PART #2889	RESTORATION CREW LIFE VEST Part Number Serial Number 63600-591 L5146121	14-APR-2021 H: 3992.00 L: 1324				01-OCT-2030	M: 102 D: 15
	Notes DOE: 10-01-2030						
25 6050-010 Airframe PART #1017	PILOT EMERGENCY VISION ASSURANCE SYSTEM - EVAS Part Number Serial Number 107P-191 0007Y03P	15-MAR-2022 H: 4455.80 L: 1495					
25 6050-010A Airframe INSPECTION PILOT EVAS #1332	CHECK PILOT EMERGENCY VISION ASSURANCE SYSTEM - EVAS - BLOWER, BATTERY, AND VERIFY GLARESHIELD LOOP FASTENER (PERIODIC INSPECTION) Part Number Serial Number 107P-191 0007Y03P	15-MAR-2022 H: 4455.80 L: 1495	M: 3			30-JUN-2022	M: 3 D: 14
25 6050-010B Airframe INSPECTION PILOT EVAS #2286	RETURN PILOT EMERGENCY VISION ASSURANCE SYSTEM - EVAS TO MANUFACTURER FOR BIENNIAL INSPECTION Part Number Serial Number 107P-191 0007Y03P	15-MAR-2022 H: 4455.80 L: 1495	M: 24			15-MAR-2024	M: 23 D: 28





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 6050-010C Airframe INSPECTION PILOT EVAS #2278	RETURN PILOT EMERGENCY VISION ASSURANCE SYSTEM - EVAS TO MANUFACTURER FOR 120M OVERHAUL Part Number: 107P-191 Serial Number: 0007Y03P	15-MAR-2022 H: 4455.80 L: 1495	M: 120			15-MAR-2032	M: 119 D: 28
25 6050-020 Airframe PART #888	COPILOT EMERGENCY VISION ASSURANCE SYSTEM - EVAS Part Number: 107-192 Serial Number: 0008Y03P	15-MAR-2022 H: 4455.80 L: 1495					
Notes REMOVED RH EVAS ASSY PN 107P-191 SN 0008Y03P AND INSTALLED LOANER EVAS ASSY PN 107P-191 SN 028GG02P , I/A/W BD700 XRS SMM 25-60-05-000/400-801,ALL TESTS SATISFACTORY.							
25 6050-020A Airframe INSPECTION COPILOT EVAS #1384	CHECK COPILOT EMERGENCY VISION ASSURANCE SYSTEM - EVAS - BLOWER AND BATTERY (PERIODIC INSPECTION) Part Number: 107-192 Serial Number: 0008Y03P	15-MAR-2022 H: 4455.80 L: 1495	M: 3			30-JUN-2022	M: 3 D: 14
25 6050-020B Airframe INSPECTION COPILOT EVAS #64	RETURN COPILOT EMERGENCY VISION ASSURANCE SYSTEM - EVAS TO MANUFACTURER FOR BIENNIAL INSPECTION Part Number: 107-192 Serial Number: 0008Y03P	15-MAR-2022 H: 4455.80 L: 1495	M: 24			15-MAR-2024	M: 23 D: 28
Notes REMOVED RH EVAS ASSY PN 107P-191 SN 0008Y03P AND INSTALLED LOANER EVAS ASSY PN 107P-191 SN 028GG02P , I/A/W BD700 XRS SMM 25-60-05-000/400-801,ALL TESTS SATISFACTORY.							
25 6050-020C Airframe INSPECTION COPILOT EVAS #1298	RETURN COPILOT EMERGENCY VISION ASSURANCE SYSTEM - EVAS TO MANUFACTURER FOR 120M OVERHAUL Part Number: 107-192 Serial Number: 0008Y03P	15-MAR-2022 H: 4455.80 L: 1495	M: 120			15-MAR-2032	M: 119 D: 28
Notes MOVED RH EREVAS ASSY PN 107P-191 SN 0008Y03P AND INSTALLED LOANER EVAS ASSY PN 107P-191 SN 028GG02P , I/A/W BD700 XRS SMM 25-60-05-000/400-801,ALL TESTS SATISFACTORY							
25 6070-702 Airframe PART #1585	SWITCH PANEL. Part Number: 3AAE0575501 Serial Number: NSN	30-JAN-2013 H: 0.00					
25 6070-703 Airframe PART #1319	SWITCH PANEL.. Part Number: 3AAE0575501 Serial Number: NSN	30-JAN-2013 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 6070-704 Airframe PART #2150	LUMBAR SWITCH PANEL Part Number 320-1157-00 Serial Number NSN	30-JAN-2013 H: 0.00					
25 6070-705 Airframe PART #1227	LUMBAR SWITCH PANEL Part Number 320-11577-00 Serial Number NSN	30-JAN-2013 H: 0.00					
25 6070-706 Airframe PART #2247	LUMBAR SWITCH PANEL. Part Number 320-11577-00 Serial Number NSN	30-JAN-2013 H: 0.00					
25 6080-701 Airframe PART - Life Limited #2455	PROTECTIVE BREATHING (PBE) EQUIPMENT Part Number MR-10010N Serial Number R1308250	09-AUG-2013 H: 0.00	M: 126		M: 0 H: 0.00 L: 0	09-FEB-2024	M: 22 D: 24
25 6080-702 Airframe PART - Life Limited #2934	PROTECTIVE BREATHING (PBE) EQUIPMENT Part Number MR-10010N Serial Number R1308251	09-AUG-2013 H: 0.00	M: 126		M: 0 H: 0.00 L: 0	09-FEB-2024	M: 22 D: 24
25 6080-703 Airframe PART - Life Limited #2734	PROTECTIVE BREATHING (PBE) EQUIPMENT Part Number MR-10010N Serial Number R1308627	09-AUG-2013 H: 0.00	M: 126		M: 0 H: 0.00 L: 0	09-FEB-2024	M: 22 D: 24
25 6080-704 Airframe PART - Life Limited #1541	PROTECTIVE BREATHING (PBE) EQUIPMENT Part Number MR-10010N Serial Number R1308634	09-AUG-2013 H: 0.00	M: 126		M: 0 H: 0.00 L: 0	09-FEB-2024	M: 22 D: 24
25 6080-705 Airframe PART - Life Limited #1222	PROTECTIVE BREATHING (PBE) EQUIPMENT Part Number MR-10010N Serial Number R1308636	09-AUG-2013 H: 0.00	M: 126		M: 0 H: 0.00 L: 0	09-FEB-2024	M: 22 D: 24
25 6080-706 Airframe PART - Life Limited #116	PROTECTIVE BREATHING (PBE) EQUIPMENT Part Number MR-10010N Serial Number R1308648	09-AUG-2013 H: 0.00	M: 126		M: 0 H: 0.00 L: 0	09-FEB-2024	M: 22 D: 24
25 6080-707 Airframe PART - Life Limited #2329	PROTECTIVE BREATHING (PBE) EQUIPMENT Part Number MR-10010N Serial Number R1308650	09-AUG-2013 H: 0.00	M: 126		M: 0 H: 0.00 L: 0	09-FEB-2024	M: 22 D: 24





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 6080-708 Airframe PART - Life Limited #2521	PROTECTIVE BREATHING (PBE) EQUIPMENT Part Number Serial Number MR-10010N R1308652	09-AUG-2013 H: 0.00	M: 126		M: 0 H: 0.00 L: 0	09-FEB-2024	M: 22 D: 24
25 6080-709 Airframe PART - Life Limited #219	PROTECTIVE BREATHING (PBE) EQUIPMENT Part Number Serial Number MR-10010N R1308668	09-AUG-2013 H: 0.00	M: 126		M: 0 H: 0.00 L: 0	09-FEB-2024	M: 22 D: 24
25 6080-710 Airframe PART - Life Limited #1025	PROTECTIVE BREATHING (PBE) EQUIPMENT Part Number Serial Number MR-10010N R1308657	09-AUG-2013 H: 0.00	M: 126		M: 0 H: 0.00 L: 0	09-FEB-2024	M: 22 D: 24
25 6080-711 Airframe PART - Life Limited #2534	PROTECTIVE BREATHING (PBE) EQUIPMENT Part Number Serial Number MR-10010N R1308659	09-AUG-2013 H: 0.00	M: 126		M: 0 H: 0.00 L: 0	09-FEB-2024	M: 22 D: 24
25 6080-712 Airframe PART - Life Limited #2239	PROTECTIVE BREATHING (PBE) EQUIPMENT Part Number Serial Number MR-10010N R1308682	09-AUG-2013 H: 0.00	M: 126		M: 0 H: 0.00 L: 0	09-FEB-2024	M: 22 D: 24
25 6080-713 Airframe PART - Life Limited #917	PROTECTIVE BREATHING (PBE) EQUIPMENT Part Number Serial Number MR-10010N R1308688	09-AUG-2013 H: 0.00	M: 126		M: 0 H: 0.00 L: 0	09-FEB-2024	M: 22 D: 24
25 6080-714 Airframe PART - Life Limited #2350	PROTECTIVE BREATHING (PBE) EQUIPMENT Part Number Serial Number MR-10010N R1309118	09-AUG-2013 H: 0.00	M: 126		M: 0 H: 0.00 L: 0	09-FEB-2024	M: 22 D: 24
25 6080-715 Airframe PART - Life Limited #1533	PROTECTIVE BREATHING (PBE) EQUIPMENT Part Number Serial Number MR-10010N R1309130	09-AUG-2013 H: 0.00	M: 126		M: 0 H: 0.00 L: 0	09-FEB-2024	M: 22 D: 24
25 6080-716 Airframe PART - Life Limited #2712	PROTECTIVE BREATHING (PBE) EQUIPMENT Part Number Serial Number MR-10010N R1309133	09-AUG-2013 H: 0.00	M: 126		M: 0 H: 0.00 L: 0	09-FEB-2024	M: 22 D: 24
25 6080-717 Airframe PART - Life Limited #276	PROTECTIVE BREATHING (PBE) EQUIPMENT Part Number Serial Number MR-10010N R1309137	09-AUG-2013 H: 0.00	M: 126		M: 0 H: 0.00 L: 0	09-FEB-2024	M: 22 D: 24





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 6085-700 Airframe PART - Expiration #4935	BLOOD-BORNE PATHOGENS KIT - AIRCRAFT Part Number: BBP-01 Serial Number: 536882	13-MAY-2021 H: 4037.10 L: 1340	M: 12	M: 12		13-MAY-2022	M: 1 D: 27
	Notes RETURN TO AIRCARE INTERNATIONAL FOR RENEWAL 401 E. 25TH ST. SUITE H TACOMA, WA 98412 360-754-1911						
25 6085-700-1 Airframe PART - Expiration #4936	BLOOD-BORNE PATHOGENS KIT - AIRCRAFT Part Number: BBP-01 Serial Number: 536817	13-MAY-2021 H: 4037.10 L: 1340	M: 12			13-MAY-2022	M: 1 D: 27
	Notes RETURN TO AIRCARE INTERNATIONAL FOR RENEWAL 401 E. 25TH ST. SUITE H TACOMA, WA 98412 360-754-1911						
25 6085-701 Airframe PART #1052	ADVANCED AVIATION MEDICAL KIT Part Number: 501240 Serial Number: 080315004	14-NOV-2020 H: 3932.20 L: 1303					
	Notes REFURBISHED BY MEDAIR.						
25 6085-702 Airframe PART #4790	PEDIATRIC SUPPLEMENTAL MEDICAL KIT Part Number: 573862 Serial Number: PMK-002	18-NOV-2021 H: 4368.30 L: 1464	M: 12			18-NOV-2022	M: 8 D: 2
	Notes REPLACED WITH NEW VENDOR AIRCAREACCESS ASSISTANCE ,DIRECT REPLACEMENT FOR MEDAIRE UNITS.						
25 6090-701 Airframe PART - Life Limited #4840	Spectrum FX, Firebane Extinguishing Agent (Crew Rest) Part Number: LKFD Serial Number: 202539	15-DEC-2020 H: 3973.00 L: 1319			M: 0 H: 0.00 L: 0	31-DEC-2022	M: 9 D: 15
	Notes EXPIRES 31 DECEMBER 2022.						
25 61-00-201 Airframe INSPECTION #2789	OPERATIONAL TEST EMERGENCY LOCATOR TRANSMITTER SYSTEM	07-NOV-2021 H: 4341.90 L: 1453	M: 12			30-NOV-2022	M: 8 D: 14





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 61-01-201 Airframe PART #2358	DISCARD EMERGENCY LOCATOR TRANSMITTER BATTERY Part Number 452-0133 Serial Number 378226-005	01-DEC-2018 H: 3011.20 L: 1025				30-SEP-2023	M: 18 D: 14
25 61-02-201 Airframe PART #5119	L/H 750 MONITOR Part Number 441-0117-100 Serial Number 93220174 Notes VENUE MODIFICATION					03-APR-2021	
25 61-08-201 Airframe PART #5126	USB INPUT PANEL Part Number 441-0091-100 Serial Number 4L9H1F Notes VENUE MODIFICATION					03-APR-2021	
25 6105-001 Airframe PART #1542	ELT ANTENNA Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
25 6117-001 Airframe PART #217	L/H ELT NAV INTERFACE UNIT Part Number 453-6500 Serial Number 8252	21-MAR-2010 H: 0.00					
25 8084-700 Airframe PART #3575	AED FRX DEFIBRILLATOR Part Number 05060167120671 Serial Number 21D910962 31L21	14-FEB-2022 H: 4413.20 L: 1483					
25 8084-700A Airframe INSPECTION #1936	VISUAL INSPECTION AED FRX DEFIBRILLATOR	02-OCT-2021 H: 4294.70 L: 1439	M: 12			02-OCT-2022	M: 6 D: 16
25 8084-700B Airframe PART - Expiration #4957	REPLACE AED FRX DEFIBRILLATOR PADS Part Number PAD-PAK-07 Serial Number D5266-057 / D5255-139	14-FEB-2022 H: 4413.20 L: 1483	M: 24			23-JAN-2026	M: 46 D: 7





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 8084-700C Airframe PART - Expiration #4958	REPLACE AED FRX DEFIBRILLATOR BATTERY	09-FEB-2020	M: 36			09-FEB-2023	M: 10 D: 24
25 9500-701B Airframe PART - Expiration #1292	FWD LIFE RAFT RESTORE Part Number: 1218FASA-6J1-1-609 Serial Number: 12UL-01780	12-APR-2021	H: 3992.00 L: 1324			12-APR-2022	M: 0 D: 27
	Notes REPLACE ELT BATTERY @ RESTORE.						
25 9500-702B Airframe PART - Expiration #648	AFT LIFE RAFT RESTORE Part Number: 1218FAUL-6J1-1-159 Serial Number: 12UL-01779	12-APR-2021	H: 3992.00 L: 1324			12-APR-2022	M: 0 D: 27
	Notes REPLACE ELT BATTERY @ RESTORE.						
25 9501-701C Airframe PART - Expiration #1103	DISCARD AFT LIFE RAFT (SRB-406) ELT BATTERY Part Number: SRB-406 Serial Number: 138520	07-APR-2021	H: 3992.00 L: 1324			07-APR-2022	M: 0 D: 22
	Notes (REPLACE ELT BATTERY @ EVERY LIFE RAFT RESTORE)						
25 9501-702C Airframe PART - Expiration #2499	DISCARD FWD LIFE RAFT (SRB-406) ELT BATTERY Part Number: SRB-406 Serial Number: 138510	16-APR-2021	H: 3992.00 L: 1324			16-APR-2022	M: 1 D: 0
	Notes (REPLACE ELT BATTERY @ EVERY LIFE RAFT RESTORE)						
25 CERTIFICATE256070-701 Airframe PART #1334	SWITCH PANEL Part Number: 3AAE0575501 Serial Number: NSN	30-JAN-2013	H: 0.00				
25 CMM-41-2018US-01 Airframe PART #4791	TEMPUS IC2 UNIT Part Number: 00-2001 Serial Number: 001443	29-JAN-2018	H: 2586.20 L: 898				
	Notes REF CMM 41-2018US-01						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 CMM-41-2018US-01-3.2 Airframe INSPECTION #4793	ANNUAL TEMPUS IC2 UNIT TEST - GENERAL VISUAL INSPECTION WITH MAIN BATTERY CHARGE , GLUCOMETER BATTERY CHANGE 2 AAA, AND THERMOMETER BATTERY CHANGE 2 AAA.	04-OCT-2021 H: 4294.70 L: 1439	M: 12			04-OCT-2022	M: 6 D: 18
<p>Notes</p> <p>Reference: Tempus IC2 Maintenance Manual P/N 41-2018US-01, Rev: FEB.17,2016 SEC 4.2.2</p>							
25 CUS-01 Airframe PART #4821	REPLACE FWD AND AFT CABIN CLOCK BATTERIES Part Number LR 1/N/230225 Serial Number NSN	07-NOV-2021 H: 4341.90 L: 1453	M: 6			31-MAY-2022	M: 2 D: 15
<p>Notes</p> <p>WEMPE CLOCKS BATTERIES ARE P/N LR1 OR N OR RADIO SHACK 2302225</p>							
25 DOC 1024901 RB Airframe INSPECTION #5014	HEADS UP TECHNOLOGIES DUAL XM WEATHER SYSTEM	04-MAR-2016 H: 1753.70 L: 622					
25 DOC 1024901 RB Airframe INSPECTION #5030	HEADS UP TECHNOLOGIES DUAL XM WEATHER SYSTEM- 24 MONTH	15-JUN-2020 H: 3778.50 L: 1252	M: 24			15-JUN-2022	M: 2 D: 30
25 DOC 1024901 RB Airframe INSPECTION #5031	HEADS UP TECHNOLOGIES DUAL XM WEATHER SYSTEM- ELECTRICAL WIRING INTERCONNECTION SYSTEM (EWIS) INSPECTION	15-APR-2021 H: 3992.00 L: 1324	M: 60			15-APR-2026	M: 48 D: 30
25 DOC 1024901 RB Airframe INSPECTION #5029	HEADS UP TECHNOLOGIES DUAL XM WEATHER SYSTEM- GENERAL VISUAL INSPECTION	15-APR-2021 H: 3992.00 L: 1324	M: 60			15-APR-2026	M: 48 D: 30
25 DOC 1024903 RA Airframe INSPECTION #5024	INSTRUCTIONS FOR CONTINUED AIRWORTHINESS FOR AIRCELL ATG 5000 HIGH SPEED BROADBAND SYSTEM	04-MAR-2016 H: 1753.70 L: 622					
25 DOC 1024903 RA Airframe INSPECTION #5027	INSTRUCTIONS FOR CONTINUED AIRWORTHINESS FOR AIRCELL ATG 5000 HIGH SPEED BROADBAND SYSTEM- 24 MONTH INSPECTION	15-JUN-2020 H: 3778.50 L: 1252	M: 24			15-JUN-2022	M: 2 D: 30
25 DOC 1024903 RA Airframe INSPECTION #5028	INSTRUCTIONS FOR CONTINUED AIRWORTHINESS FOR AIRCELL ATG 5000 HIGH SPEED BROADBAND SYSTEM- ANTENNA INSPECTION	24-FEB-2021 H: 3992.00 L: 1324	M: 60			24-FEB-2026	M: 47 D: 8



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 DOC 1024903 RA Airframe INSPECTION #5025	INSTRUCTIONS FOR CONTINUED AIRWORTHINESS FOR AIRCELL ATG 5000 HIGH SPEED BROADBAND SYSTEM- ELECTRICAL WIRING INTERCONNECTION SYSTEM	18-FEB-2021 H: 3992.00 L: 1324	M: 60			18-FEB-2026	M: 47 D: 2
25 DOC 1024903 RA Airframe INSPECTION #5026	INSTRUCTIONS FOR CONTINUED AIRWORTHINESS FOR AIRCELL ATG 5000 HIGH SPEED BROADBAND SYSTEM- GENERAL VISUAL INSPECTION	18-FEB-2021 H: 3992.00 L: 1324	M: 60			18-FEB-2026	M: 47 D: 2
25 DOC 1024905 RA Airframe INSPECTION #5013	INSTRUCTIONS FOR CONTINUED AIRWORTHINESS FOR INTERIOR ALTERATIONS	04-MAR-2016 H: 1753.70 L: 622					
25 DOC 1024905 RB Airframe INSPECTION #5011	INSTRUCTIONS FOR CONTINUED AIRWORTHINESS FOR INTERIOR ALTERATIONS	04-MAR-2016 H: 1753.70 L: 622					
25 DOC 140828002 RA Airframe INSPECTION #5012	INSTRUCTIONS FOR CONTINUED AIRWORTHINESS SATCOM DIRECT ROUTER	05-SEP-2014					
26 10-01-201 Airframe INSPECTION 60M #710	OPERATIONAL TEST OF THE FIRE-DETECTION-AND- EXTINGUISHING (FIDEEX) CONTROL-CIRCUITS, ARM AND DISCHARGE CIRCUITS	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
	Notes NO DEFECT NOTED						
26 1000-701 Airframe PART #1458	SMOKE (FWD LAVATORY) DETECTOR Part Number 473597-1 Serial Number 3706	15-FEB-2011 H: 25.00 L: 11					
26 1000-702 Airframe PART #2454	SMOKE (AFT LAVATORY) DETECTOR Part Number 473597-1 Serial Number 3631	15-FEB-2011 H: 25.00 L: 11					
26 1000-703 Airframe PART #1517	SMOKE (BAGGAGE COMPARTMENT) DETECTOR Part Number 473597-1 Serial Number 3623	15-FEB-2011 H: 25.00 L: 11					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
26 1001-001 Airframe PART #793	LH FS987 ALARM FIDEEX CONTROL UNIT Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
26 1117-001 Engine 1 PART #1699	NO. 1 ENGINE - FIRE CORE WIRE Part Number: 473899 Serial Number: 0776	21-MAR-2010 H: 0.00					
26 1117-001 Engine 2 PART #720	NO. 2 ENGINE - FIRE CORE WIRE Part Number: 473899 Serial Number: 0763	21-MAR-2010 H: 0.00					
26 12-00-201 Airframe INSPECTION 30M #3010	FUNCTIONAL TEST OF THE APU FIRE DETECTION SYSTEM	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
26 1201-001 Airframe PART #2906	EDUCTOR LOOP A SENSING ELEMENT Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
26 1201-002 Airframe PART #1819	EDUCTOR LOOP B SENSING ELEMENT Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
26 1205-001 Airframe PART #1583	RIGHT HATCH LOOP A SENSING ELEMENT Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
26 1205-002 Airframe PART #2143	RIGHT HATCH LOOP B SENSING ELEMENT Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
26 1209-001 Airframe PART #1618	LEFT STRUT LOOP A SENSING ELEMENT Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
26 1209-002 Airframe PART #2397	LEFT STRUT LOOP B SENSING ELEMENT Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
26 13-00-201 Airframe INSPECTION 30M #446	FUNCTIONAL TEST OF THE MAIN LANDING GEAR (MLG) OVERHEAT-DETECTION SYSTEM	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
26 1301-001 Airframe PART #124	LEFT MLG WHEEL WELL SENSING ELEMENT Part Number GK774-0023-3 Serial Number 7	21-MAR-2010 H: 0.00					
26 1301-002 Airframe PART #1353	RIGHT MLG WHEEL WELL SENSING ELEMENT Part Number GK774-0023-3 Serial Number 9	21-MAR-2010 H: 0.00					
26 21-00-201 Airframe INSPECTION 3000H #1864	GENERAL VISUAL INSPECTION OF THE SINGLE-PATH DISCHARGE LINES	04-MAR-2016 H: 1753.70 L: 622	H: 3000.00	H: 50.00		H: 4753.70	H: 297.90
26 21-01-201 Airframe INSPECTION 120M, 1ENG FIRE #1554	FUNCTIONAL TEST (HYDROSTATIC TEST) LH ENGINE FIRE EXTINGUISHER BOTTLE Part Number GK774-0020-3 Serial Number 50152EL	19-APR-2021 H: 3992.00 L: 1324	M: 120			19-APR-2031	M: 109 D: 3
26 21-01-201 Airframe INSPECTION 120M, 2ENG FIRE #328	FUNCTIONAL TEST (HYDROSTATIC TEST) RH ENGINE FIRE EXTINGUISHER BOTTLE Part Number GK774-0020-3 Serial Number 0512BD	19-APR-2021 H: 3992.00 L: 1324	M: 120			19-APR-2031	M: 109 D: 3
26 21-01-202 Airframe INSPECTION 120M, 1ENG FIRE #1841	FUNCTIONAL TEST LH ENGINE FIRE EXTINGUISHER BOTTLE CONTAINER PRESSURE-SWITCH Part Number GK774-0020-3 Serial Number 50152EL	19-APR-2021 H: 3992.00 L: 1324	M: 120			19-APR-2031	M: 109 D: 3
26 21-01-202 Airframe INSPECTION 120M, 2ENG FIRE #643	FUNCTIONAL TEST RH ENGINE FIRE EXTINGUISHER BOTTLE CONTAINER PRESSURE-SWITCH Part Number GK774-0020-3 Serial Number 0512BD	19-APR-2021 H: 3992.00 L: 1324	M: 120			19-APR-2031	M: 109 D: 3





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
26 21-01-203 Airframe INSPECTION 60M, 1ENG FIRE #603	FUNCTIONAL TEST LH ENGINE FIRE EXTINGUISHER BOTTLE CONTENTS WEIGHT Part Number: GK774-0020-3 Serial Number: 50152EL	19-APR-2021 H: 3992.00 L: 1324	M: 60			19-APR-2026	M: 49 D: 3
26 21-01-203 Airframe INSPECTION 60M, 2ENG FIRE #2411	FUNCTIONAL TEST RH ENGINE FIRE EXTINGUISHER BOTTLE CONTENTS WEIGHT (26-20-01-203) Part Number: GK774-0020-3 Serial Number: 0512BD	19-APR-2021 H: 3992.00 L: 1324	M: 60			19-APR-2026	M: 49 D: 3
26 21-13-201 Airframe INSPECTION 3000H #1847	OPERATIONAL TEST OF THE ENGINE FIRE-HANDLE CIRCUIT, RELATED CIRCUITS AND RELAYS	04-MAR-2016 H: 1753.70 L: 622	H: 3000.00	H: 50.00		H: 4753.70	H: 297.90
26 21-13-202 Airframe INSPECTION 3000H #2835	OPERATIONAL TEST OF THE APU FIRE-HANDLE CIRCUIT, RELATED CIRCUITS AND RELAYS	04-MAR-2016 H: 1753.70 L: 622	H: 3000.00	H: 50.00		H: 4753.70	H: 297.90
26 21-45-201 Airframe INSPECTION 60M #423	OPERATIONAL TEST OF THE DISCHARGE CHECK VALVES	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
26 21-50-601 Airframe INSPECTION #4900	DETAILED INSPECTION OF PORTABLE FIRE EXTINGUISHERS Reference Number: 26-21-50-280-801		M: 30			10-OCT-2026	M: 54 D: 24
26 21-50-602 Airframe PART #2821	RESTORE PORTABLE FIRE EXTINGUISHER Reference Number: 26-21-50-610-801; Part Number: 466090 Serial Number: Y-676237 CMM 26-20-29 Rev. 5, 07/2018	10-OCT-2014 H: 1015.50 L: 386	M: 120			10-OCT-2024	M: 30 D: 24
26 2101-001 Airframe PART #1000	LH ENGINE FIRE EXTINGUISHER BOTTLE Part Number: GK774-0020-3 Serial Number: 50152EL	12-SEP-2012 H: 388.37 L: 190					
26 2101-002 Airframe PART #833	RH ENGINE FIRE EXTINGUISHER BOTTLE Part Number: GK774-0020-3 Serial Number: 0512BD	12-SEP-2012 H: 388.37 L: 190					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
26 2105-001 Airframe PART - Life Limited #66	ENGINE NO. 1 (LEFT) EXTINGUISHER SQUIB Part Number 446518-1 Serial Number AFB4291	27-NOV-2019 H: 3575.60 L: 1184	M: 120		M: 0 H: 0.00 L: 0	27-NOV-2029	M: 92 D: 11
26 2105-002 Airframe PART - Life Limited #349	ENGINE NO. 1 (RIGHT) EXTINGUISHER SQUIB Part Number 46518-1 Serial Number AFB4262	27-NOV-2019 H: 3575.60 L: 1184	M: 120		M: 0 H: 0.00 L: 0	27-NOV-2029	M: 92 D: 11
26 2105-003 Airframe PART - Life Limited #698	ENGINE NO. 2 (LEFT) EXTINGUISHER SQUIB Part Number 446518-1 Serial Number AFL5488	27-NOV-2019 H: 3575.60 L: 1184	M: 120		M: 1 H: 0.00 L: 0	27-OCT-2029	M: 91 D: 11
26 2105-004 Airframe PART - Life Limited #1556	ENGINE NO. 2 (RIGHT) EXTINGUISHER SQUIB Part Number 446518-1 Serial Number AFL5485	27-NOV-2019 H: 3575.60 L: 1184	M: 120		M: 1 H: 0.00 L: 0	27-OCT-2029	M: 91 D: 11
26 2105-005 Airframe PART - Life Limited #242	APU (LEFT) EXTINGUISHER SQUIB Part Number 446518-1 Serial Number AFL5548	27-NOV-2019 H: 3575.60 L: 1184	M: 120		M: 1 H: 0.00 L: 0	27-OCT-2029	M: 91 D: 11
26 2105-006 Airframe PART - Life Limited #813	APU (RIGHT) EXTINGUISHER SQUIB Part Number 446518-1 Serial Number AFL5493	27-NOV-2019 H: 3575.60 L: 1184	M: 120		M: 1 H: 0.00 L: 0	27-OCT-2029	M: 91 D: 11
26 2113-001 Airframe PART #2119	FIRE S/O ENGINE LH HANDLE Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
26 2113-002 Airframe PART #910	FIRE S/O ENGINE RH HANDLE Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
26 2113-003 Airframe PART #146	FIRE S/O ENGINE APU HANDLE Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
26 23-00-201 Airframe INSPECTION COMP FIRE, FIRE BOTTLE #2527	FUNCTIONAL TEST FLIGHT COMPARTMENT PORTABLE FIRE EXTINGUISHER BOTTLE (WEIGHT TEST/VISUAL INSPECTION) Part Number: 30H673 Serial Number: f-75062565	01-FEB-2021 H: 3992.00 L: 1324	M: 15			01-MAY-2022	M: 1 D: 15
Notes PN: 30H673 SN: F-75061565. 5LBS, 2oz.							
26 23-00-201A Airframe INSPECTION FIRE BOTTLE #5050	FUNCTIONAL TEST FORWARD CABIN FIRE EXTINGUISHER. WEIGHT CHECK/VISUAL INSPECTION. Part Number: 30H673 Serial Number: F-75062565	07-NOV-2021 H: 4341.90 L: 1453	M: 15			07-FEB-2023	M: 10 D: 22
26 23-00-201B Airframe INSPECTION FIRE BOTTLE #5052	FUNCTIONAL TEST AFT CABIN FIRE EXTINGUISHER. WEIGHT CHECK/VISUAL INSPECTION. Part Number: 30H673 Serial Number: F-75062566	07-NOV-2021 H: 4341.90 L: 1453	M: 15			07-FEB-2023	M: 10 D: 22
26 23-00-201C Airframe INSPECTION FIRE BOTTLE #5054	FUNCTIONAL TEST AFT WAREDOBE FIRE EXTINGUISHER. WEIGHT CHECK. VISUAL INSPECTION. Part Number: 466090 Serial Number: F67894298	20-DEC-2021 H: 4399.80 L: 1478	M: 15			20-MAR-2023	M: 12 D: 4
26 23-00-202 Airframe PART FIRE BOTTLE #120	RESTORE/REPLACE FLIGHT COMPARTMENT PORTABLE FIRE EXTINGUISHER BOTTLE Part Number: 30H673 Serial Number: f-75062565	21-SEP-2020 H: 3875.30 L: 1284	M: 72			31-JAN-2025	M: 34 D: 15
Notes MANUFACTURER DATE 2019. REPLACE JAN 2025							
26 23-00-202A Airframe PART FIRE BOTTLE #5051	RESTORE/REPLACE FORWARD CABIN FIRE EXTINGUISHER. Part Number: 30H673 Serial Number: F-75062565	10-AUG-2020 H: 3823.90 L: 1264	M: 72			10-AUG-2025	M: 40 D: 25
Notes MANUFACTURE DATE 2019. REPLACE 2025.							
26 23-00-202B Airframe PART FIRE BOTTLE #5053	RESTORE/REPLACE AFT CABIN FIRE EXTINGUISHER. Part Number: 30H673 Serial Number: F-75062566	10-AUG-2020 H: 3823.90 L: 1264	M: 72			10-AUG-2025	M: 40 D: 25
Notes MANUFACTURE DATE 2019. RESTORE/REPLACE 2025.							





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
26 23-00-202C Airframe INSPECTION PORT FIRE, FIRE BOTTLE #2959	RESTORE/REPLACE AFT WARDROBE PORTABLE FIRE EXTINGUISHER. Reference Number Part Number Serial Number 26-21-50-610-801; 466090 Y-676237 CMM 26-20-29 Rev. 5, 07/2018 Notes AFT CLOSET SN: Y676237 MODEL PRO 9 HM-2. MANUFACTURE DATE 2014. REPLACE 2020.	22-SEP-2020 H: 3875.30 L: 1284	M: 72			22-SEP-2026	M: 54 D: 6
26 23-01-701 Airframe PART #5046	FIRE EXTINGUISHER, FLIGHT COMPARTMENT. Part Number Serial Number 30H673 F-75062553	21-SEP-2020 H: 3875.30 L: 1284					
26 23-01-702 Airframe PART #5047	FIRE EXTINGUISHER. FORWARD CABIN. Part Number Serial Number 30H673 F-75062565 Notes MANUFACTURE DATE 2019. RESTORE/REPLACE 2025.	10-AUG-2020 H: 3823.90 L: 1264					
26 23-01-703 Airframe PART #5048	FIRE EXTINGUISHER. AFT CABIN. Part Number Serial Number 30H673 F-75062566	10-AUG-2020 H: 3823.90 L: 1264					
26 23-01-704 Airframe PART #5049	FIRE EXTINGUISHER. AFT WARDROBE CLOSET. Part Number Serial Number 466090 F67894298	22-SEP-2020 H: 3875.30 L: 1284				31-DEC-2025	M: 45 D: 15
27 00-00-201 Airframe INSPECTION 60M #2422	DETAILED INSPECTION OF THE AILERON, ELEVATOR AND RUDDER CONTROL CABLES IN THE FORWARD AVIONICS COMPARTMENT, FS202.75 TO FS280.00	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
27 00-00-202 Airframe INSPECTION 60M #2996	DETAILED INSPECTION OF THE AILERON, ELEVATOR AND RUDDER CONTROL CABLES IN THE MAIN AVIONICS COMPARTMENT, FS280.00 TO FS557.00 Notes NO DEFECTS NOTED	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 00-00-203 Airframe INSPECTION 120M #503	DETAILED INSPECTION OF THE AILERON, ELEVATOR AND RUDDER CONTROL CABLES IN THE MID- LOWER FUSELAGE COMPARTMENT, FS557.00 TO FS781.00	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
Notes NO DEFECTS NOTED AT THIS TIME							
27 00-00-204 Airframe INSPECTION 60M #2097	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE MAIN LANDING GEAR (MLG) WHEEL WELL AND MID WING-TO-FUSELAGE FAIRING	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
27 00-00-205 Airframe INSPECTION 60M #1994	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE FLIGHT COMPARTMENT, FS202.75 TO FS280.00	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
Notes NO DEFECTS NOTED							
27 00-00-206 Airframe INSPECTION 60M #191	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE MID AND OUTBOARD WING BOX, WS178.00 TO WS536.50	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
27 00-00-207 Airframe INSPECTION 30M #904	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE INBOARD WING TRAILING EDGE, WS47.62 TO WS178.00	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
27 00-00-208 Airframe INSPECTION 60M #1727	DETAILED INSPECTION OF THE ELEVATOR AND RUDDER CONTROL CABLES IN THE AFT POWER DISTRIBUTION/ECS COMPARTMENT, FS781.00 TO FS861.00	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
27 00-00-209 Airframe INSPECTION 60M #554	DETAILED INSPECTION OF THE ELEVATOR AND RUDDER CONTROL CABLES IN THE AFT EQUIPMENT COMPARTMENT, FS861.00 TO FS987.55	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
27 00-00-210 Airframe INSPECTION 60M #700	DETAILED INSPECTION OF THE ELEVATOR AND RUDDER CONTROL CABLES IN THE FUSELAGE/STABILIZER SECTION, FS987.55 TO REAR SPAR	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 00-00-211 Airframe INSPECTION 60M #1229	DETAILED INSPECTION OF THE ELEVATOR CONTROL CABLES IN THE VERTICAL STABILIZER, FRONT SPAR TO REAR SPAR	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
27 00-00-212 Airframe INSPECTION 1000 H #2820	OPERATIONAL TEST OF THE AILERON, ELEVATOR AND RUDDER CONTROL POWER-CONTROL UNITS (PCU)	10-MAR-2022 H: 4455.80 L: 1495	H: 1000.00	H: 50.00		H: 5455.80	H: 1000.00
27 10-00-201 Airframe INSPECTION 60M #634	LUBRICATION OF THE AILERON POWER-CONTROL UNIT (PCU) TOGGLE-LINK SLOTTED BEARINGS	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
27 11-05-201 Airframe INSPECTION 3000H #987	FUNCTIONAL TEST OF THE ROLL DISCONNECT MECHANISM	04-MAR-2016 H: 1753.70 L: 622	H: 3000.00	H: 50.00		H: 4753.70	H: 297.90
27 11-05-202 Airframe INSPECTION 1000 H #2836	OPERATIONAL TEST OF THE ROLL DISCONNECT MECHANISM	10-MAR-2022 H: 4455.80 L: 1495	H: 1000.00	H: 50.00		H: 5455.80	H: 1000.00
27 11-25-101 Airframe INSPECTION 1500H #2991	FUNCTIONAL TEST OF THE AILERON POWER-CONTROL UNIT (PCU)	08-FEB-2022 H: 4399.80 L: 1478	H: 1500.00			H: 5899.80	H: 1444.00
27 11-25-102 Airframe INSPECTION 3000H #1310	FUNCTIONAL TEST OF THE AILERON PCU BUNGEE	01-DEC-2018 H: 3011.20 L: 1025	H: 3000.00			H: 6011.20	H: 1555.40
27 11-35-101 Airframe INSPECTION 30M #4652	FUNCTIONAL TEST OF THE AILERON CABLE TENSION- FLIGHT COMPARTMENT CABLES	19-APR-2021 H: 3992.00 L: 1324	M: 30			19-OCT-2023	M: 19 D: 3
	Notes TRANSMITOR: T4553523 JUL 31- AUG 21 FT GOOD, TENSIONS ARE WITHIN LIMITS						





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 11-35-102 Airframe INSPECTION 30M #4653	FUNCTIONAL TEST OF THE AILERON CABLE TENSION- FUSELAGE CABLES	19-APR-2021 H: 3992.00 L: 1324	M: 30			19-OCT-2023	M: 19 D: 3
27 11-35-103 Airframe INSPECTION #5088	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE MAIN LANDING GEAR (MLG) WHEEL WELL	19-APR-2021 H: 3992.00 L: 1324		M: 3			
	Notes (POST SB 700-27-086 PART I OR PART J OR PART K OR PART L OR PART M OR PART N OR PART O OR PART P)						
27 11-35-104 Airframe INSPECTION 15M #5094	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE WING TRAILING EDGE, AT THE INNER, MID AND OUTER FLAP AREAS	19-APR-2021 H: 3992.00 L: 1324					
	Notes (POST SB 700-27-086 PART M OR PART N OR PART O OR PART P)						
27 11-35-201 Airframe INSPECTION 60M #4740	FUNCTIONAL TEST OF THE AILERON CABLE TENSION - WING Reference Number AMM 27-11-35-720 -803	19-APR-2021 H: 3992.00 L: 1324	M: 60			19-APR-2026	M: 49 D: 3
27 1100-001 Airframe PART #2806	ROLL DISCONNECT ASSEMBLY Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
27 1100-003 Airframe PART #2891	LH MLG WHEEL WELL ROD Part Number GC415-0030-3 Serial Number TY13076	21-MAR-2010 H: 0.00					
27 1100-004 Airframe PART #2743	RH MLG WHEEL WELL ROD Part Number GC415-0030-3 Serial Number TY13078	21-MAR-2010 H: 0.00					
27 1101-001 Airframe PART #1220	LH ROLL SPOILER TRANSDUCER Part Number GT415-6006-5 Serial Number N8890	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 1101-002 Airframe PART #529	RH ROLL SPOILER TRANSDUCER Part Number GT415-6006-5 Serial Number N8888	21-MAR-2010 H: 0.00					
27 1109-001 Airframe PART #492	AILERON TORQUE TUBE Part Number GC413-1200-9 Serial Number E228252	21-MAR-2010 H: 0.00					
27 1117-007 Airframe PART #1802	LH TENSION AILERON REGULATOR Part Number GC415-1600-9 Serial Number FR296	21-MAR-2010 H: 0.00					
27 1117-008 Airframe PART #2652	RH TENSION AILERON REGULATOR Part Number GC415-1600-11 Serial Number FR296	21-MAR-2010 H: 0.00					
27 1121-001 Airframe PART #2690	LEFT AILERON POSITION TRANSDUCER Part Number GT415-0200-5 Serial Number P6260	21-MAR-2010 H: 0.00					
27 1121-002 Airframe PART #29	RIGHT AILERON POSITION TRANSDUCER Part Number GT415-0200-5 Serial Number P1899	21-MAR-2010 H: 0.00					
27 1125-001 Airframe PART #2431	NO. 1 AILERON PCU Part Number GT411-1700-9 Serial Number 1603	21-MAR-2010 H: 0.00					
27 1125-002 Airframe PART #172	NO. 2 AILERON PCU Part Number GT411-1700-9 Serial Number 1602	21-MAR-2010 H: 0.00					
27 1125-003 Airframe PART #2323	NO. 3 AILERON PCU Part Number GT411-1700-9 Serial Number 1583	21-MAR-2010 H: 0.00					
27 1125-004 Airframe PART #2373	NO. 4 AILERON PCU Part Number GT411-1700-9 Serial Number 1586	21-MAR-2010 H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 1125-005 Airframe PART #2677	LH OUTBD WING ROD CONTROL Part Number GC415-0030-45 Serial Number TY14102	21-MAR-2010 H: 0.00					
27 1125-006 Airframe PART #2246	RH OUTBD WING ROD CONTROL Part Number GC415-0030-45 Serial Number TY14084	21-MAR-2010 H: 0.00					
27 12-01-20 Airframe PART #5141	RUDDER/AILERON TRIM PANEL Part Number GC542-0017-5 Serial Number U132882	14-JUN-2021 H: 4081.50 L: 1358					
	Notes LOCATION CENTER PEDISTAL						
27 1205-001 Airframe PART #1945	AILERON-MLG WHEEL WELL TRIM ACTUATOR Part Number GT412-1500-5 Serial Number 3102	21-MAR-2010 H: 0.00					
27 20-00-201 Airframe INSPECTION 60M #429	LUBRICATION OF THE RUDDER POWER-CONTROL UNIT (PCU) SLOTTED BEARINGS	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
27 21-00-201 Airframe INSPECTION 4500H #348	GENERAL VISUAL INSPECTION OF THE SINGLE-RUDDER CONTROL-PATH AND PCU LINKAGE CENTERING-SPRINGS Work Order Number FLL BAS 9385 Scheduled 19-Mar-2022 Man Hours 0.00	21-MAR-2010 H: 0.00	H: 4500.00	H: 50.00		H: 4500.00	H: 44.20
27 21-05-201 Airframe INSPECTION 4500H #772	OPERATIONAL TEST OF THE RUDDER LOAD LIMITER Work Order Number FLL BAS 9385 Scheduled 19-Mar-2022 Man Hours 0.00	21-MAR-2010 H: 0.00	H: 4500.00	H: 50.00		H: 4500.00	H: 44.20
27 21-09-101 Airframe INSPECTION 3000H #692	OPERATIONAL TEST OF THE RUDDER POWER-CONTROL UNIT (PCU) INPUT LIMITERS	01-DEC-2018 H: 3011.20 L: 1025	H: 3000.00			H: 6011.20	H: 1555.40





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 21-13-101 Airframe INSPECTION 3000H #1235	FUNCTIONAL TEST OF THE RUDDER POWER-CONTROL UNITS (PCU)	01-DEC-2018 H: 3011.20 L: 1025	H: 3000.00			H: 6011.20	H: 1555.40
27 21-27-101 Airframe INSPECTION 30M #4654	FUNCTIONAL TEST OF THE RUDDER CABLE TENSION	19-APR-2021 H: 3992.00 L: 1324	M: 30			19-OCT-2023	M: 19 D: 3
27 2100-001 Airframe PART #998	LOB PEDAL PILOT CONTROL ROD ASSY - (RUDDER PEDAL) Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
27 2100-002 Airframe PART #1204	LIB PEDAL PILOT CONTROL ROD ASSY - (RUDDER PEDAL) Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
27 2100-003 Airframe PART #1184	RIB PEDAL COPILOT CONTROL ROD ASSY - (RUDDER PEDAL) Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
27 2100-004 Airframe PART #1075	ROB PEDAL COPILOT CONTROL ROD ASSY - (RUDDER PEDAL) Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
27 2100-005 Airframe PART #2418	LOB PEDAL PILOT ROD CONTROL Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
27 2100-006 Airframe PART #2752	LIB PEDAL PILOT ROD CONTROL Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
27 2100-007 Airframe PART #721	RIB PEDAL COPILOT ROD CONTROL Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 2100-008 Airframe PART #3026	ROB PEDAL COPILOT ROD CONTROL Part Number PN	21-MAR-2010 H: 0.00					
27 2100-009 Airframe PART #1995	LH FWD AVIONICS BAY ROD CONTROL Part Number PN	21-MAR-2010 H: 0.00					
27 2100-010 Airframe PART #2811	RH FWD AVIONICS BAY ROD CONTROL Part Number PN	21-MAR-2010 H: 0.00					
27 2100-011 Airframe PART #734	FWD AVIONICS BAY INTERCONNECT CONTROL ROD ASSEMBLY Part Number PN	21-MAR-2010 H: 0.00					
27 2101-001 Airframe PART #318	RUDDER (STABILIXER QUARDANT) ROD CONTROL Part Number PN	21-MAR-2010 H: 0.00					
27 2101-005 Airframe PART #2847	RUDDER LINEAR FEEL UNIT Part Number GC415-2360-5	21-MAR-2010 H: 0.00					
27 2105-001 Airframe PART #3041	AFT FUSELAGE RUDDER TRIM ACTUATOR Part Number PN	21-MAR-2010 H: 0.00	H: 5000.00			H: 5000.00	H: 544.20
27 2105-002 Airframe PART #1412	RUDDER LIMITER Part Number GC415-2400-5	21-MAR-2010 H: 0.00					
27 2105-003 Airframe PART #630	LH LINEAR YAW DAMPER ACTUATOR ASSEMBLY Part Number GC415-2565-3	21-MAR-2010 H: 0.00					



Maintenance Items

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Page 78 of 653



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 2105-004 Airframe PART #1092	RH LINEAR YAW DAMPER ACTUATOR ASSEMBLY Part Number GC415-2565-3 Serial Number 0902H473	21-MAR-2010 H: 0.00					
27 2109-011 Airframe PART #771	NO. 1 LOAD LIMITER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
27 2109-012 Airframe PART #1958	NO. 2 LOAD LIMITER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
27 2109-013 Airframe PART #2145	NO. 3 LOAD LIMITER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
27 2117-001 Airframe PART #1548	RUDDER POSITION TRANSDUCER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
27 2121-001 Airframe PART #2035	NO. 1 RUDDER PCU Part Number GT411-2800-7 Serial Number 1175	21-MAR-2010 H: 0.00					
27 2121-002 Airframe PART #2788	NO. 2 RUDDER PCU Part Number GT411-2800-7 Serial Number 1170	21-MAR-2010 H: 0.00					
27 2121-003 Airframe PART #1180	NO. 3 RUDDER PCU Part Number GT411-2800-7 Serial Number 1174	21-MAR-2010 H: 0.00					
27 2121-004 Airframe PART #2210	RUDDER Part Number GS268-0001-3 Serial Number B371	21-MAR-2010 H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 2205-001 Airframe PART #949	RUDDER FS1047, WL54 TRIM ACTUATOR Part Number: GT412-2550-3 Serial Number: 2215	21-MAR-2010 H: 0.00					
27 23-00-201 Airframe INSPECTION 4500H #521	VISUAL CHECK OF THE RUDDER TRAVEL-LIMITING SYSTEM Work Order Number: FLL BAS 9385 Scheduled: 19-Mar-2022 Man Hours: 0.00	21-MAR-2010 H: 0.00	H: 4500.00	H: 50.00		H: 4500.00	H: 44.20
27 2301-001 Airframe PART #2045	LEFT TRAVEL LIMIT (RUDDER) TRIM ACTUATOR Part Number: GT412-1500-5 Serial Number: 2974	21-MAR-2010 H: 0.00					
27 2301-002 Airframe PART #2912	RIGHT TRAVEL LIMIT (RUDDER) TRIM ACTUATOR Part Number: GT412-1500-5 Serial Number: 2993	21-MAR-2010 H: 0.00					
27 2305-002 Airframe PART #920	RUDDER LIMITER UNIT Part Number: GC413-2600-7/03 Serial Number: D984132	21-MAR-2010 H: 0.00					
27 2305-003 Airframe PART #2114	MLG WHEEL WELL ROD Part Number: GC415-0030-1 Serial Number: TY12812	21-MAR-2010 H: 0.00					
27 2305-004 Airframe PART #718	MID VERTICAL. STAB - RIB NO. 4 - NO. 5 ROD CONTROL Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
27 2305-005 Airframe PART #2599	LIMITER OUTPUT ROD CONTROL Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
27 2309-001 Airframe PART #488	LH RUDDER POSITION TRANSDUCER Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 2309-002 Airframe PART #2130	RH RUDDER POSITION TRANSDUCER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
27 30-00-201 Airframe INSPECTION 60M #2929	LUBRICATION OF THE ELEVATOR POWER-CONTROL UNIT (PCU) SLOTTED BEARINGS	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
27 31-05-201 Airframe INSPECTION 3000H #2261	FUNCTIONAL TEST OF THE PITCH DISCONNECT MECHANISM	04-MAR-2016 H: 1753.70 L: 622	H: 3000.00	H: 50.00		H: 4753.70	H: 297.90
27 31-05-202 Airframe INSPECTION 1000 H #1013	OPERATIONAL TEST OF THE PITCH DISCONNECT MECHANISM	10-MAR-2022 H: 4455.80 L: 1495	H: 1000.00	H: 50.00		H: 5455.80	H: 1000.00
27 31-17-201 Airframe INSPECTION 3000H #2404	OPERATIONAL TEST OF THE ELEVATOR POWER-CONTROL UNIT (PCU) LOAD LIMITERS	04-MAR-2016 H: 1753.70 L: 622	H: 3000.00	H: 50.00		H: 4753.70	H: 297.90
27 31-21-101 Airframe INSPECTION 1500H #470	FUNCTIONAL TEST OF THE ELEVATOR POWER-CONTROL UNITS (PCU)	08-FEB-2022 H: 4399.80 L: 1478	H: 1500.00			H: 5899.80	H: 1444.00
27 31-35-201 Airframe INSPECTION 60M #4741	FUNCTIONAL TEST OF THE ELEVATOR CABLE TENSION CABLES Reference Number AMM 27-31-35-720 -801	19-APR-2021 H: 3992.00 L: 1324	M: 60			19-APR-2026	M: 49 D: 3
27 3100-001 Airframe PART #2595	LH FORWARD QUADRANT Part Number GC413-3300-7 Serial Number E373030	21-MAR-2010 H: 0.00					
27 3100-002 Airframe PART #946	RH FORWARD QUADRANT Part Number GC413-3350-5 Serial Number E724253	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 3100-003 Airframe PART #1640	LH ELEVATOR MID VERTICAL STAB ROD CONTROL Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
27 3100-004 Airframe PART #990	RH ELEVATOR MID VERTICAL STAB ROD CONTROL Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
27 3100-005 Airframe PART #123	LH MID VERTICAL STABILIZER ROD CONTROL Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
27 3100-006 Airframe PART #2947	RH MID VERTICAL STABILIZER ROD CONTROL Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
27 3101-001 Airframe PART #2758	LH ASSEMBLY COLUMN Part Number Serial Number GC415-3149-5 9385	21-MAR-2010 H: 0.00					
27 3101-002 Airframe PART #1173	RH ASSEMBLY COLUMN Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
27 3105-001 Airframe PART #2167	PITCH DISCONNECT Part Number Serial Number GC415-3250-11 SN- UNKNOWN	21-MAR-2010 H: 0.00					
27 3109-001 Airframe PART #2156	PITCH LOCK SOLENOID Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
27 3113-001 Airframe PART #607	LEFT ELEVATOR LOAD LIMITER Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 3113-002 Airframe PART #23	RIGHT ELEVATOR LOAD LIMITER Part Number PN	21-MAR-2010 H: 0.00	Serial Number SN- UNKNOWN				
27 3113-003 Airframe PART #712	LH ELEVATOR CONTROL ROD Part Number PN	21-MAR-2010 H: 0.00	Serial Number SN- UNKNOWN				
27 3113-004 Airframe PART #1736	LH HORIZONTAL STAB ROD CONTROL Part Number GC415-0030-31	21-MAR-2010 H: 0.00	Serial Number TY14138				
27 3113-005 Airframe PART #2531	RH ELEVATOR CONTROL ROD Part Number PN	21-MAR-2010 H: 0.00	Serial Number SN- UNKNOWN				
27 3113-006 Airframe PART #2428	RH HORIZONTAL STAB ROD CONTROL Part Number GC415-0030-31	21-MAR-2010 H: 0.00	Serial Number TY14129				
27 3113-007 Airframe PART #1794	LH HORIZONTAL STAB ROD CONTROL Part Number GC415-0030-25	21-MAR-2010 H: 0.00	Serial Number TY13781				
27 3113-008 Airframe PART #22	RH HORIZONTAL STAB ROD CONTROL Part Number GC415-0030-39	21-MAR-2010 H: 0.00	Serial Number TY13561				
27 3117-001 Airframe PART #2532	NO. 1 LOAD LIMITER Part Number GC415-3790-3	21-MAR-2010 H: 0.00	Serial Number FR1442				
27 3117-002 Airframe PART #1425	NO. 2 LOAD LIMITER Part Number GC415-3790-3	21-MAR-2010 H: 0.00	Serial Number FR1444				





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 3117-003 Airframe PART #1691	NO. 3 LOAD LIMITER Part Number GC415-3790-3 Serial Number FR7186	21-MAR-2010 H: 0.00					
27 3117-004 Airframe PART #1288	NO. 4 LOAD LIMITER Part Number GC415-3790-3 Serial Number FR7193	21-MAR-2010 H: 0.00					
27 3121-001 Airframe PART #447	NO. 1 ELEVATOR PCU Part Number GT411-3800-9 Serial Number 1645	21-MAR-2010 H: 0.00					
27 3121-002 Airframe PART #2726	NO. 2 ELEVATOR PCU Part Number GT411-3800-9 Serial Number 1646	21-MAR-2010 H: 0.00					
27 3121-003 Airframe PART #237	NO. 3 ELEVATOR PCU Part Number GT411-3800-9 Serial Number 1611	21-MAR-2010 H: 0.00					
27 3121-004 Airframe PART #2938	NO. 4 ELEVATOR PCU Part Number GT411-3800-9 Serial Number 1648	21-MAR-2010 H: 0.00					
27 3125-001 Airframe PART #654	LEFT ELEVATOR POSITION TRANSDUCER Part Number GT415-0200-5 Serial Number P6912	21-MAR-2010 H: 0.00					
27 3125-002 Airframe PART #1490	RIGHT ELEVATOR POSITION TRANSDUCER Part Number GT415-0200-5 Serial Number P7902	21-MAR-2010 H: 0.00					
27 3129-001 Airframe PART #496	LH ELEVATOR Part Number GS278-0001-7 Serial Number B331	21-MAR-2010 H: 0.00					
27 3129-002 Airframe PART #306	RH ELEVATOR Part Number GS278-0001-8 Serial Number B388	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 3133-001 Airframe PART #1631	LH FWD AVIONINCS BAY ROD CONTROL Part Number PN	21-MAR-2010 H: 0.00					
	Serial Number SN- UNKNOWN						
27 3133-002 Airframe PART #2741	RH FWD AVIONINCS BAY ROD CONTROL Part Number PN	21-MAR-2010 H: 0.00					
	Serial Number SN- UNKNOWN						
27 3133-003 Airframe PART #2542	LH ELEVATOR TENSION REGULATOR Part Number GC415-3305-5	21-MAR-2010 H: 0.00					
	Serial Number FR436						
27 3133-004 Airframe PART #1874	RH ELEVATOR TENSION REGULATOR Part Number GC415-3305-13	21-MAR-2010 H: 0.00					
	Serial Number FR434						
27 3201-001 Airframe PART #1355	RIGHT FORWARD STALL PROTECTION COMPUTER Part Number GH582-3001-17	23-JAN-2011 H: 11.80 L: 6					
	Serial Number 571						
27 3205-001 Airframe PART #2266	PILOT STICK SHAKER Part Number GH582-3003-1	21-MAR-2010 H: 0.00					
	Serial Number 1409						
27 3205-002 Airframe PART #932	COPILOT STICK SHAKER Part Number GH582-3003-1	21-MAR-2010 H: 0.00					
	Serial Number 1431						
27 3209-001 Airframe PART #474	LH AOA SENSOR Part Number PN	21-MAR-2010 H: 0.00					
	Serial Number SN- UNKNOWN						
27 3209-002 Airframe PART #2565	RH AOA SENSOR Part Number PN	21-MAR-2010 H: 0.00					
	Serial Number SN- UNKNOWN						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 3213-001 Airframe PART #2380	MACH TRANSDUCER Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
27 3217-001 Airframe PART #2003	LH STICK PUSHER ACTUATOR Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
27 3217-002 Airframe PART #885	RH STICK PUSHER ACTUATOR Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
27 3221-001 Airframe PART #2281	ASSY CAPSTAN Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
27 3301-001 Airframe PART #1908	LH ELEVATOR ROD CONTROL Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
27 3301-002 Airframe PART #2416	RH ELEVATOR ROD CONTROL Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
27 3301-003 Airframe PART #886	LH PITCH WHEEL SIMULATOR Part Number GC415-3490-1	Serial Number 767	21-MAR-2010 H: 0.00				
27 3301-004 Airframe PART #604	RH PITCH WHEEL SIMULATOR Part Number GC415-3490-1	Serial Number 774	21-MAR-2010 H: 0.00				
27 3305-001 Airframe PART #2606	LEFT PITCH FEEL TRIM ACTUATOR Part Number GT412-1500-5	Serial Number 3150	11-FEB-2011 H: 19.80 L: 9				





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 3305-002 Airframe PART #1053	RIGHT PITCH FEEL TRIM ACTUATOR Part Number: GT412-1500-5 Serial Number: 3064	21-MAR-2010 H: 0.00					
27 41-00-201 Airframe INSPECTION 500H #1418	LUBRICATION OF THE HORIZONTAL STABILIZER TRIM ACTUATOR Notes NOTE: CONSIDERATION SHOULD BE GIVEN TO ACCOMPLISHMENT OF TASK 27-41-09-103* BEFORE THIS TASK IS DONE.	10-MAR-2022 H: 4455.80 L: 1495	M: 15 H: 500.00	H: 50.00		10-JUN-2023 H: 4955.80	M: 14 D: 25 H: 500.00
27 41-00-202 Airframe INSPECTION 60M #1021	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER TRIM ACTUATOR	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
27 41-09-101 Airframe INSPECTION #207	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL STABILIZER TRIM ACTUATOR (EXCLUDING AIRCRAFT ATTACHMENT PINS) Reference Number AMM: 27-41-09-280-801	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
27 41-09-103 Airframe INSPECTION 500H #1291	DETAILED INSPECTION PITCH TRIM ACTUATOR	10-MAR-2022 H: 4455.80 L: 1495	H: 500.00			H: 4955.80	H: 500.00
27 41-09-105 Airframe PART #1090	DISCARD THE PITCH TRIM ACTUATOR Part Number: GT412-4001-7 Serial Number: 417	21-MAR-2010 H: 0.00	H: 17000.00			H: 17000.00	H: 12544.20
27 41-09-106 Airframe PART #631	RESTORATION PITCH TRIM ACTUATOR OF THE (GEAR HOUSING REPLACEMENT) PART NO. GT412-4001-3 OR GT412-4001-5 Notes N/A BY PART NUMBER INSTALLED	01-OCT-2009 H: 0.00					
27 4101-001 Airframe PART #1461	PILOT CONTROL WHEEL Part Number: GC415-1100-11 Serial Number: 252	21-MAR-2010 H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 4101-002 Airframe PART #2807	COPILOT CONTROL WHEEL Part Number GC415-1100-8 Serial Number 250	21-MAR-2010 H: 0.00					
27 4117-001 Airframe PART #310	DRIVE UNIT - HORIZONTAL STAB MOTOR Part Number GT415-4002-11 Serial Number 3196	21-MAR-2010 H: 0.00					
27 50-00-201 Airframe INSPECTION 60M #1005	LUBRICATION OF THE FLAP DRIVE TORQUE-TUBE SPLINES	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
27 50-00-202 Airframe INSPECTION 60M #2842	LUBRICATION OF THE SLAT DRIVE TORQUE-TUBE SPLINES	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
27 50-00-203 Airframe INSPECTION 15M #2060	LUBRICATION OF THE FLAP ACTUATOR BALLSCREWS AND BALLNUTS	19-APR-2021 H: 3992.00 L: 1324	M: 15	M: 3		19-JUL-2022	M: 4 D: 3
27 50-00-204 Airframe INSPECTION 15M #204	LUBRICATION OF THE SLAT ACTUATOR BALLSCREWS	19-APR-2021 H: 3992.00 L: 1324	M: 15	M: 3		19-JUL-2022	M: 4 D: 3
27 50-00-205 Airframe INSPECTION 1500H #1159	LUBRICATION OF THE FLAP ROLLERS	08-FEB-2022 H: 4399.80 L: 1478	H: 1500.00	H: 50.00		H: 5899.80	H: 1444.00
27 50-00-206 Airframe INSPECTION 60M #495	LUBRICATION OF THE SLAT ROLLERS	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
27 50-00-207 Airframe INSPECTION 450L #2084	LUBRICATION OF THE FLAP SKEW SENSOR NO.1 (A/C 9001 AND SUBS), AND FLAP SKEW SENSORS NO. 2, 3 AND 4, (A/C 9002 TO 9126 AND 9128 TO 9178, PRE SB 700-27-049)	10-MAR-2022 H: 4455.80 L: 1495	L: 450	L: 50		L: 1945	L: 450





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 5101-001 Airframe PART #1276	FLAP/SLAT LEVER Part Number GT415-5600-5 Serial Number E0446	21-MAR-2010 H: 0.00					
27 5105-001 Airframe PART #1048	LH SFCU FAN Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
27 5105-002 Airframe PART #2094	RH SFCU FAN Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
27 5105-003 Airframe PART #1226	LH FLAP/SLAT CONTROL UNIT Part Number GT415-5900-17 Serial Number 1436	21-MAR-2010 H: 0.00					
27 5105-004 Airframe PART #1019	RH FLAP/SLAT CONTROL UNIT Part Number GT415-5900-17 Serial Number 1448	21-MAR-2010 H: 0.00					
27 52-57-101 Airframe INSPECTION 3000H #1375	DETAILED INSPECTION OF THE FLAP ROLLERS	01-DEC-2018 H: 3011.20 L: 1025	H: 3000.00			H: 6011.20	H: 1555.40
27 5201-001 Airframe PART #2664	LEFT MLG WHEEL WELL FLAP TORQUE TUBE Part Number GT415-5201-3 Serial Number 2740	21-MAR-2010 H: 0.00					
27 5201-002 Airframe PART #1024	LIB FLAP TORQUE TUBE Part Number GT415-5201-7 Serial Number 3018	21-MAR-2010 H: 0.00					
27 5201-003 Airframe PART #560	RIB FLAP TORQUE TUBE Part Number GT415-5201-7 Serial Number 3021	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 5205-001 Airframe PART #1784	LEFT NO.1 FLAP ACTUATOR GEARBOX Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
27 5205-002 Airframe PART #2930	LEFT NO.2 FLAP ACTUATOR GEARBOX Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
27 5205-003 Airframe PART #198	LEFT NO.3 FLAP ACTUATOR GEARBOX Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
27 5205-004 Airframe PART #577	LEFT NO.4 FLAP ACTUATOR GEARBOX Part Number GT412-5011-1	Serial Number 4303	21-MAR-2010 H: 0.00				
27 5205-005 Airframe PART #2738	RIGHT NO.1 FLAP ACTUATOR GEARBOX Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
27 5205-006 Airframe PART #2036	RIGHT NO.2 FLAP ACTUATOR GEARBOX Part Number GT412-5008-3	Serial Number 2867	21-MAR-2010 H: 0.00				
27 5205-007 Airframe PART #100	RIGHT NO.3 FLAP ACTUATOR GEARBOX Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
27 5205-008 Airframe PART #2662	RIGHT NO.4 FLAP ACTUATOR GEARBOX Part Number GT412-5011-1	Serial Number 4261	21-MAR-2010 H: 0.00				
27 5209-001 Airframe PART #1754	LH NO.1 FLAP ACTUATOR ASSEMBLY Part Number GT412-5002-1	Serial Number 2863	21-MAR-2010 H: 0.00				



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 5209-002 Airframe PART #976	RH NO.1 FLAP ACTUATOR ASSEMBLY Part Number GT412-5002-1 Serial Number 2841	21-MAR-2010 H: 0.00					
27 5209-003 Airframe PART #449	LH NO.2 FLAP ACTUATOR ASSEMBLY Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
27 5209-004 Airframe PART #2229	RH NO.2 FLAP ACTUATOR ASSEMBLY Part Number GT412-5004-1 Serial Number 2844	21-MAR-2010 H: 0.00					
27 5209-005 Airframe PART #2584	LH NO.3 FLAP ACTUATOR ASSEMBLY Part Number GT412-5006-1 Serial Number 2892	21-MAR-2010 H: 0.00					
27 5209-006 Airframe PART #1714	RH NO.3 FLAP ACTUATOR ASSEMBLY Part Number GT412-5006-1 Serial Number 2896	21-MAR-2010 H: 0.00					
27 5209-007 Airframe PART #1982	LH NO.4 FLAP ACTUATOR ASSEMBLY Part Number GT412-5005-1 Serial Number 2851	21-MAR-2010 H: 0.00					
27 5209-008 Airframe PART #2459	RH NO.4 FLAP ACTUATOR ASSEMBLY Part Number GT412-5008-3 Serial Number 2917	21-MAR-2010 H: 0.00					
27 5213-001 Airframe PART #1325	FLAP LH WS131.500 T/E DRIVE SHAFT RETAIN BEARING Part Number GT415-5101-1 Serial Number 3644	21-MAR-2010 H: 0.00					
27 5213-002 Airframe PART #656	FLAP LH WS199.000 T/E DRIVE SHAFT RETAIN BEARING Part Number GT415-5101-1 Serial Number 3783	21-MAR-2010 H: 0.00					
27 5213-003 Airframe PART #2845	FLAP RH WS131.500 T/E DRIVE SHAFT RETAIN BEARING Part Number GT415-5101-1 Serial Number 3760	21-MAR-2010 H: 0.00					



Maintenance Items

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Page 91 of 653



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 5213-004 Airframe PART #1397	FLAP RH WS199.000 T/E DRIVE SHAFT RETAIN BEARING Part Number GT415-5101-1 Serial Number 3771	21-MAR-2010 H: 0.00					
27 5249-001 Airframe PART #1679	LEFT FLAP (FLAP/SLAT) RESOLVER Part Number GT415-5300-3 Serial Number B1784	21-MAR-2010 H: 0.00					
27 5249-002 Airframe PART #612	RIGHT FLAP (FLAP/SLAT) RESOLVER Part Number GT415-5300-3 Serial Number B1758	21-MAR-2010 H: 0.00					
27 5253-001 Airframe PART #960	LEFT FLAP ASSYMETRY BRAKE Part Number GT415-5500-3 Serial Number 3001	21-MAR-2010 H: 0.00					
27 5253-002 Airframe PART #1961	RIGHT FLAP ASSYMETRY BRAKE Part Number GT415-5500-3 Serial Number 3073	21-MAR-2010 H: 0.00					
27 53-09-101 Airframe INSPECTION 3000H #2827	FUNCTIONAL TEST OF THE SLAT SYSTEM ACTUATORS	01-DEC-2018 H: 3011.20 L: 1025	H: 3000.00			H: 6011.20	H: 1555.40
27 5301-003 Airframe PART #2456	LH SLAT NO. 3 SLAT TORQUE TUBE Part Number GT415-5200-5 Serial Number 3008	21-MAR-2010 H: 0.00					
27 5301-004 Airframe PART #2162	RIGHT SLAT NO. 3 SLAT TORQUE TUBE Part Number GT415-5200-5 Serial Number 3009	21-MAR-2010 H: 0.00					
27 5301-009 Airframe PART #2872	LEFT SLAT NO.1 SLAT TORQUE TUBE Part Number GT415-5207-1 Serial Number 2970	21-MAR-2010 H: 0.00					
27 5301-010 Airframe PART #2976	RIGHT SLAT NO. 1 SLAT TORQUE TUBE Part Number GT415-5207-1 Serial Number 2971	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 5301-011 Airframe PART #500	LH SLAT NO. 4 SLAT TORQUE TUBE Part Number GT415-5200-11 Serial Number 2984	21-MAR-2010 H: 0.00					
27 5301-012 Airframe PART #2410	RIGHT SLAT NO. 4 SLAT TORQUE TUBE Part Number GT415-5200-11 Serial Number 2986	21-MAR-2010 H: 0.00					
27 5301-016 Airframe PART #1798	LH SLAT NO. 1 TORQUE TUBE Part Number GT415-5200-1 Serial Number 2985	21-MAR-2010 H: 0.00					
27 5301-017 Airframe PART #188	RH SLAT NO. 2 TORQUE TUBE Part Number GT415-5200-1 Serial Number 2986	21-MAR-2010 H: 0.00					
27 5301-018 Airframe PART #3021	LH SLAT NO. 1 TORQUE TUBE Part Number GT415-5201-1 Serial Number 2989	21-MAR-2010 H: 0.00					
27 5301-019 Airframe PART #1399	RH SLAT NO. 2 TORQUE TUBE Part Number GT415-5201-1 Serial Number 2988	21-MAR-2010 H: 0.00					
27 5301-020 Airframe PART #405	LH SLAT NO. 1 TORQUE TUBE Part Number GT415-5201-9 Serial Number 2998	21-MAR-2010 H: 0.00					
27 5301-021 Airframe PART #539	RH SLAT NO. 2 TORQUE TUBE Part Number GT415-5201-9 Serial Number 2999	21-MAR-2010 H: 0.00					
27 5309-001 Airframe PART #252	LEFT NO.1 SLAT ACTUATOR Part Number GT412-5601-1 Serial Number 2898	21-MAR-2010 H: 0.00					
27 5309-002 Airframe PART #1175	RIGHT NO. 1 SLAT ACTUATOR Part Number GT412-5601-1 Serial Number 2895	21-MAR-2010 H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 5309-003 Airframe PART #1993	LEFT NO.2 SLAT ACTUATOR Part Number GT412-5602-1	Serial Number 2821	21-MAR-2010 H: 0.00				
27 5309-004 Airframe PART #2429	RIGHT NO. 2 SLAT ACTUATOR Part Number GT412-5602-1	Serial Number 2897	21-MAR-2010 H: 0.00				
27 5309-005 Airframe PART #472	LEFT NO.3 SLAT ACTUATOR Part Number GT412-5603-1	Serial Number 2903	21-MAR-2010 H: 0.00				
27 5309-006 Airframe PART #2328	RIGHT NO. 3 SLAT ACTUATOR Part Number GT412-5603-1	Serial Number 2868	21-MAR-2010 H: 0.00				
27 5309-007 Airframe PART #2276	LEFT NO.4 SLAT ACTUATOR Part Number GT412-5604-1	Serial Number 2832	21-MAR-2010 H: 0.00				
27 5309-008 Airframe PART #109	RIGHT NO. 4 SLAT ACTUATOR Part Number GT412-5604-1	Serial Number 2879	21-MAR-2010 H: 0.00				
27 5309-009 Airframe PART #2520	LEFT NO.5 SLAT ACTUATOR Part Number GT412-5605-1	Serial Number 2890	21-MAR-2010 H: 0.00				
27 5309-010 Airframe PART #836	RIGHT NO. 5 SLAT ACTUATOR Part Number GT412-5605-1	Serial Number 2889	21-MAR-2010 H: 0.00				
27 5309-011 Airframe PART #2841	LEFT NO.6 SLAT ACTUATOR Part Number GT412-5606-1	Serial Number 2832	21-MAR-2010 H: 0.00				
27 5309-012 Airframe PART #1650	RIGHT NO. 6 SLAT ACTUATOR Part Number GT412-5606-1	Serial Number 2862	21-MAR-2010 H: 0.00				



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 5309-013 Airframe PART #2985	LEFT NO.7 SLAT ACTUATOR Part Number GT412-5607-3 Serial Number 2886	21-MAR-2010 H: 0.00					
27 5309-014 Airframe PART #2561	RIGHT NO. 7 SLAT ACTUATOR Part Number GT412-5607-3 Serial Number 2894	21-MAR-2010 H: 0.00					
27 5309-015 Airframe PART #324	LEFT NO.8 SLAT ACTUATOR Part Number GT412-5609-3 Serial Number 2848	21-MAR-2010 H: 0.00					
27 5309-016 Airframe PART #2567	RIGHT NO. 8 SLAT ACTUATOR Part Number GT412-5608-3 Serial Number 2853	21-MAR-2010 H: 0.00					
27 5313-001 Airframe PART #1456	FLAP LH WS163.416 T/E DRIVE SHAFT RETAIN BEARING Part Number GT415-5100-1 Serial Number 6685	21-MAR-2010 H: 0.00					
27 5313-002 Airframe PART #914	FLAP LH WS250.000 T/E DRIVE SHAFT RETAIN BEARING Part Number GT415-5100-1 Serial Number 6697	21-MAR-2010 H: 0.00					
27 5313-003 Airframe PART #186	FLAP LH WS420.911 T/E DRIVE SHAFT RETAIN BEARING Part Number GT415-5100-1 Serial Number 6699	21-MAR-2010 H: 0.00					
27 5313-004 Airframe PART #89	FLAP RH WS163.416 T/E DRIVE SHAFT RETAIN BEARING Part Number GT415-5100-1 Serial Number 6635	21-MAR-2010 H: 0.00					
27 5313-005 Airframe PART #2123	FLAP RH WS250.000 T/E DRIVE SHAFT RETAIN BEARING Part Number GT415-5100-1 Serial Number 6636	21-MAR-2010 H: 0.00					
27 5313-006 Airframe PART #2310	FLAP RH WS420.911 T/E DRIVE SHAFT RETAIN BEARING Part Number GT415-5100-1 Serial Number 6686	21-MAR-2010 H: 0.00					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 5313-007 Airframe PART #1403	SLAT LH WS92.954 L/E DRIVE SHAFT RETAIN BEARING Part Number GT415-5100-1 Serial Number 6434	21-MAR-2010 H: 0.00					
27 5313-008 Airframe PART #1579	SLAT LH WS265.000 L/E DRIVE SHAFT RETAIN BEARING Part Number GT415-5100-1 Serial Number 6452	21-MAR-2010 H: 0.00					
27 5313-009 Airframe PART #1396	SLAT LH WS391.000 L/E DRIVE SHAFT RETAIN BEARING Part Number GT415-5100-1 Serial Number 6628	21-MAR-2010 H: 0.00					
27 5313-010 Airframe PART #1952	SLAT RH WS92.954 L/E DRIVE SHAFT RETAIN BEARING Part Number GT415-5100-1 Serial Number 6294	21-MAR-2010 H: 0.00					
27 5313-011 Airframe PART #1690	SLAT RH WS265.000 L/E DRIVE SHAFT RETAIN BEARING Part Number GT415-5100-1 Serial Number 6301	21-MAR-2010 H: 0.00					
27 5313-012 Airframe PART #247	SLAT RH WS391.000 L/E DRIVE SHAFT RETAIN BEARING Part Number GT415-5100-1 Serial Number 6370	21-MAR-2010 H: 0.00					
27 5317-001 Airframe PART #1608	LH NO.1 SLAT Part Number GM128-1011-21 Serial Number SB0287	12-SEP-2012 H: 388.37 L: 190					
27 5317-002 Airframe PART #1644	RH NO.1 SLAT Part Number GM128-1011-22 Serial Number SB0231	21-MAR-2010 H: 0.00					
27 5321-003 Airframe PART #2858	LH NO.2 SLAT Part Number GM128-1012-17 Serial Number SB0366	12-SEP-2012 H: 388.37 L: 190					
27 5321-004 Airframe PART #2269	RH NO.2 SLAT Part Number GM128-1012-18 Serial Number SB0232	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 5325-005 Airframe PART #1128	LH NO.3 SLAT Part Number GM128-1013-15 Serial Number SB0234	21-MAR-2010 H: 0.00					
27 5325-006 Airframe PART #1653	RH NO.3 SLAT Part Number GM128-1013-16 Serial Number SB0232	21-MAR-2010 H: 0.00					
27 5327-001 Airframe PART #1562	LH ELECTRICAL SLAT/FLAP PDU MOTOR Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
27 5327-003 Airframe PART #2393	RH ELECTRICAL SLAT/FLAP PDU MOTOR Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
27 5329-007 Airframe PART #1887	LH NO.4 SLAT Part Number GM128-1014-23 Serial Number SB0236	21-MAR-2010 H: 0.00					
27 5329-008 Airframe PART #2507	RH NO.4 SLAT Part Number GM128-1014-24 Serial Number SB0240	21-MAR-2010 H: 0.00					
27 5333-001 Airframe PART #1964	SLAT FLAP/SLAT PDU Part Number GT415-5001-5 Serial Number 2885	21-MAR-2010 H: 0.00					
27 5333-002 Airframe PART #967	FLAP FLAP/SLAT PDU Part Number GT415-5001-5 Serial Number 2886	21-MAR-2010 H: 0.00					
27 5341-001 Airframe PART #1521	LEFT SLAT (FLAP/SLAT) RESOLVER Part Number GT412-5300-3 Serial Number B1303	21-MAR-2010 H: 0.00					
27 5341-002 Airframe PART #2921	RIGHT SLAT (FLAP/SLAT) RESOLVER Part Number GT412-5300-3 Serial Number B1715	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 5345-001 Airframe PART #2495	LEFT SLAT ASSYMETRY BRAKE Part Number GT415-5500-3 Serial Number 3010	21-MAR-2010 H: 0.00					
27 5345-002 Airframe PART #2785	RIGHT SLAT ASSYMETRY BRAKE Part Number GT415-5500-3 Serial Number 2937	21-MAR-2010 H: 0.00					
27 60-00-101 Airframe INSPECTION 1500H #2687	OPERATIONAL TEST OF THE SPOILER POWER-CONTROL UNITS (PCU)	08-FEB-2022 H: 4399.80 L: 1478	H: 1500.00			H: 5899.80	H: 1444.00
27 61-05-201 Airframe INSPECTION 3000H #887	OPERATIONAL TEST OF THE FLIGHT-CONTROL UNIT (FCU) BACK-UP MODULES	16-NOV-2018 H: 2586.20	H: 3000.00	H: 50.00		H: 5586.20	H: 1130.40
27 6101-001 Airframe PART #2605	FLIGHT SPOILER PANEL ASSY Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
27 6105-001 Airframe PART #1076	NO. 1 FLIGHT CONTROL UNIT FCU Part Number GT415-0100-9 Serial Number 297	14-DEC-2021 H: 4388.60 L: 1472					
27 6105-002 Airframe PART #660	NO. 2 FLIGHT CONTROL UNIT FCU Part Number GT415-0100-11 Serial Number 215	14-DEC-2021 H: 4388.60 L: 1472					
27 6201-001 Airframe PART #1829	LOB MULTIFUNCTION SPOILER PCU Part Number GT411-6001-9 Serial Number 3221A	21-MAR-2010 H: 0.00					
27 6201-002 Airframe PART #1465	LOB MULTIFUNCTION FLIGHT SPOILER PCU Part Number GT411-6001-9 Serial Number 3219A	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 6201-003 Airframe PART #2056	LIB MULTIFUNCTION SPOILER PCU Part Number Serial Number GT411-6001-9 3195A	21-MAR-2010 H: 0.00					
27 6201-004 Airframe PART #2960	LIB MULTIFUNCTION FLIGHT SPOILER PCU Part Number Serial Number GT411-6001-9 3106A	21-MAR-2010 H: 0.00					
27 6201-005 Airframe PART #973	RIB MULTIFUNCTION SPOILER PCU Part Number Serial Number GT411-6001-9 3204A	21-MAR-2010 H: 0.00					
27 6201-006 Airframe PART #2007	RIB MULTIFUNCTION FLIGHT SPOILER PCU Part Number Serial Number GT411-6001-9 3109A	21-MAR-2010 H: 0.00					
27 6201-007 Airframe PART #2129	ROB MULTIFUNCTION SPOILER PCU Part Number Serial Number GT411-6001-9 3226A	21-MAR-2010 H: 0.00					
27 6201-008 Airframe PART #2636	ROB MULTIFUNCTION FLIGHT SPOILER PCU Part Number Serial Number GT411-6001-9 2986C	07-OCT-2014 H: 1015.50 L: 386					
27 6209-001 Airframe PART #1523	LOB FLIGHT SPOILER Part Number Serial Number GM168-1500-1 386	21-MAR-2010 H: 0.00					
27 6209-002 Airframe PART #588	LIB FLIGHT SPOILER Part Number Serial Number GM168-1400-1 387	21-MAR-2010 H: 0.00					
27 6209-003 Airframe PART #1144	RIB FLIGHT SPOILER Part Number Serial Number GM168-1400-2 388	21-MAR-2010 H: 0.00					
27 6209-004 Airframe PART #3019	ROB FLIGHT SPOILER Part Number Serial Number GM168-1500-2 386	21-MAR-2010 H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 6301-001 Airframe PART #2717	INBOARD SELECTOR, GROUND SPOILER VALVE Part Number Serial Number GT411-6003-3 0118	05-DEC-2012 H: 426.50 L: 209					
27 6301-002 Airframe PART #2657	OUTBOARD SELECTOR, GROUND SPOILER VALVE Part Number Serial Number GT411-6003-3 806	21-MAR-2010 H: 0.00					
27 6305-001 Airframe PART #462	LOB GROUND SPOILER ACTUATOR Part Number Serial Number GT411-6002-3 1591	21-MAR-2010 H: 0.00					
27 6305-002 Airframe PART #3017	LIB GROUND SPOILER ACTUATOR Part Number Serial Number GT411-6002-3 1569	21-MAR-2010 H: 0.00					
27 6305-003 Airframe PART #2744	RIB GROUND SPOILER ACTUATOR Part Number Serial Number GT411-6002-3 1597	21-MAR-2010 H: 0.00					
27 6305-004 Airframe PART #684	ROB GROUND SPOILER ACTUATOR Part Number Serial Number GT411-6002-3 1599	21-MAR-2010 H: 0.00					
28 Airframe PART #5085	R/H DC AUX PUMP CANISTER Part Number Serial Number GP422-1414-11 6AP34	15-FEB-2021 H: 3992.00 L: 1324					
28 10-00-201 Airframe INSPECTION 180M #2327	DETAILED INSPECTION OF THE VENT TUBING VAPOR-BARRIER COATING	21-MAR-2010 H: 0.00	M: 180	M: 3		21-MAR-2025	M: 36 D: 5
28 10-00-202 Airframe INSPECTION 120M #266	DETAILED INSPECTION OF THE CENTER-TANK VAPOR-BARRIER COATING	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 11-00-201 Airframe INSPECTION 1000 H #404	GENERAL VISUAL INSPECTION OF THE WING-TANK EXTERNAL SURFACES	10-MAR-2022 H: 4455.80 L: 1495	H: 1000.00	H: 50.00		H: 5455.80	H: 1000.00
28 11-00-202 Airframe INSPECTION 1000 H #233	GENERAL VISUAL INSPECTION OF THE WING-TANK EXTERNAL COMPONENTS	10-MAR-2022 H: 4455.80 L: 1495	H: 1000.00	H: 50.00		H: 5455.80	H: 1000.00
28 11-05-201 Airframe INSPECTION 60M #1210	DETAILED INSPECTION OF THE WATER DRAIN VALVES	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
	Notes NO DEFECTS NOTED						
28 1101-001 Airframe PART #1747	LH LOWER PANEL, WING ACCESS DOOR Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
28 1101-002 Airframe PART #1876	RH LOWER PANEL, WING ACCESS DOOR Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
28 1105-001 Airframe PART #1529	LH WATER DRAIN (BL42.0 FSTA 640.4) VALVE Part Number GP422-1107-1 Serial Number 1905	21-MAR-2010 H: 0.00					
28 1105-002 Airframe PART #1193	LH WATER DRAIN (WS52.5 LWR STR #10 - #11) VALVE Part Number GP422-1107-1 Serial Number 1891	21-MAR-2010 H: 0.00					
28 1105-003 Airframe PART #1100	RH WATER DRAIN (BL42.0 FSTA 634.00) VALVE Part Number GP422-1107-1 Serial Number 1952	21-MAR-2010 H: 0.00					
28 1105-004 Airframe PART #863	RH WATER DRAIN (WS52.5 LWR STR #10 - #11) VALVE Part Number GP422-1107-1 Serial Number 1853	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 1109-001 Airframe PART #358	LH WING TANK PRESSURE RELIEF VALVE Part Number Serial Number GP422-1109-1 1182	21-MAR-2010 H: 0.00					
28 1109-002 Airframe PART #2590	RH WING TANK PRESSURE RELIEF VALVE Part Number Serial Number GP422-1109-1 1183	21-MAR-2010 H: 0.00					
28 1109-003 Airframe PART #786	CENTER TANK PRESSURE RELIEF VALVE Part Number Serial Number GP422-1109-2 1193	21-MAR-2010 H: 0.00					
28 1125-001 Airframe PART #938	LEFT GRAVITY FILL CAP Part Number Serial Number GP425-1104-1 1297	21-MAR-2010 H: 0.00					
28 1125-002 Airframe PART #2271	RIGHT FORWARD GRAVITY FILL CAP Part Number Serial Number GP425-1104-1 1299	21-MAR-2010 H: 0.00					
28 1125-003 Airframe PART #1208	RIGHT AFT GRAVITY FILL CAP Part Number Serial Number GP425-1104-1 1298	21-MAR-2010 H: 0.00					
28 1129-001 Airframe PART #2272	LH WING TANK GRAVITY FILL ADAPTER Part Number Serial Number GP425-1105-1 896	21-MAR-2010 H: 0.00					
28 1129-002 Airframe PART #1683	CENTER TANK GRAVITY FILL ADAPTER Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
28 1129-003 Airframe PART #2205	RH WING TANK GRAVITY FILL ADAPTER Part Number Serial Number GP425-1105-1 907	21-MAR-2010 H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 12-00-201 Airframe INSPECTION 1000 H #2037	GENERAL VISUAL INSPECTION OF THE AFT FUEL-TANK DRAIN-MAST	10-MAR-2022 H: 4455.80 L: 1495	H: 1000.00	H: 50.00		H: 5455.80	H: 1000.00
28 12-00-202 Airframe INSPECTION 120M #2497	FUNCTIONAL TEST OF THE AFT FUEL-TANK COMPARTMENT	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
Notes BAGS AND COMPARTMENT FAILED FUNCTION TEST.							
28 1205-001 Airframe PART #1990	AFT DRAIN TANK VALVE Part Number GP422-1102-1 Serial Number 0825	09-APR-2021 H: 3992.00 L: 1324					
28 1209-001 Airframe PART #905	AFT TANK PRESSURE RELIEF VALVE Part Number GP422-1105-1 Serial Number 306	21-MAR-2010 H: 0.00					
28 1213-003 Airframe PART #2833	LH FLEXIBLE, AUXILIARY TANK FUEL CELL Part Number GD421-0101-9 Serial Number T01072	05-APR-2021 H: 3992.00 L: 1324					
28 1213-004 Airframe PART #580	RH FLEXIBLE, AUXILIARY TANK FUEL CELL Part Number GD421-0101-8 Serial Number T010243	05-APR-2021 H: 3992.00 L: 1324					
28 13-00-201 Airframe INSPECTION 120M #2745	FUNCTIONAL TEST OF THE FUEL VENT TUBING	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
Notes NO DEFECTS NOTED							
28 13-00-202 Airframe INSPECTION 1000 H #2873	OPERATIONAL TEST OF THE VENT SYSTEM	10-MAR-2022 H: 4455.80 L: 1495	H: 1000.00	H: 50.00		H: 5455.80	H: 1000.00





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 1305-001 Airframe PART #1480	LH SURGE BOX Part Number GC426-0101-7 Serial Number GSC0160-09	21-MAR-2010 H: 0.00					
28 1305-002 Airframe PART #717	RH SURGE BOX Part Number GC426-0101-8 Serial Number GSC0137-08	21-MAR-2010 H: 0.00					
28 2000-001 Airframe PART #950	LH SHUT-OFF VALVE ACTUATOR Part Number PN Serial Number SN-UNKNOWN	21-MAR-2010 H: 0.00					
28 2000-002 Airframe PART #1321	RH SHUT-OFF VALVE ACTUATOR Part Number PN Serial Number SN-UNKNOWN	21-MAR-2010 H: 0.00					
28 2000-003 Airframe PART #2775	APU SHUT-OFF VALVE ACTUATOR Part Number PN Serial Number SN-UNKNOWN	21-MAR-2010 H: 0.00					
28 2000-006 Airframe PART #103	AFT SHUT-OFF VALVE ACTUATOR Part Number PN Serial Number SN-UNKNOWN	21-MAR-2010 H: 0.00					
28 2001-001 Airframe PART #729	FUEL CONTROL PANEL Part Number PN Serial Number SN-UNKNOWN	21-MAR-2010 H: 0.00					
28 21-00-201 Airframe INSPECTION 120M #332	FUNCTIONAL TEST OF THE FUEL-FEED TUBING SHROUDS Notes NO DEFECTS NOTED	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 21-00-202 Airframe INSPECTION 1000 H #502	VISUAL CHECK OF THE SHROUD DRAINS	10-MAR-2022 H: 4455.80 L: 1495	H: 1000.00	H: 50.00		H: 5455.80	H: 1000.00
28 21-29-201 Airframe INSPECTION 3000H #2359	OPERATIONAL (INTERNAL LEAK) TEST OF THE ENGINE FEED SHUTOFF-VALVES	01-DEC-2018 H: 3011.20 L: 1025	H: 3000.00	H: 50.00		H: 6011.20	H: 1555.40
28 2101-001 Airframe PART #1414	LEFT FORWARD AC BOOST PUMP CARTRIDGE Part Number Serial Number GP422-1401-3 12BE189	21-MAR-2010 H: 0.00					
28 2101-002 Airframe PART #94	RIGHT FORWARD AC BOOST PUMP CARTRIDGE Part Number Serial Number GP422-1401-3 12BE190	21-MAR-2010 H: 0.00					
28 2101-003 Airframe PART #2642	LEFT AFT AC BOOST PUMP CARTRIDGE Part Number Serial Number GP422-1401-3 12BE181	21-MAR-2010 H: 0.00					
28 2101-004 Airframe PART #2949	RIGHT AFT AC BOOST PUMP CARTRIDGE Part Number Serial Number GP422-1401-3 12BE193	21-MAR-2010 H: 0.00					
28 2105-001 Airframe PART #2665	LEFT FORWARD AC BOOST PUMP CANISTER Part Number Serial Number GP422-1401-17 12BE189	21-MAR-2010 H: 0.00					
28 2105-002 Airframe PART #2368	LEFT AFT AC BOOST PUMP CANISTER Part Number Serial Number GP422-1401-17 12BE181	21-MAR-2010 H: 0.00					
28 2105-003 Airframe PART #390	RIGHT FORWARD AC BOOST PUMP CANNISTER Part Number Serial Number GP422-1401-17 12BE190	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 2105-004 Airframe PART #386	RIGHT AFT AC BOOST PUMP CANNISTER Part Number GP422-1401-17 Serial Number 12BE193	21-MAR-2010 H: 0.00					
28 2109-001 Airframe PART #1904	LOB PRESSURE SWITCH Part Number GP422-1306-3 Serial Number 2773	21-MAR-2010 H: 0.00					
28 2109-002 Airframe PART #2440	LIB PRESSURE SWITCH Part Number GP422-1306-3 Serial Number 2694	21-MAR-2010 H: 0.00					
28 2109-003 Airframe PART #15	RIB PRESSURE SWITCH Part Number GP422-1306-3 Serial Number 2775	21-MAR-2010 H: 0.00					
28 2109-004 Airframe PART #2646	ROB PRESSURE SWITCH Part Number GP422-1306-3 Serial Number 2778	21-MAR-2010 H: 0.00					
28 2113-001 Airframe PART #818	LH DC AUXILIARY PUMP ASSY Part Number GP422-1414-13 Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
28 2113-002 Airframe PART #993	RH DC AUXILIARY PUMP ASSY Part Number GP422-1414-13 Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
28 2121-001 Airframe PART #2157	LH CENTER TRANSFER - DC AUX PRESSURE SWITCH Part Number GP422-1306-5 Serial Number 2009	21-MAR-2010 H: 0.00					
28 2121-002 Airframe PART #1818	RH CENTER TRANSFER - DC AUX PRESSURE SWITCH Part Number GP422-1306-5 Serial Number 2352	21-MAR-2010 H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 2121-701 Airframe PART #3750	LH DC FUEL PUMP PRESSURE SENSOR Part Number PN	H: 0.00					
	Serial Number SN- UNKNOWN						
28 2121-702 Airframe PART #1869	RH DC FUEL PUMP PRESSURE SENSOR Part Number GP422-1306-5	27-OCT-2013 H: 513.50 L: 241					
	Serial Number 3510						
28 2125-001 Airframe PART #2995	LH EJECTOR VENT SCAVENGE PUMP Part Number GP422-1408-3	21-MAR-2010 H: 0.00					
	Serial Number 824						
28 2125-002 Airframe PART #1891	RH EJECTOR VENT SCAVENGE PUMP Part Number GP422-1408-3	21-MAR-2010 H: 0.00					
	Serial Number 823						
28 2129-001 Airframe PART #641	LH ENGINE FEED SOV ACTUATOR Part Number PN	21-MAR-2010 H: 0.00					
	Serial Number SN- UNKNOWN						
28 2129-002 Airframe PART #2898	RH ENGINE FEED SOV ACTUATOR Part Number PN	21-MAR-2010 H: 0.00					
	Serial Number SN- UNKNOWN						
28 2129-003 Airframe PART #969	LEFT ENGINE FEED SHUTOFF VALVE Part Number PN	21-MAR-2010 H: 0.00					
	Serial Number SN- UNKNOWN						
28 2129-004 Airframe PART #1857	RIGHT ENGINE FEED SHUTOFF VALVE Part Number PN	21-MAR-2010 H: 0.00					
	Serial Number SN- UNKNOWN						
28 2137-001 Airframe PART #2437	APU BODY VALVE Part Number PN	21-MAR-2010 H: 0.00					
	Serial Number SN- UNKNOWN						



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 2145-001 Airframe PART #2612	LH SHUTOFF CROSSFEED VALVE Part Number GP422-1412-5 Serial Number 1191	21-MAR-2010 H: 0.00					
28 2145-002 Airframe PART #1764	RH SHUTOFF CROSSFEED VALVE Part Number GP422-1412-5 Serial Number 1192	21-MAR-2010 H: 0.00					
28 2153-001 Airframe PART #1824	LH CHECK FEED VALVE Part Number GP422-1410-1 Serial Number 1755	21-MAR-2010 H: 0.00					
28 2153-002 Airframe PART #2198	RH CHECK FEED VALVE Part Number GP422-1410-1 Serial Number 1805	21-MAR-2010 H: 0.00					
28 2157-001 Airframe PART #1678	LEFT CHECK FEED VALVE Part Number GP422-1410-1 Serial Number 1792	21-MAR-2010 H: 0.00					
28 2157-002 Airframe PART #417	RIGHT CHECK FEED VALVE Part Number GP422-1410-1 Serial Number 1793	21-MAR-2010 H: 0.00					
28 2161-001 Airframe PART #142	LH CHECK DC AUX PUMP VALVE Part Number GP422-1305-1 Serial Number 1058	21-MAR-2010 H: 0.00					
28 2161-002 Airframe PART #1181	RH CHECK DC AUX PUMP VALVE Part Number GP422-1305-1 Serial Number 1059	21-MAR-2010 H: 0.00					
28 22-00-201 Airframe INSPECTION 3000H #1474	OPERATIONAL TEST OF THE AFT-TANK MANUAL-TRANSFER SYSTEM	04-MAR-2016 H: 1753.70 L: 622	H: 3000.00	H: 50.00		H: 4753.70	H: 297.90





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 22-00-202 Airframe INSPECTION 3000H #1681	OPERATIONAL TEST OF THE WING TO WING MANUAL-TRANSFER SYSTEM	04-MAR-2016 H: 1753.70 L: 622	H: 3000.00	H: 50.00		H: 4753.70	H: 297.90
28 2201-001 Airframe PART #91	LH SHUTOFF WING TRANSFER VALVE Part Number Serial Number GP422-1304-3 842	21-MAR-2010 H: 0.00					
28 2201-002 Airframe PART #1303	RH SHUTOFF WING TRANSFER VALVE Part Number Serial Number GP422-1304-3 843	21-MAR-2010 H: 0.00					
28 2209-001 Airframe PART #1634	LH CENTER TRANSFER PUMP CARTRIDGE Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
28 2209-002 Airframe PART #624	RH CENTER TRANSFER PUMP CARTRIDGE Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
28 2213-001 Airframe PART #2107	LH CENTER TRANSFER PUMP ASSEMBLY Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
28 2213-002 Airframe PART #1722	RH CENTER TRANSFER PUMP ASSEMBLY Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
28 2214-001 Airframe PART #278	LH CENTER TRANSFER PUMP CANISTER Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
28 2214-002 Airframe PART #1044	RH CENTER TRANSFER PUMP CANISTER Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 2217-001 Airframe PART #1655	LH AC CENTER PRESSURE SWITCH Part Number GP422-1306-5 Serial Number 1999	21-MAR-2010 H: 0.00					
28 2217-002 Airframe PART #2420	RH AC CENTER PRESSURE SWITCH Part Number GP422-1306-5 Serial Number 2092	21-MAR-2010 H: 0.00					
28 2221-001 Airframe PART #2407	LH CHECK CENTER TANK TRANSFER VALVE Part Number GP422-1405-1 Serial Number 3658	21-MAR-2010 H: 0.00					
28 2221-002 Airframe PART #383	RH CHECK CENTER TANK TRANSFER VALVE Part Number GP422-1405-1 Serial Number 3659	21-MAR-2010 H: 0.00					
28 2225-001 Airframe PART #1870	LH AFT TANK TRANSFER PUMP ASSEMBLY Part Number GP422-1302-15 Serial Number 11BE68	21-MAR-2010 H: 0.00					
28 2225-002 Airframe PART #281	RH AFT TANK TRANSFER PUMP ASSEMBLY Part Number GP422-1302-15 Serial Number 3BM26	15-APR-2021 H: 3992.00 L: 1324					
28 2229-701 Airframe PART #3258	LH AFT PRESSURE SWITCH Part Number GP422-1306-5 Serial Number SN- UNKNOWN	H: 0.00					
28 2229-702 Airframe PART #40	RH AFT PRESSURE SWITCH Part Number GP422-1306-5 Serial Number 3939	10-MAR-2015 H: 1311.80 L: 475					
28 2233-001 Airframe PART #471	LOB FUEL CHECK VALVE Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 2233-002 Airframe PART #3004	LIB FUEL CHECK VALVE Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
28 2233-003 Airframe PART #2469	RIB FUEL CHECK VALVE Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
28 2233-004 Airframe PART #2553	ROB FUEL CHECK VALVE Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
28 2301-001 Airframe PART #224	EXTERNAL REFUEL/DEFUEL PANEL Part Number GP541-1102-1	Serial Number 1901	25-JUN-2018 H: 2769.60 L: 945				
28 2301-701 Airframe PART #1566	LH ENTRANCE ENCLOSURE REFUEL/DEFUEL PANEL Part Number GP541-1102-1	Serial Number 1585	15-FEB-2011 H: 25.00 L: 11				
28 2305-001 Airframe PART #1549	RH REFUEL ADAPTOR CAP Part Number GP516-1102-1	Serial Number 2093	21-MAR-2010 H: 0.00				
28 2305-002 Airframe PART #1524	REFUEL/DE-FUEL ADAPTOR Part Number GP425-1102-3	Serial Number 31760	21-MAR-2010 H: 0.00				
28 2313-001 Airframe PART #943	LEFT TANK MANIFOLD REFUEL/DEFUEL CONTROL Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
28 2313-002 Airframe PART #2715	CENTER TANK MANIFOLD REFUEL/DEFUEL CONTROL Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 2313-003 Airframe PART #2131	RIGHT TANK MANIFOLD REFUEL/DEFUEL CONTROL Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
28 2317-001 Airframe PART #343	LH CHECK REFUEL VALVE Part Number: GP422-1111-1 Serial Number: 826	21-MAR-2010 H: 0.00					
28 2317-002 Airframe PART #1551	RH CHECK REFUEL VALVE Part Number: GP422-1111-1 Serial Number: 813	21-MAR-2010 H: 0.00					
28 2321-001 Airframe PART #1801	CHECK REFUEL/DEFUEL VALVE Part Number: GP422-1108-1 Serial Number: 394	21-MAR-2010 H: 0.00					
28 2325-001 Airframe PART #2760	LH SHUTOFF DEFUEL VALVE Part Number: GP422-1412-4 Serial Number: AA185291	21-MAR-2010 H: 0.00					
28 2325-002 Airframe PART #1956	RH SHUTOFF DEFUEL VALVE Part Number: GP422-1412-4 Serial Number: AA185289	21-MAR-2010 H: 0.00					
28 2333-003 Airframe PART #668	AFT TANK REFUEL SHUTOFF VALVE Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
28 24-00-201 Airframe INSPECTION 120M #2388	OPERATIONAL TEST OF THE FUEL RETURN TO TANK (FRTT) CHECK VALVES, POST SB 700-28-034 AND A/C 9111 AND SUBS Notes NO DEFECTS NOTED	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
28 2705-001 Airframe PART #63	LH EJECTOR PUMP VALVE Part Number: GP422-1415-1 Serial Number: 3113	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 2705-002 Airframe PART #2262	RH EJECTOR PUMP VALVE Part Number Serial Number GP422-1415-1 3090	21-MAR-2010 H: 0.00					
28 2717-001 Airframe PART #2598	LH CENTER TRANSFERT PUMP - DC AUX PUMP VALVE CHECK Part Number Serial Number GP422-1405-1 3656	21-MAR-2010 H: 0.00					
28 2717-002 Airframe PART #2256	RH CENTER TRANSFERT PUMP - DC AUX PUMP VALVE CHECK Part Number Serial Number GP422-1405-1 3657	21-MAR-2010 H: 0.00					
28 41-00-101 Airframe INSPECTION 120M #2730	FUNCTIONAL TEST OF THE TEMPERATURE SENSORS	19-APR-2021 H: 3992.00 L: 1324	M: 120			19-APR-2031	M: 109 D: 3
28 4101-001 Airframe PART #148	FUEL MANAGEMENT AND QUANTITY GAUGING COMPUTER (FMQGC) Part Number Serial Number GP546-1501-13 0176 Notes RH AVIONICS BAY	18-MAR-2017 H: 2211.30 L: 783					
28 4102-001 Airframe PART #2751	LH (L 36.17 IN) FUEL PROBE Part Number Serial Number GP422-1501-1 852	21-MAR-2010 H: 0.00					
28 4102-002 Airframe PART #90	RH (L 36.17 IN) FUEL PROBE Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
28 4102-003 Airframe PART #1753	LH (L 35.88 IN) FUEL PROBE Part Number Serial Number GP422-1514-1 879	21-MAR-2010 H: 0.00					
28 4102-004 Airframe PART #926	RH (L 35.88 IN) FUEL PROBE Part Number Serial Number GP422-1514-3 425	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 4102-005 Airframe PART #1515	LH (L 27.81 IN) FUEL PROBE Part Number GP422-1501-2 Serial Number 834	21-MAR-2010 H: 0.00					
28 4102-006 Airframe PART #2460	RH (L 27.81 IN) FUEL PROBE Part Number GP422-1501-2 Serial Number 837	21-MAR-2010 H: 0.00					
28 4102-007 Airframe PART #2562	LH (L 17.51 IN) FUEL PROBE Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
28 4102-008 Airframe PART #425	RH (L 17.51 IN) FUEL PROBE Part Number GP422-1501-1 Serial Number 849	21-MAR-2010 H: 0.00					
28 4102-009 Airframe PART #1620	LH (L 28.85 IN) FUEL PROBE Part Number GP422-1501-3 Serial Number 818	21-MAR-2010 H: 0.00					
28 4102-010 Airframe PART #1617	RH (L 28.85 IN) FUEL PROBE Part Number GP422-1501-3 Serial Number 819	21-MAR-2010 H: 0.00					
28 4102-011 Airframe PART #1505	LH (L 30.77 IN) FUEL PROBE Part Number GP422-1501-4 Serial Number 791	21-MAR-2010 H: 0.00					
28 4102-012 Airframe PART #1770	RH (L 30.77 IN) FUEL PROBE Part Number GP422-1501-4 Serial Number 795	21-MAR-2010 H: 0.00					
28 4102-013 Airframe PART #2423	LH (L 20.16 IN) FUEL PROBE Part Number GP422-1501-5 Serial Number 773	21-MAR-2010 H: 0.00					
28 4102-014 Airframe PART #550	RH (L 20.16 IN) FUEL PROBE Part Number GP422-1501-5 Serial Number 777	21-MAR-2010 H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 4102-015 Airframe PART #416	LH (L 18.38 IN) FUEL PROBE Part Number GP422-1501-6 Serial Number 814	21-MAR-2010 H: 0.00					
28 4102-016 Airframe PART #1415	RH (L 18.38 IN) FUEL PROBE Part Number GP422-1501-6 Serial Number 816	21-MAR-2010 H: 0.00					
28 4102-017 Airframe PART #862	LH (L 17.51 IN) FUEL PROBE Part Number GP422-1501-7 Serial Number 842	21-MAR-2010 H: 0.00					
28 4102-018 Airframe PART #1920	RH (L 17.51 IN) FUEL PROBE Part Number GP422-1501-7 Serial Number 844	21-MAR-2010 H: 0.00					
28 4102-019 Airframe PART #633	LH (L 14.65 IN) FUEL PROBE Part Number GP422-1501-8 Serial Number 801	21-MAR-2010 H: 0.00					
28 4102-020 Airframe PART #1126	RH (L 14.65 IN) FUEL PROBE Part Number GP422-1501-8 Serial Number 810	21-MAR-2010 H: 0.00					
28 4102-021 Airframe PART #1926	LH (L 9.63 IN) FUEL PROBE Part Number GP422-1501-9 Serial Number 746	21-MAR-2010 H: 0.00					
28 4102-022 Airframe PART #2110	RH (L 9.63 IN) FUEL PROBE Part Number GP422-1501-9 Serial Number 758	21-MAR-2010 H: 0.00					
28 4102-023 Airframe PART #2452	LH (L 9.33 IN) FUEL PROBE Part Number GP422-1501-10 Serial Number 857	21-MAR-2010 H: 0.00					
28 4102-024 Airframe PART #1944	RH (L 9.33 IN) FUEL PROBE Part Number GP422-1501-10 Serial Number 864	21-MAR-2010 H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 4102-025 Airframe PART #1129	LH (L 8.98 IN) FUEL PROBE Part Number GP422-1501-11 Serial Number 856	21-MAR-2010 H: 0.00					
28 4102-026 Airframe PART #2197	RH (L 8.98 IN) FUEL PROBE Part Number GP422-1501-11 Serial Number 859	21-MAR-2010 H: 0.00					
28 4102-027 Airframe PART #1472	LH (L 8.12 IN) FUEL PROBE Part Number GP422-1501-12 Serial Number 761	21-MAR-2010 H: 0.00					
28 4102-028 Airframe PART #402	RH (L 8.12 IN) FUEL PROBE Part Number GP422-1501-12 Serial Number 817	21-MAR-2010 H: 0.00					
28 4102-029 Airframe PART #1545	LH (L 6.53 IN) FUEL PROBE Part Number GP422-1501-13 Serial Number 823	21-MAR-2010 H: 0.00					
28 4102-030 Airframe PART #443	RH (L 6.53 IN) FUEL PROBE Part Number GP422-1501-13 Serial Number 825	21-MAR-2010 H: 0.00					
28 4102-031 Airframe PART #1668	LH (L 7.61 IN) FUEL PROBE Part Number GP422-1501-14 Serial Number 804	21-MAR-2010 H: 0.00					
28 4102-032 Airframe PART #1427	RH (L 7.61 IN) FUEL PROBE Part Number GP422-1501-14 Serial Number 834	21-MAR-2010 H: 0.00					
28 4102-033 Airframe PART #3022	LH (L 21.67 IN) FUEL PROBE Part Number GP422-1501-15 Serial Number 790	21-MAR-2010 H: 0.00					
28 4102-034 Airframe PART #1232	RH (L 21.67 IN) FUEL PROBE Part Number GP422-1501-15 Serial Number 789	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 4102-036 Airframe PART #2963	RH (L 25.35 IN) FUEL PROBE Part Number Serial Number GP422-1514-1 885	21-MAR-2010 H: 0.00					
28 4105-001 Airframe PART #1663	LH BL4.75 UPPER STR #18 - #19 FUEL W/COMP (L36.71 IN) PROBE Part Number Serial Number GP422-1514-2 412	21-MAR-2010 H: 0.00					
28 4105-002 Airframe PART #534	RH BL4.75 UPPER STR #18 - #19 FUEL W/COMP (L36.71 IN) PROBE Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
28 4113-701 Airframe PART #619	LH TAIL TANK FUEL PROBE Part Number Serial Number GP422-1514-4 656	15-FEB-2011 H: 25.00 L: 11					
28 4113-702 Airframe PART #2761	RH TAIL TANK FUEL PROBE Part Number Serial Number GP422-1514-4 660	15-FEB-2011 H: 25.00 L: 11					
28 4117-001 Airframe PART #842	LH (WS415.4 LWR STR#10-#11) FUEL HIGH LEVEL SENSOR Part Number Serial Number GP422-1505-1 1691	21-MAR-2010 H: 0.00					
28 4117-002 Airframe PART #2581	LH (WS66.00 LWR STR#16-#17) FUEL HIGH LEVEL SENSOR Part Number Serial Number GP422-1505-1 1661	21-MAR-2010 H: 0.00					
28 4117-003 Airframe PART #2425	RH (WS415.4 LWR STR#10-#11) FUEL HIGH LEVEL SENSOR Part Number Serial Number GP422-1505-1 1642	21-MAR-2010 H: 0.00					
28 4117-004 Airframe PART #2374	RH (WS66.00 LWR STR#16-#17) FUEL HIGH LEVEL SENSOR Part Number Serial Number GP422-1505-1 1562	21-MAR-2010 H: 0.00					
28 4121-001 Airframe PART #1726	DENSIOMETER ENCLOSURE Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					



Maintenance Items

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Page 117 of 653



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 4121-002 Airframe PART #1969	FUEL DENSIMETER Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
28 4125-001 Airframe PART #1611	LH (WS66.00 LWR STR#7-#8) FUEL TEMP SENSOR Part Number Serial Number GP422-1508-3 2427	21-MAR-2010 H: 0.00					
28 4125-002 Airframe PART #2623	LH (CANT RIB LWR STR#8-#9) FUEL TEMP SENSOR Part Number Serial Number GP422-1508-3 2448	21-MAR-2010 H: 0.00					
28 4125-003 Airframe PART #702	RH (WS108.5 LWR STR#7-#8) FUEL TEMP SENSOR Part Number Serial Number GP422-1508-3 2491	21-MAR-2010 H: 0.00					
28 4125-004 Airframe PART #1114	RH (WS199.0 LWR STR#7-#8) FUEL TEMP SENSOR Part Number Serial Number GP422-1508-3 2501	21-MAR-2010 H: 0.00					
28 4125-005 Airframe PART #2442	RH (WS66.00 LWR STR#7-#8) FUEL TEMP SENSOR Part Number Serial Number GP422-1508-3 2468	21-MAR-2010 H: 0.00					
29 Airframe INSPECTION #5149	DRAIN, CLEAN, REPLACE FLITERS AND HYD FLUID ON SYSTEM 1,2 AND 3. Reference Number 29 HYD	02-SEP-2021 H: 4258.30 L: 1423	H: 3000.00	H: 50.00		H: 7258.30	H: 2802.50
29 12-00-201 Airframe INSPECTION 1000 H #2063	VISUAL CHECK OF THE NO. 1 AND NO. 2 HYDRAULIC FILTER DIFFERENTIAL-PRESSURE INDICATORS	10-MAR-2022 H: 4455.80 L: 1495	H: 1000.00	H: 50.00		H: 5455.80	H: 1000.00
29 12-33-101 Airframe INSPECTION 1500H #1401	OPERATIONAL TEST OF THE FIREWALL HYDRAULIC SHUTOFF-VALVES	08-FEB-2022 H: 4399.80 L: 1478	H: 1500.00			H: 5899.80	H: 1444.00





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
29 1201-001 Airframe PART #2282	NO. 1 ENGINE DRIVEN HYDRAULIC PUMP Part Number GX472-0010-1 Serial Number K0879	21-MAR-2010 H: 0.00					
29 1201-002 Airframe PART #11	NO. 2 ENGINE DRIVEN HYDRAULIC PUMP Part Number GX472-0010-1 Serial Number K1210	02-AUG-2013 H: 432.80 L: 211					
29 1205-001 Airframe PART #119	1B AC MOTOR PUMP Part Number GX472-0020-9 Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
29 1205-002 Airframe PART #241	2B AC MOTOR PUMP Part Number GX472-0020-9 Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
29 1205-003 Airframe PART #1113	3A AC MOTOR PUMP Part Number GX472-0020-11 Serial Number 1610	30-NOV-2012 H: 426.50 L: 209					
29 1205-004 Airframe PART #32	3B AC MOTOR PUMP Part Number GX472-0020-9 Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
29 1225-001 Airframe PART #3023	NO. 1 HYDRAULIC RESERVOIR Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
29 1225-002 Airframe PART #750	NO. 2 HYDRAULIC RESERVOIR Part Number GX471-0012-9 Serial Number PN0110	07-OCT-2014 H: 1015.50 L: 386					
29 1233-001 Airframe PART #1063	NO. 1 S/O FIREWALL VALVE Part Number GX473-0010-5 Serial Number TA2102	18-MAR-2015 H: 1339.30 L: 480					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
29 1233-002 Airframe PART #1860	NO. 2 S/O FIREWALL VALVE Part Number GX473-0010-5 Serial Number TA2106	18-MAR-2015 H: 1339.30 L: 480					
29 1233-003 Airframe PART #1110	NO. 1 HYDRAULIC FIREWALL SHUTOFF ACTUATOR ASSEMBLY Part Number GX473-0126-1 Serial Number TA4408	29-JUL-2021 H: 4179.80 L: 1402					
	Notes R&R'ED BY ANTHONY JAIRAM IN ROME, ITALY.						
29 1233-004 Airframe PART #2113	NO. 2 HYDRAULIC FIREWALL SHUTOFF ACTUATOR ASSEMBLY Part Number 975237-501 Serial Number TA5331	18-MAR-2015 H: 1339.30 L: 480					
29 1237-001 Airframe PART #1135	LH PRIORITY VALVE Part Number GX473-0060-1 Serial Number PN0608	21-MAR-2010 H: 0.00					
29 1237-002 Airframe PART #2735	RH PRIORITY VALVE Part Number GX473-0060-1 Serial Number PN0870	21-MAR-2010 H: 0.00					
29 1245-001 Airframe PART #2667	NO. 1 HEAT EXCHANGER BYPASS VALVE Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
29 1245-002 Airframe PART #2514	NO. 2 HEAT EXCHANGER BYPASS VALVE Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
29 1245-003 Airframe PART #1447	NO. 3 HEAT EXCHANGER BYPASS VALVE Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
29 1261-001 Airframe PART #549	LH CHECK VALVE Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
29 1261-002 Airframe PART #1154	RH CHECK VALVE Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
29 1261-003 Airframe PART #2149	CENTER CHECK VALVE Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
29 13-00-101 Airframe INSPECTION 1500H #1832	OPERATIONAL (INTERNAL LEAK) TEST OF THE NO. 3 HYDRAULIC SYSTEM	08-FEB-2022 H: 4399.80 L: 1478	H: 1500.00			H: 5899.80	H: 1444.00
29 13-00-201 Airframe INSPECTION 1000 H #389	VISUAL CHECK OF THE NO. 3 HYDRAULIC FILTER DIFFERENTIAL-PRESSURE INDICATORS	10-MAR-2022 H: 4455.80 L: 1495	H: 1000.00	H: 50.00		H: 5455.80	H: 1000.00
29 13-21-201 Airframe INSPECTION #1111	FUNCTIONAL TEST OF THE NO. 3 HYDRAULIC SYSTEM ACCUMULATOR	07-OCT-2019 H: 3516.60 L: 1170	H: 1000.00	H: 50.00		H: 4516.60	H: 60.80
29 1305-001 Airframe PART #2647	NO. 1 MANIFOLD FILTER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
29 1305-002 Airframe PART #1451	NO. 2 MANIFOLD FILTER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
29 1305-003 Airframe PART #369	NO. 3 MANIFOLD FILTER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
29 1321-001 Airframe PART #313	NO. 3 SYSTEM HYDRAULIC ACCUMULATOR Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
29 1329-001 Airframe PART #2318	NO. 3 HYDRAULIC RESERVOIR Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
29 1333-001 Airframe PART #1219	RELIEF/BLEED VALVE Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
29 1337-001 Airframe PART #2923	NO. 1 HEAT EXCHANGER Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
29 1337-002 Airframe PART #1342	NO. 2 HEAT EXCHANGER Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
29 1337-003 Airframe PART #2413	NO. 3 HEAT EXCHANGER Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
29 1349-001 Airframe PART #1008	NO. 1 CHECK IN LINE VALVE Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
29 1357-001 Airframe PART #505	MANIFOLD VALVE Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
29 14-00-201 Airframe INSPECTION 3000H #2069	FUNCTIONAL TEST OF THE RAM AIR TURBINE (RAT) HYDRAULIC FLUID-HEATING SYSTEM		04-MAR-2016 H: 1753.70 L: 622	H: 3000.00	H: 50.00	H: 4753.70	H: 297.90
29 1401-001 Airframe PART #2883	NO. 1 CHECK RESTRICTOR VALVE Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
29 1401-002 Airframe PART #1018	NO. 2 CHECK RESTRICTOR VALVE Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
29 1401-003 Airframe PART #2660	NO. 3 CHECK RESTRICTOR VALVE Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
29 1506-250 Airframe PART #5060	#2 HYDRAULIC TUBE Part Number GD478-1200-13	Serial Number N/A	11-SEP-2020 H: 3852.30 L: 1275				
	Notes PRESSURE FROM #2 AC PUMP TO MANIFOLD.						
29 30 Airframe PART #4777	NO. 3 HYDRAULIC SYSTEM ACCUMULATOR Part Number GX473-0100-7	Serial Number 60190-3690	23-NOV-2016 H: 2064.80 L: 722				
29 3101-001 Airframe PART #1040	NO. 1 PRESSURE TRANSDUCER Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
29 3101-002 Airframe PART #1878	NO. 2 PRESSURE TRANSDUCER Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
29 3101-003 Airframe PART #1693	NO. 3 PRESSURE TRANSDUCER Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
29 3105-001 Airframe PART #1595	1A PRESSURE SWITCH Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
29 3105-002 Airframe PART #2320	1B PRESSURE SWITCH Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
29 3105-003 Airframe PART #1871	2A PRESSURE SWITCH Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
29 3105-004 Airframe PART #798	2B PRESSURE SWITCH Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
29 3105-005 Airframe PART #1612	NO. 3A PRESSURE SWITCH Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
29 3105-006 Airframe PART #156	NO. 3B PRESSURE SWITCH Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
29 3301-001 Airframe PART #1752	NO. 1 TEMPERATURE TRANSDUCER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
29 3301-002 Airframe PART #68	NO. 2 TEMPERATURE TRANSDUCER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
29 3301-003 Airframe PART #2541	NO. 3 TEMPERATURE TRANSDUCER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
30 Airframe PART #4779	LEFT WING INBOARD LEADING EDGE ANTI ICE TEMPERATURE Part Number GG436-1003-5 Serial Number 1908						
30 11-09-202 Airframe INSPECTION 2250H #1968	OPERATIONAL TEST OF THE WING XBLEED SYSTEM	31-MAR-2020 H: 3741.10 L: 1233	H: 2250.00	H: 50.00		H: 5991.10	H: 1535.30





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
30 1101-001 Airframe PART #2552	LH MODULATING VALVE Part Number GG436-4001-13 Serial Number 01306	03-NOV-2016 H: 2040.70 L: 711					
	Notes RIMP UPGRADE PER SB 700-30-026						
30 1101-002 Airframe PART #1211	RH MODULATING VALVE Part Number GG436-4001-13 Serial Number 1507	02-MAY-2016 H: 1810.40 L: 647					
	Notes RIMP UPGRADE PER SB 700-30-026						
30 1105-001 Airframe PART #270	LEFT SLAT NO. 4 TEMPERATURE SENSOR Part Number GG436-4078-1 Serial Number 2952	31-AUG-2020 H: 3844.20 L: 1271					
30 1105-002 Airframe PART #1965	RIGHT SLAT NO. 4 TEMPERATURE SENSOR Part Number GG436-4078-1 Serial Number 1382	21-MAR-2010 H: 0.00					
30 1105-003 Airframe PART #2596	LH WAI TEMPERATURE SENSOR Part Number GG436-4003-5 Serial Number 1907	21-MAR-2010 H: 0.00					
30 1105-004 Airframe PART #181	RH WAI TEMPERATURE SENSOR Part Number GG436-4003-5 Serial Number 4034	23-NOV-2016 H: 2064.80 L: 722					
30 1109-001 Airframe PART #1996	WAI ISOLATION VALVE Part Number GG436-4004-7 Serial Number 1133	21-MAR-2010 H: 0.00					
30 12-05-102 Airframe PART #585	DISCARD THE WING ANTI-ICING TELESCOPIC- DUCT, LH SLAT NO. 1 TELESCOPIC, A/I SUPPLY LH DUCT Part Number GG468-4022-3 Serial Number 432	21-MAR-2010 H: 0.00	H: 15000.00			H: 15000.00	H: 10544.20





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
30 12-05-104 Airframe PART #1394	DISCARD THE WING ANTI-ICING TELESCOPIC- DUCT, RH SLAT NO. 1 TELESCOPIC, A/I SUPPLY RH DUCT Part Number: GG468-4022-4 Serial Number: 453	21-MAR-2010 H: 0.00	H: 15000.00			H: 15000.00	H: 10544.20
30 12-13-101 Airframe PART - Life Limited #2773	DISCARD THE WING ANTI-ICE LH FLEXIBLE JOINT Part Number: GG468-4025-1 Serial Number: 2282	15-APR-2021 H: 3992.00 L: 1324	H: 15000.00		M: 13 H: 0.00	H: 18992.00	H: 14536.20
30 12-13-101 Airframe PART - Life Limited #1186	DISCARD THE WING ANTI-ICE RH FLEXIBLE JOINT Part Number: GG468-4025-1 Serial Number: 1000	21-MAR-2010 H: 0.00	H: 15000.00		M: 0 H: 0.00 L: 0	H: 15000.00	H: 10544.20
30 1209-001 Airframe PART #485	NO. 1 COUPLING COVER Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
30 1209-002 Airframe PART #2637	NO. 2 COUPLING COVER Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
30 1209-003 Airframe PART #457	NO. 3 COUPLING COVER Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
30 1209-004 Airframe PART #2375	NO. 4 COUPLING COVER Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
30 1209-005 Airframe PART #1143	NO. 5 COUPLING COVER Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
30 1209-006 Airframe PART #2363	ANTI-ICE SUPPLY CENTER WING TO FUSE FAIRING DUCT Part Number: GG468-4033-3 Serial Number: 334	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
30 21-05-201 Airframe INSPECTION 3000H #1491	GENERAL VISUAL INSPECTION OF THE COWL ANTI-ICING-VALVE DUCTS	04-MAR-2016 H: 1753.70 L: 622	H: 3000.00	H: 50.00		H: 4753.70	H: 297.90
30 2101-001 Airframe PART #761	LH ENGINE NOSE COWL ANTI-ICE VALVE Part Number: 510-0020-7 Serial Number: D1726B	15-MAY-2020 H: 3751.60 L: 1237					
	Notes STUCK IN CLOSED POSITION AFTER SHUTDOWN.						
30 2101-002 Airframe PART #72	RH ENGINE NOSE COWL ANTI-ICE VALVE Part Number: 510-0020-7 Serial Number: D0396B	05-NOV-2015 H: 1611.50 L: 573					
30 3101-001 Airframe PART #299	NO. 1 HEATER/BRAKE TEMPERATURE MONITOR Part Number: GH569-0017-1 Serial Number: 998	21-MAR-2010 H: 0.00					
30 3101-002 Airframe PART #1406	NO. 2 HEATER/BRAKE TEMPERATURE MONITOR Part Number: GH569-0017-1 Serial Number: 999	21-MAR-2010 H: 0.00					
30 41-00-202 Airframe INSPECTION 750H/30M #319	FUNCTIONAL TEST OF THE WINDSHIELD RAIN-REPELLANT LAYER	08-FEB-2022 H: 4399.80 L: 1478	M: 12 H: 750.00	M: 3 H: 50.00		08-FEB-2023 H: 5149.80	M: 10 D: 23 H: 694.00
30 41-00-301 Airframe INSPECTION #590	DETAILED INSPECTION OF THE WINDSHIELD/SIDE WINDOW AERODYNAMIC SEAL	04-FEB-2021 H: 3992.00 L: 1324	M: 15 H: 750.00	M: 3 H: 50.00		31-MAY-2022 H: 4742.00	M: 2 D: 15 H: 286.20
30 4101-001 Airframe PART #169	LH WINDSHIELD TEMPERATURE CONTROLLER Part Number: GC584-1001-4 Serial Number: 0610	06-NOV-2021 H: 4337.30 L: 1452					
30 4101-002 Airframe PART #307	RH WINDSHIELD TEMPERATURE CONTROLLER Part Number: GC584-1001-4 Serial Number: 0170	15-MAY-2020 H: 3751.60 L: 1237					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
30 81-01-201 Airframe INSPECTION 1500H #2204	OPERATIONAL TEST OF THE ICE DETECTORS	08-FEB-2022 H: 4399.80 L: 1478	H: 1500.00	H: 50.00		H: 5899.80	H: 1444.00
Notes							
IT SHOULD BE COMPLETED WITHIN THE NEW TASK REPEAT INTERVAL OR 6 MONTHS FROM THE DATE OF INTRODUCTION TO THE MAINTENANCE PROGRAM BY THE OPERATOR WHICHEVER IS GREATER, THE EXCEPTION IS IF THIS RESCHEDULING WAS TO POSTPONE THE TASK BEYOND THE PRE-REVISION TASK ACCOMPLISHMENT DEADLINE.							
30 8101-001 Airframe PART #2736	LH ICE DETECTOR Part Number GG436-4006-9 Serial Number 00404	14-DEC-2021 H: 4388.60 L: 1472					
30 8101-002 Airframe PART #2478	RH ICE DETECTOR Part Number GG436-4006-9 Serial Number 22706	15-JUL-2020 H: 3806.80 L: 1260					
30 8101-003 Airframe PART #5128	L/H #4 PICCOLO DUCT Part Number GG468-4007-3 Serial Number 1152	08-APR-2021 H: 3992.00 L: 1324					
30 8101-003 Airframe PART #5131	R/H #4 PICCOLO DUCT Part Number GG468-4007-4 Serial Number 1165	08-APR-2021 H: 3992.00 L: 1324					
31 2101-001 Airframe PART #2163	LH DIGITAL CLOCK Part Number APE4190-030 Serial Number 644	13-FEB-2018 H: 2590.30 L: 900					
31 2101-002 Airframe PART #1309	RH DIGITAL CLOCK Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
31 31-00-201 Airframe INSPECTION 4500H, FDR #962	OPERATIONAL TEST OF THE FLIGHT DATA RECORDER (CONTROL COLUMN AND RUDDER PEDAL PARAMETERS) Part Number 980-4700-041 Serial Number SSFDR- 06307 Work Order Number FLL BAS 9385 Scheduled 19-Mar- 2022 Man Hours 0.00	11-FEB-2011 H: 18.00 L: 8	H: 4500.00	H: 50.00		H: 4568.00	H: 112.20





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
31 31-00-203 Airframe INSPECTION #1672	FUNCTIONAL TEST OF THE FLIGHT DATA RECORDER (FDR) FORCE SENSORS (POST SB 700-31-020)	21-MAR-2010 H: 0.00		M: 3			
	Notes SB700-31-020 NOT INSTALLED						
31 31-09-201 Airframe INSPECTION 30M #2942	OPERATIONAL TEST FDR (ULB) UNDERWATER LOCATOR BEACON	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
31 31-09-202 Airframe PART - Expiration #3016	DISCARD FDR (ULB) UNDERWATER LOCATOR BEACON BATTERY (31-31-09-202)	11-SEP-2020 H: 3852.30 L: 1275	M: 72			30-APR-2026	M: 49 D: 14
	Part Number DK120	Serial Number NT51872					
	Notes EXPIRATION DATE OF S/N NT51872, 1 MAY 2026.						
31 3101-001 Airframe PART #65	(FDR) FLIGHT DATA RECORDER	01-MAY-2015 H: 1411.10 L: 501					
	Part Number 980-4700-041	Serial Number SSFDR-06307					
31 3105-001 Airframe PART #230	ACCELEROMETER	21-MAR-2010 H: 0.00					
	Part Number 971-4193-001	Serial Number 12696					
31 33-00-301 Airframe INSPECTION #4739	DOWNLOAD OF THE QUICK ACCESS RECORDER (POST SB 700-31-026)	02-SEP-2021 H: 4258.30 L: 1423	H: 300.00			H: 4558.30	H: 102.50
	Reference Number AMM 31-33-00-970-801						
31 3301-701 Airframe PART #1373	QUICK ACCESS RECORDER	15-FEB-2011 H: 25.00 L: 11					
	Part Number 804-0105	Serial Number 16859					
31 40-00-301 Airframe PART #1628	NO. 3 INTEGRATED AVIONICS COMPUTER BATTERY	09-MAR-2022 H: 4455.80 L: 1496	M: 24			09-MAR-2024	M: 23 D: 22
	Part Number 7014664-902	Serial Number NOT APPLICABLE					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
31 41-00-301 Airframe PART #229	NO. 1 INTEGRATED AVIONICS COMPUTER BATTERY Part Number: 7014664-902 Serial Number: NOT APPLICABLE	09-MAR-2022 H: 4455.80 L: 1496	M: 24			09-MAR-2024	M: 23 D: 22
31 41-00-301 Airframe PART #3009	NO. 2 INTEGRATED AVIONICS COMPUTER BATTERY Part Number: 7014664-902 Serial Number: NOT APPLICABLE	09-MAR-2022 H: 4455.80 L: 1495	M: 24			09-MAR-2024	M: 23 D: 22
	Notes BATTERY MANF DATE 02/12/2022. EXPIRES 12/31/29.						
31 4101-001 Airframe PART #1518	NO.1 INTEGRATED AVIONICS COMPUTER Part Number: 7017300-61013 Serial Number: 09111843	18-JUN-2020 H: 3790.00 L: 1256					
	Notes DU1 AND DU2 AND FMS CDU OCCATIONALLY BLANKING OUT.						
31 4101-002 Airframe PART #1347	NO. 2 INTEGRATED AVIONICS COMPUTER Part Number: 7017300-61013 Serial Number: 0911837	23-FEB-2019 H: 3174.90 L: 1070					
	Notes C/W by BAS Tucson.... Worked with Tee and Louis						
31 4101-003 Airframe PART #2988	NO. 3 INTEGRATED AVIONICS COMPUTER Part Number: 7017300-61013 Serial Number: 09111834	18-JUN-2020 H: 3790.00 L: 1256					
	Notes DU1 AND DU2 AND FMS CDU OCCATIONALLY BLANK OUT.						
31 4105-001 Airframe PART #1863	NO. 1 CONFIGURATION IAC MODULE Part Number: PN Serial Number: SN- UNKNOWN	21-MAR-2010 H: 0.00					
31 4105-002 Airframe PART #1438	NO. 2 CONFIGURATION IAC MODULE Part Number: PN Serial Number: SN- UNKNOWN	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
31 4105-003 Airframe PART #565	NO. 3 CONFIGURATION IAC MODULE Part Number PN	21-MAR-2010 H: 0.00					
	Serial Number SN- UNKNOWN						
31 4201-001 Airframe PART #568	NO. 1 DATA ACQUISITION (DAU) UNIT Part Number 10604B03M09	22-DEC-2018 H: 3049.60 L: 1040					
	Serial Number 03091131						
	Notes SWAPPED #1 AND #3 DAU'S						
31 4201-002 Airframe PART #1391	NO. 2 DATA ACQUISITION (DAU) UNIT Part Number 10604B03M09	21-MAR-2010 H: 0.00					
	Serial Number 09112137						
31 4201-003 Airframe PART #896	NO. 3 DATA ACQUISITION (DAU) UNIT Part Number 10604B03M09	22-DEC-2018 H: 3049.60 L: 1040					
	Serial Number 03091132						
	Notes SWAPPED #3 AND #1 DAU'S						
31 4201-004 Airframe PART #2446	NO. 4 DATA ACQUISITION (DAU) UNIT Part Number 10604B03M09	21-MAR-2010 H: 0.00					
	Serial Number 09112139						
31 4301-001 Airframe PART #56	FWD POWER LAMP DRIVER Part Number LT45D	21-MAR-2010 H: 0.00					
	Serial Number 2485						
31 4301-002 Airframe PART #1881	AFT POWER LAMP DRIVER Part Number PN	21-MAR-2010 H: 0.00					
	Serial Number SN- UNKNOWN						
31 4301-003 Airframe PART #1257	R/H POWER LAMP DRIVER Part Number LT45D	21-MAR-2010 H: 0.00					
	Serial Number 2474						
31 4401-001 Airframe PART #937	LH ISOLATION COUPLER Part Number 5008500-002	21-MAR-2010 H: 0.00					
	Serial Number 14872						





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
31 4401-002 Airframe PART #2398	RH ISOLATION COUPLER Part Number 5008500-002 Serial Number 14901	21-MAR-2010 H: 0.00					
31 52-01-001 Airframe PART #4894	MASTER CAUTION RELAY Part Number M83536/6-022M Serial Number NSN	12-DEC-2018 H: 3033.70 L: 1035					
31 61-00-201 Airframe INSPECTION 30M #2105	OPERATIONAL TEST OF THE EICAS DISPLAY REVERSION	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
31 61-00-202 Airframe INSPECTION 30M #1646	OPERATIONAL TEST OF THE PRIMARY FLIGHT DISPLAY REVERSION	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
31 61-00-203 Airframe INSPECTION 30M #1496	OPERATIONAL TEST OF THE IRS REVERSION	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
31 61-00-204 Airframe INSPECTION 30M #1577	OPERATIONAL TEST OF THE ADC REVERSION	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
	Notes NO DEFECTS NOTED						
31 6101-001 Airframe PART #3025	PILOT PFD (DU-875) DISPLAY UNIT Part Number K9321060A13 Serial Number 1890374632	11-SEP-2020 H: 3852.30 L: 1275					
31 6101-002 Airframe PART #2621	PILOT MFD (DU-875) DISPLAY UNIT Part Number K9321060A13 Serial Number 2890005554	29-JAN-2018 H: 2586.20 L: 898					
31 6101-003 Airframe PART #350	PILOT EICAS (DU-875) DISPLAY UNIT Part Number K9321060A13 Serial Number 2890005455	29-JAN-2018 H: 2586.20 L: 898					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
31 6101-004 Airframe PART #2967	COPILOT EICAS (DU-875) DISPLAY UNIT Part Number K9321060A13 Serial Number 2890028921	11-SEP-2020 H: 3852.30 L: 1275					
	Notes DU # 4						
31 6101-005 Airframe PART #1868	COPILOT MFD (DU-875) DISPLAY UNIT Part Number K9321060A13 Serial Number 2890003974	29-JAN-2018 H: 2586.20 L: 898					
31 6101-006 Airframe PART #2801	COPILOT PFD (DU-875) DISPLAY UNIT Part Number K9321060A13 Serial Number 2890003975	29-JAN-2018 H: 2586.20 L: 898					
31 6105-001 Airframe PART #690	LH PANEL- PFD CONTROLLER CONTROL Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
31 6105-002 Airframe PART #1417	RH PANEL- PFD CONTROLLER CONTROL Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
31 6109-001 Airframe PART #1302	LH MFD CONTROLLER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
31 6109-002 Airframe PART #1145	RH MFD CONTROLLER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
31 6113-001 Airframe PART #553	EICAS (EC-900) CONTROLLER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
31 6117-001 Airframe PART #1201	PANEL - REVERSION CONTROLLER CONTROL Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 Airframe PART #5090	L/H SIDE STAY ACTUATOR ROD END CAP Part Number: 21511-1 Serial Number: 01339	23-FEB-2021 H: 3992.00 L: 1324					
32 Airframe PART #5092	L/H SIDE STAY ACTURATOR LOCK INDICATOR RING Part Number: 21524-1 Serial Number: 1901/04LY	23-FEB-2021 H: 3992.00 L: 1324					
32 Airframe PART #5089	R/H SIDE STAY ACTUATOR ROD END CAP Part Number: 21511-2 Serial Number: 097-1658	16-APR-2021 H: 3992.00 L: 1324					
	Notes CORRECTED PART NUMBER						
32 Airframe PART #5091	R/H SIDE STAY ACTURATOR LOCK INDICATOR RING Part Number: 21524-1 Serial Number: 1902/13LY	16-APR-2021 H: 3992.00 L: 1324					
32 00-00-301 Airframe INSPECTION #4621	CLEANING OF THE LANDING GEAR AND UNDERCARRIAGE AREA Notes REQUIRED AFTER OPERATION IN AIRPORTS THAT USE ACETATE-BASED OR SALT-BASED RUNWAY DE-ICING FLUID.						
32 10-00-201 Airframe INSPECTION #2593	RESTORATION OF THE LEFT MAIN LANDING GEAR	21-MAR-2010 H: 0.00	M: 240	M: 3		21-MAR-2030	M: 96 D: 5
32 10-00-201 Airframe INSPECTION #1553	RESTORATION OF THE RIGHT MAIN LANDING GEAR	21-MAR-2010 H: 0.00	M: 240	M: 3		21-MAR-2030	M: 96 D: 5
32 10-00-202 Airframe INSPECTION 120M #2307	DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) PINTLE PIN	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 10-00-203 Airframe INSPECTION 120M #1434	DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) (ATTACHMENT PINS AND LUGS)	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
32 10-00-204 Airframe INSPECTION 240M/120M #737	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) SHOCK-STRUT ASSEMBLY (INTERNAL)	21-MAR-2010 H: 0.00	M: 240	M: 3		21-MAR-2030	M: 96 D: 5
32 10-00-206 Airframe INSPECTION 240M/120M #988	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) PINTLE PINS	21-MAR-2010 H: 0.00	M: 240	M: 3		21-MAR-2030	M: 96 D: 5
32 10-00-207 Airframe INSPECTION 240M/120M #760	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) (ATTACHMENT PINS AND LUGS)	21-MAR-2010 H: 0.00	M: 240	M: 3		21-MAR-2030	M: 96 D: 5
32 10-00-208 Airframe INSPECTION 120M #189	DETAILED INSPECTION OF THE TRAILING ARM/AXLE ASSEMBLY	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
32 10-00-209 Airframe INSPECTION 240M/120M #2997	SPECIAL DETAILED INSPECTION OF THE TRAILING ARM/AXLE ASSEMBLY	21-MAR-2010 H: 0.00	M: 240	M: 3		21-MAR-2030	M: 96 D: 5
32 10-00-210 Airframe INSPECTION 120M #733	DETAILED INSPECTION OF THE SHOCK STRUT ASSEMBLY (INTERNAL)	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
32 10-00-211 Airframe INSPECTION 120M #1625	DETAILED INSPECTION OF THE SIDE BRACE ACTUATOR (INTERNAL)	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
32 10-00-212 Airframe INSPECTION 240M/120M #1627	SPECIAL DETAILED INSPECTION OF THE SIDE BRACE ACTUATOR (INTERNAL)	21-MAR-2010 H: 0.00	M: 240	M: 3		21-MAR-2030	M: 96 D: 5





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 10-00-213 Airframe INSPECTION 120M #2556	DETAILED INSPECTION OF THE RETRACTION ACTUATOR (INTERNAL)	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
32 10-00-214 Airframe INSPECTION 240M/120M #1051	SPECIAL DETAILED INSPECTION OF THE RETRACTION ACTUATOR (INTERNAL)	21-MAR-2010 H: 0.00	M: 240	M: 3		21-MAR-2030	M: 96 D: 5
32 11-00-201 Airframe INSPECTION 250 H #1785	LUBRICATION OF THE MAIN LANDING GEAR (MLG) AND COMPONENTS	08-FEB-2022 H: 4399.80 L: 1478	H: 250.00	H: 25.00		H: 4649.80	H: 194.00
32 11-01-102 Airframe PART #952	DISCARD THE LEFT MAIN LANDING GEAR CONNECTING SHOCK STRUT/MAIN FITTING PIN (LH MLG UPPER PIN) Reference Number Part Number Serial Number AMM 32-11-01-961 21274-1 09CPS0905 -802	21-MAR-2010 H: 0.00	L: 15000			L: 15000	L: 13505
32 11-01-102 Airframe PART #215	DISCARD THE RIGHT MAIN LANDING GEAR CONNECTING SHOCK STRUT/MAIN FITTING PIN (RH MLG UPPER PIN) Reference Number Part Number Serial Number AMM 32-11-01-961 21274-1 09CPS0908 -802	21-MAR-2010 H: 0.00	L: 15000			L: 15000	L: 13505
32 11-01-103 Airframe PART #2825	DISCARD THE LEFT MAIN LANDING GEAR (MLG) SHOCK STRUT CYLINDER Reference Number Part Number Serial Number AMM 32-11-01-961 21209-5 08GGC001 -803 53	21-MAR-2010 H: 0.00	L: 15000			L: 15000	L: 13505
32 11-01-103 Airframe PART #254	DISCARD THE RIGHT MAIN LANDING GEAR (MLG) SHOCK STRUT CYLINDER Reference Number Part Number Serial Number AMM 32-11-01-961 21209-5 08GGC001 -803 79	21-MAR-2010 H: 0.00	L: 15000			L: 15000	L: 13505
32 11-01-104 Airframe PART #2860	DISCARD THE LEFT MAIN LANDING GEAR (MLG) SHOCK STRUT PISTON Reference Number Part Number Serial Number AMM 32-11-01-961 21218-5 08GGC001 -804 82	21-MAR-2010 H: 0.00	L: 15000			L: 15000	L: 13505
32 11-01-104 Airframe PART #2895	DISCARD THE RIGHT MAIN LANDING GEAR (MLG) SHOCK STRUT PISTON Reference Number Part Number Serial Number AMM 32-11-01-961 21218-5 08GGC001 -804 83	21-MAR-2010 H: 0.00	L: 15000			L: 15000	L: 13505



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 11-01-105 Airframe PART #1228	DISCARD THE LEFT MAIN LANDING GEAR (MLG) CONNECTING SHOCK STRUT/TRAILING ARM PIN Part Number 21194-1 Serial Number 08EXC1072	21-MAR-2010 H: 0.00	L: 10999			L: 10999	L: 9504
32 11-01-105 Airframe PART #2695	DISCARD THE RIGHT MAIN LANDING GEAR (MLG) CONNECTING SHOCK STRUT/TRAILING ARM PIN Part Number 21194-1 Serial Number 08EXC1071	21-MAR-2010 H: 0.00	L: 10999			L: 10999	L: 9504
32 11-01-201 Airframe INSPECTION 750H/30M #513	DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) SHOCK STRUT EXTENSION	08-FEB-2022 H: 4399.80 L: 1478	H: 750.00	H: 50.00		H: 5149.80	H: 694.00
32 11-09-101 Airframe PART #519	DISCARD THE LEFT MAIN LANDING GEAR (MLG) TRAILING ARM/AXLE Part Number 21410-107 Serial Number H0707	21-MAR-2010 H: 0.00	L: 15000			L: 15000	L: 13505
32 11-09-101 Airframe PART #325	DISCARD THE RIGHT MAIN LANDING GEAR (MLG) TRAILING ARM/AXLE Part Number 21410-107 Serial Number H0720	21-MAR-2010 H: 0.00	L: 15000			L: 15000	L: 13505
32 11-09-102 Airframe PART #317	DISCARD THE LEFT MAIN LANDING GEAR (MLG) PIVOT PIN (LH MLG HINGE PIN) Part Number 21114-1 Serial Number 09EXC1760	21-MAR-2010 H: 0.00	L: 15000			L: 15000	L: 13505
32 11-09-102 Airframe PART #1543	DISCARD THE RIGHT MAIN LANDING GEAR (MLG) PIVOT PIN (RH MLG HINGE PIN) Part Number 21114-1 Serial Number 09EXC1759	21-MAR-2010 H: 0.00	L: 15000			L: 15000	L: 13505
32 11-17-101 Airframe PART #1239	DISCARD THE LEFT MAIN LANDING GEAR (MLG) SIDE-STAY LOWER-PIN (LH MLG SIDE STAY (LOWER) PIN) Part Number 21113-1 Serial Number 09EXC1774	21-MAR-2010 H: 0.00	L: 11168			L: 11168	L: 9673
32 11-17-101 Airframe PART #1526	DISCARD THE RIGHT MAIN LANDING GEAR (MLG) SIDE-STAY LOWER-PIN (RH MLG SIDE STAY (LOWER) PIN) Part Number 21113-1 Serial Number 09EXC1771	21-MAR-2010 H: 0.00	L: 11168			L: 11168	L: 9673





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 11-17-102 Airframe PART - Life Limited #302	DISCARD THE LEFT MAIN LANDING GEAR (MLG) SIDE BRACE ROD END Part Number 21510-3 Serial Number 09-23	21-MAR-2010 H: 0.00	L: 8683		M: 0 H: 0.00 L: 0	L: 8683	L: 7188
32 11-17-102 Airframe PART - Life Limited #2308	DISCARD THE RIGHT MAIN LANDING GEAR (MLG) SIDE BRACE ROD END Part Number 21510-3 Serial Number 11-12	16-APR-2021 H: 3992.00 L: 1324	L: 8683		H: 26.90 L: 15	L: 9992	L: 8497
32 11-17-103 Airframe PART - Life Limited #1967	DISCARD THE LEFT MAIN LANDING GEAR (MLG) SIDE BRACE PISTON Part Number 21512-1 Serial Number 834	21-MAR-2010 H: 0.00	L: 8683		M: 0 H: 0.00 L: 0	L: 8683	L: 7188
32 11-17-103 Airframe PART - Life Limited #1594	DISCARD THE RIGHT MAIN LANDING GEAR (MLG) SIDE BRACE PISTON Part Number 21512-1 Serial Number 975	16-APR-2021 H: 3992.00 L: 1324	L: 8683		H: 26.90 L: 15	L: 9992	L: 8497
32 11-17-103 Airframe PART - Life Limited #5137	RH ACTUATOR ASSEMBLY, MLG SIDESTAY LOCK PISTON Part Number 21531-1 Serial Number 947	15-APR-2010 H: 3992.00 L: 1324	L: 8683		M: 0 H: 0.00 L: 0	L: 10007	L: 8512
32 11-17-103 Airframe PART - Life Limited #5133	RH ACTUATOR ASSEMBLY, MLG SIDESTAY LOCK SEGMENT #1 Part Number 21513-1 Serial Number 3895	15-APR-2010 H: 3992.00 L: 1324	L: 8683		M: 0 H: 0.00 L: 0	L: 10007	L: 8512
32 11-17-103 Airframe PART - Life Limited #5134	RH ACTUATOR ASSEMBLY, MLG SIDESTAY LOCK SEGMENT #2 Part Number 21513-1 Serial Number 3896	15-APR-2010 H: 3992.00 L: 1324	L: 8683		M: 0 H: 0.00 L: 0	L: 10007	L: 8512
32 11-17-103 Airframe PART - Life Limited #5136	RH ACTUATOR ASSEMBLY, MLG SIDESTAY LOCK SEGMENT #3 Part Number 21513-1 Serial Number 3897	15-APR-2010 H: 3992.00 L: 1324	L: 8683		M: 0 H: 0.00 L: 0	L: 10007	L: 8512
32 11-17-103 Airframe PART - Life Limited #5135	RH ACTUATOR ASSEMBLY, MLG SIDESTAY LOCK SEGMENT #4 Part Number 21513-1 Serial Number 3898	15-APR-2010 H: 3992.00 L: 1324	L: 8683		M: 0 H: 0.00 L: 0	L: 10007	L: 8512
32 11-17-104 Airframe PART - Life Limited #2053	DISCARD THE LEFT MAIN LANDING GEAR (MLG) SIDE BRACE CYLINDER Part Number 21521-1 Serial Number DAY 1081	21-MAR-2010 H: 0.00	L: 8683		M: 0 H: 0.00 L: 0	L: 8683	L: 7188



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 11-17-104 Airframe PART - Life Limited #3040	DISCARD THE RIGHT MAIN LANDING GEAR (MLG) SIDE BRACE CYLINDER Part Number 21521-1 Serial Number DAY 1260	16-APR-2021 H: 3992.00 L: 1324	L: 8683		H: 26.90 L: 15	L: 9992	L: 8497
32 11-29-101 Airframe PART #2551	DISCARD THE LEFT MAIN LANDING GEAR MAIN FITTING Part Number 21310-105 Serial Number 09WHM054 7	21-MAR-2010 H: 0.00	L: 15000			L: 15000	L: 13505
32 11-29-101 Airframe PART #2568	DISCARD THE RIGHT MAIN LANDING GEAR MAIN FITTING Part Number 21310-106 Serial Number 09WHM054 4	21-MAR-2010 H: 0.00	L: 15000			L: 15000	L: 13505
32 11-29-102 Airframe PART #2100	DISCARD THE LEFT MAIN LANDING GEAR PINTLE PIN Part Number 21112-101 Serial Number 08EXC1753	21-MAR-2010 H: 0.00	L: 11271			L: 11271	L: 9776
32 11-29-102 Airframe PART #2902	DISCARD THE RIGHT MAIN LANDING GEAR PINTLE PIN Part Number 21112-102 Serial Number 08EXC1754	21-MAR-2010 H: 0.00	L: 11271			L: 11271	L: 9776
32 11-29-103 Airframe PART #1744	DISCARD THE LEFT MAIN LANDING GEAR (MLG) PINTLE PIN/CROSS PIN Part Number 21116-1 Serial Number 09EXC0945	21-MAR-2010 H: 0.00	L: 15000			L: 15000	L: 13505
32 11-29-103 Airframe PART #1603	DISCARD THE RIGHT MAIN LANDING GEAR (MLG) PINTLE PIN/CROSS PIN Part Number 21116-1 Serial Number 09EXC0944	21-MAR-2010 H: 0.00	L: 15000			L: 15000	L: 13505
32 1100-005 Airframe PART #2238	LH MLG ASSEMBLY GEAR Part Number GW318-1001-5 Serial Number 09MDT0714	21-MAR-2010 H: 0.00					
32 1100-006 Airframe PART #2634	RH MLG ASSEMBLY GEAR Part Number GW318-1001-6 Serial Number 09MDT0713	21-MAR-2010 H: 0.00					
32 1100-701 Airframe PART #1735	LH MLG DOOR HINGE PIN Part Number 21123-1 Serial Number 08EXC0906	21-MAR-2010 H: 0.00					



Maintenance Items

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Page 139 of 653



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 1100-702 Airframe PART #1004	RH MLG DOOR HINGE PIN Part Number 21123-1	Serial Number 08EXC0904	21-MAR-2010 H: 0.00				
32 1100-703 Airframe PART #2973	LH MLG SIDE STAY NUT Part Number 21129-5	Serial Number 09CPS0937	21-MAR-2010 H: 0.00				
32 1100-704 Airframe PART #2592	RH MLG SIDE STAY NUT Part Number 21129-5	Serial Number 09CPS0941	21-MAR-2010 H: 0.00				
32 1101-001 Airframe PART #1147	LH MLG SHOCK STRUT Part Number 21200-113	Serial Number 09MDT0965	21-MAR-2010 H: 0.00				
32 1101-002 Airframe PART #927	RH MLG SHOCK STRUT Part Number 21200-113	Serial Number 09MDT0966	21-MAR-2010 H: 0.00				
32 1101-003 Airframe PART #1800	LEFT HAND MLG SHOCK STRUT CYLINDER Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
32 1101-004 Airframe PART #1949	RIGHT HAND MLG SHOCK STRUT CYLINDER Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
32 1113-001 Airframe PART #2309	LOB MLG HARNESS ASSY Part Number 21802-105	Serial Number 398	21-MAR-2010 H: 0.00				
32 1113-002 Airframe PART #1300	LIB MLG HARNESS ASSY Part Number 21801-105	Serial Number 396	21-MAR-2010 H: 0.00				
32 1113-003 Airframe PART #2869	RIB MLG HARNESS ASSY Part Number 21803-105	Serial Number 403	21-MAR-2010 H: 0.00				



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 1113-004 Airframe PART #2916	ROB MLG HARNESS ASSY Part Number 21804-105	21-MAR-2010 H: 0.00	Serial Number 405				
32 1117-001 Airframe PART #2796	LH MLG SIDE BRACE ACTUATOR Part Number GW312-2001-7	21-MAR-2010 H: 0.00	Serial Number 800				
32 1117-002 Airframe PART #2680	RH MLG SIDE BRACE ACTUATOR Part Number GW312-2001-9	15-APR-2021 H: 3992.00 L: 1324	Serial Number 936				
32 1117-009 Airframe PART #2405	LH MLG SIDE-STAY UPPER PIN ASSY Part Number GM227-1725-23	21-MAR-2010 H: 0.00	Serial Number 76				
32 1117-010 Airframe PART #2555	RH MLG SIDE-STAY UPPER PIN ASSY Part Number GM227-1725-23	21-MAR-2010 H: 0.00	Serial Number 60				
32 12-00-201 Airframe INSPECTION 250 H #105	LUBRICATION OF THE MAIN LANDING GEAR (MLG) DOORS	08-FEB-2022 H: 4399.80 L: 1478		H: 250.00	H: 25.00	H: 4649.80	H: 194.00
32 12-00-202 Airframe INSPECTION 30M #342	LUBRICATION OF THE MAIN LANDING GEAR (MLG) DOOR ACTUATOR	19-APR-2021 H: 3992.00 L: 1324		M: 30	M: 3	19-OCT-2023	M: 19 D: 3
32 1201-001 Airframe PART #2848	LH OUTBOARD MLG DOOR Part Number GM329-1011-1	21-MAR-2010 H: 0.00	Serial Number 397				
32 1201-002 Airframe PART #1719	RH OUTBOARD MLG DOOR Part Number GM329-1011-2	21-MAR-2010 H: 0.00	Serial Number 393	Work Order Number FLL BAS 9385	Scheduled 19-Mar- 2022	Man Hours 0.00	





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 1205-001 Airframe PART #1346	LH INBOARD MLG DOOR Part Number GS328-0001-3 Serial Number 11164	21-MAR-2010 H: 0.00					
32 1205-002 Airframe PART #2799	RH INBOARD MLG DOOR Part Number GS328-0001-4 Serial Number 11164	21-MAR-2010 H: 0.00					
32 20-00-201 Airframe INSPECTION 240M/120M #184	RESTORATION OF THE NOSE LANDING GEAR	21-MAR-2010 H: 0.00	M: 240	M: 3		21-MAR-2030	M: 96 D: 5
32 20-00-204 Airframe INSPECTION 120M #2941	DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) PINTLE PINS	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
32 20-00-205 Airframe INSPECTION 240M/120M #2052	SPECIAL DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) PINTLE PINS	21-MAR-2010 H: 0.00	M: 240	M: 3		21-MAR-2030	M: 96 D: 5
32 20-00-206 Airframe INSPECTION 120M #81	DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) (ATTACHMENT PINS AND LUGS)	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
32 20-00-207 Airframe INSPECTION 240M/120M #2392	SPECIAL DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) (ATTACHMENT PINS AND LUGS)	21-MAR-2010 H: 0.00	M: 240	M: 3		21-MAR-2030	M: 96 D: 5
32 20-00-208 Airframe INSPECTION 120M #1676	DETAILED INSPECTION OF THE SLIDING TUBE (INTERNAL), STEERING AND AXLE ASSEMBLY	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
32 20-00-209 Airframe INSPECTION 240M/120M #1326	SPECIAL DETAILED INSPECTION OF THE SLIDING TUBE (INTERNAL), STEERING AND AXLE ASSEMBLY	21-MAR-2010 H: 0.00	M: 240	M: 3		21-MAR-2030	M: 96 D: 5





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 20-00-210 Airframe INSPECTION 120M #170	DETAILED INSPECTION OF THE NOSE LANDING GEAR RETRACTION ACTUATOR (INTERNAL)	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
32 20-00-211 Airframe INSPECTION 240M/120M #1376	SPECIAL DETAILED INSPECTION OF THE NOSE LANDING GEAR RETRACTION ACTUATOR (INTERNAL)	21-MAR-2010 H: 0.00	M: 240	M: 3		21-MAR-2030	M: 96 D: 5
32 21-00-201 Airframe INSPECTION 250 H #741	LUBRICATION OF THE NOSE LANDING GEAR (NLG) AND COMPONENTS	08-FEB-2022 H: 4399.80 L: 1478	H: 250.00	H: 25.00		H: 4649.80	H: 194.00
32 21-01-101 Airframe PART - Life Limited #442	DISCARD THE NOSE LANDING GEAR (NLG) SHOCK STRUT AXLE, PART NO. 1286-0201/-0203/-0204 Reference Number Part Number Serial Number 32-21-17-961-801 1286-0203 1249032/00 5	05-OCT-2016 H: 2002.10 L: 697	L: 15000		H: 1899.20 L: 668	L: 15029	L: 13534
32 21-01-102 Airframe PART - Life Limited #1468	DISCARD THE NOSE LANDING GEAR (NLG) SHOCK STRUT PISTON (SLIDING TUBE) Reference Number Part Number Serial Number AMM 32-21-01-961 1286-0077 1223003/00 -803 1	05-OCT-2016 H: 2002.10 L: 697	L: 15000		H: 1899.20 L: 668	L: 15029	L: 13534
32 21-01-102 Airframe PART - Life Limited SSP #5099	REMOVE AND REPLACE NLG SHOCK STRUT PISTON Part Number Serial Number 1286-0077 1333539/00 1	23-FEB-2021 H: 3992.00 L: 1324	L: 15000		H: 1075.50 L: 338	L: 15986	L: 14491
32 21-01-103 Airframe PART - Life Limited #1464	DISCARD THE NOSE LANDING GEAR (NLG) SHOCK STRUT MAIN FITTING, PART NO. 1286-0101/-0109 Reference Number Part Number Serial Number 32-21-01-961-802 1286-0101 438	05-OCT-2016 H: 2002.10 L: 697	L: 11295		H: 1899.20 L: 668	L: 11324	L: 9829
32 21-01-201 Airframe INSPECTION 750H/30M #524	DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) SHOCK STRUT EXTENSION	08-FEB-2022 H: 4399.80 L: 1478	H: 750.00	H: 50.00		H: 5149.80	H: 694.00
32 21-05-101 Airframe PART #2705	DISCARD THE NOSE LANDING GEAR UPPER DRAG BRACE Reference Number Part Number Serial Number AMM 32-21-05-961 22511-101 08ALT0073 -805	21-MAR-2010 H: 0.00	L: 12540			L: 12540	L: 11045



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 21-05-102 Airframe PART #1914	DISCARD THE NOSE LANDING GEAR LOWER DRAG BRACE Part Number: 22516-103 Serial Number: 08ALT0084	21-MAR-2010 H: 0.00	L: 11520			L: 11520	L: 10025
32 21-05-105 Airframe PART #1636	DISCARD THE NOSE LANDING GEAR APEX DRAG BRACE PIN Part Number: 22530-1 Serial Number: 08EXC0419	21-MAR-2010 H: 0.00	L: 11190			L: 11190	L: 9695
32 21-05-106 Airframe PART #1344	DISCARD THE LEFT NOSE LANDING GEAR DRAG BRACE TRUNNION PIN Part Number: 22534-1 Serial Number: 09CPS0956	21-MAR-2010 H: 0.00	L: 11220			L: 11220	L: 9725
32 21-05-106 Airframe PART #774	DISCARD THE RIGHT NOSE LANDING GEAR DRAG BRACE TRUNNION PIN Part Number: 22534-1 Serial Number: 09CPS0958	21-MAR-2010 H: 0.00	L: 11220			L: 11220	L: 9725
32 2100-702 Airframe PART #1558	NLG TORQUE LINK PIN Part Number: 1286-0003 Serial Number: 1243711/001	21-MAR-2010 H: 0.00					
32 2100-703 Airframe PART #799	NLG TORQUE LINK PIN Part Number: 1286-0003 Serial Number: 1229560/003	21-MAR-2010 H: 0.00					
32 2100-704 Airframe PART #971	NLG BOLT Part Number: 1286-0009 Serial Number: 1265207/003	21-MAR-2010 H: 0.00					
32 2100-705 Airframe PART #1476	NLG SLEEVE - MANIF BOLT Part Number: 1286-0033 Serial Number: 1265480/012	21-MAR-2010 H: 0.00					
32 2100-706 Airframe PART #338	NLG STEERING SLEEVE Part Number: 1286-0506 Serial Number: 429	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 2100-707 Airframe PART #378	NLG STEERING COLLAR Part Number 1286-0605 Serial Number 1263209/00 2	21-MAR-2010 H: 0.00					
32 2100-708 Airframe PART #2888	NLG STEERING PLATE Part Number 1286-0705 Serial Number 464	21-MAR-2010 H: 0.00					
32 2100-709 Airframe PART #2160	NLG TORQUE LINK Part Number 1286-2401 Serial Number 1269491/00 5	21-MAR-2010 H: 0.00					
32 2100-710 Airframe PART #2047	NLG TORQUE LINK Part Number 1286-2401 Serial Number 1269491/00 1	21-MAR-2010 H: 0.00					
32 2101-001 Airframe PART #547	NLG DRAG BRACE Part Number 22500-105 Serial Number 09MDT0497	21-MAR-2010 H: 0.00					
32 2101-005 Airframe PART #944	NOSE LANDING GEAR (NLG) SHOCK STRUT RETRACTION ACTUATOR BOLT Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 2101-006 Airframe PART #2249	NOSE LANDING GEAR (NLG) SHOCK STRUT STEERING ACTUATOR BOLT Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 2102-001 Airframe PART #1436	NLG ASSY GEAR Part Number GW318-2000-1 Serial Number 09MDT0490	21-MAR-2010 H: 0.00					
32 2103-001 Airframe PART #1688	NOSE LANDING GEAR STRUT Part Number 1286A0000-02 Serial Number 00535	05-OCT-2016 H: 2002.10 L: 697					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 2105-001 Airframe PART #450	DOWNLOCK NLG ACTUATOR Part Number: 22570-101 Serial Number: 09MDT0735	21-MAR-2010 H: 0.00					
32 2105-002 Airframe PART #2190	NLG SHOCK STRUT Part Number: 22175-109 Serial Number: 00535	05-OCT-2016 H: 2002.10 L: 697					
32 2105-003 Airframe PART #1925	NOSE LANDING GEAR (NLG) DRAG BRACE FORWARD STABILIZER LINK Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
32 2105-004 Airframe PART #2904	NOSE LANDING GEAR (NLG) DRAG BRACE AFT STABILIZER LINK Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
32 2107-005 Airframe PART #1395	NLG LOWER PIN Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
32 2107-007 Airframe PART #520	NLG PINTLE PIN Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
32 2107-008 Airframe PART #1538	NLG PINTLE PIN. Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
32 2109-003 Airframe PART #1765	LH NLG HARNESS Part Number: 22800-105 Serial Number: 427	21-MAR-2010 H: 0.00					
32 2109-004 Airframe PART #2014	RH NLG HARNESS Part Number: 22801-107 Serial Number: 426	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 22-00-101 Airframe INSPECTION 7500 L #555	SPECIAL DETAILED INSPECTION OF THE NOSE LANDING GEAR FORWARD DOORS Reference Number NDT ET-32-20-001, MT-32-20-001	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
32 22-00-201 Airframe INSPECTION 250 H #2172	LUBRICATION OF THE NOSE LANDING GEAR (NLG) DOORS	08-FEB-2022 H: 4399.80 L: 1478	H: 250.00	H: 25.00		H: 4649.80	H: 194.00
32 22-00-202 Airframe INSPECTION 120M #1630	DETAILED INSPECTION OF THE NOSE-GEAR-DOOR HINGES AND ACTUATOR ATTACHMENT FITTING	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
32 2205-001 Airframe PART #2537	NLG AFT DOOR ASSY Part Number GS328-0005-5 Serial Number B385	21-MAR-2010 H: 0.00					
32 2217-001 Airframe PART #2874	LH NLG FWD DOOR ASSY Part Number GS328-0003-3 Serial Number B391	21-MAR-2010 H: 0.00					
32 2217-002 Airframe PART #1331	RH NLG FWD DOOR ASSY Part Number GS328-0004-3 Serial Number B391	21-MAR-2010 H: 0.00					
32 31-09-101 Airframe INSPECTION 3000H #490	VISUAL CHECK OF THE LANDING-GEAR ELECTRONIC CONTROL UNIT (LG ECU)	01-DEC-2018 H: 3011.20 L: 1025	H: 3000.00			H: 6011.20	H: 1555.40
32 3101-001 Airframe PART #3015	LANDING GEAR CONTROL HANDLE Part Number PN Serial Number SN-UNKNOWN	21-MAR-2010 H: 0.00					
32 3102-001 Airframe PART #2177	LANDING GEAR CONTROL PANEL Part Number PN Serial Number SN-UNKNOWN	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 3109-001 Airframe PART #1976	LANDING GEAR ECU Part Number Serial Number GW415-5100-1 E498	21-MAR-2010 H: 0.00					
32 3113-001 Airframe PART #377	NO. 2 SYSTEM L/G CONTROL SELECTOR VALVE Part Number Serial Number GW415-6025-3 NGL/2209/0 9	21-MAR-2010 H: 0.00					
32 3115-001 Airframe PART #2722	NO. 3 SYSTEM L/G CONTROL SELECTOR VALVE Part Number Serial Number GW415-6025-3 NGL/2213/0 9	21-MAR-2010 H: 0.00					
32 3117-001 Airframe PART #2910	L/G DOOR CONTROL SELECTOR VALVE Part Number Serial Number GW415-6025-3 NGL/2207/0 9	21-MAR-2010 H: 0.00					
32 3121-001 Airframe PART #2819	CHECK, SIDE BRACE CONTROL VALVE Part Number Serial Number GW415-6075-7 NGL/1408/0 9	21-MAR-2010 H: 0.00					
32 32-01-105 Airframe PART - Life Limited #2600	DISCARD THE LH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR ASSEMBLY, PART NO. 21600 Reference Number Part Number Serial Number 32-32-01-961-801 21600-101 09MDT0805	21-MAR-2010 H: 0.00	L: 25000		M: 0 H: 0.00 L: 0	L: 25000	L: 23505
32 32-01-105 Airframe PART - Life Limited #525	DISCARD THE RH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR ASSEMBLY, PART NO. 21600 Reference Number Part Number Serial Number 32-32-01-961-801 21600-102 09MDT0789	21-MAR-2010 H: 0.00	L: 25000		M: 0 H: 0.00 L: 0	L: 25000	L: 23505
32 32-05-107 Airframe PART #1237	DISCARD THE LH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY, PART NO. 21900 Reference Number Part Number Serial Number 32-32-05-961-801 21900-103 09SM00027	21-MAR-2010 H: 0.00	L: 25000			L: 25000	L: 23505
32 32-05-107 Airframe PART #2791	RH MLG UPLOCK Reference Number Part Number Serial Number 32-32-05-961-801 21900-104 09SM00025	21-MAR-2010 H: 0.00	L: 25000			L: 25000	L: 23505





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 32-13-101 Airframe PART #138	DISCARD THE LEFT MAIN GEAR DOOR INBOARD UPLOCK Part Number Serial Number GW415-2200-5 09SM00029	21-MAR-2010 H: 0.00	L: 6250			L: 6250	L: 4755
32 32-13-101 Airframe PART #160	DISCARD THE RIGHT MAIN GEAR DOOR INBOARD UPLOCK Part Number Serial Number GW415-2200-6 09SM00025	21-MAR-2010 H: 0.00	L: 6250			L: 6250	L: 4755
32 3201-007 Airframe PART #428	LH MLG RETRACTION ACTUATOR PIN Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3201-008 Airframe PART #5	RH MLG RETRACTION ACTUATOR PIN Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3201-009 Airframe PART #255	LH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR CYLINDER Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3201-010 Airframe PART #1661	RH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR CYLINDER Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3201-011 Airframe PART #2248	LH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR PISTON Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3201-012 Airframe PART #556	RH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR PISTON Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3201-013 Airframe PART #53	LH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR ROD END Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 3201-014 Airframe PART #2885	RH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR ROD END Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3201-015 Airframe PART #1850	LH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR GLAND NUT Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3201-016 Airframe PART #1816	RH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR GLAND NUT Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3205-003 Airframe PART #482	LH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY SIDE PLATE Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3205-004 Airframe PART #2376	RH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY SIDE PLATE Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3205-005 Airframe PART #2866	LH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY LATCH Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3205-006 Airframe PART #291	RH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY LATCH Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3205-007 Airframe PART #1139	LH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY LOCK LEVER Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3205-008 Airframe PART #2863	RH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY LOCK LEVER Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 3205-009 Airframe PART #2155	LH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY ACTUATOR CYLINDER Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3205-010 Airframe PART #461	RH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY ACTUATOR CYLINDER Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3205-011 Airframe PART #1205	LH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY ACTUATOR PISTON Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3205-012 Airframe PART #303	RH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY ACTUATOR PISTON Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3205-013 Airframe PART #3043	LH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY MANUAL RELEASE LEVER Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3205-014 Airframe PART #803	RH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY MANUAL RELEASE LEVER Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3209-001 Airframe PART #694	LH MLG DOOR INBOARD ACTUATOR Part Number Serial Number GW412-2000-1 09MDT0685	21-MAR-2010 H: 0.00					
32 3209-002 Airframe PART #218	RH MLG DOOR INBOARD ACTUATOR Part Number Serial Number GW412-2000-1 09MDT0686	21-MAR-2010 H: 0.00					
32 3225-001 Airframe PART #1822	CHECK, BRAKE CONTROL VALVE Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 3229-001 Airframe PART #1706	MAIN LANDING GEAR MRS ALTERNATE POWER VALVE Part Number: GW415-6051-5 Serial Number: 09MDT0505	21-MAR-2010 H: 0.00					
32 33-01-105 Airframe PART - Life Limited #1879	DISCARD THE NOSE LANDING GEAR RETRACTION ACTUATOR ASSEMBLY Reference Number: AMM 32-33-01-961-801 Part Number: 22400-103 Serial Number: 09MDT0340	21-MAR-2010 H: 0.00	L: 20000		M: 0 H: 0.00 L: 0	L: 20000	L: 18505
32 33-01-111 Airframe INSPECTION #574	RESTORATION OF THE NOSE LANDING GEAR (NLG) SHOCK-STRUT ASSEMBLY TO RETRACTION-ACTUATOR MAIN-FITTING JOINT (POST SB 700-32-035 PART C) Notes TIME TRACKING OF THE ABOVE NON-SERIALIZED PARTS IS TO BE DONE AT THE NLG ASSEMBLY LEVEL (PART NO. GW311-1100-XX)	15-APR-2021 H: 3992.00 L: 1324	L: 1500			L: 2824	L: 1329
32 33-05-106 Airframe PART #143	DISCARD THE NOSE LANDING GEAR UPLOCK ASSEMBLY Reference Number: AMM 32-33-05-961-801 Part Number: 22600-103 Serial Number: 09SM00011	21-MAR-2010 H: 0.00	L: 25000			L: 25000	L: 23505
32 3301-002 Airframe PART #2265	NOSE LANDING GEAR (NLG) RETRACTION ACTUATOR CYLINDER Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
32 3301-003 Airframe PART #571	NOSE LANDING GEAR (NLG) RETRACTION ACTUATOR PISTON Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
32 3301-004 Airframe PART #674	NOSE LANDING GEAR (NLG) RETRACTION ACTUATOR GLAND NUT Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
32 3301-005 Airframe PART #111	NOSE LANDING GEAR (NLG) RETRACTION ACTUATOR ROD END Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
32 3305-002 Airframe PART #2124	NOSE LANDING GEAR (NLG) UPLOCK ACTUATOR CYLINDER Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 3305-003 Airframe PART #1122	NOSE LANDING GEAR (NLG) UPLOCK ACTUATOR PISTON Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3305-004 Airframe PART #1912	NOSE LANDING GEAR (NLG) UPLOCK ASSEMBLY HOOK Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3305-005 Airframe PART #2273	NOSE LANDING GEAR (NLG) UPLOCK ASSEMBLY LOCK LEVER Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3305-006 Airframe PART #2453	NOSE LANDING GEAR (NLG) UPLOCK ASSEMBLY STOP PIN Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3309-003 Airframe PART #1934	NLG FWD DOOR ACTUATOR Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3313-001 Airframe PART #1452	NLG FORWARD DOOR UPLOCK Part Number Serial Number GW415-2300-3 09MDT0504	21-MAR-2010 H: 0.00					
32 3314-001 Airframe PART #852	NLG DOOR QUADRANT Part Number Serial Number GW413-1000-5 DCL-381	21-MAR-2010 H: 0.00					
32 34-00-201 Airframe INSPECTION 1500H #1593	FUNCTIONAL TEST OF THE LANDING-GEAR EMERGENCY EXTENSION	08-FEB-2022 H: 4399.80 L: 1478	H: 1500.00	H: 50.00		H: 5899.80	H: 1444.00
32 34-00-202 Airframe INSPECTION 450L #1513	DETAILED INSPECTION OF THE LANDING-GEAR EMERGENCY-EXTENSION CONTROL PATH IN THE NOSE LANDING-GEAR WHEEL-WELL, FS202.75 TO FS280.00	10-MAR-2022 H: 4455.80 L: 1495	L: 450	L: 50		L: 1945	L: 450





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 34-00-203 Airframe INSPECTION 60M #1171	DETAILED INSPECTION OF THE LANDING-GEAR EMERGENCY-EXTENSION CONTROL PATH IN THE FORWARD AVIONICS COMPARTMENT, FS202.75 TO FS280.00	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
32 34-00-204 Airframe INSPECTION 60M #2006	DETAILED INSPECTION OF THE LANDING-GEAR EMERGENCY-EXTENSION CONTROL PATH IN THE MAIN AVIONICS COMPARTMENT, FS280.00 TO FS557.00	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
32 34-00-205 Airframe INSPECTION 120M #583	DETAILED INSPECTION OF THE LANDING-GEAR EMERGENCY-EXTENSION CONTROL PATH IN THE MID-LOWER FUSELAGE COMPARTMENT, FS557.00 TO FS781.00	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
	Notes NO DEFECTS NOTED						
32 34-00-206 Airframe INSPECTION 60M #768	DETAILED INSPECTION OF THE LANDING-GEAR EMERGENCY EXTENSION CONTROL PATH IN THE MAIN LANDING-GEAR WHEEL-WELL, FS719.30 TO FS781.00	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
32 3401-001 Airframe PART #1185	MLG QUADRANT Part Number Serial Number GW413-7000-3 DCL393	21-MAR-2010 H: 0.00					
32 3401-002 Airframe PART #2186	NOSE LANDING GEAR QUADRANT Part Number Serial Number GW413-2000-3 DCL-391	21-MAR-2010 H: 0.00					
32 3402-001 Airframe PART #637	MANUAL RELEASE HANDLE Part Number Serial Number GW415-7100-3 418	21-MAR-2010 H: 0.00					
32 3402-002 Airframe PART #2716	MANUAL RELEASE QUADRANT Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3405-000 Airframe INSPECTION #1308	HYD S/O DUMP MANUAL RELEASE VALVE	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 3406-001 Airframe PART #1602	HYDRAULIC DUMP VALVE Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 3409-001 Airframe PART #2355	ALTERNATE POWER VALVE Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 40-00-201 Airframe INSPECTION 500H #1805	FUNCTIONAL TEST OF THE BRAKE ACCUMULATORS	10-MAR-2022 H: 4455.80 L: 1495	H: 500.00	H: 50.00		H: 4955.80	H: 500.00
32 41-01-201 Airframe INSPECTION #1 MLG #826	SPECIAL DETAILED INSPECTION NO.1 MLG WHEEL ASSY Part Number 3-1599 Serial Number 1077	09-MAR-2022 H: 4455.80 L: 1495					
32 41-01-201 Airframe INSPECTION #2 MLG #2952	SPECIAL DETAILED INSPECTION NO.2 MLG WHEEL ASSY Part Number 3-1599 Serial Number 2033	09-MAR-2022 H: 4455.80 L: 1496					
32 41-01-201 Airframe INSPECTION #3 MLG #84	SPECIAL DETAILED INSPECTION NO.3 MLG WHEEL ASSY Part Number 3-1599 Serial Number 0006	09-MAR-2022 H: 4455.80 L: 1495					
32 41-01-201 Airframe INSPECTION #4 MLG #1873	SPECIAL DETAILED INSPECTION NO.4 MLG WHEEL ASSY Part Number 3-1599 Serial Number 2032	09-MAR-2022 H: 4455.80 L: 1495					
32 41-01-202 Airframe INSPECTION #1 MLG #1248	DETAILED INSPECTION NO.1 MLG WHEEL ASSY Part Number 3-1599 Serial Number 1077	09-MAR-2022 H: 4455.80 L: 1495					
32 41-01-202 Airframe INSPECTION #2 MLG #2334	DETAILED INSPECTION NO.2 MLG WHEEL ASSY Part Number 3-1599 Serial Number 2033	09-MAR-2022 H: 4455.80 L: 1496					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 41-01-202 Airframe INSPECTION #3 MLG #1318	DETAILED INSPECTION NO.3 MLG WHEEL ASSY Part Number 3-1599 Serial Number 0006	09-MAR-2022 H: 4455.80 L: 1495					
32 41-01-202 Airframe INSPECTION #4 MLG #913	DETAILED INSPECTION NO.4 MLG WHEEL ASSY Part Number 3-1599 Serial Number 2032	09-MAR-2022 H: 4455.80 L: 1495					
32 4101-001 Airframe PART #1 MLG #1178	NO. 1 MLG TIRE Part Number 382K02-1 Serial Number 01410822	09-MAR-2022 H: 4455.80 L: 1495					
32 4101-002 Airframe PART #2 MLG #810	NO. 2 MLG TIRE Part Number 382K02-1 Serial Number 02340857	09-MAR-2022 H: 4455.80 L: 1495					
	Notes NEW TIRE INSTALLED ON WHEEL ASSEMBLY P/N 3-1599, S/N 2033 BY FLIGHTPATH UNDER WO 171724						
32 4101-003 Airframe PART #3 MLG #814	NO. 3 MLG TIRE Part Number 382K02-1 Serial Number 00971120	09-MAR-2022 H: 4455.80 L: 1495					
32 4101-004 Airframe PART #4 MLG #991	NO. 4 MLG TIRE Part Number 382K02-1 Serial Number 01430886	09-MAR-2022 H: 4455.80 L: 1495					
32 4101-005 Airframe PART #2233	NO. 1 ASSY MLG WHEEL Part Number 3-1599 Serial Number 1077	09-MAR-2022 H: 4455.80 L: 1495					
32 4101-006 Airframe PART #2538	NO. 2 ASSY MLG WHEEL Part Number 3-1599 Serial Number 2033	09-MAR-2022 H: 4455.80 L: 1495					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 4101-007 Airframe PART #615	NO. 3 ASSY MLG WHEEL Part Number 3-1599 Serial Number 0006	09-MAR-2022 H: 4455.80 L: 1495					
32 4101-008 Airframe PART #93	NO. 4 ASSY MLG WHEEL Part Number 3-1599 Serial Number 2032	09-MAR-2022 H: 4455.80 L: 1495					
32 42-01-201 Airframe INSPECTION LH NLG WHEEL #1182	SPECIAL DETAILED INSPECTION LH NLG WHEEL ASSY Part Number 3-1560 Serial Number 1212	28-APR-2021 H: 3996.30 L: 1326					
Notes C/W BY FLIGHTPATH SVC WO# 146133							
32 42-01-201 Airframe INSPECTION RH NLG WHEEL #1481	SPECIAL DETAILED INSPECTION RH NLG WHEEL ASSY Part Number 3-1560 Serial Number 1171	28-APR-2021 H: 3996.30 L: 1326					
Notes C/W BY FLIGHTPATH SVC WO # 146134							
32 42-01-202 Airframe INSPECTION LH NLG WHEEL #671	DETAILED INSPECTION LH NLG WHEEL ASSY Reference Number AMM 32-42-01-220 -801 Part Number 3-1560 Serial Number 1212	28-APR-2021 H: 3996.30 L: 1326					
Notes C/W BY FLIGHTPATH SVC WO# 146133							
32 42-01-202 Airframe INSPECTION RH NLG WHEEL #376	DETAILED INSPECTION RH NLG WHEEL ASSY Reference Number AMM 32-42-01-220 -801 Part Number 3-1560 Serial Number 1171	28-APR-2021 H: 3996.30 L: 1326					
32 4201-001 Airframe PART #811	LH NLG TIRE Part Number 217K22-1 Serial Number 62582314	15-JUL-2019 H: 3387.90 L: 1137					
32 4201-002 Airframe PART #18	RH NLG TIRE Part Number 217K22-1 Serial Number 62562843	15-JUL-2019 H: 3387.90 L: 1137					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 4201-003 Airframe PART #2325	LH ASSY NLG WHEEL Part Number 3-1560 Serial Number 1212	28-APR-2021 H: 3996.30 L: 1326					
32 4201-004 Airframe PART #2395	RH ASSY NLG WHEEL Part Number 3-1560 Serial Number 1171	28-APR-2021 H: 3996.30 L: 1326					
32 43-00-201 Airframe INSPECTION 450L #1492	DETAILED INSPECTION OF THE BRAKE WEAR INDICATORS	10-MAR-2022 H: 4455.80 L: 1495	L: 450	L: 50		L: 1945	L: 450
32 43-07-201 Airframe INSPECTION 750H/30M #2867	VISUAL CHECK OF THE BRAKE-PEDAL RETURN SPRING	08-FEB-2022 H: 4399.80 L: 1478	H: 750.00	H: 50.00		H: 5149.80	H: 694.00
32 43-13-201 Airframe INSPECTION 30M #2566	FUNCTIONAL TEST OF THE BRAKE DISK FOR DRIVE SLOT ENLARGEMENT Notes NO DEFECTS NOTED	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
32 43-13-301 Airframe INSPECTION 60M #5140	RESTORATION (REPLATING) OF THE BRAKE ASSEMBLY - TORQUE TUBE Notes NOTE: REFER TO AW700-32-0804		M: 60			19-APR-2026	M: 49 D: 3
32 43-25-201 Airframe INSPECTION 750H/30M #1038	OPERATIONAL TEST OF THE BRAKE SHUTOFF VALVE	08-FEB-2022 H: 4399.80 L: 1478	H: 750.00	H: 50.00		H: 5149.80	H: 694.00
32 43-37-101* Airframe INSPECTION #5062	DISCARD THE NO. 2 BRAKE ACCUMULATOR, PART NO. GW415-1250-1		L: 8336			L: 8336	L: 6841





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 43-53-201 Airframe INSPECTION 120M #4745	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION OF THE WHEEL SPEED TRANSDUCERS CONNECTORS Reference Number AMM 32-43-53-210 -802	19-APR-2021 H: 3992.00 L: 1324	M: 120			19-APR-2031	M: 109 D: 3
32 4301-001 Airframe PART #655	BRAKE CONTROL UNIT Part Number Serial Number GW715-7125-7 / 42-965-3 893A Notes NOTE P/N GW415-7125-5 SAME AS HYDRO-AIRE P/N 24050-105 & P/N 42-965-2, NEW MODIFIED PN 42-965-3 (GW715-7125-7) ,UNIT REPLACED DUE TO SPOILERS / STAB BIT CYAN CAS MESSAGED REPORTED DURING LANDINGS PER CRC RECCOMENDATIONS. AFTER NVM DATA REVIEW AND FCU'S REPOSITIONING/REPLACEMENT.THIS APPLIES TO REMOVED BCU SN 533.NO SPOILERS STAB BIT MESSAGES WITH SN 533 INSTALLED ,HOWEVER CYAN BRAKE FAULT AND AUTO BRAKES NOT WORK ON LOW, WERE REPORTED BY THE FLIGHT CREW WITH THIS UNIT.	16-FEB-2022 H: 4423.10 L: 1485					
32 4305-001 Airframe PART #843	LEFT NO.1 POSITION BRAKE PEDAL TRANSDUCER Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 4305-002 Airframe PART #437	LEFT NO.2 POSITION BRAKE PEDAL TRANSDUCER Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 4305-003 Airframe PART #821	RIGHT NO. 1 POSITION BRAKE PEDAL TRANSDUCER Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 4305-004 Airframe PART #621	RIGHT NO. 2 POSITION BRAKE PEDAL TRANSDUCER Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 4309-001 Airframe PART #3030	BRAKE CONTROL VALVE, LH INBOARD Part Number Serial Number GW415-6150-1 4064	14-JUL-2021 H: 4138.20 L: 1382					
32 4309-002 Airframe PART #953	BRAKE CONTROL VALVE, RH INBOARD Part Number Serial Number GW415-6150-1 1088	16-AUG-2021 H: 4227.30 L: 1412					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 4309-003 Airframe PART #593	BRAKE CONTROL VALVE, LH OUTBOARD Part Number Serial Number GW415-6150-1 130	16-AUG-2021 H: 4227.30 L: 1412					
32 4309-004 Airframe PART #1260	BRAKE CONTROL VALVE, RH OUTBOARD Part Number Serial Number GW415-6150-01 4066	14-JUL-2021 H: 4138.20 L: 1382					
32 4311-701 Airframe PART #2857	#1 QUICK DISCONNECT COUPLER Part Number Serial Number 15406-06A-E17 3235	21-MAR-2010 H: 0.00					
32 4311-702 Airframe PART #2389	#2 QUICK DISCONNECT COUPLER Part Number Serial Number 15406-06A-E17 3239	21-MAR-2010 H: 0.00					
32 4311-703 Airframe PART #1992	#3 QUICK DISCONNECT COUPLER Part Number Serial Number 15406-06A-E17 3110	21-MAR-2010 H: 0.00					
32 4311-704 Airframe PART #1435	#4 QUICK DISCONNECT COUPLER Part Number Serial Number 15406-06A-E17 3243	21-MAR-2010 H: 0.00					
32 4313-001 Airframe PART #2258	NO. 1 MLG BRAKE Part Number Serial Number GW313-2001-3 (2-1608-2) 0647	28-JUN-2016 H: 1899.20 L: 668					
32 4313-002 Airframe PART #403	NO. 2 MLG BRAKE Part Number Serial Number GW313-2001-3 0495	25-OCT-2017 H: 2498.70 L: 877					
	Notes S/N 1701 REMOVED FROM #1 WITH 1805.6 HRS & 643 LANDINGS						
32 4313-003 Airframe PART #1893	NO. 3 MLG BRAKE Part Number Serial Number GW313-2001-3 0492	12-APR-2016 H: 1794.20 L: 640					
	Notes REMOVED #3 BRAKE FOR REPAIR AND INSTALLED REPAIRED BRAKE.						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 4313-004 Airframe PART #2209	NO. 4 MLG BRAKE Part Number Serial Number GW313-2001-3 1701	25-OCT-2017 H: 2498.70 L: 877					
	Notes SUSPECT OVERHEATING BRAKE SN 1701 IS INSTALLED IN #4 POSITION						
32 4317-001 Airframe PART #1305	LEFT FORWARD BRAKE PRESSURE TRANSDUCER Part Number Serial Number GW415-1350-3 7702-1-65	21-MAR-2010 H: 0.00					
32 4317-002 Airframe PART #372	RIGHT FORWARD BRAKE PRESSURE TRANSDUCER Part Number Serial Number GW415-1350-3 7702-1-67	21-MAR-2010 H: 0.00					
32 4317-003 Airframe PART #1955	LEFT AFT BRAKE PRESSURE TRANSDUCER Part Number Serial Number GW415-1350-3 7527-11-206	21-MAR-2010 H: 0.00					
32 4317-004 Airframe PART #272	RIGHT AFT BRAKE PRESSURE TRANSDUCER Part Number Serial Number GW415-1350-3 7702-1-69	21-MAR-2010 H: 0.00					
32 4321-001 Airframe PART #678	LOB SHUTTLE VALVE Part Number Serial Number GW415-6200-1 1654	21-MAR-2010 H: 0.00					
32 4321-002 Airframe PART #351	LIB SHUTTLE VALVE Part Number Serial Number GW415-6200-1 1655	21-MAR-2010 H: 0.00					
32 4321-003 Airframe PART #507	RIB SHUTTLE VALVE Part Number Serial Number GW415-6200-1 1660	21-MAR-2010 H: 0.00					
32 4321-004 Airframe PART #1745	ROB SHUTTLE VALVE Part Number Serial Number GW415-6200-1 1610	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 4325-001 Airframe PART #234	LH SHUTOFF VALVE Part Number PN	21-MAR-2010 H: 0.00	Serial Number SN- UNKNOWN				
32 4325-002 Airframe PART #1910	RH SHUTOFF VALVE Part Number PN	21-MAR-2010 H: 0.00	Serial Number SN- UNKNOWN				
32 4329-001 Airframe PART #2587	NO. 2 SYS PRESSURE CHECK, BRAKE CONTROL VALVE Part Number PN	21-MAR-2010 H: 0.00	Serial Number SN- UNKNOWN				
32 4333-001 Airframe PART #1062	NO. 1 HYDRAULIC FUSE VALVE Part Number GW415-1300-1	21-MAR-2010 H: 0.00	Serial Number 1665				
32 4333-002 Airframe PART #171	NO. 2 HYDRAULIC FUSE VALVE Part Number GW415-1300-1	21-MAR-2010 H: 0.00	Serial Number 1693				
32 4333-003 Airframe PART #773	NO. 3 HYDRAULIC FUSE VALVE Part Number GW415-1300-1	21-MAR-2010 H: 0.00	Serial Number 1661				
32 4333-004 Airframe PART #695	NO. 4 HYDRAULIC FUSE VALVE Part Number GW415-1300-1	21-MAR-2010 H: 0.00	Serial Number 1669				
32 4337-001 Airframe PART #209	NO. 2 BRAKE ACCUMULATOR Part Number 0860185002	06-DEC-2012 H: 426.50 L: 209	Serial Number 60185- 2166NAE				
32 4341-001 Airframe PART #536	PRESSURE GAUGE AND CHARGING VALVE Part Number PN	21-MAR-2010 H: 0.00	Serial Number SN- UNKNOWN				





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 4345-001 Airframe PART #2673	AUTOBRAKE SWITCH Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 4346-001 Airframe PART #2412	GROUND LIFT/AUTO BRAKE CONTROL PANEL Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 4349-001 Airframe PART #2434	LH PRESSURE SWITCH Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 4349-002 Airframe PART #706	RH PRESSURE SWITCH Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 4353-001 Airframe PART #1478	NO. 1 MLG WHEEL SPEED TRANSDUCER Part Number GW415-1050-9 Serial Number 2925	30-DEC-2018 H: 3059.50 L: 1043					
32 4353-002 Airframe PART #1064	NO. 2 MLG WHEEL SPEED TRANSDUCER Part Number GW415-1050-9 Serial Number 2929	30-DEC-2018 H: 3059.50 L: 1043					
32 4353-003 Airframe PART #942	NO. 3 MLG WHEEL SPEED TRANSDUCER Part Number GW415-1050-9 Serial Number 2933	10-DEC-2014 H: 1111.80 L: 414					
32 4353-004 Airframe PART #256	NO. 4 MLG WHEEL SPEED TRANSDUCER Part Number GW415-1050-9 Serial Number 2934	10-DEC-2014 H: 1111.80 L: 414					
32 4361-701 Airframe PART #2151	NO. 1 BRAKE TEMPERATURE SENSOR Part Number GW436-1001-1 Serial Number 3302	05-JAN-2015 H: 1165.90 L: 428					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 4361-702 Airframe PART #363	NO. 2 BRAKE TEMPERATURE SENSOR Part Number Serial Number GW436-1001-1 H7289	06-OCT-2017 H: 2453.60 L: 863					
32 4361-703 Airframe PART #2135	NO. 3 BRAKE TEMPERATURE SENSOR Part Number Serial Number GW436-1001-1 J3292	21-MAR-2010 H: 0.00					
32 4361-704 Airframe PART #240	NO. 4 BRAKE TEMPERATURE SENSOR Part Number Serial Number GW436-1001-1 J3297	05-JAN-2015 H: 1165.90 L: 428					
32 44-05-101 Airframe INSPECTION #5063	DISCARD THE NO. 3 BRAKE ACCUMULATOR, PART NO. GW415-1200-1/-3 Reference Number 32-44-05-961-801		L: 5816			L: 5816	L: 4321
32 4401-001 Airframe PART #287	PARKING BRAKE VALVE Part Number Serial Number GW415-6225-5 448	21-MAR-2010 H: 0.00					
32 4405-001 Airframe PART #2072	NO. 3 BRAKE ACCUMULATOR Part Number Serial Number GX415-1200-3 60188-2882	08-SEP-2015 H: 1566.00 L: 552					
32 4409-001 Airframe PART #823	PARKING BRAKE HANDLE Part Number Serial Number 24700-107 J34399-10	04-MAR-2016 H: 1753.70 L: 622					
32 5101-001 Airframe PART #397	STEERING CONTROL UNIT Part Number Serial Number GW415-8100-3 09-432	21-MAR-2010 H: 0.00					
32 5102-001 Airframe PART #280	PRESSURE STEERING CONTROL SWITCH Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
32 5105-001 Airframe PART #948	STEERING CONTROL HANDWHEEL Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 5109-001 Airframe PART #289	RVDT :LH RUDDER CONTROL RVDT Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
32 5109-002 Airframe PART #2769	RVDT :RH RUDDER CONTROL RVDT Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
32 5113-001 Airframe PART #1711	STEERING SOLENOID VALVE Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
32 5117-001 Airframe PART #2361	NOSE STEERING MANIFOLD Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
32 5121-001 Airframe PART #2226	LH SWIVEL, STEERING ACTUATOR MANIFOLD Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
32 5121-002 Airframe PART #2482	RH SWIVEL, STEERING ACTUATOR MANIFOLD Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
32 5121-003 Airframe PART #501	LH STEERING ACTUATOR Part Number 1287A0000-02	Serial Number 02230	29-JAN-2018 H: 2586.20 L: 898				
32 5121-004 Airframe PART #316	RH STEERING ACTUATOR Part Number 1288A0000-02	Serial Number 2147	21-MAR-2010 H: 0.00				
32 5133-001 Airframe PART #2512	HYDRAULIC COMPENSATOR Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 60-00-201 Airframe INSPECTION 1000 H #1115	VISUAL CHECK OF THE LANDING GEAR POSITION AND WARNING SYSTEM	10-MAR-2022 H: 4455.80 L: 1495	H: 1000.00	H: 50.00		H: 5455.80	H: 1000.00
32 6110-701 Airframe PART #592	NO. 3 HYD DOOR (MT-212) PROXIMITY SENSOR Part Number: 8-642-03 Serial Number: 50519	02-MAR-2015 H: 1257.80 L: 467					
32 ZL-00-201 Airframe INSPECTION 450L #2257	GENERAL VISUAL INSPECTION OF THE NOSE LANDING GEAR (NLG) ASSEMBLY	10-MAR-2022 H: 4455.80 L: 1495	L: 450	L: 50		L: 1945	L: 450
32 ZL-00-202 Airframe INSPECTION 450L #2133	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR ASSEMBLY - LH	10-MAR-2022 H: 4455.80 L: 1495	L: 450	L: 50		L: 1945	L: 450
32 ZL-00-203 Airframe INSPECTION 450L #819	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR ASSEMBLY - RH	10-MAR-2022 H: 4455.80 L: 1495	L: 450	L: 50		L: 1945	L: 450
32 ZL-00-204 Airframe INSPECTION 900L #1531	GENERAL VISUAL INSPECTION OF THE NOSE LANDING GEAR DOOR - LH	29-SEP-2017 H: 2431.70 L: 854	L: 900	L: 50		L: 1754	L: 259
32 ZL-00-205 Airframe INSPECTION 900L #1352	GENERAL VISUAL INSPECTION OF THE NOSE LANDING GEAR DOOR - RH	29-SEP-2017 H: 2431.70 L: 854	L: 900	L: 50		L: 1754	L: 259
32 ZL-00-206 Airframe INSPECTION 900L #2628	GENERAL VISUAL INSPECTION OF THE NOSE LANDING GEAR DOOR - AFT	29-SEP-2017 H: 2431.70 L: 854	L: 900	L: 50		L: 1754	L: 259
32 ZL-00-207 Airframe INSPECTION 450L #162	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR (MLG) INBOARD DOOR - LH	10-MAR-2022 H: 4455.80 L: 1495	L: 450	L: 50		L: 1945	L: 450





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 ZL-00-208 Airframe INSPECTION 450L #599	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR (MLG) INBOARD DOOR - RH	10-MAR-2022 H: 4455.80 L: 1495	L: 450	L: 50		L: 1945	L: 450
32 ZL-00-209 Airframe INSPECTION 450L #1086	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR (MLG) OUTBOARD DOOR - LH	10-MAR-2022 H: 4455.80 L: 1495	L: 450	L: 50		L: 1945	L: 450
32 ZL-00-210 Airframe INSPECTION 450L #605	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR (MLG) OUTBOARD DOOR - RH	10-MAR-2022 H: 4455.80 L: 1495	L: 450	L: 50		L: 1945	L: 450
33 Airframe PART #5042	AFT TAIL CONE STROBE POWER SUPPLY. Part Number 8ES456038-03 Serial Number 4659233	25-JUL-2020 H: 3814.00 L: 1262					
33 00-00-201 Airframe INSPECTION 120M #4746	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION OF THE WING TIP LIGHTS AND COMPONENTS CONNECTORS AND GROUND STUDS Reference Number AMM 33-00-00-210 -801	19-APR-2021 H: 3992.00 L: 1324	M: 120			19-APR-2031	M: 109 D: 3
33 1100-001 Airframe PART #530	LEFT 7.5A CONVERTER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
33 1100-002 Airframe PART #2016	RIGHT FORWARD 7.5A CONVERTER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
33 1100-003 Airframe PART #2179	RIGHT AFT 7.5A CONVERTER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
33 1101-001 Airframe PART #1809	LH 15A DC/DC CONVERTER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
33 1101-002 Airframe PART #392	RH 15A DC/DC CONVERTER Part Number PN	21-MAR-2010 H: 0.00					
33 1101-003 Airframe PART #3006	LH 0.1A DC/AC INVERTER Part Number PN	21-MAR-2010 H: 0.00					
33 1101-004 Airframe PART #2148	RH 0.1A DC/AC INVERTER Part Number PN	21-MAR-2010 H: 0.00					
33 1101-005 Airframe PART #2255	LH 0.5A DC/AC INVERTER Part Number PN	21-MAR-2010 H: 0.00					
33 1101-006 Airframe PART #2137	RH 0.5A DC/AC INVERTER Part Number PN	21-MAR-2010 H: 0.00					
33 1305-001 Airframe PART #1600	LH MAP READING LIGHT Part Number 2LA005163-25	29-OCT-2020 H: 3922.40 L: 1299					
33 1305-002 Airframe PART #2048	RH MAP READING LIGHT Part Number PN	21-MAR-2010 H: 0.00					
33 2000-701 Airframe PART #2023	INTERIOR LIGHTING SYSTEM DIRECTOR Part Number 8ES455611-10	15-FEB-2011 H: 25.00 L: 11					
33 24-50-601 Airframe INSPECTION #260	OPERATIONAL TEST OF THE ORDINANCE SIGNS Reference Number 33-24-50-710-801 Notes NO DEFECTS NEEDED	06-JAN-2021 H: 3992.00 L: 1324	M: 30			06-JUL-2023	M: 15 D: 20





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
33 3101-001 Airframe PART #752	NOSE GEAR BAY/TAIL LIGHT Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
33 3109-001 Airframe PART #1295	APU COMPARTMENT LIGHT Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
33 3113-001 Airframe PART #2579	NO. 1 MAIN LIGHT Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
33 3113-002 Airframe PART #2295	NO. 2 MAIN LIGHT Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
33 3113-003 Airframe PART #2450	NO. 3 MAIN LIGHT Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
33 3117-001 Airframe PART #2618	LH FS381 AUTO SHUT-OFF BOX Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
33 3117-002 Airframe PART #1734	LH FS909 AUTO SHUT-OFF BOX Part Number GE534-0001-1	Serial Number 1529868	21-MAR-2010 H: 0.00				
33 3117-003 Airframe PART #467	RH DVC AUTO SHUT-OFF LIGHT Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
33 4001-001 Airframe PART #1651	EXTERNAL LIGHTS CONTROL PANEL Part Number BI7003430004-001	Serial Number 312037	23-JAN-2011 H: 11.80 L: 6				





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
33 41-01-201 Airframe INSPECTION 120M #4747	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION OF THE WING LANDING AND TAXI LIGHTS CONNECTORS Reference Number AMM 33-41-01-210 -801	19-APR-2021 H: 3992.00 L: 1324	M: 120			19-APR-2031	M: 109 D: 3
33 4101-001 Airframe PART #662	LH LANDING LIGHT LENS Part Number PN	Serial Number SN- UNKNOWN				21-MAR-2010 H: 0.00	
33 4101-002 Airframe PART #3005	RH LANDING LIGHT LENS Part Number PN	Serial Number SN- UNKNOWN				21-MAR-2010 H: 0.00	
33 4102-001 Airframe PART #83	LH WING LANDING/TAXI LIGHT Part Number 1X4455177-50	Serial Number 2276182				28-DEC-2012 H: 426.50 L: 209	
33 4102-001A Airframe PART #5057	RH INBOARD LANDING/TAXI LAMP. Part Number 8GH410764-28	Serial Number N/A				31-AUG-2020 H: 3844.20 L: 1271	
33 4102-001B Airframe PART #5058	RH OUTBOARD LANDING/TAXI LAMP. Part Number 8GH410764-28	Serial Number N/A				28-AUG-2020 H: 3844.20 L: 1271	
33 4102-002 Airframe PART #2259	RH WING LANDING/TAXI LIGHT Part Number 1X4455177-50	Serial Number 1708867				28-DEC-2012 H: 426.50 L: 209	
33 4102-002A Airframe PART #5055	RH INBOARD LANDING/TAXI LAMP Part Number 8GH410764-28	Serial Number N/A				28-AUG-2020 H: 3844.20 L: 1271	
33 4102-002B Airframe PART #5056	RH OUTBOARD LANDING/TAXI LAMP. Part Number 8GH410764-28	Serial Number N/A				28-AUG-2020 H: 3844.20 L: 1271	





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
33 4103-001 Airframe PART #12	PULSE CONTROL UNIT Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
33 4105-001 Airframe PART #1336	LH NLG LIGHT Part Number 2LA409800-05 Serial Number 1509047	21-MAR-2010 H: 0.00					
33 4105-002 Airframe PART #2223	RH NLG LIGHT Part Number 2LA409800-05 Serial Number 1509053	21-MAR-2010 H: 0.00					
33 4201-001 Airframe PART #2901	LH WING NAVIGATION (RED) LIGHT Part Number 2LA007181-22 Serial Number 1245607	08-OCT-2015 H: 1594.00 L: 564					
33 4201-002 Airframe PART #1315	RH WING NAVIGATION (GREEN) LIGHT Part Number 2LA007182-22 Serial Number 3076214	06-OCT-2015 H: 1594.00 L: 564					
33 4209-001 Airframe PART #1330	NOSE GEAR BAY/TAIL LIGHT. Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
33 4213-001 Airframe PART #882	FAILURE IND (MID CENTER FUSE) BOX Part Number GE536-0001-01 Serial Number 2920106	15-MAY-2015 H: 1435.60 L: 510					
33 43-09-201 Airframe INSPECTION 120M #4748	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION OF THE LOWER STROBE/ANTICOLLISION LIGHT CONNECTOR Reference Number AMM 33-43-09-210 -801	19-APR-2021 H: 3992.00 L: 1324	M: 120			19-APR-2031	M: 109 D: 3
33 4301-001 Airframe PART #2493	LH STROBE WING LIGHT Part Number 2LA006178-22 Serial Number 1558171	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
33 4301-002 Airframe PART #2870	RH STROBE WING LIGHT Part Number 2LA006178-22 Serial Number 1514100	21-MAR-2010 H: 0.00					
33 4301-003 Airframe PART #1966	STROBE WING LIGHT Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
33 4305-001 Airframe PART #616	STROBE (TAIL) LIGHT Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
33 4309-001 Airframe PART #1003	UPPER STROBE, ANTICOLLISION FUSELAGE LIGHT Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
33 4309-002 Airframe PART #2935	LOWER STROBE, ANTICOLLISION FUSELAGE LIGHT Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
33 4401-001 Airframe PART #870	LH WING/TAIL STROBE LIGHT POWER SUPPLY Part Number 8ES007046-22 Serial Number 1524103	21-MAR-2010 H: 0.00					
33 4401-002 Airframe PART #158	RH WING/TAIL STROBE LIGHT POWER SUPPLY Part Number 8ES007046-22 Serial Number 1533135	21-MAR-2010 H: 0.00					
33 4401-003 Airframe PART #1484	TAIL WING/TAIL STROBE LIGHT POWER SUPPLY Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
33 4405-001 Airframe PART #866	UPPER STROBE/ANTICOLLISION LIGHT POWER SUPPLY Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
33 4405-002 Airframe PART #1973	LOWER STROBE/ANTICOLLISION LIGHT POWER SUPPLY Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
33 4501-001 Airframe PART #1900	LH SCANLITE WING Part Number: 2LA455189-50 Serial Number: 1559488	21-MAR-2010 H: 0.00					
33 4501-002 Airframe PART #1370	RH SCANLITE WING Part Number: 2LA455189-50 Serial Number: 1559492	21-MAR-2010 H: 0.00					
33 4601-001 Airframe PART #298	LH LOGO LIGHT Part Number: 2LA455179-50 Serial Number: 1579051	21-MAR-2010 H: 0.00					
33 4601-002 Airframe PART #374	RH LOGO LIGHT Part Number: 2LA455179-50 Serial Number: 1579053	21-MAR-2010 H: 0.00					
33 50-00-201 Airframe INSPECTION 15M #2854	FUNCTIONAL TEST OF THE EMERGENCY LIGHTS POWER-SUPPLIES	19-APR-2021 H: 3992.00 L: 1324	M: 15	M: 3		19-JUL-2022	M: 4 D: 3
33 50-00-202 Airframe INSPECTION 1000 H #2765	OPERATIONAL TEST OF THE EMERGENCY LIGHTS	10-MAR-2022 H: 4455.80 L: 1495	H: 1000.00	H: 50.00		H: 5455.80	H: 1000.00
33 51-50-601 Airframe INSPECTION #2969	OPERATIONAL TEST OF THE CABIN EMERGENCY LIGHTING SYSTEM Reference Number: 33-51-50-710-801 Notes: NO DEFECTS NEEDED	07-JAN-2021 H: 3992.00 L: 1324	M: 30			07-JUL-2023	M: 15 D: 21
33 5101-001 Airframe PART #1861	LH PASSENGER DOOR LIGHT Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
33 5105-001 Airframe PART #2474	RH OVER WING L/E EMERGENCY EXIT LIGHT Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
33 5105-002 Airframe PART #2966	FS797-813 EMERGENCY LIGHT Part Number: GE535-0001-5 Serial Number: 1524375	21-MAR-2010 H: 0.00					
33 5109-001 Airframe PART #1068	NO.1 EMERGENCY LIGHTING POWER SUPPLY. FS 295RH, BELOW FLOOR. Part Number: 8ES409800-00 Serial Number: 4624	21-MAR-2010 H: 0.00					
33 5109-002 Airframe PART #2417	NO.2 (FS485 AFT) EMERGENCY LIGHTING POWER SUPPLY Part Number: 8ES409800-00 Serial Number: 4302	21-MAR-2010 H: 0.00					
33 5109-003 Airframe PART #1749	NO.3 (FSTA 605 RHS) EMERGENCY LIGHTING POWER SUPPLY. Part Number: 8ES409800-00 Serial Number: 4314	21-MAR-2010 H: 0.00					
	Notes STATION 605 RHS. OPEN PSU. BEHIND ACCESS PANEL.						
33 5109-004 Airframe PART #2144	NO.4 EMERGENCY LIGHTING POWER SUPPLY. FS 825. ABOVE BAGGAGE DOOR. Part Number: 3400-20 Serial Number: 003482	15-JUL-2020 H: 3806.80 L: 1260					
33 5109-701 Airframe PART #735	NO. 1 EMERGENCY LIGHT POWER SUPPLY BATTERY PACK Part Number: 8ES360000-00 Serial Number: 17521	21-AUG-2020 H: 3831.10 L: 1266					
33 5109-702 Airframe PART #2216	NO. 2 EMERGENCY LIGHT POWER SUPPLY BATTERY PACK Part Number: 3301-31 Serial Number: 9668	13-JUN-2017 H: 2318.30 L: 811					
33 5109-703 Airframe PART #1170	NO. 3 EMERGENCY LIGHT POWER SUPPLY BATTERY PACK Part Number: 8ES360000-00 Serial Number: 18904	15-APR-2021 H: 3992.00 L: 1324					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
33 5109-704 Airframe PART #1262	NO. 4 EMERGENCY LIGHT POWER SUPPLY BATTERY PACK Part Number: 8ES360000-00 Serial Number: 17508	15-JUL-2020 H: 3806.80 L: 1260					
33 PS554-LH4 Airframe PART #4929	MID CABIN POWER SUPPLY LH NO.4 Part Number: 8ES455827 Serial Number: 4445782	01-JUL-2019 H: 3385.70 L: 1135					
33 PS554-LH5 Airframe PART #4992	AFT CABIN POWER SUPPLY NO. 5 Part Number: 8ES455827-00 Serial Number: 4746766	26-MAR-2020 H: 3736.10 L: 1232					
	Notes R&R'ed Interior Lighting Power Supply PS554, LH cabin #5.						
34 0001 Airframe INSPECTION #4656	NAV DATABASE UPDATE	04-SEP-2019 H: 3478.30 L: 1159					
34 0109-001A Airframe INSPECTION #1 ADC #2610	RECERTIFY NO. 1 MICRO AIR DATA COMPUTER PER 14 CFR 91.411 Part Number: 7030700-70708 Serial Number: 9112341	09-MAR-2022 H: 4455.80 L: 1495	M: 24			09-MAR-2024	M: 23 D: 22
34 0109-002A Airframe INSPECTION #2 ADC #2517	RECERTIFY NO. 2 MICRO AIR DATA COMPUTER PER 14 CFR 91.411 Part Number: 7030700-70708 Serial Number: 9112342	09-MAR-2022 H: 4455.80 L: 1495	M: 24			09-MAR-2024	M: 23 D: 22
34 0109-003A Airframe INSPECTION #3 ADC #2475	RECERTIFY NO. 3 MICRO AIR DATA COMPUTER PER 14 CFR 91.411 Part Number: 7030700-70708 Serial Number: 9112346	09-MAR-2022 H: 4455.80 L: 1495	M: 24			09-MAR-2024	M: 23 D: 22
34 11-00-101 Airframe INSPECTION 24M #2369	FUNCTIONAL TEST OF THE AIR DATA COMPUTER, (RVSM QUALIFIED A/C)	09-MAR-2022 H: 4455.80 L: 1495	M: 24			09-MAR-2024	M: 23 D: 22
34 11-00-202 Airframe INSPECTION 24M #2115	FUNCTIONAL TEST OF THE PITOT-STATIC SYSTEMS	09-MAR-2022 H: 4455.80 L: 1495	M: 24			09-MAR-2024	M: 23 D: 22





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 11-01-201 Airframe INSPECTION 24M #2449	DETAILED INSPECTION OF THE PITOT-STATIC PROBES	09-MAR-2022 H: 4455.80 L: 1495	M: 24			09-MAR-2024	M: 23 D: 22
34 11-03-201 Airframe INSPECTION 15M #1207	SERVICING OF THE VISUAL DRAINS	19-APR-2021 H: 3992.00 L: 1324	M: 15	M: 3		19-JUL-2022	M: 4 D: 3
34 1105-001 Airframe PART #346	TOTAL TEMPERATURE SENSOR Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
34 1109-001 Airframe PART #795	NO. 1 MICRO AIR DATA COMPUTER Part Number 7030700-70708 Serial Number 9112341	10-FEB-2015 H: 1233.60 L: 448					
34 1109-002 Airframe PART #704	NO. 2 MICRO AIR DATA COMPUTER Part Number 7030700-70708 Serial Number 9112342	10-FEB-2015 H: 1233.60 L: 448					
34 1109-003 Airframe PART #2086	NO. 3 MICRO AIR DATA COMPUTER Part Number 7030700-70708 Serial Number 9112346	10-FEB-2015 H: 1233.60 L: 448					
34 12-01-201 Airframe INSPECTION #623	FUNCTIONAL TEST OF THE STANDBY AIRSPEED/ALTIMETER INDICATOR (A/C 9002 TO 9157)	21-MAR-2010 H: 0.00					
34 1201-001 Airframe PART #1613	INTEGRATED STANDBY INDICATOR Part Number C16221RA01 Serial Number C16221012 555	01-DEC-2018 H: 3011.20 L: 1025					
34 13-00-101 Airframe PART #2251	DISCARD THE NO. 1 PITOT STATIC PROBE Part Number 0856TT1 Serial Number 305006	29-JAN-2018 H: 2586.20 L: 898	H: 9600.00			H: 12186.20	H: 7730.40





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 13-00-101 Airframe PART #110	DISCARD THE NO. 2 PITOT STATIC PROBE Part Number: 0856TT4 Serial Number: 305800	29-JAN-2018 H: 2586.20 L: 898	H: 9600.00			H: 12186.20	H: 7730.40
34 13-00-101 Airframe PART #2548	DISCARD THE NO. 3 PITOT STATIC PROBE Part Number: 0856TT3 Serial Number: 304110	29-JAN-2018 H: 2586.20 L: 898	H: 9600.00			H: 12186.20	H: 7730.40
34 13-00-101 Airframe PART #2206	DISCARD THE STANDBY PITOT STATIC PROBE Part Number: 0856TT2 Serial Number: 301418	29-JAN-2018 H: 2586.20 L: 898	H: 9600.00			H: 12186.20	H: 7730.40
34 13-00-201 Airframe INSPECTION 24M #2227	FUNCTIONAL TEST OF THE INTEGRATED ELECTRONIC STANDBY INSTRUMENT (A/C 9158 AND SUBS)	09-MAR-2022 H: 4455.80 L: 1495	M: 24			09-MAR-2024	M: 23 D: 22
34 2101-001 Airframe PART #2823	STANDBY ATTITUDE HORIZON INDICATOR Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
34 2201-001 Airframe PART #884	STANDBY COMPASS Part Number: WL1001KCA1 Serial Number: BD0570409	21-MAR-2010 H: 0.00					
34 32-00-201 Airframe INSPECTION 1000 H #2994	DETAILED INSPECTION OF THE ELECTRO-OPTICAL UNIT HYGROMETER SENSOR (IF HUDS INSTALLED)	10-MAR-2022 H: 4455.80 L: 1495	H: 1000.00	H: 50.00		H: 5455.80	H: 1000.00
34 3200-701 Airframe PART #1512	OPTICAL PROJECTOR UNIT Part Number: GT546-0003-3 Serial Number: 563	15-FEB-2011 H: 25.00 L: 11					
34 3201-701 Airframe PART #2828	OPTICAL COMBINER UNIT Part Number: GT546-0004-5 Serial Number: 448	15-FEB-2011 H: 25.00 L: 11					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 3202-701 Airframe PART #2212	HUD COMPUTER Part Number GT546-0001-7 Serial Number 671	20-JAN-2014 H: 649.70 L: 284					
34 3203-701 Airframe PART #1198	HUD COMPUTER OBRM COMM MODULE Part Number E24738BA04 Serial Number 1499	26-JAN-2014 H: 649.70 L: 284					
34 3203-702 Airframe PART #627	HUD COMPUTER OBRM MONITOR MODULE Part Number E24739BA04 Serial Number 1565	26-JAN-2014 H: 649.70 L: 284					
34 3303-001 Airframe PART #1034	EVS SYSTEM - INFRARED (ISU) SENSOR UNIT Part Number GT546-1000-1 Serial Number 10041494	21-MAR-2010 H: 0.00					
34 3303-701 Airframe PART #1782	AC IDENTIFICATION (AIT) TAG Part Number GT546-1003-1 Serial Number 9481053	15-FEB-2011 H: 25.00 L: 11					
34 3309-001 Airframe PART #1392	EVS SYSTEM - HEATER (EVSHC) CONTROLLER Part Number GC584-1002-1 Serial Number 733623IN00 356	21-MAR-2010 H: 0.00					
34 41-01-301 Airframe PART #4902	RADAR ANTENNA KIT INSTALLATION Part Number 7021451-418 Serial Number 16015872	26-JAN-2019 H: 3131.30 L: 1057					
34 4101-001 Airframe PART #699	RADAR RECEIVER/TRANSMITTER ANTENNA Part Number 7021450-801 Serial Number 1309D110	14-JAN-2020 H: 3639.20 L: 1200					
34 4105-001 Airframe PART #2041	LH WEATHER RADAR CONTROLLER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
34 4105-002 Airframe PART #1677	RH WEATHER RADAR CONTROLLER Part Number 7008471-415 Serial Number 0905B366	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 4201-001 Airframe PART #235	ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) COMPUTER Part Number: 965-0976-040-206-206 Serial Number: 25316	06-OCT-2021 H: 4294.70 L: 1439					
34 4201-002 Airframe INSPECTION #4705	UPDATE EGPWS TERRAIN DATABASE	14-JUN-2021 H: 4081.50 L: 1358					
34 4301-001 Airframe PART #364	TCAS PROCESSOR Part Number: 7517900-10020 Serial Number: 20010886	04-MAR-2013 H: 430.70 L: 211					
34 4305-001 Airframe PART #1153	TCAS LOWER TCAS ANTENNA Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
34 4309-001 Airframe PART #1364	UPPER DIRECTIONAL TCAS ANTENNA Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
34 44-05-201 Airframe INSPECTION 60M #4742	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION OF THE RADIO ALTIMETER ANTENNAS CONNECTORS Reference Number: AMM 34-44-05-210-801	19-APR-2021 H: 3992.00 L: 1324	M: 60			19-APR-2026	M: 49 D: 3
34 4401-001 Airframe PART #62	NO. 1 RADIO ALTIMETER RECEIVER Part Number: 822-0615-207 Serial Number: 3Y99J Notes RECEIVED RAD ALT SN 4TTM1 DOA FROM VENDOR,CONFIRMED UNIT FAULTY AFTER REPOSITIONING FROM RH TO LH SIDE.	05-MAR-2022 H: 4446.70 L: 1492					
34 4401-002 Airframe PART #1297	NO. 2 RADIO ALTIMETER RECEIVER Part Number: 822-0615-207 Serial Number: 3LV9R	02-MAR-2022 H: 4436.50 L: 1489					
34 4405-001 Airframe PART #2513	TRANSCEIVER NO. 1 RADIO ALTIMETER ANTENNA Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 4405-002 Airframe PART #1366	TRANSCEIVER NO. 2 RADIO ALTIMETER ANTENNA Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
34 4405-003 Airframe PART #195	RECEIVER NO. 1 RADIO ALTIMETER ANTENNA Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
34 4405-004 Airframe PART #2975	RECEIVER NO. 2 RADIO ALTIMETER ANTENNA Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
34 4501-001 Airframe PART #730	NO. 1 IRU Part Number Serial Number HG2001GD03 56023775	01-FEB-2013 H: 430.20 L: 210					
34 4501-002 Airframe PART #2147	NO. 2 IRU Part Number Serial Number HG2001GD03 03069178	24-SEP-2014 H: 1010.50 L: 381					
34 4501-003 Airframe PART #427	NO. 3 IRU Part Number Serial Number HG2001GD03 01055379	18-OCT-2019 H: 3516.60 L: 1170					
34 4505-001 Airframe PART #415	MSU TRIPLEX MODE SELECT CONTROL PANEL Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
34 4601-001 Airframe PART #2371	CONTROL DISPLAY (IRS) UNIT Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
34 4701-001 Airframe PART #1763	LIGHTNING LP-860 PROCESSOR Part Number Serial Number 7011822-904 9092165	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 4705-001 Airframe PART #747	LIGHTNING, LSS SENSOR Part Number 7014062-901 Serial Number 9071487	21-MAR-2010 H: 0.00					
34 4706-001 Airframe PART #2444	(AT-850) ANTENNA Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
34 5101-001 Airframe PART #1767	NO. 1 RECEIVER NAVIGATION UNIT Part Number 7510100-631 Serial Number 01096023	04-DEC-2015 H: 1644.60 L: 585					
34 5101-002 Airframe PART #2080	NO. 2 RECEIVER NAVIGATION UNIT Part Number 7510100-631 Serial Number 0912C201	21-MAR-2010 H: 0.00					
34 5105-001 Airframe PART #400	LH VOR/ILS (WHITE) ANTENNA Part Number S65-247170-7 Serial Number 180-10817	04-MAR-2016 H: 1753.70 L: 622					
34 5105-002 Airframe PART #1580	RH VOR/ILS (WHITE) ANTENNA Part Number S65-247170-7 Serial Number 180-10063	04-MAR-2016 H: 1753.70 L: 622					
34 5109-001 Airframe PART #359	VOR/LOC PHASING COUPLER Part Number SSPD113-38 Serial Number 666-2178	21-MAR-2010 H: 0.00					
34 5117-001 Airframe PART #382	GLIDE SLOPE ANTENNA Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
34 5121-001 Airframe PART #2406	GLIDESLOPE ANTENNA DIPLEXER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					



Maintenance Items

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Page 181 of 653



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 5125-001 Airframe PART #746	BOTTOM MARKER BEACON ANTENNA Part Number PN	21-MAR-2010 H: 0.00					Serial Number SN- UNKNOWN
34 5201-001 Airframe PART #2214	NO. 1 ADF (AT-860) ANTENNA Part Number PN	21-MAR-2010 H: 0.00					Serial Number SN- UNKNOWN
34 5201-002 Airframe PART #1314	NO. 2 ADF (AT-860) ANTENNA Part Number PN	21-MAR-2010 H: 0.00					Serial Number SN- UNKNOWN
34 5301-001 Airframe PART #409	NO.1 LOWER DME ANTENNA Part Number S65-5366-10L	12-SEP-2012 H: 388.37 L: 190					Serial Number 10735
34 5301-002 Airframe PART #2939	NO.2 LOWER DME ANTENNA Part Number PN	21-MAR-2010 H: 0.00					Serial Number SN- UNKNOWN
34 5401-001 Airframe PART #1448	NO.1 UPPER ATC ANTENNA Part Number PN	21-MAR-2010 H: 0.00					Serial Number SN- UNKNOWN
34 5401-002 Airframe PART #606	NO.2 UPPER ATC ANTENNA Part Number PN	21-MAR-2010 H: 0.00					Serial Number SN- UNKNOWN
34 5401-003 Airframe PART #523	NO.1 LOWER ATC ANTENNA Part Number PN	21-MAR-2010 H: 0.00					Serial Number SN- UNKNOWN
34 5401-004 Airframe PART #2792	NO.2 LOWER ATC ANTENNA Part Number PN	21-MAR-2010 H: 0.00					Serial Number SN- UNKNOWN





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 5501-001 Airframe PART #2644	NO. 1 GLOBAL POSITIONING SENSOR UNIT Part Number HG2021GD04 Serial Number 1346	15-DEC-2016 H: 2092.00 L: 733					
	Notes MOD 4 INCORPORATED						
34 5501-002 Airframe PART #753	NO. 2 GLOBAL POSITIONING SENSOR UNIT Part Number HG2021GD04 Serial Number 1587	15-DEC-2016 H: 2092.00 L: 733					
	Notes MOD 4 INCORPORATED						
34 5505-001 Airframe PART #2881	LH GPS ANTENNA Part Number S67-1575-137 Serial Number 773-2256	24-JAN-2014 H: 649.70 L: 284					
34 5505-002 Airframe PART #2803	RH GPS ANTENNA Part Number S67-1575-137 Serial Number 773-2257	24-JAN-2014 H: 649.70 L: 284					
34 6101-001 Airframe PART #983	NO. 1 FMS CDU UNIT Part Number 2888-09-1 Serial Number C479382	03-DEC-2020 H: 3973.00 L: 1319					
34 6101-002 Airframe PART #689	NO. 2 FMS CDU UNIT Part Number 2888-09-1 Serial Number C388622	03-DEC-2014 H: 1111.80 L: 414					
34 6101-003 Airframe PART #1604	NO. 3 FMS CDU UNIT Part Number 2888-09-1 Serial Number F001264	25-FEB-2018 H: 2604.90 L: 910					
34 6201-001 Airframe PART #528	FMS DATA LOADER Part Number G7228-01 Serial Number 35049	29-JAN-2018 H: 2586.20 L: 898					
	Notes ON/OFF BUTTON INOP.						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 DOC 1024902 RB Airframe INSPECTION #5017	ELECTRICAL WIRING INTERCONNECTION SYSTEM EWIS INSPECTION- AVIONICS INSTRUMENTS 115VAC, 60 HZ CONVERTER, MID- CONTINENT CONTROLS GROUND FAULT INTERRUPTER (GFI), MID- CONTINENT CONTROLS AND EMTEQ OUTLETS	04-MAR-2016 H: 1753.70 L: 622					
34 DOC 1024902 RB Airframe INSPECTION #5016	GFI/OUTLET SYSTEM TEST- AVIONICS INSTRUMENTS 115VAC, 60 HZ CONVERTER, MID- CONTINENT CONTROLS GROUND FAULT INTERRUPTER (GFI), MID- CONTINENT CONTROLS AND EMTEQ OUTLETS	04-MAR-2016 H: 1753.70 L: 622					
34 DOC 1024902 RB Airframe INSPECTION #5015	INSTRUCTIONS FOR CONTINUED AIRWORTHINESS FOR AVIONICS INSTRUMENTS 115VAC, 60 HZ CONVERTER, MID- CONTINENT CONTROLS GROUND FAULT INTERRUPTER (GFI), MID- CONTINENT CONTROLS AND EMTEQ OUTLETS	04-MAR-2016 H: 1753.70 L: 622					
34 DOC 1024902 RC Airframe INSPECTION #5018	ELECTRICAL WIRING INTERCONNECTION SYSTEM EWIS INSPECTION- AVIONICS INSTRUMENTS 115VAC, 60 HZ CONVERTER, MID- CONTINENT CONTROLS GROUND FAULT INTERRUPTER (GFI), MID- CONTINENT CONTROLS AND EMTEQ OUTLETS	23-FEB-2021 H: 3992.00 L: 1324	M: 60			23-FEB-2026	M: 47 D: 7
34 DOC 1024902 RC Airframe INSPECTION #5019	GFI/OUTLET SYSTEM TEST- AVIONICS INSTRUMENTS 115VAC, 60 HZ CONVERTER, MID- CONTINENT CONTROLS GROUND FAULT INTERRUPTER (GFI), MID- CONTINENT CONTROLS AND EMTEQ OUTLETS	04-MAR-2016 H: 1753.70 L: 622					
34 DOC 1024902 RC Airframe INSPECTION #5020	INSTRUCTIONS FOR CONTINUED AIRWORTHINESS FOR AVIONICS INSTRUMENTS 115VAC, 60 HZ CONVERTER, MID- CONTINENT CONTROLS GROUND FAULT INTERRUPTER (GFI), MID- CONTINENT CONTROLS AND EMTEQ OUTLETS	04-MAR-2016 H: 1753.70 L: 622					
35 0001-701A Airframe INSPECTION #861	GENERAL VISUAL INSPECTION PORTABLE OXYGEN CYLINDER/REGULATOR ASSEMBLY OF THE PORTABLE OXYGEN CYLINDER AND MASK	07-NOV-2021 H: 4341.90 L: 1453	M: 12			07-NOV-2022	M: 7 D: 22
35 01-50-602 Airframe PART #2263	RESTORATION LH ENCLOSURE HALF FACE CREW OXYGEN MASK Part Number Serial Number MC20-004 1410601	04-MAR-2016 H: 1753.70 L: 622	M: 75			04-JUN-2022	M: 2 D: 19
35 10-05-201 Airframe PART #2700	RESTORATION LH FULL FACE CREW OXYGEN MASK Part Number Serial Number MF10-08-01 SE14463	03-DEC-2020 H: 3973.00 L: 1319	M: 75			03-FEB-2027	M: 58 D: 18
35 10-05-201 Airframe PART #2850	RESTORATION RH FULL FACE CREW OXYGEN MASK Part Number Serial Number MF10-08-01 1093971	29-JAN-2018 H: 2586.20 L: 898	M: 75			29-APR-2024	M: 25 D: 13





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
35 1000-001 Airframe PART #1157	S/O THERAPEUTIC OXYGEN VALVE Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
35 11-01-201 Airframe PART #1067	LEFT INBOARD OXYGEN STORAGE CYLINDER & REGULATOR BOTTLE Part Number 806371-1 Serial Number C07110466	29-SEP-2017 H: 2431.70 L: 854	M: 180			29-SEP-2032	M: 126 D: 13
35 11-01-201 Airframe PART #2583	LEFT OUTBOARD OXYGEN STORAGE CYLINDER & REGULATOR BOTTLE Part Number 806371-130 Serial Number C08070160	29-SEP-2017 H: 2431.70 L: 854	M: 180			29-SEP-2032	M: 126 D: 13
35 11-01-201 Airframe PART #2547	RIGHT INBOARD OXYGEN STORAGE CYLINDER & REGULATOR BOTTLE Part Number 806371-130 Serial Number CC0806015 1	29-SEP-2017 H: 2431.70 L: 854	M: 180			29-SEP-2032	M: 126 D: 13
35 11-01-201 Airframe PART #722	RIGHT OUTBOARD OXYGEN STORAGE CYLINDER & REGULATOR BOTTLE Part Number 806371-130 Serial Number C09050462- A	29-SEP-2017 H: 2431.70 L: 854	M: 180			29-SEP-2032	M: 126 D: 13
35 11-01-202 Airframe INSPECTION LH IB OXY CY #1632	FUNCTIONAL TEST (HYDROSTATIC) LEFT INBOARD OXYGEN STORAGE CYLINDER & REGULATOR BOTTLE Part Number 806371-1 Serial Number C07110466	16-APR-2020 H: 3741.10 L: 1233	M: 36			16-APR-2023	M: 13 D: 0
35 11-01-202 Airframe INSPECTION LH OB OXY CY #356	FUNCTIONAL TEST (HYDROSTATIC) LEFT OUTBOARD OXYGEN STORAGE CYLINDER & REGULATOR BOTTLE Part Number 806371-130 Serial Number C08070160	16-APR-2020 H: 3741.10 L: 1233	M: 36			16-APR-2023	M: 13 D: 0
35 11-01-202 Airframe INSPECTION RH IN OXY CY #243	FUNCTIONAL TEST (HYDROSTATIC) RIGHT INBOARD OXYGEN STORAGE CYLINDER & REGULATOR BOTTLE Part Number 806371-130 Serial Number CC0806015 1	16-APR-2020 H: 3741.10 L: 1233	M: 36			16-APR-2023	M: 13 D: 0
35 11-01-202 Airframe INSPECTION RHOB OXY CY #2724	FUNCTIONAL TEST (HYDROSTATIC) RIGHT OUTBOARD OXYGEN STORAGE CYLINDER & REGULATOR BOTTLE Part Number 806371-130 Serial Number C09050462- A	16-APR-2020 H: 3741.10 L: 1233	M: 36			16-APR-2023	M: 13 D: 0





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
35 11-01-202 Airframe PART #1278	RESTORATION PORTABLE OXYGEN CYLINDER/REGULATOR ASSEMBLY (HYDROSTATIC TEST) Part Number: 5600-9C1A-YON Serial Number: P13022534	03-JAN-2022 H: 4399.80 L: 1478	M: 36			03-JAN-2025	M: 33 D: 18
Notes HYDROSTATIC TEST, DUE.							
35 11-50-601 Airframe INSPECTION #275	OPERATIONAL TEST OF CREW OXYGEN SYSTEM MODIFICATIONS MASKS Reference Number: 35-11-50-710-801	06-JAN-2021 H: 3992.00 L: 1324	M: 30			06-JUL-2023	M: 15 D: 20
Notes NO DEFECTS NEEDED							
35 11-50-602 Airframe PART #1896	RESTORATION OF THE (CO-PILOT SWEEP-ON 2000) CREW OXYGEN SYSTEM MODIFICATIONS MASKS Reference Number: 35-11-50-615-801 Part Number: 174252-14 Serial Number: 28704	04-MAR-2016 H: 1753.70 L: 622	M: 75			04-JUN-2022	M: 2 D: 19
Notes THE TASK DUE TIME IS CALCULATED FROM THE DATE NOTED IN THE CERTIFICATION DOCUMENTATION.							
35 11-50-602 Airframe PART #1290	RESTORATION OF THE (PILOT SWEEP-ON 2000) CREW OXYGEN SYSTEM MODIFICATIONS MASKS Reference Number: 35-11-50-615-801 Part Number: 174252-14 Serial Number: 28851	04-MAR-2016 H: 1753.70 L: 622	M: 75			04-JUN-2022	M: 2 D: 19
Notes THE TASK DUE TIME IS CALCULATED FROM THE DATE NOTED IN THE CERTIFICATION DOCUMENTATION.							
35 1109-001 Airframe PART #1272	LH Oxygen STOWAGE BOX (PILOT) Part Number: MXP411-3 Serial Number: SE06151	16-NOV-2017 H: 2540.30 L: 889					
35 1109-002 Airframe PART #1853	RH Oxygen STOWAGE BOX (COPILOT) Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
35 1209-001 Airframe PART #2071	OXYGEN PRESSURE TRANSDUCER Part Number: GC481-0070-5 Serial Number: 6856	21-MAR-2010 H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
35 21-01-201 Airframe INSPECTION 30M #2740	FUNCTIONAL TEST OF THE PASSENGER OXYGEN CONTROL PANEL	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
35 2101-001 Airframe PART #901	PASSENGER OXYGEN ALTIMETRIC VALVE Part Number: 7003520006-001 Serial Number: 588	23-JAN-2011 H: 11.80 L: 6					
35 2101-002 Airframe PART #484	RH ALTIMETRIC VALVE Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
35 2102-001 Airframe PART #1032	PASSENGER OXYGEN CONTROLLER Part Number: GC481-0080-3 Serial Number: 480	05-NOV-2019 H: 3554.60 L: 1177					
35 3210-701 Airframe PART #297	PORTABLE OXYGEN CYLINDER/REGULATOR ASSEMBLY Part Number: 5600.9C1A-Y0N Serial Number: P15073060	13-JAN-2019 H: 3107.00 L: 1054					
35 3220-701B Airframe INSPECTION #4905	VISUAL INSPECTION OF THE OXYGEN MASK (AVOX)	07-NOV-2021 H: 4341.90 L: 1453	M: 12			07-NOV-2022	M: 7 D: 22
36 11-21-201 Airframe PART 2250H #2802	DISCARD LH PNEUMATIC TEMP THERMOSTAT OF THE (THC) FILTER Part Number: CG0752503245N02 Serial Number: NSN	31-MAR-2020 H: 3741.10 L: 1233	H: 2250.00			H: 5991.10	H: 1535.30
36 11-21-201 Airframe PART 2250H #880	DISCARD RH PNEUMATIC TEMP THERMOSTAT OF THE (THC) FILTER Part Number: CG0752503458N02 Serial Number: NSN	31-MAR-2020 H: 3741.10 L: 1233	H: 2250.00			H: 5991.10	H: 1535.30
36 11-61-101 Airframe PART #1504	APU CROSS BLEED VALVE UROSEAL CONNECTOR Part Number: GG468-4054-19 Serial Number: 4100	21-MAR-2010 H: 0.00	H: 8000.00			H: 8000.00	H: 3544.20





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
36 11-61-101 Airframe PART #1301	LH BLEED FILTER UROSEAL CONNECTOR Part Number Serial Number GG468-4054-15 4696	21-MAR-2010 H: 0.00	H: 8000.00			H: 8000.00	H: 3544.20
36 11-61-101 Airframe PART #99	LH CROSS BLEED VALVE UROSEAL CONNECTOR Part Number Serial Number GG468-4054-17 3389	21-MAR-2010 H: 0.00	H: 8000.00			H: 8000.00	H: 3544.20
36 11-61-101 Airframe PART #273	LH FAN AIR VALVE UROSEAL CONNECTOR Part Number Serial Number GG468-4054-15 4172	21-MAR-2010 H: 0.00	H: 8000.00			H: 8000.00	H: 3544.20
36 11-61-101 Airframe PART #711	LH FLOW CONTROL VALVE UROSEAL CONNECTOR Part Number Serial Number GG468-4054-15 9882	19-FEB-2019 H: 3169.10 L: 1068	H: 8000.00			H: 11169.10	H: 6713.30
	Notes REPLACED FOR L/H BLEED FAULT CAS						
36 11-61-101 Airframe PART #1243	LH FLOW SENSOR VENTURI UROSEAL CONNECTOR Part Number Serial Number GG468-4054-15 4703	21-MAR-2010 H: 0.00	H: 8000.00			H: 8000.00	H: 3544.20
36 11-61-101 Airframe PART #1078	RH BLEED FILTER UROSEAL CONNECTOR Part Number Serial Number GG468-4054-15 4711	21-MAR-2010 H: 0.00	H: 8000.00			H: 8000.00	H: 3544.20
36 11-61-101 Airframe PART #584	RH CROSS BLEED VALVE UROSEAL CONNECTOR Part Number Serial Number GG468-4054-17 3420	21-MAR-2010 H: 0.00	H: 8000.00			H: 8000.00	H: 3544.20
36 11-61-101 Airframe PART #701	RH FAN AIR VALVE UROSEAL CONNECTOR Part Number Serial Number GG468-4054-15 4234	21-MAR-2010 H: 0.00	H: 8000.00			H: 8000.00	H: 3544.20
36 11-61-101 Airframe PART #1265	RH FLOW CONTROL VALVE UROSEAL CONNECTOR Part Number Serial Number GG468-4054-15 9830	14-DEC-2018 H: 3033.70 L: 1035	H: 8000.00			H: 11033.70	H: 6577.90



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
36 11-61-101 Airframe PART #2663	RH FLOW SENSOR VENTURI UROSEAL CONNECTOR Part Number GG468-4054-15 Serial Number 4705	21-MAR-2010 H: 0.00	H: 8000.00			H: 8000.00	H: 3544.20
36 1101-001 Airframe PART #2029	LH HIGH PRESSURE BLEED VALVE Part Number GG436-1001-9 Serial Number 00196	24-SEP-2021 H: 4282.60 L: 1434					
36 1101-002 Airframe PART #1675	RH HIGH PRESSURE BLEED VALVE Part Number GG436-1001-9 Serial Number 944	23-SEP-2021 H: 4282.60 L: 1434					
36 1105-001 Airframe PART #1536	LH CHECK INTERMEDIATE PRESSURE VALVE Part Number GG436-1002-3 Serial Number 901	21-MAR-2010 H: 0.00					
36 1105-002 Airframe PART #2250	RH CHECK INTERMEDIATE PRESSURE VALVE Part Number GG436-1002-3 Serial Number 902	21-MAR-2010 H: 0.00					
36 1109-001 Airframe PART #2228	LH BLEED PRESS - REGULATING & S/O VALVE Part Number GG436-1055-3 Serial Number 14280	04-APR-2020 H: 3741.10 L: 1233					
	Notes C/W SB 700-36-025						
36 1109-002 Airframe PART #1750	RH BLEED PRESS - REGULATING & S/O VALVE Part Number GG436-1055-3 Serial Number 13940	23-SEP-2021 H: 4282.60 L: 1434					
	Notes C/W SB 700-36-025						
36 1113-001 Airframe PART #989	LH PRECOOLER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
36 1113-002 Airframe PART #1530	RH PRECOOLER Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
36 1113-003 Airframe PART #3038	LH PLENUM INLET Part Number GG468-4072-1 Serial Number 396	21-MAR-2010 H: 0.00					
36 1113-004 Airframe PART #670	RH PLENUM INLET Part Number GG468-4072-2 Serial Number 399	21-MAR-2010 H: 0.00					
36 1118-001 Airframe PART #2193	LH FAN AIR VALVE Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
36 1118-002 Airframe PART #412	RH FAN AIR VALVE Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
36 1121-001 Airframe PART #1572	LH PNEUMATIC TEMP THERMOSTAT Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
36 1121-002 Airframe PART #2983	RH PNEUMATIC TEMP THERMOSTAT Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
36 1125-001 Airframe PART #366	LH BLEED PRESSURE TRANSDUCER Part Number GG436-1007-1 Serial Number 2299	21-MAR-2010 H: 0.00					
36 1125-002 Airframe PART #2617	RH BLEED PRESSURE TRANSDUCER Part Number GG436-1007-1 Serial Number 13138	20-SEP-2021 H: 4282.60 L: 1434					
36 1130-001 Airframe PART #546	LH BOOT Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
36 1130-002 Airframe PART #367	RH BOOT Part Number PN	21-MAR-2010 H: 0.00					
	Serial Number SN- UNKNOWN						
36 1131-001 Airframe PART #1473	CROSS BLEED VALVE Part Number GG436-1008-7	21-MAR-2010 H: 0.00					
	Serial Number 1134						
36 1132-001 Airframe PART #2315	COUPLING COVER Part Number PN	21-MAR-2010 H: 0.00					
	Serial Number SN- UNKNOWN						
36 1133-001 Airframe PART #381	LH BLEED MANAGEMENT (BMC) CONTROLLER Part Number GG546-1017-13	22-SEP-2021 H: 4282.60 L: 1434					
	Serial Number 0418						
	Notes SWAPPED DUE TO ONE TIME WING A/I FAULT. (LH OB A/I TEMP SENSOR).						
36 1133-002 Airframe PART #1815	RH BLEED MANAGEMENT (BMC) CONTROLLER Part Number GG546-1017-13	22-SEP-2021 H: 4282.60 L: 1434					
	Serial Number 00941						
	Notes SWAPPED DUE TO ONE TIME WING A/I FAULT. (LH OB A/I TEMP SENSOR).						
36 1137-001 Airframe PART #1911	LH IP PRESSURE TRANSDUCER Part Number GG436-1018-1	21-MAR-2010 H: 0.00					
	Serial Number 1066						
36 1137-002 Airframe PART #2699	RH IP PRESSURE TRANSDUCER Part Number GG436-1018-1	21-MAR-2010 H: 0.00					
	Serial Number 1065						
36 1141-001 Airframe PART #498	HP GROUND CONNECTION Part Number PN	21-MAR-2010 H: 0.00					
	Serial Number SN- UNKNOWN						



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
36 1142-001 Airframe PART #2381	DUCT Part Number GG468-4066-3 Serial Number 402	21-MAR-2010 H: 0.00					
36 1209-701 Airframe PART #1846	HOT AIR LEAK DETECTION SENSING (MT 86) ELEMENT Part Number GG584-1026-9 Serial Number 12357/26/2	23-JAN-2011 H: 0.00					
38 Airframe PART #5087	FWD MAST DRAIN Part Number 24E50670G1 Serial Number N2019201	09-APR-2021 H: 3992.00 L: 1324					
38 -11-56 Airframe PART #5155	FWD LAV SIGNAL MAT SWITCH Part Number CVP623 Serial Number N/A	02-DEC-2021 H: 4368.30 L: 1464					
38 0007-701 Airframe PART #1094	POTABLE WATER TREATMENT UNIT Part Number 09-130021-102 Serial Number 1-1610	13-APR-2020 H: 3741.10 L: 1233					
38 0010-701 Airframe PART #1341	NO. 1 WATER PUMP Part Number 4E4360-1 Serial Number C588	08-MAR-2014 H: 716.70 L: 304					
38 0010-702 Airframe PART #4213	NO. 2 WATER PUMP Part Number PN Serial Number SN- UNKNOWN	H: 0.00					
38 0040-701 Airframe PART #2648	WATER TANK LEVEL WIRING HARNESS Part Number 4E4610-1 Serial Number N1402101	02-MAY-2014 H: 801.90 L: 326					
38 0050-701 Airframe PART #2394	AFT LAVATORY HEATED HOSE Part Number 4E4376-3 Serial Number N1531001	04-MAR-2016 H: 1753.70 L: 622					
38 0050-702 Airframe PART #4671	HEATED HOSE ASSEMBLY Part Number 4E4422-21 Serial Number N1221503	04-MAR-2016 H: 1753.70 L: 622					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
38 0050-703 Airframe PART #4912	HEATED DRAIN LINE FORWARD LAV BELOW FLOOR Part Number 4E4425-04 Serial Number N1902102	27-MAR-2019 H: 3247.10 L: 1090					
38 0060-701 Airframe PART #251	AFT ABOVE FLOOR HEATED DRAIN LINE Part Number 4E4425-08 Serial Number N1234202	01-NOV-2014 H: 1036.80 L: 395					
38 03-50-601 Airframe INSPECTION #1323	RESTORE POTABLE WATER TREATMENT UNIT	31-MAR-2020 H: 3741.10 L: 1233	H: 3000.00			H: 6741.10	H: 2285.30
38 1000-701 Airframe PART #1409	PWS ELECTRONIC INTERFACE (EIB) BOX Part Number 5E2651-20 Serial Number U242	15-FEB-2011 H: 25.00 L: 11					
38 1000-701 Airframe PART #5171	WASTE VACUUM GENERATOR Part Number 7800365 Serial Number 7345	07-MAR-2022 H: 4452.20 L: 1494					
38 1000-702 Airframe PART #5172	OUTBOARD WASTE VACCUM CHECK VALVE Part Number 7700647 Serial Number 0098	07-MAR-2022 H: 4452.20 L: 1494					
38 1001-701 Airframe PART #2933	EIB CONTROL PANEL Part Number 4E4381-1 Serial Number U0257	15-FEB-2011 H: 25.00 L: 11					
38 11-17-900-801-01 Airframe PART #4910	POTABLE WATER SYSTEM HEATED HOSE AFT WARDROBE Part Number 4E4422-21 Serial Number N123011	15-FEB-2011 H: 0.00					
38 11-50-602 Airframe INSPECTION #314	OPERATIONAL TEST OF THE WATER SUPPLY SHUT-OFF CIRCUIT Reference Number 38-11-50-710-802 Notes NO DEFECTS NEEDED	06-JAN-2021 H: 3992.00 L: 1324	M: 30			06-JUL-2023	M: 15 D: 20





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
38 1100-701 Airframe PART #2034	TOILET (FWD LAVATORY) ASSEMBLY Part Number: 7900268 Serial Number: 63-1721	15-FEB-2011 H: 25.00 L: 11					
38 1101-701 Airframe PART #2937	WATER (FWD LAVATORY) HEATER Part Number: 4E4099-2 Serial Number: N1308007	11-SEP-2020 H: 3852.30 L: 1275					
38 1200-701 Airframe PART #2494	GALLEY WATER HEATER Part Number: 4E4099-3 Serial Number: N1011901	15-FEB-2011 H: 25.00 L: 11					
38 13-50-601 Airframe INSPECTION #4901	RESTORE POTABLE WATER TREATMENT UNIT Notes THE TASK DUE TIME IS CALCULATED FROM THE DATE NOTED IN THE CERTIFICATION DOCUMENTATION.		H: 3000.00			H: 6000.00	H: 1544.20
38 1300-701 Airframe PART #1327	TOILET (AFT LAVATORY) ASSEMBLY Part Number: 7900268 Serial Number: 63-1722	15-FEB-2011 H: 25.00 L: 11					
38 1301-701 Airframe PART #1648	WATER (AFT LAVATORY) HEATER Part Number: 4E4099-3 Serial Number: N1006906	15-FEB-2011 H: 25.00 L: 11					
38 1510-701 Airframe PART #2317	AFT TOILET FLUSH BUTTON Part Number: 2600-1-1-T40PA Serial Number: 447TY0	04-JUN-2015 H: 1457.60 L: 515					
38 1520-701 Airframe PART #2747	LAV DUMP VALVE Part Number: 2651-357-5 Serial Number: 101970	17-JUN-2015 H: 1493.00 L: 523					
38 3050-701 Airframe PART #2905	ACTUATOR SHUTOFF VALVE Part Number: GP422-1404-3 Serial Number: AA136266	30-JAN-2013 H: 426.50 L: 209					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
38 3050-702 Airframe PART #4668	MOTORIZED WATER VALVE Part Number 4E4348-2 Serial Number N1402206	04-MAR-2016 H: 1753.70 L: 622					
38 3050-703 Airframe PART #4669	AFT LAVATORY RINSE VALVE Part Number 7800001-008 Serial Number 17071002	29-JAN-2018 H: 2586.20 L: 898					
38 3050-703 Airframe PART #4670	FWD LAVATORY RINSE VALVE Part Number 15800-470 Serial Number 1401	29-AUG-2019 H: 3470.40 L: 1157					
38 3050-704 Airframe PART #5124	L/H WATER TANK SENSOR Part Number 4E4610-1 Serial Number N1933901	03-APR-2021 H: 3992.00 L: 1324					
	Notes SQK.# 1013 / 12370797 W/O 235072						
38 3050-704 Airframe PART #4672	WATER PUMP SELECTOR VALVE Part Number 0AJJ04E4348-2 Serial Number N0734503	04-MAR-2016 H: 1753.70 L: 622					
	Notes TESTED						
38 31-50-601 Airframe INSPECTION #1058	GENERAL VISUAL INSPECTION OF THE FORWARD TOILET INSTALLATION Reference Number 38-31-50-210-801	07-JAN-2021 H: 3992.00 L: 1324	M: 30			07-JUL-2023	M: 15 D: 21
	Notes NO DEFECTS NEEDED						
38 3108-702 Airframe PART #5006	AFT MAST DRAIN Part Number 24E506700G1 Serial Number N2005004	07-APR-2020 H: 3741.10 L: 1233					
38 32-50-601 Airframe INSPECTION #227	GENERAL VISUAL INSPECTION OF THE AFT TOILET INSTALLATION Reference Number 38-32-50-210-801	07-JAN-2021 H: 3992.00 L: 1324	M: 30			07-JUL-2023	M: 15 D: 21
	Notes NO DEFECTS NEEDED						





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
38 DWG 7003810413 Airframe PART #4934	FWD LAV TOILET FLUSH HEATED LINE ITEM 14 Part Number 4E422-18 Serial Number N1511001	30-JUL-2019 H: 3424.90 L: 1147					
39 0010-001 Airframe PART #4673	RH UPPER FORWARD COWL DAMPER Part Number A3363-5 Serial Number 3952	04-MAR-2016 H: 1753.70 L: 622					
44 Airframe PART #5147	SWITCH PANEL, AFT DIVAN, AFT ARMREST Part Number 2601-1-6-T15SA Serial Number 3MD4T	23-SEP-2021 H: 4282.60 L: 1434					
	Notes S1=5, S2=0, S3=1						
44 1009-701 Airframe PART #2742	NO.1 RELAY DRIVE (RDE) EQUIPMENT Part Number 2052-1-10 Serial Number 3D6MC	15-FEB-2011 H: 25.00 L: 11					
44 1009-702 Airframe PART #2669	NO.2 RELAY DRIVE (RDE) EQUIPMENT Part Number 2052-1-10 Serial Number 3MKWG	15-FEB-2011 H: 25.00 L: 11					
44 1009-703 Airframe PART #865	NO.3 RELAY DRIVE (RDE) EQUIPMENT Part Number 2052-1-10 Serial Number 3MKWL	15-FEB-2011 H: 25.00 L: 11					
44 1009-704 Airframe PART #2485	NO.4 RELAY DRIVE (RDE) EQUIPMENT Part Number 2052-1-10 Serial Number 3MKWM	15-FEB-2011 H: 25.00 L: 11					
44 2002-701 Airframe PART #1974	AUDIO (A563) AMPLIFIER Part Number 3600-1-2 Serial Number 407XB	15-FEB-2011 H: 25.00 L: 11					
44 2500-701 Airframe PART #177	CREW REST CES IPOD CHARGER USB POWER SUPPLY Part Number 908-2040-001 Serial Number SMD140952 7	01-NOV-2014 H: 1036.80 L: 395					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
44 9500-701 Airframe PART #566	NO. 1 HEATER - BRAKE MONITORING UNIT Part Number: GHS269-0017 Serial Number: 1006	23-JAN-2011 H: 0.00					
45 45-00-201 Airframe INSPECTION 500H #288	VISUAL CHECK OF THE ENGINE MAINTENANCE ALERTS	10-MAR-2022 H: 4455.80 L: 1495	H: 500.00	H: 50.00		H: 4955.80	H: 500.00
45 4501-701 Airframe PART #2349	PORTABLE MAINTENANCE ACCESS TERMINAL PMAT Part Number: 7023300-801 Serial Number: 11090921	03-OCT-2013 H: 458.00 L: 229					
45 4510-701 Airframe PART #2509	PMAT BATTERY Part Number: 7037534-400 Serial Number: 411	29-JAN-2018 H: 2586.20 L: 898					
46 1015-701 Airframe PART #1762	GDC64 TABLET TO AIRCRAFT UNIT Part Number: 1104-4000-01 Serial Number: 17611	08-DEC-2015 H: 1644.60 L: 585					
46 1015-702 Airframe PART #1888	GDC64 TABLET TO AIRCRAFT UNIT Part Number: 1104-4000-01 Serial Number: 17612	08-DEC-2015 H: 1644.60 L: 585					
46 2001-701 Airframe PART #561	ELECTRONIC DISPLAY (EDU) - #1 UNIT Part Number: 245-604128-000 Serial Number: 1285	15-FEB-2011 H: 25.00 L: 11					
46 2001-702 Airframe PART #2344	ELECTRONIC DISPLAY (EDU) - #2 UNIT Part Number: 245-604128-000 Serial Number: 984	12-SEP-2012 H: 388.37 L: 190					
49 0002-001 APU PART #411	APU - WIRING HARNESS Part Number: WE3888471-1 Serial Number: 09-162599-00303	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
49 1010 APU PART #4687	APU - IGNITOR PLUG #1 Part Number WE3888401-1 Serial Number N/A	02-APR-2016 H: 1894.00 C: 1616					
49 1010 APU PART #4688	APU - IGNITOR PLUG #2 Part Number WE3888401-1 Serial Number NSN						
49 1011 APU PART #4689	APU - IGNITOR PLUG LEAD #1 Part Number WE3888353-3 Serial Number NA	09-NOV-2021 H: 3686.00 C: 3184					
49 1011 APU PART #4690	APU - IGNITOR PLUG LEAD #2 Part Number WE3888353-4 Serial Number NA	09-NOV-2021 H: 3686.00 C: 3184					
49 11-00-201 Airframe INSPECTION 30M #2138	VISUAL CHECK OF THE SUPPORT MOUNTINGS	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
49 11-01-201 Airframe INSPECTION 30M #3036	VISUAL CHECK OF THE MOUNTING STRUTS	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
49 1405-001 Airframe PART #2154	LINEAR ACTUATOR Part Number 8653M12 Serial Number 9020046	21-MAR-2010 H: 0.00					
49 15-00-201 Airframe INSPECTION 30M #1363	GENERAL VISUAL INSPECTION OF THE OIL COOLER-DUCT AND BOOT ASSEMBLY	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
49 15-09-201 Airframe INSPECTION 30M #1099	GENERAL VISUAL INSPECTION OF THE INLET DUCT AND BOOT ASSEMBLY	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
49 18-00-201 APU INSPECTION APU-1000H #2958	APU - GENERAL VISUAL INSPECTION OF THE APU DRAIN LINES Reference Number AMM 49-18-00-210 -801	17-JUL-2021 H: 3565.00 C: 3059	H: 1000.00	H: 50.00		H: 4565.00	H: 777.00
49 21-00-301 APU INSPECTION #1256	APU - CLEANING OF THE AUXILIARY POWER UNIT (APU) COMBUSTOR (PRE SB RE220-49-7813) Reference Number AMM 49-21-00-170 -801	07-APR-2014 H: 1008.00 C: 831					
49 21-00-302 APU INSPECTION #2245	APU - CLEANING OF THE AUXILIARY POWER UNIT (APU) COMBUSTOR (POST SB RE220-49-7813 AND APU S/N P-286 AND SUBS) Reference Number AMM 49-21-00-170 -801	04-MAR-2016 H: 1862.80 C: 1515	H: 2000.00	H: 50.00		H: 3862.80	H: 74.80
49 24-00-201 APU PART #2279	APU - COMPRESSOR IMPELLER Part Number WB3822573-1 Serial Number 09-162053-24487	21-MAR-2010 H: 0.00	C: 20000			C: 20000.00	C: 16726
49 24-00-202 APU PART #1450	APU - DISCARD THE 1ST STAGE AXIAL TURBINE DISK Part Number WK3840141-3 Serial Number 0922410018 17	21-MAR-2010 H: 0.00	C: 20000			C: 20000.00	C: 16726
49 24-00-203 APU PART #153	APU - DISCARD THE 2ND STAGE AXIAL TURBINE DISK Part Number WE897994-3 Serial Number 09-156101-06627	21-MAR-2010 H: 0.00	C: 20000			C: 20000.00	C: 16726
49 30-00-204 APU INSPECTION APU-1000H #4740	GENERAL VISUAL INSPECTION OF THE APU FUEL-SYSTEM COMPONENTS	17-JUL-2021 H: 3565.00 C: 3059	H: 1000.00	H: 50.00		H: 4565.00	H: 777.00
49 3001-001 APU PART #1343	APU - FUEL CONTROL UNIT FCU Part Number 441950-2 Serial Number CUB20547	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
49 4001-002 APU PART #2062	APU - STARTER MOTOR Part Number 2704554-3 Serial Number 1747	15-MAY-2020 H: 3317.00 C: 2786					
	Notes EXCESSIVE BRUSH WEAR.						
49 4101-001 APU PART #1378	APU - IGNITION EXCITER Part Number WE3876295-6 Serial Number J18230050	09-NOV-2021 H: 3686.00 C: 3184					
49 42-00-301 APU INSPECTION APU- 750H #2822	APU - CLEANING OF THE STARTER MOTOR OF BRUSH DUST MATERIAL Reference Number AMM 49-42-01-110 -801	10-MAR-2022 H: 3788.00 C: 3274	H: 750.00	H: 50.00		H: 4538.00	H: 750.00
49 42-01-201 APU INSPECTION APU-1000H #716	APU - DETAILED INSPECTION OF THE STARTER MOTOR Reference Number AMM 49-42-01-220 -801	17-JUL-2021 H: 3565.00 C: 3059	H: 1000.00	H: 50.00		H: 4565.00	H: 777.00
49 5101-001 APU PART #908	APU - SURGE VALVE Part Number 3291212-4 Serial Number 1074	21-MAR-2010 H: 0.00					
49 52-00-301 APU INSPECTION #4738	CLEANING OF THE LOAD-CONTROL-VALVE INLET FILTER (LOAD CONTROL VALVE P/N 3291210-3) Reference Number AMM 49-52-05-160 -801 Notes THIS TAST IS N/A DUE TO P/N 3291210-5 INSTALLED. (Ron G)						
49 5205-001 APU PART #182	APU - LOAD CONTROL VALVE Part Number 3291210-5 Serial Number 1888	21-MAR-2010 H: 0.00					
49 6102-001 APU PART #2087	APU - INLET PRESSURE SENSOR Part Number WE3876283-1 Serial Number 0911214211 06	21-MAR-2010 H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
49 6103-001 APU PART #2046	APU - SPEED SENSOR Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
49 6105-001 APU PART #2767	APU - NO. 1 EXHAUST GAS TEMPERATURE SENSOR Part Number Serial Number WE3876352-2 N/A	18-JUN-2017 H: 2374.00 C: 1916					
49 6105-002 APU PART #533	APU - NO. 2 EXHAUST GAS TEMPERATURE SENSOR Part Number Serial Number WE3876352-2 N/A	18-JUN-2017 H: 2374.00 C: 1916					
49 6110-001 Airframe PART #1169	FADEC CONTROLLER Part Number Serial Number 2118990-3 89-K0365	21-MAR-2010 H: 0.00					
49 62-00-201 APU INSPECTION #2082	APU - OPERATIONAL TEST OF THE APU EMERGENCY SHUTDOWN (APU SHUTDOWN SWITCH AND AFT SERVICE CONTROL PANEL APU SHUT-OFF SWITCH) Reference Number AMM 49-62-00-710 -802	04-MAR-2016 H: 1862.80 C: 1515	H: 2250.00	H: 50.00		H: 4112.80	H: 324.80
49 70-00-201 Airframe INSPECTION 1000 H #830	VISUAL CHECK OF THE APU INDICATING SYSTEM	10-MAR-2022 H: 4455.80 L: 1495	H: 1000.00	H: 50.00		H: 5455.80	H: 1000.00
49 7020-701 APU PART #1560	APU - APU CYCLE METER Part Number Serial Number WE3876069-1 NSN	29-SEP-2015 H: 1712.00 C: 1379					
49 80-05-201 Airframe INSPECTION 30M #763	GENERAL VISUAL INSPECTION OF THE APU-EXHAUST TAILPIPE-DUCT	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
49 80-09-201 Airframe INSPECTION 30M #2546	GENERAL VISUAL INSPECTION OF THE APU-EXHAUST TAILPIPE-DUCT SEAL	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
49 8004-001 Airframe PART #791	APU EXHAUST DUCT ASSY (LOWER) INSULATION Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
49 8005-001 Airframe PART #2165	THERMAL BLANKET Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
49 8006-001 Airframe PART #783	EXHAUST TAILPIPE DUCT Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
49 90-00-204 APU INSPECTION APU-1000H #4741	GENERAL VISUAL INSPECTION OF THE APU OIL-SYSTEM COMPONENTS	17-JUL-2021 H: 3565.00 C: 3059	H: 1000.00	H: 50.00		H: 4565.00	H: 777.00
49 90-29-201 APU INSPECTION APU-1500H #432	APU - DISCARD THE APU OIL-FILTER ELEMENT Reference Number AMM 49-90-29-961 -801	08-DEC-2019 H: 3204.00 C: 2674	H: 1500.00	H: 50.00		H: 4704.00	H: 916.00
49 90-29-202 APU INSPECTION APU-1500H #742	APU - DISCARD THE APU-GENERATOR SCAVENGE-OIL FILTER-ELEMENT Reference Number AMM 49-90-29-961 -802	08-DEC-2019 H: 3204.00 C: 2674	H: 1500.00	H: 50.00		H: 4704.00	H: 916.00
49 9001-001 APU PART #128	APU - OIL COOLER Part Number Serial Number 160534-1 1594	15-JUL-2020 H: 3352.00 C: 2826					
49 9002-001 APU PART #1780	APU - LUBE PUMP Part Number Serial Number WE3881781-1 VE2626	21-MAR-2010 H: 0.00					
49 9035-001 APU PART #2945	APU - DIFFERENTIAL PRESSURE-GENERATOR SWITCH Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
49 9053-001 APU PART #1328	APU - APU GEARBOX Part Number WK3805055-6 Serial Number 0922410105 11	21-MAR-2010 H: 0.00					
49 APU1 Airframe PART #4419	APU Part Number WE3800714-1 Serial Number P-512	H: 0.00					
52 10-00-207 Airframe INSPECTION 1500H #130	LUBRICATION OF THE PASSENGER DOOR	08-FEB-2022 H: 4399.80 L: 1478	H: 1500.00	H: 50.00		H: 5899.80	H: 1444.00
52 11-00-101 Airframe INSPECTION #1402	DETAILED INSPECTION OF THE OUTER SKIN OF THE PASSENGER DOOR	21-MAR-2010 H: 0.00	L: 5255			L: 5255	L: 3760
52 11-00-102 Airframe INSPECTION 7500 L #1261	SPECIAL DETAILED INSPECTION OF THE PASSENGER DOOR MOUNTING SIDE FRAMES Reference Number NDT ET-52-10-001	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
52 11-00-103 Airframe INSPECTION 7500 L #193	DETAILED INSPECTION OF THE PASSENGER DOOR MOUNTING SIDE-FRAMES, STOPS, SKIN AND STIFFENERS - INTERNAL	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
52 11-00-105 Airframe INSPECTION 3750 L #3931	GENERAL VISUAL INSPECTION OF THE SKIN EXTERNAL SURFACE	H: 0.00	L: 3750			L: 3750	L: 2255
52 11-00-201 Airframe INSPECTION 2250H #1729	FUNCTIONAL TEST OF THE PASSENGER DOOR MECHANISM	31-MAR-2020 H: 3741.10 L: 1233	H: 2250.00	H: 50.00		H: 5991.10	H: 1535.30
52 11-00-202 Airframe INSPECTION 120M #1230	DETAILED INSPECTION OF THE INTERNAL STRUCTURE OF THE PASSENGER DOOR	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
52 11-00-203 Airframe INSPECTION 120M #168	DETAILED INSPECTION OF THE STOPS AND ABUTMENTS OF THE PASSENGER DOOR	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
52 11-00-205 Airframe INSPECTION 750H/30M #213	VISUAL CHECK OF THE PASSENGER-DOOR VENT-FLAP MECHANISM	08-FEB-2022 H: 4399.80 L: 1478	H: 750.00	H: 50.00		H: 5149.80	H: 694.00
52 11-21-201 Airframe INSPECTION 120M #1116	DETAILED INSPECTION OF THE HANDRAILS ATTACHMENT TO THE FUSELAGE	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
52 11-25-101 Airframe INSPECTION #1482	RESTORATION OF THE PASSENGER DOOR ACTUATOR MOTOR, PART NO. GS321-0591-9 (GEARHEAD, PART NO. 2H4A321809A)	31-MAR-2020 H: 3741.10 L: 1233	L: 850			L: 2083	L: 588
52 11-41-101 Airframe INSPECTION #2487	DISCARD THE PASSENGER DOOR TENSATOR SPRING, PART NO. GS321-0580-1	31-MAR-2020 H: 3741.10 L: 1233	L: 650			L: 1883	L: 388
52 1100-001 Airframe PART #1778	PASSENGER DOOR ASSY Part Number GS328-0010-1 Serial Number C162	21-MAR-2010 H: 0.00					
52 1121-701 Airframe PART #2580	FWD PASSENGER HANDRAIL ASSEMBLY Part Number GS328-0014-1 Serial Number 161551	28-AUG-2013 H: 462.90 L: 220					
52 1121-702 Airframe PART #1407	AFT PASSENGER HANDRAIL ASSEMBLY Part Number GS328-0014-2 Serial Number 162968	28-AUG-2013 H: 462.90 L: 220					
52 1125-001 Airframe PART - Life Limited #2081	PASSENGER DOOR ACTUATOR MOTOR Part Number GS321-0591-9 Serial Number F0315	21-JUL-2020 H: 3814.00 L: 1262	L: 850		M: 4 H: 3814.00 L: 1262	L: 2112	L: 617



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
52 1129-001 Airframe PART #1859	PASSENGER DOOR AIRSTAIR Part Number: GS328-0009-3 Serial Number: SBGX11162	21-MAR-2010 H: 0.00					
52 1161-701 Airframe PART #2702	DOOR STEP ACTUATOR Part Number: GS321-0988-3 Serial Number: 293	12-SEP-2012 H: 388.37 L: 190					
52 21-00-103 Airframe INSPECTION 3750 L #837	GENERAL VISUAL INSPECTION OF THE EXTERNAL SKIN OF THE OVERWING EMERGENCY EXIT	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
52 21-00-104 Airframe INSPECTION #4982	DETAILED INSPECTION OF THE OVER-WING EMERGENCY EXIT DOOR		L: 7500			L: 7500	L: 6005
52 21-00-201 Airframe INSPECTION 15M #326	OPERATIONAL TEST OF THE OVER-WING EMERGENCY-EXIT Notes NO DEFECTS NOTED	19-APR-2021 H: 3992.00 L: 1324	M: 15	M: 3		19-JUL-2022	M: 4 D: 3
52 21-00-202 Airframe INSPECTION 30M #663	FUNCTIONAL TEST OF THE OVER-WING EMERGENCY-EXIT EXIT PULL SIGN Notes NO DEFECTS NOTED	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
52 21-00-203 Airframe INSPECTION 30M #608	LUBRICATION OF THE OVER-WING EMERGENCY-EXIT DOOR	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
52 21-00-204 Airframe INSPECTION 60M #361	DETAILED INSPECTION OF THE LATCH FITTINGS AND DOOR STOP FITTINGS OF THE OVER-WING EMERGENCY EXIT Notes NO DEFECTS NOTED	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
52 21-00-205 Airframe INSPECTION 120M #1015	DETAILED INSPECTION OF THE INTERNAL SKIN AND STRUCTURE OF THE OVER-WING EMERGENCY EXIT	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
	Notes NO DEFECTS NOTED						
52 2100-001 Airframe PART #1883	OVERWING EMERGENCY EXIT DOOR ASSY Part Number GM329-3002-1 Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
52 30-00-101 Airframe INSPECTION #891	DETAILED INSPECTION OF THE BAGGAGE DOOR	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
52 30-00-105 Airframe INSPECTION #1615	SPECIAL DETAILED INSPECTION OF THE BAGGAGE DOOR SKIN BETWEEN DOOR UPPER SKIN EDGE AND VENT DOOR	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
52 30-00-106 Airframe INSPECTION #1249	DETAILED INSPECTION OF THE VENT DOOR OF THE BAGGAGE DOOR	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
52 30-00-107 Airframe INSPECTION 7500 L #1730	SPECIAL DETAILED INSPECTION OF THE BAGGAGE DOOR	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
52 30-00-108 Airframe INSPECTION 3750 L #1404	GENERAL VISUAL INSPECTION OF THE EXTERNAL SURFACE OF THE BAGGAGE DOOR SKIN INCLUDING DOOR HANDLE RECESS	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
52 30-00-201 Airframe INSPECTION 120M #2301	DETAILED INSPECTION OF THE SURROUND ANGLES AND STOP FITTINGS OF THE BAGGAGE DOOR	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
52 30-00-202 Airframe INSPECTION 120M #436	DETAILED INSPECTION OF THE INTERNAL SUPPORT STRUCTURE OF THE BAGGAGE DOOR	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
52 30-00-301 Airframe INSPECTION 30M #1889	LUBRICATION OF THE BAGGAGE DOOR	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
52 31-09-101 Airframe INSPECTION 15M #1244	DETAILED INSPECTION OF THE BAGGAGE DOOR SEAL	19-APR-2021 H: 3992.00 L: 1324	M: 15	M: 3		31-JUL-2022	M: 4 D: 15
52 3101-001 Airframe PART #3035	BAGGAGE COMPARTMENT DOOR ASSY Part Number Serial Number GD329-1000-1 SN- UNKNOWN	21-MAR-2010 H: 0.00					
52 41-00-201 Airframe INSPECTION 30M #650	DETAILED INSPECTION OF THE AFT EQUIPMENT-COMPARTMENT DOOR SEAL	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
52 4102-001 Airframe PART #454	REAR EQUIPMENT BAY DOOR Part Number Serial Number GS297-0304-7 SN- UNKNOWN	21-MAR-2010 H: 0.00					
52 4201-001 Airframe PART #779	LH ASSY - ACCESS DOOR Part Number Serial Number GC219-0104-3 E461265	21-MAR-2010 H: 0.00					
52 4201-002 Airframe PART #1313	RH ASSY - ACCESS DOOR Part Number Serial Number GC219-0104-4 D789241	21-MAR-2010 H: 0.00					
52 4301-701 Airframe PART #2779	LH APU ACCESS DOOR Part Number Serial Number GD239-6751-3 SB0309	15-FEB-2011 H: 25.00 L: 11					
52 4301-702 Airframe PART #770	RH APU ACCESS DOOR Part Number Serial Number GD239-6775-3 SB0307	15-FEB-2011 H: 25.00 L: 11					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
52 4425-001 Airframe PART #2059	CASTING DOOR Part Number GD236-5060-5 Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
52 4437-001 Airframe PART #541	DOOR CASTING Part Number GD236-3020-5 Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
52 4509-001 Airframe PART #1624	FORWARD EQUIPMENT COMPARTMENT DOOR Part Number GC219-0200-13 Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
52 71-50-601 Airframe INSPECTION #2980	OPERATIONAL TEST OF THE CABIN DOOR ANNUNCIATION SYSTEM Reference Number 52-71-50-710-801 Notes NO DEFECTS NEEDED	07-JAN-2021 H: 3992.00 L: 1324	M: 30			07-JUL-2023	M: 15 D: 21
52 ZL-00-201 Airframe INSPECTION 60M #2387	GENERAL VISUAL INSPECTION OF THE OVER-WING EMERGENCY EXIT - EXTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
52 ZL-00-202 Airframe INSPECTION 60M #1607	GENERAL VISUAL INSPECTION OF THE LATCH MECHANISM OF THE OVER-WING EMERGENCY EXIT Notes NO DEFECTS NOTED	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
52 ZL-00-203 Airframe INSPECTION 120M #2737	GENERAL VISUAL INSPECTION OF THE BAGGAGE DOOR - INBOARD SIDE	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
52 ZL-00-204 Airframe INSPECTION 120M #1684	GENERAL VISUAL INSPECTION OF THE BAGGAGE DOOR - OUTBOARD SIDE	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
52 ZL-00-205 Airframe INSPECTION #1740	GENERAL VISUAL INSPECTION OF THE PASSENGER DOOR - EXTERNAL	05-MAR-2022 H: 4446.70 L: 1492	M: 24	M: 3		05-MAR-2024	M: 23 D: 18
53 10-00-101 Airframe INSPECTION #508	DETAILED INSPECTION OF THE NOSE WHEEL WELL AND FRAME, FS251.00	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 10-00-102 Airframe INSPECTION 7500 L #1834	DETAILED INSPECTION OF THE LANDING GEAR BOX	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 10-00-103 Airframe INSPECTION 7500 L #200	DETAILED INSPECTION OF THE FLOOR ATTACHMENT TO THE BULKHEAD, FS202.00	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 10-00-104 Airframe INSPECTION #135	DETAILED INSPECTION OF THE BULKHEAD, FS202.00 Reference Number AMM: 53-10-00-220-822	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 10-00-105 Airframe INSPECTION #1304	GENERAL VISUAL INSPECTION OF THE FRAME, FS251.00 Reference Number AMM 53-10-00-210-822	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 10-00-106 Airframe INSPECTION #2220	SPECIAL DETAILED INSPECTION OF THE FRAME, FS280.00 - EXTERNAL	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 10-00-107 Airframe INSPECTION #1365	DETAILED INSPECTION OF THE FRAME, FS280.00 - INTERNAL	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 10-00-108 Airframe INSPECTION 7500 L #538	SPECIAL DETAILED INSPECTION OF THE SPLICE AT STRINGERS 16A AND 23 Reference Number NDT: ET-53-10-005	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 10-00-109 Airframe INSPECTION #1813	DETAILED INSPECTION OF THE SHEET METAL FRAME, FS210.00, FS220.00, FS235.00, FS265.00 Reference Number AMM 53-10-00-220 -826	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 10-00-110 Airframe INSPECTION 7500 L #778	DETAILED INSPECTION OF THE STRINGERS 16A AND 23, FROM FS202.00 TO FS280.00	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 10-00-112 Airframe INSPECTION 7500 L #1759	SPECIAL DETAILED INSPECTION OF THE COCKPIT WINDOW SURROUND STRUCTURE Reference Number NDT: ET-53-10-006 & ET-53-10-007	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 10-00-114 Airframe INSPECTION 7500 L #1231	DETAILED INSPECTION OF THE COCKPIT SKIN PANELS	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 10-00-115 Airframe INSPECTION #152	SPECIAL DETAILED INSPECTION OF THE COCKPIT WINDOW CENTER POST	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 10-00-116 Airframe INSPECTION #1162	SPECIAL DETAILED INSPECTION OF THE COCKPIT WINDOW LOWER SILL AT THE CENTER POST ATTACHMENT NEAR BL0	21-MAR-2010 H: 0.00	L: 6620			L: 6620	L: 5125
53 10-00-117 Airframe INSPECTION 3750 L #2076	DETAILED INSPECTION OF THE FORWARD FACE OF BULKHEAD, FS202.75, ABOVE FLOOR	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 10-00-118 Airframe INSPECTION 3750 L #1369	DETAILED INSPECTION OF THE FORWARD FACE OF BULKHEAD, FS202.75 WEB, BELOW FLOOR	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 10-00-119 Airframe INSPECTION 3750 L #2782	GENERAL VISUAL INSPECTION OF THE EXTERNAL SKIN, FS169.00 TO FS280.00	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 10-00-120 Airframe INSPECTION 3750 L #13	DETAILED INSPECTION OF THE LONGITUDINAL AND CIRCUMFERENTIAL SKIN JOINTS, FS202.75 TO FS280.00	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 10-00-121 Airframe INSPECTION 3750 L #558	DETAILED INSPECTION OF THE NLG AND PRESSURIZED PANEL CUTOUT SURROUND STRUCTURE	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 10-00-122 Airframe INSPECTION 3750 L #106	DETAILED INSPECTION OF THE WINDSHIELD AND SIDE-WINDOW CUTOUT SURROUND STRUCTURE	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 10-00-123 Airframe INSPECTION 3750 L #1700	DETAILED INSPECTION OF THE PRESSURIZED SURFACES OF THE NOSE LANDING GEAR (NLG) WHEEL WELL STRUCTURE	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 10-00-124 Airframe INSPECTION 7500 L #2987	DETAILED INSPECTION OF THE ACCESS PANEL SURROUND STRUCTURE	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 10-00-125 Airframe INSPECTION #4961	DETAILED INSPECTION OF THE SKIN SPLICE, FS280.00 - EXTERNAL		L: 7500			L: 7500	L: 6005
53 10-00-126 Airframe INSPECTION #4971	DETAILED INSPECTION OF THE COCKPIT WINDOW SURROUND STRUCTURE, GUSSET AND SIDE PLATES		L: 6639			L: 6639	L: 5144
53 10-00-201 Airframe INSPECTION #2861	DETAILED INSPECTION OF THE INTERNAL STRUCTURE, FS169.00 TO FS202.75, ABOVE FLOOR	10-FEB-2021 H: 3992.00 L: 1324	M: 60	M: 3		10-FEB-2026	M: 46 D: 25
53 10-00-202 Airframe INSPECTION #587	DETAILED INSPECTION OF THE INTERNAL STRUCTURE, FS169.00 TO FS202.75, BELOW FLOOR	31-JAN-2021 H: 3992.00 L: 1324	M: 60	M: 3		31-JAN-2026	M: 46 D: 15
	Notes NO DEFECTS NOTED						





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 10-00-203 Airframe INSPECTION #1141	DETAILED INSPECTION OF THE INTERNAL FORWARD FUSELAGE SKIN/STRUCTURE AND FS280.00 BULKHEAD FORWARD FACE, FS202.75 TO FS280.00, ABOVE WL79.50	21-MAR-2010 H: 0.00	M: 180	M: 3		21-MAR-2025	M: 36 D: 5
53 10-00-205 Airframe INSPECTION #2508	DETAILED INSPECTION OF THE PILOT AND COPILOT SEAT TRACKS	07-JAN-2021 H: 3992.00 L: 1324	M: 60	M: 3		07-JAN-2026	M: 45 D: 22
	Notes NO DEFECTS NOTED						
53 10-00-207 Airframe INSPECTION 120M #929	DETAILED INSPECTION OF THE FLOOR STRUCTURE, FS202.75 TO FS280.00	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
	Notes NO DEFECTS NOTED						
53 10-00-208 Airframe INSPECTION 120M #140	DETAILED INSPECTION OF THE FORWARD JACKING POINT, FS278.00	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 10-00-209 Airframe INSPECTION #1470	DETAILED INSPECTION OF THE WINDSHIELD AND SIDE-WINDOW SURROUND STRUCTURE AND RETAINERS	21-MAR-2010 H: 0.00	M: 180	M: 3		21-MAR-2025	M: 36 D: 5
	Notes NOTE: IF THERE IS ACCESS TO THE FUSELAGE INTERNAL STRUCTURE (ABOVE WL71.50 FROM FS280.00 TO FS781.00) DURING THE 120 M INSPECTION, IT IS PERMITTED TO DO THIS 180 M TASK AT THE 120 M INSPECTION. THIS WILL PREVENT THE REMOVAL OF THE INTERIOR (GALLEY, LAVATORY, SIDE PANELS, HEADLINERS ETC.) AT 180 M.						
53 10-00-210 Airframe INSPECTION 60M #2851	DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) WHEEL WELL STRUCTURE	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
	Notes NO DEFECTS NOTED						
53 10-00-211 Airframe INSPECTION 120M #75	DETAILED INSPECTION OF THE INTERNAL STRUCTURE, FS202.75 TO FS280.00, BELOW FLOOR	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 10-00-212 Airframe INSPECTION 120M #4749	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION OF THE FLIGHT COMPARTMENT CONNECTORS Reference Number AMM 53-10-00-210 -824	19-APR-2021 H: 3992.00 L: 1324	M: 120			19-APR-2031	M: 109 D: 3
53 10-00-213 Airframe INSPECTION 180M #4744	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION ON THE FORWARD FACE OF THE FORWARD PRESSURE BULKHEAD CONNECTORS, FS202.00 Reference Number AMM 53-10-00-210 -825 Notes NOTE: IF THERE IS ACCESS TO THE FUSELAGE INTERNAL STRUCTURE (ABOVE WL71.50 FROM FS280.00 TO FS781.00) DURING THE 120 M INSPECTION, IT IS PERMITTED TO DO THIS 180 M TASK AT THE 120 M INSPECTION. THIS WILL PREVENT THE REMOVAL OF THE INTERIOR (GALLEY, LAVATORY, SIDE PANELS, HEADLINERS ETC.) AT 180 M.		M: 180	M: 3		15-FEB-2026	M: 46 D: 30
53 1101-001 Airframe PART #2195	FLOOR - FLIGHT COMPARTMENT PANEL Part Number PN Serial Number SN- UNKNOWN						
53 1105-001 Airframe PART #2951	CRAWLWAY PANEL ASSY Part Number PN Serial Number SN- UNKNOWN						
53 20-00-101 Airframe INSPECTION #1270	DETAILED INSPECTION OF THE FUSELAGE UPPER SKIN AND LONGITUDINAL JOINTS FROM, FS381.00 TO FS557.00 - EXTERNAL Reference Number AMM 53-20-00-220 -864	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 20-00-104 Airframe INSPECTION #1836	SPECIAL DETAILED INSPECTION OF THE FUSELAGE KEEL BEAM	21-MAR-2010 H: 0.00	L: 6082			L: 6082	L: 4587
53 20-00-105 Airframe INSPECTION #1463	SPECIAL DETAILED INSPECTION OF THE OVER-WING LONGERON, FS525.00 TO FS574.00 Reference Number NDT ET-53-20-006	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 20-00-106 Airframe INSPECTION #483	SPECIAL DETAILED INSPECTION OF THE PRESSURE FLOOR AND THE STIFFENERS OF THE PRESSURE BULKHEAD FROM FS557.00 TO FS574.50	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 20-00-109 Airframe INSPECTION #1821	SPECIAL DETAILED INSPECTION OF THE SKIN AND FUSELAGE JOINTS FROM, FS281.00 TO FS557.00 - EXTERNAL Reference Number NDT: UT-53-20-001 & ET-53-20-007	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 20-00-110 Airframe INSPECTION #60	DETAILED INSPECTION OF THE FUSELAGE SKIN FROM, FS281.00 TO FS381.00 - EXTERNAL Reference Number AMM 53-20-00-220-863	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 20-00-117 Airframe INSPECTION #974	DETAILED INSPECTION OF THE PASSENGER DOOR CUTOUT STRUCTURE AND FITTINGS	21-MAR-2010 H: 0.00	L: 5848			L: 5848	L: 4353
53 20-00-118 Airframe INSPECTION 7500 L #1564	SPECIAL DETAILED INSPECTION OF THE FUSELAGE BARREL JOINT, FS381.00 Reference Number NDT: ET-53-20-003	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 20-00-119 Airframe INSPECTION 7500 L #790	SPECIAL DETAILED INSPECTION OF THE INTERNAL STRUCTURE OF THE FUSELAGE BARREL JOINTS, FS381.00 AND FS557.00 Reference Number NDT: ET-53-20-005	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 20-00-120 Airframe INSPECTION 7500 L #3039	SPECIAL DETAILED INSPECTION OF THE FUSELAGE BARREL JOINT, FS557.00 Reference Number NDT: ET-53-20-004	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 20-00-122 Airframe INSPECTION 7500 L #2812	DETAILED INSPECTION OF THE MACHINED FITTINGS AND SKIN AROUND THE SERVICE DOOR, FS295.00 TO FS310.00 AND STR22R TO STR24R Reference Number 53-20-00-220-832 Notes NOTE: THIS TASK IS ONLY APPLICABLE TO AIRCRAFT WITH THE SERVICE DOOR CUTOUT.	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 20-00-123 Airframe INSPECTION 7500 L #2201	DETAILED INSPECTION OF THE AVIONICS BAY DOOR AND SURROUNDING SKIN Reference Number AMM 53-20-00-220-862	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 20-00-124 Airframe INSPECTION 7500 L #1118	DETAILED INSPECTION OF THE WING INSPECTION LIGHT INSTALLATION Reference Number AMM 53-20-00-220 -865	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 20-00-125 Airframe INSPECTION #2451	DETAILED INSPECTION OF THE STRINGERS AND FRAMES FROM, FS381.00 TO FS557.00 Reference Number AMM 53-20-00-220 -860	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 20-00-126 Airframe INSPECTION #9	DETAILED INSPECTION OF THE FUSELAGE STRINGERS AND FRAMES FROM, FS281.00 TO FS381.00 Reference Number AMM 53-20-00-220 -861	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 20-00-127 Airframe INSPECTION 7500 L #2367	GENERAL VISUAL INSPECTION OF THE PRESSURE BULKHEAD FS557.00	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 20-00-128 Airframe INSPECTION 3750 L #2439	GENERAL VISUAL INSPECTION OF THE EXTERNAL TOP SKIN OF THE FUSELAGE, FS381.00 TO FS557.00 AND STR6L TO STR6R	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 20-00-129 Airframe INSPECTION 3750 L #440	GENERAL VISUAL INSPECTION OF THE LOWER EXTERNAL SKIN OF THE FUSELAGE, FS381.00 TO FS557.00 AND STR6L TO STR6R	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 20-00-130 Airframe INSPECTION 3750 L #1209	DETAILED INSPECTION OF THE EXTERNAL AVIONICS- COMPARTMENT ACCESS SURROUND STRUCTURE	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 20-00-131 Airframe INSPECTION 3750 L #1271	DETAILED INSPECTION OF THE AFT FACE OF THE PRESSURE BULKHEAD BELOW WL71.50, FS557.00	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 20-00-132 Airframe INSPECTION 3750 L #1093	DETAILED INSPECTION OF THE LOWER SIDE OF THE PRESSURE FLOOR FS557.00 TO FS574.60 AND BL46L TO BL46R Reference Number AMM: 53-20-00-220-810	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 20-00-133 Airframe INSPECTION 3750 L #2362	GENERAL VISUAL INSPECTION OF THE EXTERNAL TOP SKIN OF THE FUSELAGE, FS281.00 TO FS381.00 AND STR2L TO STR7R	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 20-00-134 Airframe INSPECTION 3750 L #2504	GENERAL VISUAL INSPECTION OF THE EXTERNAL LEFT SIDE AND LOWER SKIN, FS281.00 TO FS381.00 AND STR2L TO STR25L	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 20-00-135 Airframe INSPECTION 3750 L #2324	DETAILED INSPECTION OF THE SILLS, FRAME, SKIN AND EDGE MEMBERS AROUND THE PASSENGER DOOR CUTOUT Reference Number AMM: 53-20-00-220-821	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 20-00-136 Airframe INSPECTION 3750 L #380	GENERAL VISUAL INSPECTION OF THE EXTERNAL RIGHT SIDE AND LOWER SKIN, FS281.00 TO FS381.00 AND STR7R TO STR25F	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 20-00-137 Airframe INSPECTION 3750 L #1046	DETAILED INSPECTION OF THE EXTERNAL SKIN AROUND THE WINDOW SURROUND CUTOUTS	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 20-00-138 Airframe INSPECTION 3750 L #460	DETAILED INSPECTION OF THE FUSELAGE LONGITUDINAL JOINTS, FS281.00 TO FS381.00, STR2L, STR7R, STR14L, STR19R AND STR25L	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 20-00-139 Airframe INSPECTION 3750 L #2464	DETAILED INSPECTION OF THE FUSELAGE LONGITUDINAL JOINTS, FS381.00 TO FS557.00, STR6R, STR6L, STR20R AND STR20L	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 20-00-140 Airframe INSPECTION 3750 L #2065	<p>DETAILED INSPECTION OF THE EXTERNAL SKIN AROUND THE SERVICE DOOR CUTOUT, FS295.00 TO FS310.00 AND STR22R TO STR24R</p> <p>Reference Number 53-20-00-220-835</p> <p>Notes NOTE: THIS TASK IS ONLY APPLICABLE TO AIRCRAFT WITH THE SERVICE DOOR CUTOUT.</p>	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 20-00-201 Airframe INSPECTION 240M/120M #1012	DETAILED INSPECTION OF THE INTERNAL FUSELAGE SKIN AND STRUCTURE, FS281.00 TO FS861.00, ABOVE WL71.50	21-MAR-2010 H: 0.00	M: 240	M: 3		21-MAR-2030	M: 96 D: 5
53 20-00-202 Airframe INSPECTION 120M #2127	<p>DETAILED INSPECTION OF THE LOWER INTERNAL SKIN AND STRUCTURE, FS381.00 TO FS557.00, BELOW WL71.50</p> <p>Notes NO DEFECTS NOTED</p>	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 20-00-203 Airframe INSPECTION 60M #2470	DETAILED INSPECTION OF THE LOWER INTERNAL SKIN AND STRUCTURE, FS381.00 TO FS557.00 AS VISIBLE FROM THE CRAWLWAY	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
53 20-00-204 Airframe INSPECTION 120M #279	DETAILED INSPECTION OF THE KEEL BEAM, FS501.00 TO FS574.00 AND BL4.6L TO BL4.6R	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 20-00-205 Airframe INSPECTION 120M #464	DETAILED INSPECTION OF THE OVER-WING LONGERON, FS525.00 TO FS574.00 AND STR19L AND STR19R	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 20-00-206 Airframe INSPECTION 120M #2164	DETAILED INSPECTION OF THE FORWARD FACE OF THE PRESSURE BULKHEAD BELOW WL71.50, FS557.00	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 20-00-207 Airframe INSPECTION 120M #379	DETAILED INSPECTION OF THE AFT FACE OF THE PRESSURE BULKHEAD BELOW WL71.50, FS557.00.	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
	Notes NO DEFECTS NEEDED						
53 20-00-208 Airframe INSPECTION 120M #2794	DETAILED INSPECTION OF THE TOP SIDE OF THE PRESSURE FLOOR, FS557.00 TO FS574.50 AND BL46L TO BL46R	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 20-00-209 Airframe INSPECTION 120M #806	DETAILED INSPECTION FLOOR SUPPORT STRUCTURE, FS381.00 TO FS557.00	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 20-00-210 Airframe INSPECTION #1737	DETAILED INSPECTION OF THE FLOOR SUPPORT STRUCTURE, FS381.00 TO FS557.00 AS VISIBLE FROM THE CRAWLWAY	02-FEB-2021 H: 3992.00 L: 1324	M: 60	M: 3		02-FEB-2026	M: 46 D: 17
53 20-00-212 Airframe INSPECTION #2913	DETAILED INSPECTION OF THE INTERNAL STRUCTURE BELOW WL71.50, FS281.00 TO FS381.00	01-FEB-2021 H: 3992.00 L: 1324	M: 60	M: 3		01-FEB-2026	M: 46 D: 16
53 20-00-213 Airframe INSPECTION 60M #2109	DETAILED INSPECTION OF THE INTERNAL STRUCTURE BELOW WL71.50, FS281.00 TO FS381.00, AS VISIBLE WITH THE FLOOR PANELS INSTALLED	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
53 20-00-214 Airframe INSPECTION 120M #848	DETAILED INSPECTION OF THE FLOOR SUPPORT STRUCTURE, FS281.00 TO FS381.00	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
	Notes NO DEFECTS NOTED						
53 20-00-215 Airframe INSPECTION #345	DETAILED INSPECTION OF THE FLOOR SUPPORT STRUCTURE, FS281.00 TO FS381.00 AS VISIBLE FROM THE CRAWLWAY	02-FEB-2021 H: 3992.00 L: 1324	M: 60	M: 3		02-FEB-2026	M: 46 D: 17



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 20-00-216 Airframe INSPECTION 60M #2523	DETAILED INSPECTION OF THE FLOOR STRUCTURE IN THE WAY OF THE PASSENGER DOOR STEP, FS310.00 TO FS347.00	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
53 20-00-217 Airframe INSPECTION 60M #2342	DETAILED INSPECTION OF THE SILLS, FRAMES, SKIN AND EDGE MEMBERS AROUND THE PASSENGER DOOR CUTOUT	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
53 20-00-218 Airframe INSPECTION 120M #1002	DETAILED INSPECTION OF THE INTERNAL SKIN AROUND THE PASSENGER DOOR CUTOUT	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 20-00-219 Airframe INSPECTION 120M #1959	DETAILED INSPECTION OF THE FITTINGS AND HINGES ON THE FUSELAGE FOR THE PASSENGER DOOR	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
	Notes NO DEFECTS NOTED						
53 20-00-221 Airframe INSPECTION 120M #2385	DETAILED INSPECTION OF THE FUSELAGE LONGITUDINAL JOINTS, FS281.00 TO FS381.00, STR19R AND STR25L	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 20-00-223 Airframe INSPECTION 120M #1348	DETAILED INSPECTION OF THE FUSELAGE LONGITUDINAL JOINTS, FS381.00 TO FS557.00 - STR20L AND STR20R	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 20-00-225 Airframe INSPECTION 120M #17	DETAILED INSPECTION OF THE FUSELAGE BARREL JOINT, FS381.00, BELOW WL71.50	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
	Notes NO DEFECTS NOTED						
53 20-00-227 Airframe INSPECTION 120M #2169	DETAILED INSPECTION OF THE FUSELAGE BARREL JOINT, FS557.00, BELOW WL71.50	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 20-00-229 Airframe INSPECTION 60M #187	DETAILED INSPECTION OF THE MACHINED FITTING AND SKIN AROUND THE SERVICE DOOR, FS295.00 TO FS310.00 AND STR22R TO STR24R Notes NA DUE TO A/C NOT HAVING FWD LAV SERVICE DOOR	19-APR-2021 H: 3992.00 L: 1324		M: 3			
53 20-00-230 Airframe INSPECTION 120M #159	DETAILED INSPECTION OF THE MACHINED FITTING AND SKIN AROUND THE SERVICE DOOR, FS295.00 TO FS310.00 AND STR22R TO STR24R AS VISIBLE FROM THE CRAWLWAY	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 20-00-244 Airframe INSPECTION 120M #1751	DETAILED INSPECTION OF THE LOWER EXTERNAL SKIN OF THE FUSELAGE, FS381.00 TO FS557.00 AND STR6L TO STR6R COVERED BY THE FORWARD FUEL TANK (A/C 9003, 9096, 9159 AND SUBS)	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 20-00-246 Airframe INSPECTION 120M #4750	DETAILED INSPECTION OF THE GROUND STUDS FOR L/HIRF PROTECTION IN THE LOWER FORWARD FUSELAGE, BETWEEN FS280.00 AND FS557.00 Reference Number AMM 53-20-00-220 -867	19-APR-2021 H: 3992.00 L: 1324	M: 120			19-APR-2031	M: 109 D: 3
53 30-00-102 Airframe INSPECTION #2232	SPECIAL DETAILED INSPECTION OF THE PANEL JOINT, FS557.00 TO FS781.00, STRINGER 6 Reference Number NDT: ET-53-30-002	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 30-00-103 Airframe INSPECTION 7500 L #1957	DETAILED INSPECTION OF THE PANEL JOINT, FS557.00 AND FS797.00, STRINGERS 18L TO 18R	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 30-00-104 Airframe INSPECTION #175	DETAILED INSPECTION OF THE FUSELAGE SKIN AT THE CABIN WINDOW CUTOUTS, FS557.00 TO FS797.00	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 30-00-105 Airframe INSPECTION #222	SPECIAL DETAILED INSPECTION OF THE FRONT SPAR FRAME OUTER FLANGE, FS574.00 Reference Number NDT: UT-53-30-002	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 30-00-106 Airframe INSPECTION #2703	SPECIAL DETAILED INSPECTION OF THE REAR SPAR FRAME, FS719.30 Reference Number NDT UT-53-30-001 & ET-53-30-004	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 30-00-107 Airframe INSPECTION 7500 L #246	DETAILED INSPECTION OF THE INTERMEDIATE FRAMES	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 30-00-110 Airframe INSPECTION 7500 L #333	SPECIAL DETAILED INSPECTION OF THE FUSELAGE SKIN AND SPLICE STRAP AT STRINGER 18 Reference Number NDT: UT-53-30-005, ET-53-30-011, & ET-53-30-013	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 30-00-111 Airframe INSPECTION #1043	DETAILED INSPECTION OF THE PRESSURE FLOOR PANELS AND BEAMS FROM FS719.30 TO FS781.00	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 30-00-113 Airframe INSPECTION #1101	DETAILED INSPECTION OF THE KEEL BEAM, FS719.30 TO FS781.00	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 30-00-114 Airframe INSPECTION #477	SPECIAL DETAILED INSPECTION OF THE REAR SPAR BULKHEAD, FS719.30 Reference Number NDT: UT-53-30-008 & ET-53-30-014	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 30-00-115 Airframe INSPECTION #1359	DETAILED INSPECTION OF THE FRAME, FS781.00	21-MAR-2010 H: 0.00	L: 6654			L: 6654	L: 5159
53 30-00-116 Airframe INSPECTION #1258	DETAILED INSPECTION OF THE REAR SPAR FRAME, FS719.30	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 30-00-118 Airframe INSPECTION 7500 L #1806	SPECIAL DETAILED INSPECTION OF THE PRESSURE FLOOR PANELS FROM FS719.30 TO FS781.00 Reference Number NDT: UT-53-30-004 & ET-53-30-015	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 30-00-119 Airframe INSPECTION #664	SPECIAL DETAILED INSPECTION OF THE STRINGER 6 FROM FS719.30 TO FS781.00 Reference Number NDT: ET-53-30-012	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 30-00-120 Airframe INSPECTION #463	SPECIAL DETAILED INSPECTION OF THE FRONT SPAR FRAME OUTBOARD AND INBOARD FLANGES, FS574.00 Reference Number NDT: ET-53-30-003	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 30-00-121 Airframe INSPECTION #845	SPECIAL DETAILED INSPECTION OF THE FRONT SPAR FRAME ATTACHMENT TO THE CENTER WING BOX, FS574.00 Reference Number NDT: ET-53-30-008	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 30-00-122 Airframe INSPECTION #1587	SPECIAL DETAILED INSPECTION OF THE REAR SPAR FRAME ATTACHMENT TO THE CENTER WING BOX, FS719.30 Reference Number NDT: ET-53-30-005	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 30-00-123 Airframe INSPECTION 7500 L #2876	SPECIAL DETAILED INSPECTION OF THE FRAME SPLICE, STRINGERS 5 AND 15, FS574.50 AND FS719.30 Reference Number NDT: ET-53-30-007	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 30-00-124 Airframe INSPECTION 3750 L #667	GENERAL VISUAL INSPECTION OF THE EXTERNAL SKIN OF THE FUSELAGE NOT BEHIND THE FAIRING, FS557.00 TO FS797.60	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 30-00-125 Airframe INSPECTION 3750 L #157	GENERAL VISUAL INSPECTION OF THE EXTERNAL SKIN OF THE FUSELAGE BEHIND THE FAIRING, FS557.00 TO FS797.60	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255



ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 30-00-126 Airframe INSPECTION 3750 L #999	DETAILED INSPECTION OF THE SURROUND STRUCTURE FOR THE OVERWING EMERGENCY EXIT	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 30-00-127 Airframe INSPECTION 3750 L #1071	DETAILED INSPECTION OF THE EXTERNAL SKIN OF CABIN WINDOW CUTOUPS, SURROUND STRUCTURE	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 30-00-128 Airframe INSPECTION 3750 L #174	DETAILED INSPECTION OF THE LOWER SIDE OF THE PRESSURE FLOOR FS719.30 TO FS781.00 AND BL35L TO BL35R	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 30-00-129 Airframe INSPECTION 3750 L #2559	DETAILED INSPECTION OF THE PRESSURE BULKHEADS, FS719.30 AND FS781.00 - EXTERNAL	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 30-00-130 Airframe INSPECTION 3750 L #1419	DETAILED INSPECTION OF THE CIRCUMFERENTIAL SKIN JOINT AT FS557.00 AND LONGITUDINAL SKIN JOINTS AT STR6 AND STR18, L AND R	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 30-00-131 Airframe INSPECTION #1606	SPECIAL DETAILED INSPECTION OF THE EMERGENCY DOOR CUTOOUT AND LATCH FITTING Reference Number NDT ET-53-30-006	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 30-00-132 Airframe INSPECTION 7500 L #2463	SPECIAL DETAILED INSPECTION OF THE FUSELAGE SKIN AND SPLICE STRAP AT STRINGER 18. Reference Number NDT: UT-53-30-007 & ET-53-30-010	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 30-00-133 Airframe INSPECTION #4980	SPECIAL DETAILED INSPECTION OF THE FUSELAGE SKIN SPLICES AT FS737.00 FROM STR15 TO STR19 AND AT STR15 BETWEEN FS737.00 AND FS787.70		L: 7500			L: 7500	L: 6005
53 30-00-134 Airframe INSPECTION #4979	SPECIAL DETAILED INSPECTION OF THE REAR SPAR FRAME OUTER-CAP, FS719.30 AT BL47.61		L: 7500			L: 7500	L: 6005



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 30-00-135 Airframe INSPECTION #4963	DETAILED INSPECTION OF THE FUSELAGE SKIN PANEL AND STRINGER 18 - INTERNAL		L: 7500			L: 7500	L: 6005
53 30-00-136 Airframe INSPECTION #4975	SPECIAL DETAILED INSPECTION OF THE FRAME, FS781.00		L: 7500			L: 7500	L: 6005
53 30-00-137 Airframe INSPECTION #4962	DETAILED INSPECTION OF THE CENTER FUSELAGE SKIN PANEL-ASSEMBLY FROM FS557.00 TO FS797.60		L: 7500			L: 7500	L: 6005
53 30-00-138 Airframe INSPECTION #4986	DETAILED INSPECTION OF THE FRAME SPLICE, FS574.00 TO FS781.00, STR5 AND STR15		L: 7500			L: 7500	L: 6005
53 30-00-201 Airframe INSPECTION #24	DETAILED INSPECTION OF THE FRONT SPAR FRAME ABOVE WL71.50, FS574.50	21-MAR-2010 H: 0.00	M: 180	M: 3		21-MAR-2025	M: 36 D: 5
53 30-00-202 Airframe INSPECTION 120M #899	DETAILED INSPECTION OF THE FRONT SPAR FRAME BELOW WL71.50, FS574.50	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 30-00-203 Airframe INSPECTION #2554	DETAILED INSPECTION OF THE REAR SPAR FRAME ABOVE WL71.50, FS719.30	21-MAR-2010 H: 0.00	M: 180	M: 3		21-MAR-2025	M: 36 D: 5
53 30-00-204 Airframe INSPECTION 120M #2588	DETAILED INSPECTION OF THE REAR SPAR FRAME BELOW WL71.50, FS719.30	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 30-00-205 Airframe INSPECTION 60M #2838	DETAILED INSPECTION OF THE SURROUND STRUCTURE FOR THE OVER-WING EMERGENCY EXIT -EXTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 30-00-206 Airframe INSPECTION #2480	DETAILED INSPECTION OF THE SURROUND STRUCTURE FOR THE OVER-WING EMERGENCY EXIT - INTERNAL	21-MAR-2010 H: 0.00	M: 180	M: 3		21-MAR-2025	M: 36 D: 5
53 30-00-207 Airframe INSPECTION 60M #214	DETAILED INSPECTION OF THE FITTINGS ON THE FRAME OF THE OVER-WING EMERGENCY EXIT	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
53 30-00-208 Airframe INSPECTION 120M #809	DETAILED INSPECTION OF THE EXTERNAL SKIN AROUND THE CABIN WINDOW CUTOUTS	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
	Notes NIL FINDINGS						
53 30-00-210 Airframe INSPECTION 120M #1559	DETAILED INSPECTION OF THE INTERNAL STRUCTURE OF THE FUSELAGE BELOW WL71.50, FS557.00 TO FS797.60	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 30-00-211 Airframe INSPECTION 120M #840	DETAILED INSPECTION OF THE TOP OF THE PRESSURE FLOOR, FS719.30 TO FS781.00 AND BL35L TO BL35R	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 30-00-212 Airframe INSPECTION 120M #312	DETAILED INSPECTION OF THE LOWER SIDE OF THE PRESSURE FLOOR, FS719.30 TO FS781.00 AND BL35L TO BL35R	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 30-00-213 Airframe INSPECTION 120M #315	DETAILED INSPECTION OF THE PRESSURE FLOOR BEAMS, FS713.10 TO FS781.00, BL0.0, BL9, BL19, BL27 AND BL35	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 30-00-214 Airframe INSPECTION 120M #1500	DETAILED INSPECTION OF THE KEEL BEAM STRUCTURE, FS719.30 TO FS781.00	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
	Notes NO DEFECTS NOTED						





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 30-00-215 Airframe INSPECTION 120M #112	DETAILED INSPECTION OF THE PRESSURE BULKHEADS, FS719.30 AND FS781.00 - EXTERNAL.	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
	Notes NO DEFECTS NOTED						
53 3101-001 Airframe PART #632	CENTER FUSELAGE FLOOR PANEL Part Number PN	Serial Number SN- UNKNOWN				21-MAR-2010 H: 0.00	
53 3101-002 Airframe PART #2640	CENTER FUSELAGE FLOOR PANEL. Part Number PN	Serial Number SN- UNKNOWN				21-MAR-2010 H: 0.00	
53 3101-003 Airframe PART #1532	CENTER FUSELAGE FLOOR PANEL.. Part Number PN	Serial Number SN- UNKNOWN				21-MAR-2010 H: 0.00	
53 3101-004 Airframe PART #1539	CENTER FUSELAGE FLOOR PANEL... Part Number PN	Serial Number SN- UNKNOWN				21-MAR-2010 H: 0.00	
53 3101-005 Airframe PART #1172	CENTER FUSELAGE FLOOR PANEL.... Part Number PN	Serial Number SN- UNKNOWN				21-MAR-2010 H: 0.00	
53 3101-006 Airframe PART #49	CENTER FUSELAGE FLOOR PANEL..... Part Number PN	Serial Number SN- UNKNOWN				21-MAR-2010 H: 0.00	
53 3101-007 Airframe PART #504	CENTER FUSELAGE FLOOR PANEL..... Part Number PN	Serial Number SN- UNKNOWN				21-MAR-2010 H: 0.00	





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 3101-008 Airframe PART #414	CENTER FUSELAGE FLOOR PANEL..... Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
53 3101-009 Airframe PART #166	CENTER FUSELAGE FLOOR PANEL..... Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
53 3101-010 Airframe PART #2659	CENTER FUSELAGE FLOOR PANEL..... Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
53 3101-011 Airframe PART #856	CENTER FUSELAGE FLOOR PANEL..... Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
53 3101-012 Airframe PART #2312	CENTER FUSELAGE FLOOR PANEL..... Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
53 3101-013 Airframe PART #1575	CENTER FUSELAGE FLOOR PANEL..... Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
53 3101-014 Airframe PART #979	CENTER FUSELAGE L/H FLOOR PANEL Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
53 3101-015 Airframe PART #1255	CENTER FUSELAGE R/H FLOOR PANEL Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
53 3101-016 Airframe PART #3003	CENTER FUSELAGE FLOOR PANEL..... Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 3101-017 Airframe PART #1433	CENTER FUSELAGE FLOOR PANEL..... Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
53 3101-018 Airframe PART #2810	CENTER FUSELAGE FLOOR PANEL..... Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
53 3101-019 Airframe PART #915	CENTER FUSELAGE L/H FLOOR PANEL. Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
53 3101-020 Airframe PART #2489	CENTER FUSELAGE R/H FLOOR PANEL. Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
53 3101-021 Airframe PART #1565	CENTER FUSELAGE FLOOR PANEL..... Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
53 3101-022 Airframe PART #794	CENTER FUSELAGE FLOOR PANEL..... Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
53 3101-023 Airframe PART #2085	CENTER FUSELAGE FLOOR PANEL..... Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
53 3101-024 Airframe PART #1011	CENTER FUSELAGE FLOOR PANEL..... Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
53 3101-701 Airframe PART #2943	FLOOR BOARD Part Number GC219-3307-5 Serial Number 157943	23-JAN-2011 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 3101-702 Airframe PART #1885	FLOOR BOARD Part Number GS215-0047-21 Serial Number 157662	23-JAN-2011 H: 0.00					
53 40-00-101 Airframe INSPECTION #2140	DETAILED INSPECTION OF THE FUSELAGE SKIN FROM FS781.00 TO FS861.00 - EXTERNAL	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 40-00-102 Airframe INSPECTION #677	SPECIAL DETAILED INSPECTION OF THE REAR FUSELAGE SKIN LONGITUDINAL JOINTS Reference Number NDT: UT-53-40-005, ET-53-40-009, ET-53-40-010 Notes ET-53-40-015	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 40-00-103 Airframe INSPECTION #531	DETAILED INSPECTION OF THE BAGGAGE DOOR SURROUND STRUCTURE AND PRESSURE BULKHEAD	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 40-00-104 Airframe INSPECTION #1274	DETAILED INSPECTION OF THE FRAMES AT FS925.00 AND FS987.00 AND THE REAR FUSELAGE LONGERON PLATFORM	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 40-00-105 Airframe INSPECTION #1739	DETAILED INSPECTION OF THE FORWARD FACE OF THE PRESSURE BULKHEAD AT FS861.00, AND THE FLOOR BEAMS FS789.00 TO FS861.00	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 40-00-106 Airframe INSPECTION 7500 L #2679	GENERAL VISUAL INSPECTION OF THE FUSELAGE SKIN FROM FS861.00 TO REAR SPAR FRAME - EXTERNAL	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 40-00-108 Airframe INSPECTION #1590	DETAILED INSPECTION OF THE BAGGAGE DOOR SURROUND STRUCTURE, LOWER SILL	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 40-00-109 Airframe INSPECTION #1514	DETAILED INSPECTION OF THE BAGGAGE DOOR SURROUND STRUCTURE, FRAME AND REINFORCING STRAP	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 40-00-110 Airframe INSPECTION #434	DETAILED INSPECTION OF THE REAR-PRESSURE BULKHEAD UPPER-HORIZONTAL-BEAM	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 40-00-111 Airframe INSPECTION 7500 L #1527	DETAILED INSPECTION OF THE PRESSURE BULKHEAD AT FS861.00 VERTICAL STIFFENERS AND BAGGAGE DOOR SILL FITTING	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 40-00-113 Airframe INSPECTION #2293	SPECIAL DETAILED INSPECTION OF THE FLOOR STRUCTURE, SEAT RAIL AND LATERAL FLOOR BEAM JOINTS	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 40-00-114 Airframe INSPECTION #2674	SPECIAL DETAILED INSPECTION OF THE BAGGAGE DOOR SURROUND STRUCTURE UPPER SILL JOINT AT FS813.00	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 40-00-115 Airframe INSPECTION 7500 L #165	SPECIAL DETAILED INSPECTION OF THE BAGGAGE DOOR SURROUND STRUCTURE UPPER SILL JOINT, FORWARD OF FS861.00	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 40-00-117 Airframe INSPECTION 7500 L #1142	GENERAL VISUAL INSPECTION OF THE REAR FUSELAGE KEEL BEAM	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 40-00-119 Airframe INSPECTION 7500 L #557	DETAILED INSPECTION OF THE REAR-FUSELAGE SKIN ENGINE-MOUNT-CUTOUTS	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 40-00-120 Airframe INSPECTION 7500 L #2633	SPECIAL DETAILED INSPECTION OF THE INNER FLAP TRACK SUPPORT-FITTINGS ON THE REAR FUSELAGE Reference Number NDT ET-53-40-005	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 40-00-121 Airframe INSPECTION #872	DETAILED INSPECTION OF THE FUSELAGE FRAME AT THE VERTICAL STABILIZER FRONT-SPAR	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 40-00-122 Airframe INSPECTION #1280	DETAILED INSPECTION OF THE FUSELAGE FRAME AT THE VERTICAL STABILIZER MID-SPAR	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 40-00-123 Airframe INSPECTION #1601	DETAILED INSPECTION OF THE FUSELAGE FRAME AT THE VERTICAL STABILIZER REAR-SPAR	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 40-00-124 Airframe INSPECTION 7500 L #1393	SPECIAL DETAILED INSPECTION OF THE FUSELAGE SUPPORT FRAMES FOR THE ENGINE BEAMS, INNER FLANGE	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 40-00-125 Airframe INSPECTION #864	SPECIAL DETAILED INSPECTION OF THE FUSELAGE FRAME AT THE VERTICAL STABILIZER FRONT SPAR, INBOARD FLANGE	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 40-00-126 Airframe INSPECTION #923	DETAILED INSPECTION OF THE FLOOR STRUCTURE, SEAT RAIL AND LATERAL FLOOR BEAMS	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 40-00-127 Airframe INSPECTION 7500 L #2643	SPECIAL DETAILED INSPECTION OF THE REAR FUSELAGE SKIN CIRCUMFERENTIAL JOINTS Reference Number NDT: UT-53-40-003, UT-53-40-004, ET-53-40-011 Notes ET-53-40-013 & ET-53-40-014	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 40-00-128 Airframe INSPECTION #2466	DETAILED INSPECTION OF THE FUSELAGE SKIN AROUND THE BAGGAGE DOOR	21-MAR-2010 H: 0.00	L: 7450			L: 7450	L: 5955
53 40-00-129 Airframe INSPECTION 3750 L #2432	GENERAL VISUAL INSPECTION OF THE EXTERNAL SKIN OF PRESSURE FUSELAGE, FS797.00 TO FS861.00	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 40-00-130 Airframe INSPECTION 3750 L #1658	DETAILED INSPECTION OF THE CIRCUMFERENTIAL AND LONGITUDINAL SKIN JOINTS OF THE PRESSURE SHELL NOT COVERED BY WING-TO-FUSELAGE FAIRINGS	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 40-00-131 Airframe INSPECTION 3750 L #1194	DETAILED INSPECTION OF THE BAGGAGE DOOR CUTOUT SURROUND STRUCTURE	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 40-00-132 Airframe INSPECTION 3750 L #309	GENERAL VISUAL INSPECTION OF THE EXTERNAL SKIN OF THE FUSELAGE BENEATH THE WING-TO-FUSELAGE FAIRING IN THE PRESSURIZED ZONE	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 40-00-133 Airframe INSPECTION 3750 L #136	DETAILED INSPECTION OF THE CIRCUMFERENTIAL AND LONGITUDINAL SKIN JOINTS BENEATH THE WING-TO-FUSELAGE FAIRING	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 40-00-134 Airframe INSPECTION 3750 L #1666	DETAILED INSPECTION OF THE PRESSURE BULKHEAD FORWARD WEB BELOW FLOOR	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 40-00-135 Airframe INSPECTION 3750 L #1120	DETAILED INSPECTION OF THE PRESSURE BULKHEAD WEB ABOVE FLOOR	21-MAR-2010 H: 0.00	L: 3750			L: 3750	L: 2255
53 40-00-137 Airframe INSPECTION #4973	SPECIAL DETAILED INSPECTION OF THE REAR PRESSURE BULKHEAD AT FS861.00		L: 7500			L: 7500	L: 6005
53 40-00-138 Airframe INSPECTION #4987	SPECIAL DETAILED INSPECTION OF THE BAGGAGE DOOR SURROUND STRUCTURE - PRESSURE BULKHEAD		L: 7500			L: 7500	L: 6005
53 40-00-139 Airframe INSPECTION #4969	SPECIAL DETAILED INSPECTION OF THE REAR FUSELAGE SKIN CUTOUTS FROM FS781.00 TO FS1066.00		L: 7500			L: 7500	L: 6005
53 40-00-140 Airframe INSPECTION #4974	DETAILED INSPECTION OF THE REAR FUSELAGE SKIN CUTOUTS FROM FS781.00 TO FS1066.00		L: 7500			L: 7500	L: 6005



ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 40-00-201 Airframe INSPECTION 120M #1042	DETAILED INSPECTION OF THE EXTERNAL SKIN OF THE FUSELAGE BELOW VERTICAL STABILIZER, FS945.00 TO THE REAR SPAR OF THE VERTICAL STABILIZER	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 40-00-202 Airframe INSPECTION 120M #860	DETAILED INSPECTION OF THE EXTERNAL SKIN OF THE FUSELAGE BELOW THE PYLON, FS877.25 TO THE REAR SPAR OF THE VERTICAL STABILIZER	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 40-00-203 Airframe INSPECTION 120M #1777	DETAILED INSPECTION OF THE EXTERNAL SKIN OF THE FUSELAGE BELOW THE WING-TO-FUSELAGE FAIRING, AND THE AFT KEEL BEAM, FS781.00 TO FS945.00	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
	Notes NO DEFECTS NOTED						
53 40-00-204 Airframe INSPECTION 60M #2467	DETAILED INSPECTION OF THE STOP FITTINGS OF THE BAGGAGE DOOR ON THE FUSELAGE	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
53 40-00-205 Airframe INSPECTION 120M #978	DETAILED INSPECTION OF THE INTERNAL SURROUND STRUCTURE OF THE BAGGAGE DOOR, FORWARD OF THE PRESSURE BULKHEAD	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 40-00-206 Airframe INSPECTION 60M #804	DETAILED INSPECTION OF THE BAGGAGE DOOR CUTOUT SURROUND STRUCTURE.	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
53 40-00-208 Airframe INSPECTION 60M #3031	DETAILED INSPECTION OF THE INTERNAL FUSELAGE STRUCTURE AND FORWARD FACE OF THE REAR PRESSURE BULKHEAD BELOW THE FLOOR, AND THE FLOOR STRUCTURE OF THE BAGGAGE COMPARTMENT	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
53 40-00-209 Airframe INSPECTION #1454	DETAILED INSPECTION OF THE FORWARD FACE OF THE REAR PRESSURE BULKHEAD ABOVE THE FLOOR	21-MAR-2010 H: 0.00	M: 180	M: 3		21-MAR-2025	M: 36 D: 5



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 40-00-210 Airframe INSPECTION 120M #2181	DETAILED INSPECTION OF THE STRUCTURE OF THE AFT FACE OF THE REAR PRESSURE BULKHEAD	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 40-00-211 Airframe INSPECTION 120M #2462	DETAILED INSPECTION OF THE UPPER SILL AND STOP BACKUP STRUCTURE OF THE BAGGAGE DOOR, AFT OF THE PRESSURE BULKHEAD	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 40-00-212 Airframe INSPECTION 120M #889	DETAILED INSPECTION OF THE AUXILIARY FUEL TANK FLOOR STRUCTURE	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 40-00-213 Airframe INSPECTION 60M #1927	DETAILED INSPECTION OF THE AFT EQUIPMENT COMPARTMENT INTERIOR STRUCTURE, FS861.00, VERTICAL-STABILIZER REAR-SPAR FRAME	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
53 40-00-214 Airframe INSPECTION 120M #2473	DETAILED INSPECTION OF THE AFT EQUIPMENT COMPARTMENT INTERIOR STRUCTURE ADJACENT TO THE AUXILIARY FUEL TANK, FS861.00 TO FS893.50, WL80.25 TO WL137.00	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 40-00-215 Airframe INSPECTION #2832	DETAILED INSPECTION OF THE FORWARD ENGINE-MOUNT FRAME-ASSEMBLY	04-FEB-2021 H: 3992.00 L: 1324	M: 60	M: 3		04-FEB-2026	M: 46 D: 19
53 40-00-216 Airframe INSPECTION 120M #1970	DETAILED INSPECTION OF THE SUPPORT STRUCTURE OF THE INNER FLAP INBOARD TRACK	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 40-00-217 Airframe INSPECTION 60M #4743	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION ON THE AFT FACE OF THE AFT PRESSURE BULKHEAD CONNECTORS - FS861.00 Reference Number AMM 53-40-00-210 -831	19-APR-2021 H: 3992.00 L: 1324	M: 60			19-APR-2026	M: 49 D: 3
53 4101-001 Airframe PART #1455	AFT FUSELAGE FLOOR PANEL Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 4101-002 Airframe PART #445	AFT FUSELAGE FLOOR PANEL. Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
53 4101-003 Airframe PART #1072	AFT FUSELAGE FLOOR PANEL.. Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
53 4101-004 Airframe PART #2252	AFT FUSELAGE FLOOR PANEL Part Number GD235-7509-13 Serial Number 157159	23-JAN-2011 H: 11.80 L: 6					
53 4101-005 Airframe PART #850	AFT FUSELAGE FLOOR PANEL... Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
53 4101-006 Airframe PART #743	AFT FUSELAGE FLOOR PANEL.... Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
53 50-00-101 Airframe INSPECTION #563	DETAILED INSPECTION OF THE VERTICAL STABILIZER FRONT-SPAR CAP AND CRUCIFORM FITTING Reference Number AMM: 53-50-00-220-806	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 50-00-102 Airframe INSPECTION #1981	DETAILED INSPECTION OF THE VERTICAL STABILIZER ATTACHMENT AT THE FUSELAGE FRAMES Reference Number AMM 53-50-00-220-810	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
53 50-00-201 Airframe INSPECTION 60M #1756	DETAILED INSPECTION OF THE AFT ENGINE-MOUNT FRAME-ASSEMBLY Notes CORROSION ON MOUNT BRACKET	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 50-00-202 Airframe INSPECTION 120M #418	DETAILED INSPECTION OF THE MID SPAR FRAME	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 50-00-203 Airframe INSPECTION 120M #1659	DETAILED INSPECTION OF THE REAR SPAR FRAME	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 50-00-204 Airframe INSPECTION 120M #1588	DETAILED INSPECTION OF THE STRUT ATTACH AND BACKUP FITTINGS OF THE APU MOUNT STRUCTURE	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 6001-001 Airframe PART #2379	RADOME Part Number GC219-0504-7 Serial Number E502958	21-MAR-2010 H: 0.00					
53 6201-001 Airframe PART #2244	EVS SYSTEM - HEATED FAIRING Part Number GC214-0166-1 Serial Number 240	21-MAR-2010 H: 0.00					
53 6203-001 Airframe PART #1105	EVS SYSTEM - INFRARED WINDOW Part Number GT546-1001-1 Serial Number 16041307	14-JUL-2016 H: 1924.80 L: 674					
	Notes C/W BY BAS						
53 ZL-00-201 Airframe INSPECTION 120M #2471	GENERAL VISUAL INSPECTION OF THE NOSE RADOME - INTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 ZL-00-202 Airframe INSPECTION 120M #1082	GENERAL VISUAL INSPECTION OF THE LOWER NOSE COMPARTMENT - INTERNAL LH	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 ZL-00-203 Airframe INSPECTION 60M #1457	GENERAL VISUAL INSPECTION OF THE LOWER NOSE COMPARTMENT - INTERNAL RH	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
53 ZL-00-204 Airframe INSPECTION 450L #39	GENERAL VISUAL INSPECTION OF THE NOSE WHEEL WELL	10-MAR-2022 H: 4455.80 L: 1495	L: 450	L: 50		L: 1945	L: 450
53 ZL-00-205 Airframe INSPECTION 60M #1383	GENERAL VISUAL INSPECTION OF THE MID LOWER FUSELAGE, SLAT DRIVE COMPARTMENT - INTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
53 ZL-00-206 Airframe INSPECTION 60M #2576	GENERAL VISUAL INSPECTION OF THE FUSELAGE FROM FS781.00 TO FS861.00, BELOW WL71.5 - INTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
53 ZL-00-207 Airframe INSPECTION 60M #1943	GENERAL VISUAL INSPECTION OF THE AFT WING-TO-FUSELAGE FAIRING - INTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
53 ZL-00-208 Airframe INSPECTION 120M #2766	GENERAL VISUAL INSPECTION OF THE LOWER MID-FUSELAGE - EXTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 ZL-00-209 Airframe INSPECTION 60M #2535	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR WHEEL WELL	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
53 ZL-00-210 Airframe INSPECTION 120M #680	GENERAL VISUAL INSPECTION OF THE LOWER MID-FUSELAGE BETWEEN THE PRESSURE FLOOR AND THE CABIN FLOOR - INTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 ZL-00-211 Airframe INSPECTION 120M #1712	GENERAL VISUAL INSPECTION OF THE CENTER WING BOX LOWER SURFACE - EXTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 ZL-00-212 Airframe INSPECTION 120M #1748	GENERAL VISUAL INSPECTION OF THE CENTER WING BOX - INTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 ZL-00-213 Airframe INSPECTION 60M #2879	GENERAL VISUAL INSPECTION OF THE LOWER FORWARD FUSELAGE, BETWEEN FS280.00 AND FS557.00 - EXTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
53 ZL-00-214 Airframe INSPECTION 60M #2183	GENERAL VISUAL INSPECTION OF THE LOWER FORWARD FUSELAGE, BETWEEN FS280.00 AND FS557.00, AND BETWEEN STR22L AND STR22R - INTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
53 ZL-00-215 Airframe INSPECTION 120M #1333	GENERAL VISUAL INSPECTION OF THE LOWER FORWARD FUSELAGE, BETWEEN FS280.00 AND FS557.00, AND BETWEEN STR18L AND STR22L, AND STR18R AND STR22R - INTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 ZL-00-216 Airframe INSPECTION 1800 L #2000	GENERAL VISUAL INSPECTION OF THE WING-TO-FUSELAGE FAIRINGS - EXTERNAL	10-MAR-2022 H: 4455.80 L: 1495	L: 1800	L: 50		L: 3295	L: 1800
53 ZL-00-217 Airframe INSPECTION 3000H #2972	GENERAL VISUAL INSPECTION OF THE FUSELAGE NOSE SECTION - EXTERNAL	01-DEC-2018 H: 3011.20 L: 1025	H: 3000.00	H: 50.00		H: 6011.20	H: 1555.40
53 ZL-00-218 Airframe INSPECTION 60M #756	GENERAL VISUAL INSPECTION OF THE NOSE SECTION OF THE FORWARD EQUIPMENT COMPARTMENT - INTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
53 ZL-00-219 Airframe INSPECTION 30M #2322	GENERAL VISUAL INSPECTION OF THE FLIGHT COMPARTMENT	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
53 ZL-00-220 Airframe INSPECTION 60M #248	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT, EXCLUDING THE BAGGAGE DOOR - EXTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 ZL-00-221 Airframe INSPECTION 60M #719	GENERAL VISUAL INSPECTION OF THE ELECTRICAL POWER CONTROL-CENTER - EXTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
53 ZL-00-222 Airframe INSPECTION 180M #2101	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT - INTERNAL	21-MAR-2010 H: 0.00	M: 180	M: 3		21-MAR-2025	M: 36 D: 5
<p>Notes</p> <p>NOTE: IF THERE IS ACCESS TO THE FUSELAGE INTERNAL STRUCTURE (ABOVE WL71.50 FROM FS280.00 TO FS781.00) DURING THE 120 M INSPECTION, IT IS PERMITTED TO DO THIS 180 M TASK AT THE 120 M INSPECTION. THIS WILL PREVENT THE REMOVAL OF THE INTERIOR (GALLEY, LAVATORY, SIDE PANELS, HEADLINERS ETC.) AT 180 M.</p>							
53 ZL-00-223 Airframe INSPECTION 120M #841	GENERAL VISUAL INSPECTION OF THE MID-FUSELAGE - EXTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
53 ZL-00-224 Airframe INSPECTION 180M #1951	GENERAL VISUAL INSPECTION OF THE MID-FUSELAGE COMPARTMENT ABOVE THE CABIN FLOOR - INTERNAL	21-MAR-2010 H: 0.00	M: 180	M: 3		21-MAR-2025	M: 36 D: 5
53 ZL-00-225 Airframe INSPECTION 60M #1520	GENERAL VISUAL INSPECTION OF THE UPPER FORWARD FUSELAGE, BETWEEN FS280.00 AND FS557.00, EXCLUDING THE PASSENGER DOOR - EXTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
53 ZL-00-226 Airframe INSPECTION 180M #559	GENERAL VISUAL INSPECTION OF THE UPPER FORWARD FUSELAGE, BETWEEN FS280.00 AND FS557.00, ABOVE WL71.50, EXCLUDING THE PASSENGER DOOR - INTERNAL	21-MAR-2010 H: 0.00	M: 180	M: 3		21-MAR-2025	M: 36 D: 5
53 ZL-00-227 Airframe INSPECTION 60M #1720	GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE - EXTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
53 ZL-00-228 Airframe INSPECTION 30M #347	GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE - INTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 ZL-00-229 Airframe INSPECTION 60M #2018	GENERAL VISUAL INSPECTION OF THE TAILCONE - EXTERNAL Notes CORROSION	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
53 ZL-00-230 Airframe INSPECTION 60M #984	GENERAL VISUAL INSPECTION OF THE TAILCONE - INTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
53 ZL-00-231 Airframe INSPECTION 60M #2790	GENERAL VISUAL INSPECTION OF THE FUSELAGE FROM FS987.50 TO THE VERTICAL-STABILIZER REAR-SPAR DATUM-LINE - INTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
53 ZL-00-232 Airframe INSPECTION 60M #1506	GENERAL VISUAL INSPECTION OF THE FORWARD AVIONICS COMPARTMENT - INTERNAL LH	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
53 ZL-00-233 Airframe INSPECTION 60M #2956	GENERAL VISUAL INSPECTION OF THE FORWARD AVIONICS COMPARTMENT - INTERNAL RH	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
54 50-00-201 Airframe INSPECTION 120M #640	DETAILED INSPECTION OF THE VERTICAL FLANGE OF THE PYLON DRAG ANGLES - PS30.00 TO PS151.00	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
54 50-00-202 Airframe INSPECTION 60M #1439	DETAILED INSPECTION OF THE PYLON CENTER BOX INTERNAL STRUCTURE - PS30.00 TO PS151.00	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
54 50-01-201 Airframe INSPECTION 120M #4751	DETAILED INSPECTION OF THE L/HIRF PROTECTION OF THE ENGINE PYLONS CONNECTORS Reference Number AMM 54-50-01-220 -801	19-APR-2021 H: 3992.00 L: 1324	M: 120			19-APR-2031	M: 109 D: 3



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
54 51-00-101 Airframe INSPECTION 7500 L #1581	SPECIAL DETAILED INSPECTION OF THE ENGINE BEAM ATTACHMENT-LUGS	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
54 51-00-102 Airframe INSPECTION #645	SPECIAL DETAILED INSPECTION OF THE ENGINE BEAM PYLON, UPPER AND LOWER CAPS Reference Number NDT: ET-54-50-004	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
54 51-00-103 Airframe INSPECTION #955	SPECIAL DETAILED INSPECTION OF THE ENGINE BEAM THRUST-STRUT	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
54 51-00-106 Airframe INSPECTION #2503	SPECIAL DETAILED INSPECTION OF THE ENGINE BEAM PYLON, FUSELAGE JOINT Reference Number NDT ET-54-50-003	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
54 51-00-107 Airframe INSPECTION #4984	DETAILED INSPECTION OF THE ENGINE PYLON SKINS AND DRAG ANGLES		L: 7500			L: 7500	L: 6005
54 5209-001 Airframe PART #2401	LH PYLON LEADING EDGE Part Number PN	21-MAR-2010 H: 0.00					Serial Number SN- UNKNOWN
54 5209-002 Airframe PART #1852	RH PYLON LEADING EDGE Part Number PN	21-MAR-2010 H: 0.00					Serial Number SN- UNKNOWN
54 ZL-00-201 Airframe INSPECTION 60M #2275	GENERAL VISUAL INSPECTION OF THE PYLON - LH EXTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
54 ZL-00-202 Airframe INSPECTION 60M #448	GENERAL VISUAL INSPECTION OF THE PYLON - RH EXTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 10-00-101 Airframe INSPECTION #2486	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER TAILPLANE-ACTUATOR FITTING-LUGS INCLUDING PINS Reference Number NDT: UT-55-10-001, ET-55-10-003 & MT-55-10-003	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 10-00-102 Airframe INSPECTION #959	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER PIVOT FITTINGS Reference Number NDT ET-55-10-001; MT-55-10-001	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 10-00-103 Airframe INSPECTION 7500 L #2054	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER TAILPLANE HINGE-FITTING LUGS AND PINS Reference Number NDT: ET-55-10-002 & MT-55-10-002	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 10-00-104 Airframe INSPECTION #1501	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER REAR SPAR JOINT	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 10-00-105 Airframe INSPECTION 7500 L #2298	DETAILED INSPECTION OF THE INTERNAL SKIN AND STRUCTURE OF THE HORIZONTAL-STABILIZER	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 10-00-108 Airframe INSPECTION 7500 L #2357	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER PCU FITTINGS Reference Number NDT ET-55-10-004; PT-55-10-001	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 10-00-109 Airframe INSPECTION 7500 L #1360	DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER TAILPLANE HINGE-FITTINGS Reference Number AMM 55-10-00-220-811	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 10-00-110 Airframe INSPECTION #1946	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER FRONT SPAR JOINT Reference Number NDT ET-55-10-008	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 10-00-201 Airframe INSPECTION 120M #2283	DETAILED INSPECTION OF THE ATTACHMENT FITTINGS AND STRAPS OF THE HORIZONTAL STABILIZER	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
55 10-00-202 Airframe INSPECTION 120M #2013	DETAILED INSPECTION OF THE CENTER BOX RIBS AND FITTINGS OF THE HORIZONTAL STABILIZER	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
55 10-00-203 Airframe INSPECTION 120M #1195	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER HINGE, SUPPORT, AND BACKUP FITTINGS AT RIBS 4, 5, 9 AND 12	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
55 10-00-204 Airframe INSPECTION 7500 L #2946	DETAILED INSPECTION OF THE EXTERNAL SKIN OF THE HORIZONTAL STABILIZER	21-MAR-2010 H: 0.00	L: 7500	L: 50		L: 7500	L: 6005
55 10-00-205 Airframe INSPECTION 3750 L #581	DETAILED INSPECTION OF THE INTERNAL SKIN AND STRUCTURE OF THE HORIZONTAL STABILIZER	21-MAR-2010 H: 0.00	L: 3750	L: 50		L: 3750	L: 2255
55 10-09-101 Airframe INSPECTION 7500 L #1475	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER PIVOT-FITTING SUPPORT-STRUCTURE BASEPLATE Reference Number NDT: ET-55-10-006	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 10-09-102 Airframe INSPECTION 7500 L #2658	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER TAILPLANE CENTER-LINE JOINT-STRAPS	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 10-09-103 Airframe INSPECTION 7500 L #2839	DETAILED INSPECTION OF THE ATTACHMENT OF THE ACTUATOR FITTING TO THE HORIZONTAL-STABILIZER	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 10-09-104 Airframe INSPECTION 7500 L #2918	DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER PIVOT-FITTING SUPPORT-STRUCTURE	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 10-09-105 Airframe INSPECTION 7500 L #2224	SPECIAL DETAILED INSPECTION OF THE ATTACHMENT OF THE ACTUATOR FITTING TO THE HORIZONTAL-STABILIZER YAW RESTRAINT Reference Number NDT: ET-55-10-009	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 1000-001 Airframe PART #576	HORIZONTAL STABILIZER Part Number GS258-0001-1 Serial Number B386	21-MAR-2010 H: 0.00					
55 1001-001 Airframe PART #339	LH TIP FAIRING Part Number PN Serial Number SN-UNKNOWN	21-MAR-2010 H: 0.00					
55 1001-002 Airframe PART #2645	RH TIP FAIRING Part Number PN Serial Number SN-UNKNOWN	21-MAR-2010 H: 0.00					
55 1005-001 Airframe PART #797	BULLET FAIRING ASSY Part Number GS248-0002-1 Serial Number B387	21-MAR-2010 H: 0.00					
55 1005-701 Airframe PART #2042	SATCOM FAIRING Part Number GC245-0002-1 Serial Number 525	04-MAR-2016 H: 1753.70 L: 622					
55 20-00-101 Airframe INSPECTION 7500 L #2421	SPECIAL DETAILED INSPECTION OF THE ELEVATOR, ACTUATOR AND HINGE FITTING Reference Number NDT: ET-55-20-001	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 20-00-102 Airframe INSPECTION 7500 L #1686	DETAILED INSPECTION OF THE ELEVATOR - COMPOSITE PARTS	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 20-00-201 Airframe INSPECTION #594	SPECIAL DETAILED INSPECTION OF THE UPPER AND LOWER SKINS OF THE ELEVATOR	21-MAR-2010 H: 0.00	L: 1875	L: 50		L: 1875	L: 380





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 20-00-202 Airframe INSPECTION 7500 L #2017	DETAILED INSPECTION OF THE RIBS AND SPAR OF THE ELEVATOR	21-MAR-2010 H: 0.00	L: 7500	L: 50		L: 7500	L: 6005
55 20-05-201 Airframe INSPECTION 120M #2830	DETAILED INSPECTION OF THE FITTINGS OF THE ELEVATOR	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
55 30-00-102 Airframe INSPECTION 7500 L #1485	GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER SKIN/STRINGER PANELS	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 30-00-103 Airframe INSPECTION #1254	SPECIAL DETAILED INSPECTION OF THE SURROUND STRUCTURE OF THE ACCES HOLE ON VERTICAL STABILIZER	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 30-00-104 Airframe INSPECTION 7500 L #70	SPECIAL DETAILED INSPECTION OF THE VERTICAL STABILIZER PIVOT AND ACTUATOR FITTINGS FOR THE HORIZONTAL STABILIZER	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
	Notes NDT ET-55-30-002 NDT ET-55-30-006 NDT ET-55-30-007 NDT ET-55-30-008 NDT UT-55-30-001						
55 30-00-105 Airframe INSPECTION 7500 L #2073	DETAILED INSPECTION OF THE BACKUP STRUCTURE OF THE HORIZONTAL-STABILIZER ACTUATOR ATTACHMENT TO THE VERTICAL STABILIZER	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 30-00-106 Airframe INSPECTION #1054	DETAILED INSPECTION OF THE VERTICAL STABILIZER FRONT-SPAR STRAP	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 30-00-107 Airframe INSPECTION 7500 L #473	SPECIAL DETAILED INSPECTION OF THE VERTICAL STABILIZER RUDDER HINGE FITTINGS AND PINS	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 30-00-111 Airframe INSPECTION 7500 L #1555	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER TRIM-ACTUATOR PIN Reference Number NDT MT-55-30-001 Notes NOTE: REPLACEMENT OF PIN AND ALL ASSOCIATED HARDWARE (E.G.; NUT, WASHERS, AND COTTER PIN) RESTARTS THE INSPECTION THRESHOLD.	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 30-00-112 Airframe INSPECTION 7500 L #232	GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER DRAG ANGLES	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 30-00-113 Airframe INSPECTION 7500 L #1085	DETAILED INSPECTION OF THE VERTICAL STABILIZER SIDE-STAYS	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 30-00-114 Airframe INSPECTION #2563	DETAILED INSPECTION OF THE VERTICAL STABILIZER CLOSING RIB	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 30-00-115 Airframe INSPECTION 7500 L #2027	SPECIAL DETAILED INSPECTION OF THE RUDDER WISHBONE	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 30-00-116 Airframe INSPECTION 7500 L #2409	DETAILED INSPECTION OF THE RUDDER WISHBONE	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 30-00-117 Airframe INSPECTION #4978	DETAILED INSPECTION OF THE VERTICAL STABILIZER SKIN/STRINGER PANELS		L: 7500			L: 7500	L: 6005
55 30-00-118 Airframe INSPECTION #4972	SPECIAL DETAILED INSPECTION OF THE VERTICAL STABILIZER DRAG ANGLES		L: 7500			L: 7500	L: 6005





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 30-00-202 Airframe INSPECTION 120M #2424	DETAILED INSPECTION OF THE STABILIZER DRAG ANGLES - FRONT SPAR DATUM TO REAR SPAR DATUM	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
55 30-00-203 Airframe INSPECTION 120M #669	DETAILED INSPECTION OF THE FRONT SPAR, WEB AND STRAPS OF THE VERTICAL STABILIZER	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
55 30-00-205 Airframe INSPECTION 120M #4964	GENERAL VISUAL INSPECTION OF THE VERTICAL-STABILIZER SKIN OUTER-SURFACES COVERED BY ACCESS PANELS AND RUDDER SEAL	19-APR-2021 H: 3992.00 L: 1324	M: 60			19-APR-2026	M: 49 D: 3
55 30-00-206 Airframe INSPECTION 60M #4967	GENERAL VISUAL INSPECTION OF THE VERTICAL-STABILIZER SKIN OUTER-SURFACES COVERED BY THE DORSAL AND BULLET FAIRINGS	19-APR-2021 H: 3992.00 L: 1324	M: 60			19-APR-2026	M: 49 D: 3
55 30-01-101 Airframe INSPECTION 7500 L #724	GENERAL VISUAL INSPECTION OF THE CAPS OF THE REAR SPAR OF THE VERTICAL STABILIZER	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 30-01-102 Airframe INSPECTION #2004	DETAILED INSPECTION OF THE VERTICAL STABILIZER MID-SPAR CAP Reference Number AMM 55-30-01-220 -808	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 30-01-201 Airframe INSPECTION 60M #1641	DETAILED INSPECTION OF THE HORIZONTAL LEGS, FRONT-SPAR JOINT LEGS, AND SHEAR ANGLE OF THE VERTICAL-STABILIZER FRONT SPAR-TO-FUSELAGE INTERFACE-FITTINGS	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
55 30-01-203 Airframe INSPECTION 120M #2448	DETAILED INSPECTION OF THE FITTINGS AND WISHBONE ATTACHMENTS OF THE RUDDER AND REAR SPAR AFT FACE AND RUDDER HINGE OF THE VERTICAL STABILIZER	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
55 30-01-204 Airframe INSPECTION #1837	DETAILED INSPECTION OF THE TIP CANTED RIB AND THE RIB FITTINGS OF THE VERTICAL STABILIZER	03-FEB-2021 H: 3992.00 L: 1324	M: 60	M: 3		03-FEB-2026	M: 46 D: 18



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 30-01-205 Airframe INSPECTION #1929	DETAILED INSPECTION OF THE INTERNAL STRUCTURE AND REAR SPAR FORWARD FACE OF THE VERTICAL STABILIZER AND WISHBONE ATTACHEMENTS TO THE VERTICAL STABILIZER	03-FEB-2021 H: 3992.00 L: 1324	M: 60	M: 3		03-FEB-2026	M: 46 D: 18
55 30-01-206 Airframe INSPECTION 120M #2762	DETAILED INSPECTION OF THE ATTACHMENTS AND FITTINGS OF THE WISHBONE TO THE VERTICAL STABILIZER	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
55 30-01-207 Airframe INSPECTION 120M #487	DETAILED INSPECTION OF THE LOWER ATTACHMENT PINS OF THE PITCH TRIM ACTUATOR	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
55 30-01-208 Airframe INSPECTION 60M #805	DETAILED INSPECTION OF THE LOWER ATTACHMENT BOLTS OF THE PITCH TRIM ACTUATOR	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
55 30-01-209 Airframe INSPECTION 120M #274	DETAILED INSPECTION OF THE RUDDER HINGE PINS	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
55 3009-001 Airframe PART #1057	VERTICAL STABILIZER LEADING EDGE Part Number GS248-0003-3 Serial Number B384	21-MAR-2010 H: 0.00					
55 3011-001 Airframe PART #336	VERTICAL STAB BOX ASSY Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
55 40-00-101 Airframe INSPECTION #788	SPECIAL DETAILED INSPECTION OF THE RUDDER ACTUATOR BRACKET LUGS Reference Number NDT ET-55-40-001	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 40-00-102 Airframe INSPECTION 7500 L #2240	DETAILED INSPECTION OF THE RUDDER STRUCTURE - COMPOSITE PARTS	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 40-00-103 Airframe INSPECTION 7500 L #644	SPECIAL DETAILED INSPECTION OF THE RUDDER HINGE FITTINGS Reference Number NDT ET-55-40-002	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
55 40-00-201 Airframe INSPECTION #1357	SPECIAL DETAILED INSPECTION OF THE SKINS OF THE RUDDER, EXTERNAL	21-MAR-2010 H: 0.00	L: 1875	L: 50		L: 1875	L: 380
55 40-00-203 Airframe INSPECTION 7500 L #161	DETAILED INSPECTION OF THE RIBS AND SPAR OF THE RUDDER	21-MAR-2010 H: 0.00	L: 7500	L: 50		L: 7500	L: 6005
55 40-00-205 Airframe INSPECTION 120M #1202	DETAILED INSPECTION OF THE BACKUP FITTINGS OF THE RUDDER	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
55 ZL-00-201 Airframe INSPECTION 120M #1689	GENERAL VISUAL INSPECTION OF THE RAM AIR INTAKE AND DORSAL FAIRING - INTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
55 ZL-00-202 Airframe INSPECTION 120M #2603	GENERAL VISUAL INSPECTION OF THE RAM AIR DORSAL FAIRING AND THE LEADING EDGE OF THE VERTICAL STABILIZER - EXTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
55 ZL-00-203 Airframe INSPECTION 60M #1598	GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER - EXTERNAL LH	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
55 ZL-00-204 Airframe INSPECTION 60M #1422	GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER - EXTERNAL RH	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
55 ZL-00-205 Airframe INSPECTION 120M #2106	GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER - INTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 ZL-00-206 Airframe INSPECTION 60M #2919	GENERAL VISUAL INSPECTION OF THE HORIZONTAL-STABILIZER BULLET FAIRING - EXTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
55 ZL-00-207 Airframe INSPECTION 120M #1707	GENERAL VISUAL INSPECTION OF THE HORIZONTAL- STABILIZER BULLET FAIRING - INTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
55 ZL-00-208 Airframe INSPECTION 120M #723	GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER LEADING EDGE - INTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
55 ZL-00-209 Airframe INSPECTION 60M #2524	GENERAL VISUAL INSPECTION OF THE LEADING EDGE OF THE RUDDER - INTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
55 ZL-00-210 Airframe INSPECTION 120M #1487	GENERAL VISUAL INSPECTION OF THE RUDDER - EXTERNAL	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
55 ZL-00-211 Airframe INSPECTION 120M #163	GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER - EXTERNAL LH	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
55 ZL-00-212 Airframe INSPECTION 120M #838	GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER - EXTERNAL RH	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
55 ZL-00-213 Airframe INSPECTION 3750 L #2012	GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER LEADING-EDGE - INTERNAL LH	21-MAR-2010 H: 0.00	L: 3750	L: 50		L: 3750	L: 2255
55 ZL-00-214 Airframe INSPECTION 3750 L #2804	GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER LEADING-EDGE - INTERNAL RH	21-MAR-2010 H: 0.00	L: 3750	L: 50		L: 3750	L: 2255





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 ZL-00-215 Airframe INSPECTION 60M #909	GENERAL VISUAL INSPECTION OF THE REAR SPAR OF THE HORIZONTAL STABILIZER - EXTERNAL LH	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
55 ZL-00-216 Airframe INSPECTION 60M #1978	GENERAL VISUAL INSPECTION OF THE REAR SPAR OF THE HORIZONTAL STABILIZER - EXTERNAL RH	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
56 1001-001 Airframe PART #1131	LH WINDSHIELD Part Number Serial Number GC331-0001-13 5099	21-SEP-2020 H: 3875.30 L: 1284					
56 1001-002 Airframe PART #2125	RH WINDSHIELD Part Number Serial Number GC331-0001-14 3132	20-OCT-2015 H: 1600.70 L: 568					
56 1001-003 Airframe PART #2585	SIDE POST (LH) SPLICE STRAP Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
56 1001-004 Airframe PART #337	SIDE POST (RH) SPLICE STRAP Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
56 1005-001 Airframe PART #928	LH SIDE WINDOW Part Number Serial Number GC331-0003-5 5887	06-NOV-2021 H: 4337.30 L: 1452					
	Notes C/W BY BOMBARDIER, TUCSON IN VAN NUYS. WO #193278						
56 1005-002 Airframe PART #1069	RH SIDE WINDOW Part Number Serial Number GC331-0003-6 2454	20-DEC-2013 H: 588.80 L: 268					
56 2001-001 Airframe PART #2200	LEFT NO.1 ASSY CABIN WINDOW Part Number Serial Number GC333-0001-13 15874	23-JAN-2011 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
56 2001-002 Airframe PART #954	RIGHT NO. 1 ASSY CABIN WINDOW Part Number GC333-0001-13	Serial Number 15763				23-JAN-2011 H: 0.00	
56 2001-003 Airframe PART #283	LEFT NO.2 ASSY CABIN WINDOW Part Number GC333-0001-13	Serial Number 14289				21-MAR-2010 H: 0.00	
56 2001-004 Airframe PART #117	RIGHT NO. 2 ASSY CABIN WINDOW Part Number GC333-0001-13	Serial Number 15764				23-JAN-2011 H: 0.00	
56 2001-005 Airframe PART #2353	LEFT NO.3 ASSY CABIN WINDOW Part Number GC333-0001-13	Serial Number 14295				21-MAR-2010 H: 0.00	
56 2001-006 Airframe PART #1299	RIGHT NO. 3 ASSY CABIN WINDOW Part Number GC333-0001-13	Serial Number 15242				23-JAN-2011 H: 0.00	
56 2001-007 Airframe PART #206	LEFT NO.4 ASSY CABIN WINDOW Part Number GC333-0001-13	Serial Number 15771				23-JAN-2011 H: 0.00	
56 2001-008 Airframe PART #2468	RIGHT NO. 4 ASSY CABIN WINDOW Part Number GC333-0001-13	Serial Number 14303				21-MAR-2010 H: 0.00	
56 2001-009 Airframe PART #1123	LEFT NO.5 ASSY CABIN WINDOW Part Number GC333-0001-13	Serial Number 14298				21-MAR-2010 H: 0.00	
56 2001-010 Airframe PART #2022	RIGHT NO. 5 ASSY CABIN WINDOW Part Number GC333-0001-13	Serial Number 15765				23-JAN-2011 H: 0.00	
56 2001-011 Airframe PART #1379	LEFT NO.6 ASSY CABIN WINDOW Part Number GC333-0001-13	Serial Number 14290				21-MAR-2010 H: 0.00	





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
56 2001-012 Airframe PART #958	RIGHT NO. 6 ASSY CABIN WINDOW Part Number GC333-0001-13	Serial Number 14319	21-MAR-2010 H: 0.00				
56 2001-013 Airframe PART #875	LEFT NO.7 ASSY CABIN WINDOW Part Number GC333-0001-13	Serial Number 15240	23-JAN-2011 H: 0.00				
56 2001-014 Airframe PART #107	RIGHT NO. 7 ASSY CABIN WINDOW Part Number GC333-0001-13	Serial Number 14320	21-MAR-2010 H: 0.00				
56 2001-015 Airframe PART #1844	LEFT NO.8 ASSY CABIN WINDOW Part Number GC333-0001-13	Serial Number 12082	21-MAR-2010 H: 0.00				
56 2001-016 Airframe PART #1941	RIGHT NO. 8 ASSY CABIN WINDOW Part Number GC333-0001-13	Serial Number 12461	21-MAR-2010 H: 0.00				
56 2001-017 Airframe PART #320	LEFT NO.9 ASSY CABIN WINDOW Part Number GC333-0001-13	Serial Number 12128	23-JAN-2011 H: 0.00				
56 2001-018 Airframe PART #2032	RIGHT NO. 9 ASSY CABIN WINDOW Part Number GC333-0001-13	Serial Number 15766	21-MAR-2010 H: 0.00				
56 2001-019 Airframe PART #715	LEFT NO.10 ASSY CABIN WINDOW Part Number GC333-0001-13	Serial Number 12170	21-MAR-2010 H: 0.00				
56 2001-020 Airframe PART #2335	RIGHT NO. 10 ASSY CABIN WINDOW Part Number GC333-0001-13	Serial Number 13617	21-MAR-2010 H: 0.00				
56 2001-021 Airframe PART #2057	LEFT NO.11 ASSY CABIN WINDOW Part Number GC333-0001-13	Serial Number 12171	21-MAR-2010 H: 0.00				





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
56 2001-022 Airframe PART #2577	RIGHT NO. 11 ASSY CABIN WINDOW Part Number GC333-0001-13	Serial Number 12464	21-MAR-2010 H: 0.00				
56 2001-023 Airframe PART #1495	LEFT NO.12 ASSY CABIN WINDOW Part Number GC333-0001-13	Serial Number 12231	21-MAR-2010 H: 0.00				
56 2001-024 Airframe PART #2174	RIGHT NO. 12 ASSY CABIN WINDOW Part Number GC333-0001-13	Serial Number 13821	21-MAR-2010 H: 0.00				
56 2001-025 Airframe PART #2689	LEFT NO.13 ASSY CABIN WINDOW Part Number GC333-0001-13	Serial Number 12460	21-MAR-2010 H: 0.00				
56 2001-026 Airframe PART #1928	RIGHT NO. 13 ASSY CABIN WINDOW Part Number GC333-0001-13	Serial Number 13822	21-MAR-2010 H: 0.00				
56 2001-027 Airframe PART #2526	#14 RH FWD PASS WINDOW Part Number GC333-0001-13	Serial Number 13823	21-MAR-2010 H: 0.00				
56 2001-028 Airframe PART #2813	#15 RH FWD PASS WINDOW Part Number GC333-0001-13	Serial Number 13825	21-MAR-2010 H: 0.00				
57 0001-001 Airframe PART #2725	LEFT HAND WING ASSEMBLY Part Number GM118-1001-1	Serial Number 385	21-MAR-2010 H: 0.00				
57 0001-002 Airframe PART #2569	RIGHT HAND WING ASSEMBLY Part Number GM118-1001-2	Serial Number 385	21-MAR-2010 H: 0.00				
57 10-00-101 Airframe INSPECTION #1525	SPECIAL DETAILED INSPECTION OF THE CENTER-WING LOWER-PANEL ACCESS-HOLES		21-MAR-2010 H: 0.00	L: 7500		L: 7500	L: 6005





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 10-00-102 Airframe INSPECTION 7500 L #2187	DETAILED INSPECTION OF THE AC TRANSFER-PUMP LOWER PANEL	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 10-00-103 Airframe INSPECTION #2899	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) SIDE-STAY FITTING Reference Number NDT ET-57-10-008	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 10-00-104 Airframe INSPECTION 7500 L #2356	SPECIAL DETAILED INSPECTION OF THE CENTER WING LOWER PANEL SPLICE, BL47.61 Reference Number NDT: UT-57-10-001 & ET-57-10-004	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 10-00-106 Airframe INSPECTION #2294	DETAILED INSPECTION OF THE FRONT SPAR ROOT-SPLICE	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 10-00-107 Airframe INSPECTION #1623	DETAILED INSPECTION OF THE REAR SPAR SPLICE OF THE CENTER WING	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 10-00-108 Airframe INSPECTION 7500 L #1216	DETAILED INSPECTION OF THE CENTER-WING UPPER PANEL	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 10-00-109 Airframe INSPECTION #755	DETAILED INSPECTION OF THE KEEL BEAM RIB, BL4.75	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 10-00-110 Airframe INSPECTION #892	SPECIAL DETAILED INSPECTION OF THE INTERMEDIATE RIB, BL27.00 TRUSS SUPPORT PLATE Reference Number NDT ET-57-10-005; MT-57-10-002	21-MAR-2010 H: 0.00	L: 7400			L: 7400	L: 5905
57 10-00-111 Airframe INSPECTION #493	SPECIAL DETAILED INSPECTION OF THE LOWER-CAP OF THE CENTER-WING FRONT SPAR Reference Number NDT ET-57-10-012	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 10-00-112 Airframe INSPECTION #4976	DETAILED INSPECTION OF THE LOWER CAP OF THE CENTER-WING REAR SPAR		L: 7500			L: 7500	L: 6005
57 10-00-113 Airframe INSPECTION #1031	DETAILED INSPECTION OF THE INTERMEDIATE RIB, BL27.00 CHORD FLANGES	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 10-00-114 Airframe INSPECTION #478	DETAILED INSPECTION OF THE CENTER-WING LOWER-PANEL	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 10-00-115 Airframe INSPECTION 7500 L #1163	DETAILED INSPECTION OF THE CENTER-WING LOWER-PANEL SPLICE, BL47.61	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 10-00-116 Airframe INSPECTION #2221	SPECIAL DETAILED INSPECTION OF THE FRONT SPAR ROOT-SPLICE LOWER CAP Reference Number NDT: UT-57-10-003 & ET-57-10-006	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 10-00-117 Airframe INSPECTION #2333	SPECIAL DETAILED INSPECTION OF THE REAR SPAR SPLICE OF THE CENTER-WING Reference Number NDT: ET-57-10-014	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 10-00-118 Airframe INSPECTION #2719	SPECIAL DETAILED INSPECTION OF THE KEEL BEAM RIB, BL4.75	21-MAR-2010 H: 0.00	L: 3666			L: 3666	L: 2171
57 10-00-119 Airframe INSPECTION #2488	SPECIAL DETAILED INSPECTION OF THE REAR-SPAR LOWER-CAP, BL44.00 TO BL47.60 Reference Number NDT: RT-57-10-003	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 10-00-121 Airframe INSPECTION #4960	SPECIAL DETAILED INSPECTION OF THE REAR-SPAR LOWER-CAP AND WING SKIN BETWEEN LBL44.00 AND RBL44.00		L: 7500			L: 7500	L: 6005





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 10-00-122 Airframe INSPECTION #4970	DETAILED INSPECTION OF THE KEEL BEAM RIB TRUSS-BEAM PINS, BL4.75		L: 7500			L: 7500	L: 6005
57 10-00-123 Airframe INSPECTION #4985	SPECIAL DETAILED INSPECTION OF THE WING FRONT-SPAR LOWER-CAP AND WEB AT KEEL BEAM ATTACHMENTS, BL4.75		L: 7500			L: 7500	L: 6005
57 10-00-124 Airframe INSPECTION #4968	DETAILED INSPECTION OF THE FRONT SPAR LOWER CAP OF THE CENTER WING FROM LBL47.60 TO RBL47.60		L: 7500			L: 7500	L: 6005
57 10-00-125 Airframe INSPECTION #4977	SPECIAL DETAILED INSPECTION OF THE CENTER WING FRONT-SPAR LOWER-CAP AND WEB AT FS574.50 FROM LBL47.60 TO RBL47.60		L: 7500			L: 7500	L: 6005
57 10-00-201 Airframe INSPECTION 120M #71	DETAILED INSPECTION OF THE FORWARD FACE OF THE FRONT SPAR OF THE CENTER WING - LBL47.6 TO RBL47.6	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
57 10-00-202 Airframe INSPECTION #2484	DETAILED INSPECTION OF THE CENTER WING FRONT SPAR AFT FACE, AND CENTER WING UPPER PANEL, LOWER PANEL AND RIBS - INTERNAL LBL47.6 TO RBL47.6	09-FEB-2021 H: 3992.00 L: 1324	M: 60	M: 3		09-FEB-2026	M: 46 D: 24
57 10-00-203 Airframe INSPECTION 120M #1268	DETAILED INSPECTION OF THE FORWARD FACE OF THE REAR SPAR OF THE CENTER WING - LBL47.6 TO RBL47.6	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
57 10-00-204 Airframe INSPECTION 120M #16	DETAILED INSPECTION OF THE AFT FACE OF THE REAR SPAR OF THE CENTER WING - LBL47.6 TO RBL47.6	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
57 10-00-205 Airframe INSPECTION 120M #1217	DETAILED INSPECTION OF THE UPPER FACE OF THE CENTER WING UPPER PANEL	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 10-00-206 Airframe INSPECTION #2721	DETAILED INSPECTION OF THE LOWER FACE OF THE CENTER WING LOWER PANEL	04-FEB-2021 H: 3992.00 L: 1324	M: 60	M: 3		04-FEB-2026	M: 46 D: 19
57 10-00-208 Airframe INSPECTION #2277	DETAILED INSPECTION OF THE OUTER FACE OF THE CENTER WING ROOT RIB	03-FEB-2021 H: 3992.00 L: 1324	M: 60	M: 3		03-FEB-2026	M: 46 D: 18
57 10-00-209 Airframe INSPECTION #2296	DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) SIDE STAY FITTING	03-FEB-2021 H: 3992.00 L: 1324	M: 60	M: 3		03-FEB-2026	M: 46 D: 18
57 20-00-101 Airframe INSPECTION 7500 L #2666	DETAILED INSPECTION OF THE SPLICE ON THE LOWER SKIN OF THE WING, WCS537.40	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 20-00-102 Airframe INSPECTION #201	DETAILED INSPECTION OF THE WING LOWER FUEL-ACCESS-HOLES - EXTERNAL	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 20-00-103 Airframe INSPECTION #1281	DETAILED INSPECTION OF THE WING LOWER-SKIN FUEL-SYSTEM-HOLES	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 20-00-104 Airframe INSPECTION 7500 L #2763	SPECIAL DETAILED INSPECTION OF THE LOWER WING-PLANK STRINGER-RUNOUT Reference Number NDT: ET-57-20-014	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 20-00-105 Airframe INSPECTION 7500 L #1605	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) LOWER STRAP, WS85.50 Reference Number NDT: RT-57-20-005 & ET-57-20-013	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 20-00-106 Airframe INSPECTION 7500 L #2268	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) FITTING JOINT Reference Number NDT RT-57-20-002, ET-57-20-008	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 20-00-108 Airframe INSPECTION #696	SPECIAL DETAILED INSPECTION OF THE REAR SPAR SPLICE, WS178.00 <small>Reference Number</small> NDT ET-57-20-002	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 20-00-109 Airframe INSPECTION 7500 L #1125	SPECIAL DETAILED INSPECTION OF THE REAR SPAR SPLICE, WS287.00 <small>Reference Number</small> NDT: RT-57-20-007 & ET-57-20-009	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 20-00-110 Airframe INSPECTION #2096	SPECIAL DETAILED INSPECTION OF THE LOWER SKIN SPLICE AT THE FRONT SPAR, CANTED RIB NO. 2 TO CWS390.90	21-MAR-2010 H: 0.00	L: 3808			L: 3808	L: 2313
57 20-00-111 Airframe INSPECTION #394	DETAILED INSPECTION OF THE LOWER-SKIN SPANWISE-SPLICE	21-MAR-2010 H: 0.00	L: 6232			L: 6232	L: 4737
57 20-00-112 Airframe INSPECTION #1354	DETAILED INSPECTION OF THE OUTER WING FRONT AND REAR SPAR CAPS AND SKIN	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 20-00-113 Airframe INSPECTION 7500 L #2977	GENERAL VISUAL INSPECTION OF THE WING UPPER-SKIN	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 20-00-114 Airframe INSPECTION #479	DETAILED INSPECTION OF THE WING RIBS AT WS66.00, WS178.00, WS287.00 AND CWS464.20	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 20-00-115 Airframe INSPECTION #1197	DETAILED INSPECTION OF THE WING RIB AT WS85.50	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 20-00-116 Airframe INSPECTION 7500 L #759	SPECIAL DETAILED INSPECTION OF THE WING RIB AT WS66.00 <small>Reference Number</small> NDT ET-57-20-003	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 20-00-119 Airframe INSPECTION #1637	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) TRUNNION-FITTING Reference Number NDT RT-57-20-001, ET-57-20-007	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 20-00-120 Airframe INSPECTION 7500 L #2435	SPECIAL DETAILED INSPECTION OF THE SPLICE ON THE LOWER SKIN OF THE WING, WC537.40 Reference Number NDT: ET-57-20-012	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 20-00-121 Airframe INSPECTION #1050	DETAILED INSPECTION OF THE WING LOWER FUEL-ACCESS-HOLES - INTERNAL	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 20-00-122 Airframe INSPECTION #1441	DETAILED INSPECTION OF THE LOWER SKIN AT THE SPANWISE-SPLICE	21-MAR-2010 H: 0.00	L: 4823			L: 4823	L: 3328
57 20-00-123 Airframe INSPECTION #102	DETAILED INSPECTION OF THE LOWER SKIN AT THE FRONT AND REAR SPAR JOINTS	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 20-00-125 Airframe INSPECTION #1858	SPECIAL DETAILED INSPECTION OF THE WING RIB AT WS178.00	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 20-00-126 Airframe INSPECTION 7500 L #2697	SPECIAL DETAILED INSPECTION OF THE WING RIB AT WS287.00	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 20-00-127 Airframe INSPECTION 7500 L #1269	SPECIAL DETAILED INSPECTION OF THE WING RIB AT CWS464.20	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 20-00-128 Airframe INSPECTION #2351	DETAILED INSPECTION OF THE WING RIB AT WS85.50.	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 20-00-129 Airframe INSPECTION #4983	SPECIAL DETAILED INSPECTION OF THE LOWER SPLICE OF THE FRONT SPAR, WS275.60 AND WS549.55		L: 7500			L: 7500	L: 6005
57 20-00-201 Airframe INSPECTION 120M #426	DETAILED INSPECTION OF THE FORWARD FACE OF THE FRONT SPAR OF THE WING	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
57 20-00-202 Airframe INSPECTION 120M #1698	DETAILED INSPECTION OF THE AFT FACE OF THE FRONT SPAR OF THE WING - BL47.61 TO CWS537.40	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
57 20-00-203 Airframe INSPECTION 120M #1420	DETAILED INSPECTION OF THE FORWARD FACE OF THE REAR SPAR OF THE WING - BL47.61 TO CWS537.40	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
57 20-00-204 Airframe INSPECTION 60M #323	DETAILED INSPECTION OF THE AFT FACE OF THE REAR SPAR AND AUXILIARY SPAR OF THE WING	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
57 20-00-205 Airframe INSPECTION #936	DETAILED INSPECTION OF THE LOWER WING SURFACE COVERED BY THE FUEL ACCESS PANELS	02-FEB-2021 H: 3992.00 L: 1324	M: 60	M: 3		02-FEB-2026	M: 46 D: 17
57 20-00-206 Airframe INSPECTION #499	DETAILED INSPECTION OF THE INTERNAL SKIN AND STRUCTURE OF THE WING - BL47.61 TO CWS537.40	03-FEB-2021 H: 3992.00 L: 1324	M: 60	M: 3		03-FEB-2026	M: 46 D: 18
57 20-00-207 Airframe INSPECTION #1251	DETAILED INSPECTION OF THE INTERNAL SKIN AND STRUCTURE OF THE WING - CWS537.40 TO WS536.50	03-FEB-2021 H: 3992.00 L: 1324	M: 60	M: 3		03-FEB-2026	M: 46 D: 18
57 20-00-210 Airframe INSPECTION 120M #2931	DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) TRUNNION FITTING AND BAY	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 20-00-212 Airframe INSPECTION 120M #514	DETAILED INSPECTION OF THE AILERON SUPPORT FITTINGS	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
57 20-00-213 Airframe INSPECTION #1426	DETAILED INSPECTION OF THE INTERNAL WING STRUCTURE BETWEEN THE REAR SPAR AND AUXILIARY SPAR, WS85.00 TO WS178.00	03-FEB-2021 H: 3992.00 L: 1324	M: 60	M: 3		03-FEB-2026	M: 46 D: 18
57 30-00-101 Airframe INSPECTION 7500 L #2849	SPECIAL DETAILED INSPECTION OF THE WINGLET INSTALLATION Reference Number NDT: ET-57-30-001	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 30-00-102 Airframe INSPECTION #4981	DETAILED INSPECTION OF THE WINGLET - EXTERNAL SURFACES		L: 7500			L: 7500	L: 6005
57 30-00-202 Airframe INSPECTION 120M #745	DETAILED INSPECTION OF THE WINGLET ATTACHMENT FITTINGS	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
57 3000-001 Airframe PART #223	LEFT WINGLET Part Number Serial Number GM178-1000-1 387	21-MAR-2010 H: 0.00					
57 3000-002 Airframe PART #1275	RIGHT WINGLET Part Number Serial Number GM178-1000-2 387	21-MAR-2010 H: 0.00					
57 3001-001 Airframe PART #1935	LH WING TIP LENS Part Number Serial Number GE536-0011-3 M21349	03-FEB-2021 H: 3992.00 L: 1324					
57 3001-002 Airframe PART #600	RH WING TIP LENS Part Number Serial Number GE536-0010-3 M11398	03-FEB-2021 H: 3992.00 L: 1324					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 42-00-101 Airframe INSPECTION #2720	SPECIAL DETAILED INSPECTION OF THE NO. 1 SLAT TRACKS <small>Reference Number</small> NDT MT-57-42-002	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 42-00-103 Airframe INSPECTION 7500 L #1033	SPECIAL DETAILED INSPECTION OF THE NO. 2 SLAT TRACKS <small>Reference Number</small> NDT MT-57-42-003	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 42-00-104 Airframe INSPECTION #1741	SPECIAL DETAILED INSPECTION OF THE NO. 3 SLAT TRACKS <small>Reference Number</small> NDT MT-57-42-004	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 42-00-105 Airframe INSPECTION 7500 L #2112	SPECIAL DETAILED INSPECTION OF THE NO. 4 SLAT TRACKS <small>Reference Number</small> NDT MT-57-42-005	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 42-00-107 Airframe INSPECTION #961	SPECIAL DETAILED INSPECTION OF THE NO. 1 SLAT TO TRACK ATTACHMENTS <small>Reference Number</small> NDT: ET-57-42-007	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 42-00-108 Airframe INSPECTION #1886	SPECIAL DETAILED INSPECTION OF THE NO. 2 SLAT TO TRACK ATTACHMENTS <small>Reference Number</small> NDT: ET-57-42-006	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 42-00-109 Airframe INSPECTION 7500 L #2391	DETAILED INSPECTION OF THE SLAT TRACK ATTACHMENT LUGS, SLAT NO. 3 AND NO. 4	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 42-00-111 Airframe INSPECTION #1421	SPECIAL DETAILED INSPECTION OF THE NO. 3 SLAT TO TRACK ATTACHMENTS <small>Reference Number</small> NDT: ET-57-42-008	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 42-00-201 Airframe INSPECTION 120M #731	DETAILED INSPECTION OF THE NO. 1 SLAT SUPPORT FITTINGS	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 42-00-202 Airframe INSPECTION 120M #744	DETAILED INSPECTION OF THE NO. 2, NO. 3 AND NO. 4 SLAT SUPPORT FITTINGS	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
57 42-02-101 Airframe INSPECTION 7500 L #2505	DETAILED INSPECTION OF THE SLAT BODY, SLAT NO. 1 AND NO. 2	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 42-02-103 Airframe INSPECTION #2619	DETAILED INSPECTION OF THE SLAT BODY, SLAT NO. 3 AND NO. 4	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 42-02-104 Airframe INSPECTION 7500 L #2288	SPECIAL DETAILED INSPECTION OF THE NO. 4 SLAT BODIES INTERCONNECT PIN Reference Number NDT: ET-57-42-004 & MT-57-42-006	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 42-02-105 Airframe INSPECTION 7500 L #1349	SPECIAL DETAILED INSPECTION OF THE SLAT NO. 1 TO NO. 4 ROLLER PINS Reference Number NDT MT-57-42-001; PT-57-42-001	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 42-02-106 Airframe INSPECTION 7500 L #1317	DETAILED INSPECTION OF THE SLAT NO. 1 TO NO. 4 SUPPORT RIBS	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 42-02-201 Airframe INSPECTION 60M #244	DETAILED INSPECTION OF THE NO. 1 SLAT TRACK RAILS	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
57 42-02-202 Airframe INSPECTION 120M #27	DETAILED INSPECTION OF THE NO. 1 SLAT RAIL SUPPORT FITTINGS	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
57 42-02-203 Airframe INSPECTION 120M #203	DETAILED INSPECTION OF THE NO. 1 SLAT BODY	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 42-02-204 Airframe INSPECTION 60M #2337	DETAILED INSPECTION OF THE NO. 2, NO. 3 AND NO. 4 SLAT TRACK RAILS	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
57 42-02-205 Airframe INSPECTION 120M #586	DETAILED INSPECTION OF THE NO. 2, NO. 3 AND NO. 4 SLAT RAIL SUPPORT FITTINGS	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
57 42-02-206 Airframe INSPECTION 120M #854	DETAILED INSPECTION OF THE NO. 2, NO. 3 AND NO. 4 SLAT BODIES	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
57 51-00-101 Airframe INSPECTION #1638	SPECIAL DETAILED INSPECTION OF THE FLAP TRACK, WS47.80 Reference Number NDT ET-57-51-003 & MT-57-51-001	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 51-00-102 Airframe INSPECTION 7500 L #2511	SPECIAL DETAILED INSPECTION OF THE FLAP SUPPORT STRUCTURE, WS178.00 Reference Number NDT: ET-57-51-004 & MT-57-51-002	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 51-00-103 Airframe INSPECTION #542	SPECIAL DETAILED INSPECTION OF THE FLAP TRACK, WS287.00 Reference Number NDT: ET-57-51-001 & MT-57-51-003	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 51-00-104 Airframe INSPECTION #1915	SPECIAL DETAILED INSPECTION OF THE FLAP TRACK, WS404.00 Reference Number NDT: ET-57-51-002 & MT-57-51-004	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 51-00-105 Airframe INSPECTION #1189	SPECIAL DETAILED INSPECTION OF THE FLAP CARRIAGE, WS47.80, WS178.00, WS287.00 AND WS404.00. Reference Number NDT ET-57-51-005	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 51-00-106 Airframe INSPECTION 7500 L #1133	SPECIAL DETAILED INSPECTION OF THE FLAP SIDE FITTING, WS47.80 Reference Number NDT: ET-57-51-006, MT-57-51-006 & PT-57-51-006	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 51-00-107 Airframe INSPECTION #2793	SPECIAL DETAILED INSPECTION OF THE FLAP RAIL FORWARD FITTING, WS287.00 AND WS404.00 Reference Number NDT: ET-57-51-007 & MT-57-51-007	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 51-00-108 Airframe INSPECTION 7500 L #1386	SPECIAL DETAILED INSPECTION OF THE FLAP BODY FITTING (METALLIC), WS178.00, WS287.00 AND WS404.00 Reference Number NDT ET-57-51-008	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 51-00-109 Airframe INSPECTION #1056	SPECIAL DETAILED INSPECTION OF THE INBOARD, MID AND OUTBOARD FLAP (METALLIC) END RIBS Reference Number ET-57-51-009	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 51-00-110 Airframe INSPECTION 7500 L #564	DETAILED INSPECTION OF THE INBOARD, MID AND OUTBOARD FLAPS (COMPOSITE)	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 51-00-201 Airframe INSPECTION 60M #5066	SPECIAL DETAILED INSPECTION OF THE INBOARD-FLAP INTERNAL RIBS	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
57 51-05-201 Airframe INSPECTION 60M #1828	DETAILED INSPECTION OF THE FLAP TRACK RAILS - WS47.80, WS178.00, WS287.00 AND WS404.00	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
57 51-05-202 Airframe INSPECTION 120M #511	DETAILED INSPECTION OF THE FLAP SUPPORT FITTINGS - WS47.80, WS178.00, WS287.00 AND WS404.00	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 51-05-203 Airframe INSPECTION 60M #154	DETAILED INSPECTION OF THE INNER-FLAP INNER-FITTINGS AND END RIBS	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
57 51-05-204 Airframe INSPECTION 60M #567	DETAILED INSPECTION OF THE INNER-FLAP OUTER-FITTINGS AND THE MIDDLE-FLAP INNER-FITTINGS AND END RIBS	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
57 51-05-205 Airframe INSPECTION 60M #1544	DETAILED INSPECTION OF THE MIDDLE-FLAP OUTER-FITTINGS AND THE OUTER-FLAP INNER-FITTINGS AND END RIBS	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
57 51-05-206 Airframe INSPECTION 60M #1933	DETAILED INSPECTION OF THE OUTER-FLAP OUTER-FITTINGS AND END RIBS	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
57 51-05-207 Airframe INSPECTION #1215	DETAILED INSPECTION OF THE INNER FLAPS UPPER AND LOWER SKIN	21-MAR-2010 H: 0.00	L: 1875	L: 50		L: 1875	L: 380
57 51-05-208 Airframe INSPECTION #1849	SPECIAL DETAILED INSPECTION OF THE INNER FLAPS TRAILING EDGE UPPER AND LOWER SKIN AND CORE	29-JAN-2018 H: 2586.20 L: 898	L: 950	L: 50		L: 1848	L: 353
57 51-05-209 Airframe INSPECTION 3750 L #2597	DETAILED INSPECTION OF THE MIDDLE/OUTBOARD UPPER AND LOWER FLAPS SKIN	21-MAR-2010 H: 0.00	L: 3750	L: 50		L: 3750	L: 2255
57 51-05-210 Airframe INSPECTION #438	SPECIAL DETAILED INSPECTION OF THE MIDDLE/OUTER FLAP PANEL TRAILING EDGE UPPER AND LOWER SKIN AND CORE	21-MAR-2010 H: 0.00	L: 1875	L: 50		L: 1875	L: 380
57 5100-001 Airframe PART #2978	OUTBOARD LH FLAP Part Number GM148-1003-13 Serial Number 387	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 5100-002 Airframe PART #2625	OUTBOARD RH FLAP Part Number Serial Number GM148-1003-14 385	21-MAR-2010 H: 0.00					
57 5100-003 Airframe PART #481	MIDDLE RH FLAP Part Number Serial Number GM148-1002-30 390	21-MAR-2010 H: 0.00					
57 5100-004 Airframe PART #1252	MIDDLE LH FLAP Part Number Serial Number GM148-1002-29 389	21-MAR-2010 H: 0.00					
57 5100-005 Airframe PART #2834	INBOARD LH FLAP Part Number Serial Number GM148-1001-33 392	21-MAR-2010 H: 0.00					
57 5100-006 Airframe PART #2884	INBOARD RH FLAP Part Number Serial Number GM148-1001-34 390	21-MAR-2010 H: 0.00					
57 60-00-101 Airframe INSPECTION #1854	SPECIAL DETAILED INSPECTION OF THE AILERON CENTER-HINGE ASSEMBLY Reference Number NDT ET-57-60-001, PT-57-60-001	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 60-00-103 Airframe INSPECTION #767	SPECIAL DETAILED INSPECTION OF THE AILERON INNER-HINGE AND OUTER-HINGE PINS Reference Number NDT PT-57-60-002	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 60-00-104 Airframe INSPECTION 7500 L #290	DETAILED INSPECTION OF THE AILERONS	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 60-00-105 Airframe INSPECTION #4966	SPECIAL DETAILED INSPECTION OF THE AILERON INNER-HINGE AND OUTER-HINGE FITTING ASSEMBLIES		L: 7500			L: 7500	L: 6005





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 60-00-201 Airframe INSPECTION 120M #430	DETAILED INSPECTION OF THE AILERON HINGE FITTINGS	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
57 60-00-202 Airframe INSPECTION #1768	SPECIAL DETAILED INSPECTION OF THE AILERON SKIN	21-MAR-2010 H: 0.00	L: 1875	L: 50		L: 1875	L: 380
57 60-00-203 Airframe INSPECTION 7500 L #931	DETAILED INSPECTION OF THE AILERON SPAR	21-MAR-2010 H: 0.00	L: 7500	L: 50		L: 7500	L: 6005
57 6000-001 Airframe PART #45	LEFT AILERON Part Number Serial Number GM158-1000-5 393	21-MAR-2010 H: 0.00					
57 6000-002 Airframe PART #1775	RIGHT AILERON Part Number Serial Number Work Order Number Scheduled Man Hours GM158-1000-6 0569 FLL BAS 9385 19-Mar- 2022 0.00	11-DEC-2012 H: 426.50 L: 209					
57 70-00-101 Airframe INSPECTION #2313	SPECIAL DETAILED INSPECTION OF THE SPOILERS (NO. 1 TO NO. 6) HINGE FITTINGS	21-MAR-2010 H: 0.00	L: 3066			L: 3066	L: 1571
57 70-00-102 Airframe INSPECTION 7500 L #2897	DETAILED INSPECTION OF THE SPOILERS NO. 1 TO NO. 6	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
57 71-00-201 Airframe INSPECTION 120M #3001	DETAILED INSPECTION OF THE GROUND-SPOILER SUPPORT-FITTINGS	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
57 71-00-202 Airframe INSPECTION 120M #867	DETAILED INSPECTION OF THE GROUND-SPOILER SUPPORT-FITTINGS - BL47.61AND WS178.00	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 71-00-203 Airframe INSPECTION 3750 L #1267	SPECIAL DETAILED INSPECTION OF THE GROUND SPOILER SKIN	21-MAR-2010 H: 0.00	L: 3750	L: 50		L: 3750	L: 2255
57 7100-001 Airframe PART #2132	GROUND OUTBOARD LH SPOILER Part Number Serial Number GM168-1200-13 387	21-MAR-2010 H: 0.00					
57 7100-002 Airframe PART #911	GROUND INBOARD LH SPOILER Part Number Serial Number GM168-1100-1 389	21-MAR-2010 H: 0.00					
57 7100-003 Airframe PART #3008	GROUND INBOARD RH SPOILER Part Number Serial Number GM168-1100-2 389	21-MAR-2010 H: 0.00					
57 7100-004 Airframe PART #2815	GROUND OUTBOARD RH SPOILER Part Number Serial Number GM168-1200-14 389	21-MAR-2010 H: 0.00					
57 72-00-201 Airframe INSPECTION 120M #2756	DETAILED INSPECTION OF THE MULTI-FUNCTION SPOILER SUPPORT-FITTINGS	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
57 72-00-202 Airframe INSPECTION 120M #890	DETAILED INSPECTION OF THE MULTI-FUNCTION SPOILER HINGE FITTINGS - WS178.00 AND WS404.00	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
57 72-00-203 Airframe INSPECTION 3750 L #2525	SPECIAL DETAILED INSPECTION OF THE MULTI-FUNCTION SPOILER SKIN - WS178.00 AND WS404.00	21-MAR-2010 H: 0.00	L: 3750	L: 50		L: 3750	L: 2255
57 7200-001 Airframe PART #192	OUTBOARD LEFT SPOILERON Part Number Serial Number GM168-1800-31 389	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 7200-002 Airframe PART #384	INBOARD LEFT SPOILERON Part Number GM168-1700-31 Serial Number 388	21-MAR-2010 H: 0.00					
57 7200-003 Airframe PART #3018	INBOARD RIGHT SPOILERON Part Number GM168-1700-32 Serial Number 387	21-MAR-2010 H: 0.00					
57 7200-004 Airframe PART #2285	OUTBOARD RIGHT SPOILERON Part Number GM168-1800-32 Serial Number 388	21-MAR-2010 H: 0.00					
57 ZL-00-201 Airframe INSPECTION 30M #2774	GENERAL VISUAL INSPECTION OF THE WING LEADING EDGE SLATS - EXTERNAL LH	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
57 ZL-00-202 Airframe INSPECTION 30M #1155	GENERAL VISUAL INSPECTION OF THE WING LEADING EDGE SLATS - EXTERNAL RH	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
57 ZL-00-203 Airframe INSPECTION 60M #2136	GENERAL VISUAL INSPECTION OF THE WING LEADING-EDGE AND SLATS - INTERNAL LH	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
57 ZL-00-204 Airframe INSPECTION 60M #828	GENERAL VISUAL INSPECTION OF THE WING LEADING-EDGE AND SLATS - INTERNAL RH	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
57 ZL-00-205 Airframe INSPECTION 30M #2974	GENERAL VISUAL INSPECTION OF THE WING BETWEEN WS47.60 AND WS178.00 - EXTERNAL LH	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
57 ZL-00-206 Airframe INSPECTION 30M #451	GENERAL VISUAL INSPECTION OF THE WING BETWEEN WS47.60 AND WS178.00 - EXTERNAL RH	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3



ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 ZL-00-207 Airframe INSPECTION 120M #808	GENERAL VISUAL INSPECTION OF THE INBOARD WING BOX - INTERNAL LH	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
57 ZL-00-208 Airframe INSPECTION 120M #965	GENERAL VISUAL INSPECTION OF THE INBOARD WING BOX - INTERNAL RH	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
57 ZL-00-209 Airframe INSPECTION 120M #548	GENERAL VISUAL INSPECTION OF THE INBOARD WING BOX BETWEEN THE AUXILIARY SPAR AND THE REAR SPAR, BETWEEN WS85.50 AND WS178.00 - INTERNAL LH	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
57 ZL-00-210 Airframe INSPECTION 120M #3029	GENERAL VISUAL INSPECTION OF THE INBOARD WING BOX BETWEEN THE AUXILIARY SPAR AND THE REAR SPAR, BETWEEN WS85.50 AND WS178.00 - INTERNAL RH	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
57 ZL-00-211 Airframe INSPECTION 60M #1670	GENERAL VISUAL INSPECTION OF THE WING BETWEEN WS178.00 AND WS287.00 - EXTERNAL LH	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
57 ZL-00-212 Airframe INSPECTION 60M #2840	GENERAL VISUAL INSPECTION OF THE WING BETWEEN WS178.00 AND WS287.00 - EXTERNAL RH	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
57 ZL-00-213 Airframe INSPECTION 120M #97	GENERAL VISUAL INSPECTION OF THE MID-WING BOX - INTERNAL LH	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
57 ZL-00-214 Airframe INSPECTION 120M #2099	GENERAL VISUAL INSPECTION OF THE MID-WING BOX - INTERNAL RH	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
57 ZL-00-215 Airframe INSPECTION 60M #2402	GENERAL VISUAL INSPECTION OF THE WING BETWEEN WS287.00 AND WS544.00 - EXTERNAL LH	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 ZL-00-216 Airframe INSPECTION 60M #441	GENERAL VISUAL INSPECTION OF THE WING BETWEEN WS287.00 AND WS544.00 - EXTERNAL RH	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
57 ZL-00-217 Airframe INSPECTION 120M #1206	GENERAL VISUAL INSPECTION OF THE OUTBOARD WING BOX - INTERNAL LH	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
57 ZL-00-218 Airframe INSPECTION 120M #2445	GENERAL VISUAL INSPECTION OF THE OUTBOARD WING BOX - INTERNAL RH	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
57 ZL-00-219 Airframe INSPECTION 900L #293	GENERAL VISUAL INSPECTION OF THE INBOARD WING BETWEEN THE AUXILIARY SPAR AND THE REAR SPAR, BETWEEN BL47.60 AND WS85.50 - INTERNAL LH	29-SEP-2017 H: 2431.70 L: 854	L: 900	L: 50		L: 1754	L: 259
57 ZL-00-220 Airframe INSPECTION 900L #853	GENERAL VISUAL INSPECTION OF THE INBOARD WING BETWEEN THE AUXILIARY SPAR AND THE REAR SPAR, BETWEEN BL47.60 AND WS85.50 - INTERNAL RH	29-SEP-2017 H: 2431.70 L: 854	L: 900	L: 50		L: 1754	L: 259
57 ZL-00-221 Airframe INSPECTION 60M #2126	GENERAL VISUAL INSPECTION OF THE WINGLET - EXTERNAL LH	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
57 ZL-00-222 Airframe INSPECTION 60M #2077	GENERAL VISUAL INSPECTION OF THE WINGLET - EXTERNAL RH	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
57 ZL-00-223 Airframe INSPECTION 1800 L #966	GENERAL VISUAL INSPECTION OF THE INBOARD FLAPS - EXTERNAL LH	10-MAR-2022 H: 4455.80 L: 1495	L: 1800	L: 50		L: 3295	L: 1800
57 ZL-00-224 Airframe INSPECTION 1800 L #2075	GENERAL VISUAL INSPECTION OF THE INBOARD FLAPS - EXTERNAL RH	10-MAR-2022 H: 4455.80 L: 1495	L: 1800	L: 50		L: 3295	L: 1800



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 ZL-00-225 Airframe INSPECTION 60M #540	GENERAL VISUAL INSPECTION OF THE INBOARD-FLAP ACTUATOR SUPPORT-FITTINGS - LH	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
57 ZL-00-226 Airframe INSPECTION 60M #2447	GENERAL VISUAL INSPECTION OF THE INBOARD-FLAP ACTUATOR SUPPORT-FITTINGS - RH	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
57 ZL-00-227 Airframe INSPECTION 60M #1831	GENERAL VISUAL INSPECTION OF THE MIDDLE FLAPS, OUTBOARD FLAPS AND AILERONS - EXTERNAL LH	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
57 ZL-00-228 Airframe INSPECTION 60M #2089	GENERAL VISUAL INSPECTION OF THE MIDDLE FLAPS, OUTBOARD FLAPS AND AILERONS - EXTERNAL RH	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
57 ZL-00-229 Airframe INSPECTION 60M #1358	GENERAL VISUAL INSPECTION OF THE AILERON HINGE FITTINGS - LH	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
57 ZL-00-230 Airframe INSPECTION 60M #1540	GENERAL VISUAL INSPECTION OF THE AILERON HINGE FITTINGS - RH	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
71 00-00-201 Airframe INSPECTION 120M #4752	DETAILED INSPECTION OF THE L/HIRF PROTECTION OF THE ENGINE COMPONENTS ELECTRICAL CONNECTORS Reference Number AMM 71-00-00-220 -801	19-APR-2021 H: 3992.00 L: 1324	M: 120			19-APR-2031	M: 109 D: 3
71 10-00-201 Airframe INSPECTION 1500H #2305	GENERAL VISUAL INSPECTION OF THE COWLS	08-FEB-2022 H: 4399.80 L: 1478	H: 1500.00	H: 50.00		H: 5899.80	H: 1444.00

Notes

IT SHOULD BE COMPLETED WITHIN THE NEW TASK REPEAT INTERVAL OR 6 MONTHS FROM THE DATE OF INTRODUCTION TO THE MAINTENANCE PROGRAM BY THE OPERATOR WHICHEVER IS GREATER, THE EXCEPTION IS IF THIS RESCHEDULING WAS TO POSTPONE THE TASK BEYOND THE PRE-REVISION TASK ACCOMPLISHMENT DEADLINE.





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
71 10-00-202 Airframe INSPECTION 1500H #834	GENERAL VISUAL INSPECTION OF THE COWL DOOR SEALS	08-FEB-2022 H: 4399.80 L: 1478	H: 1500.00	H: 50.00		H: 5899.80	H: 1444.00
<p>Notes</p> <p>IT SHOULD BE COMPLETED WITHIN THE NEW TASK REPEAT INTERVAL OR 6 MONTHS FROM THE DATE OF INTRODUCTION TO THE MAINTENANCE PROGRAM BY THE OPERATOR WHICHEVER IS GREATER, THE EXCEPTION IS IF THIS RESCHEDULING WAS TO POSTPONE THE TASK BEYOND THE PRE-REVISION TASK ACCOMPLISHMENT DEADLINE.</p>							
71 11-01-201 Airframe INSPECTION 3000H #2759	DETAILED INSPECTION OF THE INLET-COWL AERODYNAMIC SURFACES	04-MAR-2016 H: 1753.70 L: 622	H: 3000.00	H: 50.00		H: 4753.70	H: 297.90
71 11-01-202 Airframe INSPECTION 3000H #925	DETAILED INSPECTION OF THE INLET-COWL FASTENERS AND ATTACHMENT RING	04-MAR-2016 H: 1753.70 L: 622	H: 3000.00	H: 50.00		H: 4753.70	H: 297.90
71 11-01-203 Airframe INSPECTION 3000H #422	GENERAL VISUAL INSPECTION OF THE INLET-COWL REAR-BULKHEAD FIREWALL-MATERIAL (EXTERNAL SURFACES)	04-MAR-2016 H: 1753.70 L: 622	H: 3000.00	H: 50.00		H: 4753.70	H: 297.90
71 1102-001 Airframe PART #996	LH ENGINE NOSE COWL Part Number: 07C0001-005 Serial Number: E369	21-MAR-2010 H: 0.00					
71 1102-001 Engine 1 PART #1826	NO. 1 ENGINE - INLET COWL PROBE / TAT (P20/T20) SENSOR Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
71 1102-001 Engine 2 PART #1960	NO. 2 ENGINE - INLET COWL PROBE / TAT (P20/T20) SENSOR Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
71 1103-002 Airframe PART #341	RH ENGINE NOSE COWL Part Number: 07C0001-006 Serial Number: E348	21-MAR-2010 H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
71 12-01-101 Airframe INSPECTION 7500 L #2573	DETAILED INSPECTION OF THE UPPER FAN-COWL-DOOR	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
71 12-01-201 Airframe INSPECTION 120M #1285	DETAILED INSPECTION OF THE UPPER COWLS	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
71 12-01-202 Airframe INSPECTION #141	SPECIAL DETAILED INSPECTION OF THE UPPER COWLS	21-MAR-2010 H: 0.00	L: 1875	L: 50		L: 1875	L: 380
71 1201-001 Airframe PART #1898	LH ENGINE FAN DOOR UPPER COWL Part Number 07D4001-001 Serial Number E372SX/SB 4184	21-MAR-2010 H: 0.00					
71 1202-001 Airframe PART #2121	RH ENGINE FAN DOOR UPPER COWL Part Number 07D4001-002 Serial Number E370/SB41 73	21-MAR-2010 H: 0.00					
71 13-01-201 Airframe INSPECTION 30M #2922	FUNCTIONAL TEST OF THE LOWER-COWL PRESSURE-RELIEF DOORS	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
71 1301-001 Airframe PART #1535	LH ENGINE FAN DOOR LOWER COWL Part Number 07D4002-001 Serial Number E370/SB41 74	21-MAR-2010 H: 0.00					
71 1302-001 Airframe PART #2853	RH ENGINE FAN DOOR LOWER COWL Part Number 07D4003-001 Serial Number E370/SB41 75	21-MAR-2010 H: 0.00					
71 14-01-201 Airframe INSPECTION 3000H #1385	GENERAL VISUAL INSPECTION OF THE FIXED COWL SEALS	04-MAR-2016 H: 1753.70 L: 622	H: 3000.00	H: 50.00		H: 4753.70	H: 297.90





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
71 14-01-202 Airframe INSPECTION 3000H #2746	DETAILED INSPECTION OF THE FIXED COWL	04-MAR-2016 H: 1753.70 L: 622	H: 3000.00	H: 50.00		H: 4753.70	H: 297.90
71 20-00-201 Airframe INSPECTION 120M #994	DETAILED INSPECTION OF THE MOUNTS	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
71 20-00-202 Airframe INSPECTION 60M #1674	DETAILED INSPECTION OF THE CASING LUGS FOR THE FRONT MOUNTS	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3
71 21-01-101 Airframe INSPECTION 7500 L #2414	SPECIAL DETAILED INSPECTION OF THE FRONT MOUNT BEAM AND LINKS	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
71 21-01-102 Airframe INSPECTION 7500 L #2242	SPECIAL DETAILED INSPECTION OF THE THRUST STRUT	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
71 21-01-103 Airframe INSPECTION 7500 L #261	SPECIAL DETAILED INSPECTION OF THE FRONT MOUNT LINK PINS, THRUST STRUT PINS, THRUST PIN AND PYLON ATTACHMENT PINS	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
<p>Notes</p> <p>REPLACEMENT OF PIN AND ALL ASSOCIATED HARDWARE (E.G.; NUT, WASHERS, AND COTTER PIN) RESTARTS THE INSPECTION INTERVAL</p>							
71 2101-001 Airframe PART #1095	LEFT UPPER FRONT MOUNT LINK ASSEMBLY	Part Number BRR24405	Serial Number THEAP1278 9	21-MAR-2010 H: 0.00			
71 2101-002 Airframe PART #1954	RIGHT UPPER FRONT MOUNT LINK ASSEMBLY	Part Number BRR24405	Serial Number THEAP1278 7	21-MAR-2010 H: 0.00			





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
71 2101-003 Airframe PART #37	LEFT LOWER FRONT MOUNT LINK ASSEMBLY Part Number: BRR24405 Serial Number: THEAP12790	21-MAR-2010 H: 0.00					
71 2101-004 Airframe PART #1639	RIGHT LOWER FRONT MOUNT LINK ASSEMBLY Part Number: BRR24405 Serial Number: THEAP12788	21-MAR-2010 H: 0.00					
71 2102-001 Airframe PART #2033	NO. 1 MOUNT TO BEAM ATTACH PIN Part Number: BRR15812 Serial Number: 200340037	21-MAR-2010 H: 0.00					
71 2102-002 Airframe PART #1066	NO. 2 MOUNT TO BEAM ATTACH PIN Part Number: BRR15812 Serial Number: 200340005	21-MAR-2010 H: 0.00					
71 2102-003 Airframe PART #2134	NO. 3 MOUNT TO BEAM ATTACH PIN Part Number: BRR15812 Serial Number: 200340041	21-MAR-2010 H: 0.00					
71 2102-004 Airframe PART #431	NO. 4 MOUNT TO BEAM ATTACH PIN Part Number: BRR15812 Serial Number: 200340010	21-MAR-2010 H: 0.00					
71 2103-001 Airframe PART #322	FWD LH UPPER PYLON ATTACHMENT PIN Part Number: BRR15805 Serial Number: KWBA1597	21-MAR-2010 H: 0.00					
71 2103-002 Airframe PART #73	FWD LH LOWER PYLON ATTACHMENT PIN Part Number: BRR15805 Serial Number: KWBA1602	21-MAR-2010 H: 0.00					
71 2104-001 Airframe PART #657	FWD RH UPPER PYLON ATTACHMENT PIN Part Number: BRR15805 Serial Number: KWBA1603	21-MAR-2010 H: 0.00					
71 2104-002 Airframe PART #1621	FWD RH LOWER PYLON ATTACHMENT PIN Part Number: BRR15805 Serial Number: KWBA1604	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
71 2105-001 Airframe PART #465	FWD, L/H PIN Part Number Serial Number BRR15809 200492012	21-MAR-2010 H: 0.00					
71 2105-002 Airframe PART #1865	FWD, R/H PIN Part Number Serial Number BRR15809 200492045	21-MAR-2010 H: 0.00					
71 2106-001 Airframe PART #595	AFT L/H PIN Part Number Serial Number BRR15824 201749004	21-MAR-2010 H: 0.00					
71 2106-002 Airframe PART #455	AFT R/H PIN Part Number Serial Number BRR15824 201749006	21-MAR-2010 H: 0.00					
71 22-01-101 Airframe INSPECTION 7500 L #1931	SPECIAL DETAILED INSPECTION OF THE REAR MOUNT BEAM AND LINKS	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
71 22-01-102 Airframe INSPECTION 7500 L #1279	SPECIAL DETAILED INSPECTION OF THE REAR MOUNT LINK PINS AND PYLON ATTACHMENT PINS	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005
	Notes REPLACEMENT OF PIN AND ALL ASSOCIATED HARDWARE (E.G.; NUT, WASHERS, AND COTTER PIN) RESTARTS THE INSPECTION INTERVAL						
71 2201-001 Airframe PART #2039	LEFT UPPER REAR MOUNT LINK ASSEMBLY Part Number Serial Number BRR24413 THEAP1231 0	21-MAR-2010 H: 0.00					
71 2201-002 Airframe PART #1030	RIGHT UPPER REAR MOUNT LINK ASSEMBLY Part Number Serial Number BRR24413 THEAP1233 8	21-MAR-2010 H: 0.00					
71 2201-003 Airframe PART #1259	LEFT LOWER REAR MOUNT LINK ASSEMBLY Part Number Serial Number BRR24413 THEAP1231 3	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
71 2201-004 Airframe PART #1117	RIGHT LOWER REAR MOUNT LINK ASSEMBLY Part Number BRR24413 Serial Number THEAP1233 9	21-MAR-2010 H: 0.00					
71 2202-001 Airframe PART #1851	NO. 1 MOUNT BEAM TO LINK PIN Part Number BRR15835 Serial Number 200037B16 35	21-MAR-2010 H: 0.00					
71 2202-002 Airframe PART #1165	NO. 2 MOUNT BEAM TO LINK PIN Part Number BRR15835 Serial Number 200037B16 39	21-MAR-2010 H: 0.00					
71 2202-003 Airframe PART #2907	NO. 3 MOUNT BEAM TO LINK PIN Part Number BRR15835 Serial Number 200037B16 37	21-MAR-2010 H: 0.00					
71 2202-004 Airframe PART #269	NO. 4 MOUNT BEAM TO LINK PIN Part Number BRR15835 Serial Number 200037B16 50	21-MAR-2010 H: 0.00					
71 2203-001 Airframe PART #661	AFT LH UPPER MOUNT BEAM TO PYLON PIN Part Number BRR15840 Serial Number KWBD1580	21-MAR-2010 H: 0.00					
71 2203-002 Airframe PART #1006	AFT LH LOWER MOUNT BEAM TO PYLON PIN Part Number BRR15840 Serial Number KWBD1582	21-MAR-2010 H: 0.00					
71 2203-003 Airframe PART #2092	AFT RH UPPER MOUNT BEAM TO PYLON PIN Part Number BRR15840 Serial Number KWBD1583	21-MAR-2010 H: 0.00					
71 2203-004 Airframe PART #1424	AFT RH LOWER MOUNT BEAM TO PYLON PIN Part Number BRR15840 Serial Number KWBD1585	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
71 2204-001 Airframe PART #2671	L/H APRON ASSY Part Number 07E0001-023	Serial Number E371	21-MAR-2010 H: 0.00				
71 2205-001 Airframe PART #1443	R/H APRON ASSY Part Number 07E0001-024	Serial Number E371	21-MAR-2010 H: 0.00				
71 2207-001 Airframe PART #980	LINK TO MOUNT RING, L/H LOWER PIN Part Number BRR15838	Serial Number KWBC1253	21-MAR-2010 H: 0.00				
71 2207-002 Airframe PART #956	LINK TO MOUNT RING L/H UPPER PIN Part Number BRR15838	Serial Number KWBC1242	21-MAR-2010 H: 0.00				
71 2207-003 Airframe PART #1253	LINK TO MOUNT RING, R/H LOWER PIN Part Number BRR15838	Serial Number KWBC1584	21-MAR-2010 H: 0.00				
71 2207-004 Airframe PART #238	LINK TO MOUNT RING, R/H UPPER PIN Part Number BRR15838	Serial Number KWBC1583	21-MAR-2010 H: 0.00				
71 2220-001 Airframe PART #1892	L/H BEAM REAR MOUNT ASSEMBLY Part Number BRR24391	Serial Number BSTDK0426	21-MAR-2010 H: 0.00				
71 2220-002 Airframe PART #1814	R/H BEAM REAR MOUNT ASSEMBLY Part Number BRR24400	Serial Number BSTDK0437	21-MAR-2010 H: 0.00				
71 2221-001 Airframe PART #2727	L/H BEAM OF REAR MOUNT ASSEMBLY Part Number BRR24407	Serial Number BSEAP0224	21-MAR-2010 H: 0.00				
71 2221-002 Airframe PART #2718	R H BEAM OF REAR MOUNT ASSEMBLY Part Number BRR24407	Serial Number BSEAP0172	21-MAR-2010 H: 0.00				



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
71 7102-001 Engine 1 PART #259	NO. 1 ENGINE - DRAINS EJECTOR PUMP Part Number CV41-14-2 Serial Number 09-110440	21-MAR-2010 H: 0.00					
71 7102-001 Engine 2 PART #2515	NO. 2 ENGINE - DRAINS EJECTOR PUMP Part Number CV41-14-2 Serial Number 09-110446	21-MAR-2010 H: 0.00					
71 EN1 Airframe PART #3389	NO. 1 ENGINE Part Number BR710 Serial Number 12889	H: 0.00					
71 EN2 Airframe PART #3589	NO. 2 ENGINE Part Number BR710 Serial Number 12890	H: 0.00					
71 ZL-00-201 Airframe INSPECTION 3000H #1073	GENERAL VISUAL INSPECTION OF THE NACELLE - RH	01-DEC-2018 H: 3011.20 L: 1025	H: 3000.00	H: 50.00		H: 6011.20	H: 1555.40
71 ZL-00-202 Airframe INSPECTION 3000H #1322	GENERAL VISUAL INSPECTION OF THE NACELLE - LH	01-DEC-2018 H: 3011.20 L: 1025	H: 3000.00	H: 50.00		H: 6011.20	H: 1555.40
71 ZL-00-203 Airframe INSPECTION 3000H #2207	GENERAL VISUAL INSPECTION OF THE ENGINE - INTERNAL LH	01-DEC-2018 H: 3011.20 L: 1025	H: 3000.00	H: 50.00		H: 6011.20	H: 1555.40
71 ZL-00-204 Airframe INSPECTION 3000H #1097	GENERAL VISUAL INSPECTION OF THE ENGINE - INTERNAL RH	01-DEC-2018 H: 3011.20 L: 1025	H: 3000.00	H: 50.00		H: 6011.20	H: 1555.40
72 -CUS-9001 Airframe INSPECTION #4655	DOWNLOAD ENGINE TREND DATA & SEND TO Email: reports@jet-care.com	05-MAR-2022 H: 4446.70 L: 1492	M: 1			30-APR-2022	M: 1 D: 14





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 0001-001 Engine 1 PART #620	NO. 1 ENGINE - 31 LP COMPRESSOR FAN MODULE Part Number M31-113 Serial Number 31101923	21-MAR-2010 H: 0.00					
72 0001-001 Engine 2 PART #1725	NO. 2 ENGINE - 31 LP COMPRESSOR FAN MODULE Part Number M31-113 Serial Number 31101924	21-MAR-2010 H: 0.00					
72 0002-001 Engine 1 PART #1037	NO. 1 ENGINE - 32 INTERMEDIATE CASE MODULE Part Number M32-121 Serial Number 32121790	21-MAR-2010 H: 0.00					
72 0002-001 Engine 2 PART #800	NO. 2 ENGINE - 32 INTERMEDIATE CASE MODULE Part Number M32-121 Serial Number 32121791	21-MAR-2010 H: 0.00					
72 0003-001 Engine 1 PART #2415	NO. 1 ENGINE - 33 HP COMPRESSOR MODULE Part Number M33-114 Serial Number 33121792	21-MAR-2010 H: 0.00					
72 0003-001 Engine 2 PART #2120	NO. 2 ENGINE - 33 HP COMPRESSOR MODULE Part Number M33-114 Serial Number 33121793	21-MAR-2010 H: 0.00					
72 0004-001 Engine 1 PART #284	NO. 1 ENGINE - 34 LP COMPRESSOR CASE MODULE Part Number M34-110 Serial Number 34101911	21-MAR-2010 H: 0.00					
72 0004-001 Engine 2 PART #2808	NO. 2 ENGINE - 34 LP COMPRESSOR CASE MODULE Part Number M34-110 Serial Number 34101912	21-MAR-2010 H: 0.00					
72 0005-001 Engine 1 PART #74	NO. 1 ENGINE - 41 COMBUSTION & HP TURBINE MODULE Part Number M41-125 Serial Number 41121791	21-MAR-2010 H: 0.00					
72 0005-001 Engine 2 PART #34	NO. 2 ENGINE - 41 COMBUSTION & HP TURBINE MODULE Part Number M41-125 Serial Number 41121792	21-MAR-2010 H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 0006-001 Engine 1 PART #614	NO. 1 ENGINE - 51 LP TURBINE MODULE Part Number: M51-111 Serial Number: 51101911	21-MAR-2010 H: 0.00					
72 0006-001 Engine 2 PART #330	NO. 2 ENGINE - 51 LP TURBINE MODULE Part Number: M51-111 Serial Number: 51101912	21-MAR-2010 H: 0.00					
72 0007-001 Engine 1 PART #1380	NO. 1 ENGINE - 61 ACCESSORY GEARBOX MODULE Part Number: M61-204 Serial Number: 61121790	21-MAR-2010 H: 0.00					
72 0007-001 Engine 2 PART #1136	NO. 2 ENGINE - 61 ACCESSORY GEARBOX MODULE Part Number: M61-204 Serial Number: 61121791	21-MAR-2010 H: 0.00					
72 001 Engine 1 INSPECTION #4854	GENERAL VISUAL INSPECTION OF THE INTERMEDIATE CASE STRUTS	25-FEB-2022 H: 4428.00 C: 1487	M: 2 D: 60			25-APR-2022	M: 1 D: 9
72 002 Engine 2 INSPECTION #4876	GENERAL VISUAL INSPECTION OF THE INTERMEDIATE CASE STRUTS	25-FEB-2022 H: 4428.00 C: 1487	M: 2 D: 60			25-APR-2022	M: 1 D: 9
72 1066 Airframe PART #4778	DAMPER ON RH ENGINE LOWER COWL Part Number: A3363-4 Serial Number: 7461	23-NOV-2016 H: 2064.80 L: 722					
72 2104-001 Airframe PART #2797	LH THRUST STRUT Part Number: BRR17672 Serial Number: 204756RF5 840	21-MAR-2010 H: 0.00					
72 2104-002 Airframe PART #1547	RH THRUST STRUT Part Number: BRR15817 Serial Number: 204756RF6 509	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 30-01-201 Engine 1 INSPECTION ENG 1-2000 #2170	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LP-COMPRESSOR CASE LINERS	01-DEC-2018 H: 3011.20 C: 1025	H: 2000.00	H: 50.00		H: 5011.20	H: 555.40
72 30-01-201 Engine 2 INSPECTION ENG 2 - 2000 #2928	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LP-COMPRESSOR CASE LINERS	01-DEC-2018 H: 3011.20 C: 1025	H: 2000.00	H: 50.00		H: 5011.20	H: 555.40
72 31-02-201 Engine 1 INSPECTION ENG 1-1000 #10	NO. 1 ENGINE - DETAILED INSPECTION OF THE LP COMPRESSOR BLADES	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30
72 31-02-201 Engine 2 INSPECTION ENG 2-1000 #1459	NO. 2 ENGINE - DETAILED INSPECTION OF THE LP COMPRESSOR BLADES	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30
72 31-02-202 Engine 1 INSPECTION ENG 1-1000 #1148	NO. 1 ENGINE - DETAILED INSPECTION OF THE LP-COMPRESSOR ANNULUS FILLERS	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30
72 31-02-202 Engine 2 INSPECTION ENG 2-1000 #1429	NO. 2 ENGINE - DETAILED INSPECTION OF THE LP-COMPRESSOR ANNULUS FILLERS	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30
72 31-02-203 Engine 1 INSPECTION #3412	NO. 1 ENGINE - REFURBISH COMPRESSOR ROTOR BLADE ROOT COPPER NICKEL INDIUM COATING (***) OPTION 2 - SECOND REQUIREMENT)	H: 0.00	H: 8000.00 C: 3000	H: 400.00 C: 400		H: 8000.00 C: 3000.00	H: 3544.20 C: 1505
	Notes OPT 2/2						
72 31-02-203 Engine 1 INSPECTION ENG 1-1000 #4548	NO. 1 ENGINE - REFURBISH COMPRESSOR ROTOR BLADE ROOT DRY FILM LUBRICANT (***) OPTION 2 - FIRST REQUIREMENT)	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00 C: 750	H: 100.00		H: 4741.10 C: 1983.00	H: 285.30 C: 488
	Notes OPT 2/1						





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 31-02-203 Engine 1 INSPECTION #679	NO. 1 ENGINE - RESTORATION OF THE LP COMPRESSOR FAN BLADES [RR TLM - REFURBISH COMPRESSOR ROTOR BLADE ROOT COPPER NICKEL INDIUM AND DRY FILM LUBRICANT (***) OPTION 1]]	18-APR-2020 H: 3741.10 C: 1233	H: 4000.00 C: 3000	H: 400.00		H: 7741.10 C: 4233.00	H: 3285.30 C: 2738
	Notes OPT 1						
72 31-02-203 Engine 1 INSPECTION #2219	NO. 1 ENGINE - RESTORATION OF THE LP COMPRESSOR FAN BLADES [RR TLM - REFURBISH COMPRESSOR ROTOR BLADE ROOT DRY FILM LUBRICANT (**)]	21-MAR-2010 H: 0.00					
72 31-02-203 Engine 2 INSPECTION #3722	NO. 2 ENGINE - REFURBISH COMPRESSOR ROTOR BLADE ROOT COPPER NICKEL INDIUM COATING (***) OPTION 2 - SECOND REQUIREMENT)	H: 0.00	H: 8000.00 C: 3000	H: 400.00 C: 400		H: 8000.00 C: 3000.00	H: 3544.20 C: 1505
	Notes OPT 2/2						
72 31-02-203 Engine 2 INSPECTION ENG 2-1000 #3619	NO. 2 ENGINE - REFURBISH COMPRESSOR ROTOR BLADE ROOT DRY FILM LUBRICANT (***) OPTION 2 - FIRST REQUIREMENT)	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00 C: 750	H: 100.00		H: 4741.10 C: 1983.00	H: 285.30 C: 488
72 31-02-203 Engine 2 INSPECTION #807	NO. 2 ENGINE - RESTORATION OF THE LP COMPRESSOR FAN BLADES [RR TLM - REFURBISH COMPRESSOR ROTOR BLADE ROOT COPPER NICKEL INDIUM AND DRY FILM LUBRICANT (***) OPTION 1]]	18-APR-2020 H: 3741.10 C: 1233	H: 4000.00 C: 3000	H: 400.00		H: 7741.10 C: 4233.00	H: 3285.30 C: 2738
	Notes OPT 1						
72 31-02-203 Engine 2 INSPECTION #2390	NO. 2 ENGINE - RESTORATION OF THE LP COMPRESSOR FAN BLADES [RR TLM - REFURBISH COMPRESSOR ROTOR BLADE ROOT DRY FILM LUBRICANT (**)]	21-MAR-2010 H: 0.00					
72 31-02-301 Airframe INSPECTION 30M #5069	SPECIAL DETAILED INSPECTION OF THE LP-COMPRESSOR FAN-TRACK-LINER (PRE SB BR700 -72-100981)	19-APR-2021 H: 3992.00 L: 1324	M: 30	M: 3		19-OCT-2023	M: 19 D: 3
72 3101-001 Engine 1 PART - Life Limited #3007	NO. 1 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number BRR22626 Serial Number HLAH88739	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 3101-001 Engine 2 PART - Life Limited #2199	NO. 2 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH88611	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-002 Engine 1 PART - Life Limited #2188	NO. 1 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH89839	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-002 Engine 2 PART - Life Limited #827	NO. 2 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH88690	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-003 Engine 1 PART - Life Limited #1810	NO. 1 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH89841	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-003 Engine 2 PART - Life Limited #726	NO. 2 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH88694	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-004 Engine 1 PART - Life Limited #1047	NO. 1 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH89845	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-004 Engine 2 PART - Life Limited #1289	NO. 2 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH88733	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-005 Engine 1 PART - Life Limited #1757	NO. 1 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH89850	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-005 Engine 2 PART - Life Limited #972	NO. 2 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH88734	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-006 Engine 1 PART - Life Limited #1177	NO. 1 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH89851	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 3101-006 Engine 2 PART - Life Limited #2694	NO. 2 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH89009	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-007 Engine 1 PART - Life Limited #537	NO. 1 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH89860	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-007 Engine 2 PART - Life Limited #2185	NO. 2 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH89012	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-008 Engine 1 PART - Life Limited #2108	NO. 1 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH89867	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-008 Engine 2 PART - Life Limited #393	NO. 2 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH89013	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-009 Engine 1 PART - Life Limited #2019	NO. 1 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH89889	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-009 Engine 2 PART - Life Limited #2986	NO. 2 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH89014	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-010 Engine 1 PART - Life Limited #1760	NO. 1 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH89891	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-010 Engine 2 PART - Life Limited #245	NO. 2 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH89312	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-011 Engine 1 PART - Life Limited #2025	NO. 1 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH89893	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 3101-011 Engine 2 PART - Life Limited #268	NO. 2 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number: BRR22626 Serial Number: HLAH89313	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-012 Engine 1 PART - Life Limited #1899	NO. 1 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number: BRR22626 Serial Number: HLAH89894	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-012 Engine 2 PART - Life Limited #52	NO. 2 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number: BRR22626 Serial Number: HLAH89827	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-013 Engine 1 PART - Life Limited #683	NO. 1 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number: BRR22626 Serial Number: HLAH89898	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-013 Engine 2 PART - Life Limited #292	NO. 2 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number: BRR22626 Serial Number: HLAH89828	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-014 Engine 1 PART - Life Limited #2964	NO. 1 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number: BRR22626 Serial Number: HLAH89900	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-014 Engine 2 PART - Life Limited #764	NO. 2 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number: BRR22626 Serial Number: HLAH89830	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-015 Engine 1 PART - Life Limited #2990	NO. 1 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number: BRR22626 Serial Number: HLAH89905	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-015 Engine 2 PART - Life Limited #1497	NO. 2 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number: BRR22626 Serial Number: HLAH89832	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-016 Engine 1 PART - Life Limited #1629	NO. 1 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number: BRR22626 Serial Number: HLAH89907	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 3101-016 Engine 2 PART - Life Limited #968	NO. 2 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH89833	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-017 Engine 1 PART - Life Limited #2346	NO. 1 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH89911	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-017 Engine 2 PART - Life Limited #2770	NO. 2 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH89840	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-018 Engine 1 PART - Life Limited #2601	NO. 1 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH89915	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-018 Engine 2 PART - Life Limited #420	NO. 2 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH89859	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-019 Engine 1 PART - Life Limited #1953	NO. 1 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH89916	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-019 Engine 2 PART - Life Limited #551	NO. 2 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH89861	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-020 Engine 1 PART - Life Limited #2161	NO. 1 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH89949	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-020 Engine 2 PART - Life Limited #228	NO. 2 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH89882	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-021 Engine 1 PART - Life Limited #304	NO. 1 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number Serial Number BRR22626 HLAH89987	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 3101-021 Engine 2 PART - Life Limited #391	NO. 2 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number: BRR22626 Serial Number: HLAH89925	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-022 Engine 1 PART - Life Limited #1223	NO. 1 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number: BRR22626 Serial Number: HLAH89988	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-022 Engine 2 PART - Life Limited #395	NO. 2 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number: BRR22626 Serial Number: HLAH89926	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-023 Engine 1 PART - Life Limited #1224	NO. 1 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number: BRR22626 Serial Number: HLAH89989	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-023 Engine 2 PART - Life Limited #725	NO. 2 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number: BRR22626 Serial Number: HLAH89927	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-024 Engine 1 PART - Life Limited #703	NO. 1 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number: BRR22626 Serial Number: HLAH89991	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3101-024 Engine 2 PART - Life Limited #2914	NO. 2 ENGINE - LP COMPRESSOR ANNULUS FILLER Part Number: BRR22626 Serial Number: HLAH89931	21-MAR-2010 H: 0.00	C: 6300		M: 0 H: 0.00 C: 0	C: 6300.00	C: 4805
72 3102-001 Engine 1 PART - Life Limited #2968	NO. 1 ENGINE - LP COMPRESSOR DISK Part Number: FW33927 Serial Number: STDK54074	21-MAR-2010 H: 0.00	C: 4800		M: 0 H: 0.00 C: 0	C: 4800.00	C: 3305
72 3102-001 Engine 2 PART - Life Limited #2787	NO. 2 ENGINE - LP COMPRESSOR DISK Part Number: FW33927 Serial Number: STDK54400	21-MAR-2010 H: 0.00	C: 4800		M: 0 H: 0.00 C: 0	C: 4800.00	C: 3305
72 3103-001 Engine 1 PART - Life Limited #2656	NO. 1 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number: FW33513 Serial Number: RGE59909	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 3103-001 Engine 2 PART - Life Limited #1483	NO. 2 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE61980	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-002 Engine 1 PART - Life Limited #151	NO. 1 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE59873	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-002 Engine 2 PART - Life Limited #150	NO. 2 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE61959	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-003 Engine 1 PART - Life Limited #2609	NO. 1 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE59937	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-003 Engine 2 PART - Life Limited #3042	NO. 2 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE61284	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-004 Engine 1 PART - Life Limited #2061	NO. 1 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE59943	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-004 Engine 2 PART - Life Limited #646	NO. 2 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE60810	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-005 Engine 1 PART - Life Limited #1022	NO. 1 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE59856	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-005 Engine 2 PART - Life Limited #453	NO. 2 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE62051	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-006 Engine 1 PART - Life Limited #2168	NO. 1 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE59753	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 3103-006 Engine 2 PART - Life Limited #190	NO. 2 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE61968	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-007 Engine 1 PART - Life Limited #2957	NO. 1 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE60047	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-007 Engine 2 PART - Life Limited #1339	NO. 2 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE61626	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-008 Engine 1 PART - Life Limited #1250	NO. 1 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE59940	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-008 Engine 2 PART - Life Limited #1200	NO. 2 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE61529	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-009 Engine 1 PART - Life Limited #2055	NO. 1 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE57509	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-009 Engine 2 PART - Life Limited #626	NO. 2 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE61683	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-010 Engine 1 PART - Life Limited #895	NO. 1 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE59870	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-010 Engine 2 PART - Life Limited #2430	NO. 2 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE62071	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-011 Engine 1 PART - Life Limited #1872	NO. 1 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE59974	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 3103-011 Engine 2 PART - Life Limited #527	NO. 2 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number FW33513 Serial Number RGE61969	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-012 Engine 1 PART - Life Limited #2506	NO. 1 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number FW33513 Serial Number RGE59144	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-012 Engine 2 PART - Life Limited #1963	NO. 2 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number FW33513 Serial Number RGE61728	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-013 Engine 1 PART - Life Limited #1055	NO. 1 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number FW33513 Serial Number RGE59801	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-013 Engine 2 PART - Life Limited #751	NO. 2 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number FW33513 Serial Number RGE62106	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-014 Engine 1 PART - Life Limited #2314	NO. 1 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number FW33513 Serial Number RGE59860	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-014 Engine 2 PART - Life Limited #1398	NO. 2 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number FW33513 Serial Number RGE62093	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-015 Engine 1 PART - Life Limited #2856	NO. 1 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number FW33513 Serial Number RGE59488	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-015 Engine 2 PART - Life Limited #2925	NO. 2 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number FW33513 Serial Number RGE61902	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-016 Engine 1 PART - Life Limited #757	NO. 1 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number FW33513 Serial Number RGE59487	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 3103-016 Engine 2 PART - Life Limited #941	NO. 2 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE61979	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-017 Engine 1 PART - Life Limited #2176	NO. 1 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE58738	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-017 Engine 2 PART - Life Limited #1550	NO. 2 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE61932	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-018 Engine 1 PART - Life Limited #858	NO. 1 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE59984	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-018 Engine 2 PART - Life Limited #2685	NO. 2 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE62017	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-019 Engine 1 PART - Life Limited #1667	NO. 1 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE60037	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-019 Engine 2 PART - Life Limited #1835	NO. 2 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE62058	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-020 Engine 1 PART - Life Limited #1808	NO. 1 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE60054	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-020 Engine 2 PART - Life Limited #2574	NO. 2 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE62084	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-021 Engine 1 PART - Life Limited #2254	NO. 1 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number Serial Number FW33513 RGE59730	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 3103-021 Engine 2 PART - Life Limited #894	NO. 2 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number: FW33513 Serial Number: RGE61909	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-022 Engine 1 PART - Life Limited #883	NO. 1 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number: FW33513 Serial Number: RGE59982	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-022 Engine 2 PART - Life Limited #1174	NO. 2 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number: FW33513 Serial Number: RGE61754	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-023 Engine 1 PART - Life Limited #2510	NO. 1 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number: FW33513 Serial Number: RGE57854	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-023 Engine 2 PART - Life Limited #1020	NO. 2 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number: FW33513 Serial Number: RGE61682	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-024 Engine 1 PART - Life Limited #2696	NO. 1 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number: FW33513 Serial Number: RGE57508	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 3103-024 Engine 2 PART - Life Limited #1916	NO. 2 ENGINE - LP COMPRESSOR ROTOR BLADE Part Number: FW33513 Serial Number: RGE61984	21-MAR-2010 H: 0.00	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 8505
72 32-02-201 Engine 1 INSPECTION ENG 1-1000 #847	NO. 1 ENGINE - DETAILED INSPECTION OF THE LP-COMPRESSOR OUTLET GUIDE- VANES	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30
72 32-02-201 Engine 2 INSPECTION ENG 2-1000 #2809	NO. 2 ENGINE - DETAILED INSPECTION OF THE LP-COMPRESSOR OUTLET GUIDE- VANES	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 32-02-202 Engine 1 INSPECTION ENG 1-1000 #61	NO. 1 ENGINE - DETAILED INSPECTION OF THE LP-COMPRESSOR ENGINE STATOR-VANES	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30
72 32-02-202 Engine 2 INSPECTION ENG 2-1000 #1938	NO. 2 ENGINE - DETAILED INSPECTION OF THE LP-COMPRESSOR ENGINE STATOR-VANES	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30
72 3201-001 Engine 1 PART - Life Limited #1986	NO. 1 ENGINE - FAN SHAFT Part Number Serial Number BRR23914 RRDSFTCL 28872	21-MAR-2010 H: 0.00	C: 25000		M: 0 H: 0.00 C: 0	C: 25000.00	C: 23505
72 3201-001 Engine 2 PART - Life Limited #497	NO. 2 ENGINE - FAN SHAFT Part Number Serial Number BRR23914 CL26583	21-MAR-2010 H: 0.00	C: 25000		M: 0 H: 0.00 C: 0	C: 25000.00	C: 23505
72 3202-001 Engine 1 PART - Life Limited #1697	NO. 1 ENGINE - INTERMEDIATE CASE Part Number Serial Number BRR22752 01699	21-MAR-2010 H: 0.00	C: 20000		M: 0 H: 0.00 C: 0	C: 20000.00	C: 18505
72 3202-001 Engine 2 PART - Life Limited #301	NO. 2 ENGINE - INTERMEDIATE CASE Part Number Serial Number BRR22752 01707	21-MAR-2010 H: 0.00	C: 20000		M: 0 H: 0.00 C: 0	C: 20000.00	C: 18505
72 3202-002 Engine 1 PART - Life Limited #4827	NO. 1 ENGINE - INTERMEDIATE CASE (P/N: KH96888)		C: 20000			C: 20000.00	C: 18505
	Notes NOTE: DENOTES FINITE LIFE						
72 3202-002 Engine 2 PART - Life Limited #4849	NO. 2 ENGINE - INTERMEDIATE CASE (P/N: KH96888)		C: 20000			C: 20000.00	C: 18505
	Notes NOTE: DENOTES FINITE LIFE						





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 3203-001 Engine 1 PART #2698	NO. 1 ENGINE - REAR BEARING SUPPORT STRUCTURE Part Number Serial Number BRR23504 01734	21-MAR-2010 H: 0.00					
72 3203-001 Engine 2 PART #2443	NO. 2 ENGINE - REAR BEARING SUPPORT STRUCTURE Part Number Serial Number BRR23504 01727	21-MAR-2010 H: 0.00					
72 3204-001 Engine 1 PART #1070	NO. 1 ENGINE - NO 3 BEARING Part Number Serial Number BRR22056 1719	21-MAR-2010 H: 0.00					
72 3204-001 Engine 2 PART #2887	NO. 2 ENGINE - NO 3 BEARING Part Number Serial Number BRR22056 1716	21-MAR-2010 H: 0.00					
72 3205-001 Engine 1 PART #1702	NO. 1 ENGINE - LPC TRIM BALANCE PROBE Part Number Serial Number 1022-1-11 6973	21-MAR-2010 H: 0.00					
72 3205-001 Engine 2 PART #572	NO. 2 ENGINE - LPC TRIM BALANCE PROBE Part Number Serial Number 1022-1-11 6981	21-MAR-2010 H: 0.00					
72 3205-002 Engine 1 PART #1112	NO. 1 ENGINE - LPC TRIM BALANCE PROBE Part Number Serial Number 1022-1-11 6974	21-MAR-2010 H: 0.00					
72 3205-002 Engine 2 PART #1907	NO. 2 ENGINE - LPC TRIM BALANCE PROBE Part Number Serial Number 1022-1-11 6982	21-MAR-2010 H: 0.00					
72 3205-003 Engine 1 PART #714	NO. 1 ENGINE - LPC TRIM BALANCE PROBE Part Number Serial Number 1022-1-11 6975	21-MAR-2010 H: 0.00					
72 3205-003 Engine 2 PART #1091	NO. 2 ENGINE - LPC TRIM BALANCE PROBE Part Number Serial Number 1022-1-11 6983	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 3205-004 Engine 1 PART #1616	NO. 1 ENGINE - LPC TRIM BALANCE PROBE Part Number 1022-1-11 Serial Number 6976	21-MAR-2010 H: 0.00					
72 3205-004 Engine 2 PART #3002	NO. 2 ENGINE - LPC TRIM BALANCE PROBE Part Number 1022-1-11 Serial Number 6984	21-MAR-2010 H: 0.00					
72 3206-001 Engine 1 PART #2153	NO. 1 ENGINE - BEARING OUTER RING Part Number BRR12474 Serial Number 1670	21-MAR-2010 H: 0.00					
72 3206-001 Engine 2 PART #2231	NO. 2 ENGINE - BEARING OUTER RING Part Number BRR12474 Serial Number 1523	21-MAR-2010 H: 0.00					
72 3206-002 Engine 1 PART #1901	NO. 1 ENGINE - BEARING ASSEMBLY Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
72 3206-002 Engine 2 PART #945	NO. 2 ENGINE - BEARING ASSEMBLY Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
72 3207-001 Engine 1 PART #406	NO. 1 ENGINE - INNER REAR BEARING Part Number BRR23643 Serial Number 1534	21-MAR-2010 H: 0.00					
72 3207-001 Engine 2 PART #981	NO. 2 ENGINE - INNER REAR BEARING Part Number BRR23643 Serial Number 1533	21-MAR-2010 H: 0.00					
72 3208-001 Engine 1 PART #2624	NO. 1 ENGINE - FRONT LPC BEARING Part Number BRR24148 Serial Number 1650	21-MAR-2010 H: 0.00					
72 3208-001 Engine 2 PART #2604	NO. 2 ENGINE - FRONT LPC BEARING Part Number BRR24148 Serial Number 1630	21-MAR-2010 H: 0.00					



ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 33-00-301 Engine 1 INSPECTION ENG 1-1000 #1723	NO. 1 ENGINE - LUBRICATION OF THE VARIABLE STATOR VANES (VSV) ACTUATING MECHANISM (PRE SB BR700-72-101414)	29-JAN-2018 H: 2586.20 C: 898	H: 1000.00			H: 4741.10	H: 285.30
	Notes NOTE: This task is recommended by the engine manufacturer (Manual Ref. T-710-2BR)						
72 33-00-301 Engine 2 INSPECTION ENG 2-1000 #2208	NO. 2 ENGINE - LUBRICATION OF THE VARIABLE STATOR VANES (VSV) ACTUATING MECHANISM (PRE SB BR700-72-101414)	29-JAN-2018 H: 2586.20 C: 898	H: 1000.00			H: 4741.10	H: 285.30
	Notes NOTE: This task is recommended by the engine manufacturer (Manual Ref. T-710-2BR)						
72 3301-001 Engine 1 PART #2235	NO. 1 ENGINE - HP COMPRESSOR ROTOR (STAGES 1 - 6) DISK Part Number Serial Number BRR24382 3089	21-MAR-2010 H: 0.00	C: 15000			C: 15000.00	C: 13505
72 3301-001 Engine 2 PART #2441	NO. 2 ENGINE - HP COMPRESSOR ROTOR (STAGES 1 - 6) DISK Part Number Serial Number BRR24382 3006	21-MAR-2010 H: 0.00	C: 15000			C: 15000.00	C: 13505
72 3302-001 Engine 1 PART #898	NO. 1 ENGINE - HP COMPRESSOR ROTOR (STAGES 7 - 10) DISK Part Number Serial Number BRR24357 3948	21-MAR-2010 H: 0.00	C: 15000			C: 15000.00	C: 13505
72 3302-001 Engine 2 PART #401	NO. 2 ENGINE - HP COMPRESSOR ROTOR (STAGES 7 - 10) DISK Part Number Serial Number BRR24357 3920	21-MAR-2010 H: 0.00	C: 15000			C: 15000.00	C: 13505
72 3303-001 Engine 1 PART #2009	NO. 1 ENGINE - ASSEMBLY OF HPC NOZZLE Part Number Serial Number FW32678 1372	21-MAR-2010 H: 0.00					
72 3303-001 Engine 2 PART #1932	NO. 2 ENGINE - ASSEMBLY OF HPC NOZZLE Part Number Serial Number FW32678 1382	21-MAR-2010 H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 34-01-201 Engine 1 INSPECTION #1977	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LP-COMPRESSOR CASE KEVLAR-WRAP	01-DEC-2018 H: 3011.20 C: 1025	H: 3000.00	H: 50.00		H: 6011.20	H: 1555.40
72 34-01-201 Engine 2 INSPECTION #2386	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LP-COMPRESSOR CASE KEVLAR-WRAP	01-DEC-2018 H: 3011.20 C: 1025	H: 3000.00	H: 50.00		H: 6011.20	H: 1555.40
72 38-01-201 Engine 1 INSPECTION ENG 1-2000 #2093	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE INTAKE ROTATING FAIRING	01-DEC-2018 H: 3011.20 C: 1025	H: 2000.00	H: 50.00		H: 5011.20	H: 555.40
72 38-01-201 Engine 2 INSPECTION ENG 2 - 2000 #754	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE INTAKE ROTATING FAIRING	01-DEC-2018 H: 3011.20 C: 1025	H: 2000.00	H: 50.00		H: 5011.20	H: 555.40
72 3801-001 Engine 1 PART #2500	NO. 1 ENGINE - NOSE CONE FAIRING Part Number BRR24368 Serial Number BA82283	21-MAR-2010 H: 0.00					
72 3801-001 Engine 2 PART #1643	NO. 2 ENGINE - NOSE CONE FAIRING Part Number BRR24368 Serial Number BA82280	21-MAR-2010 H: 0.00					
72 3802-001 Engine 1 PART #1335	NO. 1 ENGINE - NOSE CONE ASSEMBLY Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
72 3802-001 Engine 2 PART #2339	NO. 2 ENGINE - NOSE CONE ASSEMBLY Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
72 40-00-203 Engine 1 INSPECTION ENG 1-1000 #1423	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE COMBUSTION LINER	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30
	Notes NOTE: AFTER ENGINE SHOP VISIT FOR M41 RESTORATION (EMP WORK-PACKAGE LEVEL 2.5 OR LEVEL 3), THE FIRST INSPECTION IS AT 2000 ENG H AND REPEAT AT 1000 ENG H.						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 40-00-203 Engine 2 INSPECTION ENG 2-1000 #1416	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE COMBUSTION LINER	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30
<p>Notes</p> <p>NOTE: AFTER ENGINE SHOP VISIT FOR M41 RESTORATION (EMP WORK-PACKAGE LEVEL 2.5 OR LEVEL 3), THE FIRST INSPECTION IS AT 2000 ENG H AND REPEAT AT 1000 ENG H.</p>							
72 40-00-204 Engine 1 INSPECTION ENG 1-1000 #1134	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE HP TURBINES BLADES	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30
<p>Notes</p> <p>NOTE: AFTER ENGINE SHOP VISIT FOR M41 RESTORATION (EMP WORK-PACKAGE LEVEL 2.5 OR LEVEL 3), THE FIRST INSPECTION IS AT 2000 ENG H AND REPEAT AT 1000 ENG H.</p>							
72 40-00-204 Engine 2 INSPECTION ENG 2-1000 #2522	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE HP TURBINES BLADES	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30
<p>Notes</p> <p>NOTE: AFTER ENGINE SHOP VISIT FOR M41 RESTORATION (EMP WORK-PACKAGE LEVEL 2.5 OR LEVEL 3), THE FIRST INSPECTION IS AT 2000 ENG H AND REPEAT AT 1000 ENG H.</p>							
72 40-00-205 Engine 1 INSPECTION ENG 1-1000 #183	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE HP TURBINE STAGE-1 NOZZLE GUIDE-VANES	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30
<p>Notes</p> <p>NOTE: AFTER ENGINE SHOP VISIT FOR M41 RESTORATION (EMP WORK-PACKAGE LEVEL 2.5 OR LEVEL 3), THE FIRST INSPECTION IS AT 2000 ENG H AND REPEAT AT 1000 ENG H.</p>							
72 40-00-205 Engine 2 INSPECTION ENG 2-1000 #2993	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE HP TURBINE STAGE-1 NOZZLE GUIDE-VANES	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30
<p>Notes</p> <p>NOTE: AFTER ENGINE SHOP VISIT FOR M41 RESTORATION (EMP WORK-PACKAGE LEVEL 2.5 OR LEVEL 3), THE FIRST INSPECTION IS AT 2000 ENG H AND REPEAT AT 1000 ENG H.</p>							
72 4101-001 Engine 1 PART #2890	NO. 1 ENGINE - STAGE 4 AIR PIPE						
	Part Number	Serial Number					
	PN	SN- UNKNOWN					
			21-MAR-2010	H: 0.00			





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 4101-001 Engine 2 PART #740	NO. 2 ENGINE - STAGE 4 AIR PIPE Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
72 4101-002 Engine 1 PART #2158	NO. 1 ENGINE - STAGE 4 AIR PIPE. Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
72 4101-002 Engine 2 PART #1059	NO. 2 ENGINE - STAGE 4 AIR PIPE. Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
72 4101-003 Engine 1 PART #1771	NO. 1 ENGINE - STAGE 4 AIR PIPE.. Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
72 4101-003 Engine 2 PART #1089	NO. 2 ENGINE - STAGE 4 AIR PIPE.. Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
72 4101-004 Engine 1 PART #1570	NO. 1 ENGINE - STAGE 4 AIR PIPE... Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
72 4101-004 Engine 2 PART #947	NO. 2 ENGINE - STAGE 4 AIR PIPE... Part Number PN	Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00				
72 4101-010 Engine 1 PART #86	NO. 1 ENGINE - CURVIC RING Part Number BRR20340	Serial Number 7137	21-MAR-2010 H: 0.00	C: 15000		C: 15000.00	C: 13505
72 4101-010 Engine 2 PART #2649	NO. 2 ENGINE - CURVIC RING Part Number BRR20340	Serial Number 7217	21-MAR-2010 H: 0.00	C: 15000		C: 15000.00	C: 13505





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 4102-001 Engine 1 PART #738	NO. 1 ENGINE - HP TURBINE ROTOR STAGE 1 DISK Part Number: BRR23952 Serial Number: LDRQA04174	21-MAR-2010 H: 0.00	C: 6200			C: 6200.00	C: 4705
72 4102-001 Engine 2 PART #652	NO. 2 ENGINE - HP TURBINE ROTOR STAGE 1 DISK Part Number: BRR23952 Serial Number: LDRQA04179	21-MAR-2010 H: 0.00	C: 6200			C: 6200.00	C: 4705
72 4103-001 Engine 1 PART #1838	NO. 1 ENGINE - HP TURBINE ROTOR STAGE 2 DISK Part Number: BRR22008 Serial Number: LDRQA04064	21-MAR-2010 H: 0.00	C: 10500			C: 10500.00	C: 9005
72 4103-001 Engine 2 PART #1877	NO. 2 ENGINE - HP TURBINE ROTOR STAGE 2 DISK Part Number: BRR22008 Serial Number: LDRQA04061	21-MAR-2010 H: 0.00	C: 10500			C: 10500.00	C: 9005
72 4143-001 Engine 1 PART #1567	NO. 1 ENGINE - NO. 4 STUB SHAFT Part Number: BRR24545 Serial Number: 1116	21-MAR-2010 H: 0.00					
72 4143-001 Engine 2 PART #687	NO. 2 ENGINE - NO. 4 STUB SHAFT Part Number: BRR24545 Serial Number: 1125	21-MAR-2010 H: 0.00					
72 50-00-204 Engine 1 INSPECTION ENG1- 5000 #2461	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY SHUTDOWN SYSTEM	21-MAR-2010 H: 0.00	H: 5000.00	H: 50.00		H: 5000.00	H: 544.20
72 50-00-204 Engine 2 INSPECTION ENG 2- 5000 #2965	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY SHUTDOWN SYSTEM	21-MAR-2010 H: 0.00	H: 5000.00	H: 50.00		H: 5000.00	H: 544.20
72 50-00-205 Engine 1 INSPECTION ENG1- 5000 #4834	NO. 1 DETAILED INSPECTION OF THE EMERGENCY SHUTDOWN SYSTEM		H: 5000.00			H: 5000.00	H: 544.20
	Notes PHASE-IN: FIRST COMPLIANCE OF THIS TASK IS TO BE DONE IN CONJUNCTION WITH THE NEXT ACCOMPLISHMENT OF TASK 72-50-00-204.						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 50-00-205 Engine 2 INSPECTION ENG 2- 5000 #4856	NO. 2 DETAILED INSPECTION OF THE EMERGENCY SHUTDOWN SYSTEM		H: 5000.00			H: 5000.00	H: 544.20
	Notes PHASE-IN: FIRST COMPLIANCE OF THIS TASK IS TO BE DONE IN CONJUNCTION WITH THE NEXT ACCOMPLISHMENT OF TASK 72-50-00-204.						
72 5101-001 Engine 1 PART #2213	NO. 1 ENGINE - LP TURBINE ROTOR STAGE 1 DISK Part Number: BRR15535 Serial Number: 7096	21-MAR-2010 H: 0.00	C: 25000			C: 25000.00	C: 23505
72 5101-001 Engine 2 PART #610	NO. 2 ENGINE - LP TURBINE ROTOR STAGE 1 DISK Part Number: BRR15535 Serial Number: 7072	21-MAR-2010 H: 0.00	C: 25000			C: 25000.00	C: 23505
72 5101-002 Engine 1 PART #653	NO. 1 ENGINE - LP TURBINE ROTOR STAGE 2 DISK Part Number: BRR11896 Serial Number: 7054	21-MAR-2010 H: 0.00	C: 25000			C: 25000.00	C: 23505
72 5101-002 Engine 2 PART #1913	NO. 2 ENGINE - LP TURBINE ROTOR STAGE 2 DISK Part Number: BRR11896 Serial Number: 7082	21-MAR-2010 H: 0.00	C: 25000			C: 25000.00	C: 23505
72 5123-001 Engine 1 PART #1972	NO. 1 ENGINE - STUB SHAFT ASSEMBLY Part Number: BRR40703 Serial Number: 1520	21-MAR-2010 H: 0.00					
72 5123-001 Engine 2 PART #2095	NO. 2 ENGINE - STUB SHAFT ASSEMBLY Part Number: BRR40703 Serial Number: 1518	21-MAR-2010 H: 0.00					
72 5124-001 Engine 1 PART #697	NO. 1 ENGINE - LP TURBINE ROTOR SHAFT Part Number: BRR19612 Serial Number: RRDSFTSB AN1451	21-MAR-2010 H: 0.00	C: 25000			C: 25000.00	C: 23505
72 5124-001 Engine 2 PART #2026	NO. 2 ENGINE - LP TURBINE ROTOR SHAFT Part Number: BRR19612 Serial Number: RRDSFTSB AN1479	21-MAR-2010 H: 0.00	C: 25000			C: 25000.00	C: 23505



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 5613-001 Engine 1 PART #42	NO. 1 ENGINE - REAR MOUNT RING Part Number PN	21-MAR-2010 H: 0.00					
	Serial Number SN- UNKNOWN						
72 5613-001 Engine 2 PART #1842	NO. 2 ENGINE - REAR MOUNT RING Part Number PN	21-MAR-2010 H: 0.00					
	Serial Number SN- UNKNOWN						
72 6100-001 Engine 1 PART #1817	NO. 1 ENGINE - ACCESSORY GEARBOX Part Number 39600221	21-MAR-2010 H: 0.00					
	Serial Number 5235						
72 6100-001 Engine 2 PART #250	NO. 2 ENGINE - ACCESSORY GEARBOX Part Number 39600221	10-JUL-2013 H: 432.80 C: 211					
	Serial Number 5236						
72 6102-001 Engine 1 PART #975	NO. 1 ENGINE - GRAVITY OIL FILLER Part Number PN	21-MAR-2010 H: 0.00					
	Serial Number SN- UNKNOWN						
72 6102-001 Engine 2 PART #2982	NO. 2 ENGINE - GRAVITY OIL FILLER Part Number PN	21-MAR-2010 H: 0.00					
	Serial Number SN- UNKNOWN						
72 71-00-201 Engine 1 INSPECTION ENG 1-2000 #1039	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT	01-DEC-2018 H: 3011.20 C: 1025	H: 2000.00	H: 50.00		H: 5011.20	H: 555.40
72 71-00-201 Engine 2 INSPECTION ENG 2 - 2000 #1077	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT	01-DEC-2018 H: 3011.20 C: 1025	H: 2000.00	H: 50.00		H: 5011.20	H: 555.40
73 00-00-201 Engine 1 INSPECTION ENG 1-1000 #609	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL SYSTEM COMPONENTS	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
73 00-00-201 Engine 2 INSPECTION ENG 2-1000 #59	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL SYSTEM COMPONENTS	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30
73 11-01-000-801 Engine 1 PART #4861	NO. 1 ENG - REPLACE THE FUEL PUMP VESPEL COUPLING WITH A NEW PART (PN 39504900)		H: 3500.00			H: 4753.70	H: 297.90
	Notes 3500 FLIGHT HOURS (MAXIMUM) FOR THE FUEL PUMP VESPEL COUPLING						
73 11-01-000-801 Engine 2 PART #5149	NO. 2 ENG - REPLACE THE FUEL PUMP VESPEL COUPLING WITH A NEW PART (PN 39504900)		H: 3500.00			H: 4753.70	H: 297.90
	Notes 3500 FLIGHT HOURS (MAXIMUM) FOR THE FUEL PUMP VESPEL COUPLING						
73 11-01-000-801-1 Engine 1 PART #4860	NO. 1 ENG - REPLACE THE FUEL PUMP VESPEL COUPLING WITH A NEW PART (PN 39504901)		H: 5000.00			H: 5000.00	H: 544.20
	Notes 5000 FLIGHT HOURS (MAXIMUM) FOR THE FUEL PUMP VESPEL COUPLING						
73 11-01-000-801-1 Engine 2 PART #5148	NO. 2 ENG - REPLACE THE FUEL PUMP VESPEL COUPLING WITH A NEW PART (PN 39504901)		H: 5000.00			H: 5000.00	H: 544.20
	Notes 5000 FLIGHT HOURS (MAXIMUM) FOR THE FUEL PUMP VESPEL COUPLING						
73 1101-001 Engine 1 PART #1718	NO. 1 ENGINE - FUEL PUMP Part Number 828200-2 Serial Number 1954	21-MAR-2010 H: 0.00					
73 1101-001 Engine 2 PART #1591	NO. 2 ENGINE - FUEL PUMP Part Number 828200-2 Serial Number 1960	21-MAR-2010 H: 0.00					



ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
73 12-01-201 Engine 1 INSPECTION ENG 1-1000 #1296	NO. 1 ENGINE - DISCARD THE LP FUEL FILTER	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30
73 12-01-201 Engine 2 INSPECTION ENG 2-1000 #3013	NO. 2 ENGINE - DISCARD THE LP FUEL FILTER	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30
73 12-15-170-001 Engine 1 INSPECTION #4703	#1 ENGINE - CLEANING OF DRAINS EJECTOR FUEL FILTER	03-MAR-2016 H: 1753.70 C: 622					
73 12-15-170-001 Engine 2 INSPECTION #4704	#2 ENGINE - CLEANING OF DRAINS EJECTOR FUEL FILTER	03-MAR-2016 H: 1753.70 C: 622					
73 1201-001 Engine 1 PART #1687	NO. 1 ENGINE - TUBE ASSY Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
73 1201-001 Engine 2 PART #2701	NO. 2 ENGINE - TUBE ASSY Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					
73 1301-001 Engine 1 PART #2539	NO. 1 ENGINE - FUEL BURNER Part Number Serial Number 6940426E14 N31364	21-MAR-2010 H: 0.00					
73 1301-001 Engine 2 PART #1045	NO. 2 ENGINE - FUEL BURNER Part Number Serial Number 6940426E14 N33803	21-MAR-2010 H: 0.00					
73 1301-002 Engine 1 PART #1074	NO. 1 ENGINE - FUEL BURNER Part Number Serial Number 6940426E14 N31365	21-MAR-2010 H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
73 1301-002 Engine 2 PART #435	NO. 2 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N33804	21-MAR-2010 H: 0.00					
73 1301-003 Engine 1 PART #308	NO. 1 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N31366	21-MAR-2010 H: 0.00					
73 1301-003 Engine 2 PART #486	NO. 2 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N33805	21-MAR-2010 H: 0.00					
73 1301-004 Engine 1 PART #2635	NO. 1 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N31367	21-MAR-2010 H: 0.00					
73 1301-004 Engine 2 PART #47	NO. 2 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N33806	21-MAR-2010 H: 0.00					
73 1301-005 Engine 1 PART #877	NO. 1 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N31368	21-MAR-2010 H: 0.00					
73 1301-005 Engine 2 PART #388	NO. 2 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N33807	21-MAR-2010 H: 0.00					
73 1301-006 Engine 1 PART #2166	NO. 1 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N31369	21-MAR-2010 H: 0.00					
73 1301-006 Engine 2 PART #957	NO. 2 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N33808	21-MAR-2010 H: 0.00					
73 1301-007 Engine 1 PART #1796	NO. 1 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N31370	21-MAR-2010 H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
73 1301-007 Engine 2 PART #526	NO. 2 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N33809	21-MAR-2010 H: 0.00					
73 1301-008 Engine 1 PART #1656	NO. 1 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N31371	21-MAR-2010 H: 0.00					
73 1301-008 Engine 2 PART #413	NO. 2 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N33810	21-MAR-2010 H: 0.00					
73 1301-009 Engine 1 PART #2116	NO. 1 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N31372	21-MAR-2010 H: 0.00					
73 1301-009 Engine 2 PART #1522	NO. 2 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N33811	21-MAR-2010 H: 0.00					
73 1301-010 Engine 1 PART #1149	NO. 1 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N31373	21-MAR-2010 H: 0.00					
73 1301-010 Engine 2 PART #398	NO. 2 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N33812	21-MAR-2010 H: 0.00					
73 1301-011 Engine 1 PART #36	NO. 1 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N31374	21-MAR-2010 H: 0.00					
73 1301-011 Engine 2 PART #675	NO. 2 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N33813	21-MAR-2010 H: 0.00					
73 1301-012 Engine 1 PART #1715	NO. 1 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N31375	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
73 1301-012 Engine 2 PART #963	NO. 2 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N33814	21-MAR-2010 H: 0.00					
73 1301-013 Engine 1 PART #2498	NO. 1 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N31376	21-MAR-2010 H: 0.00					
73 1301-013 Engine 2 PART #424	NO. 2 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N33815	21-MAR-2010 H: 0.00					
73 1301-014 Engine 1 PART #475	NO. 1 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N31377	21-MAR-2010 H: 0.00					
73 1301-014 Engine 2 PART #681	NO. 2 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N33816	21-MAR-2010 H: 0.00					
73 1301-015 Engine 1 PART #1948	NO. 1 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N31378	21-MAR-2010 H: 0.00					
73 1301-015 Engine 2 PART #2104	NO. 2 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N33817	21-MAR-2010 H: 0.00					
73 1301-016 Engine 1 PART #3032	NO. 1 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N31379	21-MAR-2010 H: 0.00					
73 1301-016 Engine 2 PART #1387	NO. 2 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N33818	21-MAR-2010 H: 0.00					
73 1301-017 Engine 1 PART #2102	NO. 1 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N31380	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
73 1301-017 Engine 2 PART #2961	NO. 2 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N33819	21-MAR-2010 H: 0.00					
73 1301-018 Engine 1 PART #2002	NO. 1 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N31381	21-MAR-2010 H: 0.00					
73 1301-018 Engine 2 PART #344	NO. 2 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N33820	21-MAR-2010 H: 0.00					
73 1301-019 Engine 1 PART #1389	NO. 1 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N31382	21-MAR-2010 H: 0.00					
73 1301-019 Engine 2 PART #285	NO. 2 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N33821	21-MAR-2010 H: 0.00					
73 1301-020 Engine 1 PART #2058	NO. 1 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N31383	21-MAR-2010 H: 0.00					
73 1301-020 Engine 2 PART #2940	NO. 2 ENGINE - FUEL BURNER Part Number 6940426E14 Serial Number N33822	21-MAR-2010 H: 0.00					
73 1302-001 Engine 1 PART #2713	NO. 1 ENGINE - SPLITTER & OVERSPEED UNIT MANIFOLD Part Number 8910-214 Serial Number 8910-214	21-MAR-2010 H: 0.00					
73 1302-001 Engine 2 PART #1001	NO. 2 ENGINE - SPLITTER & OVERSPEED UNIT MANIFOLD Part Number 8910-214 Serial Number 16741281	21-MAR-2010 H: 0.00					
73 1303-001 Engine 1 PART #1236	NO. 1 ENGINE - FUEL RETURN TANK TRANSFERS VALVE Part Number 8910-312 Serial Number 16721088	21-MAR-2010 H: 0.00					

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
73 1303-001 Engine 2 PART #55	NO. 2 ENGINE - FUEL RETURN TANK TRANSFERS VALVE Part Number Serial Number 8910-312 16753951	21-MAR-2010 H: 0.00					
73 21-05-201 Airframe INSPECTION 120M #4753	DETAILED INSPECTION OF THE L/HIRF PROTECTION OF THE T20/P20 SENSORS CONNECTORS Reference Number AMM 73-21-05-220 -801	19-APR-2021 H: 3992.00 L: 1324	M: 120			19-APR-2031	M: 109 D: 3
73 2101-001 Engine 1 PART #758	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROLLER EEC Part Number Serial Number EECU1000-01AD BX960052	23-NOV-2016 H: 2064.80 C: 722					
73 2101-001 Engine 2 PART #231	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROLLER EEC Part Number Serial Number EECU1000-01AD BX960181	23-NOV-2016 H: 2064.80 C: 722					
73 2102-001 Engine 1 PART #876	NO. 1 ENGINE - FUEL UNIT METER Part Number Serial Number 8061-977 16764875	21-MAR-2010 H: 0.00					
73 2102-001 Engine 2 PART #194	NO. 2 ENGINE - FUEL UNIT METER Part Number Serial Number 8061-977 16766656	21-MAR-2010 H: 0.00					
73 2103-001 Engine 1 PART #1287	NO. 1 ENGINE - DEDICATED GENERATOR ROTOR Part Number Serial Number 83311-430242 N09390015	21-MAR-2010 H: 0.00					
73 2103-001 Engine 2 PART #1743	NO. 2 ENGINE - DEDICATED GENERATOR ROTOR Part Number Serial Number 83311-430242 N09480034	21-MAR-2010 H: 0.00					
73 2104-001 Engine 1 PART #1061	NO. 1 ENGINE - DEDICATED GENERATOR STATOR Part Number Serial Number 83311-430117 5485	21-MAR-2010 H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
73 2104-001 Engine 2 PART #54	NO. 2 ENGINE - DEDICATED GENERATOR STATOR Part Number: 83311-430117 Serial Number: N09460031	21-MAR-2010 H: 0.00					
73 2104-002 Engine 1 PART #1742	NO. 1 ENGINE - DATA ENTRY PLUG Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
73 2104-002 Engine 2 PART #1432	NO. 2 ENGINE - DATA ENTRY PLUG Part Number: PN Serial Number: SN-UNKNOWN	21-MAR-2010 H: 0.00					
73 2105-001 Engine 1 PART #19	NO. 1 ENGINE - T30 THERMOCOUPLE PROBE Part Number: TC428-01 Serial Number: RRAD2904	21-MAR-2010 H: 0.00					
73 2105-001 Engine 2 PART #2829	NO. 2 ENGINE - T30 THERMOCOUPLE PROBE Part Number: TC428-01 Serial Number: RRAD2889	21-MAR-2010 H: 0.00					
73 2105-002 Engine 1 PART #2608	NO. 1 ENGINE - T30 THERMOCOUPLE PROBE Part Number: TC428-01 Serial Number: RRAD2827	21-MAR-2010 H: 0.00					
73 2105-002 Engine 2 PART #1890	NO. 2 ENGINE - T30 THERMOCOUPLE PROBE Part Number: TC428-01 Serial Number: RRAD2883	21-MAR-2010 H: 0.00					
73 3101-001 Engine 1 PART #2639	NO. 1 ENGINE - FUEL FLOW TRANSMITTER Part Number: 9-217-49 Serial Number: 170436-724	21-MAR-2010 H: 0.00					
73 3101-001 Engine 2 PART #642	NO. 2 ENGINE - FUEL FLOW TRANSMITTER Part Number: 9-217-49 Serial Number: 170436-726	21-MAR-2010 H: 0.00					
73 3303-001 Engine 1 PART #1999	NO. 1 ENGINE - FUEL LOW PRESSURE SWITCH Part Number: 21SN04-433 Serial Number: K050107	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
73 3303-001 Engine 2 PART #202	NO. 2 ENGINE - FUEL LOW PRESSURE SWITCH Part Number 21SN04-433 Serial Number K045536	21-MAR-2010 H: 0.00					
73 3401-001 Engine 1 PART #2516	NO. 1 ENGINE - FUEL FILTER DIFFERENTIAL PRESS SWITCH Part Number 21SN04-430 Serial Number K050490	21-MAR-2010 H: 0.00					
73 3401-001 Engine 2 PART #1431	NO. 2 ENGINE - FUEL FILTER DIFFERENTIAL PRESS SWITCH Part Number 21SN04-430 Serial Number K044714	21-MAR-2010 H: 0.00					
74 1001-001 Engine 1 PART #1084	NO. 1 ENGINE - EXCITER UNIT IGNITION Part Number 9060440-2 Serial Number J09400296	21-MAR-2010 H: 0.00					
74 1001-001 Engine 2 PART #512	NO. 2 ENGINE - IGNITION EXITER BOX #1 Part Number 9060440-2 Serial Number 06444514	14-JUL-2021 H: 4138.20 C: 1382					
74 1001-002 Engine 1 PART #1589	NO. 1 ENGINE - EXCITER UNIT IGNITION Part Number 9060440-2 Serial Number J09400297	21-MAR-2010 H: 0.00					
74 1001-002 Engine 2 PART #1647	NO. 2 ENGINE - EXCITER UNIT IGNITION Part Number 9060440-2 Serial Number J09450798	21-MAR-2010 H: 0.00					
74 2001-001 Engine 1 PART #1716	NO. 1 ENGINE - IGNITOR PLUG, INBOARD #1 Part Number CH34760-2 Serial Number NSN	16-APR-2021 H: 3992.00 C: 1324					
74 2001-001 Engine 2 PART #1337	NO. 2 ENGINE - IGNITOR PLUG, INBOARD #1 Part Number CH34760-2 Serial Number NSN	14-JUL-2021 H: 4138.20 C: 1382					
74 2001-002 Engine 1 PART #1196	NO. 1 ENGINE - IGNITOR PLUG, OUTBOARD #2 Part Number CH34760-2 Serial Number NSN	16-APR-2021 H: 3992.00 C: 1324					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
74 2001-002 Engine 2 PART #1746	NO. 2 ENGINE - IGNITOR PLUG, OUTBOARD #2 Part Number: CH34760-2 Serial Number: NSN	16-APR-2021 H: 3992.00 C: 1324					
74 30-01-201 Engine 1 INSPECTION 500H #1233	NO. 1 ENGINE - OPERATIONAL TEST OF THE IGNITION SWITCH Notes IT SHOULD BE COMPLETED WITHIN THE NEW TASK REPEAT INTERVAL OR 6 MONTHS FROM THE DATE OF INTRODUCTION TO THE MAINTENANCE PROGRAM BY THE OPERATOR WHICHEVER IS GREATER, THE EXCEPTION IS IF THIS RESCHEDULING WAS TO POSTPONE THE TASK BEYOND THE PRE-REVISION TASK ACCOMPLISHMENT DEADLINE.	10-MAR-2022 H: 4455.80 C: 1495	H: 500.00	H: 50.00		H: 4955.80	H: 500.00
74 30-01-201 Engine 2 INSPECTION 500H #311	NO. 2 ENGINE - OPERATIONAL TEST OF THE IGNITION SWITCH Notes IT SHOULD BE COMPLETED WITHIN THE NEW TASK REPEAT INTERVAL OR 6 MONTHS FROM THE DATE OF INTRODUCTION TO THE MAINTENANCE PROGRAM BY THE OPERATOR WHICHEVER IS GREATER, THE EXCEPTION IS IF THIS RESCHEDULING WAS TO POSTPONE THE TASK BEYOND THE PRE-REVISION TASK ACCOMPLISHMENT DEADLINE.	10-MAR-2022 H: 4455.80 C: 1495	H: 500.00	M: 3 H: 50.00		H: 4955.80	H: 500.00
74 74-2001-002 Airframe PART #5125	L/H O/B IGNITER LEAD Part Number: 83311-430973-10 Serial Number: S19130238	16-APR-2021 H: 3992.00 L: 1324					
75 2201-001 Engine 1 PART #216	NO. 1 ENGINE - AIR BUFFER VALVE Part Number: 8910-512 Serial Number: 16736614	21-MAR-2010 H: 0.00					
75 2201-001 Engine 2 PART #878	NO. 2 ENGINE - AIR BUFFER VALVE Part Number: 8910-512 Serial Number: 16736618	21-MAR-2010 H: 0.00					
75 3101-001 Engine 1 PART #131	NO. 1 ENGINE - HPC BLEED HANDLING VALVE Part Number: EB100420D Serial Number: HNB330	21-MAR-2010 H: 0.00					
75 3101-001 Engine 2 PART #433	NO. 2 ENGINE - HPC BLEED HANDLING VALVE Part Number: EB100420D Serial Number: HNA119	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
75 3101-002 Engine 1 PART #58	NO. 1 ENGINE - HPC BLEED HANDLING VALVE Part Number Serial Number EB100420D HNB331	21-MAR-2010 H: 0.00					
75 3101-002 Engine 2 PART #1685	NO. 2 ENGINE - HPC BLEED HANDLING VALVE Part Number Serial Number EB100420D HNA120	21-MAR-2010 H: 0.00					
75 3101-003 Engine 1 PART #2457	NO. 1 ENGINE - HPC BLEED HANDLING VALVE Part Number Serial Number EB100420D HNB332	21-MAR-2010 H: 0.00					
75 3101-003 Engine 2 PART #602	NO. 2 ENGINE - HPC BLEED HANDLING VALVE Part Number Serial Number EB100420D HNA121	21-MAR-2010 H: 0.00					
75 3101-004 Engine 1 PART #2274	NO. 1 ENGINE - HPC BLEED HANDLING VALVE Part Number Serial Number EB100420D HNB333	21-MAR-2010 H: 0.00					
75 3101-004 Engine 2 PART #829	NO. 2 ENGINE - HPC BLEED HANDLING VALVE Part Number Serial Number EB100420D HNA122	21-MAR-2010 H: 0.00					
75 3102-001 Engine 1 PART #2908	NO. 1 ENGINE - BLEED SOLENOID BLOCK VALVE Part Number Serial Number EA100118G HNB296	21-MAR-2010 H: 0.00					
75 3102-001 Engine 2 PART #178	NO. 2 ENGINE - BLEED SOLENOID BLOCK VALVE Part Number Serial Number EA100118G HNA275	21-MAR-2010 H: 0.00					
75 3103-001 Engine 1 PART #1971	NO. 1 ENGINE - VANE STATOR VARIABLE ACTUATOR Part Number Serial Number 8100-115 16739992	21-MAR-2010 H: 0.00					
75 3103-001 Engine 2 PART #691	NO. 2 ENGINE - VANE STATOR VARIABLE ACTUATOR Part Number Serial Number 8100-115 16730884	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
76 1001-001 Airframe PART #2175	THROTTLE QUADRANT Part Number GH562-3001-5	Serial Number E0065	01-DEC-2014 H: 1111.80 L: 414				
77 1201-001 Engine 1 PART #995	NO. 1 ENGINE - N2 SHAFT SPEED PROBE Part Number 889-3-13	Serial Number 11996	21-MAR-2010 H: 0.00				
77 1201-001 Engine 2 PART #1516	NO. 2 ENGINE - N2 SHAFT SPEED PROBE Part Number 889-3-13	Serial Number 11972	21-MAR-2010 H: 0.00				
77 1201-002 Engine 1 PART #1839	NO. 1 ENGINE - N2 SHAFT SPEED PROBE Part Number 889-3-13	Serial Number 11997	21-MAR-2010 H: 0.00				
77 1201-002 Engine 2 PART #1430	NO. 2 ENGINE - N2 SHAFT SPEED PROBE Part Number 889-3-13	Serial Number 11973	21-MAR-2010 H: 0.00				
77 1201-003 Engine 1 PART #2817	NO. 1 ENGINE - N2 SHAFT SPEED PROBE Part Number 889-3-13	Serial Number 11998	21-MAR-2010 H: 0.00				
77 1201-003 Engine 2 PART #2627	NO. 2 ENGINE - N2 SHAFT SPEED PROBE Part Number 889-3-13	Serial Number 11974	21-MAR-2010 H: 0.00				
77 1201-004 Engine 1 PART #509	NO. 1 ENGINE - N2 SHAFT SPEED PROBE Part Number 889-3-13	Serial Number 11999	21-MAR-2010 H: 0.00				
77 1201-004 Engine 2 PART #2816	NO. 2 ENGINE - N2 SHAFT SPEED PROBE Part Number 889-3-13	Serial Number 11975	21-MAR-2010 H: 0.00				
77 2101-001 Engine 1 PART #373	NO. 1 ENGINE - NO. 1 THERMOCOUPLE PROBE Part Number TC429-01	Serial Number RRAE06090	21-MAR-2010 H: 0.00				





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
77 2101-001 Engine 2 PART #516	NO. 2 ENGINE - NO. 1 THERMOCOUPLE PROBE Part Number Serial Number TC429-01 RRAE06089	21-MAR-2010 H: 0.00					
77 2101-002 Engine 1 PART #375	NO. 1 ENGINE - NO. 2 THERMOCOUPLE PROBE Part Number Serial Number TC429-01 RRAE06093	21-MAR-2010 H: 0.00					
77 2101-002 Engine 2 PART #2564	NO. 2 ENGINE - NO. 2 THERMOCOUPLE PROBE Part Number Serial Number TC429-01 RRAE06101	21-MAR-2010 H: 0.00					
77 2101-003 Engine 1 PART #253	NO. 1 ENGINE - NO. 3 THERMOCOUPLE PROBE Part Number Serial Number TC429-01 RRAE06095	21-MAR-2010 H: 0.00					
77 2101-003 Engine 2 PART #1991	NO. 2 ENGINE - NO. 3 THERMOCOUPLE PROBE Part Number Serial Number TC429-01 RRAE06103	21-MAR-2010 H: 0.00					
77 2101-004 Engine 1 PART #2882	NO. 1 ENGINE - NO. 4 THERMOCOUPLE PROBE Part Number Serial Number TC429-01 RRAE06097	21-MAR-2010 H: 0.00					
77 2101-004 Engine 2 PART #2364	NO. 2 ENGINE - NO. 4 THERMOCOUPLE PROBE Part Number Serial Number TC429-01 RRAE06104	21-MAR-2010 H: 0.00					
77 2101-005 Engine 1 PART #1732	NO. 1 ENGINE - NO. 5 THERMOCOUPLE PROBE Part Number Serial Number TC429-01 RRAE06098	21-MAR-2010 H: 0.00					
77 2101-005 Engine 2 PART #2141	NO. 2 ENGINE - NO. 5 THERMOCOUPLE PROBE Part Number Serial Number TC429-01 RRAE06106	21-MAR-2010 H: 0.00					
77 2101-006 Engine 1 PART #1191	NO. 1 ENGINE - NO. 6 THERMOCOUPLE PROBE Part Number Serial Number TC429-01 RRAE06100	21-MAR-2010 H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
77 2101-006 Engine 2 PART #1571	NO. 2 ENGINE - NO. 6 THERMOCOUPLE PROBE Part Number Serial Number TC429-01 RRAE06107	21-MAR-2010 H: 0.00					
77 2101-007 Engine 1 PART #1568	NO. 1 ENGINE - NO. 7 THERMOCOUPLE PROBE Part Number Serial Number TC429-01 RRAE06102	21-MAR-2010 H: 0.00					
77 2101-007 Engine 2 PART #76	NO. 2 ENGINE - NO. 7 THERMOCOUPLE PROBE Part Number Serial Number TC429-01 RRAE06109	21-MAR-2010 H: 0.00					
77 2201-001 Engine 1 PART #1312	NO. 1 ENGINE - TURBINE DISC OVERHEAT THERMOCOUPLE Part Number Serial Number 920-4-14 3754	21-MAR-2010 H: 0.00					
77 2201-001 Engine 2 PART #2005	NO. 2 ENGINE - TURBINE DISC OVERHEAT THERMOCOUPLE Part Number Serial Number 920-4-14 3294	21-MAR-2010 H: 0.00					
77 2201-002 Engine 1 PART #494	NO. 1 ENGINE - TURBINE DISC OVERHEAT THERMOCOUPLE Part Number Serial Number 920-4-14 3755	21-MAR-2010 H: 0.00					
77 2201-002 Engine 2 PART #122	NO. 2 ENGINE - TURBINE DISC OVERHEAT THERMOCOUPLE Part Number Serial Number 920-4-14 3295	21-MAR-2010 H: 0.00					
77 3104-001 Airframe PART #2078	EVMU ENGINE VIBRATION MONITORING UNIT Part Number Serial Number GB544-1001-1 AD24041	21-MAR-2010 H: 0.00					
78 0000-001 Airframe PART #8	THRUST REVERSER BOX Part Number Serial Number PN SN- UNKNOWN	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining		
78 10-01-201 Engine 1 INSPECTION ENG 1-1000 #4844	NO. 1 ENGINE GENERAL VISUAL INSPECTION OF THE EXHAUST NOZZLE	31-MAR-2020 H: 3741.10 L: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30		
78 10-01-201 Engine 2 INSPECTION ENG 2-1000 #4866	NO. 2 ENGINE GENERAL VISUAL INSPECTION OF THE EXHAUST NOZZLE		H: 1000.00	H: 50.00		H: 4741.10	H: 285.30		
78 10-02-201 Engine 1 INSPECTION ENG 1-1000 #4845	NO. 1 ENGINE GENERAL VISUAL INSPECTION OF THE EXHAUST CONE	31-MAR-2020 H: 3741.10 L: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30		
78 10-02-201 Engine 2 INSPECTION ENG 2-1000 #4867	NO. 2 ENGINE GENERAL VISUAL INSPECTION OF THE EXHAUST CONE		H: 1000.00	H: 50.00		H: 4741.10	H: 285.30		
78 30-00-201 Airframe INSPECTION 3000H #1320	GENERAL VISUAL INSPECTION OF THE THRUST-REVERSER THERMAL BLANKET	31-MAR-2020 H: 3741.10 L: 1233	H: 3000.00	H: 50.00		H: 6741.10	H: 2285.30		
78 30-00-204 Airframe INSPECTION 4500H #3011	FUNCTIONAL TEST OF THE THRUST REVERSER								
		Work Order Number	Scheduled	Man Hours					
		FLL BAS 9385	19-Mar-2022	0.00	21-MAR-2010 H: 0.00	H: 4500.00	H: 50.00	H: 4500.00	H: 44.20
78 30-00-205 Airframe INSPECTION 30M #2676	GENERAL VISUAL INSPECTION OF THE THRUST REVERSER P-SEALS AND SEAL DEPRESSORS/SUPPORT		M: 30	M: 3		19-OCT-2023	M: 19 D: 3		
78 30-00-206 Airframe INSPECTION 120M #4754	DETAILED INSPECTION OF THE L/HIRF PROTECTION OF THE THRUST REVERSERS ELECTRICAL CONNECTORS		M: 120			19-APR-2031	M: 109 D: 3		
	Reference Number								
	AMM 78-30-00-220-801								
78 31-01-101 Airframe INSPECTION #1987	DETAILED INSPECTION OF THE THRUST REVERSER UPPER DOOR	21-MAR-2010 H: 0.00	L: 7500			L: 7500	L: 6005		



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
78 31-01-201 Airframe INSPECTION 120M #2926	DETAILED INSPECTION OF THE UPPER PIVOTING DOORS (METALLIC)	19-APR-2021 H: 3992.00 L: 1324	M: 120	M: 3		19-APR-2031	M: 109 D: 3
78 31-01-202 Airframe INSPECTION #1361	SPECIAL DETAILED INSPECTION OF THE UPPER PIVOTING DOORS (COMPOSITE)	21-MAR-2010 H: 0.00	L: 1875	L: 50		L: 1875	L: 380
78 3103-001 Airframe PART #1104	UPPER LEFT THRUST REVERSER DOOR Part Number 04G2037-003 Serial Number UL1518	21-MAR-2010 H: 0.00					
78 3103-002 Airframe PART #1283	LOWER LEFT THRUST REVERSER DOOR Part Number 07G2039-001 Serial Number LL1330	21-MAR-2010 H: 0.00					
78 3200-001 Airframe PART #1862	LEFT THRUST REVERSER Part Number 07G0001-013 Serial Number 789	21-MAR-2010 H: 0.00					
78 3200-002 Airframe PART #510	RIGHT THRUST REVERSER Part Number 07G0001-015 Serial Number 778	21-MAR-2010 H: 0.00					
78 3203-001 Airframe PART #1010	UPPER RIGHT THRUST REVERSER DOOR Part Number 04G2037-004 Serial Number UR1576	21-MAR-2010 H: 0.00					
78 3203-002 Airframe PART #2182	LOWER RIGHT THRUST REVERSER DOOR Part Number 07G2039-002 Serial Number LR1350	21-MAR-2010 H: 0.00					
78 33-03-201 Airframe INSPECTION 60M #5067	DETAILED INSPECTION OF THE THRUST REVERSER UNIT (TRU) PRIMARY-DOOR ACTUATOR-ROD END	19-APR-2021 H: 3992.00 L: 1324	M: 60	M: 3		19-APR-2026	M: 49 D: 3





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
78 33-05-101 Airframe INSPECTION 4500H #353	OPERATIONAL TEST OF THE TERTIARY LOCK Work Order Number FLL BAS 9385 Scheduled 19-Mar-2022 Man Hours 0.00	21-MAR-2010 H: 0.00	H: 4500.00	H: 50.00		H: 4500.00	H: 44.20
78 33-05-201 Airframe INSPECTION 3000H #2692	GENERAL VISUAL INSPECTION OF THE TERTIARY LOCK HOOK	31-MAR-2020 H: 3741.10 L: 1233	H: 3000.00	H: 50.00		H: 6741.10	H: 2285.30
78 33-05-203 Airframe INSPECTION 3000H #5068	GENERAL VISUAL INSPECTION OF THE PIVOTING DOOR KEEPER BAR		H: 3000.00			H: 6011.20	H: 1555.40
78 3301-001 Airframe PART #239	LH ISOLATION THRUST REVERSER VALVE Part Number P472A0001-02 Serial Number A0072106	21-MAR-2010 H: 0.00					
78 3301-002 Airframe PART #515	RH ISOLATION THRUST REVERSER VALVE Part Number P472A0001-02 Serial Number A0072108	21-MAR-2010 H: 0.00					
78 3302-001 Airframe PART #2319	LH DIRECTIONAL CONTROL UNIT DCU Part Number P473A0001-01 Serial Number A0071911	21-MAR-2010 H: 0.00					
78 3302-002 Airframe PART #543	RH DIRECTIONAL CONTROL UNIT DCU Part Number P473A0001-01 Serial Number A0063077	21-MAR-2010 H: 0.00					
78 3303-001 Airframe PART #408	LEFT UPPER THRUST REVERSER DOOR ACTUATOR Part Number P471A0001-01 Serial Number A0072173	21-MAR-2010 H: 0.00					
78 3303-002 Airframe PART #2483	LEFT LOWER THRUST REVERSER DOOR ACTUATOR Part Number P471A0001-01 Serial Number A0072174	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
78 3303-003 Airframe PART #1662	RIGHT UPPER THRUST REVERSER DOOR ACTUATOR Part Number P471A0001-01 Serial Number A0066633	21-MAR-2010 H: 0.00					
78 3303-004 Airframe PART #1388	RIGHT LOWER THRUST REVERSER DOOR ACTUATOR Part Number P471A0001-01 Serial Number A0062737	21-MAR-2010 H: 0.00					
78 3304-001 Airframe PART #709	LOB PRIMARY LOCK ACTUATOR Part Number P466A0001-02 Serial Number A0073089	21-MAR-2010 H: 0.00					
78 3304-002 Airframe PART #2989	LIB PRIMARY LOCK ACTUATOR Part Number P466A0001-02 Serial Number A0073088	21-MAR-2010 H: 0.00					
78 3304-003 Airframe PART #44	RIB PRIMARY LOCK ACTUATOR Part Number P466A0001-02 Serial Number A0061429	21-MAR-2010 H: 0.00					
78 3304-004 Airframe PART #267	ROB PRIMARY LOCK ACTUATOR Part Number P466A0001-02 Serial Number A0064113	21-MAR-2010 H: 0.00					
78 3305-001 Airframe PART #1783	LEFT UPPER T/R TERTIARY LOCK Part Number P516A0001-00 Serial Number DAW3305-08	21-MAR-2010 H: 0.00					
78 3305-002 Airframe PART #589	LEFT LOWER T/R TERTIARY LOCK Part Number P516A0001-00 Serial Number DAW3197-08	21-MAR-2010 H: 0.00					
78 3305-003 Airframe PART #95	RIGHT UPPER T/R TERTIARY LOCK Part Number P516A0001-00 Serial Number DAW3562-09	21-MAR-2010 H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
78 3305-004 Airframe PART #897	RIGHT LOWER T/R TERTIARY LOCK Part Number P516A0001-00 Serial Number DAW3405-08	21-MAR-2010 H: 0.00					
78 3400-001 Airframe PART #1119	NO. 1 DOOR POSITION (LDVT) TRANSMITTER Part Number 133F025-005 Serial Number A102249	21-MAR-2010 H: 0.00					
78 3400-002 Airframe PART #1246	NO. 2 DOOR POSITION (LDVT) TRANSMITTER Part Number 133F025-005 Serial Number A102247	21-MAR-2010 H: 0.00					
78 3400-003 Airframe PART #611	NO. 3 DOOR POSITION (LDVT) TRANSMITTER Part Number 133F025-005 Serial Number A102113	21-MAR-2010 H: 0.00					
78 3400-004 Airframe PART #1264	NO. 4 DOOR POSITION (LDVT) TRANSMITTER Part Number 133F025-005 Serial Number A02100	21-MAR-2010 H: 0.00					
78 3401-001 Airframe PART #1241	LEFT UPPER INBOARD STOW SWITCH Part Number T7013-2 Serial Number 1300	21-MAR-2010 H: 0.00					
78 3401-002 Airframe PART #1985	LEFT UPPER OUTBOARD STOW SWITCH Part Number T7013-2 Serial Number 1326	21-MAR-2010 H: 0.00					
78 3401-003 Airframe PART #881	LEFT LOWER OUTBOARD STOW SWITCH Part Number T7013-2 Serial Number 1320	21-MAR-2010 H: 0.00					
78 3401-004 Airframe PART #2757	LEFT LOWER INBOARD STOW SWITCH Part Number T7013-2 Serial Number 1372	21-MAR-2010 H: 0.00					
78 3401-005 Airframe PART #727	RIGHT UPPER INBOARD STOW SWITCH Part Number T7013-2 Serial Number 1108	21-MAR-2010 H: 0.00					



Maintenance Items

Copyright © 2022 Flightdocs, Inc. All Rights Reserved

Page 325 of 653



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
78 3401-006 Airframe PART #1895	RIGHT UPPER OUTBOARD STOW SWITCH Part Number T7013-2 Serial Number 1110	21-MAR-2010 H: 0.00					
78 3401-007 Airframe PART #2944	RIGHT LOWER OUTBOARD STOW SWITCH Part Number T7013-2 Serial Number 1097	21-MAR-2010 H: 0.00					
78 3401-008 Airframe PART #125	RIGHT LOWER INBOARD STOW SWITCH Part Number T7013-2 Serial Number 1137	21-MAR-2010 H: 0.00					
78 ZL-00-201 Airframe INSPECTION 1800 L #1738	GENERAL VISUAL INSPECTION OF THE THRUST REVERSER - LH	10-MAR-2022 H: 4455.80 L: 1495	L: 1800	L: 50		L: 3295	L: 1800
78 ZL-00-202 Airframe INSPECTION 1800 L #874	GENERAL VISUAL INSPECTION OF THE THRUST REVERSER - RH	10-MAR-2022 H: 4455.80 L: 1495	L: 1800	L: 50		L: 3295	L: 1800
79 11-00-201 Engine 1 INSPECTION ENG 1-2000 #1843	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL TANK	01-DEC-2018 H: 3011.20 C: 1025	H: 2000.00	H: 50.00		H: 5011.20	H: 555.40
79 11-00-201 Engine 2 INSPECTION ENG 2 - 2000 #1680	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL TANK	01-DEC-2018 H: 3011.20 C: 1025	H: 2000.00	H: 50.00		H: 5011.20	H: 555.40
79 11-00-202 Engine 1 INSPECTION #781	NO. 1 ENGINE - FUNCTIONAL TEST OF THE ENGINE OIL TANK	04-MAR-2016 H: 1753.70 C: 622	H: 3000.00	H: 50.00		H: 4753.70	H: 297.90
79 11-00-202 Engine 2 INSPECTION #2360	NO. 2 ENGINE - FUNCTIONAL TEST OF THE ENGINE OIL TANK	04-MAR-2016 H: 1753.70 C: 622	H: 3000.00	H: 50.00		H: 4753.70	H: 297.90





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
79 11-00-204 Engine 1 INSPECTION 750H/30M #693	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL TANK (POST SB BR700-72-100455)	08-FEB-2022 H: 4399.80 C: 1478	H: 750.00	H: 50.00		H: 5149.80	H: 694.00
79 11-00-204 Engine 2 INSPECTION 750H/30M #2289	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL TANK (POST SB BR700-72-100455)	08-FEB-2022 H: 4399.80 C: 1478	H: 750.00	H: 50.00		H: 5149.80	H: 694.00
79 1201-001 Airframe PART #2936	OIL REPLENISHMENT TANK ASSY Part Number GC639-0011-3 Serial Number 432	21-MAR-2010 H: 0.00					
79 1203-001 Airframe PART #1190	OIL REPLENISHMENT PUMP Part Number GC639-0013-1 Serial Number 3BM8	10-JAN-2016 H: 1711.50 L: 606					
79 1204-001 Airframe PART #1947	SELECTOR VALVE Part Number V100000-250 Serial Number 945	24-APR-2015 H: 1397.60 L: 497					
79 1210-701 Engine 1 PART #3643	NO. 1 ENGINE - OIL FILLER ASSEMBLY Part Number 39504403 Serial Number SN- UNKNOWN	H: 0.00					
79 1210-701 Engine 2 PART #1350	NO. 2 ENGINE - OIL FILLER ASSEMBLY Part Number 39504403 Serial Number 1516	08-DEC-2015 H: 1644.60 C: 585					
79 21-02-201 Engine 1 INSPECTION ENG 1-1000 #1921	NO. 1 ENGINE - DISCARD THE PRESSURE FILTER ELEMENT	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30
79 21-02-201 Engine 2 INSPECTION ENG 2-1000 #1009	NO. 2 ENGINE - DISCARD THE PRESSURE FILTER ELEMENT	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
79 21-04-201 Engine 1 INSPECTION ENG 1-1000 #1286	NO. 1 ENGINE - DETAILED INSPECTION OF THE FRONT-BEARING-CHAMBER MAGNETIC CHIP-DETECTOR	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30
79 21-04-201 Engine 2 INSPECTION ENG 2-1000 #6	NO. 2 ENGINE - DETAILED INSPECTION OF THE FRONT-BEARING-CHAMBER MAGNETIC CHIP-DETECTOR	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30
79 21-04-202 Engine 1 INSPECTION ENG 1-1000 #1867	NO. 1 ENGINE - DETAILED INSPECTION OF THE REAR-BEARING-CHAMBER MAGNETIC CHIP-DETECTOR	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30
79 21-04-202 Engine 2 INSPECTION ENG 2-1000 #578	NO. 2 ENGINE - DETAILED INSPECTION OF THE REAR-BEARING-CHAMBER MAGNETIC CHIP-DETECTOR	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30
79 21-04-203 Engine 1 INSPECTION ENG 1-1000 #2706	NO. 1 ENGINE - DETAILED INSPECTION OF THE ACCESSORY-GEARBOX MAGNETIC CHIP-DETECTOR	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30
79 21-04-203 Engine 2 INSPECTION ENG 2-1000 #2557	NO. 2 ENGINE - DETAILED INSPECTION OF THE ACCESSORY-GEARBOX MAGNETIC CHIP-DETECTOR	31-MAR-2020 H: 3741.10 C: 1233	H: 1000.00	H: 50.00		H: 4741.10	H: 285.30
79 2101-001 Engine 1 PART #1983	NO. 1 ENGINE - OIL UNIT PUMP Part Number LR47000C Serial Number C0843	21-MAR-2010 H: 0.00					
79 2101-001 Engine 2 PART #2142	NO. 2 ENGINE - OIL UNIT PUMP Part Number LR47000C Serial Number B1201	21-MAR-2010 H: 0.00					
79 2102-001 Engine 1 PART #1922	NO. 1 ENGINE - OIL FILTER ELEMENT Part Number PN Serial Number SN-UNKNOWN	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
79 2102-001 Engine 2 PART #1124	NO. 2 ENGINE - OIL FILTER ELEMENT Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
79 2201-001 Engine 1 PART #625	NO. 1 ENGINE - FUEL/OIL TEMP TRANSDUCER Part Number 1122806 Serial Number V4441	21-MAR-2010 H: 0.00					
79 2201-001 Engine 2 PART #2781	NO. 2 ENGINE - FUEL/OIL TEMP TRANSDUCER Part Number 1122806 Serial Number V3098	21-MAR-2010 H: 0.00					
79 2201-002 Engine 1 PART #964	NO. 1 ENGINE - FUEL/OIL TEMP TRANSDUCER Part Number 1122806 Serial Number V4448	21-MAR-2010 H: 0.00					
79 2201-002 Engine 2 PART #2326	NO. 2 ENGINE - FUEL/OIL TEMP TRANSDUCER Part Number 1122806 Serial Number V4339	21-MAR-2010 H: 0.00					
79 2201-003 Engine 1 PART #1919	NO. 1 ENGINE - FUEL/OIL TEMP TRANSDUCER Part Number 1122806 Serial Number V4342	21-MAR-2010 H: 0.00					
79 2201-003 Engine 2 PART #2653	NO. 2 ENGINE - FUEL/OIL TEMP TRANSDUCER Part Number 1122806 Serial Number V3103	21-MAR-2010 H: 0.00					
79 2201-004 Engine 1 PART #221	NO. 1 ENGINE - FUEL/OIL TEMP TRANSDUCER Part Number 1122806 Serial Number V4442	21-MAR-2010 H: 0.00					
79 2201-004 Engine 2 PART #3024	NO. 2 ENGINE - FUEL/OIL TEMP TRANSDUCER Part Number 1122806 Serial Number V4371	21-MAR-2010 H: 0.00					
79 2201-005 Engine 1 PART #2302	NO. 1 ENGINE - FUEL/OIL TEMP TRANSDUCER Part Number 1122806 Serial Number V5134	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
79 2201-005 Engine 2 PART #31	NO. 2 ENGINE - FUEL/OIL TEMP TRANSDUCER Part Number 1122806 Serial Number V5132	21-MAR-2010 H: 0.00					
79 2202-001 Engine 1 PART #1499	NO. 1 ENGINE - OIL, FUEL COOLED COOLER Part Number 55007001-41 Serial Number 55007-1455	21-MAR-2010 H: 0.00					
79 2202-001 Engine 2 PART #1654	NO. 2 ENGINE - OIL, FUEL COOLED COOLER Part Number 55007001-41 Serial Number 55007-1460	21-MAR-2010 H: 0.00					
79 3102-001 Airframe PART #1614	OIL PROBE Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
79 3301-001 Engine 1 PART #2196	NO. 1 ENGINE - OIL DIFFERENTIAL PRESSURE TRANSDUCER Part Number PDCR300164001M1 Serial Number 3046357	21-MAR-2010 H: 0.00					
79 3301-001 Engine 2 PART #2400	NO. 2 ENGINE - OIL DIFFERENTIAL PRESSURE TRANSDUCER Part Number PDCR300164001M1 Serial Number 3046359	21-MAR-2010 H: 0.00					
79 3301-002 Engine 1 PART #2458	NO. 1 ENGINE - OIL DIFFERENTIAL PRESSURE TRANSDUCER Part Number PDCR300164001M1 Serial Number 3037728	21-MAR-2010 H: 0.00					
79 3301-002 Engine 2 PART #3027	NO. 2 ENGINE - OIL DIFFERENTIAL PRESSURE TRANSDUCER Part Number PDCR300164001M1 Serial Number 3046362	21-MAR-2010 H: 0.00					
79 3401-001 Engine 1 PART #1664	NO. 1 ENGINE - OIL FILTER DIFFERENTIAL PRESS SWITCH Part Number 21SN04-472 Serial Number K057744	21-MAR-2010 H: 0.00					
79 3401-001 Engine 2 PART #2886	NO. 2 ENGINE - OIL FILTER DIFFERENTIAL PRESS SWITCH Part Number 21SN04-472 Serial Number K057746	21-MAR-2010 H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
79 3402-001 Engine 1 PART #2083	NO. 1 ENGINE - OIL FILTER POP-UP INDICATOR Part Number: QA07508 Serial Number: RT10-2319	21-MAR-2010 H: 0.00					
79 3402-001 Engine 2 PART #902	NO. 2 ENGINE - OIL FILTER POP-UP INDICATOR Part Number: QA07508 Serial Number: RT10-2314	21-MAR-2010 H: 0.00					
79 6101-001 Engine 1 PART #4349	NO. 1 ENGINE - OIL TANK PRESSURE RELIEF VALVE Part Number: 39556600 Serial Number: SN-UNKNOWN	H: 0.00					
79 6101-001 Engine 2 PART #591	NO. 2 ENGINE - OIL TANK PRESSURE RELIEF VALVE Part Number: 39556600 Serial Number: EE074221-B	12-AUG-2015 H: 1547.10 C: 542					
80 11-01-203 Engine 1 INSPECTION #3000	NO. 1 ENGINE - DISCARD THE AIR TURBINE STARTER OIL	09-AUG-2021 H: 4217.20 C: 1408	H: 500.00	H: 50.00		H: 4717.20	H: 261.40
80 11-01-203 Engine 2 INSPECTION #1338	NO. 2 ENGINE - DISCARD THE AIR TURBINE STARTER OIL	09-AUG-2021 H: 4217.20 C: 1408	H: 500.00	H: 50.00		H: 4717.20	H: 261.40
80 1101-001 Engine 1 PART #1807	NO. 1 ENGINE - AIR TURBINE STARTER ASSY Part Number: 3505934-11 Serial Number: 0601-0941	27-MAR-2017 H: 2219.50 C: 785					
	Notes LESS THAN 5.9 FL OZ OF OIL WHEN DISCARDING OIL						
80 1101-001 Engine 2 PART #2800	NO. 2 ENGINE - AIR TURBINE STARTER ASSY Part Number: 3505934-11 Serial Number: 0701-0982	04-MAR-2016 H: 1753.70 C: 622					
80 1102-001 Engine 1 PART #1703	NO. 1 ENGINE - AIR STARTER VALVE Part Number: 3291182-4 Serial Number: 1109-2574	21-MAR-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
80 1102-001 Engine 2 PART #1845	NO. 2 ENGINE - AIR STARTER VALVE Part Number 3291182-4 Serial Number 1109-2575	21-MAR-2010 H: 0.00					
80 1102-002 Engine 1 PART #2079	NO. 1 ENGINE - AIR STARTER VALVE Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
80 1102-002 Engine 2 PART #1508	NO. 2 ENGINE - AIR STARTER VALVE Part Number PN Serial Number SN- UNKNOWN	21-MAR-2010 H: 0.00					
95 Airframe PART #4632	CALIBRATE CABLE TENSIO METER						
95 Airframe PART #4631	CALIBRATE PELOUZE WEIGHT SCALE 150 LB						
95 Airframe PART #4633	CALIBRATE SHIMPO DIGITAL SCALE						
95 Airframe PART #4635	CALIBRATE SIMPSON 260						
95 Airframe PART #4634	CALIBRATE ULB TESTER						
95 Airframe INSPECTION #4636	DOWNLOAD ENGINE TREND AND SEND TO GXTRENDS@O-SYS.COM	03-MAR-2016 H: 1757.30 L: 622					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AB-BR700-72-900062 R4 Engine 1 SB - N/A #4838	NO. 1 ENGINE - ENGINE - INSTALLATION CHECK OF THE FASTENERS ON THE ENGINE COMPRESSOR AND COMBUSTION SECTION CORE FAIRINGS NON-MODIFICATION, SERVICE BULLETIN	25-FEB-2010					
	Notes NOT APPLICABLE BY ENGINE SERIAL NUMBER. NO FURTHER ACTION REQUIRED.						
AB-BR700-72-900062 R4 Engine 2 SB - N/A #4860	NO. 2 ENGINE - ENGINE - INSTALLATION CHECK OF THE FASTENERS ON THE ENGINE COMPRESSOR AND COMBUSTION SECTION CORE FAIRINGS NON-MODIFICATION, SERVICE BULLETIN						
	Notes NOT APPLICABLE BY ENGINE SERIAL NUMBER. NO FURTHER ACTION REQUIRED.						
ASB A700-11-015 Airframe SB - N/A #3645	MODIFICATION - FLIGHT COMPARTMENT - ADDITION OF A COCKPIT PLACARD (A/C 9002 TO 9103), ALERT SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
ASB A700-25-008 R1 PART B Airframe SB - N/A #3776	MODIFICATION PERMANENT REPAIR OF PILOT AND COPILOT SEAT TRACK STOP FITTING (A/C 9002 TO 9105), ALERT SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
ASB A700-25-008 R1 PART C Airframe SB - N/A #3535	RETROACTIVE ACTION-MODIFICATION OF THE PILOT AND COPILOT SEAT TRACK STOP FITTING (A/C 9002 TO 9105 POST SB 700-25-008, PART B (BASIC ISSUE) AND A/C 9106 TO 9134), ALERT SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
ASB A700-25-008 R1 PART A Airframe SB - N/A #4437	SPECIAL CHECK/REWORK OF PILOT AND COPILOT SEAT TRACK STOP FITTING (A/C 9002 TO 9073), ALERT SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
ASB A700-25-008 R2 PART B Airframe SB - N/A #4266	MODIFICATION (PERMANENT REPAIR) OF THE PILOT AND CO-PILOT SEATS (A/C 9002 TO 9105), ALERT SERVICE BULLETIN Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					
ASB A700-25-008 R2 PART C Airframe SB - N/A #4585	MODIFICATION (RETROACTIVE ACTION FOR AIRCRAFT THAT COMPLY TO PART B OF THE BASIC ISSUE OF THIS SB) OF THE PILOT AND CO-PILOT SEATS (A/C 9002 TO 9105 POST SB A700-25-008, BASIC ISSUE PART B AND A/C 9106 TO 9134), ALERT SERVICE BULLETIN Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					
ASB A700-25-008 R2 PART F Airframe SB - N/A #3687	MODIFICATION - ADDITION OF NEW SERRATED PLATES ON THE PILOT AND CO-PILOT SEATS (A/C 9002 TO 9165 & 9169), ALERT SERVICE BULLETIN Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					
ASB A700-25-008 R2 PART E Airframe SB - N/A #4260	SPECIAL CHECK/REWORK OF SLOTTED PLATES ON THE PILOT AND CO-PILOT SEATS (A/C 9002 TO 9160), ALERT SERVICE BULLETIN Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					
ASB A700-25-008 R2 PART D Airframe SB - N/A #3500	SPECIAL CHECK/REWORK OF THE OLD BOLT ON THE PILOT AND CO-PILOT SEATS (A/C 9002 TO 9105 POST SB A700-25-008, PART B BASIC ISSUE ORREV 1), ALERT SERVICE BULLETIN Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					
ASB A700-25-008 R2 PART A Airframe SB - N/A #3203	SPECIAL CHECK/REWORK OF THE PILOT AND CO-PILOT SEAT-TRACK STOP-FITTINGS (A/C 9002 TO 9073), ALERT SERVICE BULLETIN Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
ASB A700-25-014 Airframe SB - Open #3907	SPECIAL CHECK - PASSENGERCOMPARTMENT - INSPECT SEAT BELTS ON 16G DIVAN FOR PROPER INSTALLATION, ALERT SERVICE BULLETIN	H: 0.00					
ASB A700-25-017 PART A Airframe SB - N/A #3962	SPECIAL CHECK/REWORK - FLIGHT CREW SEATS - CHECK THE ENGAGMENT OF THE FLIGHT CREW SEAT FORE AND AFT TRACK LOCK PINS AND REPLACEMENT OF DEFECTIVE LEVERASSEMBLIES (A/C 9002 TO 9126, 9128, 9129, 9131, TO 9139, 9141 TO 9148, 9150, 9153 TO 9159), ALERT S	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
ASB A700-25-017 PART B Airframe SB - N/A #3405	SPECIAL CHECK/REWORK - FLIGHT CREW SEATS - CHECK THE ENGAGMENT OF THE FLIGHT CREW SEAT FORE AND AFT TRACK LOCK PINS AND REPLACEMENT OF DEFECTIVE LEVERASSEMBLIES (A/C 9002 TO 9126, 9128, 9129, 9131, TO 9139, 9141 TO 9148, 9150, 9153 TO 9159), ALERT S.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
ASB A700-26-006 PART A Airframe SB - Open #4580	SPECIAL CHECK/MODIFICATION - FIRE EXTINGUISHING SYSTEM - HARNESS CONNECTION TO THE FIREX BOTTLE CARTRIDGES, ALERT SERVICE BULLETIN	H: 0.00					
ASB A700-26-006 PART B Airframe SB - Open #4075	SPECIAL CHECK/MODIFICATION - FIRE EXTINGUISHING SYSTEM - HARNESS CONNECTION TO THE FIREX BOTTLE CARTRIDGES, ALERT SERVICE BULLETIN.	H: 0.00					
ASB A700-26-006 R1 PART A Airframe SB - Superseded #3330	ACCOMPLISH - SPECIAL CHECK/MODIFICATION FIRE EXTINGUISHING SYSTEM - HARNESS CONNECTION TO THE FIREX BOTTLE CARTRIDGES, ALERT SERVICE BULLETIN	H: 0.00					
ASB A700-26-006 R1 PART B Airframe SB - Superseded #3261	ACCOMPLISH - SPECIAL CHECK/MODIFICATION FIRE EXTINGUISHING SYSTEM - HARNESS CONNECTION TO THE FIREX BOTTLE CARTRIDGES, ALERT SERVICE BULLETIN.	H: 0.00					
ASB A700-26-006 R1 Airframe SB - Open #3768	SPECIAL CHECK/MODIFICATION FIRE EXTINGUISHING SYSTEM - HARNESS CONNECTION TO THE FIREX BOTTLE CARTRIDGES, ALERT SERVICE BULLETIN	H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
ASB A700-26-006 R2 PART A Airframe SB - Superseded #3245	ACCOMPLISH - SPECIAL CHECK/MODIFICATION FIRE EXTINGUISHING SYSTEM - HARNESS CONNECTION TO THE FIREX BOTTLE CARTRIDGES, ALERT SERVICE BULLETIN..	H: 0.00					
ASB A700-26-006 R2 PART B Airframe SB - Superseded #4063	ACCOMPLISH - SPECIAL CHECK/MODIFICATION FIRE EXTINGUISHING SYSTEM - HARNESS CONNECTION TO THE FIREX BOTTLE CARTRIDGES, ALERT SERVICE BULLETIN...	H: 0.00					
ASB A700-26-006 R2 Airframe SB - Open #4368	SPECIAL CHECK/MODIFICATION FIRE EXTINGUISHING SYSTEM - HARNESS CONNECTION TO THE FIREX BOTTLE CARTRIDGES, ALERT SERVICE BULLETIN.	H: 0.00					
ASB A700-26-006 R3 PART A Airframe SB - Open #3871	SPECIAL CHECK/MODIFICATION - FIRE EXTINGUISHING SYSTEM - HARNESS CONNECTION TO THE FIREX BOTTLE CARTRIDGES, ALERT SERVICE BULLETIN..	H: 0.00					
ASB A700-26-006 R3 PART B Airframe SB - Open #4074	SPECIAL CHECK/MODIFICATION - FIRE EXTINGUISHING SYSTEM - HARNESS CONNECTION TO THE FIREX BOTTLE CARTRIDGES, ALERT SERVICE BULLETIN...	H: 0.00					
ASB A700-26-010 PART B Airframe SB - N/A #2241	INSPECTION - SPECIAL CHECK/REPLACEMENT - FIRE EXTINGUISHING SYSTEM - INSPECTION OF CHECK TEE, PART NO. 446651, ALERT-AND/ORREPLACEMENT OF CHECK TEE FITTING(S)	04-DEC-2013 H: 561.10 L: 260					
	Notes NOT APPLICABLE - N/A PERSN: APU 3130 # 1 / 3128 # 2 / 31422						
ASB A700-26-010 Airframe SB - Complied With #1356	SPECIAL CHECK/REPLACEMENT - FIRE EXTINGUISHING SYSTEM - INSPECTION OF CHECK TEE, PART NO. 446651, ALERT SERVICE BULLETIN	04-DEC-2013 H: 561.10 L: 260					
	Notes COMPLIED WITH						
ASB A700-26-010 PART A Airframe SB - Complied With #452	SPECIAL CHECK/REPLACEMENT- FIRE EXTINGUISHING SYSTEM - INSPECTION OF CHECK TEE, PART NO. 446651, ALERT-SERIAL NUMBER VERIFICATION	04-DEC-2013 H: 561.10 L: 260					
	Notes COMPLIED WITH						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
ASB A700-26-010 R1 Airframe SB - Open #3248	ICA - SPECIAL CHECK/REPLACEMENT - FIRE EXTINGUISHING SYSTEM - INSPECTION OF CHECK TEE, PART NO. 446651, ALERT SERVICE BULLETIN	H: 0.00					
ASB A700-26-010 R1 PART B Airframe SB - Open #4301	ICA - SPECIAL CHECK/REPLACEMENT - FIRE EXTINGUISHING SYSTEM - INSPECTION OF CHECK TEE, PART NO. 446651, ALERT-INSPECTION AND/ORREPLACEMENT OF CHECK TEE FITTING(S)	H: 0.00					
ASB A700-26-010 R1 PART A Airframe SB - Open #4121	ICA - SPECIAL CHECK/REPLACEMENT - FIRE EXTINGUISHING SYSTEM - INSPECTION OF CHECK TEE, PART NO. 446651, ALERT-SERIAL NUMBERVERIFICATION	H: 0.00					
ASB A700-27-032 Airframe SB - Superseded #3217	REWORK - FLAP SYSTEM - APPLICATION OF MOISTURE-PROOFING COMPOUND TO PREVENT SEIZURE OF FLAP SKEW SENSOR, ALERT SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
ASB A700-27-032 R1 Airframe SB - Superseded #4559	REWORK - FLAP SYSTEM - APPLICATION OF MOISTURE-PROOFING COMPOUND TO PREVENT SEIZURE OF FLAP SKEW SENSOR, ALERT SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
ASB A700-27-032 R2 Airframe SB - Superseded #4279	REWORK - FLAP SYSTEM - APPLICATION OF MOISTURE-PROOFING COMPOUND TO PREVENT SEIZURE OF FLAP SKEW SENSOR, ALERT SERVICE BULLETIN..	H: 0.00					
	Notes SUPERSEDED						
ASB A700-27-032 R3 Airframe SB - Open #4535	REWORK FLAP-SYSTEM-APPLICATION OF MOISTURE PROOFING COMPOUND TO PREVENT SEIZURE OF FLAP SKEW SENSORS, ALERT SERVICE BULLETIN	H: 0.00					
ASB A700-27-035 PART A Airframe SB - Open #3332	SPECIAL CHECK/MODIFICATION - CONTROL AND INDICATION SYSTEMS - VISUAL CHECK OF THE SLAT/FLAP CONTROL UNITS (SFCU) AND REPLACEMENT OF UNSATISFACTORY SFCU WITH UNITS THAT HAVE BETTERPOWER MONITORING CIRCUITRY AND POWER MODULE CONFIGURATION, ALERT SERVI	H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
ASB A700-27-035 PART B Airframe SB - Open #4453	SPECIAL CHECK/MODIFICATION - CONTROL AND INDICATION SYSTEMS - VISUAL CHECK OF THE SLAT/FLAP CONTROL UNITS (SFCU) AND REPLACEMENT OF UNSATISFACTORY SFCU WITH UNITS THAT HAVE BETTERPOWER MONITORING CIRCUITRY AND POWER MODULE CONFIGURATION, ALERT SERVI.	H: 0.00					
ASB A700-27-043 Airframe SB - Open #4051	SPECIAL CHECK - CONTROL AND INDICATION SYSTEMS - VISUALLY EXAMINE LEAD WIRE OF RESISTORR1 ON POWER ASSEMBLY A4 INSIDE SLAT/FLAP CONTROL UNIT (SFCU), ALERT SERVICE BULLETIN	H: 0.00					
ASB A700-27-055 PART A Airframe SB - N/A #3518	MODIFICATION - ELEVATORCONTROL SYSTEM - REPLACE ELEVATOR LOAD LIMITERS THAT HAVE LOCKING NUTS WHICH HAVE LOOSENED (A/C 9139, 9142, 9148, 9151 AND 9153), ALERT SERVICE BULLETIN Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					
ASB A700-27-055 PART B Airframe SB - N/A #3345	MODIFICATION - ELEVATORCONTROL SYSTEM - REPLACE ELEVATOR LOAD LIMITERS THAT HAVE LOCKING NUTS WHICH HAVE LOOSENED (A/C 9143 AND 9150), ALERT SERVICE BULLETIN Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					
ASB A700-27-056 Airframe SB - N/A #3365	MODIFICATION - RUDDERCONTROL SYSTEM - REPLACE RUDDER LOAD LIMITERS THAT HAVE LOCKING NUTS WHICH HAVE LOOSENED (A/C 9144, 9145, 9150, 9151, 9153, AND 9159), ALERT SERVICE BULLETIN Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					
ASB A700-27-062 Airframe SB - N/A #4105	REWORK - FLAP SYSTEM - APPLICATION OF MOISTURE-PROOFING COMPOUND TO PREVENT SEIZURE OF FLAP SKEW SENSORS NO.1, ALERT SERVICE BULLETIN Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					
ASB A700-27-066 Airframe SB - N/A #3627	SPECIAL CHECK/REWORK - ELEVATORCONTROL SYSTEM - INSPECTION OF ELEVATOR PCU, P/N GT411-3800-7, ATTACHMENT FITTINGS AND SLOTTED ENTRY BEARINGS (A/C 9002 TO 9222), ALERT SERVICE BULLETIN Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					





Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
ASB A700-27-066 R1 Airframe SB - N/A #3796	SPECIAL CHECK/REWORK - ELEVATORCONTROL SYSTEM - INSPECTION OF ELEVATOR PCU, P/N GT411-3800-5 & -7, ATTACHMENT FITTINGS AND SLOTTED ENTRY BEARINGS (A/C 9002 TO 9222), ALERT SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
ASB A700-27-066 R2 Airframe SB - N/A #3495	SPECIAL CHECK/REWORK - ELEVATORCONTROL SYSTEM - INSPECTION OF ELEVATOR PCU, P/N GT411-3800-5 & -7, ATTACHMENT FITTINGS AND SLOTTED ENTRY BEARINGS (A/C 9002 TO 9222), ALERT SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
ASB A700-28-031 Airframe SB - Superseded #4454	MODIFICATION - FUEL FEED SYSTEM - REPLACEMENT OF THE EXISTING APU FUEL FEED LINE FITTING WITH A SHROUDED ONE, ALERT SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
ASB A700-28-031 R1 Airframe SB - Open #3459	MODIFICATION - FUEL FEED SYSTEM - REPLACEMENT OF THE EXISTING APU FUEL FEED LINE FITTING WITH A SHROUDED ONE, ALERT SERVICE BULLETIN.	H: 0.00					
ASB A700-29-016 Airframe SB - Open #4328	SPECIAL CHECK/REWORK - NO. 3 HYDRAULIC SYSTEM - POSSIBLE CONTAMINATION CAUSED BY RAM AIRTURBINE (RAT) PIVOT SHAFT, ALERT SERVICE BULLETIN	H: 0.00					
ASB A700-31-029 PART B Airframe SB - Superseded #4442	MODIFICATION - INTEGRATED AVIONICS COMPUTER(IAC) SYSTEM - AIRBORNE DATA-LINK SYSTEM DEACTIVATION OR IAC REVERSION FROM BATCH 2 TO BATCH 1 (A/C 9002 TO 9137, 9139 TO 9150 AND 9153 TO 9999), ALERT SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
ASB A700-31-029 PART A Airframe SB - Superseded #3236	MODIFICATION - INTEGRATED AVIONICS COMPUTER(IAC) SYSTEM - AIRBORNE DATA-LINK SYSTEM DEACTIVATION OR IAC REVERSION FROM BATCH 2 TO BATCH 1(A/C 9002 TO 9126, 9128 TO 9151 AND 9153 TO 9999), ALERT SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
ASB A700-31-029 R1 PART A Airframe SB - N/A #3277	MODIFICATION - INTEGRATED AVIONICS COMPUTER(IAC) SYSTEM - AIRBORNE DATA-LINK SYSTEM DEACTIVATION OR IAC REVERSION FROM BATCH 2 TO BATCH 1(9002 TO 9126, 9128 TO 9151 AND 9153 TO 9173), ALERT SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
ASB A700-31-029 R1 PART B Airframe SB - N/A #4192	MODIFICATION - INTEGRATED AVIONICS COMPUTER(IAC) SYSTEM - AIRBORNE DATA-LINK SYSTEM DEACTIVATION OR IAC REVERSION FROM BATCH 2 TO BATCH 1(9002 TO 9137, 9139 TO 9150, 9153 TO 9173), ALERT SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
ASB A700-32-009 Airframe SB - Open #3802	MODIFICATION - BRAKE CONTROL SYSTEM - REPLACEMENT OF BRAKE CONTROL UNIT TO PREVENT POSSIBLE UNCOMMANDED BRAKING, ALERT SERVICE BULLETIN	H: 0.00					
ASB A700-32-011 PART A Airframe SB - Superseded #3894	SPECIAL CHECK/ MODIFICATION/REWORK - LANDING-GEAREMERGENCY EXTENSION - EXAMINE THE MAIN QUADRANT, THE NLG DOOR QUADRANT AND THE NLG UPLOCK QUADRANT FOR THE PRESENCE OF CABLE GUARD PINS AND FOULING CONDITION, ALERT SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
ASB A700-32-011 PART B Airframe SB - Superseded #4382	SPECIAL CHECK/ MODIFICATION/REWORK - LANDING-GEAREMERGENCY EXTENSION - EXAMINE THE MAIN QUADRANT, THE NLG DOOR QUADRANT AND THE NLG UPLOCK QUADRANT FOR THE PRESENCE OF CABLE GUARD PINS AND FOULING CONDITION, ALERT SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
ASB A700-32-011 PART C Airframe SB - Superseded #3906	SPECIAL CHECK/ MODIFICATION/REWORK - LANDING-GEAREMERGENCY EXTENSION - EXAMINE THE MAIN QUADRANT, THE NLG DOOR QUADRANT AND THE NLG UPLOCK QUADRANT FOR THE PRESENCE OF CABLE GUARD PINS AND FOULING CONDITION, ALERT SERVICE BULLETIN..	H: 0.00					
	Notes SUPERSEDED						
ASB A700-32-011 R1 PART A Airframe SB - Open #3282	SPECIAL CHECK/ MODIFICATION/REWORK - LANDING-GEAREMERGENCY EXTENSION - EXAMINE THE MAIN QUADRANT, THE NLG DOOR QUADRANT AND THE NLG UPLOCK QUADRANT FOR THE PRESENCE OF CABLE GUARD PINS AND FOULING CONDITION, ALERT SERVICE BULLETIN...	H: 0.00					

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
ASB A700-32-011 R1 PART B Airframe SB - Open #3628	SPECIAL CHECK/ MODIFICATION/REWORK - LANDING-GEAREMERGENCY EXTENSION - EXAMINE THE MAIN QUADRANT, THE NLG DOOR QUADRANT AND THE NLG UPLOCK QUADRANT FOR THE PRESENCE OF CABLE GUARD PINS AND FOULING CONDITION, ALERT SERVICE BULLETIN....	H: 0.00					
ASB A700-32-011 R1 PART C Airframe SB - Open #4390	SPECIAL CHECK/ MODIFICATION/REWORK - LANDING-GEAREMERGENCY EXTENSION - EXAMINE THE MAIN QUADRANT, THE NLG DOOR QUADRANT AND THE NLG UPLOCK QUADRANT FOR THE PRESENCE OF CABLE GUARD PINS AND FOULING CONDITION, ALERT SERVICE BULLETIN.....	H: 0.00					
ASB A700-32-012 PART A Airframe SB - Superseded #4096	SPECIAL CHECK/REWORK - NOSE LANDING GEAR- EXAMINE NOSE LANDING GEAR (NLG) CENTERING CAM FOR ROTATIONAL FREE PLAY, ALERT SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
ASB A700-32-012 PART B Airframe SB - Superseded #3913	SPECIAL CHECK/REWORK - NOSE LANDING GEAR- EXAMINE NOSE LANDING GEAR (NLG) CENTERING CAM FOR ROTATIONAL FREE PLAY, ALERT SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
ASB A700-32-012 PART C Airframe SB - Superseded #3444	SPECIAL CHECK/REWORK - NOSE LANDING GEAR- EXAMINE NOSE LANDING GEAR (NLG) CENTERING CAM FOR ROTATIONAL FREE PLAY, ALERT SERVICE BULLETIN..	H: 0.00					
	Notes SUPERSEDED						
ASB A700-32-012 R1 PART A Airframe SB - Open #3241	SPECIAL CHECK/REWORK - NOSE LANDING GEAR- EXAMINE NOSE LANDING GEAR (NLG) CENTERING CAM FOR ROTATIONAL FREE PLAY, ALERT SERVICE BULLETIN...	H: 0.00					
ASB A700-32-012 R1 PART B Airframe SB - Open #3836	SPECIAL CHECK/REWORK - NOSE LANDING GEAR- EXAMINE NOSE LANDING GEAR (NLG) CENTERING CAM FOR ROTATIONAL FREE PLAY, ALERT SERVICE BULLETIN....	H: 0.00					

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
ASB A700-32-012 R1 PART C Airframe SB - Open #3466	SPECIAL CHECK/REWORK - NOSE LANDING GEAR- EXAMINE NOSE LANDING GEAR (NLG) CENTERING CAM FOR ROTATIONAL FREE PLAY, ALERT SERVICE BULLETIN.....	H: 0.00					
ASB A700-32-017 Airframe SB - N/A #4067	SPECIAL CHECK/REWORK - BRAKE CONTROL SYSTEM - REPLACEMENT OF BRAKE CONTROL UNITS (BCU) WITH SPECIFIC SERIAL NUMBER(A/C 9138, 9145 TO 9147, 9150, 9151 AND 9159), ALERT SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
ASB A700-32-019 PART A Airframe SB - N/A #3231	SPECIAL CHECK/REWORK - NOSE WHEELS AND TIRES INSPECT AND REPLACE DEFECTIVE NOSE LANDING GEAR(NLG) TIRES (A/C 9002 TO 9126 AND 9128 TO 9175), ALERT SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
ASB A700-32-019 PART B Airframe SB - N/A #3445	SPECIAL CHECK/REWORK - NOSE WHEELS AND TIRES INSPECT AND REPLACE DEFECTIVE NOSE LANDING GEAR(NLG) TIRES (A/C 9002 TO 9126 AND 9128 TO 9175), ALERT SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
ASB A700-33-022 Airframe SB - N/A #4119	MODIFICATION - EMERGENCY LIGHTING - CHANGE OF BOLTS ON THE EXTERIOREMERGENCY LIGHTS (A/C S/N 9165 TO 9180), ALERT SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
ASB A700-34-001 Airframe SB - Open #3923	SPECIAL CHECK/MODIFICATION - ON-BOARD DATA-LOADERSYSTEM - VERIFICATION AND/OR INSTALLATION OF LATEST AIRCRAFT DATABASE VERSION (GEX003V2 OR LATER), ALERT SERVICE BULLETIN	H: 0.00					
ASB A700-34-029 Airframe SB - Open #3911	SPECIAL CHECK - VHF NAVIGATION SYSTEM - POTENTIAL MISLEADING GLIDE SLOPE DATA FROM NV-850 NAV RECEIVERMODULE A2, ALERT SERVICE BULLETIN	H: 0.00					

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
ASB A700-53-026 PART B Airframe SB - Open #3257	SPECIAL CHECK/REWORK - WINDOWS - EXAMINE INBOARD SKIN PERIPHERY AROUND CABIN WINDOWS FORCORROSION, ALERT SERVICE BULLETIN	H: 0.00					
ASB A700-53-033 PART A Airframe SB - N/A #4036	CHECK FORFLUID CONTAMINATION OF SOUNDPROOFING MATERIAL AND MODIFY AND REMOVE SOUNDPROOFING MATERIAL FROM SPECIFIED AREAS (A/C 9121, 9136, 9139, 9141 AND 9143), ALERT SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
ASB A700-53-033 PART B Airframe SB - N/A #4180	CHECK FORFLUID CONTAMINATION OF SOUNDPROOFING MATERIAL AND MODIFY AND REMOVE SOUNDPROOFING MATERIAL FROM SPECIFIED AREAS (A/C 9121, 9136, 9139, 9141 AND 9143), ALERT SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
ASB A700-53-039 PART A Airframe SB - Complied With #4371	INSPECTION - SPECIAL CHECK/REWORK - BELLY FAIRINGS - INSPECT FASTENERS THAT RETAIN BELLY FAIRINGS, ALERT SERVICE BULLETIN	H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
ASB A700-53-039 PART C Airframe SB - Open #3867	REPLACEMENT - SPECIAL CHECK/REWORK - BELLY FAIRINGS - INSPECT FASTENERS THAT RETAIN BELLY FAIRINGS, ALERT-OF FAULTY FASTENERS	H: 0.00					
ASB A700-53-039 PART B Airframe SB - Complied With #3136	REWORK - SPECIAL CHECK/REWORK - BELLY FAIRINGS - INSPECT FASTENERS THAT RETAIN BELLY FAIRINGS, ALERT SERVICE BULLETIN	H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
ASB A700-53-039 Airframe SB - Complied With #2496	SPECIAL CHECK/REWORK - BELLY FAIRINGS - INSPECT FASTENERS THAT RETAIN BELLY FAIRINGS, ALERT SERVICE BULLETIN	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
ASB A700-53-045 PART A Airframe SB - Complied With #3924	INSPECTION - SPECIAL CHECK/REWORK - BELLY FAIRINGS - BELLY FAIRINGS FASTENERS ENGAGEMENT CHECK, ALERT SERVICE BULLETIN	23-NOV-2016 H: 2064.80 L: 722					
	Notes COMPLIED WITH						
ASB A700-53-045 PART C Airframe SB - N/A #893	REPLACE - SPECIAL CHECK/REWORK - BELLY FAIRINGS - BELLY FAIRINGS FASTENERS ENGAGEMENT CHECK, ALERT SERVICE BULLETIN	23-NOV-2016 H: 2064.80 L: 722					
	Notes NOT APPLICABLE						
ASB A700-53-045 PART B Airframe SB - N/A #3089	REWORK - SPECIAL CHECK/REWORK - BELLY FAIRINGS - BELLY FAIRINGS FASTENERS ENGAGEMENT CHECK, ALERT SERVICE BULLETIN	23-NOV-2016 H: 2064.80 L: 722					
	Notes NOT APPLICABLE						
ASB A700-53-045 Airframe SB - Complied With #857	SPECIAL CHECK/REWORK - BELLY FAIRINGS - BELLY FAIRINGS FASTENERS ENGAGEMENT CHECK, ALERT SERVICE BULLETIN	20-NOV-2016 H: 2064.80 L: 722					
	Notes COMPLIED WITH						
ASB A700-57-045 PART A Airframe SB - Complied With #3937	INSPECT - SPECIAL CHECK/REWORK - AILERON CONTROL SYSTEM - ENSURE WING SEALING DOES NOT PERMIT FREEZING OF THE AILERON CONTROL, ALERT SERVICE BULLETIN	H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
ASB A700-57-045 PART B Airframe SB - Complied With #3939	REWORK - SPECIAL CHECK/REWORK - AILERON CONTROL SYSTEM - ENSURE WING SEALING DOES NOT PERMIT FREEZING OF THE AILERON CONTROL, ALERT SERVICE BULLETIN	H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
ASB A700-57-045 Airframe SB - Complied With #173	SPECIAL CHECK/REWORK - AILERON CONTROL SYSTEM - ENSURE WING SEALING DOES NOT PERMIT FREEZING OF THE AILERON CONTROL, ALERT SERVICE BULLETIN	03-FEB-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
ASB A700-72-003 Airframe SB - Superseded #3736	REWORK - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL-PUMP SPLINED COUPLING, ALERT SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
ASB A700-72-003 R1 Airframe SB - Superseded #4263	ICA - REWORK - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL-PUMP SPLINED COUPLING, ALERT SERVICE BULLETIN	31-MAR-2020 H: 3741.10 L: 1233					
	Notes SUPERSEDED BY REV 2						
ASB A700-73-007 Airframe SB - N/A #3275	MODIFICATION - FULL-AUTHORITY DIGITAL ENGINE CONTROL (FADEC) - INTRODUCTION OF EEC SOFTWARE UPGRADE X1.1 (A/C 9249 AND 9255 TO 9274), ALERT SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
ASB BR700-72-A101523 R3 Engine 1 SB - N/A #3481	NO. 1 ENGINE - LOW PRESSURE (LP) TURBINE SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUTOFF PAWL CARRIERPIVOT PINS MADE FROM A DIFFERENT MATERIAL WITH IMPROVED CORROSION PROTECTION PROPERTIES, ALERT SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
ASB BR700-72-A101523 R3 Engine 2 SB - N/A #3324	NO. 2 ENGINE - LOW PRESSURE (LP) TURBINE SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUTOFF PAWL CARRIERPIVOT PINS MADE FROM A DIFFERENT MATERIAL WITH IMPROVED CORROSION PROTECTION PROPERTIES, ALERT SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
ASB BR700-72-A900297 Engine 1 SB - Open #3856	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSORFAIRINGS - INSPECTION OF THE UPPER LEFT HP COMPRESSOR FAIRING FOR POTENTIAL PROFILE NON-CONFORMANCE AND REPLACEMENT OF NON-CONFORMING UPPER LEFT HP COMPRESSOR FAIRING - NON-MODIFICATION, ALERT SER	H: 0.00					
ASB BR700-72-A900297 Engine 2 SB - Open #4189	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSORFAIRINGS - INSPECTION OF THE UPPER LEFT HP COMPRESSOR FAIRING FOR POTENTIAL PROFILE NON-CONFORMANCE AND REPLACEMENT OF NON-CONFORMING UPPER LEFT HP COMPRESSOR FAIRING - NON-MODIFICATION, ALERT SER	H: 0.00					
ASB BR700-72-A900297 R1 Engine 1 SB - Open #3667	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESOR FAIRINGS - INSPECTION OF THE UPPER LEFT FAIRING FORPOTENTIAL PROFILE NON CONFORMANCE AND REPLACEMENT OF NON-CONFORMING UPPER LEFT HP COMPRESSOR FAIRING - NON MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN	H: 0.00					
ASB BR700-72-A900297 R1 Engine 2 SB - Open #3076	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR FAIRINGS - INSPECTION OF THE UPPER LEFFAIRING FORPOTENTIAL PROFILE NON CONFORMANCE AND REPLACEMENT OF NON-CONFORMING UPPER LEFT HP COMPRESSOR FAIRING - NON MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN.	H: 0.00					
ASB BR700-72-A900298 Engine 1 SB - Open #4518	NO. 1 ENGINE - ENGINE - ENGINE COMBUSTION FAIRINGS - REPLACEMENT OF NON-CONFORMING UPPERLEFT, UPPER RIGHT AND LOWER RIGHT COMBUSTION SECTION FAIRINGS - NON-MODIFICATION, ALERT RECOMMENDED	H: 0.00					
ASB BR700-72-A900298 Engine 2 SB - Open #3740	NO. 2 ENGINE - ENGINE - ENGINE COMBUSTION FAIRINGS - REPLACEMENT OF NON-CONFORMING UPPERLEFT, UPPER RIGHT AND LOWER RIGHT COMBUSTION SECTION FAIRINGS - NON-MODIFICATION, ALERT RECOMMENDED	H: 0.00					
ASB BR700-72-A900298 R1 Engine 1 SB - Open #3809	NO. 1 ENGINE - ENGINE COMBUSTION FAIRINGS - REPLACEMENT OF NON-CONFORMING UPPER LEFT, UPPER RIGHT AND LOWERRIGHT COMBUSTION SECTION FAIRINGS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN	H: 0.00					
ASB BR700-72-A900298 R1 Engine 2 SB - Open #4500	NO. 2 ENGINE - ENGINE COMBUSTION FAIRINGS - REPLACEMENT OF NON-CONFORMING UPPER LEFT, UPPER RIGHT AND LOWERRIGHT COMBUSTION SECTION FAIRINGS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN.	H: 0.00					

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
ASB BR700-72-A900497 Engine 1 SB - N/A #4449	NO. 1 ENGINE - HPT ROTORDISCS - DECREASE OF TIME LIMITS MANUAL MAXIMUM APPROVED LIVES OF STG 1 & 2 DISCS, ALERT SERVICE BULLETIN	21-JAN-2011 H: 11.80 C: 6					
	Notes NOT APPLICABLE - NO ACTION REQUIRED DUE CYCLES WITHIN LIFE LIMITATION INCORPORATED						
ASB BR700-72-A900497 Engine 2 SB - N/A #3849	NO. 2 ENGINE - HPT ROTORDISCS - DECREASE OF TIME LIMITS MANUAL MAXIMUM APPROVED LIVES OF STG 1 & 2 DISCS, ALERT SERVICE BULLETIN	21-JAN-2011 H: 11.80 C: 6					
	Notes NOT APPLICABLE - NO ACTION REQUIRED DUE CYCLES WITH IN LIFE LIMITATION INCORPORATED.						
ASB BR700-72-A900504 Engine 1 SB - Superseded #4104	NO. 1 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FORTOUCH-AND-GO AND OVERSHOOT, ALERT SERVICE BULLETIN	H: 0.00					
ASB BR700-72-A900504 Engine 2 SB - Superseded #3325	NO. 2 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FORTOUCH-AND-GO AND OVERSHOOT, ALERT SERVICE BULLETIN	H: 0.00					
ASB BR700-72-A900504 R1 Engine 1 SB - N/A #4233	NO. 1 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT, ALERT SERVICE BULLETIN	21-JAN-2011 H: 11.80 C: 6					
	Notes NOT APPLICABLE - NO ACTION REQUIRED DUE TO CYCLES WITH IN LIFE LIMITATION						
ASB BR700-72-A900504 R1 Engine 2 SB - N/A #3890	NO. 2 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT, ALERT SERVICE BULLETIN	21-JAN-2011 H: 11.80 C: 6					
	Notes NOT APPLICABLE - NO ACTION REQUIRED DUE TO CYCLES WITHIN LIFE LIMITATION						
ASB BR700-72-A900508 Engine 1 SB - Open #4194	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE ROTORDISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 AND 2 DISCS DUE TO POTENTIAL STEEL INCLUSION - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN	H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
ASB BR700-72-A900508 Engine 2 SB - Open #3701	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE ROTORDISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 AND 2 DISCS DUE TO POTENTIAL STEEL INCLUSION - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN	H: 0.00					
ASB BR700-72-A900508 R1 Engine 1 SB - Open #3833	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 AND 2 DISCS DUE TO POTENTIAL STEEL INCLUSION - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN	H: 0.00	C: 3000			C: 3000.00	C: 1505
ASB BR700-72-A900508 R1 Engine 2 SB - Open #3674	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 AND 2 DISCS DUE TO POTENTIAL STEEL INCLUSION - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN.	H: 0.00	C: 3000			C: 3000.00	C: 1505
ASB BR700-72-A900509 Engine 1 SB - Superseded #4184	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION, ALERT SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED BY REV 1						
ASB BR700-72-A900509 Engine 2 SB - Superseded #4052	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION, ALERT SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED BY REV 1						
ASB BR700-72-A900509 R1 Engine 1 SB - Superseded #3652	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION, ALERT SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED BY REV 2						
ASB BR700-72-A900509 R1 Engine 2 SB - Superseded #4068	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION, ALERT SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED BY REV 2						





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
ASB BR700-72-A900509 R2 Engine 1 SB - Superseded #4567	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION, ALERT SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED BY REV 3						
ASB BR700-72-A900509 R2 Engine 2 SB - Superseded #3771	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION, ALERT SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED BY REV 3						
ASB BR700-72-A900509 R3 Engine 1 SB - Superseded #3227	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION, ALERT SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED BY REV 4						
ASB BR700-72-A900509 R3 Engine 2 SB - Superseded #4094	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION, ALERT SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED BY REV 4						
ASB BR700-72-A900509 R4 Engine 1 SB - Recurring #3137	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION, ALERT SERVICE BULLETIN	31-MAR-2020 H: 3741.10 C: 1233	H: 4000.00			H: 7741.10	H: 3285.30
ASB BR700-72-A900509 R4 Engine 2 SB - Recurring #4503	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION, ALERT SERVICE BULLETIN	31-MAR-2020 H: 3741.10 C: 1233	H: 4000.00			H: 7741.10	H: 3285.30





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
ASB BR700-72-A900556 R2 Engine 1 SB - N/A #3083	NO. 1 ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR SPECIAL FLIGHT REPFIL - NON- MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN Notes NOT APPLICABLE	H: 0.00					
ASB BR700-72-A900556 R2 Engine 2 SB - N/A #3888	NO. 2 ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR SPECIAL FLIGHT REPFIL - NON- MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN Notes NOT APPLICABLE	H: 0.00					
ASB BR700-73-A900083 Engine 1 SB - N/A #3523	NO. 1 ENGINE - ENGINE FUEL AND CONTROL ENGINE ELECTRONIC CONTROLLER(EEC) - REPLACEMENT OF NON-CONFORMING PARTS OF THE EEC FIREBOX ASSEMBLY - NON-MODIFICATION, ALERT SERVICE BULLETIN Notes NOT APPLICABLE	H: 0.00					
ASB BR700-73-A900083 Engine 2 SB - N/A #3608	NO. 2 ENGINE - ENGINE FUEL AND CONTROL ENGINE ELECTRONIC CONTROLLER(EEC) - REPLACEMENT OF NON-CONFORMING PARTS OF THE EEC FIREBOX ASSEMBLY - NON-MODIFICATION, ALERT SERVICE BULLETIN Notes NOT APPLICABLE	H: 0.00					
ASB BR700-73-A900451 Engine 1 SB - N/A #4483	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL METERING UNIT (FMU) - COMBINED OVERSPEED SHUTOFF SOLENOID (COSS) SCREENING FORREVERSE WIRED INDEPENDENT OVERSPEED PROTECTION (IOP) COILS, ALERT SERVICE BULLETIN Notes NOT APPLICABLE - BY SERIAL NUMBER	25-FEB-2010 H: 0.00					
ASB BR700-73-A900451 Engine 2 SB - N/A #4512	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL METERING UNIT (FMU) - COMBINED OVERSPEED SHUTOFF SOLENOID (COSS) SCREENING FORREVERSE WIRED INDEPENDENT OVERSPEED PROTECTION (IOP) COILS, ALERT SERVICE BULLETIN Notes NOT APPLICABLE - BY SERIAL NUMBER	25-FEB-2010 H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
MODSUM IS700-23-0001 RA Airframe SB - Open #3902	GROUND SIGNAL ADDED ON COCKPIT PRINTERCONNECTOR (A/C 9002 - 9999), MODIFICATION SUMMARY	H: 0.00					
MODSUM IS700-23-0002 RC Airframe SB - Open #4178	ACP WIRING CHANGE TO PREVENT COMM AUDIO BLEEDING ON HEADPHONE OUTPUTS - AUDIO INTEGRATING SYSTEM (A/C 9002 - 9269), MODIFICATION SUMMARY	H: 0.00					
MODSUM IS700-24-0001 RB Airframe SB - Open #3677	EMS CDU - DISABLING UNUSED THERMAL CIRCUIT BREAKER(A/C 9002 - 9184, 9186 - 9999), MODIFICATION SUMMARY	H: 0.00					
MODSUM IS700-24-0002 RA Airframe SB - Open #3474	CRAWLWAY FLOORPANEL - ADDITION OF PROTECTIVE TAPE, MODIFICATION SUMMARY	H: 0.00					
MODSUM IS700-32-0001 RA Airframe SB - Complied With #1902	INSTL MLG-DOOR, OUTBOARD, HINGE PIN REPLACEMENT, MODIFICATION SUMMARY	02-AUG-2013 H: 432.80 L: 211					
	Notes COMPLIED WITH						
MODSUM IS700-32-0001 RB Airframe SB - Open #3514	INSTALL - MLG DOOR, OUTBOARD, HINGE PIN REPLACEMENT, MODIFICATION SUMMARY	H: 0.00					
MODSUM IS700-32-0002 RA Airframe SB - Open #3556	KIT - INTRO OF ADDITIONAL HYDRAULIC LINE SUPPORT - MLG BAY (EFFECTIVITY 9002-9999), MODIFICATION SUMMARY	H: 0.00					
MODSUM IS700-52-0001 RA Airframe SB - Open #3225	PAX DOOR- ABUTMENT FITTING - WATER DIVERTER INSTALLTION (A/C 9002 - 9126, 9128 - 9999), MODIFICATION SUMMARY	H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
MODSUM IS700-52-0004 RA Airframe SB - Open #4314	KIT, REMOVAL OF THE PASSENGERDOOR AESTHETIC SIDE COVERS, MODIFICATION SUMMARY	H: 0.00					
MODSUM IS700-52-0005 RB Airframe SB - Open #3775	LUBRICATION OF PAX DOORHANDRAIL TELESCOPIC STRUTS, MODIFICATION SUMMARY	H: 0.00					
MODSUM IS700-53-0001 RC Airframe SB - Open #3135	INSTALATION OF EVS DRIP TRAY, MODIFICATION SUMMARY	H: 0.00					
MODSUM IS700-53-0002 RA Airframe SB - Open #3169	FUSELAGE - AVIONICS BAY - INSTALATION OF LGECU DRIP COVER(CLASSIC GX & XRS), MODIFICATION SUMMARY	H: 0.00					
MODSUM IS700-53-0003 RA Airframe SB - Open #3058	FUSELAGE - AVIONICS BAY - INSTALATION OF IRU DRIP COVER(CLASSIC GLOBAL EXPRESS, G500 & XRS), MODIFICATION SUMMARY	H: 0.00					
MODSUM IS700-53-0004 RA Airframe SB - Open #3320	FUSELAGE - AVIONICS BAY - INSTALATION OF HUD COMPUTERDRIP COVER (CLASSIC GX & XRS), MODIFICATION SUMMARY	H: 0.00					
MODSUM IS700-53-0005 RA Airframe SB - Open #3454	FUSELAGE - AVIONICS BAY - INSTALATION OF TCAS RECIEVER/TRANSMITTERDRIP COVER (CLASSIC GX & XRS), MODIFICATION SUMMARY	H: 0.00					
MODSUM IS700-53-0013 RA1 Airframe SB - Complied With #4665	FUSELAGE- AFT TAILCONE- KIT- ADDITION OF DRAIN HOLES TO LHS AND RHS AFT TAILCONE SKINS	04-MAR-2016 H: 1753.70 L: 622					
MODSUM IS700-57-0003 Airframe SB - Complied With #4666	WINGS- FLAP CANOE WS404 FAIRING, CHAFFING PROTECTION	04-MAR-2016 H: 1753.70 L: 622					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SAIB NE-18-01 Airframe SB - N/A #4820	NAVIGATION- INTEGRATED FLIGHT DIRECTOR SYSTEM- ESTERLINE DU-875, DU-885 AND DU-885AF DISPLAYS	03-NOV-2017 H: 2514.20 L: 881					
	Notes SAIB NE-18-01 IS N/A DUE DU875 DISPLAYS NOT INSTALLED						
SB 1285A-32-06 Airframe SB - Complied With #1158	NLG STRUT ASY PNR22175-10X (LIEBHERR PNR 1285A0000-0X) - HARMONIZATION OF SHRINK SLEEVE DESIGN, SERVICE BULLETIN	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
SB 3615880-49-8149 R1 APU SB - Open #4140	APU - AIRBORNE AUXILIARY POWER- GAS TURBINE ENGINE - BALANCE REPAIR OF THE TURBINE ROTORS, PN 3615880-1, PN 3615880-002, PN 3615880-3, AND PN 3615880-4, ON MULTIPLE APUS, SERVICE BULLETIN	H: 0.00					
SB 3822101-49-8148 R1 APU SB - Open #3658	APU - AIRBORNE AUXILIARY POWER- GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTORS, PN 3822101-1, ON MULTIPLE APUS, SERVICE BULLETIN	H: 0.00					
SB 49-7933 R10 APU SB - Open #4742	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS						
SB 49-7933 R2 APU SB - Superseded #4557	APU - AIRBORNE AUXILIARY POWERUNIT (APU) - OIL - GENERAL - APPROVED OILS, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 49-7933 R3 APU SB - Superseded #3086	APU - AIRBORNE AUXILIARY POWERUNIT (APU) - OIL - GENERAL - APPROVED OILS, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 49-7933 R4 APU SB - Superseded #3695	APU - OIL - GENERAL - APPROVED OILS, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 49-7933 R5 APU SB - N/A #3449	APU - OIL - GENERAL - APPROVED OILS, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE						
SB 49-7997 R1 APU SB - Superseded #3636	APU - AIRBORNE AUXILIARY POWER- GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 49-7997 R2 APU SB - Superseded #4280	APU - AIRBORNE AUXILIARY POWER- GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 49-7997 R3 APU SB - Superseded #4330	APU - AIRBORNE AUXILIARY POWER- GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES, SERVICE BULLETIN..	H: 0.00					
	Notes SUPERSEDED						
SB 49-7997 R4 APU SB - Open #3082	APU - AIRBORNE AUXILIARY POWER- GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES, SERVICE BULLETIN...	H: 0.00					
SB 49-8039 APU SB - Open #4441	APU - AIRBORNE AUXILIARY POWER- GAS TURBINE ENGINE - REPLACE THE STARTER MOTOR, PN 2704554-2 WITH PN 2704554-3, SERVICE BULLETIN	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 49-8039 R1 APU SB - Open #4179	APU - AIRBORNE AUXILIARY POWER- GAS TURBINE ENGINE - REPLACE THE STARTER MOTOR, PN 2704554-2 WITH PN 2704554-3, SERVICE BULLETIN.	H: 0.00					
SB 700-00-004 R1 Airframe SB - Open #4760	CONTROLLED EFFECTIVITY - SERVICE BULLETIN PRICING (REV. 1)						
SB 700-00-004 R4 Airframe SB - Open #4831	CONTROLLED EFFECTIVITY SERVICE BULLETIN PRICING (REV. 4)						
SB 700-11-007 Airframe SB - Superseded #3685	MODIFICATION - FLIGHT COMPARTMENT PLACARDS - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 95,000 LB (43,092 KG), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-11-007 R1 Airframe SB - N/A #3531	MODIFICATION - FLIGHT COMPARTMENT PLACARDS - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 95,000 LB (43,092 KG) (A/C 9002 TO 9158), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-11-008 Airframe SB - N/A #4132	MODIFICATION - INTERIORPLACARDS - REPLACEMENT AND REPOSITIONING OF THE HYDRAULIC SYSTEM ACCUMULATOR CHARGING DECALS, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-11-009 Airframe SB - N/A #3979	SPECIAL CHECK/MODIFICATION OF SPECIFIED AFT EQUIPMENT - COMPARTMENT DECALS, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-11-011 Airframe SB - N/A #3642	MODIFICATION - FLIGHT COMPARTMENT PLACARDS - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 96,000 LB (43,545 KG), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-11-013 Airframe SB - N/A #4264	MODIFICATION - DOORPLACARDS - ADDITION OF "CAUTION" MAINTENANCE PLACARD ON PASSENGER DOOR, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-11-014 Airframe SB - N/A #4226	MODIFICATION - EXTERIORPLACARDS AND MARKINGS - INTRODUCTION OF NEW PLACARD PART NO. KGC991-1124-3 FOR THE REFUEL/DEFUEL CONTROL PANEL, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-11-016 Airframe SB - Superseded #4581	MODIFICATION - GENERAL - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 98,000 LBS, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-11-016 R1 Airframe SB - Superseded #3835	MODIFICATION - GENERAL - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 98,000 LBS, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-11-016 R2 Airframe SB - Superseded #3573	MODIFICATION - GENERAL - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 98,000 LBS (A/C 9002 TO 9158), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-11-016 R3 Airframe SB - Superseded #3170	MODIFICATION - GENERAL - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 98,000 LBS (A/C 9002 TO 9158), SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-11-016 R4 Airframe SB - Superseded #3821	MODIFICATION - GENERAL - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 98,000 LBS (A/C 9002 TO 9158), SERVICE BULLETIN..	H: 0.00					
	Notes SUPERSEDED						
SB 700-11-016 R5 Airframe SB - N/A #4569	MODIFICATION - GENERAL - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 98,000 LBS, SERVICE BULLETIN..	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-11-017 Airframe SB - N/A #4572	MODIFICATION - JAPANESE AIRWORTHINESS REQUIREMENTS, SERVICE BULLETIN					07-NOV-2019	
SB 700-11-018 Airframe SB - Superseded #3156	OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-11-018 R1 Airframe SB - Superseded #3602	OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS (A/C 9002 TO 9999), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-11-018 R2 PART A Airframe SB - Complied With #789	OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS (A/C 9002 TO 9999), SERVICE BULLETIN.					23-JAN-2011 H: 0.00	
	Notes COMPLIED WITH - AT COMPLETION						



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-11-018 R3 PART A Airframe SB - Complied With #3932	ACCOMPLISH - OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS,- AIRCRAFT OPERATING AT AIRPORTS WITH A 74,955 LB (33,999 KG) MAXIMUM WEIGHT LIMITATION						
SB 700-11-018 R4 Airframe SB - Complied With #3458	OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS, SERVICE BULLETIN..						
SB 700-11-018 R5 Airframe SB - Complied With #4886	OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS						
	Notes C/W PER REV 2						
SB 700-11-020 Airframe SB - Superseded #3920	MODIFICATION - FLIGHT COMPARTMENT PLACARDS - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 99,500 LBS (CONTROLLED EFFECTIVITY), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-11-020 R1 Airframe SB - Complied With #688	MODIFICATION - FLIGHT COMPARTMENT PLACARDS - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 99,500 LBS (CONTROLLED EFFECTIVITY), SERVICE BULLETIN.	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
SB 700-11-021 Airframe SB - N/A #3339	MODIFICATION - EXTERIORPLACARDS AND MARKINGS - REPLACEMENT OF THE PRESSURE FUELING PLACARD ON THE REFUEL/DEFUEL DOOR AND THE PLACARDS AT THE WING GRAVITY FILLER CAPS (A/C 9002 TO 9205), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-11-023 PART B Airframe SB - Superseded #4415	MODIFICATION - INTERIORPLACARDS - INSTALLATION OF NEW PLACARDS TO PREVENT WATER SPILLAGE (9003 TO 9009, 9012 TO 9015, 9017, 9018, 9021, 9026 TO 9030, 9032, 9033, 9035, 9037, 9038, 9040, 9045, 9047, 9050 TO 9053, 9055, 9057 TO 9062, 9066, 9068 TO 907	H: 0.00					
	Notes SUPERSEDED						



ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-11-023 PART A Airframe SB - Superseded #4456	MODIFICATION - INTERIORPLACARDS - INSTALLATION OF NEW PLACARDS TO PREVENT WATER SPILLAGE (A/C 9002 TO 9106, 9108 TO 9122, 9124 TO 9126, 9128, 9129, 9133, 9134, 9136 TO 9139, 9141 TO 9148, 9150, 9151, 9153, 9159, 9162, 9163, 9165, 9167, 9169, 9171, 9	H: 0.00					
	Notes SUPERSEDED						
SB 700-11-023 R1 PART A Airframe SB - N/A #3673	MODIFICATION - INTERIORPLACARDS - INSTALLATION OF NEW PLACARDS TO PREVENT WATER SPILLAGE -INSTALLATION OF THE NO STORAGE PLACARDS, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-11-023 R1 PART B Airframe SB - N/A #3684	MODIFICATION - INTERIORPLACARDS - INSTALLATION OF NEW PLACARDS TO PREVENT WATER SPILLAGE -INSTALLATION OF THE OVERRIDE PLACARDS (APPLICABLE TO AIRCRAFT WHICH HAVE BURKERT VALVES PART NO. 452808A INSTALLED), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-11-024 Airframe SB - Superseded #3489	MODIFICATION - PLACARDS AND MARKINGS - MAXIMUM ZERO FUEL WEIGHT (MZFW) INCREASE OPTION TO 58,000 LB (26,308 KG), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-11-024 R1 Airframe SB - Superseded #4247	MODIFICATION - PLACARDS AND MARKINGS - MAXIMUM ZERO FUEL WEIGHT (MZFW) INCREASE OPTION TO 58,000 LB (26,308 KG), SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-11-024 R2 Airframe SB - Superseded #3609	MODIFICATION - PLACARDS AND MARKINGS - MAXIMUM ZERO FUEL WEIGHT (MZFW) INCREASE OPTION TO 58,000 LB (26,308 KG), SERVICE BULLETIN..	07-NOV-2019					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-11-024 R3 Airframe SB - Superseded #3934	MODIFICATION - PLACARDS AND MARKINGS - MAXIMUM ZERO FUEL WEIGHT (MZFW) INCREASE OPTION TO 58,000 LBS (26,308 KG), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 700-11-024 R4 Airframe SB - N/A #3686	MODIFICATION - PLACARDS AND MARKINGS - MAXIMUM ZERO FUEL WEIGHT (MZFW) INCREASE OPTION TO 58,000 LB (26,308 KG), SERVICE BULLETIN...	H: 0.00					
	Notes NOT APPLICABLE						
SB 700-11-025 Airframe SB - Open #3705	OPERATIONS TO AND FROM AUSTRALIAN AIRPORTS WITH MAXIMUM TAKE-OFF WEIGHT RESTRICTIONS IN EFFECT DURING CURFEW PERIODS, SERVICE BULLETIN	H: 0.00					
SB 700-11-026 Airframe SB - Open #3071	OPERATION AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS OF 95,000 LB (43, 091 KG), SERVICE BULLETIN	H: 0.00					
SB 700-11-6002 R4 Airframe SB - N/A #4938	MODIFICATION - FLIGHT COMPARTMENT PLACARDS -INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 99,500 LBS						
	Notes N/A PER S/N						
SB 700-20-002 PART A Airframe SB - N/A #4534	SPECIAL CHECK/REWORK/ MODIFICATION - WIRING - EXAMINE UNDERFLOORWIRE HARNESS AT FS265 FOR DAMAGE AND REROUTE, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-20-002 PART B Airframe SB - N/A #4025	SPECIAL CHECK/REWORK/ MODIFICATION - WIRING - EXAMINE UNDERFLOORWIRE HARNESS AT FS265 FOR DAMAGE AND REROUTE, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-20-003 PART A Airframe SB - N/A #3757	SPECIAL CHECK/REWORK - WIRES AND CABLES - REPLACEMENT OF TRANSITION ADAPTERS, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-20-003 PART B Airframe SB - N/A #3199	SPECIAL CHECK/REWORK - WIRES AND CABLES - REPLACEMENT OF TRANSITION ADAPTERS, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-21-001 Airframe SB - N/A #4517	MODIFICATION - MOISTURE CONTROL - INSTALLATION OF A CABIN HUMIDIFIERSYSTEM, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-21-020 Airframe SB - Open #4361	MODIFICATION - MOISTURE CONTROL INSTALLATION OF THE CABIN HUMIDIFICATION SYSTEM, SERVICE BULLETIN	H: 0.00					
SB 700-21-021 Airframe SB - N/A #4459	MODIFICATION - AIRCONDITIONING - AVIONICS COOLING FAN CHANGES, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-21-022 Airframe SB - N/A #4206	SPECIAL CHECK/MODIFICATION - TEMPERATURE CONTROL - INSPECT TRIM AIRCHECK VALVE FOR PREFORMED PACKING AND INSTALL IF MISSING, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-21-023 Airframe SB - N/A #3795	MODIFICATION - AIRCONDITIONING SYSTEM - INTRODUCTION OF AIR CONDITIONING SYSTEM CONTROLLER (ACSC) SOFTWARE VERSION L92131AR, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-21-024 Airframe SB - N/A #3862	MODIFICATION - CABIN-PRESSURE CONTROL SYSTEM - INTRODUCTION OF CABIN PRESSURE CONTROLLER(CPC) SOFTWARE VERSION 92129BM, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-21-026 Airframe SB - N/A #3112	MODIFICATION - VENTILATION - REPLACE FLIGHT COMPARTMENT AIRVENT DUCTS, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-21-027 Airframe SB - N/A #3101	MODIFICATION - CABIN-PRESSURE CONTROL SYSTEM - ADDITION OF A SELF-ADHESIVE DECAL AROUND THE EMERGENCY DEPRESSURIZATION SWITCH FOR VISIBLE DISTINCTION FROM OTHER SWITCHES IN CLOSE VICINITY, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-21-028 PART A Airframe SB - N/A #3314	SPECIAL CHECK/REWORK - CABIN PRESSURE CONTROL SYSTEM - INSPECT OUTFLOW VALVE SERIAL NUMBER AND REPLACE UNSATISFACTORY UNITS THAT HAVE POOR ELECTRICAL CONTACT ON ACTUATOR MOTHERBOARD, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-21-028 PART B Airframe SB - N/A #4049	SPECIAL CHECK/REWORK - CABIN PRESSURE CONTROL SYSTEM - INSPECT OUTFLOW VALVE SERIAL NUMBER AND REPLACE UNSATISFACTORY UNITS THAT HAVE POOR ELECTRICAL CONTACT ON ACTUATOR MOTHERBOARD, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-21-029 Airframe SB - N/A #3702	MODIFICATION - MOISTURE CONTROL - UPGRADE OF THE HUMIDIFIER SYSTEM FOR AIRCRAFT POST SB 700-21-001 OR SB 700-21-020, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-21-030 Airframe SB - N/A #4473	MODIFICATION - MOISTURE CONTROL - INSTALLATION OF THE PROVISIONS FOR THE NEW AND IMPROVED CABIN HUMIDIFIER SYSTEM, PART NO. GG432-2105-11 (A/C 9002 TO 9166), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-21-031 Airframe SB - N/A #3637	MODIFICATION - MOISTURE CONTROL - FINAL INSTALLATION FOR THE NEW AND IMPROVED CABIN HUMIDIFIER SYSTEM, PART NO. GG432-2105-11 (A/C 9002 TO 9166), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-21-034 Airframe SB - Superseded #3747	MODIFICATION - PRESSURIZATION CONTROL - CABIN ALTITUDE REDUCTION DURING FLIGHT FOR IMPROVED PASSENGER COMFORT (A/C 9002 TO 9158), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-21-034 R1 Airframe SB - N/A #4150	MODIFICATION - PRESSURIZATION CONTROL - CABIN ALTITUDE REDUCTION DURING FLIGHT FOR IMPROVED PASSENGER COMFORT (A/C 9002 TO 9158), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-21-035 Airframe SB - Superseded #3657	MODIFICATION - INTERNAL DISTRIBUTION - ADDITION OF ICE FILTER ASSEMBLIES AT THE MIX MANIFOLD (A/C 9002 TO 9355), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-21-035 R1 Airframe SB - N/A #4309	MODIFICATION - INTERNAL DISTRIBUTION - ADDITION OF ICE FILTER ASSEMBLIES AT THE MIX MANIFOLD, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-21-036 Airframe SB - N/A #3786	MODIFICATION - PRESSURIZATION CONTROL - CABIN ALTITUDE REDUCTION DURING FLIGHT FORIMPROVED PASSENGER COMFORT (A/C 9159 TO 9174), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-21-041 PART A Airframe SB - N/A #4283	SPECIAL CHECK/MODIFICATION - CABIN-PRESSURE CONTROL SYSTEM - INSTALLATION OF NEW ACOUSTIC SHIELD ON FORWARD OUTFLOW VALVE TO EASE ACCESS (A/C 9002 TO 9159), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-21-041 PART B Airframe SB - N/A #3881	SPECIAL CHECK/MODIFICATION - CABIN-PRESSURE CONTROL SYSTEM - INSTALLATION OF NEW ACOUSTIC SHIELD ON FORWARD OUTFLOW VALVE TO EASE ACCESS (A/C 9002 TO 9159), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-21-049 PART A Airframe SB - Superseded #3182	MODIFICATION - MOISTURE CONTROL - AUTOMATION OF THE CABIN HUMIDIFICATION SYSTEM (A/C 9002 TO 9999), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-21-049 PART B Airframe SB - Superseded #4077	MODIFICATION - MOISTURE CONTROL - AUTOMATION OF THE CABIN HUMIDIFICATION SYSTEM (A/C 9002 TO 9999), SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-21-049 R1 PART A Airframe SB - Open #4214	MODIFICATION - MOISTURE CONTROL - AUTOMATION OF THE CABIN HUMIDIFICATION SYSTEM (A/C 9002 TO 9999), SERVICE BULLETIN..	H: 0.00					
SB 700-21-049 R1 PART B Airframe SB - Open #3457	MODIFICATION - MOISTURE CONTROL - AUTOMATION OF THE CABIN HUMIDIFICATION SYSTEM (A/C 9002 TO 9999), SERVICE BULLETIN...	H: 0.00					

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-21-050 Airframe SB - N/A #4248	MODIFICATION - HUMIDIFIERSYSTEM - INSTALLATION OF NEW AND IMPROVED CABIN HUMIDIFICATION SYSTEM WITH AUTOMATED CONTROL (A/C 9159 TO 9999), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-21-050 R1 Airframe SB - Open #3162	MODIFICATION - HUMIDIFIERSYSTEM - INSTALLATION OF NEW AND IMPROVED CABIN HUMIDIFICATION SYSTEM WITH AUTOMATED CONTROL, SERVICE BULLETIN	H: 0.00					
SB 700-21-051 Airframe SB - N/A #3823	MODIFICATION - HUMIDIFIERSYSTEM - INSTALLATION OF THE NEW CABIN HUMIDIFICATION SYSTEM WITH AUTOMATED CONTROL, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-21-052 Airframe SB - Complied With #1582	MODIFICATION - TEMPERATURE CONTROL - REPLACE SUSPECT PACKINGS AT HOT-AIRCHECK VALVE, SERVICE BULLETIN	12-SEP-2012 H: 388.37 L: 190					
	Notes COMPLIED WITH						
SB 700-21-054 Airframe SB - Open #4795	MODIFICATION – PASSENGER COMPARTMENT AND AIR DISTRIBUTION SYSTEM – MODIFICATION OF AIR GASPERS FOR NOISE REDUCTION						
SB 700-21-055 Airframe SB - Open #4707	MODIFICATION - TEMPERATURE CONTROL - REPLACEMENT OF TRIM AIR VALVES PART NO. GG436-2038-5 WITH GG436-2038-7						
SB 700-21-056 Airframe SB - Complied With #4848	MODIFICATION - TEMPERATURE CONTROL - REPLACEMENT OF THE AIR-CONDITIONING SYSTEM CONTROLLER (ACSC)	27-NOV-2019 H: 3575.60 L: 1184					
SB 700-21-056 R1 Airframe SB - Complied With #4873	MODIFICATION - TEMPERATURE CONTROL - REPLACEMENT OF THE AIR-CONDITIONING SYSTEM CONTROLLER (ACSC) (REV. 1)	27-NOV-2019 H: 3575.60 L: 1184					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-22-001 Airframe SB - N/A #3806	MODIFICATION - YAW DAMPER SYSTEM - YAW DAMPER BACKDRIVE IMPROVEMENT, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-22-002 Airframe SB - Superseded #3753	MODIFICATION - AUTOPILOT SYSTEM - ADDITION OF PROTECTIVE FOD SHIELD TO AILERON AUTOPILOT SERVO, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-22-002 R1 Airframe SB - N/A #3443	MODIFICATION - AUTOPILOT SYSTEM - ADDITION OF PROTECTIVE FOD SHIELD TO AILERON AUTOPILOT SERVO (A/C 9002 AND 9004 TO 9080), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-22-003 Airframe SB - Superseded #3499	MODIFICATION - GENERAL - INTRODUCTION OF THE AUTOPILOT EMERGENCY DESCENT MODE, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-22-003 R1 Airframe SB - Complied With #579	MODIFICATION - AUTOMATIC FLIGHT-CONTROL SYSTEM (AFCS) - INTRODUCTION OF THE AUTOPILOT EMERGENCY DESCENT MODE, SERVICE BULLETIN	23-JAN-2014 H: 649.70 L: 284					
	Notes COMPLIED WITH						
SB 700-22-005 Airframe SB - Superseded #3347	MODIFICATION - AUTOMATIC FLIGHT CONTROL SYSTEM (AFCS) - INTRODUCTION OF WINDSHEARESCAPE GUIDANCE, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-22-005 R1 Airframe SB - Complied With #1453	MODIFICATION - AUTOMATIC FLIGHT CONTROL SYSTEM (AFCS) - INTRODUCTION OF WINDSHEARESCAPE GUIDANCE, SERVICE BULLETIN	23-JAN-2014 H: 649.70 L: 284					
	Notes COMPLIED WITH						
SB 700-22-006 PART A Airframe SB - Complied With #4014	INSPECTION - SPECIAL CHECK/MODIFICATION - AUTOPILOT SYSTEM - AILERON AND ELEVATORAUTOPILOT SERVO CABLE KEEPER WEAR,-OF THE CABLE KEEPERS AND MODIFICATION OF THE AILERON SERVO CABLE TENSION	03-MAR-2016 H: 1753.70 L: 622					
SB 700-22-006 PART B Airframe SB - Complied With #4611	INSPECTION - SPECIAL CHECK/MODIFICATION - AUTOPILOT SYSTEM - AILERON AND ELEVATORAUTOPILOT SERVO CABLE KEEPER WEAR,-OF THE CABLE KEEPERS AND MODIFICATION OF THE ELEVATOR SERVO CABLE TENSION	03-MAR-2016 H: 1753.70 L: 622					
SB 700-22-006 Airframe SB - Complied With #4574	SPECIAL CHECK/MODIFICATION - AUTOPILOT SYSTEM - AILERON AND ELEVATORAUTOPILOT SERVO CABLE KEEPER WEAR, SERVICE BULLETIN	04-MAR-2016 H: 1753.70 L: 622					
SB 700-23-001 Airframe SB - N/A #4153	MODIFICATION - SATELLITE COMMUNICATIONS (SATCOM) SYSTEM - INSTALLATION (9002 TO 9139), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-23-002 Airframe SB - Superseded #4070	MODIFICATION - THIRD VERY HIGH FREQUENCY (VHF 3) COMMUNICATION SYSTEM - INSTALLATION, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-23-002 R1 Airframe SB - Superseded #4318	MODIFICATION - THIRD VERY HIGH FREQUENCY (VHF 3) COMMUNICATION SYSTEM - INSTALLATION (A/C 9002 TO 9999), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-23-002 R2 Airframe SB - Complied With #407	MODIFICATION - THIRD VERY HIGH FREQUENCY (VHF 3) COMMUNICATION SYSTEM - INSTALLATION, SERVICE BULLETIN.	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
SB 700-23-003 Airframe SB - Superseded #3295	MODIFICATION - CABIN COMMUNICATION SYSTEM (CCS) - "OFFICE IN THE SKY" INSTALLATION, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-23-003 R1 Airframe SB - N/A #3625	MODIFICATION - CABIN COMMUNICATION SYSTEM (CCS) - "OFFICE IN THE SKY" INSTALLATION, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-23-004 Airframe SB - Superseded #4412	MODIFICATION - FLIGHT COMPARTMENT PRINTER- INSTALLATION, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-23-004 R1 Airframe SB - Superseded #3966	MODIFICATION - FLIGHT COMPARTMENT PRINTER- INSTALLATION, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-23-004 R2 Airframe SB - Complied With #1446	MODIFICATION - FLIGHT COMPARTMENT PRINTER- INSTALL, SERVICE BULLETIN	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-23-005 Airframe SB - Superseded #3364	MODIFICATION - AIRBORNE DATA LINK SYSTEM (ADLS) - INSTALLATION, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-23-005 R1 Airframe SB - Superseded #3769	MODIFICATION - AIRBORNE DATA LINK SYSTEM (ADLS) - INSTALLATION, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-23-005 R2 Airframe SB - Complied With #1905	MODIFICATION - AIRBORNE DATA LINK SYSTEM (ADLS) - INSTALLATION, SERVICE BULLETIN..	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
SB 700-23-012 Airframe SB - N/A #4315	MODIFICATION - AUDIO INTEGRATING SYSTEM - INTERCOM CAPABILITY ADDED TO THE PILOT AND COPILOT PUSH-TO-TALK (PTT) SWITCH FORFULL FUNCTIONALITY, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-23-013 Airframe SB - N/A #4027	MODIFICATION - HF COMMUNICATION SYSTEM - ADDITION OF WIRE HARNESS SUPPORT TO PREVENT FOULING WITH ADJACENT FUEL LINE, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-23-014 Airframe SB - N/A #3682	MODIFICATION - CABIN COMMUNICATION SYSTEM - ENABLE GPWS AURAL MESSAGES TO THE THIRD CREW AUDIO CONTROL PANEL, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-23-015 Airframe SB - Open #4523	MODIFICATION - AIRBORNE DATA LINK SYSTEM (ADLS) - SOFTWARE UPGRADE OF THE ADLU TO PART NO. 8400021-01, SERVICE BULLETIN	H: 0.00					





Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-23-017 PART A Airframe SB - N/A #3661	AUDIO AND VIDEO MONITORING - CHECK FORMHT REMOTE UNIT APPLICABILITY, SERVICE BULLETIN Notes SUPERSEDED	H: 0.00					
SB 700-23-017 PART B Airframe SB - N/A #3430	AUDIO AND VIDEO MONITORING - MODIFICATION - INSTALLATION OF MODIFIED MHT REMOTE UNITS, SERVICE BULLETIN Notes SUPERSEDED	H: 0.00					
SB 700-23-017 R1 Airframe SB - N/A #4444	SPECIAL CHECK/MODIFICATION - AUDIO AND VIDEO MONITORING - CHECK FORMHT REMOTE UNITS THAT ARE NOT MODIFIED (CAN CAUSE A SQUELCH BREAK ANOMALY) AND INSTALLATION OF MODIFIED MHT REMOTE UNITS, SERVICE BULLETIN Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					
SB 700-23-019 Airframe SB - Open #3896	MODIFICATION - CABIN COMMUNICATION SYSTEM - "OFFICE IN THE SKY" INSTALLATION ON AIRCRAFT WITH PROVISIONS, SERVICE BULLETIN	H: 0.00					
SB 700-23-027 Airframe SB - N/A #4265	MODIFICATION - CABIN COMMUNICATION SYSTEM - INSTALLATION OF NEW BACKLIT TELEPHONE HANDSET, SERVICE BULLETIN Notes N/A PER S/N	H: 0.00					
SB 700-23-029 Airframe SB - N/A #4552	MODIFICATION - SATELLITE COMMUNICATIONS SYSTEM INSTALLATION OF PROVISIONS FORINMARSAT SWIFT BROADBAND HIGH SPEED SERVICE, SERVICE BULLETIN Notes N/A PER S/N ON SB700-23-029 CESB S/N NOT LISTED	H: 0.00					
SB 700-23-033 Airframe SB - N/A #3239	MODIFICATION - VOICE RECORDERSYSTEM - INSTALLATION OF RECORDER INDEPENDENT POWER SUPPLY (RIPS) FOR COCKPIT VOICE RECORDER (CVR), SERVICE BULLETIN Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-23-034 Airframe SB - Superseded #3870	MODIFICATION - SATELLITE COMMUNICATIONS SYSTEM INSTALLATION OF INMARSAT SWIFT BROADBAND HIGH SPEED SERVICE, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-23-034 R1 Airframe SB - Superseded #3441	MODIFICATION - SATELLITE COMMUNICATIONS SYSTEM - INSTALLATION OF INMARSAT SWIFT BROADBAND HIGH SPEED SERVICE, SERVICE BULLETIN	H: 0.00					
SB 700-23-034 R2 Airframe SB - N/A #3	MODIFICATION – SATELLITE COMMUNICATIONS SYSTEM – INSTALLATION OF INMARSAT SWIFTBROADBAND HIGH SPEED SERVICE (REV. 2)						
	Notes N/A PER S/N AS LISTED IN SB700-23-034 CESB S/N MNOT LISTED						
SB 700-23-037 Airframe SB - Superseded #4160	MODIFICATION - VOICE RECORDING SYSTEM - UPGRADE THE COCKPIT VOICE RECORDERSYSTEM TO STORE DATALINK MESSAGES, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-23-037 R1 Airframe SB - Complied With #1671	MODIFICATION - VOICE RECORDERSYSTEM - UPGRADE THE COCKPIT VOICE RECORDER SYSTEM TO STORE DATALINK MESSAGES, SERVICE BULLETIN	25-JAN-2014 H: 649.70 L: 284					
	Notes COMPLIED WITH						
SB 700-23-037 R2 Airframe SB - N/A #4799	MODIFICATION - VOICE RECORDER SYSTEM - UPGRADE THE COCKPIT VOICE RECORDER SYSTEM TO STORE DATALINK MESSAGES (REV. 2)						
	Notes PREVIOUSLY COMPLIED WITH ON REV 1						
SB 700-23-037 R3 Airframe SB - N/A #4885	MODIFICATION - VOICE RECORDER SYSTEM - UPGRADE THE COCKPIT VOICE RECORDER SYSTEM TO STORE DATALINK MESSAGES						
	Notes PREVIOUSLY COMPLIED WITH ON REV 1						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-23-039 Airframe SB - N/A #3348	ICA - MODIFICATION - AUDIO INTEGRATING SYSTEM - INTRODUCTION OF INTERCOM CAPABILITY ADDED TO THE PILOT AND COPILOT PUSH-TO-TALK (PTT) SWITCH FORFULL FUNCTIONALITY, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
SB 700-23-039 R1 PART A Airframe SB - N/A #4275	AIRCRAFT - ICA - MODIFICATION - AUDIO INTEGRATING SYSTEM - INTRODUCTION OF INTERCOM CAPABILITY ADDED TO THE PILOT AND COPILOT PUSH-TO-TALK (PTT) SWITCH FORFULL FUNCTIONALITY, MODIFICATION	H: 0.00					
	Notes NOT APPLICABLE						
SB 700-23-039 R1 PART B Airframe SB - N/A #3850	AIRCRAFT - ICA - MODIFICATION - AUDIO INTEGRATING SYSTEM - INTRODUCTION OF INTERCOM CAPABILITY ADDED TO THE PILOT AND COPILOT PUSH-TO-TALK (PTT) SWITCH FORFULL FUNCTIONALITY,-SETUP	H: 0.00					
	Notes NOT APPLICABLE						
SB 700-23-039 R1 Airframe SB - N/A #3522	ICA - MODIFICATION - AUDIO INTEGRATING SYSTEM - INTRODUCTION OF INTERCOM CAPABILITY ADDED TO THE PILOT AND COPILOT PUSH-TO-TALK (PTT) SWITCH FORFULL FUNCTIONALITY, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE						
SB 700-23-040 Airframe SB - Superseded #4683	MODIFICATION - CABIN COMMUNICATION SYSTEM - REPLACEMENT OF CORDLESS HANDSET ASSEMBLY						
	Notes SUPERSEDED BY REV 1						
SB 700-23-040 R1 Airframe SB - Superseded #4855	MODIFICATION - CABIN COMMUNICATION SYSTEM - REPLACEMENT OF CORDLESS HANDSET ASSEMBLY (REV. 1)						
	Notes SUPERSEDED BY REV 2						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-23-040 R2 Airframe SB - Open #4863	MODIFICATION - CABIN COMMUNICATION SYSTEM - REPLACEMENT OF CORDLESS HANDSET ASSEMBLY (REV. 2)						
SB 700-23-041 Airframe SB - Superseded #3532	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INTRODUCTION OF HONEYWELL JETWAVE KA-BAND RADOME FAIRING, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED BY REV 1						
SB 700-23-041 R1 Airframe SB - Superseded #4758	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INTRODUCTION OF HONEYWELL JETWAVE™ KA-BAND RADOME FAIRING (REV. 1)						
	Notes SUPERSEDED BY REV 2						
SB 700-23-041 R2 Airframe SB - Complied With #4827	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INTRODUCTION OF HONEYWELL JETWAVE KA-BAND RADOME FAIRING (REV. 2)						
		29-JAN-2018					
		H: 2586.20					
		L: 898					
SB 700-23-041 R3 Airframe SB - N/A #4853	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INTRODUCTION OF HONEYWELL JETWAVE™ KA-BAND RADOME FAIRING (REV. 3)						
	Notes PREVIOUSLY COMPLIED WITH PER REV 2						
SB 700-23-042 Airframe SB - Open #4808	MODIFICATION - CABIN COMMUNICATION SYSTEM - REPLACEMENT OF ICS 100/200 SERIES IRIDIUM TRANSCEIVER WITH ICS 120/220 A/AF/B/BF SERIES IRIDIUM TRANSCEIVER						
SB 700-23-043 Airframe SB - Superseded #4802	MODIFICATION - SATELLITE COMMUNICATIONS SYSTEM - UPGRADE TO HONEYWELL MCS-7000 SATCOM						
	Notes SUPERSEDED BY REV 2						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-23-043 R1 Airframe SB - N/A #4809	MODIFICATION -SATELLITE COMMUNICATIONS SYSTEM -UPGRADE TO HONEYWELL MCS-7000 SATCOM (REV. 1) Notes N/A PER SB700-23-043 REV 1 S/N NOT LISTED IN CESB						
SB 700-23-045 Airframe SB - N/A #4918	MODIFICATION - CABIN COMMUNICATION SYSTEM - DEACTIVATION OF OFFICE IN THE SKY UHF Notes N/A PER SB700-23-045 CESB S/N NOT LISTED						
SB 700-23-046 Airframe SB - Open #4952	MODIFICATION - CABIN COMMUNICATION SYSTEM - SIGMA 7 HANDSETS REPLACEMENT						
SB 700-23-046 R01 Airframe SB - Open #5084	MODIFICATION - CABIN COMMUNICATION SYSTEM - SIGMA 7 HANDSETS REPLACEMENT						
SB 700-24-029 Airframe SB - N/A #4072	MODIFICATION - ELECTRICAL MANAGEMENT SYSTEM (EMS) - CONTROL AND DISPLAY UNIT (CDU) REPLACEMENT, SERVICE BULLETIN Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					
SB 700-24-030 Airframe SB - N/A #3148	SPECIAL CHECK - AC POWERCENTER (ACPC) - POSSIBLE CRACKING ON ACPC CHASSIS, SERVICE BULLETIN Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					
SB 700-24-031 Airframe SB - N/A #3315	MODIFICATION - DC POWERCENTER (DCPC) - DCPC BLOCK 1A OR 1A+ HARDWARE MODIFICATION FOR BLOCK 2, SERVICE BULLETIN Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-24-032 Airframe SB - N/A #3247	MODIFICATION - SECONDARY POWERDISTRIBUTION - SECONDARY POWER DISTRIBUTION ASSEMBLY (SPDA) UNIT REPLACEMENT, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-033 Airframe SB - N/A #3915	MODIFICATION - SECONDARY POWERDISTRIBUTION - APU STARTER CONTACTOR ASSEMBLY (ASCA) HARDWARE MODIFICATION FOR BLOCK 2, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-034 Airframe SB - N/A #3288	MODIFICATION - AC-POWERCENTER (ACPC) - ACPC BLOCK 1A OR 1A+ HARDWARE MODIFICATION FOR BLOCK 2, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-036 Airframe SB - N/A #3109	MODIFICATION - COCKPIT CIRCUIT BREAKER PANEL - RELOCATION OF WIRING AC BUS 1 AND AC BUS 3, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-037 PART A Airframe SB - N/A #3453	MODIFICATION - BATTERY SYSTEM - REMOVAL OF APU BATTERY SUMP JARAND ACCESS IMPROVEMENT TO THE APU BATTERY CONNECTOR, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-037 PART B Airframe SB - N/A #3353	MODIFICATION - BATTERY SYSTEM - REMOVAL OF APU BATTERY SUMP JARAND ACCESS IMPROVEMENT TO THE APU BATTERY CONNECTOR, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-24-038 Airframe SB - N/A #3253	MODIFICATION - EXTERNAL AC POWER- ELIMINATE STRESS ON AC POWER RECEPTACLE, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-040 Airframe SB - N/A #3212	MODIFICATION - SECONDARY POWERDISTRIBUTION - INCREASED FUSE RATING FOR THE APU START-CONTACTOR ASSEMBLY (ASCA), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-041 Airframe SB - N/A #4054	MODIFICATION - ELECTRICAL POWER- BUILD 4 CABIN WIRING PROVISION, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-042 Airframe SB - N/A #4589	MODIFICATION - EMERGENCY AC-POWERSUPPLY - RESOLUTION OF RAT GENERATOR OVERRIDE ANOMALY, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-043 PART A Airframe SB - N/A #4488	SPECIAL CHECK/MODIFICATION - GENERAL - VISUAL CHECK OF THE EMS CDU, ACPC, DCPC AND SPDA PART NUMBER/SERIAL NUMBERAND REPLACEMENT/MODIFICATION OF THE UNITS IDENTIFIED TO CONTAIN DEFECTIVE TRANSCEIVER MICROCIRCUITS, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-043 PART B Airframe SB - N/A #4445	SPECIAL CHECK/MODIFICATION - GENERAL - VISUAL CHECK OF THE EMS CDU, ACPC, DCPC AND SPDA PART NUMBER/SERIAL NUMBERAND REPLACEMENT/MODIFICATION OF THE UNITS IDENTIFIED TO CONTAIN DEFECTIVE TRANSCEIVER MICROCIRCUITS, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-24-044 Airframe SB - Superseded #3644	SPECIAL CHECK - DC POWERCENTER (DCPC) - CHECK FOR FOD INSIDE THE DC POWER CENTER (DCPC), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-24-044 R1 Airframe SB - N/A #4367	SPECIAL CHECK - DC POWERCENTER (DCPC) - CHECK FOR FOD INSIDE THE DC POWER CENTER (DCPC), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-045 Airframe SB - Superseded #3860	MODIFICATION - AC AND DC POWERDISTRIBUTION - UNIT CHANGE AND ACTIVATION OF BUILD 4 ELECTRICAL SYSTEM, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-24-045 R1 PART 1 Airframe SB - Superseded #4342	MODIFICATION - AC AND DC POWERDISTRIBUTION - UNIT CHANGE AND ACTIVATION OF BUILD 4 ELECTRICAL SYSTEM, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-24-045 R1 PART 2 Airframe SB - Superseded #3895	MODIFICATION - AC AND DC POWERDISTRIBUTION - UNIT CHANGE AND ACTIVATION OF BUILD 4 ELECTRICAL SYSTEM, SERVICE BULLETIN..	H: 0.00					
	Notes SUPERSEDED						
SB 700-24-045 R2 PART 2 Airframe SB - N/A #4219	MODIFICATION - AC AND DC POWERDISTRIBUTION - UNIT CHANGE AND ACTIVATION OF BUILD 4 ELECTRICAL SYSTEM - (RETROACTIVE ACTION), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-24-045 R2 PART 1 Airframe SB - N/A #3382	MODIFICATION - AC AND DC POWERDISTRIBUTION - UNIT CHANGE AND ACTIVATION OF BUILD 4 ELECTRICAL SYSTEM, SERVICE BULLETIN...	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-046 Airframe SB - N/A #3646	SPECIAL CHECK/REWORK - BATTERY SYSTEM - INSPECT AVIONICS BATTERY WIRE LUGS AND REPLACE, IF NECESSARY, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-047 Airframe SB - N/A #4614	MODIFICATION - ELECTRICAL CONTROL - CENTRAL AIRCRAFT-INFORMATION MAINTENANCE-SYSTEM (CAIMS) SOFTWARE FORGENERATOR CONTROL UNIT (GL511-3103), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-048 Airframe SB - N/A #3749	SPECIAL CHECK/REWORK - EMERGENCY AC-POWERSUPPLY - REPLACEMENT OF THE RAT LINE CONTACTOR (RATLC), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-049 Airframe SB - Superseded #3525	MODIFICATION - SECONDARY POWERDISTRIBUTION - APU STARTER CONTACTOR ASSEMBLY (ASCA) ACCESS IMPROVEMENT, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-24-049 R1 Airframe SB - N/A #3600	MODIFICATION - SECONDARY POWERDISTRIBUTION - APU STARTER CONTACTOR ASSEMBLY (ASCA) ACCESS IMPROVEMENT, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-24-050 Airframe SB - Superseded #4592	MODIFICATION - BATTERY SYSTEM - RE-ROUTING OF THE APU BATTERY VENT TUBE TO IMPROVE VENTILATION OF THE APU BATTERY GASES, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-24-050 R1 Airframe SB - N/A #3266	MODIFICATION - BATTERY SYSTEM - RE-ROUTING OF THE APU BATTERY VENT TUBE TO IMPROVE VENTILATION OF THE APU BATTERY GASES (A/C 9002 TO 9149), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-051 PART A Airframe SB - N/A #3745	SPECIAL CHECK/REWORK - DC POWERCONVERSION - VERIFICATION OF ELECTRICAL TERMINAL LUGS INSTALLED ON THE AUXILIARY (AUX) TRANSFORMER RECTIFIER UNIT (TRU) WIRES AND REWORK OF THE POWER FEEDERS TO THE CABIN TRU BUS, SERVICE BULLETIN	H: 0.00					
	Notes N/A BY EFFECTIVELY						
SB 700-24-051 PART B Airframe SB - N/A #3557	SPECIAL CHECK/REWORK - DC POWERCONVERSION - VERIFICATION OF ELECTRICAL TERMINAL LUGS INSTALLED ON THE AUXILIARY (AUX) TRANSFORMER RECTIFIER UNIT (TRU) WIRES AND REWORK OF THE POWER FEEDERS TO THE CABIN TRU BUS, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-051 PART C Airframe SB - N/A #3670	SPECIAL CHECK/REWORK - DC POWERCONVERSION - VERIFICATION OF ELECTRICAL TERMINAL LUGS INSTALLED ON THE AUXILIARY (AUX) TRANSFORMER RECTIFIER UNIT (TRU) WIRES AND REWORK OF THE POWER FEEDERS TO THE CABIN TRU BUS, SERVICE BULLETIN..	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-052 Airframe SB - N/A #3501	MODIFICATION - BATTERY SYSTEM - ADDITION OF A SPIGOT TO THE APU BATTERY VENT FITTING TO PREVENT FUEL FROM ENTERING THE BATTERY CASE, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-24-053 Airframe SB - N/A #3159	MODIFICATION - BATTERY SYSTEM - COOLING INSTALLATION FOR THE FORWARD EQUIPMENT COMPARTMENT (A/C EFFECTIVITY : S/N 9002 TO 9164), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-054 Airframe SB - N/A #3110	SPECIAL CHECK/REWORK/MODIFICATION - DC POWER CONVERSION - TRU 2 FEEDER WIRE CHAFING (EFFECTIVITY A/C S/N 9002 TO 9070, 9126, 9128, 9129, 9131 TO 9139, 9141 TO 9148, 9150, 9151, 9153, 9159 AND 9162), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-056 Airframe SB - Superseded #3599	MODIFICATION - BATTERY SYSTEM - DEACTIVATION OF THE AUXILIARY POWER UNIT (APU) AND AVIONICS BATTERY HEATER BLANKETS, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-24-056 R1 Airframe SB - N/A #3146	MODIFICATION - BATTERY SYSTEM - DEACTIVATION OF THE AUXILIARY POWER UNIT (APU) AND AVIONICS BATTERY HEATER BLANKETS (A/C 9002 TO 9126, 9128, 9129, 9131 TO 9189), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-057 Airframe SB - N/A #4298	MODIFICATION - PRIMARY AC-POWER SUPPLY - UPGRADE VARIABLE FREQUENCY GENERATOR FROM PART NUMBER GL511-1103-1 TO GL511-1103-5 (A/C 9002 TO 9108), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-059 Airframe SB - N/A #4201	SPECIAL CHECK/MODIFICATION - ELECTRICAL CONTROL - VISUAL CHECK OF THE SERIAL NUMBER FOR THE GENERATOR CONTROL UNIT (GCU), P/N GL511-3104-1 AND REPLACEMENT OF THE AFFECTED UNITS (EFFECTIVITY 9117, 9154, 9161 TO 9167, 9169 AND 9172), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-24-061 Airframe SB - N/A #3450	MOD - AC AND DC POWERDISTRIBUTION - BUILD 6.0 ELECTRICAL SYSTEM UPGRADE (A/C S/N 9149 TO 9169), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-062 Airframe SB - Superseded #4162	MODIFICATION - AC AND DC POWERDISTRIBUTION - REPLACEMENT OF UNITS FOR ACTIVATION OF BUILD 6.0 UPGRADE, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-24-062 R1 Airframe SB - N/A #3712	MODIFICATION - AC AND DC POWERDISTRIBUTION - REPLACEMENT OF UNITS FOR ACTIVATION OF BUILD 6.0 UPGRADE (A/C 9002 TO 9148), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-063 Airframe SB - N/A #3520	MODIFICATION - AC AND DC POWERDISTRIBUTION - ACPC AND DCPC IMPROVEMENTS (A/C 9002 TO 9148), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-24-063 R1 Airframe SB - N/A #4487	MODIFICATION - AC AND DC POWERDISTRIBUTION - ACPC AND DCPC IMPROVEMENTS (A/C 9002 TO 9148), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-065 Airframe SB - N/A #3423	MODIFICATION - COCKPIT CIRCUIT-BREAKERPANEL (CCBP) AC CIRCUITS - REWORK OF THE CCBP FOR THE ENHANCED VISION SYSTEM (EVS).-EFFECTIVITY S/N 9002 TO 9156., SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-24-066 Airframe SB - Superseded #3813	MODIFICATION - BATTERY SYSTEM - UPGRADE BATTERY CHARGERS TO PART NO. GL511-2401-9 (A/C 9002 TO 9193), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-24-066 R1 Airframe SB - N/A #3185	MODIFICATION - BATTERY SYSTEM - UPGRADE BATTERY CHARGERS TO PART NO. GL511-2401-9, RECOMMENDED	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-067 Airframe SB - N/A #4231	MODIFICATION - AC POWERCENTER (ACPC) - REPLACE DEFECTIVE AC TO DC CONVERTER ASSEMBLY (A/C 9149 TO 9169 POST SB 700-24-061 BASIC ISSUE, A/C 9002 TO 9149 POST SB 700-24-063 BASIC ISSUE, AND A/C 9170 TO 9218), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-068 PART A Airframe SB - Superseded #3659	MODIFICATION - EMERGENCY AC POWERSUPPLY - REPLACE RAM AIR TURBINE (RAT) WITH DEFECTIVE BEARING SHIELD (A/C 9002 TO 9234), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-24-068 PART B Airframe SB - Superseded #3069	MODIFICATION - EMERGENCY AC POWERSUPPLY - REPLACE RAM AIR TURBINE (RAT) WITH DEFECTIVE BEARING SHIELD (A/C 9002 TO 9234), SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-24-068 R1 Airframe SB - N/A #4376	ICA - MODIFICATION - EMERGENCY AC POWERSUPPLY - REPLACE RAM AIR TURBINE (RAT) WITH DEFECTIVE BEARING SHIELD, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-24-069 Airframe SB - N/A #3209	MODIFICATION - EMERGENCY AC POWERSUPPLY - REPLACE UPLOCK ROLLER ASSEMBLY ON RAM AIR TURBINE (RAT) (A/C 9180 TO 9259), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-070 Airframe SB - N/A #4336	MODIFICATION - DC ELECTRICAL LOAD DISTRIBUTION - REROUTE WIRING TO SUPPLY CABIN POWERIN GROUND SERVICE MODE, SERVICE BULLETIN	H: 0.00					
	Notes N/A PER S/N						
SB 700-24-071 PART A Airframe SB - Superseded #3984	REWORK - GENERAL - PREVENTION OF FOULING BETWEEN WIRE HARNESS FROM CONNECTORJ666 AND FUEL VENT LINE, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-24-071 PART B Airframe SB - Superseded #3952	REWORK - GENERAL - PREVENTION OF FOULING BETWEEN WIRE HARNESS FROM CONNECTORJ666 AND FUEL VENT LINE, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-24-071 R1 Airframe SB - Superseded #3956	REWORK - GENERAL - PREVENTION OF FOULING BETWEEN WIRE HARNESS FROM CONNECTORJ666 AND FUEL VENT LINE, SERVICE BULLETIN..	H: 0.00					
	Notes SUPERSEDED						
SB 700-24-071 R1 PART A Airframe SB - Superseded #3648	REWORK - REWORK - GENERAL - PREVENTION OF FOULING BETWEEN WIRE HARNESS FROM CONNECTORJ666 AND FUEL VENT LINE,- GENERAL PREVENTION OF FOULING BETWEEN WIRE HARNESS FROM CONNECTOR J666 AND FUEL VENT LINE	H: 0.00					
	Notes SUPERSEDED						

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-24-071 R1 PART B Airframe SB - Superseded #4093	REWORK - REWORK - GENERAL - PREVENTION OF FOULING BETWEEN WIRE HARNESS FROM CONNECTORJ666 AND FUEL VENT LINE,- GENERAL PREVENTION OF FOULING BETWEEN WIRE HARNESS FROM CONNECTOR J666 AND FUEL VENT LINE.	H: 0.00					
	Notes SUPERSEDED						
SB 700-24-071 R2 Airframe SB - N/A #4474	ICA - REWORK - GENERAL - PREVENTION OF FOULING BETWEEN WIRE HARNESS FROM CONNECTORJ666 AND FUEL VENT LINE, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-074 Airframe SB - N/A #4223	MODIFICATION - POWERCONVERTER SYSTEM - INSTALLATION OF A NEW FUSE IN THE FREQUENCY GENERATOR OUTPUT LINE, SERVICE BULLETIN	H: 0.00					
	Notes N/A PER S/N						
SB 700-24-075 PART A Airframe SB - Superseded #4378	PERFORM - SPECIAL CHECK/REWORK - EMERGENCY AC-POWER- INSPECT AND REPLACE SUSPECT BALANCE SCREWS ON RAT,- INSPECTION	H: 0.00					
	Notes SUPERSEDED						
SB 700-24-075 PART B Airframe SB - Superseded #4350	PERFORM - SPECIAL CHECK/REWORK - EMERGENCY AC-POWER- INSPECT AND REPLACE SUSPECT BALANCE SCREWS ON RAT,- REPLACEMENT OF BALANCE SCREWS	H: 0.00					
	Notes SUPERSEDED						
SB 700-24-075 Airframe SB - Superseded #4215	SPECIAL CHECK/REWORK - EMERGENCY AC-POWER- INSPECT AND REPLACE SUSPECT BALANCE SCREWS ON RAT, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-24-075 R1 PART A Airframe SB - Superseded #3777	PERFORM - SPECIAL CHECK/REWORK - EMERGENCY AC-POWER- INSPECT AND REPLACE SUSPECT BALANCE SCREWS ON RAT,- INSPECTION. Notes SUPERSEDED	H: 0.00					
SB 700-24-075 R1 PART B Airframe SB - Superseded #3051	PERFORM - SPECIAL CHECK/REWORK - EMERGENCY AC-POWER- INSPECT AND REPLACE SUSPECT BALANCE SCREWS ON RAT,- REPLACEMENT OF ALL BALANCE SCREWS Notes SUPERSEDED	H: 0.00					
SB 700-24-075 R1 Airframe SB - Superseded #3362	SPECIAL CHECK/REWORK - EMERGENCY AC-POWER- INSPECT AND REPLACE SUSPECT BALANCE SCREWS ON RAT, SERVICE BULLETIN. Notes SUPERSEDED	H: 0.00					
SB 700-24-075 R2 PART A Airframe SB - N/A #3528	INSPECT - SPECIAL CHECK/REWORK - EMERGENCY AC-POWER-INSPECT AND REPLACE SUSPECT BALANCE SCREWS ON RAT, SUSPECT BALANCE SCREWS ON RAT Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					
SB 700-24-075 R2 PART B Airframe SB - N/A #2044	REPLACEMENT - SPECIAL CHECK/REWORK - EMERGENCY AC-POWER-INSPECT AND REPLACE SUSPECT BALANCE SCREWS ON RAT, OF ALL BALANCE SCREWS Notes NOT APPLICABLE - N/A BY AIRCRAFT S/N	12-SEP-2012 H: 388.37 L: 190					
SB 700-24-075 R2 Airframe SB - N/A #3372	SPECIAL CHECK/REWORK - EMERGENCY AC-POWER- INSPECT AND REPLACE SUSPECT BALANCE SCREWS ON RAT, SERVICE BULLETIN.. Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-24-076 Airframe SB - Terminated #3664	ICA - MODIFICATION - MAIN GENERATOR OIL SYSTEM - DRAIN AND FLUSH OIL SYSTEM AND REPLACE WITH LOWER VISCOSITY OIL, SERVICE BULLETIN	H: 0.00					
	Notes SB TERMINATED						
SB 700-24-076 PART C Airframe SB - Terminated #3727	MODIFICATION - ICA - MODIFICATION - MAIN GENERATOR OIL SYSTEM - DRAIN AND FLUSH OIL SYSTEM AND REPLACE WITH LOWER VISCOSITY OIL,-OF THE VFG OIL PLATE	H: 0.00					
	Notes SB TERMINATED						
SB 700-24-076 PART A Airframe SB - Terminated #3126	REWORK - ICA - MODIFICATION - MAIN GENERATOR OIL SYSTEM - DRAIN AND FLUSH OIL SYSTEM AND REPLACE WITH LOWER VISCOSITY OIL,-ALL FOUR VFGS	H: 0.00					
	Notes SB TERMINATED						
SB 700-24-076 PART B Airframe SB - Terminated #3377	REWORK - ICA - MODIFICATION - MAIN GENERATOR OIL SYSTEM - DRAIN AND FLUSH OIL SYSTEM AND REPLACE WITH LOWER VISCOSITY OIL,-THREE OR LESS VFGS	H: 0.00					
	Notes SB TERMINATED						
SB 700-24-077 Airframe SB - Complied With #2893	MODIFICATION - MAIN GENERATOR OIL SYSTEM INTRODUCTION OF NEW VARIABLE FREQUENCY GENERATOR FILTER ELEMENT, SERVICE BULLETIN	16-FEB-2012 H: 292.60 L: 134					
	Notes COMPLIED WITH - PART D, INTRODUCTION OF NEW VARIABLE FREQ GENERATOR						
SB 700-24-077 R1 PART A Airframe SB - Superseded #3732	ACCOMPLISH - MODIFICATION - MAIN GENERATOR OIL SYSTEM - INTRODUCTION OF NEW VARIABLE FREQUENCY GENERATOR FILTER ELEMENT,-MODIFICATION	H: 0.00					
	Notes SUPERSEDED						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-24-077 R1 PART B Airframe SB - Superseded #3204	ACCOMPLISH - MODIFICATION - MAIN GENERATOR OIL SYSTEM - INTRODUCTION OF NEW VARIABLE FREQUENCY GENERATOR FILTER ELEMENT,-MODIFICATION. Notes SUPERSEDED	H: 0.00					
SB 700-24-077 R1 Airframe SB - Superseded #4102	MODIFICATION - MAIN GENERATOR OIL SYSTEM - INTRODUCTION OF NEW VARIABLE FREQUENCY GENERATOR FILTER ELEMENT, SERVICE BULLETIN Notes SUPERSEDED	H: 0.00					
SB 700-24-077 R2 PART A Airframe SB - N/A #1586	ACCOMPLISH - MODIFICATION - MAIN GENERATOR OIL SYSTEM - INTRODUCTION OF NEW VARIABLE FREQUENCY GENERATOR FILTER ELEMENT,-MODIFICATION.. Notes NOT APPLICABLE	16-FEB-2012 H: 292.60 L: 134					
SB 700-24-077 R2 PART B Airframe SB - N/A #824	ACCOMPLISH - MODIFICATION - MAIN GENERATOR OIL SYSTEM - INTRODUCTION OF NEW VARIABLE FREQUENCY GENERATOR FILTER ELEMENT,-MODIFICATION... Notes NOT APPLICABLE	16-FEB-2012 H: 292.60 L: 134					
SB 700-24-077 R2 PART C Airframe SB - N/A #295	ACCOMPLISH - MODIFICATION - MAIN GENERATOR OIL SYSTEM - INTRODUCTION OF NEW VARIABLE FREQUENCY GENERATOR FILTER ELEMENT,-MODIFICATION.... Notes NOT APPLICABLE	16-FEB-2012 H: 292.60 L: 134					
SB 700-24-077 R2 PART D Airframe SB - Complied With #1377	ACCOMPLISH - MODIFICATION - MAIN GENERATOR OIL SYSTEM - INTRODUCTION OF NEW VARIABLE FREQUENCY GENERATOR FILTER ELEMENT,-MODIFICATION..... Notes COMPLIED WITH	16-FEB-2012 H: 292.60 L: 134					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-24-077 R2 Airframe SB - Complied With #2971	MODIFICATION - MAIN GENERATOR OIL SYSTEM - INTRODUCTION OF NEW VARIABLE FREQUENCY GENERATOR FILTER ELEMENT, SERVICE BULLETIN.	16-FEB-2012 H: 292.60 L: 134					
	Notes COMPLIED WITH						
SB 700-24-078 Airframe SB - Complied With #748	MODIFICATION - MAIN GENERATOR OIL SYSTEM - ADDITION OF HIGH CONDUCTIVITY OIL TO DISSIPATE ELECTRO STATIC DISCHARGE, SERVICE BULLETIN	16-FEB-2012 H: 292.60 L: 134					
	Notes COMPLIED WITH						
SB 700-24-079 Airframe SB - N/A #4227	MODIFICATION - DC POWERCENTER (DCPC) - INSTALLATION OF A BRACKET TO THE CIRCUIT BREAKER BOX ASSEMBLY FOR THE TRU FEEDER CABLE, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-24-080 PART A Airframe SB - Complied With #2031	CHECK - MODIFICATION - MAIN GENERATOR OIL SYSTEM - REPLACEMENT OF THE VARIABLE FREQUENCY GENERATOR, SERVICE BULLETIN	11-FEB-2014 H: 673.80 L: 291					
	Notes COMPLIED WITH - INSTALLED S/N #1 2360, #23092, #3 2924, #4 3081						
SB 700-24-080 PART B Airframe SB - N/A #1694	INSPECTION - MODIFICATION - MAIN GENERATOR OIL SYSTEM - REPLACEMENT OF THE VARIABLE FREQUENCY GENERATOR, SERVICE BULLETIN	11-FEB-2014 H: 673.80 L: 291					
	Notes NOT APPLICABLE - BY S/N						
SB 700-24-080 Airframe SB - Complied With #96	MODIFICATION - MAIN GENERATOR OIL SYSTEM - REPLACEMENT OF THE VARIABLE FREQUENCY GENERATOR, SERVICE BULLETIN	11-FEB-2014 H: 673.80 L: 291					
	Notes COMPLIED WITH						



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-24-080 PART C Airframe SB - N/A #2343	REPLACEMENT - MODIFICATION - MAIN GENERATOR OIL SYSTEM - REPLACEMENT OF THE VARIABLE FREQUENCY GENERATOR, SERVICE BULLETIN	11-FEB-2014 H: 673.80 L: 291					
	Notes NOT APPLICABLE - BY S/N						
SB 700-24-081 Airframe SB - Complied With #3875	MODIFICATION - ELECTRICAL POWER- BUS BAR HARNESS CLAMP REPLACEMENT IN THE LEFT HAND SIDE CIRCUIT BREAKER PANEL, SERVICE BULLETIN	31-MAR-2020 H: 3741.10 L: 1233					
SB 700-24-082 Airframe SB - Superseded #4383	SPECIAL CHECK - PRIMARY AC-POWER SUPPLY - VFG VIBRATION GROUND TEST, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-24-082 R1 Airframe SB - Complied With #2855	SPECIAL CHECK - PRIMARY AC-POWER SUPPLY - VFG VIBRATION GROUND TEST, SERVICE BULLETIN.	24-JAN-2014 H: 649.70 L: 284					
	Notes COMPLIED WITH						
SB 700-24-082 R2 Airframe SB - Superseded #3127	SPECIAL CHECK - PRIMARY AC-POWER SUPPLY - VFG VIBRATION GROUND TEST, SERVICE BULLETIN..	H: 0.00					
SB 700-24-082 R3 Airframe SB - N/A #4029	SPECIAL CHECK - PRIMARY AC-POWER SUPPLY - VARIABLE FREQUENCY GENERATOR (VFG) VIBRATION GROUND TEST, SERVICE BULLETIN	H: 0.00					
	Notes N/A PREVIOUSLY COMPLIED WITH BY REV 1						
SB 700-24-083 Airframe SB - Complied With #3817	MODIFICATION - MAIN GENERATOR OIL SYSTEM - REPLACEMENT OF THE VARIABLE FREQUENCY GENERATOR, SERVICE BULLETIN.	04-MAR-2016 H: 1753.70 L: 622					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-24-084 Airframe SB - N/A #3977	SPECIAL CHECK/MODIFICATION - ELECTRICAL POWER- INSTALLATION OF BOOT COVER ON THE FREQUENCY CONVERTER CIRCUIT BREAKER INSTALLATION, SERVICE BULLETIN	H: 0.00					
	Notes N/A PER S/N						
SB 700-24-085 Airframe SB - N/A #3999	SPECIAL CHECK - PRIMARY AC-POWERSUPPLY - REBALANCE OF VARIABLE FREQUENCY GENERATOR (VFG), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
SB 700-24-085 PART B Airframe SB - N/A #4300	SPECIAL CHECK - PRIMARY AC-POWERSUPPLY - REBALANCE OF VARIABLE FREQUENCY GENERATOR (VFG),-REPLACEMENT OF VFG(S)	H: 0.00					
	Notes NOT APPLICABLE						
SB 700-24-085 PART A Airframe SB - N/A #4177	SPECIAL CHECK - PRIMARY AC-POWERSUPPLY - REBALANCE OF VARIABLE FREQUENCY GENERATOR (VFG),-SPECIAL CHECK	H: 0.00					
	Notes NOT APPLICABLE						
SB 700-24-086 Airframe SB - Superseded #3064	MODIFICATION - DC POWERCENTER (DCPC) - ADD CBC1 TERMINAL INSULATOR ON CHASSIS, SERVICE BULLETIN	H: 0.00					
SB 700-24-086 R1 Airframe SB - Complied With #4755	MODIFICATION - DC POWER CENTER (DCPC) - ADD CBC1 TERMINAL INSULATOR ON CHASSIS (REV. 1)	29-SEP-2017 H: 2431.70 L: 854					
SB 700-24-087 Airframe SB - Complied With #4818	SPECIAL CHECK/MODIFICATION – PRIMARY AC-POWER SUPPLY – INSPECTION OF THE VARIABLE FREQUENCY GENERATOR (VFG) HOUSING WALL THICKNESS AND IF NECESSARY REPLACEMENT OF VFG	29-JAN-2018 H: 2586.20 L: 898					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-24-087 R1 Airframe SB - N/A #4847	SPECIAL CHECK/MODIFICATION – PRIMARY AC-POWER SUPPLY – INSPECTION OF THE VARIABLE FREQUENCY GENERATOR (VFG) HOUSING WALL THICKNESS AND IF NECESSARY REPLACEMENT OF VFG (REV. 1)						
	Notes BASIC SB C/W SO R1 IS NA						
SB 700-24-088 Airframe SB - Open #4888	MODIFICATION - CIRCUIT BREAKER - CABIN FIXED FREQUENCY MAIN CIRCUIT BREAKER						
SB 700-24-089 Airframe SB - Superseded #4849	MODIFICATION - VARIABLE FREQUENCY GENERATOR (VFG) - MODIFICATION TO THE VFG CABLES INSTALLATION, REAR FUSELAGE						
SB 700-24-089 R1 Airframe SB - Complied With #4867	MODIFICATION - VARIABLE FREQUENCY GENERATOR (VFG) - MODIFICATION TO THE VFG CABLES INSTALLATION, REAR FUSELAGE (REV. 1)					25-SEP-2018 H: 2870.00 L: 992	
	Notes PART B NOT REQUIRED DUE CLEARANCE OF .050" OR GREATER MEET WITH PART A						
SB 700-24-089 R2 Airframe SB - N/A #4876	MODIFICATION - VARIABLE FREQUENCY GENERATOR (VFG) - MODIFICATION TO THE VFG CABLES INSTALLATION, REAR FUSELAGE (REV. 2)						
SB 700-24-090 Airframe SB - N/A #4908	SPECIAL CHECK/MODIFICATION - EMERGENCY AC-POWER SUPPLY - REPLACEMENT OF THE RAM AIR TURBINE (RAT) DEPLOYMENT ACTUATOR PART NO. BZ02001-01 (GL456-1301-1)					19-APR-2020 H: 3741.10 L: 1233	
SB 700-25-003 Airframe SB - Open #4216	MODIFICATION - ADDITION OF THE EMERGENCY LOCATORSYSTEM (A/C 9002 TO 9999), SERVICE BULLETIN					H: 0.00	
SB 700-25-004 Airframe SB - Superseded #4087	MODIFICATION - EMERGENCY LOCATORSYSTEM - INSTALLATION AND TRANSMITTER LOCATION CHANGE, SERVICE BULLETIN					H: 0.00	
	Notes SUPERSEDED						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-25-004 R1 Airframe SB - N/A #4379	MODIFICATION - EMERGENCY LOCATOR SYSTEM - INSTALLATION AND TRANSMITTER LOCATION CHANGE, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-25-008 PART B Airframe SB - N/A #3982	MODIFICATION(PERMANENT REPAIR), SERVICE BULLETIN	H: 0.00					
	Notes N/A PER S/N						
SB 700-25-008 PART A Airframe SB - N/A #4043	SPECIAL CHECK/REWORK OF PILOT/, SERVICE BULLETIN	H: 0.00					
	Notes N/A PER S/N						
SB 700-25-010 PART A Airframe SB - Superseded #4618	MODIFICATION - INSULATION - CHANGES IN THE FLIGHT AND BAGGAGE COMPARTMENTS FORMOISTURE CONTROL, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-25-010 PART B Airframe SB - Superseded #3916	MODIFICATION - INSULATION - CHANGES IN THE FLIGHT AND BAGGAGE COMPARTMENTS FORMOISTURE CONTROL, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-25-010 R1 PART A Airframe SB - N/A #4520	MODIFICATION - INSULATION - CHANGES IN THE FLIGHT AND BAGGAGE COMPARTMENTS FORMOISTURE CONTROL (A/C 9002 TO 9023, 9025 TO 9069, 9071 TO 9073, 9076 TO 9139), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-25-010 R1 PART B Airframe SB - N/A #3622	MODIFICATION - INSULATION - CHANGES IN THE FLIGHT AND BAGGAGE COMPARTMENTS FORMOISTURE CONTROL (A/C 9002 TO 9126, 9128, 9129 AND 9131 TO 9139), SERVICE BULLETIN Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					
SB 700-25-022 Airframe SB - N/A #4513	MODIFICATION - BUFFET/GALLEY - SEALING OF GALLEY FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR (A/C 9002, 9011, 9016, 9020, 9022, 9024, 9034, 9036, 9041, 9042, 9049, 9050, 9052, 9054, 9055, 9060, 9062, 9070 TO 9072, 9074, 9075, 9077, 9078, 9080, 9082, Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					
SB 700-25-023 Airframe SB - N/A #4544	MODIFICATION - FLIGHT CREW SEATS - INSTALLATION OF A STOP FOR THE FORE/AFT ADJUSTMENT CABLE (A/C 9002 TO 9126 AND 9128 TO 9281), SERVICE BULLETIN Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					
SB 700-25-024 Airframe SB - Superseded #4545	MODIFICATION - FLIGHT CREW SEATS - INTRODUCTION OF NEW GOODRICH CREW SEATS, SERVICE BULLETIN Notes SUPERSEDED	H: 0.00					
SB 700-25-024 R1 Airframe SB - Superseded #4288	MODIFICATION - FLIGHT CREW SEATS - INTRODUCTION OF NEW GOODRICH CREW SEATS, SERVICE BULLETIN. Notes SUPERSEDED	H: 0.00					
SB 700-25-024 R2 Airframe SB - Open #3812	MODIFICATION - FLIGHT CREW SEATS - INTRODUCTION OF NEW GOODRICH CREW SEATS, SERVICE BULLETIN..	H: 0.00					
SB 700-25-024 R2 PART B Airframe SB - Open #3922	MODIFICATION - MODIFICATION - FLIGHT CREW SEATS - INTRODUCTION OF NEW GOODRICH CREW SEATS,-OF THE COPILOT SEAT	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-25-024 R2 PART A Airframe SB - Open #3774	MODIFICATION - MODIFICATION - FLIGHT CREW SEATS - INTRODUCTION OF NEW GOODRICH CREW SEATS,-OF THE PILOT SEAT	H: 0.00					
SB 700-25-025 Airframe SB - Superseded #3904	MODIFICATION - FLIGHT CREW SEATS - INTRODUCTION OF THICKERFORE/AFT CABLE FOR CREW SEAT (A/C 9002 TO 9314), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-25-025 R1 Airframe SB - Superseded #4196	MODIFICATION - FLIGHT CREW SEATS - INTRODUCTION OF THICKERFORE/AFT CABLE FOR CREW SEAT (A/C 9002 TO 9314), SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-25-025 R2 Airframe SB - N/A #3240	MODIFICATION - FLIGHT CREW SEATS - INTRODUCTION OF THICKERFORE/AFT CABLE FOR CREW SEAT, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-25-026 PART D Airframe SB - Superseded #4325	ACCESS - MODIFICATION - GENERAL - SEALING OF CABIN FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR,-THE AFT CABIN FLOOR PANELS	H: 0.00					
	Notes SUPERSEDED						
SB 700-25-026 PART E Airframe SB - Superseded #3577	ACCESS - MODIFICATION - GENERAL - SEALING OF CABIN FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR,-THE AFT LAVATORY AND BAGGAGE AREA FLOOR PANELS	H: 0.00					
	Notes SUPERSEDED						
SB 700-25-026 PART A Airframe SB - Superseded #3612	ACCESS - MODIFICATION - GENERAL - SEALING OF CABIN FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR,-THE ENTRANCE AREA FLOOR PANELS	H: 0.00					
	Notes SUPERSEDED						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-25-026 PART B Airframe SB - Superseded #3787	ACCESS - MODIFICATION - GENERAL - SEALING OF CABIN FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR,-THE FORWARD CABIN FLOOR PANELS	H: 0.00					
	Notes SUPERSEDED						
SB 700-25-026 PART C Airframe SB - Superseded #4125	ACCESS - MODIFICATION - GENERAL - SEALING OF CABIN FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR,-THE MID CABIN FLOOR PANELS	H: 0.00					
	Notes SUPERSEDED						
SB 700-25-026 Airframe SB - Superseded #4410	MODIFICATION - GENERAL - SEALING OF CABIN FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-25-026 R1 Airframe SB - N/A #3669	MODIFICATION - GENERAL - SEALING OF CABIN FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-25-026 R1 PART D Airframe SB - N/A #3889	MODIFICATION - MODIFICATION - GENERAL - SEALING OF CABIN FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR,- SEALING OF THE AFT CABIN FLOOR	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-25-026 R1 PART E Airframe SB - N/A #3259	MODIFICATION - MODIFICATION - GENERAL - SEALING OF CABIN FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR,- SEALING OF THE AFT LAV AND BAGGAGE AREA FLOOR	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-25-026 R1 PART A Airframe SB - N/A #3516	MODIFICATION - MODIFICATION - GENERAL - SEALING OF CABIN FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR,- SEALING OF THE ENTRANCE AREA FLOOR	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-25-026 R1 PART B Airframe SB - N/A #3072	MODIFICATION - MODIFICATION - GENERAL - SEALING OF CABIN FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR,- SEALING OF THE FORWARD CABIN FLOOR	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-25-026 R1 PART C Airframe SB - N/A #4493	MODIFICATION - MODIFICATION - GENERAL - SEALING OF CABIN FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR,- SEALING OF THE MID CABIN FLOOR	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-25-026 R2 PART D Airframe SB - N/A #3558	MODIFICATION - ICA - MODIFICATION - BLEED-AIRLEAK-DETECTION SYSTEM -REROUTING OF BLEED LEAK-DETECTION LOOPS AND RELOCATION OF A VENT HOLE,- INSTALLATION OF ADDITIONAL BONDING JUMPERS	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-25-027 Airframe SB - N/A #3604	MODIFICATION - BUFFET/GALLEY - SEALING OF GALLEY FLOOR TO PREVENT WATER SEEPAGE TO UNDERFLOOR, SERVICE BULLETIN	H: 0.00					
	Notes N/A PER S/N						
SB 700-25-028 Airframe SB - N/A #3840	MODIFICATION - CABIN INTERIOR- INTRODUCTION OF NEW DOOR LATCH FOR THE INTERIOR DOORS, SERVICE BULLETIN	H: 0.00					
	Notes N/A PER S/N						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-25-029 Airframe SB - N/A #3496	MODIFICATION - FLIGHT CREW SEATS - INTRODUCTION OF A STOP FOR THE GOODRICH COPILOT SEAT, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-25-030 Airframe SB - Superseded #3463	MODIFICATION - PASSENGER COMPARTMENT - REPLACE PASSENGER SERVICE UNIT (PSU) LATCH WITH A MORE ROBUST LATCH, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-25-030 R1 Airframe SB - N/A #3327	MODIFICATION - PASSENGER COMPARTMENT - REPLACE PASSENGER SERVICE UNIT (PSU) LATCH WITH A MORE ROBUST LATCH, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-25-030 R2 Airframe SB - N/A #3838	MODIFICATION - PASSENGER COMPARTMENT - REPLACE PASSENGER SERVICE UNIT (PSU) LATCH WITH A MORE ROBUST LATCH, SERVICE BULLETIN..	H: 0.00					
	Notes N/A PER S/N						
SB 700-25-031 Airframe SB - N/A #4018	MODIFICATION - PASSENGER COMPARTMENT - NEW ROLLER AND GUIDE INSTALLATION FOR THE CABIN DOORS, SERVICE BULLETIN	H: 0.00					
	Notes N/A PER S/N						
SB 700-25-032 Airframe SB - Superseded #4397	MODIFICATION - BUFFET/GALLEY - INSTALLATION OF INLET AND OUTLET GRILLS ON THE GALLEY CHILLER, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-25-032 R1 Airframe SB - N/A #4447	MODIFICATION - BUFFET/GALLEY - INSTALLATION OF INLET AND OUTLET GRILLS ON THE GALLEY CHILLER, SERVICE BULLETIN.	H: 0.00					
	Notes N/A PER S/N						
SB 700-25-033 Airframe SB - Open #4292	MODIFICATION FLIGHT CREW SEATS - INTRODUCTION OF A STOP FOR THE GOODRICH COPILOT SEAT, SERVICE BULLETIN	H: 0.00					
SB 700-25-034 Airframe SB - Complied With #2292	MODIFICATION - BUFFET/GALLEY - ADDITIONAL COOLING MODIFICATION FORMICROWAVE, SERVICE BULLETIN	12-SEP-2012 H: 388.37 L: 190					
	Notes COMPLIED WITH						
SB 700-25-035 Airframe SB - N/A #3211	MODIFICATION - PASSENGER SEATING REPLACE SUSPECT SWIVEL ASSEMBLY ON PASSENGER SEAT, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-25-036 Airframe SB - Open #4197	MODIFICATION - FLIGHT CREW SEATS - INTRODUCTION OF NEW SEAT CUSHION, SERVICE BULLETIN	H: 0.00					
SB 700-25-036 PART B Airframe SB - Open #3305	MODIFICATION - MODIFICATION - FLIGHT CREW SEATS - INTRODUCTION OF NEW SEAT CUSHION, OF THE COPILOT SEAT	H: 0.00					
SB 700-25-036 PART A Airframe SB - Open #4146	MODIFICATION - MODIFICATION - FLIGHT CREW SEATS - INTRODUCTION OF NEW SEAT CUSHION, OF THE PILOT SEAT	H: 0.00					
SB 700-25-037 Airframe SB - Complied With #3730	SPECIAL CHECK/REWORK - GALLEY - REWORK OF THE COFFEE BREWER, SERVICE BULLETIN	08-NOV-2019 H: 3554.60 L: 1177					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-25-039 Airframe SB - Open #4436	MODIFICATION - CABIN INTERIOR- REPLACEMENT OF STRIKER LATCH ON CABINETS, SERVICE BULLETIN	H: 0.00					
SB 700-25-040 Airframe SB - Open #4564	MODIFICATION - BUFFET/GALLEY - MODIFICATION OF MICROWAVE OVEN PART NO. 400-1409-01-L OR400-1409-01-R, SERVICE BULLETIN	H: 0.00					
SB 700-25-041 Airframe SB - Open #4001	MODIFICATION - WARDROBE CABINETS - REPLACEMENT OF THE MAXIMUM WEIGHT LIMITATION PLACARD IN THE LEFT HAND BAGGAGE COMPARTMENT, SERVICE BULLETIN	H: 0.00					
SB 700-25-043 Airframe SB - Superseded #3959	MODIFICATION - FORWARD AND AFT LAVATORY - IMPROVEMENT OF THE SIDE LATCHES, HANDLE INSTALLATIONS AND STOPPERS ON THE DOORS DECOMPRESSION TYPE, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED BY SB 700-25-053						
SB 700-25-044 Airframe SB - Open #3432	MODIFICATION - EMERGENCY LOCATOR SYSTEM (ELT) - EMERGENCY LOCATOR TRANSMITTER REMOVAL/INSTALLATION IMPROVEMENT, SERVICE BULLETIN	H: 0.00					
SB 700-25-045 Airframe SB - N/A #4380	MODIFICATION - GALLEY - HOT CUP PLACARD INSTALLATION, SERVICE BULLETIN	H: 0.00					
	Notes N/A PER S/N						
SB 700-25-047 Airframe SB - N/A #4097	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE ELECTRIC RELEASE POCKET-DOOR FOOTER MECHANISM (FORWARD), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
SB 700-25-047 R03 Airframe SB - N/A #4926	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE ELECTRIC RELEASE POCKET - DOOR FOOTER MECHANISM (FORWARD)						
	Notes N/A PER S/N						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-25-047 R1 Airframe SB - N/A #4020	MODIFICATION - PASSENGERCOMPARTMENT - MODIFICATION OF THE ELECTRIC RELEASE POCKET-DOOR FOOTER MECHANISM (FORWARD), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE						
SB 700-25-047 R2 Airframe SB - N/A #4685	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE ELECTRIC RELEASE POCKET-DOOR FOOTER MECHANISM (FORWARD) (REV. 2)						
	Notes N/A PER S/N						
SB 700-25-048 Airframe SB - N/A #3957	MODIFICATION - PASSENGERCOMPARTMENT - MODIFICATION OF THE ELECTRIC RELEASE POCKET-DOOR FOOTER MECHANISM (MID), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
SB 700-25-048 R03 Airframe SB - N/A #4911	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE ELECTRIC RELEASE POCKET-DOOR FOOTER MECHANISM (MID)						
	Notes N/A PER S/N						
SB 700-25-048 R04 Airframe SB - N/A #4925	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE ELECTRIC RELEASE POCKET-DOOR FOOTER MECHANISM (MID)						
	Notes N/A PER S/N						
SB 700-25-048 R1 Airframe SB - N/A #4504	MODIFICATION - PASSENGERCOMPARTMENT - MODIFICATION OF THE ELECTRIC RELEASE POCKET-DOOR FOOTER MECHANISM (MID), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-25-048 R2 Airframe SB - N/A #4684	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE ELECTRIC RELEASE POCKET-DOOR FOOTER MECHANISM (MID) (REV. 2)						
	Notes N/A PER S/N						
SB 700-25-049 Airframe SB - Superseded #4570	MODIFICATION - PASSENGERCOMPARTMENT - MODIFICATION OF THE MANUAL RELEASE POCKET-DOOR FOOTER MECHANISM (FORWARD), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED BY R1						
SB 700-25-049 R1 Airframe SB - Open #4428	MODIFICATION - PASSENGERCOMPARTMENT - MODIFICATION OF THE MANUAL RELEASE POCKET-DOOR FOOTER MECHANISM (FORWARD), SERVICE BULLETIN.	H: 0.00					
SB 700-25-050 Airframe SB - Open #3497	MODIFICATION - PASSENGERCOMPARTMENT - MODIFICATION OF THE MANUAL RELEASE POCKET-DOOR FOOTER MECHANISM (MID), SERVICE BULLETIN	H: 0.00					
SB 700-25-050 R1 Airframe SB - Open #3273	MODIFICATION - PASSENGERCOMPARTMENT - MODIFICATION OF THE MANUAL RELEASE POCKET-DOOR FOOTER MECHANISM (MID), SERVICE BULLETIN.	H: 0.00					
SB 700-25-051 Airframe SB - Superseded #4261	MODIFICATION - PASSENGERCOMPARTMENT - REPLACEMENT OF MICROSWITCH IN ELECTRICAL CONTROLS, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED BY R1						
SB 700-25-051 R1 Airframe SB - Complied With #3479	MODIFICATION - PASSENGERCOMPARTMENT - REPLACEMENT OF MICROSWITCH IN ELECTRICAL CONTROLS, SERVICE BULLETIN.	16-APR-2021					
		H: 3992.00					
		L: 1324					
SB 700-25-052 Airframe SB - N/A #3073	ICA - SPECIAL CHECK/REWORK - PASSENGERCOMPARTMENT - INSPECTION AND REPLACEMENT OF EJECTOR BASE, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-25-052 PART B Airframe SB - N/A #4597	REPLACEMENT - ICA - SPECIAL CHECK/REWORK - PASSENGERCOMPARTMENT - INSPECTION AND REPLACEMENT OF EJECTOR BASE,-OF THE EJECTOR BASE	H: 0.00					
	Notes NOT APPLICABLE						
SB 700-25-052 PART A Airframe SB - N/A #3407	VERIFICATION - ICA - SPECIAL CHECK/REWORK - PASSENGERCOMPARTMENT - INSPECTION AND REPLACEMENT OF EJECTOR BASE,-OF INSTALLED PARTS	H: 0.00					
	Notes NOT APPLICABLE						
SB 700-25-052 R1 Airframe SB - N/A #4622	ICA SPECIAL CHECK/REWORK PASSENGER COMPARTMENT REPLACEMENT OF EJECTOR BASE (REV. 1)						
	Notes N/A PER S/N						
SB 700-25-053 Airframe SB - Complied With #4708	MODIFICATION - FORWARD AND AFT LAVATORY - IMPROVEMENT OF THE HANDLE INSTALLATIONS, LATCH AND STOPPERS ON THE DOORS DECOMPRESSION TYPE	17-JUL-2020					
		H: 3806.80 L: 1260					
SB 700-25-054 Airframe SB - Open #3470	MODIFICATION - ENTRY AREA HEADLINER- IMPROVEMENT OF MAIN ENTRANCE HEADLINER ATTACHMENTS, SERVICE BULLETIN	H: 0.00					
SB 700-25-055 Airframe SB - Complied With #4763	MODIFICATION - PASSENGER COMPARTMENT - REPLACEMENT OF DRAWER LATCH AND WIRE STRIKER ON CABINETS	23-NOV-2016					
		H: 2072.50 L: 725					
SB 700-25-055 R1 Airframe SB - N/A #4884	MODIFICATION - PASSENGER COMPARTMENT - REPLACEMENT OF DRAWER LATCH AND WIRE STRIKER ON CABINETS						
	Notes PREVIOUSLY COMPLIED WITH						
SB 700-25-057 Airframe SB - Complied With #4801	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE AFT LAVATORY DOOR HINGES	29-SEP-2017					
		H: 2431.70 L: 854					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-25-057 R1 Airframe SB - Complied With #4846	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE AFT LAVATORY DOOR HINGES (REV. 1)	01-DEC-2018 H: 3011.20 L: 1025					
SB 700-25-057 R2 Airframe SB - N/A #4904	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE AFT LAVATORY DOOR HINGES						
	Notes PREVIOUSLY COMPLIED WITH						
SB 700-25-058 Airframe SB - Open #4817	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE FWD LAVATORY DOOR HINGES						
SB 700-25-059 Airframe SB - Open #4813	MODIFICATION - MISCELLANEOUS EQUIPMENT- REPLACEMENT OF THE AIRSTAIR ANTI-SLIP MAT						
SB 700-25-060 Airframe SB - Superseded #4824	MODIFICATION - EMERGENCY LOCATOR SYSTEM - INTRODUCTION OF THE DK180 LOW FREQUENCY (8.8KHZ) UNDERWATER LOCATOR DEVICE						
	Notes SUPERSEDED BY REV 1						
SB 700-25-060 R02 Airframe SB - Open #4990	MODIFICATION - EMERGENCY LOCATOR SYSTEM - INTRODUCTION OF THE DK180 LOW FREQUENCY (8.8KHZ) UNDERWATER LOCATOR DEVICE						
SB 700-25-060 R1 Airframe SB - Open #4837	MODIFICATION - EMERGENCY LOCATOR SYSTEM - INTRODUCTION OF THE DK180 LOW FREQUENCY (8.8KHZ) UNDERWATER LOCATOR DEVICE (REV. 1)						
SB 700-25-061 Airframe SB - N/A #4828	INSPECTION - EMERGENCY EQUIPMENT - REPLACEMENT OF THE CREWMEMBER PROTECTIVE BREATHING EQUIPMENT (PBE) UNITS WITH PART NO. 119003-11 OR PART NO. 119003-21 (WITHIN SPECIFIED SERIAL NUMBER FOR -21 ONLY).	16-JAN-2018 H: 2586.20 L: 898					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-25-062 Airframe SB - Superseded #4845	MODIFICATION - BUFFET/GALLEY - MODIFICATION OF THE GALLEY MICROWAVE COMPARTMENT Notes SUPERSEDED						
SB 700-25-062 R1 Airframe SB - Superseded #4850	MODIFICATION - BUFFET/GALLEY - MODIFICATION OF THE GALLEY MICROWAVE COMPARTMENT (REV. 1) Notes SUPERSEDED						
SB 700-25-062 R2 Airframe SB - Open #4896	MODIFICATION - GALLEY - MODIFICATION OF THE MICROWAVE COMPARTMENT						
SB 700-25-063 Airframe SB - Open #4860	MODIFICATION - PASSENGER SEATING -INSTALLATION OF ADDITIONAL GROMMETS TO PREVENT INTERFERENCE BETWEEN SEAT ARMREST AND DADO MOLDING						
SB 700-25-064 Airframe SB - N/A #4872	MODIFICATION - DOOR STOPPER - IMPROVEMENT OF THE DOOR STOPPER AND STAY OPEN FOR THE AFT LAVATORY DOOR AND THE BAGGAGE COMPARTMENT DOOR Notes N/A PER S/N						
SB 700-25-065 R01 Airframe SB - Open #4923	SPECIAL CHECK/REWORK - PASSENGER COMPARTMENT - REPLACEMENT OF THE SEAT BELT EJECTOR BASE						
SB 700-25-069 Airframe SB - Open #5073	SPECIAL CHECK/MODIFICATION - UNDERWATER LOCATING DEVICE - INSPECTION OF THE DK180 LOW FREQUENCY (8.8KHZ) UNDERWATER LOCATING DEVICE (LF-ULD)						
SB 700-26-008 Airframe SB - Complied With #2008	MODIFICATION - FIRE EXTINGUISHING SYSTEM - REPLACEMENT OF FIRE EXTINGUISHERCONTAINER PART NO. 473776-2, SERVICE BULLETIN Notes COMPLIED WITH					12-SEP-2012 H: 388.37 L: 190	





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-26-009 Airframe SB - Complied With #357	MODIFICATION - SMOKE DETECTION SYSTEM - MODIFICATION TO THE FIDEEX SMOKE DETECTORWIRING, SERVICE BULLETIN	16-FEB-2012 H: 292.60 L: 134					
	Notes COMPLIED WITH						
SB 700-26-009 R1 Airframe SB - N/A #3448	MODIFICATION - SMOKE DETECTION SYSTEM - MODIFICATION TO THE FIDEEX SMOKE DETECTORWIRING, SERVICE BULLETIN.	H: 0.00					
	Notes N/A PREVIOUSLY COMPLIED WITH						
SB 700-26-011 Airframe SB - Superseded #4829	SPECIAL CHECK/MODIFICATION - FIRE EXTINGUISHING SYSTEM - SQUIBB CONNECTORS A111P2, A112P1 AND A111P3 WIRE LENGTHS						
	Notes SUPERSEDED						
SB 700-26-011 R1 Airframe SB - Complied With #4844	SPECIAL CHECK/MODIFICATION - FIRE EXTINGUISHING SYSTEM - SQUIB CONNECTORS A111P2, A112P1 AND A111P3 WIRE LENGTHS (REV. 1)	24-MAY-2018 H: 2727.40 L: 933					
SB 700-26-011 R2 Airframe SB - N/A #4865	SPECIAL CHECK/MODIFICATION - FIRE EXTINGUISHING SYSTEM - SQUIB CONNECTORS A111P2, A112P1 AND A111P3 WIRE LENGTHS (REV. 2)						
	Notes N/A PREVIOUSLY COMPLIED WITH						
SB 700-26-011 R3 Airframe SB - Complied With #4868	SPECIAL CHECK/MODIFICATION - FIRE EXTINGUISHING SYSTEM - SQUIB CONNECTORS A111P2, A112P1 AND A111P3 WIRE LENGTHS (REV. 3)	01-DEC-2018 H: 3011.20 L: 1025					
SB 700-27-015 Airframe SB - N/A #3429	MODIFICATION - STALL PROTECTION SYSTEM - INTRODUCTION OF STALL PROTECTION COMPUTER(SPC), PART NO. GH582-3001-5, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-27-016 Airframe SB - N/A #3502	SPECIAL CHECK/MODIFICATION - GROUND SPOILERS - REPLACEMENT OF GROUND SPOILERSELECTOR VALVE TO PREVENT POSSIBLE FAILURE OF GROUND SPOILER, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-018 Airframe SB - N/A #4142	MODIFICATION - FLAPS AND SLATS - SOFTWARE UPGRADE OF THE SLAT/FLAP CONTROL UNIT TO PREVENT UNNECESSARY FLAP SYSTEM SHUTDOWN DURING FLIGHT, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-019 Airframe SB - Superseded #3770	MODIFICATION - PITCH TRIM SYSTEM - INCORPORATION OF MOTORS WITH IMPROVED BRAKE MATERIAL ON THE HORIZONTAL STABILIZERTRIM-ACTUATOR (HSTA), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-27-019 R1 Airframe SB - N/A #4305	MODIFICATION - PITCH TRIM SYSTEM - INCORPORATION OF MOTORS WITH IMPROVED BRAKE MATERIAL ON THE HORIZONTAL STABILIZERTRIM-ACTUATOR (HSTA), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-020 Airframe SB - N/A #4524	MODIFICATION - FLAP SYSTEM - ADDITION OF ALIGNMENT PLATES ON FLAP FAIRINGS, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-021 Airframe SB - Superseded #4510	MODIFICATION - LEADING EDGE SLAT-SYSTEM - REPLACEMENT OF DOG BONE SEALS, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-27-021 R1 Airframe SB - Superseded #3820	MODIFICATION - LEADING EDGE SLAT-SYSTEM - REPLACEMENT OF DOG BONE SEALS, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-27-021 R2 Airframe SB - Superseded #3409	MODIFICATION - LEADING EDGE SLAT-SYSTEM - REPLACEMENT OF DOG BONE SEALS, SERVICE BULLETIN..	H: 0.00					
	Notes SUPERSEDED						
SB 700-27-021 R3 Airframe SB - N/A #4416	MODIFICATION - LEADING EDGE SLAT-SYSTEM - REPLACEMENT OF DOG BONE SEALS, SERVICE BULLETIN...	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-022 Airframe SB - N/A #3752	SPECIAL CHECK/REWORK - FLAP SYSTEM - REPLACEMENT OF DEFECTIVE SKEW SENSORS, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-023 Airframe SB - N/A #4173	MODIFICATION - RUDDER- RUDDER LEADING EDGE EXTENSION TO PREVENT DAMAGE TO RUDDER, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-024 Airframe SB - Superseded #3593	MODIFICATION -AILERON CONTROL SYSTEM - AERODYNAMIC IMPROVEMENT, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-27-024 R1 Airframe SB - N/A #4282	MODIFICATION - AILERON CONTROL SYSTEM - AERODYNAMIC IMPROVEMENT, SERVICE BULLETIN. Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					
SB 700-27-025 Airframe SB - Complied With #2805	MODIFICATION - STALL PROTECTION - DISABLE STICK PUSHERCANCEL FUNCTION FROM AUTOPILOT MASTER DISCONNECT SWITCH FOR JAA AIRCRAFT, SERVICE BULLETIN Notes COMPLIED WITH - AT COMPLETION	16-FEB-2011 H: 0.00					
SB 700-27-025 R02 Airframe SB - Open #5004	MODIFICATION - STALL PROTECTION SYSTEM - DISABLE STICK PUSHER CANCEL FUNCTION FROM AUTOPILOT MASTER DISCONNECT SWITCH FOR JAA AIRCRAFT						
SB 700-27-025 R1 Airframe SB - N/A #3271	MODIFICATION - STALL PROTECTION SYSTEM - DISABLE STICK PUSHERCANCEL FUNCTION FROM AUTOPILOT MASTER DISCONNECT SWITCH FOR JAA AIRCRAFT, SERVICE BULLETIN Notes N/A PREVIOUSLY COMPLIED WITH	H: 0.00					
SB 700-27-026 PART A Airframe SB - Superseded #4151	SPECIAL CHECK/REWORK - PITCH TRIM SYSTEM - REPLACE THE GREASE IN THE HORIZONTAL STABILIZERTRIM ACTUATOR (9002 TO 9126 AND 9128 TO 9134), SERVICE BULLETIN Notes SUPERSEDED	H: 0.00					
SB 700-27-026 PART B Airframe SB - Superseded #4446	SPECIAL CHECK/REWORK - PITCH TRIM SYSTEM - REPLACE THE GREASE IN THE HORIZONTAL STABILIZERTRIM ACTUATOR (9002 TO 9126 AND 9128 TO 9134), SERVICE BULLETIN. Notes SUPERSEDED	H: 0.00					
SB 700-27-026 PART C Airframe SB - Superseded #3882	SPECIAL CHECK/REWORK - PITCH TRIM SYSTEM - REPLACE THE GREASE IN THE HORIZONTAL STABILIZERTRIM ACTUATOR (9002 TO 9126 AND 9128 TO 9134), SERVICE BULLETIN.. Notes SUPERSEDED	H: 0.00					

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-27-026 R1 PART B Airframe SB - N/A #3830	SPECIAL CHECK/REWORK - PITCH TRIM SYSTEM - REPLACE THE GREASE IN THE HORIZONTAL STABILIZERTRIM ACTUATOR (9002 TO 9126 AND 9128 TO 9134) SERVICE BULLETIN, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-026 R1 PART C Airframe SB - N/A #4246	SPECIAL CHECK/REWORK - PITCH TRIM SYSTEM - REPLACE THE GREASE IN THE HORIZONTAL STABILIZERTRIM ACTUATOR (9002 TO 9126 AND 9128 TO 9134) SERVICE BULLETIN, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-026 R1 PART A Airframe SB - N/A #3312	SPECIAL CHECK/REWORK - PITCH TRIM SYSTEM - REPLACE THE GREASE IN THE HORIZONTAL STABILIZERTRIM ACTUATOR (9002 TO 9126 AND 9128 TO 9134), SERVICE BULLETIN...	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-027 Airframe SB - Superseded #3538	SPECIAL CHECK/REWORK - LEADING EDGE SLAT-SYSTEM - VERIFICATION OF THE SLAT CONNECTORPINS FOR CORRECT INSTALLATION, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-27-027 R1 Airframe SB - N/A #4494	SPECIAL CHECK/REWORK - LEADING EDGE SLAT-SYSTEM - VERIFICATION OF THE SLAT CONNECTORPINS FOR CORRECT INSTALLATION, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-029 Airframe SB - N/A #4281	SPECIAL CHECK/REWORK - CONTROL AND INDICATION SYSTEMS - EXAMINE SLAT/FLAP SYSTEM WIRING FORDAMAGE AND SLAT/FLAP CONTROL UNIT CONNECTOR FOR CORRECT INSTALLATION, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-27-030 Airframe SB - N/A #3095	SPECIAL CHECK/MODIFICATION - RUDDERCONTROL SYSTEM - RUDDER CABLE AND QUADRANT GUARD PIN CLEARANCE LIMITS, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-031 PART A Airframe SB - N/A #4594	SPECIAL CHECK/REWORK - ELEVATORCONTROL SYSTEM - CHECK FOR DEFECTIVE LOCK SOLENOID AND PITCH DISCONNECT MECHANISM AND REPLACEMENT OF DEFECTIVE PITCH DISCONNECT MECHANISM (A/C 9002 TO 9085 AND 9091), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-031 PART B Airframe SB - N/A #4133	SPECIAL CHECK/REWORK - ELEVATORCONTROL SYSTEM - CHECK FOR DEFECTIVE LOCK SOLENOID AND PITCH DISCONNECT MECHANISM AND REPLACEMENT OF DEFECTIVE PITCH DISCONNECT MECHANISM (A/C 9002 TO 9085 AND 9091), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-036 Airframe SB - Superseded #4228	MODIFICATION - CONTROL AND INDICATING SYSTEMS - UPGRADE OF THE FLIGHT CONTROL UNIT (FCU) "SOFTWARE STANDARD 1102", SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-27-036 R1 Airframe SB - N/A #4011	MODIFICATION - CONTROL AND INDICATING SYSTEMS - UPGRADE OF THE FLIGHT CONTROL UNIT (FCU) "SOFTWARE STANDARD 1102" (A/C 9002 TO 9124), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-039 Airframe SB - N/A #4430	SPECIAL CHECK/MODIFICATION - FLIGHT CONTROLS - REPLACEMENT OF THE MULTI-FUNCTION SPOILERPOWER CONTROL UNIT CONNECTOR AND CONDUIT.-(EFFECTIVITY: A/C S/N 9002 - 9113), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-27-040 Airframe SB - N/A #4149	SPECIAL CHECK/MODIFICATION - PITCH TRIM SYSTEM - INSPECT THE PITCH-TRIM ACTUATOR MOTOR DRIVE-UNIT (MDU) AND REPLACE, IF NECESSARY, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-042 PART A Airframe SB - Superseded #3766	SPECIAL CHECK/MODIFICATION - CONTROL AND INDICATION SYSTEMS - CHECK AND REPLACE SLAT/FLAP POWERDRIVE UNIT (PDU) MOTORS IF NECESSARY AND UPGRADE THE SLAT/FLAP CONTROL UNIT (SFCU) TO -11 CONFIGURATION WITH NEW SOFTWARE, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-27-042 PART B Airframe SB - Superseded #3401	SPECIAL CHECK/MODIFICATION - CONTROL AND INDICATION SYSTEMS - CHECK AND REPLACE SLAT/FLAP POWERDRIVE UNIT (PDU) MOTORS IF NECESSARY AND UPGRADE THE SLAT/FLAP CONTROL UNIT (SFCU) TO -11 CONFIGURATION WITH NEW SOFTWARE, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-27-042 PART C Airframe SB - Superseded #4601	SPECIAL CHECK/MODIFICATION - CONTROL AND INDICATION SYSTEMS - CHECK AND REPLACE SLAT/FLAP POWERDRIVE UNIT (PDU) MOTORS IF NECESSARY AND UPGRADE THE SLAT/FLAP CONTROL UNIT (SFCU) TO -11 CONFIGURATION WITH NEW SOFTWARE, SERVICE BULLETIN..	H: 0.00					
	Notes SUPERSEDED						
SB 700-27-042 R1 PART A Airframe SB - N/A #3506	SPECIAL CHECK/MODIFICATION - CONTROL AND INDICATION SYSTEMS - CHECK AND REPLACE SLAT/FLAP POWERDRIVE UNIT (PDU) MOTORS IF NECESSARY AND UPGRADE THE SLAT/FLAP CONTROL UNIT (SFCU) TO -11 CONFIGURATION WITH NEW SOFTWARE, SERVICE BULLETIN...	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-042 R1 PART B Airframe SB - N/A #4352	SPECIAL CHECK/MODIFICATION - CONTROL AND INDICATION SYSTEMS - CHECK AND REPLACE SLAT/FLAP POWERDRIVE UNIT (PDU) MOTORS IF NECESSARY AND UPGRADE THE SLAT/FLAP CONTROL UNIT (SFCU) TO -11 CONFIGURATION WITH NEW SOFTWARE, SERVICE BULLETIN....	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-27-044 Airframe SB #3949	MODIFICATION - FLAP SYSTEM - IMPROVED THE RIGIDITY OF THE FLAP SEAL PLATE ASSEMBLIES TO PREVENT FOULING BETWEEN THE FLAP AND FUSELAGE FAIRINGS, SERVICE BULLETIN	18-DEC-2019					
	Notes C/W ON LEFT HAND INBOARD FLAP SEAL PLATE IN TEB BY SL ON 12/19/19. SEE LOG BOOK THIS DATE.						
SB 700-27-045 Airframe SB - Superseded #3222	SPECIAL CHECK/MODIFICATION - CONTROL AND INDICATION SYSTEMS - SLAT/FLAP RESOLVERCHECK AND SLAT/FLAP CONTROL UNIT (SFCU) UPGRADE TO GT415-5900-13, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-27-045 R1 Airframe SB - N/A #4120	SPECIAL CHECK/MODIFICATION - CONTROL AND INDICATION SYSTEMS - SLAT/FLAP RESOLVERCHECK AND SLAT/FLAP CONTROL UNIT (SFCU) UPGRADE TO GT415-5900-13, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-047 Airframe SB - Superseded #3297	SPECIAL CHECK/REWORK - AILERON CONTROL SYSTEM - INSPECT, CLEAN AND GREASE AILERON TOGGLE LINK ASSEMBLY, ROD END ASSEMBLY AND BEARING ASSEMBLY (A/C 9002 TO 9126 AND 9128 TO 9160), SUPERSEDED	H: 0.00					
	Notes SUPERSEDED						
SB 700-27-047 R1 Airframe SB - N/A #4056	SPECIAL CHECK/REWORK - AILERON CONTROL SYSTEM - INSPECT, CLEAN AND GREASE AILERON TOGGLE LINK ASSEMBLY, ROD END ASSEMBLY AND BEARING ASSEMBLY (A/C 9002 TO 9126 AND 9128 TO 9160), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-048 Airframe SB - N/A #3386	MODIFICATION - STALL PROTECTION SYSTEM - SOFTWARE UPGRADE OF THE STALL PROTECTION COMPUTER(A/C 9002 TO 9175), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-27-049 Airframe SB - Superseded #4053	MODIFICATION - FLAP SYSTEM - REPLACEMENT OF SKEW SENSORS NO. 2, NO. 3 AND NO. 4 (A/C 9002 TO 9126 AND 9128 TO 9178), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-27-049 R1 Airframe SB - Superseded #4593	MODIFICATION - FLAP SYSTEM - REPLACEMENT OF SKEW SENSORS NO. 2, NO. 3 AND NO. 4 (A/C 9002 TO 9126 AND 9128 TO 9178), SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-27-049 R2 Airframe SB - Superseded #4398	MODIFICATION - FLAP SYSTEM - REPLACEMENT OF SKEW SENSORS NO. 2, NO. 3 AND NO. 4 (A/C 9002 TO 9126 AND 9128 TO 9178), SERVICE BULLETIN..	H: 0.00					
	Notes SUPERSEDED						
SB 700-27-049 R3 Airframe SB - N/A #3918	MODIFICATION - FLAP SYSTEM-REPLACEMENT OF SKEW SENSORS NO. 2, NO. 3 AND NO. 4 (A/C 9002 TO 9126 AND 9128 TO 9178), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-050 Airframe SB - Superseded #3780	MODIFICATION - CONTROL AND INDICATION SYSTEMS - SLAT/FLAP CONTROL UNIT (SFCU) UPGRADE TO PART NO. GT415-5900-15 (A/C 9002 TO 9181), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-27-050 R1 Airframe SB - N/A #3192	MODIFICATION - CONTROL AND INDICATION SYSTEMS - SLAT/FLAP CONTROL UNIT (SFCU) UPGRADE TO PART NO. GT415-5900-15 (A/C 9002 TO 9181), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-27-051 Airframe SB - N/A #3376	MODIFICATION - CONTROL AND INDICATION SYSTEMS - SLAT/FLAP CONTROL UNIT (SFCU) UPGRADE TO GT415-5900-13 MOD-10. REF. HAMILTON SUNDSTRAND VSB NO. FAS02C-27-10., SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-052 Airframe SB - N/A #3201	SPECIAL CHECK - FLAPS AND SLATS - CHECK OF THE SLAT AND FLAP TORQUE TUBES FORCORRECT ENGAGEMENT (A/C 9002 TO 9126 AND 9128 TO 9211), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-053 Airframe SB - N/A #3337	MODIFICATION - CONTROL AND INDICATION SYSTEMS - FLIGHT CONTROL UNIT (FCU) UPGRADE TO PART NO. GT415-0100-9 (A/C 9002 TO 9169), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-054 Airframe SB - N/A #3925	MODIFICATION - CONTROL AND INDICATION SYSTEMS - MODIFICATIONS TO PERMIT ZERO- FLAP TAKE-OFF CAPABILITY, SERVICE BULLETIN	H: 0.00					
	Notes N/A PER S/N						
SB 700-27-057 Airframe SB - Superseded #3157	MODIFICATION - AILERON CONTROL SYSTEM - INTRODUCTION OF NEW TOGGLE LINK PART NO. 376046-103-(A/C 9002 TO 9203), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-27-057 R1 Airframe SB - N/A #3129	MODIFICATION - AILERON CONTROL SYSTEM - INTRODUCTION OF NEW TOGGLE LINK PART NO. 376046-103 (A/C 9002 TO 9203), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						





Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-27-058 Airframe SB - Superseded #3724	MODIFICATION - PITCH TRIM SYSTEM - INTRODUCTION OF NEW MOTORDRIVE UNIT (MDU) PART NO. GT415-4002-11 TO CORRECT DUAL CHANNEL FAILURES (A/C 9002 TO 9126 AND 9128 TO 9192), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-27-058 R1 Airframe SB - N/A #3397	MODIFICATION - PITCH TRIM SYSTEM - INTRODUCTION OF NEW MOTORDRIVE UNIT (MDU) PART NO. GT415-4002-11 TO CORRECT DUAL CHANNEL FAILURES (A/C 9002 TO 9126 AND 9128 TO 9192), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-059 PART A Airframe SB - Superseded #3533	MODIFICATION - CONTROL AND INDICATION SYSTEMS - MODIFICATIONS TO PERMIT ZERO-FLAP TAKE-OFF CAPABILITY WITH FULL PERFORMANCE (A/C 9159 TO 9207), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-27-059 PART B Airframe SB - Superseded #4065	MODIFICATION - CONTROL AND INDICATION SYSTEMS - MODIFICATIONS TO PERMIT ZERO-FLAP TAKE-OFF CAPABILITY WITH FULL PERFORMANCE (A/C 9159 TO 9304), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-27-059 PART C Airframe SB - Superseded #4017	MODIFICATION - CONTROL AND INDICATION SYSTEMS - MODIFICATIONS TO PERMIT ZERO-FLAP TAKE-OFF CAPABILITY WITH FULL PERFORMANCE (PRE SB 700-11-020, A/C 9159, 9162, 9163, 9165, 9167, 9169, 9171, 9173, 9175, 9177, 9179, 9181, 9183 TO 9185, 9187, 9189, 9191	H: 0.00					
	Notes SUPERSEDED						
SB 700-27-059 R1 Airframe SB - N/A #4401	MODIFICATION - CONTROL AND INDICATION SYSTEMS-MODIFICATIONS TO PERMIT ZERO FLAP TAKE-OFF CAPABILITY WITH FULL PERFORMANCE, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-27-059 R1 PART C Airframe SB - N/A #4236	MODIFICATION - MODIFICATION CONTROL AND INDICATION SYSTEMS MODIFICATIONS TO PERMIT ZERO FLAP TAKE-OFF CAPABILITY WITH FULL PERFORMANCE,- MLG TIRE REPLACEMENT (AIRCRAFT, SERIAL NO. 9159 TO 9205 PRE SB 700-11-020)	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-059 R1 PART B Airframe SB - N/A #3294	MODIFICATION - MODIFICATION CONTROL AND INDICATION SYSTEMS MODIFICATIONS TO PERMIT ZERO FLAP TAKE-OFF CAPABILITY WITH FULL PERFORMANCE,- REPLACEMENT OF WHEEL SPEED TRANSDUCERS (AIRCRAFT, SERIAL NO. 9159 TO 9304)	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-059 R1 PART A Airframe SB - N/A #3620	MODIFICATION - MODIFICATION CONTROL AND INDICATION SYSTEMS MODIFICATIONS TO PERMIT ZERO FLAP TAKE-OFF CAPABILITY WITH FULL PERFORMANCE,- SFCU STRAPPING (AIRCRAFT, SERIAL NO. 9159 TO 9207)	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-061 Airframe SB - N/A #3707	MODIFICATION - CONTROL AND INDICATION SYSTEMS - REPLACEMENT OF SFCU WITH PART NO. GT415-5900-17 (A/C 9002 TO 9312 AND 9314 TO 9317), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-063 Airframe SB - N/A #4137	SPECIAL CHECK/REWORK - FLAP SYSTEM - INSPECT OUTBOARD FLAP CARRIAGE ASSEMBLY FOR INVERSE INSTALLATION OF BOLTS (A/C 9002 TO 9050 AND 9188 TO 9190), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-064 PART A Airframe SB - N/A #4490	SPECIAL CHECK/REWORK - PITCH TRIM SYSTEM - UPGRADE OF MDU P/N GT415-4002-11 TO MOD STRIKE 1 TO PREVENT NUISANCE MESSAGES (9193 TO 9271 AND 9002 TO 9192 POST SB 700-27-058, BASIC ISSUE), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-27-064 PART B Airframe SB - N/A #3494	SPECIAL CHECK/REWORK - PITCH TRIM SYSTEM - UPGRADE OF MDU P/N GT415-4002-11 TO MOD STRIKE 1 TO PREVENT NUISANCE MESSAGES (9193 TO 9271 AND 9002 TO 9192 POST SB 700-27-058, BASIC ISSUE), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-065 Airframe SB - N/A #4224	SPECIAL CHECK/REWORK - FLAPS AND SLATS - CHECK FLAP AND SLAT ACTUATORS FORCORRECT GREASE (A/C 9002 TO 9282), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-067 Airframe SB - Superseded #3553	REWORK - ELEVATORCONTROL SYSTEM - CORROSION PREVENTION OF ELEVATOR PCU, P/N GT411-3800-5 & -7, ATTACHMENT FITTINGS AND SLOTTED ENTRY BEARINGS (A/C 9002 TO 9222), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-27-067 R1 Airframe SB - N/A #3190	REWORK - ELEVATORCONTROL SYSTEM - CORROSION PREVENTION OF ELEVATOR PCU, P/N GT411-3800-5 & -7, ATTACHMENT FITTINGS AND SLOTTED ENTRY BEARINGS (A/C 9002 TO 9222), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-068 Airframe SB - N/A #4190	REWORK - RUDDERCONTROL SYSTEM - INSPECTION AND CORROSION PREVENTION OF PCU SLOTTED ENTRY BEARINGS, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-069 Airframe SB - Complied With #2732	REWORK - AILERON CONTROL SYSTEM - REPLACEMENT OF THE FLANGED BUSHINGS AND HINGE BOLT ASSEMBLY ON THE INBOARD AND OUTBOARD SIDES OF THE AILERON (9002 TO 9126 AND 9128 TO 9999), SERVICE BULLETIN	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-27-069 R1 Airframe SB - N/A #4549	REWORK - AILERON CONTROL SYSTEM - REPLACEMENT OF THE FLANGED BUSHINGS AND HINGE BOLT ASSEMBLY ON THE INBOARD AND OUTBOARD SIDES OF THE AILERON, SERVICE BULLETIN	H: 0.00					
	Notes N/A PREVIOUSLY COMPLIED WITH						
SB 700-27-070 Airframe SB - Superseded #3596	SPECIAL CHECK/REWORK - RUDDERCONTROL SYSTEM - EXAMINE YAW DAMPER FOR CORRECT INSTALLATION, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-27-070 R1 Airframe SB - N/A #4003	SPECIAL CHECK/REWORK - RUDDERCONTROL SYSTEM EXAMINE YAW DAMPER FOR CORRECT INSTALLATION, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-071 Airframe SB - Complied With #992	MODIFICATION - STALL PROTECTION SYSTEM - INTRODUCTION OF THE STALL PROTECTION COMPUTERPART NO. GH582-3001-17 TO CORRECT LOOPBACK ARINC 429 ISSUE, SERVICE BULLETIN	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
SB 700-27-072 Airframe SB - N/A #3184	MODIFICATION - PITCH TRIM SYSTEM RELOCATE EVS SWITCH TO PREVENT FOULING CONDITION WITH PITCH TRIM SWITCH, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-073 Airframe SB - N/A #3191	REWORK - PITCH TRIM SYSTEM - LUBRICATE HORIZONTAL-STABILIZERPIVOT-FITTINGS, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-27-074 Airframe SB - N/A #3714	MODIFICATION - MULTI FUNCTION SPOILERS REPLACE UNITS WITH POSSIBLE THIN WALL CONDITION, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-075 Airframe SB - Complied With #2616	CHECK/MODIFICATION - FLAPS AND SLATS - CHECK SLAT/FLAP ASYMMETRY BRAKE DECAL COVERFOR CORRECT INSTALLATION, SERVICE BULLETIN	12-SEP-2012 H: 388.37 L: 190					
	Notes COMPLIED WITH						
SB 700-27-076 Airframe SB - Superseded #4296	MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVERFOR NO. 1 AILERON PULLEY, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-27-076 R1 Airframe SB - Complied With #2225	ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVERFOR NO.1 AILERON PULLEY, SERVICE BULLETIN	07-FEB-2014 H: 673.80 L: 291					
	Notes COMPLIED WITH						
SB 700-27-076 R1 PART A Airframe SB - Complied With #2215	INSPECTION - ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVERFOR NO.1 AILERON PULLEY,-AND REWORK	04-FEB-2014 H: 673.80 L: 291					
	Notes COMPLIED WITH						
SB 700-27-076 R1 PART B Airframe SB - Complied With #1137	MODIFICATION - ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVERFOR NO.1 AILERON PULLEY, SERVICE BULLETIN	04-FEB-2014 H: 673.80 L: 291					
	Notes COMPLIED WITH						

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-27-076 R2 Airframe SB - N/A #3985	ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVERFOR NO. 1 AILERON PULLEY, SERVICE BULLETIN	H: 0.00					
	Notes N/A PREVIOUSLY COMPLIED WITH						
SB 700-27-076 R2 PART A Airframe SB - N/A #3054	INSPECTION - ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVERFOR NO. 1 AILERON PULLEY,-AND REWORK	H: 0.00					
	Notes N/A PREVIOUSLY COMPLIED WITH						
SB 700-27-076 R2 PART B Airframe SB - N/A #3855	MODIFICATION - ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVERFOR NO. 1 AILERON PULLEY, SERVICE BULLETIN	H: 0.00					
	Notes N/A PREVIOUSLY COMPLIED WITH						
SB 700-27-076 R3 Airframe SB - N/A #3699	ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVERFOR NO.1 AILERON PULLEY, SERVICE BULLETIN.	H: 0.00					
	Notes N/A PREVIOUSLY COMPLIED WITH						
SB 700-27-076 R3 PART A Airframe SB - N/A #3114	INSPECTION - ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVERFOR NO.1 AILERON PULLEY,-AND REWORK.	H: 0.00					
	Notes N/A PREVIOUSLY COMPLIED WITH						
SB 700-27-076 R3 PART B Airframe SB - N/A #3662	MODIFICATION - ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVERFOR NO.1 AILERON PULLEY, SERVICE BULLETIN.	H: 0.00					
	Notes N/A PREVIOUSLY COMPLIED WITH						

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-27-076 R4 Airframe SB - N/A #4418	ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVERFOR NO. 1 AILERON PULLEY, SERVICE BULLETIN.	H: 0.00					
	Notes N/A PREVIOUSLY COMPLIED WITH						
SB 700-27-076 R4 PART A Airframe SB - N/A #3632	INSPECTION - ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVERFOR NO. 1 AILERON PULLEY,-AND REWORK.	H: 0.00					
	Notes N/A PREVIOUSLY COMPLIED WITH						
SB 700-27-076 R4 PART B Airframe SB - N/A #3093	MODIFICATION - ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVERFOR NO. 1 AILERON PULLEY, SERVICE BULLETIN.	H: 0.00					
	Notes N/A PREVIOUSLY COMPLIED WITH						
SB 700-27-077 Airframe SB - N/A #3689	SPECIAL CHECK / MODIFICATION - RUDDERTRAVEL LIMITING SYSTEM REPLACEMENT OF RUDDER-LIMITER POSITION TRANSDUCER (RLPT), SERVICE BULLETIN	H: 0.00					
	Notes N/A PER S/N						
SB 700-27-079 PART A Airframe SB - N/A #3815	SPECIAL CHECK/REWORK - ELEVATORCONTROL -INSPECTION OF ELEVATOR AND APPLICATION OF SEALANT, IF NECESSARY, - INSPECTION OF THE INBOARD AND OUTBOARD TRAILING-EDGE TAPERED FITTINGS	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-079 PART B Airframe SB - N/A #4533	SPECIAL CHECK/REWORK - ELEVATORCONTROL -INSPECTION OF ELEVATOR AND APPLICATION OF SEALANT, IF NECESSARY, - SEALING OF THE INBOARD AND OUTBOARD TRAILING-EDGE TAPERED FITTINGS	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-27-079 Airframe SB - N/A #3213	SPECIAL CHECK/REWORK - ELEVATORCONTROL -INSPECTION OF ELEVATOR AND APPLICATION OF SEALANT, IF NECESSARY, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-27-083 Airframe SB - Open #5044	SPECIAL CHECK – ELEVATOR CONTROL SYSTEM – INSPECTION OF TORQUE TUBE BEARINGS						
SB 700-27-083 R01 Airframe SB - Complied With #5079	SPECIAL CHECK – ELEVATOR CONTROL SYSTEM – INSPECTION OF TORQUE TUBE BEARINGS					04-MAR-2021 H: 3992.00 L: 1324	
SB 700-27-086 Airframe SB - Open #5095	MODIFICATION - AILERON CONTROL SYSTEM - INTRODUCTION OF ZINC-ONLY COATED CONTROL CABLES						
SB 700-28-001 Airframe SB - Superseded #4229	MODIFICATION - DISTRIBUTION - PIPING PROVISION INSTALLATION FORTHE FUEL RE-CIRCULATION SYSTEM, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-28-001 R1 PART A Airframe SB - N/A #3735	MODIFICATION - DISTRIBUTION - PIPING PROVISION INSTALLATION FORTHE FUEL RE-CIRCULATION SYSTEM, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-28-001 R1 PART B Airframe SB - N/A #4462	MODIFICATION - DISTRIBUTION - PIPING PROVISION INSTALLATION FORTHE FUEL RE-CIRCULATION SYSTEM, SERVICE BULLETIN..	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-28-002 Airframe SB - Superseded #3251	MODIFICATION - REFUEL/DEFUEL SYSTEM - ADDITION OF REFUEL/DEFUEL CONTROL PANEL IN FLIGHT COMPARTMENT, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-28-002 R1 Airframe SB - Superseded #3841	MODIFICATION - REFUEL/DEFUEL SYSTEM - ADDITION OF REFUEL/DEFUEL CONTROL PANEL IN FLIGHT COMPARTMENT. (A/C 9002 TO 9999), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-28-002 R2 Airframe SB - Complied With #1444	MODIFICATION - REFUEL/DEFUEL SYSTEM - ADDITION OF REFUEL/DEFUEL CONTROL PANEL IN FLIGHT COMPARTMENT, SERVICE BULLETIN.	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
SB 700-28-020 Airframe SB - Superseded #3491	MODIFICATION - VENT SYSTEM - INSTALLATION OF COVERS OVERFUEL VENT LINES, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-28-020 R1 Airframe SB - N/A #4377	MODIFICATION - VENT SYSTEM - INSTALLATION OF COVERS OVERFUEL VENT LINES, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-28-021 Airframe SB - Superseded #4448	MODIFICATION - VENT SYSTEM - CABIN CROSSOVERLINES REWORKED FOR SUFFICIENT CLEARANCE, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-28-021 R1 Airframe SB - Superseded #3402	MODIFICATION - VENT SYSTEM - CABIN CROSSOVERLINES REWORKED FOR SUFFICIENT CLEARANCE, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-28-021 R2 Airframe SB - N/A #4536	REWORK - VENT SYSTEM - CABIN CROSSOVERLINES REWORKED FOR SUFFICIENT CLEARANCE, RECOMMENDED	H: 0.00					
	Notes SUPERSEDED						
SB 700-28-021 R3 Airframe SB - N/A #4461	REWORK - VENT SYSTEM - CABIN CROSSOVERLINES REWORKED FOR SUFFICIENT CLEARANCE, RECOMMENDED.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-28-026 Airframe SB - Superseded #4022	MODIFICATION - REFUEL/DEFUEL SYSTEM - REPLACEMENT OF THE REFUEL/DEFUEL TUBE WITH A SHORTERONE TO ELIMINATE STRESS PROBLEM, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-28-026 R1 Airframe SB - Superseded #3088	MODIFICATION - REFUEL/DEFUEL SYSTEM - REPLACEMENT OF THE REFUEL/DEFUEL TUBE WITH A SHORTERONE TO ELIMINATE STRESS PROBLEM, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-28-026 R2 Airframe SB - N/A #3517	MODIFICATION - REFUEL/DEFUEL SYSTEM - REPLACEMENT OF THE REFUEL/DEFUEL TUBE WITH A SHORTERONE TO ELIMINATE STRESS PROBLEM, SERVICE BULLETIN..	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-28-027 Airframe SB - N/A #3633	SPECIAL CHECK/REWORK - FUEL FEED AND TRANSFERSYSTEMS - POSSIBLE DAMAGE OF FUEL PUMP WIRING IN CONDUITS, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-28-028 Airframe SB - N/A #3151	MODIFICATION - FUEL MANAGEMENT AND QUANTITY GAUGING SYSTEM (FMQGS) - INTRODUCTION OF NEW COMPUTERPART NUMBER-GP546-1501-3, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-28-029 Airframe SB - Superseded #3220	MODIFICATION - FUEL FEED SYSTEM - SCAVENGE SYSTEM INSTALLATION TO REDUCE UNUSABLE FUEL QUANTITY, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-28-029 R1 Airframe SB - N/A #3946	MODIFICATION - FUEL FEED SYSTEM - SCAVENGE SYSTEM INSTALLATION TO REDUCE UNUSABLE FUEL QUANTITY, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-28-032 Airframe SB - Superseded #3161	MODIFICATION - DISTRIBUTION - WIRING PROVISION INSTALLATION FORTHE FUEL RE-CIRCULATION SYSTEM, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-28-032 R1 Airframe SB - Superseded #4600	MODIFICATION - DISTRIBUTION - WIRING PROVISION INSTALLATION FORTHE FUEL RE-CIRCULATION SYSTEM, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-28-032 R2 Airframe SB - N/A #3413	MODIFICATION - DISTRIBUTION - WIRING PROVISION INSTALLATION FORTHE FUEL RE-CIRCULATION SYSTEM, SERVICE BULLETIN..	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-28-033 Airframe SB - N/A #3237	MODIFICATION - FUEL MANAGEMENT AND QUANTITY GAUGING SYSTEM (FMQGS) - FMQGS COMPUTERCHANGE TO PART NO. GP546-1501-5, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-28-034 Airframe SB - N/A #3289	MODIFICATION - DISTRIBUTION - REPLACEMENT OF THE FUEL CONTROL PANEL / ACTIVATION OF THE FUEL RE-CIRCULATION SYSTEM, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-28-035 Airframe SB - N/A #3560	MODIFICATION - DISTRIBUTION - INSTALLATION OF FUEL RE-CIRCULATION AND SCAVENGE SYSTEMS FORAIRCRAFT '9003' ONLY, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-28-039 Airframe SB - N/A #3872	MODIFICATION - DISTRIBUTION - PERMANENT WIRING CONFIGURATION FORTHE FUEL RE-CIRCULATION SYSTEM FOLLOWING POWER SOURCE CHANGE, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-28-041 Airframe SB - N/A #3062	MODIFICATION - FUEL FEED SYSTEM - TEMPORARY DE-ACTIVATION OF THE FUEL SCAVENGE SYSTEM, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-28-042 Airframe SB - Superseded #3152	MODIFICATION/REWORK - FUEL FEED SYSTEM - DESIGN IMPROVEMENTS TO THE FUEL SCAVENGE SYSTEM INSTALLATION, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-28-042 R1 Airframe SB - Superseded #4242	MODIFICATION/REWORK - FUEL FEED SYSTEM - DESIGN IMPROVEMENTS TO THE FUEL SCAVENGE SYSTEM INSTALLATION, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-28-042 R2 PART A Airframe SB - N/A #3176	MODIFICATION/REWORK - FUEL FEED SYSTEM - DESIGN IMPROVEMENTS TO THE FUEL SCAVENGE SYSTEM INSTALLATION, SERVICE BULLETIN..	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-28-042 R2 PART B Airframe SB - N/A #4208	MODIFICATION/REWORK - FUEL FEED SYSTEM - DESIGN IMPROVEMENTS TO THE FUEL SCAVENGE SYSTEM INSTALLATION, SERVICE BULLETIN...	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-28-042 R2 PART C Airframe SB - N/A #3716	MODIFICATION/REWORK - FUEL FEED SYSTEM - DESIGN IMPROVEMENTS TO THE FUEL SCAVENGE SYSTEM INSTALLATION, SERVICE BULLETIN....	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-28-043 Airframe SB - Superseded #3133	MODIFICATION - FUEL FEED SYSTEM - INTRODUCTION OF INTEGRAL FUEL TANK COATING BETWEEN THE DC FUEL PUMP AND MATING FLANGE (A/C 9002 TO 9124), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-28-043 R1 Airframe SB - N/A #4270	MODIFICATION - FUEL FEED SYSTEM - INTRODUCTION OF INTEGRAL FUEL TANK COATING BETWEEN THE DC FUEL PUMP AND MATING FLANGE, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-28-044 Airframe SB - N/A #3228	MODIFICATION - FUEL MANAGEMENT AND QUANTITY GAUGING SYSTEM (FMQGS) - UPGRADE OF THE FMQGS COMPUTERTO PART NO. GP546-1501-8, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-28-045 Airframe SB - N/A #3671	MODIFICATION - FUEL MANAGEMENT AND QUANTITY GAUGING SYSTEM (FMQGS) - UPGRADE OF THE FMQGS COMPUTERTO PART NO. GP546-1501-9 (A/C 9003, 9096, 9115 TO 9132), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-28-046 Airframe SB - Superseded #3761	MODIFICATION - FUEL MANAGEMENT AND QUANTITY GAUGING SYSTEM (FMQGS) - SEGREGATION OF PINS AT LTP1 TO PREVENT EXCESS EICAS ERRORMESSAGES (A/C 9002 TO 9126, 9128, 9129 AND 9131 TO 9139), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-28-046 R1 Airframe SB - Superseded #3134	MODIFICATION - FUEL MANAGEMENT AND QUANTITY GAUGING SYSTEM (FMQGS) - SEGREGATION OF PINS AT LTP1 TO PREVENT EXCESS EICAS ERRORMESSAGES (A/C 9002 TO 9126, 9128, 9129 AND 9131 TO 9139), SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-28-046 R2 Airframe SB - N/A #3456	MODIFICATION - FUEL MANAGEMENT AND QUANTITY GAUGING SYSTEM (FMQGS) - SEGREGATION OF PINS AT LTP1 TO PREVENT EXCESS EICAS ERRORMESSAGES (A/C 9002 TO 9126, 9128, 9129 AND 9131 TO 9139), SERVICE BULLETIN..	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-28-047 Airframe SB - Superseded #3663	MODIFICATION - REFUEL/DEFUEL SYSTEM - NEW TUBE INSTALLATION TO REDUCE REFUELING TIME (A/C 9002, 9004 TO 9095, 9097 TO 9158), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-28-047 R1 Airframe SB - N/A #3224	MODIFICATION - REFUEL/DEFUEL SYSTEM - NEW TUBE INSTALLATION TO REDUCE REFUELING TIME, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-28-048 Airframe SB - N/A #3996	MODIFICATION - DISTRIBUTION - CHANGE OF PLACARDS ON THE FUEL CONTROL PANEL FORAUTOMATIC FUEL RE-CIRCULATION SYSTEM (A/C 9159 TO 9219), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-28-049 Airframe SB - N/A #3826	MODIFICATION - FUEL MANAGEMENT AND QUANTITY GAUGING SYSTEM (FMQGS) - UPGRADE OF THE FMQGS COMPUTERTO PART NO. GP546-1501-11 (A/C 9003, 9096, 9115 TO 9126, AND 9128 TO 9301, AND A/C 9002, 9004 TO 9095 AND 9097 TO 9114 WITH A FMQGC -9 INSTALLED), SERV	H: 0.00					
	Notes SUPERSEDED						
SB 700-28-049 R1 Airframe SB - N/A #4092	MODIFICATION - FUEL MANAGEMENT AND QUANTITY GAUGING SYSTEM (FMQGS) - UPGRADE OF THE FMQGS COMPUTERTO PART NO. GP546-1501-11 OR GP546-1501-13, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-28-050 Airframe SB - N/A #3585	MODIFICATION - FUEL MANAGEMENT AND QUANTITY GAUGING SYSTEM (FMQGS) - UPGRADE OF THE FMQGS COMPUTERTO PART NO. GP546-1501-10 (A/C 9002, 9004 TO 9095 AND 9097 TO 9114), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-28-051 PART A Airframe SB - N/A #4271	SPECIAL CHECK/MODIFICATION/REWORK - FUEL FEED SYSTEM - INSPECT FUEL TUBE, PART NO. GD428-1003 FORFOULING ON BRACKET AND TRIM BRACKET TO PROVIDE LARGER CLEARANCE (A/C 9002 TO 9266), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-28-051 PART B Airframe SB - N/A #3219	SPECIAL CHECK/MODIFICATION/REWORK - FUEL FEED SYSTEM - INSPECT FUEL TUBE, PART NO. GD428-1003 FORFOULING ON BRACKET AND TRIM BRACKET TO PROVIDE LARGER CLEARANCE (A/C 9002 TO 9266), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-28-051 PART C Airframe SB - N/A #4339	SPECIAL CHECK/MODIFICATION/REWORK - FUEL FEED SYSTEM - INSPECT FUEL TUBE, PART NO. GD428-1003 FORFOULING ON BRACKET AND TRIM BRACKET TO PROVIDE LARGER CLEARANCE (A/C 9002 TO 9266), SERVICE BULLETIN..	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-28-052 Airframe SB #3784	MODIFICATION - AFT FUEL TANK - TRIM PULL TAB NEXT TO RELIEF VALVE, SERVICE BULLETIN					16-FEB-2021 H: 3992.00 L: 1324	
SB 700-28-053 Airframe SB - Open #4485	MODIFICATION - FUEL TRANSFERSYSTEM - DESIGN IMPROVEMENT TO THE CENTER TRANSFER PUMP, SERVICE BULLETIN	H: 0.00					
SB 700-28-054 PART A Airframe SB - Complied With #924	INSPECTION - SPECIAL CHECK/MODIFICATION - FUEL FEED SYSTEM - CHECK THE FUEL FEED LINE OF THE LEFT-HAND ENGINE FORCHAFING, SERVICE BULLETIN					04-DEC-2013 H: 561.10 L: 260	
	Notes COMPLIED WITH - PCW BY JET AVIATION REF, LOG BOOK ENTRY WO: GVBRL008.						
SB 700-28-054 PART B Airframe SB - N/A #368	REPLACEMENT - SPECIAL CHECK/MODIFICATION - FUEL FEED SYSTEM - CHECK THE FUEL FEED LINE OF THE LEFT-HAND ENGINE FORCHAFING,-OF THE FUEL FEED LINE					04-DEC-2013 H: 561.10 L: 260	
	Notes NOT APPLICABLE						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-28-054 Airframe SB - Complied With #352	SPECIAL CHECK/MODIFICATION - FUEL FEED SYSTEM - CHECK THE FUEL FEED LINE OF THE LEFT-HAND ENGINE FORCHAFING, SERVICE BULLETIN	04-DEC-2013 H: 561.10 L: 260					
	Notes COMPLIED WITH - PCW BY JET AVIATION REF, LOG BOOK ENTRY WO: GVBRL008.						
SB 700-28-082 Airframe SB - Open #4920	MODIFICATION - FLAP SYSTEM - MLG FLAP TORQUE TUBE FLAP CONTAINMENT IMPROVEMENT						
SB 700-29-013 Airframe SB - N/A #3307	MODIFICATION - NO. 3 HYDRAULIC SYSTEM - HYDRAULIC TUBE GM478-1442-9 REPLACEMENT, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-29-014 Airframe SB - N/A #4422	MODIFICATION - QUICK DISCONNECTS - ADD P-CLAMPS TO HYDRAULIC TUBES GM478-4300 AND GM478-4330 (CENTERWING AT FS573.70), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-29-015 Airframe SB - N/A #3066	MODIFICATION - HYDRAULIC SYSTEMS NO. 1 AND NO. 3 - REPLACE FLOW-DIRECTION IDENTIFICATION TAPE ON HYDRAULIC LINES (A/C 9022, 9039, 9044 AND 9057), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-29-017 Airframe SB - N/A #3530	SPECIAL CHECK/REWORK - NO. 1, NO. 2 AND NO. 3 HYDRAULIC SYSTEMS - INSPECTION OF ALL HYDRAULIC FILTERELEMENT PART NUMBERS, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-29-018 PART A Airframe SB - N/A #3765	SPECIAL CHECK/MODIFICATION - NO. 1 HYDRAULIC SYSTEM TUBES - INTERFERENCE BETWEEN TWO HYDRAULIC TUBES (A/C 9002 TO 9126 AND 9128 TO 9171), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-29-018 PART B Airframe SB - N/A #3543	SPECIAL CHECK/MODIFICATION - NO. 1 HYDRAULIC SYSTEM TUBES - INTERFERENCE BETWEEN TWO HYDRAULIC TUBES (A/C 9002 TO 9126 AND 9128 TO 9171), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-29-019 Airframe SB - N/A #3866	MODIFICATION - NO. 2 AND 3 HYDRAULIC SYSTEMS - REPLACE FAULTY PRIORITY VALVE PART NO. GX473-0060-1 (A/C 9145 TO 9148, 9150, 9151, 9153, 9162, 9163 AND 9165), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-29-020 PART A Airframe SB - N/A #4016	SPECIAL CHECK/REWORK - NO. 3 HYDRAULIC SYSTEM - CHECK FAILREAD SUPPORT BRACKETS FORCORRECT INSTALLATION AND REWORK HYDRAULIC TUBES IF DAMAGED (A/C 9002 TO 9126 AND 9128 TO 9215), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-29-020 PART B Airframe SB - N/A #3424	SPECIAL CHECK/REWORK - NO. 3 HYDRAULIC SYSTEM - CHECK FAILREAD SUPPORT BRACKETS FORCORRECT INSTALLATION AND REWORK HYDRAULIC TUBES IF DAMAGED (A/C 9002 TO 9126 AND 9128 TO 9215), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-29-021 Airframe SB - Superseded #3759	MODIFICATION - NO. 2 & NO. 3 HYDRAULIC SYSTEMS - RELOCATION OF HYDRAULIC LINES IN THE WING AUXILIARY SPAR, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-29-021 R1 Airframe SB - Complied With #2306	MODIFICATION - NO. 2 & NO. 3 HYDRAULIC SYSTEMS - RELOCATION OF HYDRAULIC LINES IN THE WING AUXILIARY SPAR, SERVICE BULLETIN.	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-29-022 Airframe SB - N/A #3046	MODIFICATION - NO. 1, NO. 2 AND NO. 3 HYDRAULIC SYSTEMS - REPLACEMENT OF HEAT-EXCHANGERBYPASS-VALVES WITH NON EPDM RUBBER, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-29-023 Airframe SB - N/A #3562	MODIFICATION - QUICK DISCONNECTS - RELOCATE AND REPLACE HYDRAULIC HOSE IN BOTH PYLONS, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-29-024 Airframe SB - Complied With #1552	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS NEW PRESSURE LINE BRACKET IN AFT EQUIPMENT BAY, SERVICE BULLETIN	12-SEP-2012 H: 388.37 L: 190					
	Notes COMPLIED WITH						
SB 700-29-025 Airframe SB - Complied With #545	SPECIAL CHECK/REWORK - NO. 1, NO. 2 AND NO. 3 HYDRAULIC SYSTEM ADDITION OF CLAMPS TO HYDRAULIC TUBES IN MLG BAY AND UNDERACCESS PANEL 185BL, SERVICE BULLETIN	12-SEP-2012 H: 388.37 L: 190					
	Notes COMPLIED WITH						
SB 700-29-026 PART B Airframe SB - Complied With #732	ACCOMPLISH - MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - REPLACEMENT OF EDP V-BAND COUPLING CLAMP,-EDP V-BAND COUPLING CLAMP REPLACEMENT	16-FEB-2012 H: 292.60 L: 134					
	Notes COMPLIED WITH - PART B ON #2 ENGINE ONLY						
SB 700-29-026 PART A Airframe SB - Complied With #2501	ACCOMPLISH - MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - REPLACEMENT OF EDP V-BAND COUPLING CLAMP,-INSPECTION	16-FEB-2012 H: 292.60 L: 134					
	Notes COMPLIED WITH - PART A ON BOTH ENGINES						



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-29-026 Airframe SB - Complied With #2352	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - REPLACEMENT OF EDP V-BAND COUPLING CLAMP, SERVICE BULLETIN	16-FEB-2012 H: 292.60 L: 134					
	Notes COMPLIED WITH						
SB 700-29-027 Airframe SB - Complied With #2651	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - HYDRAULIC FIREWALL SHUT-OFF VALVES (HF50V) INTRODUCTION OF IMPROVED ACTUATORAS A SEPARATE LRU PART NO. 975237-501 (GX473-0126-1), SERVICE BULLETIN	18-MAR-2015 H: 1339.30 L: 480					
	Notes COMPLIED WITH						
SB 700-29-028 PART A Airframe SB - Open #3371	MODIFICATION - MODIFICATION - NO. 3 HYDRAULIC SYSTEM - INSPECTION OF RAT ACCUMULATOREND CAPS, PART NO. 900094-5 (GX473-0100-5),- MARKING OF SUFFIX "E" AT THE END OF ACCUMULATOR SERIAL NO.	H: 0.00	L: 3500			L: 3859	L: 2364
SB 700-29-028 PART B Airframe SB - Open #3460	MODIFICATION - MODIFICATION - NO. 3 HYDRAULIC SYSTEM - INSPECTION OF RAT ACCUMULATOREND CAPS, PART NO. 900094-5 (GX473-0100-5),- REMOVAL - INSTALLATION OF NEW ACCUMULATOR (FOR ALL ACCUMULATORS, PART NO. 900094-5 NOT LISTED IN PART A AND WITHOUT "E	H: 0.00	L: 3500			L: 3859	L: 2364
SB 700-29-028 Airframe SB - Open #3451	MODIFICATION - NO. 3 HYDRAULIC SYSTEM - INSPECTION OF RAT ACCUMULATOREND CAPS, PART NO. 900094-5 (GX473-0100-5), SERVICE BULLETIN	H: 0.00					
SB 700-29-030 Airframe SB - Complied With #3656	MODIFICATION - NO. 3 HYDRAULIC SYSTEM - REPLACEMENT OF RAT ACCUMULATOR, PART NO. GX473-0100-5 WITH RAT ACCUMULATOR, PART NO. GX473-0100-7, SERVICE BULLETIN	23-NOV-2016 H: 2064.80 L: 722					
SB 700-29-031 Airframe SB - Complied With #4730	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - NEW PRESSURE LINE AND BRACKET IN AFT EQUIPMENT BAY HYDRAULIC SYSTEM NO. 1	23-NOV-2016 H: 2064.80 L: 722					
SB 700-29-031 R01 Airframe SB - Open #4949	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - NEW PRESSURE LINE AND BRACKET IN AFT EQUIPMENT BAY HYDRAULIC SYSTEM NO. 1						
SB 700-29-031 R02 Airframe SB - Open #5032	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - NEW PRESSURE LINE AND BRACKET IN AFT EQUIPMENT BAY HYDRAULIC SYSTEM NO. 1						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-29-031 R03 Airframe SB - Complied With #5070	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - NEW PRESSURE LINE AND BRACKET IN AFT EQUIPMENT BAY HYDRAULIC SYSTEM NO. 1	13-APR-2021 H: 3992.00 L: 1324					
SB 700-29-031 R4 Airframe SB - Open #5138	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - NEW PRESSURE LINE AND BRACKET IN AFT EQUIPMENT BAY HYDRAULIC SYSTEM NO. 1						
SB 700-29-032 Airframe SB - Superseded #4869	Modification No. 1 and No. 2 Hydraulic Systems Addition of Support Bracket on the Case Drain Line Notes SUPERSEDED						
SB 700-29-032 R1 Airframe SB - Superseded #4882	MODIFICATION NO. 1 AND NO. 2 HYDRAULIC SYSTEMS ADDITION OF SUPPORT BRACKET ON THE CASE DRAIN LINE Notes SUPERSEDED						
SB 700-29-032 R2 Airframe SB - Superseded #4897	MODIFICATION NO. 1 AND NO. 2 HYDRAULIC SYSTEMS ADDITION OF SUPPORT BRACKET ON THE CASE DRAIN LINE Notes SUPERSEDED						
SB 700-29-032 R3 Airframe SB #4940	MODIFICATION – NO. 2 HYDRAULIC SYSTEM – ADDITION OF SUPPORT BRACKET ON THE CASE DRAIN LINE	29-JAN-2021 H: 3992.00 L: 1324					
SB 700-30-015 Airframe SB - N/A #3694	MODIFICATION - ANTI-ICING SYSTEM - DUCT SUPPORTS AT FS708.00 TO GIVE ADDED CLEARANCE TO THE BELLY FAIRING, SERVICE BULLETIN Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-30-016 Airframe SB - N/A #4163	MODIFICATION - AIRDATA PROBES AND SENSORS - HEATER/BRAKE TEMPERATURE MONITORING UNITS (HBMU) SOFTWARE UPGRADE (A/C 9005 TO 9024 AND 9026 TO 9045), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-30-018 Airframe SB - Superseded #3468	SPECIAL CHECK/MODIFICATION - WING ANTI-ICING SYSTEM - BOROSCOPIC INSPECTION OF LEADING EDGE SLAT TELESCOPIC WIRING ASSEMBLIES FOR POSSIBLE DAMAGE (SUPERSEDED BY SB 700-30-020), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED BY SB 700-30-020						
SB 700-30-020 Airframe SB - N/A #4540	MODIFICATION - WING ANTI-ICING SYSTEM - INTRODUCTION OF IMPROVED TELESCOPIC WIRING FOR THE LEADING EDGE AND SLAT (A/C 9002, 9004, TO 9126, AND 9128 TO 9160), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-30-021 Airframe SB - Superseded #3782	MODIFICATION - AIRDATA PROBES AND SENSORS-RECONFIGURATION OF RELAY TO HMBU TO REMOVE NUMBER 2 PITOT HEAT NUISANCE, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-30-021 R1 Airframe SB - N/A #3375	MODIFICATION - AIRDATA PROBES AND SENSORS - RECONFIGURATION OF RELAY TO HMBU TO REMOVE NUMBER 2 PITOT HEAT NUISANCE, SERVICE BULLETIN	H: 0.00					
	Notes N/A PER S/N						
SB 700-30-022 Airframe SB - N/A #4555	SPECIAL CHECK/REWORK - WING ANTI-ICE (WAI) SYSTEM - CHECK SLAT-TO-SLAT DISTANCE AND SHIMS AT WAI FLEXIBLE JOINTS (EFFECTIVITY-9169 TO 9194), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-30-023 PART A Airframe SB - N/A #4395	MODIFICATION - MODIFICATION WING ANTI-ICING SYSTEM INSTALLATION OF A CONNECTOR ON THE INBOARD SENSOR,- LEFT WING	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-30-023 PART B Airframe SB - N/A #3869	MODIFICATION - MODIFICATION WING ANTI-ICING SYSTEM INSTALLATION OF A CONNECTOR ON THE INBOARD SENSOR,- RIGHT WING	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-30-023 Airframe SB - N/A #3230	MODIFICATION - WING ANTI-ICING SYSTEM INSTALLATION OF A CONNECTOR ON THE INBOARD SENSOR, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-30-023 R1 Airframe SB - N/A #4796	MODIFICATION - ANTI-ICING SYSTEM - INSTALLATION OF A CONNECTOR ON THE INBOARD SENSOR (REV. 1)						
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-30-024 Airframe SB - N/A #4460	SPECIAL CHECK/MODIFICATION - WINDSHIELD AND SIDE WINDOW ANTI-ICING SYSTEM - CHECK THE HEATERBRAIDED WIRE CONNECTION OF THE WINDSHIELD (A/C 9002 TO 9257), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-30-025 Airframe SB - N/A #3873	SPECIAL CHECK/REWORK - WING ANTI-ICING (WAI) SYSTEM - INSPECT WAI DUCT BELLOWS FOR CHAFING WITH ELEVATOR CABLE (A/C 9002 TO 9126, 9128 TO 9235 AND 9237 TO 9244), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-30-026 Airframe SB - Complied With #4222	MODIFICATION - ANTI-ICING SYSTEM - PART NO. CHANGE OF THE WING ANTI-ICE VALVE (WAIV) TO GG436-4001-13, SERVICE BULLETIN	02-MAY-2016 H: 1810.40 L: 647					
	Notes COMPLIED WITH SB 700-30-026						
SB 700-31-009 Airframe SB - N/A #4252	MODIFICATION - INTEGRATED AVIONICS COMPUTER(IAC) SYSTEM - INTRODUCTION OF NEW UNITS FOR FULL FUNCTIONALITY CERTIFICATION, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-31-010 Airframe SB - N/A #3763	MODIFICATION - INDICATING/RECORDING SYSTEM - DATA ACQUISITION UNITS (DAU) - REPLACEMENT FORFULL FUNCTIONALITY CERTIFICATION, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-31-012 Airframe SB - Superseded #4156	MODIFICATION - CLOCK SYSTEM - INTRODUCTION OF TWO DIGITAL CLOCKS USING GPS INPUT FORTIME SETTING, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-31-012 R1 Airframe SB - N/A #3198	MODIFICATION - CLOCK SYSTEM - INTRODUCTION OF TWO DIGITAL CLOCKS USING GPS INPUT FORTIME SETTING, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-31-013 Airframe SB - N/A #4344	MODIFICATION - IAC/DAU - SOFTWARE UPDATE FORPOST FULL FUNCTIONALITY CERTIFICATION, RECOMMENDED	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-31-014 Airframe SB - Superseded #3865	MODIFICATION) FLIGHT DATA RECORDING-SYSTEM) INSTALLATION OF ROTARY VARIABLE DIFFERENTIAL TRANSFORMERS (RVDT) TO RECORD THE CONTROL COLUMNS AND RUDDERPEDALS POSITIONS, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-31-014 R1 Airframe SB - N/A #3590	MODIFICATION) FLIGHT DATA RECORDING-SYSTEM) INSTALLATION OF ROTARY VARIABLE DIFFERENTIAL TRANSFORMERS (RVDT) TO RECORD THE CONTROL COLUMNS AND RUDDERPEDALS POSITIONS (SERIAL NO. 9002, 9025, 9066 TO 9089), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-31-015 Airframe SB - N/A #3799	SPECIAL CHECK/MODIFICATION - INTEGRATED AVIONICS COMPUTER(IAC) - POSSIBLE CRACKS ON MOUNTING TRAY, MODEL NO. MT-854, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-31-016 Airframe SB - N/A #3919	MODIFICATION - DATA ACQUISITION SYSTEM - DATA ACQUISITION UNIT (DAU) SOFTWARE UPGRADE TO P/N 10604B03M09 (EFFECTIVITY 9002 TO 9106 AND 9108 TO 9117), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-31-017 Airframe SB - N/A #4086	MODIFICATION - CENTRAL WARNING SYSTEM - INSTALLATION OF AUDIO PANELS WITH LOWERAURAL WARNING AUDIO SETTINGS, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-31-018 Airframe SB - Superseded #3942	MODIFICATION - INTEGRATED AVIONICS COMPUTERS (IAC) - AVIONICS 2001 BATCH 1 IAC UPGRADE, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-31-018 R1 Airframe SB - N/A #3469	MODIFICATION - INTEGRATED AVIONICS COMPUTERS (IAC) - AVIONICS 2001 BATCH 1 IAC UPGRADE, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-31-019 PART A Airframe SB - N/A #3582	MODIFICATION - FLIGHT DATA RECORDING (FDR) SYSTEM - PROVISIONS FOR THE CREW FORCE MEASURING SYSTEM (CFMS) 2002, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-31-019 PART B Airframe SB - N/A #3354	MODIFICATION - FLIGHT DATA RECORDING (FDR) SYSTEM - PROVISIONS FOR THE CREW FORCE MEASURING SYSTEM (CFMS) 2002, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-31-020 PART A Airframe SB - Superseded #3415	MODIFICATION - FLIGHT DATA RECORDING (FDR) SYSTEM - INSTALLATION OF THE FORCE TRANSDUCER UNITS (FTU) AND ACTIVATION OF THE CREW FORCE MEASURING SYSTEM (CFMS) 2002 (A/C 9107 AND 9119 TO 9147), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-31-020 PART B Airframe SB - Superseded #3103	MODIFICATION - FLIGHT DATA RECORDING (FDR) SYSTEM - INSTALLATION OF THE FORCE TRANSDUCER UNITS (FTU) AND ACTIVATION OF THE CREW FORCE MEASURING SYSTEM (CFMS) 2002 (A/C 9119 TO 9999), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-31-020 R1 PART A Airframe SB - Superseded #3991	MODIFICATION - FLIGHT DATA RECORDING (FDR) SYSTEM - INSTALLATION OF THE FORCE TRANSDUCER UNITS (FTU) AND ACTIVATION OF THE CREW FORCE MEASURING SYSTEM (CFMS) 2002 (A/C 9107 AND 9119 TO 9147), SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-31-020 R1 PART B Airframe SB - Superseded #3690	MODIFICATION - FLIGHT DATA RECORDING (FDR) SYSTEM - INSTALLATION OF THE FORCE TRANSDUCERUNITS (FTU) AND ACTIVATION OF THE CREW FORCE MEASURING SYSTEM (CFMS) 2002 (A/C 9119 TO 9999), SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-31-020 R2 Airframe SB - Open #3381	MODIFICATION - FLIGHT DATA RECORDING (FDR) SYSTEM - INSTALLATION OF THE FORCE TRANSDUCERUNITS (FTU) AND ACTIVATION OF THE CREW FORCE MEASURING SYSTEM (CFMS) 2002, SERVICE BULLETIN	H: 0.00					
SB 700-31-020 R2 PART B Airframe SB - Open #3287	MODIFICATION - MODIFICATION - FLIGHT DATA RECORDING (FDR) SYSTEM - INSTALLATION OF THE FORCE TRANSDUCERUNITS (FTU) AND ACTIVATION OF THE CREW FORCE MEASURING SYSTEM (CFMS) 2002,- INSTALLATION OF THE FTUS AND ACTIVATION OF THE CFMS	H: 0.00					
SB 700-31-020 R2 PART A Airframe SB - Open #4221	MODIFICATION - MODIFICATION - FLIGHT DATA RECORDING (FDR) SYSTEM - INSTALLATION OF THE FORCE TRANSDUCERUNITS (FTU) AND ACTIVATION OF THE CREW FORCE MEASURING SYSTEM (CFMS) 2002,- REPLACEMENT OF THE FDR AND THE DAU 1, 2, 3 AND 4	H: 0.00					
SB 700-31-020 R3 Airframe SB - Open #5156	MODIFICATION - FLIGHT DATA RECORDING (FDR) SYSTEM -INSTALLATION OF THE FORCE TRANSDUCER UNITS (FTU) AND ACTIVATIONOF THE CREW FORCE MEASURING SYSTEM (CFMS) 2002						
SB 700-31-021 Airframe SB - Superseded #4556	MODIFICATION - INTEGRATED AVIONICS COMPUTER(IAC) SYSTEM - BATCH 2 IAC UPGRADE (A/C 9002 TO 9153), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-31-021 R1 Airframe SB - N/A #3447	MODIFICATION - INTEGRATED AVIONICS COMPUTER(IAC) SYSTEM - BATCH 2 IAC UPGRADE (A/C 9002 TO 9153), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-31-022 Airframe SB - N/A #3864	MODIFICATION - DATA ACQUISITION SYSTEM - DATA ACQUISITION UNIT (DAU) UPGRADE TO PART NO. 10604B03M09. EFFECTIVITY S/N 9118 TO 9126 AND 9128 TO 9158, SERVICE BULLETIN Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					
SB 700-31-023 Airframe SB - N/A #3567	MODIFICATION - WARNING/CAUTION CONTROL SYSTEM - REDUCTION OF AURAL WARINING OUTPUTS (9002 TO 9208), SERVICE BULLETIN Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					
SB 700-31-024 Airframe SB - N/A #3568	MODIFICATION - INTEGRATED AVIONICS COMPUTER(IAC) SYSTEM - RETERMINATE EGPWS STRAPPING TO GIVE PRIORITY TO IACS "MINIMUMS, MINIMUMS" AURAL CALLOUT, SERVICE BULLETIN Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					
SB 700-31-025 Airframe SB - Superseded #3250	MODIFICATION - INTEGRATED AVIONICS COMPUTER(IAC) SYSTEM - BATCH 2+ IAC UPGRADE (A/C 9002 TO 9174), SERVICE BULLETIN Notes SUPERSEDED	H: 0.00					
SB 700-31-025 R1 Airframe SB - N/A #3726	MODIFICATION - INTEGRATED AVIONICS COMPUTER(IAC) SYSTEM - BATCH 2+ IAC UPGRADE (A/C 9002 TO 9174), SERVICE BULLETIN. Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					
SB 700-31-026 Airframe SB - Superseded #4059	MODIFICATION - FLIGHT DATA RECORDING-SYSTEM - INTRODUCTION OF A QUICK ACCESS RECORDER(A/C S/N 9002 TO 9999), SERVICE BULLETIN Notes SUPERSEDED	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-31-026 R1 Airframe SB - Superseded #3649	MODIFICATION - FLIGHT DATA RECORDING-SYSTEM - INTRODUCTION OF A QUICK ACCESS RECORDER(A/C S/N 9002 TO 9999), SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-31-026 R2 Airframe SB - Complied With #1340	MODIFICATION - FLIGHT DATA RECORDING-SYSTEM - INTRODUCTION OF A QUICK ACCESS RECORDER, SERVICE BULLETIN	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
SB 700-31-027 Airframe SB - N/A #3102	MODIFICATION - INTEGRATED AVIONICS COMPUTER(IAC) SYSTEM - DISPLAY OF METRIC UNITS INSTEAD OF IMPERIAL UNITS, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-31-027 R1 Airframe SB - Open #3595	MODIFICATION - INTEGRATED AVIONICS COMPUTER(IAC) SYSTEM - DISPLAY OF METRIC UNITS INSTEAD OF IMPERIAL UNITS, SERVICE BULLETIN.	H: 0.00					
SB 700-31-028 Airframe SB - N/A #4364	MODIFICATION - INTEGRATED AVIONIC COMPUTER(IAC) SYSTEM - EXAMINE IACS FOR POSSIBLE DEFECTIVE SRAM DEVICES, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-31-030 Airframe SB - Superseded #4514	MODIFICATION - INTEGRATED AVIONICS COMPUTER(IAC) SYSTEM - BATCH 3 SOFTWARE UPGRADE, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-31-030 R1 Airframe SB - Superseded #3471	MODIFICATION - INTEGRATED AVIONICS COMPUTER(IAC) SYSTEM - BATCH 3 SOFTWARE UPGRADE, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-31-030 R2 Airframe SB - Complied With #939	MODIFICATION - INTEGRATED AVIONICS COMPUTER(IAC) SYSTEM - BATCH 3 SOFTWARE UPGRADE, SERVICE BULLETIN..	25-JAN-2014 H: 649.70 L: 284					
	Notes COMPLIED WITH						
SB 700-31-030 R3 Airframe SB - N/A #2	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - BATCH 3 SOFTWARE UPGRADE (REV. 3)						
	Notes PREVIOUSLY COMPLIED WITH						
SB 700-31-030 R4 Airframe SB - N/A #4766	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - BATCH 3 SOFTWARE UPGRADE (REV. 4)						
	Notes PREVIOUSLY COMPLIED WITH						
SB 700-31-031 Airframe SB - N/A #3993	MODIFICATION - INTEGRATED AVIONICS COMPUTER(IAC) SYSTEM - IAC -009 SOFTWARE UPGRADE (A/C 9128 TO 9174 POST SB 700-31-025 AND 9175 TO 9244), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-31-034 Airframe SB - Superseded #4732	MODIFICATION - CENTRAL PROCESSING SYSTEM - BATCH 3.3 SOFTWARE UPGRADE						
	Notes SUPERSEDED						
SB 700-31-034 R1 Airframe SB - Complied With #4757	MODIFICATION - CENTRAL PROCESSING SYSTEM - BATCH 3.3 SOFTWARE UPGRADE (REV. 1)	23-NOV-2016 H: 2064.80 L: 722					
SB 700-31-034 R2 Airframe SB - N/A #4794	MODIFICATION – INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM – BATCH 3 SOFTWARE UPGRADE (REV. 2)						
	Notes PREVIOUSLY COMPLIED WITH REV 1						



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-31-038 R01 Airframe SB - Open #4928	MODIFICATION – ELECTRONIC FLIGHT-INSTRUMENT SYSTEM (EFIS) – INSTALLATION OF SYNTHETIC VISION WITH THE PRIMUS ELITE DU-875AF						
SB 700-31-038 R02 Airframe SB - Open #5072	MODIFICATION - ELECTRONIC FLIGHT-INSTRUMENT SYSTEM (EFIS) - INSTALLATION OF SYNTHETIC VISION WITH THE PRIMUS ELITE DU-875AF						
SB 700-31-039 Airframe SB - Open #4927	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - BATCH 3.4 SOFTWARE UPGRADE						
SB 700-31-039 R01 Airframe SB - Open #4932	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - BATCH 3.4 SOFTWARE UPGRADE						
SB 700-31-039 R02 Airframe SB - Complied With #4991	MODIFICATION - INTEGRATED AVIONICS COMPUTER (IAC) SYSTEM - BATCH 3.4 SOFTWARE UPGRADE					18-APR-2020 H: 3741.10 L: 1233	
SB 700-31-040 Airframe SB - Open #5034	MODIFICATION - FLIGHT DATA RECORDING SYSTEM - INTRODUCTION OF A QUICK ACCESS RECORDER						
SB 700-31-6002 R1 Airframe SB - Open #4939	MODIFICATION FLIGHT DATA - RECORDING (FDR) SYSTEM - INSTALLATION OF THE FORCE TRANSDUCER UNITS (FTU) AND ACTIVATION OF THE CREW FORCE MEASURING SYSTEM (CFMS) 2002						
SB 700-31-6004 R03 Airframe SB - Open #4917	MODIFICATION - FLIGHT DATA RECORDING SYSTEM- IMPLEMENTATION OF GVFD AVIONICS SOFTWARE VERSION 5.2 FDR PARAMETER UPDATE						
SB 700-32-006 Airframe SB - N/A #4218	MODIFICATION - LANDING GEAREMERGENCY EXTENSION - INSTALLATION OF A NEW SUPPORT PLATE ON THE SHUTOFF AND DUMP VALVE ASSEMBLY, SERVICE BULLETIN					H: 0.00	
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-32-007 Airframe SB - Superseded #3357	MODIFICATION - NOSE GEAREXTENSION AND RETRACTION - DOOR UPLOCK FITTING REPLACEMENT (A/C 9002 TO 9085, 9091 TO 9093), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-32-007 R1 Airframe SB - N/A #3100	MODIFICATION - NOSE GEAREXTENSION AND RETRACTION - DOOR UPLOCK FITTING REPLACEMENT (A/C 9002 TO 9085, 9091 TO 9093), SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-32-007 R2 Airframe SB - N/A #4573	MODIFICATION - NOSE GEAREXTENSION AND RETRACTION - DOOR UPLOCK FITTING REPLACEMENT, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-32-008 Airframe SB - N/A #3356	SPECIAL CHECK/MODIFICATION - NOSE-GEARDOOR SYSTEM - FORWARD DOOR SPRING, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-32-010 Airframe SB - Superseded #3249	REWORK - MAIN LANDING GEAR(MLG) - SERIALIZATION OF MLG SIDE STAY PIN (A/C 9002 TO 9173), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-32-010 R1 Airframe SB - N/A #3940	REWORK - MAIN LANDING GEAR(MLG) - SERIALIZATION OF MLG SIDE STAY PIN (A/C 9002 TO 9173), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-32-013 Airframe SB - N/A #4164	SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR- INSTALLATION OF NINE-PIECE RETAINING RING ON NOSE LANDING GEAR SHOCK STRUT, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-32-014 Airframe SB - N/A #4047	MODIFICATION/REWORK - MAIN LANDING GEAR(MLG) - TO PREVENT INGRESS OF MOISTURE TO THE MLG SIDE BRACE INDICATOR HOUSING, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-32-015 Airframe SB - Superseded #3908	SPECIAL CHECK/REWORK - BRAKE CONTROL SYSTEM - CHECK TORQUE AND SAFETY HYDRAULIC LINES WITH SUPPORT HARDWARE, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-32-015 R1 Airframe SB - N/A #3965	SPECIAL CHECK/REWORK - BRAKE CONTROL SYSTEM - CHECK TORQUE AND SAFETY HYDRAULIC LINES WITH SUPPORT HARDWARE, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-32-016 Airframe SB - N/A #3117	MODIFICATION - BRAKE CONTROL SYSTEM - PART NO. CHANGE OF THE BRAKE CONTROL UNIT TO GW415-7125-5, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-32-018 Airframe SB - Open #3267	MODIFICATION - GENERAL - PREVENT INGRESS OF FOREIGN OBJECT DAMAGE (FOD) IN THE MAIN LANDING GEAR(MLG) WHEEL WELL (9002 TO 9126 AND 9128 TO 9999)., SERVICE BULLETIN	H: 0.00					
SB 700-32-021 Airframe SB - Superseded #3084	SPECIAL CHECK/MODIFICATION - WHEELS AND BRAKES SYSTEM - INSPECT BRAKES FOR IMPROPER OXIDATION INHIBITOR AND REPLACE WHERE FOUND (A/C 9173, 9175, 9177, 9179, 9181, 9183, 9184, 9185, 9193, 9194, 9199, 9220, 9230, 9234, 9235, 9236, 9238, 9240, 9242, 924)	H: 0.00					
	Notes SUPERSEDED						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-32-021 R1 Airframe SB - Superseded #4532	SPECIAL CHECK/MODIFICATION - WHEELS AND BRAKES SYSTEM - INSPECT BRAKES FOR IMPROPER OXIDATION INHIBITOR AND REPLACE WHERE FOUND (A/C 9002 TO 9302), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-32-021 R2 Airframe SB - Superseded #3756	SPECIAL CHECK/MODIFICATION - WHEELS AND BRAKES - INSPECT BRAKES FOR IMPROPER OXIDATION INHIBITOR AND REPLACE WHERE FOUND, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-32-021 R3 Airframe SB - N/A #3056	ICA - SPECIAL CHECK/MODIFICATION - WHEELS AND BRAKES - INSPECT BRAKES FOR IMPROPER OXIDATION INHIBITOR AND REPLACE WHERE FOUND, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-32-022 Airframe SB - N/A #3594	MODIFICATION - MAIN GEARDOOR SYSTEM - INSTALLATION OF IMPROVED MLG DOOR SURROUND FAIRING CLIP (EFFECTIVITY 9002 TO 9272), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-32-023 Airframe SB - Complied With #2303	MODIFICATION - NOSE-GEARDOOR SYSTEM - IMPROVED INSTALLATION OF THE NLG DOOR PROXIMITY SWITCH TARGET, SERVICE BULLETIN	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
SB 700-32-024 PART A Airframe SB - N/A #4272	MODIFICATION - MAIN LANDING GEAR (MLG) - REPLACE SUSPECT SHOCK STRUT PINS (A/C 9002 TO 9009, 9016, 9019, 9020, 9024, 9060, 9062 AND 9104), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-32-024 PART B Airframe SB - N/A #4143	MODIFICATION - MAIN LANDING GEAR(MLG) - REPLACE SUSPECT SHOCK STRUT PINS (A/C 9002 TO 9009, 9016, 9019, 9020, 9024, 9060, 9062 AND 9104), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-32-027 Airframe SB - N/A #3336	SPECIAL CHECK/MODIFICATION - LANDING-GEARCONTROL SYSTEM - REPLACEMENT OF LANDING-GEAR SELECTOR-VALVE, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-32-028 Airframe SB - N/A #2050	REWORK - BRAKE CONTROL SYSTEM APPLICATION OF SEALANT AT THE AXLE TRAILING ARM AND WHEEL SPEED TRANSDUCER-HARNESS, SERVICE BULLETIN	12-SEP-2012 H: 388.37 L: 190					
	Notes NOT APPLICABLE - N/A BY EFFECTIVITY						
SB 700-32-028 R1 Airframe SB - Complied With #739	REWORK - BRAKE CONTROL SYSTEM - APPLICATION OF SEALANT AT THE AXLE TRAILING ARM AND WHEEL SPEED TRANSDUCER-HARNESS, SERVICE BULLETIN	20-JUN-2015 H: 1493.00 L: 523					
	Notes COMPLIED WITH						
SB 700-32-028 R2 Airframe SB - Open #3697	REWORK - BRAKE CONTROL SYSTEM - APPLICATION OF SEALANT AT THE AXLE TRAILING ARM AND WHEEL SPEED TRANSDUCER-HARNESS, SERVICE BULLETIN.	H: 0.00					
SB 700-32-029 PART A Airframe SB - Open #4341	INSPECTION - MODIFICATION - BRAKE CONTROL SYSTEM - INSPECTION OF HYDRAULIC SYSTEM NO. 2 OUTBOARD BRAKE ACCUMULATOR, PART NO. GW415-1250-1 (24550-101), SERVICE BULLETIN	H: 0.00	L: 3500			L: 3892	L: 2397
SB 700-32-029 Airframe SB - Open #4293	MODIFICATION - BRAKE CONTROL SYSTEM - INSPECTION OF HYDRAULIC SYSTEM NO. 2 OUTBOARD BRAKE ACCUMULATOR, PART NO. GW415-1250-1 (24550-101), SERVICE BULLETIN	H: 0.00					
SB 700-32-029 PART B Airframe SB - Open #4465	MODIFICATION - BRAKE CONTROL SYSTEM - INSPECTION OF HYDRAULIC SYSTEM NO. 2 OUTBOARD BRAKE ACCUMULATOR, PART NO. GW415-1250-1 (24550-101),-MODIFICATION	H: 0.00	L: 3500			L: 3892	L: 2397

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-32-030 Airframe SB - Open #3764	MODIFICATION - BRAKE CONTROL SYSTEM - INSPECTION OF HYDRAULIC SYSTEM NO. 3 INBOARD BRAKE ACCUMULATOR, PART NO. GW415-1200-1 (33-119500), SERVICE BULLETIN	H: 0.00					
SB 700-32-030 PART A Airframe SB - Open #3318	MODIFICATION - BRAKE CONTROL SYSTEM - INSPECTION OF HYDRAULIC SYSTEM NO. 3 INBOARD BRAKE ACCUMULATOR, PART NO. GW415-1200-1 (33-119500),-MODIFICATION - MARKING OF SUFFIX "E" AT THE END OF ACCUMULATOR SERIAL NO.	H: 0.00	L: 3500			L: 3892	L: 2397
SB 700-32-030 PART B Airframe SB - Open #4217	MODIFICATION - BRAKE CONTROL SYSTEM - INSPECTION OF HYDRAULIC SYSTEM NO. 3 INBOARD BRAKE ACCUMULATOR, PART NO. GW415-1200-1 (33-119500),-MODIFICATION - REMOVAL - INSTALLATION OF NEW ACCUMULATOR	H: 0.00	L: 3500			L: 3892	L: 2397
SB 700-32-031 PART A Airframe SB - Complied With #2998	INSPECTION - SPECIAL CHECK/MODIFICATION - BRAKE CONTROL SYSTEM -POSSIBILITY OF UNEXPECTED BRAKE RELEASING AT LOW TAXI SPEED, OF THE WHEEL SPEED TRANSDUCERS	10-DEC-2014 H: 1111.80 L: 414					
	Notes COMPLIED WITH						
SB 700-32-031 PART B Airframe SB - Complied With #1160	REPLACEMENT - SPECIAL CHECK/MODIFICATION - BRAKE CONTROL SYSTEM -POSSIBILITY OF UNEXPECTED BRAKE RELEASING AT LOW TAXI SPEED, OF THE WHEEL SPEED TRANSDUCERS	10-DEC-2014 H: 1111.80 L: 414					
	Notes COMPLIED WITH						
SB 700-32-031 Airframe SB - Complied With #1108	SPECIAL CHECK/MODIFICATION - BRAKE CONTROL SYSTEM -POSSIBILITY OF UNEXPECTED BRAKE RELEASING AT LOW TAXI SPEED, SERVICE BULLETIN	10-DEC-2014 H: 1111.80 L: 414					
	Notes COMPLIED WITH						
SB 700-32-032 Airframe SB - Open #3395	ICA - SPECIAL CHECK/MODIFICATION - BRAKE CONTROL UNIT (BCU) - INSPECTION AND REPLACEMENT OF PART NUMBER42-965-2 WITH INCORRECT ZENER DIODES INSTALLED, SERVICE BULLETIN	H: 0.00					
SB 700-32-032 PART A Airframe SB - Open #3246	INSPECTION - ICA - SPECIAL CHECK/MODIFICATION - BRAKE CONTROL UNIT (BCU) - INSPECTION AND REPLACEMENT OF PART NUMBER42-965-2 WITH INCORRECT ZENER DIODES INSTALLED, SERVICE BULLETIN	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-32-032 PART B Airframe SB - Open #4066	REMOVE - ICA - SPECIAL CHECK/MODIFICATION - BRAKE CONTROL UNIT (BCU) - INSPECTION AND REPLACEMENT OF PART NUMBER42-965-2 WITH INCORRECT ZENER DIODES INSTALLED,-AND REPLACE THE BCU	H: 0.00					
SB 700-32-033 Airframe SB - Complied With #7	MODIFICATION - BRAKE CONTROL SYSTEM - REPLACEMENT OF NO. 3 BRAKE ACCUMULATOR, PART NO. GW415-1200-1 WITH NO. 3 BRAKE ACCUMULATOR, PART NO. GW415-1200-3, SERVICE BULLETIN	09-SEP-2015 H: 1566.00 L: 552					
Notes COMPLIED WITH - LEAKING END CAP							
SB 700-32-034 Airframe SB - Open #4257	MODIFICATION - BRAKE CONTROL SYSTEM - INTRODUCTION OF WHEEL SPEED TRANSDUCERPART NO 140-209-4 (GW415-1050-9), SERVICE BULLETIN	10-DEC-2014 H: 1111.80 L: 414					
SB 700-32-034 R1 PART A Airframe SB - Open #4521	INSPECTION - SPECIAL CHECK/MODIFICATION - BRAKE CONTROL SYSTEM - INTRODUCTION OF IMPROVED WHEEL SPEED TRANSDUCERS, SERVICE BULLETIN	H: 0.00					
SB 700-32-034 R1 PART B Airframe SB - Open #3783	MODIFICATION - SPECIAL CHECK/MODIFICATION - BRAKE CONTROL SYSTEM - INTRODUCTION OF IMPROVED WHEEL SPEED TRANSDUCERS, SERVICE BULLETIN	H: 0.00					
SB 700-32-034 R1 Airframe SB - Open #3187	SPECIAL CHECK/MODIFICATION - BRAKE CONTROL SYSTEM - INTRODUCTION OF IMPROVED WHEEL SPEED TRANSDUCERS, SERVICE BULLETIN	H: 0.00					
SB 700-32-034 R2 Airframe SB - Open #1	MODIFICATION - BRAKE CONTROL SYSTEM - INTRODUCTION OF WHEEL SPEED TRANSDUCER PART NO 140-209-4 (GW415-1050-9) (REV. 2)						
SB 700-32-035 PART B Airframe SB - Complied With #1576	ICA - SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR(NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN-FITTING JOINT, NLG STRUT IDENTIFICATION PLATE MODIFICATION NUMBER CHECK	18-JUN-2015 H: 1493.00 L: 523					
Notes COMPLIED WITH							





Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-32-035 Airframe SB - Complied With #1411	ICA - SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR(NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN-FITTING JOINT, SERVICE BULLETIN	18-JUN-2015 H: 1493.00 L: 523					
	Notes COMPLIED WITH						
SB 700-32-035 PART C Airframe SB - N/A #2384	INSTALLATION - ICA - SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR(NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN-FITTING JOINT, OF THE NEW ATTACHMENT HARDWARE SECURING THE RETRACTION ACTUATOR TO NLG STRUT	18-JUN-2015 H: 1493.00 L: 523					
	Notes NOT APPLICABLE						
SB 700-32-035 PART A Airframe SB - Complied With #114	VISUAL INSPECTION-ICA - SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR(NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN - FITTING JOINT, OF THE BOLT THAT SECURES THE RETRACTION ACTUATOR TO THE NLG STRUT	18-JUN-2015 H: 1493.00 L: 523					
	Notes COMPLIED WITH						
SB 700-32-035 R1 Airframe SB - Open #3998	ICA - SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR(NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN	H: 0.00					
SB 700-32-035 R1 PART B Airframe SB - Open #4144	ICA - SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR(NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT,-NLG STRUT IDENTIFICATION PLATE MODIFICATION NUMBER CHECK	H: 0.00					
SB 700-32-035 R1 PART C Airframe SB - Open #3909	INSTALLATION - ICA - SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR(NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT,-OF THE NEW ATTACHMENT HARDWARE SECURING THE RETRACTION ACTUATOR TO NLG STRUT	H: 0.00					
SB 700-32-035 R1 PART A Airframe SB - Open #4181	VISUAL INSPECTION-ICA - SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR(NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, - OF THE BOLT THAT SECURES THE RETRACTION ACTUATOR TO THE NLG STRUT	H: 0.00					
SB 700-32-035 R2 Airframe SB - Complied With #4823	SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT (REV. 2)	14-APR-2021 H: 3992.00 L: 1324					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-32-037 PART A Airframe SB - Complied With #3243	ACCOMPLISH - MODIFICATION - PARKING BRAKE SYSTEM - REPLACEMENT OF THE PARK BRAKE HANDLE ASSEMBLY,-VISUAL INSPECTION OF THE EMERGENCY/PARKING BRAKE HANDLE ASSEMBLY	04-MAR-2016 H: 1753.70 L: 622					
SB 700-32-037 Airframe SB - Complied With #3704	MODIFICATION - PARKING BRAKE SYSTEM - REPLACEMENT OF THE PARK BRAKE HANDLE ASSEMBLY, SERVICE BULLETIN	04-MAR-2016 H: 1753.70 L: 622					
SB 700-32-037 PART B Airframe SB - Complied With #3639	REPLACEMENT - MODIFICATION - PARKING BRAKE SYSTEM - REPLACEMENT OF THE PARK BRAKE HANDLE ASSEMBLY,-OF THE EMERGENCY/PARKING BREAK HANDLE ASSEMBLY	04-MAR-2016 H: 1753.70 L: 622					
SB 700-32-038 Airframe SB - Open #4686	REPAIR – NOSE WHEEL STEERING CONTROL SYSTEM – NOSEWHEEL-STEERING CONTROL SYSTEM – REPAIR OF STEERING CYLINDER LVDT CONDUIT, PART NO. 9070A0036-01						
SB 700-32-038 R1 Airframe SB - Complied With #4728	REPAIR - NOSE WHEEL STEERING CONTROL SYSTEM - NOSEWHEEL-STEERING CONTROL SYSTEM - REPAIR OF STEERING CYLINDER LVDT CONDUIT, PART NO. 9070A0036-01 (REV. 1)	23-NOV-2016 H: 2064.80 L: 722					
SB 700-32-039 Airframe SB - Superseded #4921	SPECIAL CHECK– MAIN LANDING GEAR– TRAILING ARM ASSEMBLY INSPECTION OF THE PAINT IN THE AXLE BORE						
	Notes SUPERSEDED BY R01						
SB 700-32-039 R01 Airframe SB - N/A #4948	SPECIAL CHECK - MAIN LANDING GEAR - TRAILING ARM ASSEMBLY INSPECTION OF THE PAINT IN THE AXLE BORE	27-FEB-2020 H: 3695.30 L: 1216					
SB 700-32-040 Airframe SB - N/A #4903	MODIFICATION - BRAKE CONTROL SYSTEM - LH AND RH ASSEMBLY REPLACEMENT OF THE SWIVEL JOINT ASSEMBLIES	22-FEB-2021					
	Notes NA - PER SAFRAN SB CHECKLIST						
SB 700-32-042 Airframe SB #5082	MODIFICATION - MLG - MAIN LANDING GEAR ASSEMBLY IMPROVED RESISTANCE TO WATER INGRESS	22-FEB-2021 H: 3992.00 L: 1324					





Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-32-042 R1 Airframe SB - Open #5086	MODIFICATION - MLG - MAIN LANDING GEAR ASSEMBLY IMPROVED RESISTANCE TO WATER INGRESS						
SB 700-32-043 Airframe SB - Open #5153	SPECIAL CHECK-BRAKE CONTROL SYSTEM-DETERMINATION OF HYDRAULIC SYSTEM NO.2 AND NO.3 BRAKE ACCUMULATOR CYCLES(PARTNO.GW415-1250 AND GW415-1200)						
SB 700-32-043 R1 Airframe SB - Open #5173	SPECIAL CHECK-BRAKE CONTROL SYSTEM-DETERMINATION OF HYDRAULIC SYSTEM NO.2 AND NO.3 BRAKE ACCUMULATOR CYCLES (PARTNO.GW415-1250 AND GW415-1200)						
SB 700-33-001 Airframe SB - Superseded #3688	MODIFICATION - LOGO LIGHTING - ADDITION OF LOGO LIGHTS, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-33-001 R1 Airframe SB - Superseded #3853	MODIFICATION - LOGO LIGHTING - ADDITION OF LOGO LIGHTS, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-33-001 R2 Airframe SB - Superseded #3551	MODIFICATION - LOGO LIGHTING - ADDITION OF LOGO LIGHTS (A/C 9002 TO 9999), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-33-001 R3 Airframe SB - Complied With #985	MODIFICATION - LOGO LIGHTING - ADDITION OF LOGO LIGHTS (A/C 9002 TO 9398), SERVICE BULLETIN	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-33-010 Airframe SB - N/A #4619	MODIFICATION - SERVICE COMPARTMENT LIGHTING - RELOCATION OF AVIONICS BAY LIGHT SWITCHES TO ELIMINATE FOULING CONDITION, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-33-011 Airframe SB - Superseded #3760	MODIFICATION - LANDING AND TAXI LIGHTING - REPLACEMENT OF LANDING/TAXI LIGHT LENS RETAINERS ON EXISTING FRAME, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-33-011 R1 Airframe SB - N/A #4458	MODIFICATION - LANDING AND TAXI LIGHTING - REPLACEMENT OF LANDING/TAXI LIGHT LENS RETAINERS ON EXISTING FRAME, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-33-014 Airframe SB - N/A #3989	MODIFICATION - LANDING AND TAXI LIGHTING - ADDITION OF MISSING BACKSHELLS AT CONNECTORS DS30P1 AND DS31P1, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-33-019 Airframe SB - N/A #3650	MODIFICATION - LOGO LIGHTING - WIRING CHANGES AND SHIELDING PROVISIONS FORBUILD 4.0 ELECTRICAL SYSTEM, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-33-023 Airframe SB - Open #3323	MODIFICATION - NAVIGATION LIGHTING - REPLACEMENT OF THE HALOGEN NAVIGATION LIGHTS WITH LED UNITS, SERVICE BULLETIN	H: 0.00					
SB 700-33-024 Airframe SB - N/A #4924	SPECIAL CHECK/MODIFICATION - INTERNAL AND EXTERNAL EMERGENCY LIGHTING - STLMC DISCARD TASK	20-MAY-2019 H: 3301.70 L: 1108					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-34-002 Airframe SB - Superseded #4098	MODIFICATION - HEAD-UP DISPLAY (HUD) SYSTEM - INSTALLATION, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-002 R1 Airframe SB - Superseded #4343	MODIFICATION - HEAD-UP DISPLAY (HUD) SYSTEM - INSTALLATION, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-002 R2 Airframe SB - Superseded #4130	MODIFICATION - HEAD-UP DISPLAY (HUD) SYSTEM - INSTALLATION, SERVICE BULLETIN..	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-002 R3 Airframe SB - Superseded #3877	MODIFICATION - HEAD-UP DISPLAY (HUD) SYSTEM - INSTALLATION (A/C EFFECTIVITY : S/N 9002 TO 9139), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-002 R4 Airframe SB - Superseded #3647	MODIFICATION - HEAD-UP DISPLAY (HUD) SYSTEM - INSTALLATION (A/C 9002 TO 9139), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-002 R5 Airframe SB - N/A #3713	MODIFICATION - HEAD-UP DISPLAY (HUD) SYSTEM - INSTALLATION (A/C 9002 TO 9139), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-34-003 Airframe SB - N/A #3578	MODIFICATION - LIGHTNING SENSORSYSTEM (LSS) - INSTALLATION, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-34-004 Airframe SB - Superseded #3874	MODIFICATION - FLIGHT MANAGEMENT SYSTEM (FMS) - ADDITION OF A THIRD FMS (FMS 3), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-004 R1 Airframe SB - Superseded #3477	MODIFICATION - FLIGHT MANAGEMENT SYSTEM (FMS) - ADDITION OF A THIRD FMS (FMS 3), SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-004 R2 Airframe SB - Superseded #3789	MODIFICATION - FLIGHT MANAGEMENT SYSTEM (FMS) - ADDITION OF A THIRD FMS (FMS 3), SERVICE BULLETIN..	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-004 R3 Airframe SB - Superseded #3825	MODIFICATION - FLIGHT MANAGEMENT SYSTEM (FMS) - ADDITION OF A THIRD FMS (FMS 3), SERVICE BULLETIN...	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-004 R4 Airframe SB - Superseded #4413	MODIFICATION - FLIGHT MANAGEMENT SYSTEM (FMS) - ADDITION OF A THIRD FMS (FMS 3), SERVICE BULLETIN....	H: 0.00					
	Notes SUPERSEDED						

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-34-004 R5 RETRO Airframe SB - Superseded #3486	MODIFICATION - FLIGHT MANAGEMENT SYSTEM (FMS) - ADDITION OF A THIRD FMS (FMS 3) (A/C 9002 TO 9999) - RETROACTIVE ACTION, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-004 R5 Airframe SB - Superseded #3892	MODIFICATION - FLIGHT MANAGEMENT SYSTEM (FMS) - ADDITION OF A THIRD FMS (FMS 3) (A/C 9002 TO 9999), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-004 R6 Airframe SB - N/A #3744	MODIFICATION - FLIGHT MANAGEMENT SYSTEM (FMS) - ADDITION OF A THIRD FMS (FMS 3) (A/C 9002 TO 9269), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-34-005 Airframe SB - Superseded #4575	MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - ADDITION OF A SECOND GPS, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-005 R1 Airframe SB - N/A #4259	MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - ADDITION OF A SECOND GPS (A/C 9002 TO 9139), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-34-013 Airframe SB - Superseded #3492	MODIFICATION - TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM - CHANGE 7 SOFTWARE UPGRADE, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-34-013 R1 Airframe SB - N/A #3328	MODIFICATION - TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM - CHANGE 7 SOFTWARE UPGRADE, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-34-014 PART A Airframe SB - Superseded #3762	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FEET - AIRCRAFT QUALIFICATION REQUIREMENTS, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-014 PART B Airframe SB - Superseded #4239	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FEET - AIRCRAFT QUALIFICATION REQUIREMENTS, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-014 PART C Airframe SB - Superseded #3829	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FEET - AIRCRAFT QUALIFICATION REQUIREMENTS, SERVICE BULLETIN..	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-014 R1 PART A Airframe SB - N/A #4225	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FEET - AIRCRAFT QUALIFICATION REQUIREMENTS, SERVICE BULLETIN...	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-34-014 R1 PART B Airframe SB - N/A #3155	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FEET - AIRCRAFT QUALIFICATION REQUIREMENTS, SERVICE BULLETIN....	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-34-014 R1 PART C Airframe SB - N/A #3311	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FEET - AIRCRAFT QUALIFICATION REQUIREMENTS, SERVICE BULLETIN..... Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					
SB 700-34-015 Airframe SB - N/A #3238	MODIFICATION - NAVIGATION - TRAFFIC/COLLISION AVOIDANCE SYSTEM (TCAS) UNIT WIRING CHANGES, SERVICE BULLETIN Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					
SB 700-34-016 Airframe SB - Superseded #4528	MODIFICATION - NAVIGATION - FLIGHT MANAGEMENT SYSTEM CONTROL AND DISPLAY UNITS (FMS CDU) DIMMING WIRING CHANGES, SERVICE BULLETIN Notes SUPERSEDED	H: 0.00					
SB 700-34-016 R1 Airframe SB - N/A #3681	MODIFICATION - NAVIGATION - FLIGHT MANAGEMENT SYSTEM CONTROL AND DISPLAY UNITS (FMS CDU) DIMMING WIRING CHANGES, SERVICE BULLETIN. Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					
SB 700-34-017 Airframe SB - N/A #4015	MODIFICATION - INERTIAL REFERENCE SYSTEM (IRS) - INTRODUCTION OF "LASERREF IV", SERVICE BULLETIN Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					
SB 700-34-019 Airframe SB - Superseded #3653	SPECIAL CHECK/REWORK - AIRDATA SYSTEM - PITOT-STATIC PROBES ALIGNMENT, SERVICE BULLETIN Notes SUPERSEDED	H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-34-019 R1 Airframe SB - Superseded #3569	SPECIAL CHECK/REWORK - AIRDATA SYSTEM - PITOT-STATIC PROBES ALIGNMENT, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-019 R2 Airframe SB - Superseded #3234	SPECIAL CHECK/REWORK - AIRDATA SYSTEM - PITOT-STATIC PROBES ALIGNMENT, SERVICE BULLETIN..	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-019 R3 Airframe SB - N/A #3541	SPECIAL CHECK/REWORK - AIRDATA SYSTEM - PITOT-STATIC PROBES ALIGNMENT, SERVICE BULLETIN...	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-34-020 Airframe SB - Superseded #3418	MODIFICATION - AIRDATA SYSTEM - REPLACEMENT OF MICRO AIR-DATA COMPUTER, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-020 R1 Airframe SB - N/A #3819	MODIFICATION - AIRDATA SYSTEM - REPLACEMENT OF MICRO AIR-DATA COMPUTER, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-34-021 Airframe SB - N/A #3343	MODIFICATION - GENERAL - REPLACEMENT OF SOME 90 DEGREE ANTENNA CONNECTORS TO MAKE TEH SERVICING OF EXTERNAL ANTENNAS EASIERAND FASTER, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-34-022 Airframe SB - N/A #3739	MODIFICATION - STANDBY ARTIFICIAL-HORIZON SYSTEM - CHANGE POWERSOURCE TO 28 V DC DIRECT FROM AVIONICS BATTERY BUS, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-34-023 Airframe SB - N/A #4058	MODIFICATION - RADIO ALTIMETERSYSTEM - RADIO ALTIMETER ANTENNA CORROSION PROTECTION, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-34-025 Airframe SB - Superseded #4028	MODIFICATION - NAVIGATION - INTRODUCTION OF FLIGHT MANAGEMENT SYSTEM (FMS) CONTROL DISPLAY UNIT (CDU) -820 (PART NO. 2888-03-1), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-025 R1 Airframe SB - Superseded #3309	MODIFICATION - NAVIGATION - INTRODUCTION OF FLIGHT MANAGEMENT SYSTEM (FMS) CONTROL DISPLAY UNIT (CDU) -820 (PART NO. 2888-03-1), SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-025 R2 Airframe SB - N/A #3104	MODIFICATION - NAVIGATION - INTRODUCTION OF FLIGHT MANAGEMENT SYSTEM (FMS) CONTROL DISPLAY UNIT (CDU) -820 (PART NO. 2888-03-1 OR2888-09-1) (A/C 9002, 9004 TO 9124), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-34-027 Airframe SB - Superseded #4186	MODIFICATION - AIRTRAFFIC CONTROL (ATC) TRANSPONDER SYSTEM - NEW MODE 'S' TRANSPONDER TO MEET EUROCONTROL ELEMENTARY SURVEILLANCE REQUIREMENTS, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-34-027 R1 Airframe SB - Superseded #4235	MODIFICATION - AIRTRAFFIC CONTROL (ATC) TRANSPONDER SYSTEM - NEW MODE 'S' TRANSPONDER TO MEET EUROCONTROL ELEMENTARY SURVEILLANCE REQUIREMENTS (A/C 9002 TO 9126 AND 9128 TO 9139), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-027 R2 Airframe SB - N/A #3319	MODIFICATION - AIRTRAFFIC CONTROL (ATC) TRANSPONDER SYSTEM - NEW MODE 'S' TRANSPONDER TO MEET EUROCONTROL ELEMENTARY SURVEILLANCE REQUIREMENTS (A/C 9002 TO 9126 AND 9128 TO 9139), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-34-028 Airframe SB - N/A #3120	SPECIAL CHECK/REWORK - STANDBY ARTIFICIAL-HORIZON SYSTEM - IDENTIFY AND REPLACE DEFECTIVE STBY ADI (CB-18) CIRCUIT BREAKER ON THE STBY ADI CB/RELAY PANEL, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-34-030 Airframe SB - Superseded #3994	MODIFICATION - LIGHTNING SENSOR SYSTEM (LSS) - INSTALLATION ON AIRCRAFT WITH PROVISIONS FOR LSS (A/C 9140 TO 9999), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-030 R1 Airframe SB - Complied With #622	MODIFICATION - LIGHTNING SENSOR SYSTEM (LSS) - INSTALLATION ON AIRCRAFT WITH PROVISIONS FOR LSS, SERVICE BULLETIN	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
SB 700-34-031 Airframe SB - N/A #4099	MODIFICATION - VHF NAVIGATION SYSTEM - REPLACEMENT OF THE RNZ-851 NAVIGATION RECEIVER UNITS TO ELIMINATE ERRONEOUS GLIDE SLOPE INDICATION ON INSTRUMENT LANDING SYSTEM (ILS) APPROACH, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-34-032 Airframe SB - Superseded #3683	MODIFICATION - HEAD UP DISPLAY (HUD) SYSTEM - INSTALLATION ON AIRCRAFT WITH PROVISION FORHUD (A/C 9141 TO 9148), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-032 R2 Airframe SB - Complied With #982	MODIFICATION - PROVISIONS - HEAD UP DISPLAY (HUD) SYSTEM - INSTALLATION ON AIRCRAFT WITH PROVISIONS FORHUD, SERVICE BULLETIN	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
SB 700-34-033 Airframe SB - Superseded #3351	MODIFICATION - ENHANCED VISION SYSTEM - INSTALLATION OF THE ENHANCED VISION SYSTEM (EVS), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-033 R1 Airframe SB - Superseded #3967	MODIFICATION - ENHANCED VISION SYSTEM (EVS) - INSTALLATION OF THE ENHANCED VISION SYSTEM (A/C 9159 TO 9999), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-033 R2 Airframe SB - Complied With #705	MODIFICATION - ENHANCED VISION SYSTEM - INSTALLATION OF THE ENHANCED VISION SYSTEM (EVS), SERVICE BULLETIN	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
SB 700-34-035 Airframe SB - N/A #4050	MODIFICATION - TRAFFIC COLLISION AVOIDANCE SYSTEM (TCAS) - CHANGE TCAS CLIMB INHIBIT ALTITUDE TO OPTIMUM ALTITUDE - EFFECTIVITY 9002 TO 9158, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-34-036 Airframe SB - N/A #3498	MODIFICATION - HEAD-UP DISPLAY (HUD) SYSTEM - REPLACEMENT OF SUNVISORSTOWAGE BRACKET (A/C 9002 TO 9139 AND 9141 TO 9165), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-34-037 Airframe SB - Superseded #4073	MODIFICATION - ENHANCED VISION SYSTEM - INSTALLATION OF THE ENHANCED VISION SYSTEM (EVS) - EFFECTIVITY 9002 TO 9158, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-037 R1 Airframe SB - Superseded #3778	MODIFICATION - ENHANCED VISION SYSTEM - INSTALLATION OF THE ENHANCED VISION SYSTEM (EVS) - EFFECTIVITY 9002 TO 9158, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-037 R2 Airframe SB - N/A #3385	MODIFICATION - ENHANCED VISION SYSTEM - INSTALLATION OF THE ENHANCED VISION SYSTEM (EVS), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-34-038 Airframe SB - N/A #3526	MODIFICATION - ENHANCED VISION SYSTEM (EVS) - INSTALLATION OF THE EVS PROVISIONS - EFFECTIVITY 9002 TO 9148, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-34-039 Airframe SB - Superseded #4124	MODIFICATION - ATC TRANSPONDERSYSTEM - MODE "S" TRANSPONDER TO MEET EUROCONTROL ENHANCED SURVEILLANCE REQUIREMENTS, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-34-039 R1 Airframe SB - N/A #4587	MODIFICATION - AIRTRAFFIC CONTROL (ATC) TRANSPONDER SYSTEM - MODE "S" TRANSPONDER TO MEET EUROCONTROL ENHANCED SURVEILLANCE REQUIREMENTS (A/C 9002 TO 9189), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-34-041 Airframe SB - Open #4127	MODIFICATION - GENERAL - ELECTRONIC FLIGHT BAG (EFB) AND COCKPIT TOUCH SCREENS PROVISION INSTALLATION, SERVICE BULLETIN	H: 0.00					
SB 700-34-042 Airframe SB - Open #3428	MODIFICATION - PROVISIONS - GENERAL - INSTALLATION OF THE DIGITAL TAPPING EQUIPMENT (DTE), THE RIGHT HAND SIDE USB PORT AND CONNECTORASSEMBLY FOR ELECTRONIC FLIGHT BAG (EFB) INSTALLATION, SERVICE BULLETIN	H: 0.00					
SB 700-34-043 Airframe SB - Open #3623	MODIFICATION - PROVISIONS - GENERAL - INSTALLATION OF THE DIGITAL TAPPING EQUIPMENT (DTE), THE LEFT HAND SIDE USB PORT AND CONNECTORASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB 700-34-044 Airframe SB - N/A #3181	SPECIAL CHECK/REWORK - FLIGHT MANAGEMENT SYSTEM - ENSURE THE CORRECT AIRCRAFT DATABASE IS INSTALLED ON THE FMS (A/C 9002 TO 9126, 9128 TO 9180), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-34-046 Airframe SB - Superseded #3986	MODIFICATION - AIR-DATA COMPUTERSYSTEM - INTRODUCTION OF NEW AMADC FOR TAT SPLIT (A/C 9002 TO 9205), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-046 R1 Airframe SB - N/A #3818	MODIFICATION - AIR-DATA COMPUTERSYSTEM - INTRODUCTION OF NEW AMADC FOR TAT SPLIT (A/C 9002 TO 9204), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						





Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-34-047 Airframe SB - N/A #3863	MODIFICATION - FLIGHT MANAGEMENT SYSTEM - INTRODUCTION OF FLIGHT MANAGEMENT SYSTEM (FMS) CONTROL DISPLAY UNIT (CDU) -820 (PART NO. 2888-09-1), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-34-048 Airframe SB - Superseded #3693	MODIFICATION - WEATHERRADAR SYSTEM - CAP AND STOW TWO CAIMS WIRES TO PREVENT GROUND CLUTTER ON MULTI-FUNCTION DISPLAY (MFD) (A/C 9002 TO 9999), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-048 R1 Airframe SB - Open #3195	MODIFICATION - WEATHERRADAR SYSTEM - CAP AND STOW TWO CAIMS WIRES TO PREVENT GROUND CLUTTER ON MULTI-FUNCTION DISPLAY (MFD), SERVICE BULLETIN	H: 0.00					
SB 700-34-050 Airframe SB - Superseded #3634	MODIFICATION - HEAD-UP-DISPLAY SYSTEM - INTRODUCTION OF NEW HEAD-UP FLIGHT-DISPLAY COMPUTER(HFDC) TO SUPPORT BATCH 3, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-050 R1 Airframe SB - Complied With #147	MODIFICATION - HEAD-UP-DISPLAY SYSTEM - INTRODUCTION OF NEW HEAD-UP FLIGHT-DISPLAY COMPUTER(HFDC) TO SUPPORT BATCH 3, SERVICE BULLETIN.	20-JAN-2014 H: 649.70 L: 284					
	Notes COMPLIED WITH						
SB 700-34-051 Airframe SB - N/A #4333	MODIFICATION - GENERAL - INSTALLATION OF NEW PILOTVIEWTM CLASS 2 ELECTRONIC FLIGHT BAG (EFB) (A/C 9167, 9171, 9173, 9175, 9177, 9181, 9183, 9193, 9194, 9196, 9197, 9200, 9202, 9208, 9210, 9213, 9215, 9223, AND 9225 POST SB'S 700-34-041, 700-34-042, A	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-34-052 Airframe SB - N/A #3696	MODIFICATION - FLIGHT MANAGEMENT SYSTEM (FMS) - REMOVAL OF ATTENUATORWHEN FMS CDU -820 PART NO. 2888-03-1 IS REPLACED WITH PART NO. 2888-09-1 IN THE NO. 2 POSITION AND EVS IS INSTALLED (A/C 9002 TO 9199), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-34-053 Airframe SB - Superseded #4426	MODIFICATION - FLIGHT MANAGEMENT SYSTEM - INTRODUCTION OF FANS 1/A+ AND RNP 4 30/30 FUNCTIONALITY, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-053 R1 Airframe SB - Complied With #1940	MODIFICATION - FLIGHT MANAGEMENT SYSTEM - INTRODUCTION OF FANS 1/A+ AND RNP 4 30/30 FUNCTIONALITY, SERVICE BULLETIN.	25-JAN-2014 H: 649.70 L: 284					
	Notes COMPLIED WITH						
SB 700-34-053 R2 Airframe SB - Open #4440	MODIFICATION - FLIGHT MANAGEMENT SYSTEM - INTRODUCTION OF FANS 1/A+ AND RNP 4 30/30 FUNCTIONALITY, SERVICE BULLETIN..	H: 0.00					
SB 700-34-053 R3 Airframe SB - Open #4812	MODIFICATION - FLIGHT MANAGEMENT SYSTEM - INTRODUCTION OF FANS 1/A+ AND RNP 4 30/30 FUNCTIONALITY (REV. 3)						
SB 700-34-054 Airframe SB - Superseded #4290	MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INTRODUCTION OF SBAS WITH LPV APPROACH CAPABILITY, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-054 R1 Airframe SB - Complied With #1410	MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INTRODUCTION OF SBAS WITH LPV APPROACH CAPABILITY, SERVICE BULLETIN.	25-JAN-2014 H: 649.70 L: 284					
	Notes COMPLIED WITH						
SB 700-34-054 R2 Airframe SB - Open #4770	MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INTRODUCTION OF SBAS WITH LPV APPROACH CAPABILITY (REV. 2)						



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-34-058 Airframe SB - N/A #3283	MODIFICATION - HEAD-UP-DISPLAY (HUD) SYSTEM - REPLACEMENT OF FAN ON HFDC TRAY, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-34-059 Airframe SB - Open #3404	MODIFICATION - WEATHERRADAR SYSTEM - CONNECT TWO CAIMS WIRES AND PERFORM SOFTWARE UPLOAD TO PREVENT WEATHER RADAR TILT DROOPING, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-059 R1 Airframe SB - Open #3487	MODIFICATION - WEATHERRADAR SYSTEM - CONNECT TWO CAIMS WIRES AND PERFORM SOFTWARE UPLOAD TO PREVENT WEATHER RADAR TILT DROOPING, SERVICE BULLETIN.	H: 0.00					
SB 700-34-061 Airframe SB - Complied With #2237	MODIFICATION - HEAD-UP DISPLAY (HUD) SYSTEM - INSTALLATION OF LABELS ON THE HUD OPTICAL COMBINERUNIT (COU), SERVICE BULLETIN	12-SEP-2012 H: 388.37 L: 190					
	Notes COMPLIED WITH						
SB 700-34-062 Airframe SB - Superseded #3887	MODIFICATION - DEPENDENT POSITION DETERMINING - INTRODUCTION OF AUTOMATIC DEPENDENT SURVEILLANCE - BROADCAST OUT CAPABILITY (ADS-B OUT), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-34-062 R04 Airframe SB - Open #4955	MODIFICATION – DEPENDENT POSITION DETERMINING – INTRODUCTION OF AUTOMATIC DEPENDENT SURVEILLANCE – BROADCAST OUT CAPABILITY (ADS-B OUT)						
SB 700-34-062 R05 Airframe SB - Open #5071	MODIFICATION - DEPENDENT POSITION DETERMINING - INTRODUCTION OF AUTOMATIC DEPENDENT SURVEILLANCE - BROADCAST OUT CAPABILITY (ADS-B OUT)						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-34-062 R1 Airframe SB - Superseded #4385	MODIFICATION - DEPENDENT POSITION DETERMINING - INTRODUCTION OF AUTOMATIC DEPENDENT SURVEILLANCE - BROADCAST OUT CAPABILITY (ADS-B OUT), SERVICE BULLETIN. Notes SUPERSEDED	H: 0.00					
SB 700-34-062 R2 Airframe SB - Open #3493	MODIFICATION - DEPENDENT POSITION DETERMINING - INTRODUCTION OF AUTOMATIC DEPENDENT SURVEILLANCE - BROADCAST OUT CAPABILITY (ADS-B OUT), SERVICE BULLETIN..	H: 0.00					
SB 700-34-062 R3 Airframe SB - Complied With #1218	MODIFICATION - DEPENDENT POSITION DETERMINING - INTRODUCTION OF AUTOMATIC DEPENDENT SURVEILLANCE - BROADCAST OUT CAPABILITY (ADS-B OUT), SERVICE BULLETIN... Notes COMPLIED WITH - REV 3 DATED 7-21-2014	09-OCT-2014 H: 1015.50 L: 386					
SB 700-34-063 Airframe SB - Open #4617	MODIFICATION - TRAFFIC COLLISION AVOIDANCE SYSTEM (TCAS) - INSTALLATION OF NEW RECEIVER/TRANSMITTERUNIT WITH SOFTWARE VERSION 7.0 UPGRADE, SERVICE BULLETIN	H: 0.00					
SB 700-34-064 Airframe SB - Complied With #469	MODIFICATION - TRAFFIC COLLISION AVOIDANCE SYSTEM (TCAS) - INSTALLATION OF NEW RECEIVER/TRANSMITTERUNIT WITH SOFTWARE VERSION 7.1 UPGRADE, SERVICE BULLETIN Notes COMPLIED WITH - PCW	04-MAR-2013 H: 430.70 L: 211					
SB 700-34-066 Airframe SB - Complied With #4724	SPECIAL CHECK/MODIFICATION – STANDBY COMPASS SYSTEM – INSPECTION AND REPLACEMENT OF ELECTRICAL LEAD ASSEMBLY FOR STANDBY COMPASS PART NO. WL1001KCA1	29-SEP-2017 H: 2431.70 L: 854					
SB 700-35-004 Airframe SB - N/A #3549	SPECIAL CHECK/MODIFICATION - LOW PRESSURE/HIGH PRESSURE DISCHARGE SYSTEM - REPLACEMENT OF FLEXIBLE HOSE INSTALLED ON RIGHT-OUTBOARD OXYGEN CYLINDERTO PREVENT POSSIBLE RUPTURE, SERVICE BULLETIN Notes NOT APPLICABLE - BY EFFECTIVITY	H: 0.00					

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-35-005 PART A Airframe SB - Open #4037	SPECIAL CHECK/MODIFICATION - OXYGEN CONTENTS INDICATION-SYSTEM - INSPECT THE OXYGEN SYSTEM PRESSURE TRANSDUCERS KNOWN TO HAVE INCOMPATIBLE POTTING COMPOUND AND REPLACE, IF NECESSARY, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-35-005 PART B Airframe SB - Open #4590	SPECIAL CHECK/MODIFICATION - OXYGEN CONTENTS INDICATION-SYSTEM - INSPECT THE OXYGEN SYSTEM PRESSURE TRANSDUCERS KNOWN TO HAVE INCOMPATIBLE POTTING COMPOUND AND REPLACE, IF NECESSARY, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-35-005 R1 PART A Airframe SB - N/A #3358	SPECIAL CHECK/MODIFICATION - OXYGEN CONTENTS INDICATION-SYSTEM - INSPECT THE OXYGEN SYSTEM PRESSURE TRANSDUCERS KNOWN TO HAVE INCOMPATIBLE POTTING COMPOUND AND REPLACE, IF NECESSARY (A/C 9002 TO 9100 AND 9102 TO 9105), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-35-005 R1 PART B Airframe SB - N/A #3108	SPECIAL CHECK/MODIFICATION - OXYGEN CONTENTS INDICATION-SYSTEM - INSPECT THE OXYGEN SYSTEM PRESSURE TRANSDUCERS KNOWN TO HAVE INCOMPATIBLE POTTING COMPOUND AND REPLACE, IF NECESSARY (A/C 9002 TO 9100 AND 9102 TO 9105), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-35-006 PART B Airframe SB - N/A #3194	POSSIBLE DEGRADED CONNECTIONS AT SWAGE JOINTS OF THE CREW OXYGEN SYSTEM HOSES - MODIFICATION - REPLACEMENT OF AFFECTED HOSES, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-35-006 PART A Airframe SB - N/A #3917	POSSIBLE DEGRADED CONNECTIONS AT SWAGE JOINTS OF THE CREW OXYGEN SYSTEM HOSES - SPECIAL CHECK - VISUAL INSPECTION OF SUSPECT HOSES, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-35-007 PART B Airframe SB - N/A #4508	MODIFICATION - REPLACEMENT OF AFFECTED HOSES -OXYGEN SYSTEM - POSSIBLE DEGRADED CONNECTIONS AT SWAGE JOINTS OF STC INSTALLED OXYGEN SYSTEM HOSES - FORA/C S/N 9002 TO 9126, 9128, 9129, 9133, 9134, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-35-007 PART A Airframe SB - N/A #4302	SPECIAL CHECK - VISUAL INSPECTION OF SUSPECTED HOSES -OXYGEN SYSTEM - POSSIBLE DEGRADED CONNECTIONS AT SWAGE JOINTS OF STC INSTALLED OXYGEN SYSTEM HOSES - FORA/C S/N 9002 TO 9126, 9128, 9129, 9133, 9134, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-35-009 Airframe SB - Superseded #3284	MODIFICATION - OXYGEN SUPPLY SYSTEM - INTRODUCTION OF NEW OXYGEN CYLINDERAND REGULATOR ASSEMBLY WITH AN IMPROVED HIGH-PRESSURE RELIEF DEVICE (EFFECTIVITY A/C 9002 TO 9174), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-35-009 R1 Airframe SB - N/A #4039	MODIFICATION - OXYGEN SUPPLY SYSTEM - INTRODUCTION OF NEW OXYGEN CYLINDERAND REGULATOR ASSEMBLY WITH AN IMPROVED HIGH-PRESSURE RELIEF DEVICE (EFFECTIVITY A/C 9002 TO 9174), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-35-011 PART A Airframe SB - Open #4579	INSPECTION - SPECIAL CHECK/REWORK - OXYGEN SUPPLY SYSTEM - INSPECT SERIAL NO. OF OXYGEN CYLINDERAND REGULATOR ASSY (CRA) AND REGULATOR ASSY AND REPLACE IF FOUND IN LIST OF AFFECTED UNITS,-OF SERIAL NUMBERS.	H: 0.00					
	Notes SUPERSEDED						
SB 700-35-011 PART B Airframe SB - Open #4577	REPLACEMENT - SPECIAL CHECK/REWORK OXYGEN SUPPLY SYSTEM INSPECT SERIAL NO. OF OXYGEN CYLINDERAND REGULATOR ASSY (CRA) AND REGULATOR ASSY AND REPLACE IF FOUND IN LIST OF AFFECTED UNITS,-OF THE OXYGEN STORAGE CYLINDER AND THE REGULATOR	H: 0.00					
	Notes SUPERSEDED						

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-35-011 Airframe SB - Superseded #3105	SPECIAL CHECK/REWORK - OXYGEN SUPPLY SYSTEM INSPECT SERIAL NO. OF OXYGEN CYLINDERAND REGULATOR ASSY (CRA) AND REGULATOR ASSY AND REPLACE IF FOUND IN LIST OF AFFECTED UNITS, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-35-011 R1 PART A Airframe SB - N/A #3607	INSPECTION - SPECIAL CHECK/REWORK - OXYGEN SUPPLY SYSTEM - INSPECT SERIAL NO. OF OXYGEN CYLINDERAND REGULATOR ASSY (CRA) AND REGULATOR ASSY AND REPLACE IF FOUND IN LIST OF AFFECTED UNITS,-OF SERIAL NUMBERS	H: 292.60 L: 134					
	Notes NOT APPLICABLE - N/A BY A/C S/N						
SB 700-35-011 R1 PART B Airframe SB - N/A #3440	REPLACEMENT - SPECIAL CHECK/REWORK - OXYGEN SUPPLY SYSTEM - INSPECT SERIAL NO. OF OXYGEN CYLINDERAND REGULATOR ASSY (CRA) AND REGULATOR ASSY AND REPLACE IF FOUND IN LIST OF AFFECTED UNITS,-OF THE OXYGEN STORAGE CYLINDER AND THE REGULATOR	H: 292.60 L: 134					
	Notes NOT APPLICABLE - N/A BY A/C S/N						
SB 700-35-011 R1 Airframe SB - N/A #1610	SPECIAL CHECK/REWORK - OXYGEN SUPPLY SYSTEM - INSPECT SERIAL NO. OF OXYGEN CYLINDERAND REGULATOR ASSY (CRA) AND REGULATOR ASSY AND REPLACE IF FOUND IN LIST OF AFFECTED UNITS, SERVICE BULLETIN	16-FEB-2012 H: 292.60 L: 134					
	Notes NOT APPLICABLE - N/A BY A/C S/N						
SB 700-35-012 Airframe SB - N/A #1534	SPECIAL CHECK/MODIFICATION - OXYGEN SUPPLY SYSTEM - INSPECTION FORPOTENTIAL DEFECTIVE COMPONENT ON THE INFLATABLE HARNESS OF THE CREW OXYGEN MASK, SERVICE BULLETIN	16-FEB-2012 H: 292.60 L: 134					
	Notes NOT APPLICABLE - BY A/C S/N						
SB 700-35-012 R1 Airframe SB - N/A #3410	SPECIAL CHECK/MODIFICATION - OXYGEN SUPPLY SYSTEM - INSPECTION FORPOTENTIAL DEFECTIVE COMPONENT ON THE INFLATABLE HARNESS OF THE CREW OXYGEN MASK, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-35-013 Airframe SB - Complied With #1374	ICA - MODIFICATION - OXYGEN CREW - REPLACEMENT OF FLEXIBLE RELIEF HOSES, SERVICE BULLETIN	19-MAR-2015 H: 1339.30 L: 480					
	Notes COMPLIED WITH						
SB 700-35-013 R1 Airframe SB - Complied With #3437	ICA - MODIFICATION - OXYGEN CREW - REPLACEMENT OF FLEXIBLE RELIEF HOSES, SERVICE BULLETIN.	H: 0.00					
SB 700-35-014 Airframe SB - N/A #4858	MODIFICATION - PORTABLE OXYGEN PROVISION - REPLACEMENT OF THE BRACKET OF THE OXYGEN BOTTLE BRACKET	06-FEB-2020 H: 3664.80 L: 1207					
SB 700-36-016 Airframe SB - Superseded #4466	MODIFICATION - DISTRIBUTION - UROSEAL INSTALLATION BETWEEN DUCT ASSEMBLY AND PRECOOLERDOES NOT MATCH GAP REQUIREMENTS, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-36-016 R1 Airframe SB - N/A #4042	MODIFICATION - DISTRIBUTION - UROSEAL INSTALLATION BETWEEN DUCT ASSEMBLY AND PRECOOLERDOES NOT MATCH GAP REQUIREMENTS, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-36-017 Airframe SB - N/A #4249	MODIFICATION - BLEED AIRSYSTEM - INTRODUCTION OF NEW BLEED MANAGEMENT CONTROLLERS, PART NO. GG546-1017-11, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-36-018 Airframe SB - N/A #3737	MODIFICATION - BLEED-AIRLEAK DETECTION SYSTEM - REPLACEMENT OF SUPPORT BRACKET FOR THE THERMAL ANTI-ICE (TAI) BLEED DETECTION WIRE, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-36-021 R1 Airframe SB - Superseded #3505	MODIFICATION - BLEED-AIRLEAK-DETECTION SYSTEM - REROUTING OF BLEED LEAK-DETECTION LOOPS AND RELOCATION OF A VENT HOLE, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-36-021 R2 Airframe SB - N/A #4108	ICA - MODIFICATION - BLEED-AIRLEAK-DETECTION SYSTEM -REROUTING OF BLEED LEAK-DETECTION LOOPS AND RELOCATION OF A VENT HOLE, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-36-021 R2 PART A Airframe SB - N/A #3436	MODIFICATION - ICA - MODIFICATION - BLEED-AIRLEAK-DETECTION SYSTEM -REROUTING OF BLEED LEAK-DETECTION LOOPS AND RELOCATION OF A VENT HOLE,- TRIM AIR DUCT BLEED LEAK-DETECTION ELEMENTS RELOCATION	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-36-021 R2 PART B Airframe SB - N/A #4199	MODIFICATION - ICA - MODIFICATION - BLEED-AIRLEAK-DETECTION SYSTEM -REROUTING OF BLEED LEAK-DETECTION LOOPS AND RELOCATION OF A VENT HOLE,-BLEED AIR DUCT BLEED LEAK-DETECTION ELEMENTS RELOCATION	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-36-021 R2 PART C Airframe SB - N/A #3483	MODIFICATION - ICA - MODIFICATION - BLEED-AIRLEAK-DETECTION SYSTEM -REROUTING OF BLEED LEAK-DETECTION LOOPS AND RELOCATION OF A VENT HOLE,-THREE-BRANCH DUCT (LEFT SIDE) RELOCATION OF INSULATION VENT HOLE	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-36-023 PART B Airframe SB - Superseded #3847	SPECIAL CHECK/MODIFICATION - BLEED AIRSYSTEM - EXAMINE THE APU UROSEAL AND REPLACE IF NECESSARY (A/C 9002 TO 9126 AND 9128 TO 9220), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-36-023 PART A Airframe SB - Superseded #3426	SPECIAL CHECK/MODIFICATION - BLEED AIRSYSTEM - EXAMINE THE APU UROSEAL AND REPLACE IF NECESSARY (A/C 9002 TO 9126 AND 9128 TO 9234), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-36-023 R1 Airframe SB - N/A #4138	ICA - SPECIAL CHECK/MODIFICATION - BLEED AIRSYSTEM - EXAMINE THE APU UROSEAL AND REPLACE IF NECESSARY, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-36-023 R1 PART B Airframe SB - N/A #4463	MODIFICATION - ICA - SPECIAL CHECK/MODIFICATION - BLEED AIRSYSTEM - EXAMINE THE APU UROSEAL AND REPLACE IF NECESSARY, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-36-023 R1 PART A Airframe SB - N/A #4198	SPECIAL CHECK-ICA - SPECIAL CHECK/MODIFICATION - BLEED AIRSYSTEM - EXAMINE THE APU UROSEAL AND REPLACE IF NECESSARY, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-36-024 Airframe SB - Superseded #4525	MODIFICATION - BLEED AIRSYSTEM - UPGRADE BLEED MANAGEMENT CONTROLLERS (BMC) TO PART NO. GG546-1017-13, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-36-024 R1 Airframe SB - N/A #4571	MODIFICATION - BLEED AIRSYSTEM - UPGRADE BLEED MANAGEMENT CONTROLLERS (BMC) TO PART NO. GG546-1017-13, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-36-025 Airframe SB - Complied With #4859	MODIFICATION - BLEED AIR SYSTEM - REPLACEMENT OF THE BLEED-PRESSURE REGULATING-AND-SHUTOFF VALVE (PRSOV)	31-MAR-2020 H: 3741.10 L: 1233					
SB 700-38-002 Airframe SB - N/A #3773	SPECIAL CHECK/REWORK - MAGAIRVACUUM TOILET, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-38-003 Airframe SB - N/A #3342	SPECIAL CHECK/REWORK - POTABLE WATERSYSTEM OPERATION (AIR PRESSURIZED), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-38-004 PART A Airframe SB - N/A #4159	SPECIAL CHECK/REWORK - POTABLE WATERSYSTEM - CHECK FOR CORROSION IN FORWARD AND/OR AFT WATER TANKS AND REPLACEMENT OF UNSERVICEABLE WATER TANK(S), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-38-004 PART B Airframe SB - N/A #3884	SPECIAL CHECK/REWORK - POTABLE WATERSYSTEM - CHECK FOR CORROSION IN FORWARD AND/OR AFT WATER TANKS AND REPLACEMENT OF UNSERVICEABLE WATER TANK(S), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-38-004 PART C Airframe SB - N/A #4482	SPECIAL CHECK/REWORK - POTABLE WATERSYSTEM - CHECK FOR CORROSION IN FORWARD AND/OR AFT WATER TANKS AND REPLACEMENT OF UNSERVICEABLE WATER TANK(S), SERVICE BULLETIN..	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-38-005 PART A Airframe SB - N/A #4048	MODIFICATION - WASTE DISPOSAL - REPLACEMENT OF AFT LIQUID LEVEL SENSOR AND MODIFICATION OF AFT HEATED WASTE LINE AND AFT WASTE TANK VENTING SYSTEM, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-38-005 PART B Airframe SB - N/A #3779	MODIFICATION - WASTE DISPOSAL - REPLACEMENT OF AFT LIQUID LEVEL SENSOR AND MODIFICATION OF AFT HEATED WASTE LINE AND AFT WASTE TANK VENTING SYSTEM, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-38-005 PART C Airframe SB - N/A #3879	MODIFICATION - WASTE DISPOSAL - REPLACEMENT OF AFT LIQUID LEVEL SENSOR AND MODIFICATION OF AFT HEATED WASTE LINE AND AFT WASTE TANK VENTING SYSTEM, SERVICE BULLETIN..	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-38-006 PART B Airframe SB - N/A #4537	MODIFICATION - INSTALLATION OF UPGRADED MAGAIRTOILET ASSEMBLY(S), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-38-006 PART C Airframe SB - N/A #3226	MODIFICATION - INSTALLATION OR REPLACEMENT OF HYDRAFLOW HOSE(S), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-38-006 PART A Airframe SB - N/A #4324	SPECIAL CHECK - CHECK FOR UNSERVICEABLE HYDRAFLOW HOSES., SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-38-007 Airframe SB - N/A #3772	MODIFICATION - WASTE DISPOSAL - REPLACEMENT OF INLET FITTING, FORWARD LIQUID LEVEL SENSOR(LLS) AND ADDITION OF WATER SEPARATOR TO THE VENT LINE ON THE FORWARD WASTE HOLDING TANK AND REACTIVATION OF FORWARD LLS (AS NECESSARY), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-38-008 Airframe SB - Superseded #3729	MODIFICATION - FORWARD CANTED DRAIN MAST (A/C 9002, 9004 TO 9095, AND 9097 TO 9153), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-38-008 R1 Airframe SB - Superseded #3816	MODIFICATION - WASTE DISPOSAL - INSTALLATION OF CANTED DRAIN MAST (A/C 9002, 9004 TO 9095, AND 9097 TO 9153), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-38-008 R2 Airframe SB - N/A #3435	MODIFICATION - WASTE DISPOSAL - INSTALLATION OF CANTED DRAIN MAST, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-38-013 Airframe SB - N/A #3333	MODIFICATION - POTABLE WATERSYSTEM - IMPROVEMENT OF THE WATER TANKS PURGE PERFORMANCE.-(SEE SB OR NOTE ON WORKCARD FOR EFFECTIVITY), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-38-013 R1 Airframe SB - N/A #4083	MODIFICATION - POTABLE WATERSYSTEM - IMPROVEMENT OF THE WATER TANKS PURGE PERFORMANCE, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
SB 700-38-014 Airframe SB - N/A #4606	MODIFICATION - GENERAL - REWIRE TEMPERATURE SENSOR TO PREVENT FREEZING IN THE AFT WATER SYSTEM, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-38-015 PART B Airframe SB - Superseded #4046	INSTALL - MODIFICATION - POTABLE WATERSYSTEM - INTRODUCTION OF NEW 13 GALLON WATER TANK FOR AIR PRESSURIZED SYSTEM,-NEW AFT 13 GALLON PARKER AIR/FUEL WATER TANK, PART NO. 330-0039-02 (BOMBARDIER PART NO. BAS67038442-3)	H: 0.00					
	Notes SUPERSEDED						
SB 700-38-015 PART A Airframe SB - Superseded #4327	INSTALL - MODIFICATION - POTABLE WATERSYSTEM - INTRODUCTION OF NEW 13 GALLON WATER TANK FOR AIR PRESSURIZED SYSTEM,-NEW FORWARD 13 GALLON PARKER AIR/FUEL WATER TANK, PART NO. 330-0039-02 (BOMBARDIER PART NO. BAS67038442-3),	H: 0.00					
	Notes SUPERSEDED						
SB 700-38-015 Airframe SB - Superseded #4457	MODIFICATION - POTABLE WATERSYSTEM - INTRODUCTION OF NEW 13 GALLON WATER TANK FOR AIR PRESSURIZED SYSTEM, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-38-015 R1 Airframe SB - Open #3930	MODIFICATION - POTABLE WATERSYSTEM INTRODUCTION OF NEW 13 GALLON WATER TANK FOR AIR PRESSURIZED SYSTEM, SERVICE BULLETIN	H: 0.00					
SB 700-38-015 R1 PART B Airframe SB - Open #4543	REPLACEMENT - MODIFICATION POTABLE WATERSYSTEM INTRODUCTION OF NEW 13 GALLON WATER TANK FOR AIR PRESSURIZED SYSTEM,-OF THE AFT WATER TANK(S)	H: 0.00					
SB 700-38-015 R1 PART A Airframe SB - Open #4200	REPLACEMENT - MODIFICATION POTABLE WATERSYSTEM INTRODUCTION OF NEW 13 GALLON WATER TANK FOR AIR PRESSURIZED SYSTEM,-OF THE FORWARD WATER TANK	H: 0.00					
SB 700-38-016 Airframe SB - N/A #3300	MODIFICATION - POTABLE WATERSYSTEM - INTRODUCTION OF NEW 26 GALLON WATER TANK FOR AIR PRESSURIZED SYSTEM, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-38-016 PART B Airframe SB - N/A #3728	REPLACEMENT - MODIFICATION - POTABLE WATERSYSTEM - INTRODUCTION OF NEW 26 GALLON WATER TANK FOR AIR PRESSURIZED SYSTEM,-OF THE AFT WATER TANK	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-38-016 PART A Airframe SB - N/A #4603	REPLACEMENT - MODIFICATION - POTABLE WATERSYSTEM - INTRODUCTION OF NEW 26 GALLON WATER TANK FOR AIR PRESSURIZED SYSTEM,-OF THE FORWARD WATER TANK	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-38-018 Airframe SB - N/A #3488	WATERTANK PRESSURIZATION SYSTEM - RELOCATION OF THE PRESSURE SENSOR, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-38-019 Airframe SB - N/A #3138	MODIFICATION - WASTE DISPOSAL - REPLACE VACUUM HOSE WITH RIGID PIPE, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-38-020 Airframe SB - N/A #4010	REWORK - POTABLE WATERSYSTEM (PWS) - TERMINATE CES WIRING TO EIB (EFFECTIVITY: A/C 9167, 9171, 9181, 9185, 9187, 9193), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-38-022 Airframe SB - N/A #3255	MODIFICATION - POTABLE WATERSYSTEM (PWS) - REPLACE VENT VALVES THAT MAY CAUSE WATER LEAKS (A/C 9167, 9171 TO 9194 AND 9196 TO 9205), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-38-023 Airframe SB - N/A #3279	MODIFICATION - POTABLE WATERSYSTEM (PWS) - REPLACE WATER TANK VENT VALVES THAT MAY CAUSE WATER LEAKS (A/C 9167, 9171 TO 9264), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-38-024 PART B Airframe SB - N/A #3941	ACCESS - MODIFICATION - POTABLE WATERSYSTEM - REPLACEMENT OF THE 13 GALLON SHAW WATER TANK WITH A NEWLY DESIGNED TANK,-THE AFT 13 GALLON SHAW AERO DEVICES WATER TANK	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-38-024 PART A Airframe SB - N/A #4431	ACCESS - MODIFICATION - POTABLE WATERSYSTEM - REPLACEMENT OF THE 13 GALLON SHAW WATER TANK WITH A NEWLY DESIGNED TANK,-THE FORWARD 13 GALLON SHAW AERO DEVICES WATER TANK(S)	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-38-024 Airframe SB - N/A #3733	MODIFICATION - POTABLE WATERSYSTEM - REPLACEMENT OF THE 13 GALLON SHAW WATER TANK WITH A NEWLY DESIGNED TANK, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-38-025 PART A Airframe SB - Superseded #3793	MODIFICATION - POTABLE WATERSYSTEM - INTRODUCTION OF NEW 13 GALLON WATER TANK FOR PUMP SYSTEM, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-38-025 PART B Airframe SB - Superseded #3584	MODIFICATION - POTABLE WATERSYSTEM - INTRODUCTION OF NEW 13 GALLON WATER TANK FOR PUMP SYSTEM, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-38-025 R1 Airframe SB - Open #4321	MODIFICATION - POTABLE WATERSYSTEM INTRODUCTION OF NEW 13 GALLON WATER TANK FOR PUMP SYSTEM, SERVICE BULLETIN	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-38-025 R1 PART A Airframe SB - Open #3215	REPLACEMENT - MODIFICATION POTABLE WATERSYSTEM INTRODUCTION OF NEW 13 GALLON WATER TANK FOR PUMP SYSTEM,-OF THE FORWARD WATER TANK	H: 0.00					
SB 700-38-025 R1 PART B Airframe SB - Open #4191	REPLACEMENT - MODIFICATION POTABLE WATERSYSTEM INTRODUCTION OF NEW 13 GALLON WATER TANK FOR PUMP SYSTEM,-OF THE AFT WATER TANK	H: 0.00					
SB 700-38-026 PART A Airframe SB - Superseded #3672	MODIFICATION - POTABLE WATERSYSTEM - INTRODUCTION OF NEW 26 GALLON WATER TANK FOR PUMP SYSTEM, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-38-026 PART B Airframe SB - Superseded #4004	MODIFICATION - POTABLE WATERSYSTEM - INTRODUCTION OF NEW 26 GALLON WATER TANK FOR PUMP SYSTEM, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-38-026 R1 Airframe SB - Open #4062	MODIFICATION - POTABLE WATERSYSTEM INTRODUCTION OF NEW 26 GALLON WATER TANK FOR PUMP SYSTEM, SERVICE BULLETIN	H: 0.00					
SB 700-38-026 R1 PART B Airframe SB - Open #4103	REPLACEMENT - MODIFICATION POTABLE WATERSYSTEM INTRODUCTION OF NEW 26 GALLON WATER TANK FOR PUMP SYSTEM,-OF THE AFT WATER TANK	H: 0.00					
SB 700-38-026 R1 PART A Airframe SB - Open #4478	REPLACEMENT - MODIFICATION POTABLE WATERSYSTEM INTRODUCTION OF NEW 26 GALLON WATER TANK FOR PUMP SYSTEM,-OF THE FORWARD WATER TANK	H: 0.00					
SB 700-38-027 Airframe SB - Open #3145	MODIFICATION - WASTE DISPOSAL - SEALING THE MAGAIRTOILET BASE TO PREVENT STRUCTURAL DAMAGE, SERVICE BULLETIN	H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-38-029 Airframe SB - Open #4145	MODIFICATION - WASTE DISPOSAL - ADDITION OF A GALLEY DRAIN, SERVICE BULLETIN	H: 0.00					
SB 700-38-030 Airframe SB - N/A #4486	MODIFICATION - WASTE DISPOSAL - RELOCATION OF CHILLERDRAIN LINES TO PREVENT FREEZING AND SUBSEQUENT WATER SPILLS, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-38-031 Airframe SB - Open #3467	MODIFICATION - POTABLE WATERSYSTEM - QUICK DISCONNECT INSTALLATION AT POTABLE WATER TREATMENT UNIT (PWTU), SERVICE BULLETIN	H: 0.00					
SB 700-38-032 Airframe SB - N/A #4469	MODIFICATION - POTABLE WATERSYSTEM SECURE BLANKET HEATER TO WASTE WATER TEE-FITTING BELOW FLOOR, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-38-033 Airframe SB - Superseded #4311	MODIFICATION - WASTE DISPOSAL - INTRODUCTION OF IMPROVED RINSE VALVE TO PREVENT RINSE VALVE LEAKAGE, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-38-033 R1 Airframe SB - Complied With #4307	MODIFICATION - WASTE DISPOSAL - INTRODUCTION OF IMPROVED RINSE VALVE TO PREVENT RINSE VALVE LEAKAGE, SERVICE BULLETIN.	04-MAR-2016 H: 1753.70 L: 622					
SB 700-38-034 PART A Airframe SB - Complied With #1168	INSPECTION - MODIFICATION - POTABLE WATERSYSTEM - FWD LAV CLAMP RELOCATION, SERVICE BULLETIN	12-SEP-2012 H: 388.37 L: 190					
	Notes COMPLIED WITH						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-38-034 PART B Airframe SB - Complied With #2051	MODIFICATION - MODIFICATION - POTABLE WATERSYSTEM - FWD LAV CLAMP RELOCATION, SERVICE BULLETIN	12-SEP-2012 H: 388.37 L: 190					
	Notes COMPLIED WITH						
SB 700-38-034 Airframe SB - Complied With #1950	MODIFICATION - POTABLE WATERSYSTEM - FWD LAV CLAMP RELOCATION, SERVICE BULLETIN	12-SEP-2012 H: 388.37 L: 190					
	Notes COMPLIED WITH						
SB 700-38-035 Airframe SB - Open #3433	MODIFICATION - WASTE DISPOSAL - ADDITION OF HEATER AND INSULATION BLANKET TO THE DELTA PRESSURE (DP) SENSOR OF THE WATER TANK ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB 700-38-036 Airframe SB - Open #3581	MODIFICATION - POTABLE WATERSYSTEM - INSTALLATION OF WATER TREATMENT UNIT BYPASS SWITCH, SERVICE BULLETIN	H: 0.00					
SB 700-38-036 R1 Airframe SB - Open #3997	MODIFICATION - POTABLE WATERSYSTEM - INSTALLATION OF WATER TREATMENT UNIT BYPASS SWITCH, SERVICE BULLETIN.	H: 0.00					
SB 700-38-037 Airframe SB - N/A #4157	MODIFICATION - POTABLE WATERSYSTEM - REPLACEMENT OF THE 13 GALLON SHAW OR PARKER WATER TANK WITH A NEWLY-DESIGNED TANK, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
SB 700-38-037 PART B Airframe SB - N/A #3611	REPLACEMENT - MODIFICATION - POTABLE WATERSYSTEM - REPLACEMENT OF THE 13 GALLON SHAW OR PARKER WATER TANK WITH A NEWLY-DESIGNED TANK, OF THE AFT WATER TANK	H: 0.00					
	Notes NOT APPLICABLE						





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-38-037 PART A Airframe SB - N/A #4195	REPLACEMENT -MODIFICATION - POTABLE WATERSYSTEM - REPLACEMENT OF THE 13 GALLON SHAW OR PARKER WATER TANK WITH A NEWLY - DESIGNED TANK, OF THE FORWARD WATER TANK(S)	H: 0.00					
	Notes NOT APPLICABLE						
SB 700-38-037 R1 Airframe SB - N/A #3900	MODIFICATION - POTABLE WATERSYSTEM - REPLACEMENT OF THE 13 GALLON SHAW OR PARKER WATER TANK WITH A NEWLY DESIGNED TANK, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
SB 700-38-037 R1 PART B Airframe SB - N/A #3507	REPLACEMENT - MODIFICATION - POTABLE WATERSYSTEM - REPLACEMENT OF THE 13 GALLON SHAW OR PARKER WATER TANK WITH A NEWLY DESIGNED TANK,-OF AFT WATER TANK	H: 0.00					
	Notes NOT APPLICABLE						
SB 700-38-037 R1 PART A Airframe SB - N/A #4175	REPLACEMENT - MODIFICATION - POTABLE WATERSYSTEM - REPLACEMENT OF THE 13 GALLON SHAW OR PARKER WATER TANK WITH A NEWLY DESIGNED TANK,-OF FORWARD WATER TANK(S)	H: 0.00					
	Notes NOT APPLICABLE						
SB 700-44-003 Airframe SB - Complied With #4386	MODIFICATION - CABIN SYSTEMS - WIRELESS PASSENGERCONTROL UNIT (WPCU) SMART DOCK INSTALLATION, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-44-003 R1 Airframe SB - Open #3366	MODIFICATION - CABIN SYSTEMS - WIRELESS PASSENGERCONTROL UNIT (WPCU) SMART DOCK INSTALLATION, SERVICE BULLETIN.	H: 0.00					
SB 700-44-004 Airframe SB - Open #3205	MODIFICATION - CABIN ELECTRONICS SYSTEM - WIRELESS PASSENGERCONTROL UNIT (WPCU) NEW IPOD TOUCH(5) INSTALLATION WITH THE POST SMART DOCK INSTALLATION, SERVICE BULLETIN	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-44-004 R1 Airframe SB - Open #3316	MODIFICATION - CABIN ELECTRONICS SYSTEM - WIRELESS PASSENGERCONTROL UNIT (WPCU) NEW IPOD TOUCH(5) INSTALLATION WITH THE POST SMART DOCK INSTALLATION, SERVICE BULLETIN.	H: 0.00					
SB 700-44-004 R2 Airframe SB - Open #4122	MODIFICATION - CABIN ELECTRONICS SYSTEM - WIRELESS PASSENGERCONTROL UNIT (WPCU) NEW IPOD TOUCH(5) INSTALLATION WITH THE POST SMART DOCK INSTALLATION, SERVICE BULLETIN..	H: 0.00					
SB 700-44-006 Airframe SB - Open #3570	INSPECTION - CABIN ELECTRONICS SYSTEM - VARIABLE FREQUENCY CABLES, SAC HARNESSSES, CMS EMI CONNECTORS, GFI OUTLETS AND QUADRAX CONNECTORS, SERVICE BULLETIN	H: 0.00					
SB 700-44-007 Airframe SB - N/A #4230	MODIFICATION - CABIN ELECTRONICS SYSTEM - WIRELESS PASSENGERCONTROL UNIT (WPCU) NEW IPOD TOUCH (5) INSTALLATION, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
SB 700-44-007 R1 Airframe SB - N/A #4402	MODIFICATION - CABIN ELECTRONICS SYSTEM - WIRELESS PASSENGERCONTROL UNIT (WPCU) NEW IPOD TOUCH(5) INSTALLATION, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
SB 700-44-011 Airframe SB - Open #4806	MODIFICATION – SATELLITE COMMUNICATION SYSTEM – INSTALLATION OF A HONEYWELL JETWAVE™ KA BAND SATELLITE DATA SYSTEM						
SB 700-44-011 R03 Airframe SB - Open #4937	MODIFICATION – SATELLITE COMMUNICATION SYSTEM – INSTALLATION OF A HONEYWELL JETWAVE™ KA-BAND SATELLITE DATA SYSTEM						
SB 700-44-011 R1 Airframe SB - Complied With #4810	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INSTALLATION OF A HONEYWELL JETWAVE KA BAND SATELLITE DATA SYSTEM (REV. 1)	29-JAN-2018 H: 2586.20 L: 898					
SB 700-44-011 R2 Airframe SB - Complied With #4839	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INSTALLATION OF A HONEYWELL JETWAVE KA BAND SATELLITE DATA SYSTEM (REV. 2)	29-JAN-2018 H: 2586.20 L: 9385					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-44-011 R2 Airframe SB - Open #4879	MODIFICATION – SATELLITE COMMUNICATION SYSTEM – INSTALLATION OF A HONEYWELL JETWAVE KA BAND SATELLITE DATA SYSTEM						
SB 700-44-012 R1 Airframe SB - Open #4883	MODIFICATION SATELLITE COMMUNICATION SYSTEM HONEYWELL JETWAVE KA-BAND RADIO FREQUENCY UNIT (KRFU) REPLACEMENT						
SB 700-44-012 R2 Airframe SB - Open #4895	MODIFICATION SATELLITE COMMUNICATION SYSTEM HONEYWELL JETWAVE KA-BAND RADIO FREQUENCY UNIT (KRFU) REPLACEMENT						
SB 700-45-001 Airframe SB - Superseded #4602	MODIFICATION - CENTRAL AIRCRAFT-INFORMATION MAINTENANCE-SYSTEM (CAIMS) - INSTALLATION OF THE CAIMS REPORT-TO-PRINTERSWITCH, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-45-001 R1 Airframe SB - N/A #3613	MODIFICATION - CENTRAL AIRCRAFT-INFORMATION MAINTENANCE-SYSTEM (CAIMS) - INSTALLATION OF THE CAIMS REPORT-TO-PRINTERSWITCH (A/C 9002 TO 9139), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-45-004 Airframe SB - N/A #3824	MODIFICATION - CENTRAL MAINTENANCE SYSTEM - PORTABLE MAINTENANCE ACCESS TERMINAL (PMAT) (AM-200) PART NUMBERCHANGE, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-45-006 Airframe SB - N/A #4116	MODIFICATION - CENTRAL AIRCRAFT-INFORMATION MAINTENANCE SYSTEM (CAIMS) - INSTALL PORTABLE MAINTENANCE-ACCESS TERMINAL (PMAT) AND CABLE ASSEMBLY ON GREEN AIRCRAFT, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-45-008 Airframe SB - N/A #3842	MODIFICATION - CENTRAL AIRCRAFT INFORMATION MAINTENANCE SYSTEM (CAIMS) - INTRODUCTION OF CAIMS VERSION 7.1 TO SUPPORT POST FULL FUNCTIONALITY CERTIFICATION (PFF), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-45-009 Airframe SB - N/A #4616	MODIFICATION - CENTRAL AIRCRAFT INFORMATION MAINTENANCE SYSTEM (CAIMS) - INTRODUCTION OF PORTABLE MAINTENANCE ACCESS TERMINAL (PMAT) SOFTWARE VERSION 7.3 - FORA/C S/N 9002 TO 9165, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-45-010 Airframe SB - N/A #3303	MODIFICATION - CENTRAL AIRCRAFT INFORMATION MAINTENANCE SYSTEM (CAIMS) - INTRODUCTION OF PMAT -801 (A/C 9002 TO 9205), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-45-010 R1 Airframe SB - N/A #3903	MODIFICATION - CENTRAL AIRCRAFT-INFORMATION MAINTENANCE-SYSTEM (CAIMS)- INTRODUCTION OF PMAT -801, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-46-001 Airframe SB - Open #4679	MODIFICATION – ELECTRONIC FLIGHT BAG (EFB) SYSTEM – CMC ELECTRONIC FLIGHT BAG (EFB) UPGRADE						
SB 700-46-001 R1 Airframe SB - Open #4759	MODIFICATION - ELECTRONIC FLIGHT BAG (EFB) SYSTEM - CMC ELECTRONIC FLIGHT BAG (EFB) UPGRADE (REV. 1)						
SB 700-46-001 R2 Airframe SB - Open #4842	MODIFICATION – ELECTRONIC FLIGHT BAG (EFB) SYSTEM – CMC ELECTRONIC FLIGHT BAG (EFB) UPGRADE (REV. 2)						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-49-001 Airframe SB - Superseded #4374	MODIFICATION - AUTOMATIC CONTROL SYSTEM - REPLACEMENT OF THE AUXILIARY POWERUNIT (APU) FULL-AUTHORITY DIGITAL ENGINE-CONTROLLER (FADEC) UNIT, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-49-001 R1 Airframe SB - N/A #4582	MODIFICATION - AUTOMATIC CONTROL SYSTEM - REPLACEMENT OF THE AUXILIARY POWERUNIT (APU) FULL-AUTHORITY DIGITAL ENGINE-CONTROLLER (FADEC) UNIT, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-49-002 Airframe SB - Superseded #3630	MODIFICATION - EXHAUST - AUXILIARY POWERUNIT (APU) EXHAUST DUCT REPLACEMENT, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-49-002 R1 Airframe SB - N/A #4443	MODIFICATION - EXHAUST - AUXILIARY POWERUNIT (APU) EXHAUST DUCT REPLACEMENT, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-49-006 Airframe SB - Superseded #3614	MODIFICATION - AIR-INLET DOORSYSTEM - REPLACEMENT OF RIGHT HINGE ARM FOR CORRECT RIGGING, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-49-006 R1 Airframe SB - Superseded #3124	MODIFICATION - AIR-INLET DOORSYSTEM - REPLACEMENT OF RIGHT HINGE ARM FOR CORRECT RIGGING, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-49-006 R2 Airframe SB - Superseded #3832	MODIFICATION - AIR-INLET DOORSYSTEM - REPLACEMENT OF RIGHT HINGE ARM FOR CORRECT RIGGING, SERVICE BULLETIN..	H: 0.00					
	Notes SUPERSEDED						
SB 700-49-006 R3 Airframe SB - N/A #3953	MODIFICATION - AIR-INLET DOORSYSTEM - REPLACEMENT OF RIGHT HINGE ARM FOR CORRECT RIGGING, SERVICE BULLETIN..	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-49-007 Airframe SB - N/A #3180	MODIFICATION - BLEED AIRDUCTING - REPLACEMENT OF THE APU BLEED AIR SHROUD ASSEMBLY, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-49-010 Airframe SB - N/A #4000	MODIFICATION - INLET DOOR- LINEAR ACTUATOR, ACTUATOR ARM AND TAIL-CONE AFT FITTING REPLACEMENT (A/C 9002 TO 9085), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-49-010 R1 Airframe SB - N/A #4451	MODIFICATION - INLET DOOR- LINEAR ACTUATOR, ACTUATOR ARM AND TAIL-CONE AFT FITTING REPLACEMENT (A/C 9002 TO 9085), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-49-011 Airframe SB - N/A #4082	MODIFICATION - AIR-INLET DOORSYSTEM - INTRODUCTION OF A NEW AIR-INLET DOOR AND SURROUNDING STRUCTURE (A/C 9001 TO 9085), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-49-012 Airframe SB - N/A #3521	REWORK - POWERPLANT - REPAIR OF APU COMPRESSOR SHROUD, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-49-013 Airframe SB - N/A #4241	MODIFICATION - AUTOMATIC CONTROL SYSTEM - REPLACEMENT OF THE SECONDARY POWERWIRE FOR THE AUXILIARY POWER UNIT (APU) FULL-AUTHORITY DIGITAL ENGINE-CONTROLLER (FADAC) (A/C 9002 TO 9129), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-49-014 Airframe SB - Complied With #1345	MODIFICATION - AIRINLET DOOR SYSTEM-RELOCATION OF THE BONDING JUMPER, SERVICE BULLETIN	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
SB 700-49-015 Airframe SB - Complied With #2399	MODIFICATION - INDICATING - AUXILIARY POWERUNIT (APU) EXHAUST-GAS TEMPERATURE SENSOR UPGRADE TO PART NUMBER WE3876352-2 WITH SERIAL NUMBER 50413-1000204 OR ABOVE, SERVICE BULLETIN	12-SEP-2012 H: 388.37 L: 190					
	Notes COMPLIED WITH						
SB 700-49-016 Airframe SB - Open #4807	SPECIAL CHECK/MODIFICATION - AUTOMATIC CONTROL SYSTEM - VISUAL INSPECTION AND SEALANT APPLICATION METHOD FOR THE EXHAUST GAS TEMPERATURE (EGT) SENSOR, PART NUMBER WE3876352-1 AND WE3876352-2						
SB 700-52-005 Airframe SB - N/A #3391	MODIFICATION - PASSENGERDOOR - REPLACEMENT OF EXTERNAL HANDLE ATTACHMENT BOLTS, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-52-006 Airframe SB - N/A #3080	MODIFICATION - PASSENGERDOOR - BOTTOM STEP LIGHT REPLACEMENT, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-52-007 Airframe SB - Superseded #4019	MODIFICATION - PASSENGERDOOR - INTERNAL-HANDLE COVER IMPROVEMENT, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-52-007 R1 Airframe SB - N/A #4209	MODIFICATION - PASSENGERDOOR - INTERNAL-HANDLE COVER IMPROVEMENT, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-52-008 Airframe SB - Superseded #3154	MODIFICATION - SERVICE DOORS - REPLACEMENT OF NO. 3 HYDRAULIC-SYSTEM SERVICING DOORSEALS, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-52-008 R1 Airframe SB - N/A #3706	MODIFICATION - SERVICE DOORS - REPLACEMENT OF NO. 3 HYDRAULIC-SYSTEM SERVICING DOORSEALS, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-52-009 Airframe SB - N/A #4331	MODIFICATION - PASSENGERDOOR - BOTTOM STEP STOP BRACKETS AND RUBBER STOP TO STAINLESS STEEL STOP REPLACEMENT, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-52-010 Airframe SB - N/A #4134	MODIFICATION - EMERGENCY EXIT - ADDITION OF DRAINAGE FOROVER WING EMERGENCY EXIT DOOR, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-52-011 Airframe SB - N/A #4316	MODIFICATION - PASSENGERDOOR UPGRADE OF THE PASSENGER DOOR ACTUATOR WITH A HIGH-TORQUE ACTUATOR, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-52-014 Airframe SB - Superseded #3719	MODIFICATION - PASSENGERDOOR - REPLACEMENT OF TOP-STEP SUPPORT STRUCTURE AND REPLACEMENT OF TOP-STEP HINGE PINS AND NYLON COVER, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-52-014 R1 Airframe SB - N/A #3723	MODIFICATION - PASSENGERDOOR - REINFORCEMENT OF TOP-STEP SUPPORT STRUCTURE AND REPLACEMENT OF TOP-STEP HINGE PINS AND NYLON COVER (A/C 9002 TO 9095), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-52-015 Airframe SB - N/A #3189	MODIFICATION - AFT EQUIPMENT-COMPARTMENT DOOR- DOOR LANYARD ATTACHMENT POINT MODIFICATION TO PREVENT PREMATURE BUSHING FAILURE, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-52-017 Airframe SB - N/A #3299	MODIFICATION - SERVICE DOOR- PREVENT FOULING CONDITION BETWEEN FOWARD TOILET WASTE SERVICE DOOR AND FUSELAGE SKIN, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-52-018 Airframe SB - N/A #4355	MODIFICATION - PASSENGERDOOR - ADDITION OF A HANDHOLD FEATURE TO ASSIST DOOR CLOSURE, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-52-019 Airframe SB - N/A #3822	MODIFICATION - PASSENGERDOOR - INTRODUCTION OF PAX DOOR DAMPER MECHANISM FOR LOWER FOLDING-STEP (A/C EFFECTIVITY : S/N 9002 TO 9126, 9128, 9129 AND 9131 TO 9138), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-52-020 Airframe SB - N/A #4467	MODIFICATION - PASSENGERDOOR - INSTALLATION OF ADJUSTABLE BOTTOM-STEP STOPS, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-52-021 Airframe SB - Superseded #3605	MODIFICATION - PASSENGERDOOR - INSTALLATION OF AESTHETIC SIDE COVERS, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-52-021 R1 Airframe SB - Superseded #3992	MODIFICATION - PASSENGERDOOR - INSTALLATION OF AESTHETIC SIDE COVERS (EFFECTIVITY A/C 9002 TO 9999), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-52-021 R2 Airframe SB - Superseded #3163	MODIFICATION - PASSENGERDOOR - INSTALLATION OF AESTHETIC SIDE COVERS (A/C 9002 TO 9999), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-52-021 R3 Airframe SB - Superseded #4599	MODIFICATION - PASSENGERDOOR - INSTALLATION OF AESTHETIC SIDE COVERS, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-52-021 R4 Airframe SB - Complied With #1081	MODIFICATION - PASSENGERDOOR - INSTALLATION OF AESTHETIC SIDE COVERS, SERVICE BULLETIN..	22-JUN-2015 H: 1493.00 L: 523					
	Notes COMPLIED WITH						
SB 700-52-022 Airframe SB - N/A #3434	MODIFICATION - PASSENGERDOOR - INTERNAL HANDLE INDICATION IMPROVEMENT (A/C 9002 TO 9095), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-52-024 Airframe SB - N/A #3859	SPECIAL CHECK/REWORK - AFT EQUIPMENT COMPARTEMENT DOOR- POSSIBLE GAPS BETWEEN APERTURE P-SEALS, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-52-025 Airframe SB - Superseded #3461	MODIFICATION - PASSENGERDOOR - HANDRAIL RETAINER MECHANISM (A/C 9096 TO 9999), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-52-025 R1 Airframe SB - Superseded #3074	MODIFICATION - PASSENGERDOOR - HANDRAIL RETAINER MECHANISM, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-52-025 R2 Airframe SB - N/A #4396	MODIFICATION - PASSENGERDOOR - HANDRAIL RETAINER MECHANISM (A/C 9096 TO 9183, AND 9002 TO 9095), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-52-026 Airframe SB - N/A #4323	MODIFICATION - PASSENGERDOOR - INSTALLATION OF RETENTION STOPS ON AIRCRAFT WITH SUPPLEMENTAL TYPE CERTIFICATE (STC)-INSTALLED HANDRAIL ASSEMBLIES (A/C 9002 TO 9095), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-52-027 Airframe SB - Superseded #3178	MODIFICATION - PASSENGERDOOR - INTRODUCTION OF NEW INSTALLATION OF PAX DOOR KEYLOCK (A/C 9002 TO 9999), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-52-027 R1 Airframe SB - Superseded #3554	MODIFICATION - PASSENGERDOOR - INTRODUCTION OF NEW INSTALLATION OF PAX DOOR KEYLOCK (A/C 9002 TO 9303), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-52-027 R2 Airframe SB - N/A #4338	MODIFICATION - PASSENGERDOOR - INTRODUCTION OF NEW INSTALLATION OF PAX DOOR KEYLOCK (A/C 9002 TO 9303), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-52-029 Airframe SB - N/A #3144	MODIFICATION - PASSENGERDOOR - VENT FLAP IMPROVEMENTS TO PASSENGER DOOR (A/C 9002 TO 9204), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-52-030 Airframe SB - N/A #3561	MODIFICATION - PASSENGERDOOR - ADDITION OF A PAD FOR THE PASSENGER DOOR EXTERNAL HANDLE DETENT (A/C 9002 TO 9126 AND 9128 TO 9187), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-52-031 PART A Airframe SB - N/A #115	MODIFICATION - PASSENGERDOOR - MIGRATION PREVENTION OF THE FORWARD AND AFT HANDRAIL SUPPORT-PIN BUSHINGS (A/C 9001 TO 9170), SERVICE BULLETIN	02-AUG-2013 H: 432.80 L: 211					
	Notes NOT APPLICABLE - PERAIRCRAFT SERIAL NUMBER						
SB 700-52-031 PART B Airframe SB - N/A #2377	MODIFICATION - PASSENGERDOOR - MIGRATION PREVENTION OF THE FORWARD AND AFT HANDRAIL SUPPORT-PIN BUSHINGS (A/C 9171 TO 9207), SERVICE BULLETIN	02-AUG-2013 H: 432.80 L: 211					
	Notes NOT APPLICABLE - PERA/C SERIAL NUMBER EFFECTIVITY						
SB 700-52-032 Airframe SB - N/A #3807	MODIFICATION - BAGGAGE DOOR- ADDITION OF A NYLON BLOCK TO THE BAGGAGE DOOR TO PREVENT AN UNWANTED EICAS MESSAGE (A/C 9002 TO 9298), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-52-033 Airframe SB - Superseded #4578	MODIFICATION - BAGGAGE DOOR- REPLACE BAGGAGE DOOR TRACK ROLLERS TO IMPROVE OPERATION (A/C 9002 TO 9314), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-52-033 R1 Airframe SB - N/A #3223	MODIFICATION - BAGGAGE DOOR- REPLACE BAGGAGE DOOR TRACK ROLLERS TO IMPROVE OPERATION, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-52-034 Airframe SB - Complied With #277	MODIFICATION - BAGGAGE DOOR- INTRODUCTION OF NEW INTERNAL DOOR "T" HANDLE, SERVICE BULLETIN	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
SB 700-52-034 R1 Airframe SB - Open #4530	MODIFICATION - BAGGAGE DOOR INTRODUCTION OF NEW INTERNAL DOOR "T" HANDLE, SERVICE BULLETIN	H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-52-035 Airframe SB - Superseded #4425	MODIFICATION - BAGGAGE BAY DOOR- MODIFICATION TO DOOR LOCKING MECHANISM TO PREVENT LOCK ROTATION, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-52-035 R1 Airframe SB - Open #3158	MODIFICATION - BAGGAGE BAY DOOR- MODIFICATION TO DOOR LOCKING MECHANISM TO PREVENT LOCK ROTATION, SERVICE BULLETIN.	H: 0.00					
SB 700-52-036 Airframe SB - Superseded #3263	MODIFICATION - BAGGAGE DOOR- INSTALLATION OF A MECHANICAL STOP ON THE DOOR HANDLE, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-52-036 R1 Airframe SB - Complied With #104	MODIFICATION - BAGGAGE DOOR- INSTALLATION OF A MECHANICAL STOP ON THE DOOR HANDLE, SERVICE BULLETIN.	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
SB 700-52-037 Airframe SB - Superseded #4546	MODIFICATION - PASSENGERDOOR - INTRODUCTION OF VARIABLE RADIUS PULLEY AND NEW ACTUATOR, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-52-037 R1 Airframe SB - Superseded #4185	MODIFICATION - PASSENGERDOOR - INTRODUCTION OF VARIABLE RADIUS PULLEY AND NEW ACTUATOR, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-52-037 R2 Airframe SB - N/A #2338	MODIFICATION - PASSENGERDOOR INTRODUCTION OF VARIABLE RADIUS PULLEY AND NEW ACTUATOR, SERVICE BULLETIN	16-FEB-2012 H: 292.60 L: 134					
	Notes NOT APPLICABLE - N/A BY A/C S/N						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-52-038 Airframe SB - Superseded #4476	SPECIAL CHECK/REWORK - PASSENGERDOOR - REPLACEMENT OF PAX DOOR TENSATOR SPRINGS, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-52-038 R1 Airframe SB - Open #3068	SPECIAL CHECK/REWORK - PASSENGERDOOR - REPLACEMENT OF PAX DOOR TENSATOR SPRINGS, SERVICE BULLETIN.	H: 0.00					
SB 700-52-039 Airframe SB - Open #4586	REWORK - PASSENGERDOOR - REWORK PAX DOOR AESTHETIC COVERS TO FIT NEW DOOR PULLEY, SERVICE BULLETIN	H: 0.00					
SB 700-52-040 Airframe SB - Superseded #3092	MODIFICATION - PASSENGERDOOR - INTRODUCTION OF PAX DOOR BOTTOM STEP MOTOR WITH IMPROVED PERFORMANCE AND FILTER, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-52-040 R1 Airframe SB - Complied With #851	MODIFICATION - PASSENGERDOOR - INTRODUCTION OF PAX DOOR BOTTOM STEP MOTOR WITH IMPROVED PERFORMANCE AND FILTER, SERVICE BULLETIN.	12-SEP-2012 H: 388.37 L: 190					
	Notes COMPLIED WITH						
SB 700-52-041 Airframe SB - Open #3692	MODIFICATION - PASSENGERDOOR - INSTALLATION OF ECCENTRIC BUSHINGS IN TOP STEP FOR IMPROVED ALIGNMENT, SERVICE BULLETIN	H: 0.00					
SB 700-52-042 Airframe SB - Complied With #2299	ICA - MODIFICATION - AFT EQUIPMENT-COMPARTMENT DOOR- MODIFICATION TO PREVENT FUEL INGRESS INTO THE AFT EQUIPMENT BAY, SERVICE BULLETIN	12-SEP-2012 H: 388.37 L: 190					
	Notes COMPLIED WITH						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-52-043 Airframe SB - Complied With #822	MODIFICATION - PASSENGERDOOR - REPLACEMENT OF NYLON SCREW ON HANDRAIL EXTENSION, SERVICE BULLETIN	22-DEC-2011 H: 253.80 L: 116					
	Notes COMPLIED WITH						
SB 700-52-044 Airframe SB - Complied With #2950	MODIFICATION - PASSENGERDOOR - RECONFIGURATION OF THE PASSENGER DOOR EXTERNAL HANDLE DETENT, SERVICE BULLETIN	08-OCT-2014 H: 1015.50 L: 386					
	Notes COMPLIED WITH - INCORPORATED SB700-52-044 (BASIC) ON ACFT 9385						
SB 700-52-044 R1 Airframe SB - Open #4491	MODIFICATION - PASSENGERDOOR - RECONFIGURATION OF THE PASSENGER DOOR EXTERNAL HANDLE DETENT, SERVICE BULLETIN.	H: 0.00					
SB 700-52-044 R2 Airframe SB - Open #4680	ICA - MODIFICATION - PASSENGER DOOR -RECONFIGURATION OF THE PASSENGER DOOR EXTERNAL HANDLE DETENT (REV. 2)						
SB 700-52-046 Airframe SB - Open #3070	REWORK - PASSENGERDOOR - REPLACEMENT OF PAX DOOR TENSATOR SPRINGS, SERVICE BULLETIN	H: 0.00					
SB 700-53-013 Airframe SB - N/A #4522	REWORK - BELLY FAIRINGS - ADDITION OF DRAIN HOLE NEARREFUEL/DEFUEL COMPARTMENT, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-53-016 Airframe SB - Superseded #4135	MODIFICATION - BELLY FAIRINGS - ADDITION OF DRAIN HOLES TO BELLY FAIRING PANELS, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-53-016 R1 Airframe SB - Superseded #3098	MODIFICATION - BELLY FAIRINGS - ADDITION OF DRAIN HOLES TO BELLY FAIRING PANELS, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-53-016 R2 Airframe SB - N/A #3317	MODIFICATION - BELLY FAIRINGS - ADDITION OF DRAIN HOLES TO BELLY FAIRING PANELS, SERVICE BULLETIN..	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-53-018 Airframe SB - N/A #3439	MODIFICATION - FUSELAGE - INSTALLATION OF LOUVERS TO RAM AIROUTLET DUCT, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-53-019 Airframe SB - Superseded #3306	MODIFICATION - FORWARD FUSELAGE FLOOR- ALLOW REMOVAL OF STRUCTURAL FLOOR PANEL FOR INSPECTION AND EASE OF REPLACEMENT, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-53-019 R1 Airframe SB - N/A #4472	MODIFICATION - FORWARD FUSELAGE FLOOR- ALLOW REMOVAL OF STRUCTURAL FLOOR PANEL FOR INSPECTION AND EASE OF REPLACEMENT, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-53-021 Airframe SB - N/A #3208	MODIFICATION - FORWARD WING-TO-FUSELAGE FAIRING - ADDITION OF SEALANT IN THE LAVATORY SERVICE BAY TO PREVENT WASTE SPILLAGE FROM ENTERING FORWARD WING-TO-FUSELAGE FAIRING, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-53-022 Airframe SB - N/A #3290	SPECIAL CHECK/REWORK - AFT FUSELAGE - CENTER-TO-AFT FUSELAGE JOINT CONFIGURATION (FS785.00), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-53-024 Airframe SB - N/A #4008	MODIFICATION - CENTERFUSELAGE - REMOVAL OF WHEEL BIN SOUND - DAMPING BLANKETS TO REDUCE WEIGHT, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-53-025 Airframe SB - N/A #3141	MODIFICATION - WING-TO-FUSELAGE FAIRINGS - REPLACEMENT OF TEFLON SHEET ON VISORPANEL TO PREVENT DAMAGE TO AFT OVER-WING FAIRING PAINT FINISH, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-53-025 R1 Airframe SB - N/A #3512	MODIFICATION - WING-TO-FUSELAGE FAIRINGS - REPLACEMENT OF TEFLON SHEET ON VISORPANEL TO PREVENT DAMAGE TO AFT OVER-WING FAIRING PAINT FINISH (A/C 9002 TO 9043 AND 9045 TO 9163), SERVICE BULLETIN	H: 0.00					
SB 700-53-027 Airframe SB - Superseded #3485	MODIFICATION - AFT FUSELAGE - ADDITION OF DRAINAGE PROVISIONS AT THE BAGGAGE DOORSILL, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-53-027 R1 Airframe SB - N/A #4131	MODIFICATION - AFT FUSELAGE - ADDITION OF DRAINAGE PROVISIONS AT THE BAGGAGE DOORSILL, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-53-028 Airframe SB - Complied With #2544	MODIFICATION - AFT EQUIPMENT COMPARTMENT - DRIP TRAY INSTALLATION TO PROTECT RADIO ALTIMETERAND HF TRANSCEIVER NO. 2, SERVICE BULLETIN	12-SEP-2012 H: 388.37 L: 190					
	Notes COMPLIED WITH						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-53-029 Airframe SB - Superseded #4403	SPECIAL CHECK/MODIFICATION - GENERAL - ADDITION OF HARNESS SUPPORT TO PREVENT CONTACT BETWEEN WIRE HARNESS AND FUEL LINES, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-53-029 R1 Airframe SB - Superseded #4035	SPECIAL CHECK/MODIFICATION - GENERAL - ADDITION OF HARNESS SUPPORT TO PREVENT CONTACT BETWEEN WIRE HARNESS AND FUEL LINES, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-53-029 R2 PART B Airframe SB - N/A #4356	SPECIAL CHECK/REWORK/MODIFICATION - GENERAL - ADDITION OF HARNESS SUPPORT TO PREVENT CONTACT BETWEEN WIRE HARNESS AND FUEL LINES (A/C 9002 TO 9126, 9128 TO 9201), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-53-029 R2 PART A Airframe SB - N/A #4262	SPECIAL CHECK/REWORK/MODIFICATION - GENERAL - ADDITION OF HARNESS SUPPORT TO PREVENT CONTACT BETWEEN WIRE HARNESS AND FUEL LINES (A/C 9002 TO 9126, 9128, 9129 AND 9131 TO 9134), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-53-031 Airframe SB - N/A #3301	SPECIAL CHECK/REWORK - BELLY FAIRINGS - REMOVAL OF REDUNDANT AERODYNAMIC SEALANT TO ALLOW DRAINAGE OF FLUIDS, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-53-034 Airframe SB - N/A #3264	MODIFICATION - FORWARD-FUSELAGE FLOOR- ADDITION OF DRAIN HOLES AT FRAME FS328.50 AND STRINGER 24LH (A/C 9002 TO 9126 AND 9128 TO 9328), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-53-035 Airframe SB - Superseded #4211	MODIFICATION - EMPENNAGE/TAIL - ADDITION OF DRAIN HOLE ON RIB NO. 7 OF RUDDER, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-53-035 R1 Airframe SB - N/A #4095	MODIFICATION - EMPENNAGE/TAIL - ADDITION OF DRAIN HOLE ON RIB NO. 7 OF RUDDER-(A/C 9002 TO 9126 AND 9128 TO 9294), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-53-037 Airframe SB - N/A #3852	MODIFICATION - NOSE FUSELAGE - REPLACE CLIP-NUTS WITH NUT-PLATES FORTRIM PANELS AT FS280.00, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-53-038 Airframe SB - N/A #3641	MODIFICATION - BELLY FAIRING - ADDITION OF DRAIN HOLES TO PREVENT WATERACCUMULATION (A/C 9002 TO 9126 AND 9128 TO 9229), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-53-040 Airframe SB - Complied With #2795	MODIFICATION - AVIONICS BAY - INSTALLATION OF PROTECTIVE COVERS OVERTHE FCU AND SFCU UNITS, SERVICE BULLETIN	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
SB 700-53-040 R1 Airframe SB - Open #4553	MODIFICATION - AVIONICS BAY - INSTALLATION OF PROTECTIVE COVERS OVERTHE FCU AND SFCU UNITS, SERVICE BULLETIN.	H: 0.00					
SB 700-53-040 R2 Airframe SB - Open #3286	MODIFICATION - AVIONICS BAY - INSTALLATION OF PROTECTIVE COVERS OVERTHE FCU AND SFCU UNITS, SERVICE BULLETIN..	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-53-041 Airframe SB - N/A #3168	REWORK - CENTERFUSELAGE - REWORK SURFACE FINISH AT FITTING ASSEMBLY ON THE EMERGENCY EXIT DOOR, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-53-042 Airframe SB - Superseded #3308	SPECIAL CHECK/REWORK - AFT FUSELAGE - INSPECTION OF BOLTS ON BAGGAGE DOORSTOPS AND REPLACE IF LOOSE, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-53-042 R1 Airframe SB - Complied With #2028	ICA - SPECIAL CHECK/REWORK - AFT FUSELAGE - INSPECTION OF BOLTS ON BAGGAGE DOORSTOPS AND REPLACE IF LOOSE, SERVICE BULLETIN	16-FEB-2012 H: 292.60 L: 134					
	Notes COMPLIED WITH - C/W PART A & PART B N/A						
SB 700-53-043 Airframe SB - Superseded #3396	MODIFICATION - AFT EQUIPMENT COMPARTMENT - INSTALLATION OF STORAGE PROVISION FORGROUND AIR SUPPLY ADAPTOR, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-53-043 R1 Airframe SB - Superseded #4155	MODIFICATION - AFT EQUIPMENT COMPARTMENT - INSTALLATION OF STORAGE PROVISION FORGROUND AIR SUPPLY ADAPTOR, SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-53-043 R2 Airframe SB - Complied With #3703	MODIFICATION - AFT EQUIPMENT COMPARTMENT - INSTALLATION OF STORAGE PROVISION FORGROUND AIR SUPPLY ADAPTOR, SERVICE BULLETIN..	04-MAR-2016 H: 1753.70 L: 622					
SB 700-53-044 Airframe SB - Complied With #2675	MODIFICATION - FORWARD FUSELAGE FLOOR- INSTALLATION OF A PROTECTIVE COVER OVER THE EGPWS, SERVICE BULLETIN	12-SEP-2012 H: 388.37 L: 190					
	Notes COMPLIED WITH						





Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-53-047 Airframe SB - Open #3974	SPECIAL CHECK/REWORK - AFT FUSELAGE - REWORK WING/FUSELAGE FAIRING SILL TO PREVENT CORROSION, SERVICE BULLETIN	H: 0.00					
SB 700-53-048 Airframe SB - N/A #4423	SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLY FORCORROSION, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
SB 700-53-049 PART A Airframe SB - N/A #3119	DETAILED VISUAL INSPECTION-SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLYAND APU DOORS FORCORROSION, - (DVI) OF THE TAILCONE ASSEMBLY	H: 0.00					
	Notes NOT APPLICABLE						
SB 700-53-049 Airframe SB - N/A #3160	SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLYAND APU DOORS FORCORROSION, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
SB 700-53-049 PART B Airframe SB - N/A #3794	SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLYAND APU DOORS FORCORROSION,-LOCAL REWORK OF THE TAILCONE ASSEMBLY	H: 0.00					
	Notes NOT APPLICABLE						
SB 700-53-049 PART D Airframe SB - N/A #3048	SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLYAND APU DOORS FORCORROSION,-MAJOR REWORK OF THE APU DOOR SKINS	H: 0.00					
	Notes NOT APPLICABLE						
SB 700-53-049 PART C Airframe SB - N/A #4183	SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLYAND APU DOORS FORCORROSION,-MAJOR REWORK OF THE FORWARD/AFT TAILCONE AND END CAP SKINS	H: 0.00					
	Notes NOT APPLICABLE						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-53-049 R1 Airframe SB - Open #4792	SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLY AND APU DOORS FOR CORROSION (REV. 1)						
SB 700-53-050 Airframe SB - Complied With #4729	MODIFICATION - BELLY FAIRINGS - REPLACEMENT OF ATTACHMENTS FOR THE ACCESS PANELS	23-NOV-2016					H: 2064.80 L: 722
SB 700-53-050 R1 Airframe SB - N/A #4789	MODIFICATION – BELLY FAIRINGS –REPLACEMENT OF ATTACHMENTS FOR THE ACCESS PANEL (REV. 1)						
	Notes NA PER SB DUE SB700-53-050 HAS BEEN PREVIOUSLY COMPLIED WITH						
SB 700-53-051 Airframe SB - Complied With #4804	SPECIAL CHECK/REWORK - BELLY FAIRINGS - INSPECT FORWARD AND MIDDLE ACCESS PANEL (181BB) AND (183BB) FOR DRAINAGE HOLE BLOCKAGE, AND IF NECESSARY REMOVE SEALANT	29-SEP-2017					H: 2431.70 L: 854
SB 700-53-052 Airframe SB - Complied With #4874	MODIFICATION - AFT FUSELAGE - REPLACEMENT AND REINFORCEMENT OF THE RUDDER QUADRANT BOX ASSEMBLY HALF RIBS	18-APR-2020					H: 3741.10 L: 1233
SB 700-53-053 Airframe SB - Open #4819	SPECIAL CHECK - BELLY FAIRING ACCESS PANELS - RE-TORQUE OF THE BELLY FAIRING FASTENERS ON 185CL AND 186CR						
SB 700-53-054 Airframe SB - Complied With #4875	SPECIAL CHECK - AFT FUSELAGE - INSPECTION OF THE RUDDER QUADRANT BOX ASSEMBLY	31-MAR-2020					H: 3741.10 L: 1233
	Notes COMPLIANCE DUE AT 2000 cycles						
SB 700-53-055 Airframe SB - Complied With #4887	MODIFICATION - AUXILIARY POWER UNIT (APU) ACCESS DOORS - MODIFICATION OF APU ACCESS DOORS AND FORWARD/AFT TAILCONE TO IMPROVE DRAINAGE AND PREVENT CORROSION	01-DEC-2018					H: 3011.20 L: 1025



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-55-002 Airframe SB - Superseded #3592	MODIFICATION/REWORK - ELEVATORCONTROL SURFACES - ELIMINATE GAP BETWEEN ELEVATOR AND BULLET FAIRING, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-55-002 R1 Airframe SB - N/A #3797	MODIFICATION/REWORK - ELEVATORCONTROL SURFACES - ELIMINATE GAP BETWEEN ELEVATOR AND BULLET FAIRING, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-55-004 PART A Airframe SB - N/A #4609	MODIFICATION - HORIZONTAL STABILIZER- ADDITION OF DRAINAGE HOLES TO ELIMINATE WATER ACCUMULATION AND ADDITION OF RIVETS ON THE ACCESS PANELS NUTPLATE ASSEMBLIES, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-55-004 PART B Airframe SB - N/A #4505	MODIFICATION - HORIZONTAL STABILIZER- ADDITION OF DRAINAGE HOLES TO ELIMINATE WATER ACCUMULATION AND ADDITION OF RIVETS ON THE ACCESS PANELS NUTPLATE ASSEMBLIES, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-55-005 Airframe SB - N/A #4439	SPECIAL CHECK/REWORK - HORIZONTAL STABILIZER- INSPECT THE L/H AND R/H INBOARD LEADING EDGES AND REPLACE, IF NECESSARY, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-55-006 Airframe SB - Complied With #4076	MODIFICATION - HORIZONTAL STABILIZER- ADDITION OF DRAINAGE HOLES TO ELIMINATE WATER ACCUMULATION, SERVICE BULLETIN	04-MAR-2016 H: 1753.70 L: 622					
SB 700-55-007 Airframe SB - Open #4797	MODIFICATION – VERTICAL STABILIZER – MODIFICATION OF BULLET AND DORSAL FAIRINGS TO IMPROVE DRAINAGE AND PREVENT CORROSION						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-55-007 R1 Airframe SB - Open #4803	MODIFICATION – VERTICAL STABILIZER – MODIFICATION OF BULLET AND DORSAL FAIRINGS TO IMPROVE DRAINAGE AND PREVENT CORROSION (REV. 1)						
SB 700-55-007 R2 Airframe SB - Complied With #4852	MODIFICATION - VERTICAL STABILIZER - MODIFICATION OF BULLET AND DORSAL FAIRINGS TO IMPROVE DRAINAGE AND PREVENT CORROSION (REV. 2)					31-MAR-2021 H: 3992.00 L: 1324	
SB 700-56-001 Airframe SB - N/A #3111	MODIFICATION - PASSENGERCOMPARTMENT - OPTIONAL CABIN WINDOW(S), SERVICE BULLETIN			H: 0.00			
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-56-006 Airframe SB - N/A #3359	MODIFICATION - ELECTRIC WINDOW SHADE ASSEMBLY - REMOVAL OF SHEARSHADE FROM WINDOW, SERVICE BULLETIN			H: 0.00			
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-56-007 Airframe SB - Complied With #4389	SPECIAL CHECK/REWORK - FLIGHT COMPARTMENT - INSPECT THE WINDSHIELD/SIDE WINDOW AND IF NECESSARY REPAIRSEAL, SERVICE BULLETIN					17-FEB-2021 H: 3992.00 L: 1324	
SB 700-57-021 Airframe SB - Superseded #3624	REWORK - LEADING EDGE SLATS - AERODYNAMIC CLEAN-UP - (A/C 9006), SERVICE BULLETIN			H: 0.00			
	Notes SUPERSEDED						
SB 700-57-021 R1 Airframe SB - Superseded #3188	REWORK - LEADING EDGE SLATS - AERODYNAMIC CLEAN-UP - (A/C 9006), SERVICE BULLETIN.			H: 0.00			
	Notes SUPERSEDED						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-57-021 R2 Airframe SB - N/A #3122	REWORK - LEADING EDGE SLATS - AERODYNAMIC CLEAN-UP (A/C 9006), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-57-022 Airframe SB - N/A #3944	MODIFICATION - CENTERWING - OVER-WING FAIRINGS AND UNDER-WING FAIRINGS SEALS REPLACEMENT, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-57-023 Airframe SB - N/A #4308	MODIFICATION - OUTERWING - REVISE SEAL OF WING LOWER TRAILING EDGE TO INBOARD FLAP, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-57-024 Airframe SB - Superseded #3503	MODIFICATION - LEADING EDGE SLATS - SLAT ACTUATORNO. 8 AERODYNAMIC SEAL IMPROVEMENT, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-57-024 R1 Airframe SB - N/A #3242	MODIFICATION - LEADING EDGE SLATS - SLAT ACTUATORNO. 8 AERODYNAMIC SEAL IMPROVEMENT, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-57-025 Airframe SB - N/A #3631	MODIFICATION - FLAP FAIRINGS - ADDITION OF DRAIN HOLES IN FLAP FAIRING ASSEMBLIES, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-57-027 Airframe SB - Superseded #4294	MODIFICATION - LEADING EDGE AND LEADING EDGE DEVICES - REPLACEMENT OF FASTENERS ON THE FIXED LEADING EDGES, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-57-027 R1 PART A Airframe SB - N/A #4450	MODIFICATION - LEADING EDGE AND LEADING EDGE DEVICES - REPLACEMENT OF FASTENERS ON THE FIXED LEADING EDGES (A/C 9002 AND 9004 TO 9064), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-57-027 R1 PART B Airframe SB - N/A #3256	MODIFICATION - LEADING EDGE AND LEADING EDGE DEVICES - REPLACEMENT OF FASTENERS ON THE FIXED LEADING EDGES (A/C 9002 AND 9004 TO 9064), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-57-028 PART B Airframe SB - Superseded #3970	MODIFICATION - LEADING EDGE SLATS - REPLACEMENT OF SLAT SPACERON SLAT NO.1 INBOARD, MID AND OUTBOARD TRACKS, SLAT NO. 2 INBOARD AND OUTBOARD TRACKS AND SLAT NO.3 AND NO.4 INBOARD TRACKS, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-57-028 PART A Airframe SB - Superseded #4480	SPECIAL CHECK/REWORK - LEADING EDGE SLATS - REPLACEMENT OF SLAT SPACERON SLAT NO.1 INBOARD, MID AND OUTBOARD TRACKS, SLAT NO. 2 INBOARD AND OUTBOARD TRACKS AND SLAT NO.3 AND NO.4 INBOARD TRACKS, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-57-028 R1 PART B Airframe SB - N/A #4492	MODIFICATION - LEADING EDGE SLATS - REPLACEMENT OF SLAT SPACERON SLAT NO.1 INBOARD, MID AND OUTBOARD TRACKS, SLAT NO. 2 INBOARD AND OUTBOARD TRACKS AND SLAT NO.3 AND NO.4 INBOARD TRACKS, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-57-028 R1 PART A Airframe SB - N/A #3262	SPECIAL CHECK/REWORK - LEADING EDGE SLATS - REPLACEMENT OF SLAT SPACERON SLAT NO.1 INBOARD, MID AND OUTBOARD TRACKS, SLAT NO. 2 INBOARD AND OUTBOARD TRACKS AND SLAT NO.3 AND NO.4 INBOARD TRACKS, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-57-029 Airframe SB - N/A #3958	MODIFICATION - LEADING EDGE SLAT SYSTEM - REPLACEMENT OF THE SLAT NO. 4 OUTBOARD END SEAL RETAINERFOR BETTER SUPPORT, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-57-030 Airframe SB - Superseded #3452	MODIFICATION - OUTERWING - ADDITION OF A DRAINAGE HOLE AT THE LOWEST POINT OF THE WING LOWER SURFACE AFT OF THE REAR SPAR TO PREVENT CORROSION, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-57-030 R1 Airframe SB - N/A #3513	MODIFICATION - OUTERWING - ADDITION OF A DRAINAGE HOLE AT THE LOWEST POINT OF THE WING LOWER SURFACE AFT OF THE REAR SPAR TO PREVENT CORROSION, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-57-031 Airframe SB - Superseded #3196	MODIFICATION - OUTERWING - INTRODUCTION OF SCREEN ASSEMBLY AT THE AUXILIARY SPAR VENT HOLE COVER TO PREVENT F.O.D., SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-57-031 R1 Airframe SB - N/A #3484	MODIFICATION - OUTERWING - INTRODUCTION OF SCREEN ASSEMBLY AT THE AUXILIARY SPAR VENT HOLE COVER TO PREVENT F.O.D. (A/C 9002 TO 9153), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-57-032 PART A Airframe SB - Superseded #4369	MODIFICATION - WINGLET AND REARSPAR BUSHING (APPLICABLE TO AIRCRAFT 9002 TO 9068), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-57-032 PART B Airframe SB - Superseded #3490	SPECIAL CHECK/MODIFICATION - BUSHINGS AND WASHERS (APPLICABLE TO AIRCRAFT 9002 TO 9113), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-57-032 R1 PART A Airframe SB - Superseded #3552	MODIFICATION - WINGLET AND REARSPAR BUSHING (APPLICABLE TO AIRCRAFT 9002, AND 9004 TO 9068), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-57-032 R1 PART B Airframe SB - Superseded #4171	SPECIAL CHECK/MODIFICATION - BUSHINGS AND WASHERS (APPLICABLE TO AIRCRAFT 9002 TO 9113), SERVICE BULLETIN.	H: 0.00					
	Notes SUPERSEDED						
SB 700-57-032 R2 PART A Airframe SB - Superseded #4071	SPECIAL CHECK/MODIFICATION - WINGTIP - REPLACEMENT OF WINGLET-TO-WING ATTACHMENT BUSHINGS AND HARDWARE (PART A EFFECTIVITY 9002 AND 9004 TO 9068), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-57-032 R2 PART B Airframe SB - Superseded #3616	SPECIAL CHECK/MODIFICATION - WINGTIP - REPLACEMENT OF WINGLET-TO-WING ATTACHMENT BUSHINGS AND HARDWARE (PART B EFFECTIVITY 9002 TO 9113), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-57-032 R2 PC RETRO Airframe SB - Superseded #4060	SPECIAL CHECK/MODIFICATION - WINGTIP - REPLACEMENT OF WINGLET-TO-WING ATTACHMENT BUSHINGS AND HARDWARE (PART C EFFECTIVITY 9002 TO 9134) - RETROACTIVE ACTION, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-57-032 R3 PART A Airframe SB - N/A #4291	SPECIAL CHECK/MODIFICATION - WINGTIP - REPLACEMENT OF WINGLET-TO-WING ATTACHMENT BUSHINGS AND HARDWARE (PART A EFFECTIVITY 9002 AND 9004 TO 9068), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-57-032 R3 PART B Airframe SB - N/A #3540	SPECIAL CHECK/MODIFICATION - WINGTIP - REPLACEMENT OF WINGLET-TO-WING ATTACHMENT BUSHINGS AND HARDWARE (PART B EFFECTIVITY 9002 TO 9113), SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-57-032 R3 PC RETRO Airframe SB - N/A #3629	SPECIAL CHECK/MODIFICATION - WINGTIP - REPLACEMENT OF WINGLET-TO-WING ATTACHMENT BUSHINGS AND HARDWARE (PART C EFFECTIVITY 9114 TO 9134) - RETROACTIVE ACTION, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-57-033 PART A Airframe SB - N/A #3563	SPECIAL CHECK/REWORK - GENERAL - CORROSION PREVENTION ON THE EDGE OF THE WING-TANK ACCESS PANELS AND THE FUEL ACCESS OPENINGS AT THE LOWERWING PLANK, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-57-033 PART B Airframe SB - N/A #4568	SPECIAL CHECK/REWORK - GENERAL - CORROSION PREVENTION ON THE EDGE OF THE WING-TANK ACCESS PANELS AND THE FUEL ACCESS OPENINGS AT THE LOWERWING PLANK, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-57-034 Airframe SB - N/A #4115	SPECIAL CHECK/REWORK - CENTERWING - UPPER SKIN/STRINGER FASTENER HOLES, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-57-035 Airframe SB - N/A #3597	SPECIAL CHECK/REWORK - OUTERWING - ADDITION OF DRAIN HOLES IN OUTBOARD LOWER WING PLANK, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-57-036 Airframe SB - N/A #3431	MODIFICATION - FLAP SYSTEM - INBOARD FLAP COTTERPINS REPLACEMENT, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-57-037 PART A Airframe SB - Superseded #4237	SPECIAL CHECK/REWORK WING AFT-LOWERSKIN) CHECK AND REWORK WING AFT-LOWER SKIN THICKNESS AT WS404.00, REWORK PRESSURE RELIEF VALVE BRACKET AT WS199.00 TO WS221.00 STRINGER NO. 8 AND REPLACEMENT OF HI-LITE BETWEEN WING LOWER SKIN AND FRONT SPAR, SERV	H: 0.00					
	Notes SUPERSEDED						
SB 700-57-037 PART B Airframe SB - Superseded #4244	SPECIAL CHECK/REWORK WING AFT-LOWERSKIN) CHECK AND REWORK WING AFT-LOWER SKIN THICKNESS AT WS404.00, REWORK PRESSURE RELIEF VALVE BRACKET AT WS199.00 TO WS221.00 STRINGER NO. 8 AND REPLACEMENT OF HI-LITE BETWEEN WING LOWER SKIN AND FRONT SPAR, SERV.	H: 0.00					
	Notes SUPERSEDED						
SB 700-57-037 PART C Airframe SB - Superseded #4495	SPECIAL CHECK/REWORK WING AFT-LOWERSKIN) CHECK AND REWORK WING AFT-LOWER SKIN THICKNESS AT WS404.00, REWORK PRESSURE RELIEF VALVE BRACKET AT WS199.00 TO WS221.00 STRINGER NO. 8 AND REPLACEMENT OF HI-LITE BETWEEN WING LOWER SKIN AND FRONT SPAR, SERV..	H: 0.00					
	Notes SUPERSEDED						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-57-037 R1 PART C Airframe SB - N/A #4354	SPECIAL CHECK/REWORK - WING AFT-LOWERSKIN - CHECK AND REWORK WING AFT-LOWER SKIN THICKNESS AT WS404.00, REWORK PRESSURE RELIEF VALVE BRACKET AT WS199.00 TO WS221.00 STRINGER NO. 8 AND REPLACEMENT OF HI-LITE (BETWEEN WING LOWER SKIN AND FRONT SPAR (A	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-57-037 R1 PART A Airframe SB - N/A #4273	SPECIAL CHECK/REWORK - WING AFT-LOWERSKIN - CHECK AND REWORK WING AFT-LOWER SKIN THICKNESS AT WS404.00, REWORK PRESSURE RELIEF VALVE BRACKET AT WS199.00 TO WS221.00 STRINGER NO. 8 AND REPLACEMENT OF HI-LITE BETWEEN WING LOWER SKIN AND FRONT SPAR (A/	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-57-037 R1 PART B Airframe SB - N/A #3175	SPECIAL CHECK/REWORK - WING AFT-LOWERSKIN - CHECK AND REWORK WING AFT-LOWER SKIN THICKNESS AT WS404.00, REWORK PRESSURE RELIEF VALVE BRACKET AT WS199.00 TO WS221.00 STRINGER NO. 8 AND REPLACEMENT OF HI-LITE BETWEEN WING LOWER SKIN AND FRONT SPAR (A/.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-57-039 PART B Airframe SB - N/A #4251	ADDITION OF DRAINAGE HOLES AT THE PYLON TRAILING EDGES (A/C 9002 TO 9099), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-57-039 PART A Airframe SB - N/A #4174	ADDITION OF DRAINAGE HOLES AT THE WING FIXED TRAILING EDGES (A/C 9002 TO 9223), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-57-040 Airframe SB - N/A #3326	SPECIAL CHECK/MODIFICATION - LEADING EDGES - CHECK FORCRACKED SHROUDS AND REPLACE OR MODIFY AS NECESSARY, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-57-041 Airframe SB - Superseded #4329	MODIFICATION - OUTERWING - ADDITION OF SEALANT BETWEEN THE VISOR PANEL AND THE UPPER WING SURFACE (EFFECTIVITY 9002 TO 9299), SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-57-041 R1 Airframe SB - Superseded #3065	MODIFICATION - OUTERWING - ADDITION OF SEALANT BETWEEN THE VISOR PANEL AND THE UPPER WING SURFACE, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-57-041 R2 Airframe SB - N/A #3587	ICA - MODIFICATION - OUTERWING - ADDITION OF SEALANT BETWEEN THE VISOR PANEL AND THE UPPER WING SURFACE, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-57-043 Airframe SB - N/A #3462	REWORK - OUTERWING - SEAL DRAIN HOLE AND AROUND SUPPORT FITTING, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-57-044 Airframe SB - Complied With #3785	MODIFICATION - GENERAL-APPLICATION OF ADDITIONAL SEALANT AND ADD WATERDRAINAGE IN THE COLLECTOR BOX, SERVICE BULLETIN	31-MAR-2020 H: 3741.10 L: 1233	M: 120			31-MAR-2030	M: 96 D: 15
SB 700-57-046 Airframe SB - N/A #3615	SPECIAL CHECK/REWORK - GENERAL - APPLICATION OF AERODYNAMIC SEALANT ON INBOARD AND OUTBOARD WINGLETS AND FORWARD WING TO BODY FAIRINGS/BELLY FAIRINGS, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-57-047 Airframe SB - Complied With #3473	SPECIAL CHECK/MODIFICATION - LEADING EDGES -REPLACEMENT OF THE ATTACHMENT ANGLES AND MODIFICATION OF SHROUD PANEL MOUNTING HOLES, SERVICE BULLETIN	04-MAR-2016 H: 1753.70 L: 622					
	Notes SCHEDULED						





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-57-048 Airframe SB - Open #4706	MODIFICATION - FLAPS - INSPECTION AND REPLACEMENT OF THE INNER FLAPS AUXILIARY-RIB BUSHING						
SB 700-57-048 R2 Airframe SB - Complied With #4861	MODIFICATION - FLAPS - INSPECTION AND REPLACEMENT OF THE INNER FLAPS AUXILIARY-RIB BUSHING (REV. 2)					09-APR-2021 H: 3992.00 L: 1324	
SB 700-57-050 Airframe SB - Open #4838	SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INNER FLAPS						
SB 700-57-050 R02 Airframe SB - Open #5037	SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INBOARD FLAPS						
SB 700-57-050 R1 Airframe SB - Open #4851	SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INNER FLAPS (REV. 1)						
SB 700-57-050 R3 Airframe SB - Complied With #5077	SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INBOARD FLAPS					31-MAR-2021 H: 3992.00 L: 1324	
	Notes C/W PARTS A & D. PARTS B, C & E N/A.						
SB 700-57-051 Airframe SB - Open #4830	SPECIAL CHECK/REWORK - FLAP - CHAFING PROTECTION AT FLAP CANOE FAIRING (W.S. 404.00)						
SB 700-57-051 R01 Airframe SB - Open #5033	SPECIAL CHECK/REWORK - FLAP - CHAFING PROTECTION AT FLAP CANOE FAIRING (W.S. 404.00)						
SB 700-57-052 Airframe SB - Complied With #4989	MODIFICATION - GENERAL - WING-TANK ACCESS PANEL AND WING-PLANK FRETTING CORROSION PREVENTION					19-FEB-2021 H: 3992.00 L: 1324	





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-57-053 Airframe SB - Complied With #5080	SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - MIDDLE FLAP	08-APR-2021 H: 3992.00 L: 1324					
	Notes C/W PARTS A,B,& D. PART C IS N/A DUE TO CORROSION.						
SB 700-57-053 R1 Airframe SB - Open #5151	SPECIAL CHECK/MODIFICATION-FLAPS-CORROSION PROTECTIONANDDRAINAGE IMPROVEMENT FOR THE FLAPS-MIDDLE FLAP						
SB 700-57-054 Airframe SB - Complied With #5081	SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - OUTER FLAPS	08-APR-2021 H: 3992.00 L: 1324					
SB 700-57-054 R1 Airframe SB - Open #5150	SPECIAL CHECK/MODIFICATION-FLAPS-CORROSION PROTECTIONANDDRAINAGE IMPROVEMENT FOR THE FLAPS-OUTER FLAPS						
SB 700-57-055 Airframe SB - Open #5154	MODIFICATION - OUTER WING -INSTALLATIONOFDRAINHOLECOVERSONMIDDLE AND OUTER FLAPS						
SB 700-57-5005 R3 Airframe SB - Open #5078	SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INBOARD FLAPS						
SB 700-71-001 Airframe SB - Complied With #164	MODIFICATION - FIXED COWLS - INTRODUCTION OF A DRAINAGE HOLE IN THE FRONT MOUNT ACCESS PANEL ON THE FIXED COWL, SERVICE BULLETIN	02-AUG-2013 H: 432.80 L: 211					
	Notes COMPLIED WITH						
SB 700-71-001 R1 Airframe SB - Open #3963	MODIFICATION - FIXED COWLS - INTRODUCTION OF A DRAINAGE HOLE IN THE FRONT MOUNT ACCESS PANEL ON THE FIXED COWL, SERVICE BULLETIN.	H: 0.00					
SB 700-71-001 R1 PART B Airframe SB - Open #3715	REIDENTIFY - MODIFICATION - FIXED COWLS - INTRODUCTION OF A DRAINAGE HOLE IN THE FRONT MOUNT ACCESS PANEL ON THE FIXED COWL,-THE FIXED COWL ACCESS PANEL ON THE RH NACELLE	H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-71-001 R1 PART A Airframe SB - Open #4421	REMOVE - MODIFICATION - FIXED COWLS - INTRODUCTION OF A DRAINAGE HOLE IN THE FRONT MOUNT ACCESS PANEL ON THE FIXED COWL,-THE ACCESS PANEL - DRILL A DRAIN HOLE IN THE ACCESS PANEL AND FIXED COWL ON THE AIRCRAFT - IDENTIFY THE ACCESS PANEL AND FIXED CO	H: 0.00					
SB 700-71-002 Airframe SB - Open #4716	SPECIAL CHECK/REWORK - REAR MOUNT - INSPECT THE RETAINING BOLT AND NUT ON THE LOWER/UPPER ENGINE REAR MOUNT ASSEMBLY						
SB 700-71-002 R1 Airframe SB - Complied With #4727	SPECIAL CHECK/REWORK - REAR MOUNT - INSPECT THE RETAINING BOLT AND NUT ON THE LOWER/UPPER ENGINE REAR MOUNT ASSEMBLY (REV. 1)	19-JUL-2016 H: 1924.80 L: 674					
SB 700-71-003 Airframe SB - Complied With #4787	MODIFICATION - REAR MOUNT - REPLACEMENT OF RETAINING BOLT AND NUT ON THE LOWER/UPPER ENGINE REAR MOUNT ASSEMBLY	16-JAN-2017 H: 2112.40 L: 746					
SB 700-71-005 Airframe SB - Complied With #5076	SPECIAL CHECK - FRONT AND REAR ENGINE MOUNT ASSEMBLIES - INSPECTION OF BUSHINGS ON THE ENGINE MOUNT SYSTEM	23-FEB-2021 H: 3992.00 L: 1324					
SB 700-71-005 R1 Airframe SB - Complied With #5132	SPECIAL CHECK - FRONT AND REAR ENGINE MOUNT ASSEMBLIES - INSPECTION OF BUSHINGS ON THE ENGINE MOUNT SYSTEM	20-DEC-2021 H: 4399.80 L: 1478					
SB 700-73-006 Airframe SB - Superseded #4497	MODIFICATION - DISTRIBUTION - ENGINE PROVISION INSTALLATION FORTHE FUEL RE-CIRCULATION SYSTEM, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-73-006 R1 Airframe SB - N/A #3171	MODIFICATION - DISTRIBUTION - ENGINE PROVISION INSTALLATION FORTHE FUEL RE-CIRCULATION SYSTEM, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						





Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700-73-008 Airframe SB - N/A #3293	MODIFICATION - FULL AUTHORITY DIGITAL ENGINE-CONTROL (FADEC) SYSTEM - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C.8.0, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-73-009 Airframe SB - Complied With #4767	MODIFICATION – FULL-AUTHORITY DIGITAL ENGINE-CONTROL (FADEC) SYSTEM – EEC SOFTWARE UPGRADE OF VERSION X2.0	23-NOV-2016 H: 2064.80 L: 722					
SB 700-76-002 Airframe SB - N/A #3097	MODIFICATION - POWERCONTROL - INSTALLATION OF PROTECTIVE GUARDS FOR ENGINE RUN SWITCHES (EFFECTIVITY: 9002 TO 9182), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-76-003 Airframe SB - N/A #3988	MODIFICATION - THROTTLE QUADRANT - INSTALLATION OF THROTTLE QUADRANT ASSEMBLY WITH IMPROVED ENGINE RUN SWITCHES (EFFECTIVITY 9002 TO 9126 AND 9128 TO 9222), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-78-002 Airframe SB - N/A #3961	SPECIAL CHECK/REWORK - THRUST REVERSERACTUATING SYSTEM - INSPECTION AND CLEANING OF THE SPHERICAL BEARING ON THE PRIMARY DOOR LOCK ACTUATOR (9002 TO 9126, 9128 TO 9179, 9181 AND 9182), SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB 700-79-005 Airframe SB - Superseded #3379	MODIFICATION - OIL REPLENISHMENT SYSTEM - POWERSOURCE CHANGE-TO BATTERY POWER ON AIRCRAFT POST BUILD 4, SERVICE BULLETIN	H: 0.00					
	Notes SUPERSEDED						
SB 700-79-005 R1 Airframe SB - N/A #4287	MODIFICATION - OIL REPLENISHMENT SYSTEM - POWERSOURCE CHANGE-TO BATTERY POWER ON AIRCRAFT POST BUILD 4, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700D23-024 R2 Airframe SB - Complied With #2711	MODIFICATION - CABIN COMMUNICATION SYSTEM - ICS-100 TELEPHONE SYSTEM PROVISIONS, SERVICE BULLETIN	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
SB 700D25-015 R1 Airframe SB - Open #4346	MODIFICATION - MISCELLANEOUS EQUIPMENT - INSTALLATION OF SPARE NOSE WHEEL STOWAGE PROVISIONS, SERVICE BULLETIN	H: 0.00					
SB 700D25-015 R2 Airframe SB - Open #3398	MODIFICATION - MISCELLANEOUS EQUIPMENT - INSTALLATION OF SPARE NOSE WHEEL STOWAGE PROVISIONS, SERVICE BULLETIN.	H: 0.00					
SB 700D25-018 R4 Airframe SB - Complied With #205	MODIFICATION - CARGO COMPARTMENT - MODIFICATION TO ALLOW INSTALLATION OF BAGGAGE COMPARTMENT, SERVICE BULLETIN	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
SB 700D25-019 R2 Airframe SB - Complied With #1079	MODIFICATION - PROVISIONS - AVIONICS COMPARTMENT - CES UNDERFLOORLRU RELOCATION, SERVICE BULLETIN	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
SB 700D25-021 Airframe SB - Complied With #1787	MODIFICATION - PROVISIONS - CARGO COMPARTMENT - INSTALLATION OF NET AND SHELF IN THE BAGGAGE COMPARTMENT, SERVICE BULLETIN	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
SB 700D34-040 R1 Airframe SB - Complied With #167	MODIFICATION - HEAD-UP DISPLAY (HUD) SYSTEM - INSTALL THE HUD TRAY AND PERFORM BORESIGHTING, SERVICE BULLETIN	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 700D38-009 R3 Airframe SB - Open #3626	MODIFICATION - PROVISIONS - GENERAL - ENVIROVAC WASTE SYSTEM KIT INSTALLATION, SERVICE BULLETIN	H: 0.00					
SB 700D38-011 R2 Airframe SB - Complied With #1390	REWORK - PROVISIONS - GENERAL - REWORK INTERIORFURNISHINGS AND STRUCTURAL PROVISIONS FOR THE WATER SYSTEM - KIT INSTALLATION, SERVICE BULLETIN	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
SB 70721598-49-8168 R1 APU SB - Open #3668	APU - AIRBORNE AUXILIARY POWER- GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTOR, PN 70721598-1, ON MULTIPLE APUS, SERVICE BULLETIN	H: 0.00					
SB 70721725-49-8152 R1 APU SB - Open #3854	APU - AIRBORNE AUXILIARY POWER- GAS TURBINE ENGINE - BALANCE REPAIR OF THE DUAL PILOT TURBINE ROTORS, PN 70721725-2 AND PN 70721725-5, ON MULTIPLE APUS, SERVICE BULLETIN	H: 0.00					
SB A700-72-003 R2 Airframe SB - Complied With #4800	ICA - REWORK - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL-PUMP SPLINED COUPLING (REV. 2)	31-MAR-2020 H: 3741.10 L: 1233					
SB AV637155A Engine 1 SB - Complied With #4804	UPGRADE OF DU-875 DISPLAYS	29-JAN-2018 H: 2586.20 C: 898					
SB AV637155A Engine 2 SB - Complied With #4826	UPGRADE OF DU-875 DISPLAYS	29-JAN-2018 H: 2586.20 C: 898					
SB BR-700-71-101976 Engine 1 SB - Open #4808	NO. 1 POWER PLANT - FRONT SUSPENSION-ENGINE/AIRCRAFT ATTACH PARTS AND LEFT AND RIGHT ENGINE FRONT SUSPENSION-AIRCRAFT MOUNTED - INTRODUCTION OF REVISED RETAINING BOLTS AND ASSOCIATED NUTS						
SB BR-700-71-101976 Engine 2 SB - Open #4830	NO. 2 POWER PLANT - FRONT SUSPENSION-ENGINE/AIRCRAFT ATTACH PARTS AND LEFT AND RIGHT ENGINE FRONT SUSPENSION-AIRCRAFT MOUNTED - INTRODUCTION OF REVISED RETAINING BOLTS AND ASSOCIATED NUTS						

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-24-100384 R1 Engine 1 SB - N/A #3883	NO. 1 ENGINE - ELECTRICAL POWER- ENGINE GENERATOR SURFACE AIR COOLED OIL COOLER (SACOC) TRANSFER TUBES AND FITTINGS - INTRODUCTION OF A MODIFIED SACOC TO VARIABLE FREQUENCY GENERATOR (VFG) OIL TUBE, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-24-100384 R1 Engine 2 SB - N/A #3995	NO. 2 ENGINE - ELECTRICAL POWER- ENGINE GENERATOR SURFACE AIR COOLED OIL COOLER (SACOC) TRANSFER TUBES AND FITTINGS - INTRODUCTION OF A MODIFIED SACOC TO VARIABLE FREQUENCY GENERATOR (VFG) OIL TUBE, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-24-102120 Engine 1 SB - Open #4831	ELECTRICAL POWER - ENGINE GENERATOR - INTRODUCTION OF TWO ALTERNATIVE SPAREABLE NUTS FOR THE V-CLAMP ASSEMBLY OF THE VARIABLE FREQUENCY GENERATOR (VFG)						
SB BR700-24-102120 Engine 2 SB - Open #4853	ELECTRICAL POWER - ENGINE GENERATOR - INTRODUCTION OF TWO ALTERNATIVE SPAREABLE NUTS FOR THE V-CLAMP ASSEMBLY OF THE VARIABLE FREQUENCY GENERATOR (VFG)						
SB BR700-29-101877 Engine 1 SB - Open #4722	NO. 1 ENGINE - HYDRAULIC POWER - RIGHT ENGINE HYDRAULIC TUBES AND FITTINGS ENGINE BUILD UNIT (EBU) - INTRODUCTION OF PART NUMBER CORRECTIONS						
SB BR700-29-101877 Engine 2 SB - Open #4723	NO. 2 ENGINE - HYDRAULIC POWER - RIGHT ENGINE HYDRAULIC TUBES AND FITTINGS ENGINE BUILD UNIT (EBU) - INTRODUCTION OF PART NUMBER CORRECTIONS						
SB BR700-29-900511 R1 Engine 1 SB - Open #4659	NO. 1 ENGINE - HYDRAULIC POWER - LEFT ENGINE HYDRAULIC TUBES AND FITTINGS (ENGINE BUILD UNIT (EBU)) - INSPECTION REPLACEMENT OF PIPE ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN (REV. 1)						
SB BR700-29-900511 R1 Engine 2 SB - Open #4660	NO. 2 ENGINE - HYDRAULIC POWER - LEFT ENGINE HYDRAULIC TUBES AND FITTINGS (ENGINE BUILD UNIT (EBU)) - INSPECTION REPLACEMENT OF PIPE ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN (REV. 1)						

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-29-900512 Engine 1 SB - Complied With #1755	NO. 1 ENGINE - HYDRAULIC POWER- LEFT AND RIGHT ENGINE HYDRAULIC TUBES AND FITTINGS (ENGINE BUILD UNIT (EBU)) - INSPECTION/REPLACEMENT OF QUICK DISCONNECT COUPLING, SERVICE BULLETIN	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
SB BR700-29-900512 Engine 2 SB - Complied With #82	NO. 2 ENGINE - HYDRAULIC POWER- LEFT AND RIGHT ENGINE HYDRAULIC TUBES AND FITTINGS (ENGINE BUILD UNIT (EBU)) - INSPECTION/REPLACEMENT OF QUICK DISCONNECT COUPLING, SERVICE BULLETIN	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
SB BR700-29-900512 R1 Engine 1 SB - Open #3708	NO. 1 ENGINE - HYDRAULIC POWER- LEFT AND RIGHT ENGINE HYDRAULIC TUBES AND FITTINGS (ENGINE BUILD UNIT (EBU)) - INSPECTION/REPLACEMENT OF QUICK DISCONNECT COUPLING - NON-MODIFICATION, SERVICE BULLETIN	H: 0.00					
SB BR700-29-900512 R1 Engine 2 SB - Open #4141	NO. 2 ENGINE - HYDRAULIC POWER- LEFT AND RIGHT ENGINE HYDRAULIC TUBES AND FITTINGS (ENGINE BUILD UNIT (EBU)) - INSPECTION/REPLACEMENT OF QUICK DISCONNECT COUPLING - NON-MODIFICATION, SERVICE BULLETIN	H: 0.00					
SB BR700-30-101826 Engine 1 SB - Open #4375	NO. 1 ENGINE - ICE AND RAIN PROTECTION - COWL THERMAL ANTI-ICING (TAI) DUCTS AND TUBES (ENGINE BUILD UNIT) - INTRODUCTION OF A NEW TAI VALVE WHICH CONTAINS A MORE CORROSION RESISTANT BEARING AND AN ADDITIONAL VENT HOLE (EFF. EBU S/N E005 TO E560), SE	H: 0.00					
SB BR700-30-101826 Engine 2 SB - Open #3140	NO. 2 ENGINE - ICE AND RAIN PROTECTION - COWL THERMAL ANTI-ICING (TAI) DUCTS AND TUBES (ENGINE BUILD UNIT) - INTRODUCTION OF A NEW TAI VALVE WHICH CONTAINS A MORE CORROSION RESISTANT BEARING AND AN ADDITIONAL VENT HOLE (EFF. EBU S/N E005 TO E560), SE	H: 0.00					
SB BR700-30-101826 R1 Engine 1 SB - Open #3790	NO. 1 ENGINE - ICE AND RAIN PROTECTION - COWL THERMAL ANTI-ICING (TAI) DUCTS AND TUBES (ENGINE BUILD UNIT (EBU)) - INTRODUCTION OF A NEW TAI VALVE WHICH CONTAINS A MORE CORROSION RESISTANT BEARING AND AN ADDITIONAL VENT HOLE, SERVICE BULLETIN	H: 0.00					
SB BR700-30-101826 R1 Engine 2 SB - Open #3721	NO. 2 ENGINE - ICE AND RAIN PROTECTION - COWL THERMAL ANTI-ICING (TAI) DUCTS AND TUBES (ENGINE BUILD UNIT (EBU)) - INTRODUCTION OF A NEW TAI VALVE WHICH CONTAINS A MORE CORROSION RESISTANT BEARING AND AN ADDITIONAL VENT HOLE, SERVICE BULLETIN	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-30-101826 R2 Engine 1 SB - Open #3193	NO. 1 ENGINE - ICE AND RAIN PROTECTION - COWL THERMAL ANTI-ICING (TAI) DUCTS AND TUBES (ENGINE BUILD UNIT (EBU)) - INTRODUCTION OF A NEW TAI VALVE WHICH CONTAINS A MORE CORROSION RESISTANT BEARING AND AN ADDITIONAL VENT HOLE, SERVICE BULLETIN.	H: 0.00					
SB BR700-30-101826 R2 Engine 2 SB - Open #3280	NO. 2 ENGINE - ICE AND RAIN PROTECTION - COWL THERMAL ANTI-ICING (TAI) DUCTS AND TUBES (ENGINE BUILD UNIT (EBU)) - INTRODUCTION OF A NEW TAI VALVE WHICH CONTAINS A MORE CORROSION RESISTANT BEARING AND AN ADDITIONAL VENT HOLE, SERVICE BULLETIN.	H: 0.00					
SB BR700-30-101889 Engine 1 SB - Open #4720	NO. 1 ENGINE - ICE AND RAIN PROTECTION - COWL THERMAL ANTI-ICING (TAI) DUCTS AND TUBES ENGINE BUILD UNIT (EBU) - INTRODUCTION OF PART NUMBER CORRECTIONS						
SB BR700-30-101889 Engine 2 SB - Open #4721	NO. 2 ENGINE - ICE AND RAIN PROTECTION - COWL THERMAL ANTI-ICING (TAI) DUCTS AND TUBES ENGINE BUILD UNIT (EBU) - INTRODUCTION OF PART NUMBER CORRECTIONS						
SB BR700-7-100783 R7 Engine 1 SB - Open #4811	NO. 1 ENGINE - EXHAUST - LEFT AND RIGHT ENGINE THRUST REVERSER - MATERIAL CHANGE OF THE PIVOTING DOOR SEAL DEPRESSOR AND CARRIER SEGMENTS (REV. 7)						
SB BR700-7-100783 R7 Engine 2 SB - Open #4833	NO. 2 ENGINE - EXHAUST - LEFT AND RIGHT ENGINE THRUST REVERSER - MATERIAL CHANGE OF THE PIVOTING DOOR SEAL DEPRESSOR AND CARRIER SEGMENTS (REV. 7)						
SB BR700-70-900040 R10 Engine 1 SB - Open #4253	NO. 1 ENGINE - ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES - NON-MODIFICATION, SERVICE BULLETIN	H: 0.00					
SB BR700-70-900040 R10 Engine 2 SB - Open #3115	NO. 2 ENGINE - ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES - NON-MODIFICATION, SERVICE BULLETIN	H: 0.00					
SB BR700-70-900040 R11 Engine 1 SB - Open #3947	NO. 1 ENGINE - ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES, SERVICE BULLETIN	H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-70-900040 R11 Engine 2 SB - Open #3843	NO. 2 ENGINE - ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES, SERVICE BULLETIN	H: 0.00					
SB BR700-70-900040 R12 Engine 1 SB - Open #3335	NO. 1 ENGINE - ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES -NON-MODIFICATION, SERVICE BULLETIN	H: 0.00					
SB BR700-70-900040 R12 Engine 2 SB - Open #4384	NO. 2 ENGINE - ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES -NON-MODIFICATION, SERVICE BULLETIN	H: 0.00					
SB BR700-70-900040 R13 Engine 1 SB - Open #3075	NO. 1 ENGINE - ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES -NON-MODIFICATION, SERVICE BULLETIN..	H: 0.00					
SB BR700-70-900040 R13 Engine 2 SB - Open #3987	NO. 2 ENGINE - ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES -NON-MODIFICATION, SERVICE BULLETIN..	H: 0.00					
SB BR700-70-900040 R14 Engine 1 SB - Open #3165	NO. 1 ENGINE - ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES -NON-MODIFICATION, SERVICE BULLETIN.	H: 0.00					
SB BR700-70-900040 R14 Engine 2 SB - Open #3128	NO. 2 ENGINE - ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES -NON-MODIFICATION, SERVICE BULLETIN.	H: 0.00					
SB BR700-70-900295 R2 Engine 1 SB - Open #4187	NO. 1 ENGINE - ENGINE LIFE MANAGEMENT - ON CONDITION OPERATION ENGINES - IN-SHOP REWORK - NON-MODIFICATION, SERVICE BULLETIN	H: 0.00					
SB BR700-70-900295 R2 Engine 2 SB - Open #3268	NO. 2 ENGINE - ENGINE LIFE MANAGEMENT - ON CONDITION OPERATION ENGINES - IN-SHOP REWORK - NON-MODIFICATION, SERVICE BULLETIN	H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-70-900295 R3 Engine 1 SB - Open #3116	NO. 1 ENGINE - ENGINE LIFE MANAGEMENT - ON CONDITION OPERATION ENGINES - IN-SHOP REWORK - NON-MODIFICATION, SERVICE BULLETIN.	H: 0.00					
SB BR700-70-900295 R3 Engine 2 SB - Open #4424	NO. 2 ENGINE - ENGINE LIFE MANAGEMENT - ON CONDITION OPERATION ENGINES - IN-SHOP REWORK - NON-MODIFICATION, SERVICE BULLETIN.	H: 0.00					
SB BR700-70-900295 R4 Engine 1 SB - Open #4126	NO. 1 ENGINE - ENGINE LIFE MANAGEMENT - ON CONDITION OPERATION ENGINES - IN-SHOP REWORK - NON-MODIFICATION, SERVICE BULLETIN..	H: 0.00					
SB BR700-70-900295 R4 Engine 2 SB - Open #3983	NO. 2 ENGINE - ENGINE LIFE MANAGEMENT - ON CONDITION OPERATION ENGINES - IN-SHOP REWORK - NON-MODIFICATION, SERVICE BULLETIN..	H: 0.00					
SB BR700-70-900295 R5 Engine 1 SB - Open #3583	NO. 1 ENGINE - ENGINE LIFE MANAGEMENT - ON CONDITION OPERATION ENGINES - IN-SHOP REWORK - NON-MODIFICATION, SERVICE BULLETIN...	H: 0.00					
SB BR700-70-900295 R5 Engine 2 SB - Open #4169	NO. 2 ENGINE - ENGINE LIFE MANAGEMENT - ON CONDITION OPERATION ENGINES - IN-SHOP REWORK - NON-MODIFICATION, SERVICE BULLETIN...	H: 0.00					
SB BR700-70-900295 R7 Engine 1 SB - Open #4829	ENGINE LIFE MANAGEMENT - ON CONDITION OPERATION ENGINES - IN-SHOP REWORK - NON-MODIFICATION SERVICE BULLETIN						
SB BR700-70-900295 R7 Engine 2 SB - Open #4851	ENGINE LIFE MANAGEMENT - ON CONDITION OPERATION ENGINES - IN-SHOP REWORK - NON-MODIFICATION SERVICE BULLETIN						
SB BR700-70-900387 R1 Engine 1 SB - Open #4269	NO. 1 ENGINE - WORKSCOPE FORSAMPLING PROGRAM, SERVICE BULLETIN	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-70-900387 R1 Engine 2 SB - Open #4507	NO. 2 ENGINE - WORKSCOPE FORSAMPLING PROGRAM, SERVICE BULLETIN	H: 0.00					
SB BR700-71-100602 Engine 1 SB - Open #4734	NO. 1 ENGINE - POWER PLANT - FRONT SUSPENSION-ENGINE MOUNTED - INTRODUCTION OF THRUST TRUNNION FLANGE BOLTS WITH A THINNER HEAD						
SB BR700-71-100602 Engine 2 SB - Open #4735	NO. 2 ENGINE - POWER PLANT - FRONT SUSPENSION-ENGINE MOUNTED - INTRODUCTION OF THRUST TRUNNION FLANGE BOLTS WITH A THINNER HEAD						
SB BR700-71-100830 Airframe SB - Open #4736	NO. 1 ENGINE - POWER PLANT - FRONT SUSPENSION-ENGINE MOUNTED - INTRODUCTION OF A WEIGHT DECREASED THRUST TRUNNION WITH REVISED DRY FILM LUBRICANT (DFL)						
SB BR700-71-100830 Engine 2 SB - Open #4737	NO. 2 ENGINE - POWER PLANT - FRONT SUSPENSION-ENGINE MOUNTED - INTRODUCTION OF A WEIGHT DECREASED THRUST TRUNNION WITH REVISED DRY FILM LUBRICANT (DFL)						
SB BR700-71-101279 Engine 1 SB - Open #4429	NO. 1 ENGINE - LEFT AND RIGHT UPPERCOWL - INTRODUCTION OF CHANGES TO THE VENT INLET DUCT ASSEMBLIES, SERVICE BULLETIN	H: 0.00					
SB BR700-71-101279 Engine 2 SB - Open #4561	NO. 2 ENGINE - LEFT AND RIGHT UPPERCOWL - INTRODUCTION OF CHANGES TO THE VENT INLET DUCT ASSEMBLIES, SERVICE BULLETIN	H: 0.00					
SB BR700-71-101357 Engine 1 SB - Open #4295	NO. 1 ENGINE - POWERPLANT - BREATHER OUTLET TUBES AND FITTINGS - INTRODUCTION OF CHANGES RELATED TO A NEW OIL TUBE ROUTING BETWEEN THE GEARBOX OIL PUMP AND THE FUEL COOLED OIL COOLER (FCOC), SERVICE BULLETIN	H: 0.00					
SB BR700-71-101357 Engine 2 SB - Open #4360	NO. 2 ENGINE - POWERPLANT - BREATHER OUTLET TUBES AND FITTINGS - INTRODUCTION OF CHANGES RELATED TO A NEW OIL TUBE ROUTING BETWEEN THE GEARBOX OIL PUMP AND THE FUEL COOLED OIL COOLER (FCOC), SERVICE BULLETIN	H: 0.00					

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-71-101569 R1 Engine 1 SB - Open #3617	NO. 1 ENGINE - POWERPLANT - LEFT UPPER COWL - INTRODUCTION OF A NEW MONOLITHIC UPPER COWL DOOR ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-71-101569 R1 Engine 2 SB - Open #3846	NO. 2 ENGINE - POWERPLANT - LEFT UPPER COWL - INTRODUCTION OF A NEW MONOLITHIC UPPER COWL DOOR ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-71-101570 R1 Engine 1 SB - Open #4274	NO. 1 ENGINE - POWERPLANT - RIGHT UPPER COWL - INTRODUCTION OF A NEW MONOLITHIC UPPER COWL DOOR ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-71-101570 R1 Engine 2 SB - Open #3149	NO. 2 ENGINE - POWERPLANT - RIGHT UPPER COWL - INTRODUCTION OF A NEW MONOLITHIC UPPER COWL DOOR ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-71-101571 R1 Engine 1 SB - Open #3202	NO. 1 ENGINE - POWERPLANT - LEFT LOWER COWL - INTRODUCTION OF A NEW MONOLITHIC LOWER COWL DOOR ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-71-101571 R1 Engine 2 SB - Open #4207	NO. 2 ENGINE - POWERPLANT - LEFT LOWER COWL - INTRODUCTION OF A NEW MONOLITHIC LOWER COWL DOOR ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-71-101572 R1 Engine 1 SB - Open #3606	NO. 1 ENGINE - POWERPLANT - RIGHT LOWER COWL - INTRODUCTION OF A NEW MONOLITHIC LOWER COWL DOOR ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-71-101572 R1 Engine 2 SB - Open #4359	NO. 2 ENGINE - POWERPLANT - RIGHT LOWER COWL - INTRODUCTION OF A NEW MONOLITHIC LOWER COWL DOOR ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-71-101581 Engine 1 SB - Open #4475	NO. 1 ENGINE - INTRODUCTION OF AN OIL DRAIN TUBE SUPPORT BRACKET WITH A SLOTTED HOLE, SERVICE BULLETIN	H: 0.00					

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-71-101581 Engine 2 SB - Open #4526	NO. 2 ENGINE - INTRODUCTION OF AN OIL DRAIN TUBE SUPPORT BRACKET WITH A SLOTTED HOLE, SERVICE BULLETIN	H: 0.00					
SB BR700-71-101675 Engine 1 SB - Open #4714	NO. 1 ENGINE - POWER PLANT - VARIOUS NACELLE AND ENGINE BUILD UNIT (EBU) SYSTEMS - INTRODUCTION OF AMENDMENTS AND CORRECTIONS TO THE BASELINE DEFINITION OF THE SPAREABLE PARTS FOR THE NACELLE AND EBU FOR SPARES ORDERING PURPOSES						
SB BR700-71-101675 Engine 2 SB - Open #4715	NO. 2 ENGINE - POWER PLANT - VARIOUS NACELLE AND ENGINE BUILD UNIT (EBU) SYSTEMS - INTRODUCTION OF AMENDMENTS AND CORRECTIONS TO THE BASELINE DEFINITION OF THE SPAREABLE PARTS FOR THE NACELLE AND EBU FOR SPARES ORDERING PURPOSES						
SB BR700-71-101830 Engine 1 SB - Open #4114	NO. 1 ENGINE - POWERPLANT - LEFT AND RIGHT FIXED COWL - INTRODUCTION OF A DRAINAGE HOLE WITHIN THE FRONT MOUNT ACCESS PANEL AND THE FIXED COWL ASSEMBLIES TO PREVENT CORROSION OF THE ENGINE FRONT MOUNT ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-71-101830 Engine 2 SB - Open #4347	NO. 2 ENGINE - POWERPLANT - LEFT AND RIGHT FIXED COWL - INTRODUCTION OF A DRAINAGE HOLE WITHIN THE FRONT MOUNT ACCESS PANEL AND THE FIXED COWL ASSEMBLIES TO PREVENT CORROSION OF THE ENGINE FRONT MOUNT ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-71-101830 R1 Engine 1 SB - Open #3057	NO. 1 ENGINE - POWERPLANT - LEFT AND RIGHT FIXED COWL - INTRODUCTION OF A DRAINAGE HOLE WITHIN THE FRONT MOUNT ACCESS PANEL AND THE FIXED COWL ASSEMBLIES TO PREVENT CORROSION OF THE ENGINE FRONT MOUNT ASSEMBLY, SERVICE BULLETIN.	H: 0.00					
SB BR700-71-101830 R1 Engine 2 SB - Open #3281	NO. 2 ENGINE - POWERPLANT - LEFT AND RIGHT FIXED COWL - INTRODUCTION OF A DRAINAGE HOLE WITHIN THE FRONT MOUNT ACCESS PANEL AND THE FIXED COWL ASSEMBLIES TO PREVENT CORROSION OF THE ENGINE FRONT MOUNT ASSEMBLY, SERVICE BULLETIN.	H: 0.00					
SB BR700-71-101883 Engine 1 SB - Open #3085	NO. 1 ENGINE - POWERPLANT - LEFT AND RIGHT FIXED COWL - INTRODUCTION OF NEW UPPER AND LOWER FIXED COWL HOOKS WITH A SLIGHTLY MODIFIED CONTOUR, SERVICE BULLETIN	H: 0.00					
SB BR700-71-101883 Engine 2 SB - Open #3408	NO. 2 ENGINE - POWERPLANT - LEFT AND RIGHT FIXED COWL - INTRODUCTION OF NEW UPPER AND LOWER FIXED COWL HOOKS WITH A SLIGHTLY MODIFIED CONTOUR, SERVICE BULLETIN	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-71-101974 Engine 1 SB - Open #4764	NO. 1 ENGINE - POWER PLANT - LEFT AND RIGHT FIXED COWL - INTRODUCTION OF A MODIFIED FIRE BOX CENTRE PIECE						
SB BR700-71-101974 Engine 2 SB - Open #4765	NO. 2 ENGINE - POWER PLANT - LEFT AND RIGHT FIXED COWL - INTRODUCTION OF A MODIFIED FIRE BOX CENTRE PIECE						
SB BR700-71-101975 R1 Engine 1 SB - Complied With #4781	NO. 1 ENGINE - POWER PLANT - REAR SUSPENSION-ENGINE MOUNTS REAR LINKS AND ATTACHING PARTS AND ENGINE/AIRCRAFT ATTACH PARTS - INTRODUCTION OF REVISED RETAINING BOLTS AND ASSOCIATED NUTS (REV. 1)			16-JAN-2017 H: 2112.40 C: 746			
SB BR700-71-101975 R1 Engine 2 SB - Open #4782	NO. 2 ENGINE - POWER PLANT - REAR SUSPENSION-ENGINE MOUNTS REAR LINKS AND ATTACHING PARTS AND ENGINE/AIRCRAFT ATTACH PARTS - INTRODUCTION OF REVISED RETAINING BOLTS AND ASSOCIATED NUTS (REV. 1)						
SB BR700-71-102013 Engine 1 SB - Open #4802	NO. 1 ENGINE - POWER PLANT - LEFT AND RIGHT ENGINE-ENGINE ELECTRONIC CONTROLLER (EEC) LANE A HARNESS 1C AND LANE B HARNESS 1F - INTRODUCTION OF AN ALTERNATIVE HARNESS TAPE						
SB BR700-71-102013 Engine 2 SB - Open #4824	NO. 2 ENGINE - POWER PLANT - LEFT AND RIGHT ENGINE-ENGINE ELECTRONIC CONTROLLER (EEC) LANE A HARNESS 1C AND LANE B HARNESS 1F - INTRODUCTION OF AN ALTERNATIVE HARNESS TAPE						
SB BR700-71-102026 Engine 1 SB - Open #4807	NO. 1 POWER PLANT - LEFT AND RIGHT QUICK ENGINE CHANGE UNIT (QECU) - INTRODUCTION OF A NEW PRESSURE REGULATING VALVE						
SB BR700-71-102026 Engine 2 SB - Open #4829	NO. 2 POWER PLANT - LEFT AND RIGHT QUICK ENGINE CHANGE UNIT (QECU) - INTRODUCTION OF A NEW PRESSURE REGULATING VALVE						
SB BR700-71-102085 Engine 1 SB - Open #4841	POWER PLANT - LEFT AND RIGHT FIXED COWL - INTRODUCTION OF NEW UPPER MIDDLE FIXED COWL HOOKS						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-71-102085 Engine 2 SB - Open #4863	POWER PLANT - LEFT AND RIGHT FIXED COWL - INTRODUCTION OF NEW UPPER MIDDLE FIXED COWL HOOKS						
SB BR700-71-102124 Engine 1 SB - Complied With #4842	POWER PLANT - LEFT AND RIGHT QUICK ENGINE CHANGE UNIT (QECU) - INTRODUCTION OF A NEW RIGID V-CLAMP FOR THE INSTALLATION OF THE HYDRAULIC PUMP UNIT	01-APR-2021					H: 3992.00 C: 1324
SB BR700-71-102124 Engine 2 SB - Complied With #4864	POWER PLANT - LEFT AND RIGHT QUICK ENGINE CHANGE UNIT (QECU) - INTRODUCTION OF A NEW RIGID V-CLAMP FOR THE INSTALLATION OF THE HYDRAULIC PUMP UNIT	01-APR-2021					H: 3992.00 C: 1324
SB BR700-71-900282 Engine 1 SB - Open #3123	NO. 1 ENGINE - INSPECTION OF FIRE WALL CABLE FORWEAR, SERVICE BULLETIN						H: 0.00
SB BR700-71-900282 Engine 2 SB - Open #3680	NO. 2 ENGINE - INSPECTION OF FIRE WALL CABLE FORWEAR, SERVICE BULLETIN						H: 0.00
SB BR700-71-900377 Engine 1 SB - Open #4365	NO. 1 ENGINE - ENGINE - ENGINE ELECTRONIC CONTROLLER(EEC) LANE A HARNESSSES 1A AND 1B - INSPECTION AND CORRECTION OF TIGHT CLEARANCE BETWEEN THE ELECTRICAL CONNECTOR BRR1066 OR P1066 AT THE STARTER AIR VALVE (SAV) AND THE ADJACENT EEC LANE A, SERVICE						H: 0.00
SB BR700-71-900377 Engine 2 SB - Open #3933	NO. 2 ENGINE - ENGINE - ENGINE ELECTRONIC CONTROLLER(EEC) LANE A HARNESSSES 1A AND 1B - INSPECTION AND CORRECTION OF TIGHT CLEARANCE BETWEEN THE ELECTRICAL CONNECTOR BRR1066 OR P1066 AT THE STARTER AIR VALVE (SAV) AND THE ADJACENT EEC LANE A, SERVICE						H: 0.00
SB BR700-71-900675 Engine 1 SB - Open #4836	POWER PLANT - GENERAL - ENGINE CONVERSION FROM A FLIGHT-TEST STANDARD ENGINE TO A PRODUCTION STANDARD ENGINE - NON-MODIFICATION SERVICE BULLETIN						
SB BR700-71-900675 Engine 2 SB - Open #4858	POWER PLANT - GENERAL - ENGINE CONVERSION FROM A FLIGHT-TEST STANDARD ENGINE TO A PRODUCTION STANDARD ENGINE - NON-MODIFICATION SERVICE BULLETIN						
SB BR700-72-100044 R3 Engine 1 SB - Open #4031	NO. 1 ENGINE - ENGINE - HP COMPRESSOR(HPC) - INTRODUCTION OF VARIABLE STATOR VANES SOLID TIE RODS, SERVICE BULLETIN						H: 0.00





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-100044 R3 Engine 2 SB - Open #3403	NO. 2 ENGINE - ENGINE - HP COMPRESSOR(HPC) - INTRODUCTION OF VARIABLE STATOR VANES SOLID TIE RODS, SERVICE BULLETIN	H: 0.00					
SB BR700-72-100207 R3 Engine 1 SB - N/A #4608	NO. 1 ENGINE - HP COMPRESSOR- INTRODUCTION OF A TUBED VORTEX REDUCER AND A MODIFIED STAGE 7 TO 10 ROTOR ASSEMBLY, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-100207 R3 Engine 2 SB - N/A #4484	NO. 2 ENGINE - HP COMPRESSOR- INTRODUCTION OF A TUBED VORTEX REDUCER AND A MODIFIED STAGE 7 TO 10 ROTOR ASSEMBLY, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-100262 R2 Engine 1 SB - Open #4657	NO. 1 ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF A SLEEVE IN THE PRESSURE RELIEF VALVE (PRV) HOUSING BORE OF THE ACCESSORY GEARBOX MAIN HOUSING ASSEMBLY (REV. 2)						
SB BR700-72-100262 R2 Engine 2 SB - Open #4658	NO. 2 ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF A SLEEVE IN THE PRESSURE RELIEF VALVE (PRV) HOUSING BORE OF THE ACCESSORY GEARBOX MAIN HOUSING ASSEMBLY (REV. 2)						
SB BR700-72-100263 R1 Engine 1 SB - Open #4626	NO. 1 ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF A SLEEVE IN THE PRESSURE RELIEF VALVE (PRV) HOUSING BORE OF THE ACCESSORY GEARBOX MAIN HOUSING ASSEMBLY (REV. 1)						
SB BR700-72-100263 R1 Engine 2 SB - Open #4625	NO. 2 ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF A SLEEVE IN THE PRESSURE RELIEF VALVE (PRV) HOUSING BORE OF THE ACCESSORY GEARBOX MAIN HOUSING ASSEMBLY (REV. 1)						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-100266 R1 Engine 1 SB - N/A #3344	NO. 1 ENGINE - TURBINE AND REARSUPPORT - INTRODUCTION OF REVISED LOW PRESSURE (LP) TURBINE EXHAUST CASE FUEL SHUT-OFF EXIT RADIUS, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-100266 R1 Engine 2 SB - N/A #3878	NO. 2 ENGINE - TURBINE AND REARSUPPORT - INTRODUCTION OF REVISED LOW PRESSURE (LP) TURBINE EXHAUST CASE FUEL SHUT-OFF EXIT RADIUS, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-100296 R1 Engine 1 SB - Open #4434	NO. 1 ENGINE - ENGINE - SUPPORT, BEARING FRONT - LOW PRESSURE (LP) COMPRESSOR/DRIVEN ASSEMBLY - INTERNAL GEARBOX DRIVE - INTRODUCTION OF REVISED NO.1 AND NO. 2 BEARING SUPPORT HOUSINGS AND ASSOCIATED COMPONENTS, SERVICE BULLETIN	H: 0.00					
SB BR700-72-100296 R1 Engine 2 SB - Open #3980	NO. 2 ENGINE - ENGINE - SUPPORT, BEARING FRONT - LOW PRESSURE (LP) COMPRESSOR/DRIVEN ASSEMBLY - INTERNAL GEARBOX DRIVE - INTRODUCTION OF REVISED NO.1 AND NO. 2 BEARING SUPPORT HOUSINGS AND ASSOCIATED COMPONENTS, SERVICE BULLETIN	H: 0.00					
SB BR700-72-100561 R1 Engine 1 SB - Open #4697	NO. 1 ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF TRANSPORTATION PARTS FOR THE INTERMEDIATE CASE MODULE (REV. 1)						
SB BR700-72-100561 R1 Engine 2 SB - Open #4698	NO. 2 ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF TRANSPORTATION PARTS FOR THE INTERMEDIATE CASE MODULE (REV. 1)						
SB BR700-72-100563 R1 Engine 1 SB - Open #3455	NO. 1 ENGINE - LP/HP TURBINE SUPPORT AND OUTERBEARINGS - INTRODUCTION OF STAGE 4 AIR TUBES AND REAR BEARING SUPPORT STRUCTURE (RBSS) WITH INCREASED CONTACT AREA, SERVICE BULLETIN	H: 0.00					
SB BR700-72-100563 R1 Engine 2 SB - Open #4118	NO. 2 ENGINE - LP/HP TURBINE SUPPORT AND OUTERBEARINGS - INTRODUCTION OF STAGE 4 AIR TUBES AND REAR BEARING SUPPORT STRUCTURE (RBSS) WITH INCREASED CONTACT AREA, SERVICE BULLETIN	H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-100740 R2 Engine 1 SB - Open #4701	NO. 1 ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF PART NUMBERS OF SPAREABLE ITEMS OF THE APT GEARBOX THAT MAY BE REPLACED ON AIRCRAFT (REV. 2)						
SB BR700-72-100740 R2 Engine 2 SB - Open #4702	NO. 2 ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF PART NUMBERS OF SPAREABLE ITEMS OF THE APT GEARBOX THAT MAY BE REPLACED ON AIRCRAFT (REV. 2)						
SB BR700-72-100741 R2 Engine 1 SB - Open #4695	NO. 1 ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF PART NUMBERS OF SPAREABLE ITEMS OF THE APT GEARBOX THAT MAY BE REPLACED ON AIRCRAFT (REV. 2)						
SB BR700-72-100741 R2 Engine 2 SB - Open #4696	NO. 2 ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF PART NUMBERS OF SPAREABLE ITEMS OF THE APT GEARBOX THAT MAY BE REPLACED ON AIRCRAFT (REV. 2)						
SB BR700-72-100746 R1 Engine 1 SB - Open #4693	NO. 1 ENGINE - ACCESSORY GEARBOX - RE-ITEMIZATION OF THE ACCESSORY GEARBOX (REV. 1)						
SB BR700-72-100746 R1 Engine 2 SB - Open #4694	NO. 2 ENGINE - ACCESSORY GEARBOX - RE-ITEMIZATION OF THE ACCESSORY GEARBOX (REV. 1)						
SB BR700-72-100767 R1 Engine 1 SB - Open #4699	NO. 1 ENGINE - ACCESSORY GEARBOX - RE-ITEMIZATION OF THE ACCESSORY GEARBOX (REV. 1)						
SB BR700-72-100767 R1 Engine 2 SB - Open #4700	NO. 2 ENGINE - ACCESSORY GEARBOX - RE-ITEMIZATION OF THE ACCESSORY GEARBOX (REV. 1)						
SB BR700-72-100879 R1 Engine 1 SB - Open #3244	NO. 1 ENGINE - LP/HP TURBINE STATORRETAINERS/SEALS - INTRODUCTION OF ABRADABLE LININGS WITH INCREASED CORROSION RESISTANCE, SERVICE BULLETIN			H: 0.00			





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-100879 R1 Engine 2 SB - Open #3216	NO. 2 ENGINE - LP/HP TURBINE STATORRETAINERS/SEALS - INTRODUCTION OF ABRADABLE LININGS WITH INCREASED CORROSION RESISTANCE, SERVICE BULLETIN	H: 0.00					
SB BR700-72-100900 R1 Engine 1 SB - N/A #179	NO. 1 ENGINE - HP COMPRESSORAND COMBUSTION FAIRINGS-INTRODUCTION OF NEW FAIRINGS WITH NEW ATTACHMENT FEATURES, SERVICE BULLETIN	25-FEB-2010 H: 0.00					
	Notes NOT APPLICABLE - TERMINATED CANCELS 1998-467 ISSUE 03.INSPECTION REQUIREMENT TERMINATED BY MOD 72-100900.NO FURTHERACTION REQUIRED						
SB BR700-72-100900 R1 Engine 2 SB - N/A #1238	NO. 2 ENGINE - HP COMPRESSORAND COMBUSTION FAIRINGS-INTRODUCTION OF NEW FAIRINGS WITH NEW ATTACHMENT FEATURES, SERVICE BULLETIN	25-FEB-2010 H: 0.00					
	Notes NOT APPLICABLE - TERMINATED TERMINATED BY MOD 72-100900.						
SB BR700-72-100914 R1 Engine 1 SB - Open #3047	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE BLADES - INTRODUCTION OF A NEW PROCEDURE FORMANUFACTURE OF THE HP TURBINE STAGE 2 BLADES, SERVICE BULLETIN	H: 0.00					
SB BR700-72-100914 R1 Engine 2 SB - Open #4040	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE BLADES - INTRODUCTION OF A NEW PROCEDURE FORMANUFACTURE OF THE HP TURBINE STAGE 2 BLADES, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101139 R1 Engine 1 SB - Complied With #3020	NO. 1 ENGINE - HPC ROTORSHAFT-INTRODUCTION OF A NEW FITTING INSTRUCTION FOR THE HP COMPRESSOR STUB SHAFT TO ALIGN WITH THE HP COMPRESSOR ROTOR, SERVICE BULLETIN	15-JAN-2010 H: 0.00					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB BR700-72-101139 R1 Engine 2 SB - Complied With #636	NO. 2 ENGINE - HPC ROTORSHAFT-INTRODUCTION OF A NEW FITTING INSTRUCTION FOR THE HP COMPRESSOR STUB SHAFT TO ALIGN WITH THE HP COMPRESSOR ROTOR, SERVICE BULLETIN	15-JAN-2010 H: 0.00					
	Notes COMPLIED WITH - AT MANUFACTURE						





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-10117 R1 Engine 1 SB - Open #4815	NO. 1 ENGINE - HIGH PRESSURE (HP) TURBINE BLADES - INTRODUCTION OF HP TURBINE STAGE 1 BLADES WITH A NEW FILM COOLING HOLE CONFIGURATION (REV. 1)						
SB BR700-72-10117 R1 Engine 2 SB - Open #4837	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE BLADES - INTRODUCTION OF HP TURBINE STAGE 1 BLADES WITH A NEW FILM COOLING HOLE CONFIGURATION (REV. 1)						
SB BR700-72-101195 R1 Engine 1 SB - Open #3113	NO. 1 ENGINE - INTRODUCTION OF AN INTERMEDIATE CASE MANUFACTURED FROM A NEW CASTING, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101195 R1 Engine 2 SB - Open #3751	NO. 2 ENGINE - INTRODUCTION OF AN INTERMEDIATE CASE MANUFACTURED FROM A NEW CASTING, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101197 R1 Engine 1 SB - N/A #3709	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - DELETION OF THE FIRE SHIELD ASSEMBLY, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-101197 R1 Engine 2 SB - N/A #3755	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - DELETION OF THE FIRE SHIELD ASSEMBLY, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-101222 Engine 1 SB - Open #4161	NO. 1 ENGINE - ENGINE - COMPRESSORINTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF NEW BUILD INSTRUCTIONS TO DECREASE HIGH PRESSURE (HP) VIBRATION LEVELS, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101222 Engine 2 SB - Open #3588	NO. 2 ENGINE - ENGINE - COMPRESSORINTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF NEW BUILD INSTRUCTIONS TO DECREASE HIGH PRESSURE (HP) VIBRATION LEVELS, SERVICE BULLETIN	H: 0.00					





Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-101234 R2 Engine 1 SB - Open #4498	NO. 1 ENGINE - LOW PRESSURE/HIGH PRESSURE (LP/HP) TURBINE SUPPORT AND OUTERBEARINGS - INTRODUCTION OF REWORKED REAR BEARING SUPPORT STRUCTURES (RBSS) OF EARLIER STANDARDS, REWORKED HP AND LP TURBINE BEARING RETAINERS AND NEW STAGE 4 AIR TUBES, SERVI	H: 0.00					
SB BR700-72-101234 R2 Engine 2 SB - Open #4353	NO. 2 ENGINE - LOW PRESSURE/HIGH PRESSURE (LP/HP) TURBINE SUPPORT AND OUTERBEARINGS - INTRODUCTION OF REWORKED REAR BEARING SUPPORT STRUCTURES (RBSS) OF EARLIER STANDARDS, REWORKED HP AND LP TURBINE BEARING RETAINERS AND NEW STAGE 4 AIR TUBES, SERVI	H: 0.00					
SB BR700-72-101246 R1 Engine 1 SB - Open #4774	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSOR DISC - INTRODUCTION OF A NEW FAN DISC DESIGN FOR LIFE ENHANCEMENT(REV. 1)						
SB BR700-72-101246 R1 Engine 2 SB - Open #4775	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR DISC - INTRODUCTION OF A NEW FAN DISC DESIGN FOR LIFE ENHANCEMENT(REV. 1)						
SB BR700-72-101258 R1 Engine 1 SB - Open #4479	NO. 1 ENGINE - ENGINE - LP COMPRESSORCASE - INTRODUCTION OF A LP COMPRESSOR CASE WHICH IS MADE FROM A FORGING, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101258 R1 Engine 2 SB - Open #4452	NO. 2 ENGINE - ENGINE - LP COMPRESSORCASE - INTRODUCTION OF A LP COMPRESSOR CASE WHICH IS MADE FROM A FORGING, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101260 R1 Engine 1 SB - N/A #4417	NO. 1 ENGINE - HIGH PRESSURE (HP) TURBINE ROTORSHAFT AND (NO. 4) BEARING - INTRODUCTION OF AN HP TURBINE STUB SHAFT WHICH IS DECREASED IN WEIGHT, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-101260 R1 Engine 2 SB - N/A #3416	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE ROTORSHAFT AND (NO. 4) BEARING - INTRODUCTION OF AN HP TURBINE STUB SHAFT WHICH IS DECREASED IN WEIGHT, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						



ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-101326 Engine 1 SB - Open #4255	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW SELF LOCKING NUT FORTHE ACCESSORY GEARBOX LINE NUMBER 9 BREATHER SHAFT, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101326 Engine 2 SB - Open #3801	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW SELF LOCKING NUT FORTHE ACCESSORY GEARBOX LINE NUMBER 9 BREATHER SHAFT, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101326 R1 Engine 1 SB - Open #4598	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW SELF LOCKING NUT FORTHE ACCESSORY GEARBOX LINE NUMBER 9 BREATHER SHAFT, SERVICE BULLETIN.	H: 0.00					
SB BR700-72-101326 R1 Engine 2 SB - Open #3831	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW SELF LOCKING NUT FORTHE ACCESSORY GEARBOX LINE NUMBER 9 BREATHER SHAFT, SERVICE BULLETIN.	H: 0.00					
SB BR700-72-101419 R1 Engine 1 SB - Complied With #387	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) VARIABLE INLET GUIDE VANE (VIGV) ACTUATING MECHANISM - INTRODUCTION OF A NEW BUILD INSTRUCTION TO INCREASE END FLOAT AND CENTRALISERGAP, SERVICE BULLETIN	15-JAN-2010 H: 0.00					
Notes COMPLIED WITH - AT MANUFACTURE							
SB BR700-72-101419 R1 Engine 2 SB - Complied With #1731	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) VARIABLE INLET GUIDE VANE (VIGV) ACTUATING MECHANISM - INTRODUCTION OF A NEW BUILD INSTRUCTION TO INCREASE END FLOAT AND CENTRALISERGAP, SERVICE BULLETIN	15-JAN-2010 H: 0.00					
Notes COMPLIED WITH - AT MANUFACTURE							
SB BR700-72-101419 R2 Engine 1 SB - Open #4106	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) VARIABLE INLET GUIDE VANE (VIGV) ACTUATING MECHANISM - INTRODUCTION OF A NEW BUILD INSTRUCTION TO INCREASE END FLOAT AND CENTRALISERGAP, SERVICE BULLETIN.	H: 0.00					
SB BR700-72-101419 R2 Engine 2 SB - Open #4566	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) VARIABLE INLET GUIDE VANE (VIGV) ACTUATING MECHANISM - INTRODUCTION OF A NEW BUILD INSTRUCTION TO INCREASE END FLOAT AND CENTRALISERGAP, SERVICE BULLETIN.	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-101436 R2 Engine 1 SB - N/A #3950	NO. 1 ENGINE - RE-SOURCING LOW PRESSURE (LP) EXIT GUIDE STATORVANES - FAN OUTLET GUIDE VANE (OGV), SERVICE BULLETIN Notes NOT APPLICABLE	H: 0.00					
SB BR700-72-101436 R2 Engine 2 SB - N/A #3665	NO. 2 ENGINE - RE-SOURCING LOW PRESSURE (LP) EXIT GUIDE STATORVANES - FAN OUTLET GUIDE VANE (OGV), SERVICE BULLETIN Notes NOT APPLICABLE	H: 0.00					
SB BR700-72-101440 Engine 1 SB - Open #4527	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE AND GEARBOX RADIAL DRIVE - INTRODUCTION OF REVISED INSTALLATION PROCEDURE, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101440 Engine 2 SB - Open #4006	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE AND GEARBOX RADIAL DRIVE - INTRODUCTION OF REVISED INSTALLATION PROCEDURE, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101453 R1 Engine 1 SB - Open #3542	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORSTATOR VANES - INTRODUCTION OF A FULLY MACHINED ENGINE SECTION STATOR (ESS) BLADE INTEGRATED RING (BLING), SERVICE BULLETIN	H: 0.00					
SB BR700-72-101453 R1 Engine 2 SB - Open #3363	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORSTATOR VANES - INTRODUCTION OF A FULLY MACHINED ENGINE SECTION STATOR (ESS) BLADE INTEGRATED RING (BLING), SERVICE BULLETIN	H: 0.00					
SB BR700-72-101469 R1 Engine 1 SB - N/A #4170	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSORVORTEX REDUCER - INTRODUCTION OF A NEW FORGING MATERIAL FOR THE HP COMPRESSOR VORTEX REDUCER RING, SERVICE BULLETIN Notes NOT APPLICABLE	H: 0.00					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-101469 R1 Engine 2 SB - N/A #4064	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSORVORTEX REDUCER - INTRODUCTION OF A NEW FORGING MATERIAL FOR THE HP COMPRESSOR VORTEX REDUCER RING, SERVICE BULLETIN Notes NOT APPLICABLE	H: 0.00					
SB BR700-72-101471 Engine 1 SB - Superseded #3679	NO. 1 ENGINE - INTRODUCTION OF METCO 58 COATED LP COMPRESSORBLADES WITH A TRANSITION STRIP, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101471 Engine 2 SB - Superseded #4596	NO. 2 ENGINE - INTRODUCTION OF METCO 58 COATED LP COMPRESSORBLADES WITH A TRANSITION STRIP, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101471 R1 Engine 1 SB - Complied With #1026	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - INTRODUCTION OF METCO 58 COATED LP COMPRESSOR BLADES WITH A TRANSITION STRIP, SERVICE BULLETIN Notes COMPLIED WITH - AT MANUFACTURE	15-JAN-2010 H: 0.00					
SB BR700-72-101471 R1 Engine 2 SB - Complied With #25	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - INTRODUCTION OF METCO 58 COATED LP COMPRESSOR BLADES WITH A TRANSITION STRIP, SERVICE BULLETIN Notes COMPLIED WITH - AT MANUFACTURE	15-JAN-2010 H: 0.00					
SB BR700-72-101471 R2 Engine 1 SB - Open #3276	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - INTRODUCTION OF METCO 58 COATED LP COMPRESSOR BLADES WITH A TRANSITION STRIP, SERVICE BULLETIN.	H: 0.00					
SB BR700-72-101471 R2 Engine 2 SB - Open #3482	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - INTRODUCTION OF METCO 58 COATED LP COMPRESSOR BLADES WITH A TRANSITION STRIP, SERVICE BULLETIN.	H: 0.00					
SB BR700-72-101473 Engine 1 SB - Superseded #3559	NO. 1 ENGINE - INTRODUCTION OF DRY FILM LUBRICANT (DFL) COATED LP COMPRESSORBLADES WITH A TRANSITION STRIP, SERVICE BULLETIN	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-101473 Engine 2 SB - Superseded #4306	NO. 2 ENGINE - INTRODUCTION OF DRY FILM LUBRICANT (DFL) COATED LP COMPRESSORBLADES WITH A TRANSITION STRIP, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101473 R1 Engine 1 SB - Superseded #4245	NO. 1 ENGINE - INTRODUCTION OF DRY FILM LUBRICANT (DFL) COATED LP COMPRESSORBLADES WITH A TRANSITION STRIP, SERVICE BULLETIN.	H: 0.00					
SB BR700-72-101473 R1 Engine 2 SB - Superseded #4531	NO. 2 ENGINE - INTRODUCTION OF DRY FILM LUBRICANT (DFL) COATED LP COMPRESSORBLADES WITH A TRANSITION STRIP, SERVICE BULLETIN.	H: 0.00					
SB BR700-72-101473 R2 Engine 1 SB - Open #3464	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - INTRODUCTION OF DRY FLIM LUBIRCANT (DFL) COATED LP COMPRESSOR BLADES WITH A TRANSITION STRIP, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101473 R2 Engine 2 SB - Open #4078	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - INTRODUCTION OF DRY FLIM LUBIRCANT (DFL) COATED LP COMPRESSOR BLADES WITH A TRANSITION STRIP, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101474 Engine 1 SB - Open #3651	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORROTOR DISC - INTRODUCTION OF A LASER SHOCK PEENED (LSP) LP COMPRESSOR ROTOR DISC WITH A NEW-PART NUMBER, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101474 Engine 2 SB - Open #3166	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORROTOR DISC - INTRODUCTION OF A LASER SHOCK PEENED (LSP) LP COMPRESSOR ROTOR DISC WITH A NEW-PART NUMBER, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101474 R1 Engine 1 SB - N/A #3378	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSORROTOR DISC - INTRODUCTION OF A LASER SHOCK PEENED (LSP) LP COMPRESSOR ROTOR DISC WITH A NEW PART NUMBER, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-101474 R1 P1 Engine 1 SB - N/A #3901	NO. 1 ENGINE - REIDENTIFICATION-LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF A LASER SHOCK PEENED (LSP) LP COMPRESSOR ROTOR DISC WITH A NEW PART NUMBER, OF A NON-FLOWN LP COMPRESSOR ROTOR DISC	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-101474 R1 P2 Engine 1 SB - N/A #3094	NO. 1 ENGINE - REMOVAL-LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF A LASER SHOCK PEENED (LSP) LP COMPRESSOR ROTOR DISC WITH A NEW PART NUMBER, AND INSTALLATION OF THE LP COMPRESSOR ROTOR DISC	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-101474 R1 Engine 2 SB - N/A #3748	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF A LASER SHOCK PEENED (LSP) LP COMPRESSOR ROTOR DISC WITH A NEW PART NUMBER, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-101474 R1 P1 Engine 2 SB - N/A #3742	NO. 2 ENGINE - REIDENTIFICATION-LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF A LASER SHOCK PEENED (LSP) LP COMPRESSOR ROTOR DISC WITH A NEW PART NUMBER, OF A NON-FLOWN LP COMPRESSOR ROTOR DISC	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-101474 R1 P2 Engine 2 SB - N/A #3547	NO. 2 ENGINE - REMOVAL-LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF A LASER SHOCK PEENED (LSP) LP COMPRESSOR ROTOR DISC WITH A NEW PART NUMBER, AND INSTALLATION OF THE LP COMPRESSOR ROTOR DISC	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-101476 R1 Engine 1 SB - N/A #4168	NO. 1 ENGINE - COMBUSTION LINER- INTRODUCTION OF A NEW COMBUSTION CHAMBER WITHOUT COOLING RIBS, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-101476 R1 Engine 2 SB - N/A #4204	NO. 2 ENGINE - COMBUSTION LINER- INTRODUCTION OF A NEW COMBUSTION CHAMBER WITHOUT COOLING RIBS, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-101476 R2 Engine 1 SB - N/A #4612	NO. 1 ENGINE - COMBUSTION LINER- INTRODUCTION OF A NEW COMBUSTION CHAMBER WITHOUT COOLING RIBS, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-101476 R2 Engine 2 SB - N/A #4091	NO. 2 ENGINE - COMBUSTION LINER- INTRODUCTION OF A NEW COMBUSTION CHAMBER WITHOUT COOLING RIBS, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-101498 Engine 1 SB - Open #4409	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF METAL TRANSPORTATION BLANKS WITH PLASTIC TRANSPORTATION BLANKS AND INTRODUCTION OF ALTERNATIVE ORIGINAL SUPPLIERPART NUMBERS FOR CERTAIN ACCESSORY GEARBOX COMPONENTS, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101498 Engine 2 SB - Open #4420	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF METAL TRANSPORTATION BLANKS WITH PLASTIC TRANSPORTATION BLANKS AND INTRODUCTION OF ALTERNATIVE ORIGINAL SUPPLIERPART NUMBERS FOR CERTAIN ACCESSORY GEARBOX COMPONENTS, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101500 Engine 1 SB - Open #4489	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW ACCESSORY GEARBOX MAIN HOUSING ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101500 Engine 2 SB - Open #4107	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW ACCESSORY GEARBOX MAIN HOUSING ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101523 R1 Engine 1 SB - Open #3442	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE SHUT-OFF PAWL CARRIER- INTRODUCTION OF FUEL SHUT-OFF PAWL CARRIER PIVOT PINS MADE FROM A DIFFERENT MATERIAL WITH IMPROVED CORROSION PROTECTION PROPERTIES, SERVICE BULLETIN	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-101523 R1 Engine 2 SB - Open #3374	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE SHUT-OFF PAWL CARRIER- INTRODUCTION OF FUEL SHUT-OFF PAWL CARRIER PIVOT PINS MADE FROM A DIFFERENT MATERIAL WITH IMPROVED CORROSION PROTECTION PROPERTIES, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101523 R2 Engine 1 SB - Open #3921	NO. 1 ENGINE - LOW PRESSURE (LP) TURBINE SHUT-OFF PAWL CARRIER- INTRODUCTION OF FUEL SHUT-OFF PAWL CARRIER PIVOT PINS MADE FROM A DIFFERENT MATERIAL WITH IMPROVED CORROSION PROTECTION PROPERTIES, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101523 R2 Engine 2 SB - Open #4278	NO. 2 ENGINE - LOW PRESSURE (LP) TURBINE SHUT-OFF PAWL CARRIER- INTRODUCTION OF FUEL SHUT-OFF PAWL CARRIER PIVOT PINS MADE FROM A DIFFERENT MATERIAL WITH IMPROVED CORROSION PROTECTION PROPERTIES, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101526 Engine 1 SB - Open #4591	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE MODULE ATTACH PARTS AND FITTINGS - INTRODUCTION OF A NEW LP TURBINE AXIAL SETTING PROCEDURE WITH AN INCREASED RANGE OF ADJUSTING RINGS, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101526 Engine 2 SB - Open #3118	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE MODULE ATTACH PARTS AND FITTINGS - INTRODUCTION OF A NEW LP TURBINE AXIAL SETTING PROCEDURE WITH AN INCREASED RANGE OF ADJUSTING RINGS, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101527 Engine 1 SB - Open #3586	NO. 1 ENGINE - INTERMEDIATE CASE MODULE ATTACH PARTS AND FITTINGS - INTRODUCTION OF A NEW AIRTURBINE STARTER BRACKET ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101527 Engine 2 SB - Open #4111	NO. 2 ENGINE - INTERMEDIATE CASE MODULE ATTACH PARTS AND FITTINGS - INTRODUCTION OF A NEW AIRTURBINE STARTER BRACKET ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101538 Engine 1 SB - Open #3938	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSORREAR INNER CASE - INTRODUCTION OF A DIFFERENT STANDARD OF HP COMPRESSOR REAR INNER CASES STAGES 5 TO 10, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101538 Engine 2 SB - Open #3218	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSORREAR INNER CASE - INTRODUCTION OF A DIFFERENT STANDARD OF HP COMPRESSOR REAR INNER CASES STAGES 5 TO 10, SERVICE BULLETIN	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-101540 Engine 1 SB - Open #4357	NO. 1 ENGINE - INTRODUCTION OF AN OUTLET GUIDE VANE (OGV) HOUSING ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101540 Engine 2 SB - Open #3150	NO. 2 ENGINE - INTRODUCTION OF AN OUTLET GUIDE VANE (OGV) HOUSING ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101540 R2 Engine 1 SB - Open #4123	NO. 1 ENGINE - ENGINE - EXHAUST CASE - INTRODUCTION OF AN OUTLET GUIDE VANE (OGV) HOUSING ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101540 R2 Engine 2 SB - Open #3666	NO. 2 ENGINE - ENGINE - EXHAUST CASE - INTRODUCTION OF AN OUTLET GUIDE VANE (OGV) HOUSING ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101540 R3 Engine 1 SB - Open #4212	NO. 1 ENGINE - EXHAUST CASE - INTRODUCTION OF AN OUTLET GUIDE VANE (OGV) HOUSING ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101540 R3 Engine 2 SB - Open #3179	NO. 2 ENGINE - EXHAUST CASE - INTRODUCTION OF AN OUTLET GUIDE VANE (OGV) HOUSING ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101540 R4 Engine 1 SB - N/A #4529	NO. 1 ENGINE - EXHAUST CASE - INTRODUCTION OF AN OUTLET GUIDE VANE (OGV) HOUSING ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-101540 R4 Engine 2 SB - N/A #4541	NO. 2 ENGINE - EXHAUST CASE - INTRODUCTION OF AN OUTLET GUIDE VANE (OGV) HOUSING ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-101549 Engine 1 SB - Open #3905	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - REWORK OF IN-SERVICE LP COMPRESSOR BLADES TO APPLY METCO 58 COATING ON THE BLADE ROOT FLANK, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101549 Engine 2 SB - Open #3928	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - REWORK OF IN-SERVICE LP COMPRESSOR BLADES TO APPLY METCO 58 COATING ON THE BLADE ROOT FLANK, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101573 Engine 1 SB - Open #3804	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR- INCREASED TIP CLEARANCE FOR HP COMPRESSOR STAGE 4 STATOR VANES, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101573 Engine 2 SB - Open #3207	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR- INCREASED TIP CLEARANCE FOR HP COMPRESSOR STAGE 4 STATOR VANES, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101580 Engine 1 SB - Open #3788	NO. 1 ENGINE - ENGINE - COMPRESSORINTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF A NEW ENGINE NAME PLATE, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101580 Engine 2 SB - Open #4285	NO. 2 ENGINE - ENGINE - COMPRESSORINTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF A NEW ENGINE NAME PLATE, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101584 Engine 1 SB - Open #4113	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - DELETION OF BLACK OXIDE TREATMENT FROM THE LINE 1 BEVEL GEARASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101584 Engine 2 SB - Open #3861	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - DELETION OF BLACK OXIDE TREATMENT FROM THE LINE 1 BEVEL GEARASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101618 Engine 1 SB - Open #3296	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF AN ACCESSORY GEARBOX OIL TANK OIL FILL INSTRUCTION LABEL SUITABLE FOR USE WITH AN ALUMINUM ACCESSORY GEARBOX MAIN HOUSING, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101618 Engine 2 SB - Open #4470	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF AN ACCESSORY GEARBOX OIL TANK OIL FILL INSTRUCTION LABEL SUITABLE FOR USE WITH AN ALUMINUM ACCESSORY GEARBOX MAIN HOUSING, SERVICE BULLETIN	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-101623 Engine 1 SB - Open #3340	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW LUBRICLONE FORTHE ACCESSORY GEARBOX, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101623 Engine 2 SB - Open #4139	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW LUBRICLONE FORTHE ACCESSORY GEARBOX, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101663 Engine 1 SB - Open #3969	NO. 1 ENGINE - ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY AND LOW PRESSURE (LP) COMPRESSOR/INTERNAL GEARBOX OIL DISTRIBUTION TUBES - INTRODUCTION OF REVISED OIL JET HOUSINGS, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101663 Engine 2 SB - Open #4202	NO. 2 ENGINE - ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY AND LOW PRESSURE (LP) COMPRESSOR/INTERNAL GEARBOX OIL DISTRIBUTION TUBES - INTRODUCTION OF REVISED OIL JET HOUSINGS, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101664 R2 Engine 1 SB - Open #3121	NO. 1 ENGINE - ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - INTRODUCTION OF A NEW NO. 2 BEARING SUPPORT HOUSING, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101664 R2 Engine 2 SB - Open #3885	NO. 2 ENGINE - ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - INTRODUCTION OF A NEW NO. 2 BEARING SUPPORT HOUSING, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101699 Engine 1 SB - Open #4176	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - INTRODUCTION OF A NEW LP COMPRESSOR ANNULUS FILLER WITH AN INTEGRAL HOOK DESIGN, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101699 Engine 2 SB - Open #3214	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - INTRODUCTION OF A NEW LP COMPRESSOR ANNULUS FILLER WITH AN INTEGRAL HOOK DESIGN, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101705 Engine 1 SB - Open #3839	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSORROTOR AND SHAFT DISCS - INTRODUCTION OF A NEW HP COMPRESSOR FRONT ROTOR ASSEMBLY WITH SHANK NUTS HAVING SILVER COATED THREADS ONLY, SERVICE BULLETIN	H: 0.00					

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-101705 Engine 2 SB - Open #4345	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR ROTOR AND SHAFT DISCS - INTRODUCTION OF A NEW HP COMPRESSOR FRONT ROTOR ASSEMBLY WITH SHANK NUTS HAVING SILVER COATED THREADS ONLY, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101722 Engine 1 SB - Open #4012	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 2 ONWARD NOZZLE GUIDE SEALS - INTRODUCTION OF A DIFFERENT STANDARD HP TURBINE RIM SEAL ASSEMBLY AND HP TURBINE SUPPORT RING ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101722 Engine 2 SB - Open #3964	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 2 ONWARD NOZZLE GUIDE SEALS - INTRODUCTION OF A DIFFERENT STANDARD HP TURBINE RIM SEAL ASSEMBLY AND HP TURBINE SUPPORT RING ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101728 Engine 1 SB - Open #3067	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) ACTUATING RINGS AND LEVERS - INTRODUCTION OF A NEW MOUNTING BRACKET ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101728 Engine 2 SB - Open #3087	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) ACTUATING RINGS AND LEVERS - INTRODUCTION OF A NEW MOUNTING BRACKET ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101731 Engine 1 SB - Open #3414	NO. 1 ENGINE - ENGINE - BYPASS SERVICE FAIRING - INTRODUCTION OF ALTERNATIVE SPLITTER FAIRING ASSEMBLY RIVETS, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101731 Engine 2 SB - Open #4405	NO. 2 ENGINE - ENGINE - BYPASS SERVICE FAIRING - INTRODUCTION OF ALTERNATIVE SPLITTER FAIRING ASSEMBLY RIVETS, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101734 Engine 1 SB - Open #4615	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) ACTUATING RINGS AND LEVERS - INTRODUCTION OF CHANGES TO THE HP COMPRESSOR VARIABLE STATOR VANE (VSV) SYSTEM COMPONENTS, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101734 Engine 2 SB - Open #4024	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) ACTUATING RINGS AND LEVERS - INTRODUCTION OF CHANGES TO THE HP COMPRESSOR VARIABLE STATOR VANE (VSV) SYSTEM COMPONENTS, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101734 R1 Engine 1 SB - Open #4055	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) ACTUATING RINGS AND LEVERS - INTRODUCTION OF CHANGES TO THE HP COMPRESSOR VARIABLE STATOR VANE (VSV) SYSTEM COMPONENTS, SERVICE BULLETIN.	H: 0.00					

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-101734 R1 Engine 2 SB - Open #3837	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSORVARIABLE INLET GUIDE VANE (VIGV) ACTUATING RINGS AND LEVERS - INTRODUCTION OF CHANGES TO THE HP COMPRESSOR VARIABLE STATOR VANE (VSV) SYSTEM COMPONENTS, SERVICE BULLETIN.	H: 0.00					
SB BR700-72-101757 Engine 1 SB - Open #3341	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSORFRONT BEARING AND SUPPORT - INTRODUCTION OF A NEW ALTERNATIVE HP COMPRESSOR NO.3 BEARING ASSEMBLY WITH A MORE ROBUST DESIGN, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101757 Engine 2 SB - Open #3274	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSORFRONT BEARING AND SUPPORT - INTRODUCTION OF A NEW ALTERNATIVE HP COMPRESSOR NO.3 BEARING ASSEMBLY WITH A MORE ROBUST DESIGN, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101774 Engine 1 SB - Open #4117	NO. 1 ENGINE - ENGINE - CORE ENGINE FAIRINGS - INTRODUCTION OF A NEW STANDARD OF CORE ENGINE FAIRINGS, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101774 Engine 2 SB - Open #4373	NO. 2 ENGINE - ENGINE - CORE ENGINE FAIRINGS - INTRODUCTION OF A NEW STANDARD OF CORE ENGINE FAIRINGS, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101794 Engine 1 SB - Open #4427	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSORVARIABLE INLET GUIDE VANE (VIGV) RINGS AND SEALS - INTRODUCTION OF NUTS WITH SILVER COATED THREADS ONLY, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101794 Engine 2 SB - Open #4313	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSORVARIABLE INLET GUIDE VANE (VIGV) RINGS AND SEALS - INTRODUCTION OF NUTS WITH SILVER COATED THREADS ONLY, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101805 R2 Engine 1 SB - Open #3898	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW STANDARD OF PRESSURE RELIEF VALVE (PRV), SERVICE BULLETIN	H: 0.00					
SB BR700-72-101805 R2 Engine 2 SB - Open #3603	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW STANDARD OF PRESSURE RELIEF VALVE (PRV), SERVICE BULLETIN	H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-101805 R3 Engine 1 SB - Open #3099	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW STANDARD OF PRESSURE RELIEF VALVE (PRV), SERVICE BULLETIN.	H: 0.00					
SB BR700-72-101805 R3 Engine 2 SB - Open #3472	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW STANDARD OF PRESSURE RELIEF VALVE (PRV), SERVICE BULLETIN.	H: 0.00					
SB BR700-72-101805 R4 Engine 1 SB - Open #4400	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW STANDARD OF PRESSURE RELIEF VALVE (PRV), SERVICE BULLETIN..	H: 0.00					
SB BR700-72-101805 R4 Engine 2 SB - Complied With #3034	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW STANDARD OF PRESSURE RELIEF VALVE (PRV), SERVICE BULLETIN..	07-OCT-2014 H: 1015.50 C: 386					
	<p>Notes</p> <p>COMPLIED WITH - REMOVED PT 39504500 & INSTALLED NEW PT 39556600 PERBR710 MM CH 72-61-01 & SB BR700-72-101805 R4</p>						
SB BR700-72-101813 Engine 1 SB - Open #3876	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 1 LINER- INTRODUCTION OF NEW HP TURBINE STAGE 1 LINER SEGMENTS WITH AN INCREASED HONEYCOMB AREA, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101813 Engine 2 SB - Open #3254	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 1 LINER- INTRODUCTION OF NEW HP TURBINE STAGE 1 LINER SEGMENTS WITH AN INCREASED HONEYCOMB AREA, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101817 Engine 1 SB - Open #3091	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - RECONFIGURATION OF THE VESPEL COUPLINGS AND THE RETAINING RINGS USED FORINSTALLATION OF THE FUEL PUMP AND OIL PUMP AS NON-MODULAR PARTS, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101817 Engine 2 SB - Open #3329	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - RECONFIGURATION OF THE VESPEL COUPLINGS AND THE RETAINING RINGS USED FORINSTALLATION OF THE FUEL PUMP AND OIL PUMP AS NON-MODULAR PARTS, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101817 R1 Engine 1 SB - Open #4607	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - RECONFIGURATION OF THE VESPEL COUPLINGS AND THE RETAINING RINGS USED FORINSTALLATION OF THE FUEL PUMP AND OIL PUMP AS NON-MODULAR PARTS, SERVICE BULLETIN.	H: 0.00					

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-101817 R1 Engine 2 SB - Open #4584	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - RECONFIGURATION OF THE VESPEL COUPLINGS AND THE RETAINING RINGS USED FOR INSTALLATION OF THE FUEL PUMP AND OIL PUMP AS NON-MODULAR PARTS, SERVICE BULLETIN.	H: 0.00					
SB BR700-72-101837 Engine 1 SB - Open #4814	NO. 1 ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - INTRODUCTION OF AN HP TURBINE STAGE 1 DISC MADE FROM A DIFFERENT MATERIAL						
SB BR700-72-101837 Engine 2 SB - Open #4836	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - INTRODUCTION OF AN HP TURBINE STAGE 1 DISC MADE FROM A DIFFERENT MATERIAL						
SB BR700-72-101855 Engine 1 SB - Open #3955	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR FRONT CASE - INTRODUCTION OF AN ALTERNATIVE HP COMPRESSOR FRONT CASE ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101855 Engine 2 SB - Open #3361	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR FRONT CASE - INTRODUCTION OF AN ALTERNATIVE HP COMPRESSOR FRONT CASE ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101858 Engine 1 SB - Open #3186	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101858 PART 1 Engine 1 SB - Open #3421	NO. 1 ENGINE - REPLACEMENT-HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, OF THE OLD HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY (P/N BRR24357) WI	H: 0.00					
SB BR700-72-101858 PART 2 Engine 1 SB - Open #4286	NO. 1 ENGINE - REWORK-HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, OF THE OLD HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY FROM THE OLD STANDARD	H: 0.00					
SB BR700-72-101858 PART 3 Engine 1 SB - Open #4605	NO. 1 ENGINE - REWORK-HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, OF THE OLD HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY FROM THE OLD STANDARD .	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-101858 PART 4 Engine 1 SB - Open #3954	NO. 1 ENGINE - REWORK-HIGH PRESSURE (HP) COMPRESSORREAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, OF THE OLD HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY FROM THE OLD STANDARD ..	H: 0.00					
SB BR700-72-101858 PART 5 Engine 1 SB - Open #3229	NO. 1 ENGINE - REWORK-HIGH PRESSURE (HP) COMPRESSORREAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, OF THE OLD HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY FROM THE OLD STANDARD ...	H: 0.00					
SB BR700-72-101858 PART 6 Engine 1 SB - Open #3758	NO. 1 ENGINE - REWORK-HIGH PRESSURE (HP) COMPRESSORREAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, OF THE OLD HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY FROM THE OLD STANDARD	H: 0.00					
SB BR700-72-101858 Engine 2 SB - Open #3352	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSORREAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101858 PART 1 Engine 2 SB - Open #3544	NO. 2 ENGINE - REPLACEMENT-HIGH PRESSURE (HP) COMPRESSORREAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, OF THE OLD HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY (P/N BRR24357) WI	H: 0.00					
SB BR700-72-101858 PART 2 Engine 2 SB - Open #4610	NO. 2 ENGINE - REWORK-HIGH PRESSURE (HP) COMPRESSORREAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, OF THE OLD HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY FROM THE OLD STANDARD	H: 0.00					
SB BR700-72-101858 PART 3 Engine 2 SB - Open #4319	NO. 2 ENGINE - REWORK-HIGH PRESSURE (HP) COMPRESSORREAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, OF THE OLD HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY FROM THE OLD STANDARD .	H: 0.00					
SB BR700-72-101858 PART 4 Engine 2 SB - Open #4166	NO. 2 ENGINE - REWORK-HIGH PRESSURE (HP) COMPRESSORREAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, OF THE OLD HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY FROM THE OLD STANDARD ..	H: 0.00					
SB BR700-72-101858 PART 5 Engine 2 SB - Open #3480	NO. 2 ENGINE - REWORK-HIGH PRESSURE (HP) COMPRESSORREAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, OF THE OLD HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY FROM THE OLD STANDARD ...	H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-101858 PART 6 Engine 2 SB - Open #3373	NO. 2 ENGINE - REWORK-HIGH PRESSURE (HP) COMPRESSORREAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, OF THE OLD HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY FROM THE OLD STANDARD	H: 0.00					
SB BR700-72-101858 R1 Engine 1 SB - Open #4576	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSORREAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, SERVICE BULLETIN.	H: 0.00					
SB BR700-72-101858 R1 Engine 2 SB - Open #3338	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSORREAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, SERVICE BULLETIN.	H: 0.00					
SB BR700-72-101880 Engine 1 SB - Open #4079	NO. 1 ENGINE - BYPASS DUCT - INTRODUCTION OF A WEIGHT REDUCED BYPASS DUCT ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101880 Engine 2 SB - Open #3321	NO. 2 ENGINE - BYPASS DUCT - INTRODUCTION OF A WEIGHT REDUCED BYPASS DUCT ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101881 Engine 1 SB - Open #3475	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF AN ALTERNATIVE PRESSURE RELIEF VALVE (PRV), SERVICE BULLETIN	H: 0.00					
SB BR700-72-101881 Engine 2 SB - Open #4090	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF AN ALTERNATIVE PRESSURE RELIEF VALVE (PRV), SERVICE BULLETIN	H: 0.00					
SB BR700-72-101884 Engine 1 SB - Open #3350	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSORREAR OUTER CASE - INTRODUCTION OF AN ALTERNATIVE HP COMPRESSOR REAR OUTER CASE ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101884 Engine 2 SB - Open #3910	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSORREAR OUTER CASE - INTRODUCTION OF AN ALTERNATIVE HP COMPRESSOR REAR OUTER CASE ASSEMBLY, SERVICE BULLETIN	H: 0.00					

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-101887 Engine 1 SB - Open #3063	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSORMODULE - INTRODUCTION OF INCREASED TIP CLEARANCES FOR THE HP COMPRESSOR STAGES 6 TO 9 STATOR VANES, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101887 Engine 2 SB - Open #3743	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSORMODULE - INTRODUCTION OF INCREASED TIP CLEARANCES FOR THE HP COMPRESSOR STAGES 6 TO 9 STATOR VANES, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101888 Engine 1 SB - Open #3960	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW ACCESSORY GEARBOX MAIN HOUSING WITH A REVISED PRESSURE RELIEF VALVE (PRV) PORT, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101888 Engine 2 SB - Open #4435	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW ACCESSORY GEARBOX MAIN HOUSING WITH A REVISED PRESSURE RELIEF VALVE (PRV) PORT, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101890 Engine 1 SB - Open #3388	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEARLINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101890 Engine 2 SB - Open #4182	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEARLINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101890 R1 Engine 1 SB - Open #3053	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEARLINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR, SERVICE BULLETIN.	H: 0.00					
SB BR700-72-101890 R1 P1 Engine 1 SB - Open #3655	NO. 1 ENGINE - ACCOMPLISH,-REPLACEMENT OF THE OLD ACCESSORY GEARBOX ASSEMBLY (P/N 39600222) WITH A NEW PRODUCTION STANDARD ACCESSORY GEARBOX ASSEMBLY (P/N 39600223)	H: 0.00					
SB BR700-72-101890 R1 P2 Engine 1 SB - Open #4032	NO. 1 ENGINE - ACCOMPLISH,-REWORK OF THE ACCESSORY GEARBOX ASSEMBLY FROM THE OLD STANDARD (P/N 39600221) TO THE NEW STANDARD (P/N 39600224)	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-101890 R1 Engine 2 SB - Open #4002	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEARLINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR, SERVICE BULLETIN.	H: 0.00					
SB BR700-72-101890 R1 P1 Engine 2 SB - Open #3791	NO. 2 ENGINE - ACCOMPLISH,-REPLACEMENT OF THE OLD ACCESSORY GEARBOX ASSEMBLY (P/N 39600222) WITH A NEW PRODUCTION STANDARD ACCESSORY GEARBOX ASSEMBLY (P/N 39600223)	H: 0.00					
SB BR700-72-101890 R1 P2 Engine 2 SB - Open #4084	NO. 2 ENGINE - ACCOMPLISH,-REWORK OF THE ACCESSORY GEARBOX ASSEMBLY FROM THE OLD STANDARD (P/N 39600221) TO THE NEW STANDARD (P/N 39600224)	H: 0.00					
SB BR700-72-101890 R2 Engine 1 SB - Open #4801	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEAR LINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR (REV. 2)						
SB BR700-72-101890 R2 Engine 2 SB - Open #4823	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEAR LINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR (REV. 2)						
SB BR700-72-101890 R3 Engine 1 SB - Open #4809	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEARLINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR (REV. 3)						
SB BR700-72-101890 R3 Engine 2 SB - Open #4831	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REDESIGNED GEARLINE 12 ASSEMBLY WHICH IS BALANCED INCLUDING THE PERMANENT MAGNETIC ALTERNATOR (PMA) ROTOR (REV. 3)						
SB BR700-72-101893 Engine 1 SB - Open #4511	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSORCASE - INTRODUCTION OF A REVISED LP COMPRESSOR CASE WITH AN IMPROVED FAN TRACK LINER, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101893 Engine 2 SB - Open #3828	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSORCASE - INTRODUCTION OF A REVISED LP COMPRESSOR CASE WITH AN IMPROVED FAN TRACK LINER, SERVICE BULLETIN	H: 0.00					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-101893 R1 Engine 1 SB - N/A #4506	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSORCASE - INTRODUCTION OF A REVISED LP COMPRESSOR CASE WITH AN IMPROVED FAN TRACK LINER, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-101893 R1 Engine 2 SB - N/A #3370	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSORCASE - INTRODUCTION OF A REVISED LP COMPRESSOR CASE WITH AN IMPROVED FAN TRACK LINER, SERVICE BULLETIN.	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-101895 Engine 1 SB - Open #4080	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSORFAIRINGS - INTRODUCTION OF A NEW FAIRING PANEL (CHANNEL) WITH ADJUSTED DIMENSIONS AND DELETED BLANKING PLATE, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101895 Engine 2 SB - Open #4501	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSORFAIRINGS - INTRODUCTION OF A NEW FAIRING PANEL (CHANNEL) WITH ADJUSTED DIMENSIONS AND DELETED BLANKING PLATE, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101897 Engine 1 SB - Open #3929	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSORBLADES - INTRODUCTION OF AN ALTERNATIVE STANDARD OF HP COMPRESSOR STAGE 1 BLADE, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101897 Engine 2 SB - Open #3406	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSORBLADES - INTRODUCTION OF AN ALTERNATIVE STANDARD OF HP COMPRESSOR STAGE 1 BLADE, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101901 Engine 1 SB - Open #3621	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSORVIGV AND STAGES 1 TO 4 STATOR VANES - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR VARIABLE INLET GUIDE VANES (VIGV) AND HP COMPRESSOR STAGES 1 TO 3 VARIABLE STATOR VANES (VSV) WITH HELICOIL INSERTS, SERVICE	H: 0.00					
SB BR700-72-101901 Engine 2 SB - Open #3519	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSORVIGV AND STAGES 1 TO 4 STATOR VANES - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR VARIABLE INLET GUIDE VANES (VIGV) AND HP COMPRESSOR STAGES 1 TO 3 VARIABLE STATOR VANES (VSV) WITH HELICOIL INSERTS, SERVICE	H: 0.00					



ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-101901 R1 Engine 1 SB - Open #3504	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSORVIGV AND STAGES 1 TO 4 STATOR VANES - INTRODUCTION OF NEW HP COMPRESSOR VARIABLE INLET GUIDE VANES (VIGV) AND HP COMPRESSOR STAGES 1 TO 3 VARIABLE STATOR VANES (VSV) WITH HELICOIL INSERTS, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101901 R1 Engine 2 SB - Open #3899	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSORVIGV AND STAGES 1 TO 4 STATOR VANES - INTRODUCTION OF NEW HP COMPRESSOR VARIABLE INLET GUIDE VANES (VIGV) AND HP COMPRESSOR STAGES 1 TO 3 VARIABLE STATOR VANES (VSV) WITH HELICOIL INSERTS, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101908 Engine 1 SB - Open #4203	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSORFRONT BEARING AND SUPPORT - INTRODUCTION OF A NEW HP COMPRESSOR NO.3 BEARING ASSEMBLY WITH A DECREASED OUTER DIAMETER TO PROVIDE AN INCREASED SQUEEZE FILM DAMPER GAP, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101908 Engine 2 SB - Open #3868	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSORFRONT BEARING AND SUPPORT - INTRODUCTION OF A NEW HP COMPRESSOR NO.3 BEARING ASSEMBLY WITH A DECREASED OUTER DIAMETER TO PROVIDE AN INCREASED SQUEEZE FILM DAMPER GAP, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101909 Engine 1 SB - Open #4267	NO. 1 ENGINE - TURBINE EXHAUST SUPPORTS - INTRODUCTION OF ALTERNATIVE REARMOUNT SUPPORT STRUTS MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101909 Engine 2 SB - Open #4304	NO. 2 ENGINE - TURBINE EXHAUST SUPPORTS - INTRODUCTION OF ALTERNATIVE REARMOUNT SUPPORT STRUTS MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101911 Engine 1 SB - Open #3147	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSORREAR ROTOR DISCS - INTRODUCTION OF SILVER-FREE NUTS AT THE HP COMPRESSOR FRONT DRUM TO REAR DRUM JOINT FLANGE, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101911 Engine 2 SB - Open #3564	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSORREAR ROTOR DISCS - INTRODUCTION OF SILVER-FREE NUTS AT THE HP COMPRESSOR FRONT DRUM TO REAR DRUM JOINT FLANGE, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101916 Engine 1 SB - Open #4477	NO. 1 ENGINE - NL SPEED PROBE HARNESS AND ACCESSORIES - INTRODUCTION OF A REVISED NL SPEED PROBE HARNESS ASSEMBLY, SERVICE BULLETIN	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-101916 Engine 2 SB - Open #4205	NO. 2 ENGINE - NL SPEED PROBE HARNESS AND ACCESSORIES - INTRODUCTION OF A REVISED NL SPEED PROBE HARNESS ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101917 Engine 1 SB - Open #4539	NO. 1 ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - INTRODUCTION OF ALTERNATIVE BEARING ASSEMBLIES FOR THE RADIAL DRIVE SHAFT (RDS), SERVICE BULLETIN	H: 0.00					
SB BR700-72-101917 Engine 2 SB - Open #3260	NO. 2 ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - INTRODUCTION OF ALTERNATIVE BEARING ASSEMBLIES FOR THE RADIAL DRIVE SHAFT (RDS), SERVICE BULLETIN	H: 0.00					
SB BR700-72-101922 Engine 1 SB - Open #3548	NO. 1 ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - INTRODUCTION OF A NEW ALTERNATIVE LOCK NUT ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101922 Engine 2 SB - Open #3077	NO. 2 ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - INTRODUCTION OF A NEW ALTERNATIVE LOCK NUT ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101931 Engine 1 SB - Open #3478	NO. 1 ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF FOUR ADDITIONAL SPACERS BELOW THE ENGINE NAME PLATE MOUNTING BRACKET AND LONGER BOLTS TO IMPROVE THE CLEARANCE BETWEEN THE ENGINE NAME PLATE MOUNTING BRACKET AND THE INTERMEDI	H: 0.00					
SB BR700-72-101931 Engine 2 SB - Open #3945	NO. 2 ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF FOUR ADDITIONAL SPACERS BELOW THE ENGINE NAME PLATE MOUNTING BRACKET AND LONGER BOLTS TO IMPROVE THE CLEARANCE BETWEEN THE ENGINE NAME PLATE MOUNTING BRACKET AND THE INTERMEDI	H: 0.00					
SB BR700-72-101931 R1 Engine 1 SB - Open #4515	NO. 1 ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF FOUR ADDITIONAL SPACERS BELOW THE ENGINE NAME PLATE MOUNTING BRACKET AND LONGER BOLTS TO IMPROVE THE CLEARANCE BETWEEN THE ENGINE NAME PLATE MOUNTING BRACKET AND THE INTERMEDI.	H: 0.00					
SB BR700-72-101931 R1 Engine 2 SB - Open #4234	NO. 2 ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF FOUR ADDITIONAL SPACERS BELOW THE ENGINE NAME PLATE MOUNTING BRACKET AND LONGER BOLTS TO IMPROVE THE CLEARANCE BETWEEN THE ENGINE NAME PLATE MOUNTING BRACKET AND THE INTERMEDI.	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-101933 Engine 1 SB - Open #3698	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSORBLADES - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR STAGES 7 TO 10 BLADES WITH REVISED LEADING EDGES, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101933 Engine 2 SB - Open #3539	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSORBLADES - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR STAGES 7 TO 10 BLADES WITH REVISED LEADING EDGES, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101934 Engine 1 SB - Open #4101	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSORVARIABLE INLET GUIDE VANES (VIGV) AND STAGES 1 TO 4 STATOR VANES AND HP COMPRESSOR STAGE 5 ONWARD STATOR VANES - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR STAGES 4 TO 9 VANES WITH REVISED LEADING EDGES, SE	H: 0.00					
SB BR700-72-101934 Engine 2 SB - Open #3107	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSORVARIABLE INLET GUIDE VANES (VIGV) AND STAGES 1 TO 4 STATOR VANES AND HP COMPRESSOR STAGE 5 ONWARD STATOR VANES - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR STAGES 4 TO 9 VANES WITH REVISED LEADING EDGES, SE	H: 0.00					
SB BR700-72-101934 R1 Engine 1 SB - Open #4547	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSORVARIABLE INLET GUIDE VANES (VIGV) AND STAGES 1 TO 4 STATOR VANES AND HP COMPRESSOR STAGE 5 ONWARD STATOR VANES - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR STAGES 4 TO 9 VANES WITH REVISED LEADING EDGES, SE.	H: 0.00					
SB BR700-72-101934 R1 Engine 2 SB - Open #3734	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSORVARIABLE INLET GUIDE VANES (VIGV) AND STAGES 1 TO 4 STATOR VANES AND HP COMPRESSOR STAGE 5 ONWARD STATOR VANES - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR STAGES 4 TO 9 VANES WITH REVISED LEADING EDGES, SE.	H: 0.00					
SB BR700-72-101937 Engine 1 SB - Open #3640	NO. 1 ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - DELETION OF THE BEVEL WHEEL SHIELD FROM THE INTERNAL GEARBOX, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101937 Engine 2 SB - Open #4299	NO. 2 ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - DELETION OF THE BEVEL WHEEL SHIELD FROM THE INTERNAL GEARBOX, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101939 Engine 1 SB - Open #4709	NO. 1 - ENGINE - LOW PRESSURE (LP) COMPRESSOR STATIC AND BEARING SEALS - INTRODUCTION OF AN INTEGRATED INTERNAL GEARBOX FRONT BUFFER SEAL ASSEMBLY						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-101939 Engine 2 SB - Open #4710	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR STATIC AND BEARING SEALS - INTRODUCTION OF AN INTEGRATED INTERNAL GEARBOX FRONT BUFFER SEAL ASSEMBLY						
SB BR700-72-101940 Engine 1 SB - Open #3183	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSORBLADES - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR STAGES 2 TO 6 BLADES WITH REVISED LEADING EDGES, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101940 Engine 2 SB - Open #3691	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSORBLADES - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR STAGES 2 TO 6 BLADES WITH REVISED LEADING EDGES, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101946 Engine 1 SB - Open #3390	NO. 1 ENGINE - LOW PRESSURE (LP) TURBINE ROTORSHAFT - INTRODUCTION OF AN ALTERNATIVE LP TURBINE SHAFT, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101946 Engine 2 SB - Open #4583	NO. 2 ENGINE - LOW PRESSURE (LP) TURBINE ROTORSHAFT - INTRODUCTION OF AN ALTERNATIVE LP TURBINE SHAFT, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101947 Engine 1 SB - Open #3304	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSORVIGV AND STAGES 1 TO 4 STATOR VANES - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) ASSEMBLIES AND HP COMPRESSOR STAGES 1 TO 3 VARIABLE STATOR VANE (VSV) ASSEMBLIES, SERVICE BU	H: 0.00					
SB BR700-72-101947 Engine 2 SB - Open #4393	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSORVIGV AND STAGES 1 TO 4 STATOR VANES - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) ASSEMBLIES AND HP COMPRESSOR STAGES 1 TO 3 VARIABLE STATOR VANE (VSV) ASSEMBLIES, SERVICE BU	H: 0.00					
SB BR700-72-101949 Engine 1 SB - Open #3576	NO. 1 ENGINE - COMBUSTION FRONT INNERCASE AND VANES - INTRODUCTION OF AN ALTERNATIVE COMBUSTION FRONT INNER CASING, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101949 Engine 2 SB - Open #3322	NO. 2 ENGINE - COMBUSTION FRONT INNERCASE AND VANES - INTRODUCTION OF AN ALTERNATIVE COMBUSTION FRONT INNER CASING, SERVICE BULLETIN	H: 0.00					
SB BR700-72-101952 Engine 1 SB - Open #4783	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF AN LP COMPRESSOR ROTOR DISC PRODUCED IN ACCORDANCE WITH A DIFFERENT MANUFACTURING PROCESS						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-101952 Engine 2 SB - Open #4784	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF AN LP COMPRESSOR ROTOR DISC PRODUCED IN ACCORDANCE WITH A DIFFERENT MANUFACTURING PROCESS						
SB BR700-72-101953 Engine 1 SB - Open #4681	NO. 1 ENGINE - HIGH PRESSURE (HP) TURBINE BLADES - INTRODUCTION OF AN INSTRUCTION FOR MATCHED TIP GRINDING OF THE HP TURBINE STAGE 2 BLADES DURING NEW PRODUCTION OF THE ENGINE						
SB BR700-72-101953 Engine 2 SB - Open #4682	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE BLADES - INTRODUCTION OF AN INSTRUCTION FOR MATCHED TIP GRINDING OF THE HP TURBINE STAGE 2 BLADES DURING NEW PRODUCTION OF THE ENGINE						
SB BR700-72-101959 Airframe SB - Open #4628	NO. 1ENGINE - HIGH PRESSURE (HP) TURBINE CASE - INTRODUCTION OF A NEW HP TURBINE CASE ASSEMBLY WITH A MODIFIED FRONT HOOK TO AXIALLY POSITION THE SEAL STRIPS FOR THE HP TURBINE STAGE 1 LINERS						
SB BR700-72-101959 Engine 2 SB - Open #4627	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE CASE - INTRODUCTION OF A NEW HP TURBINE CASE ASSEMBLY WITH A MODIFIED FRONT HOOK TO AXIALLY POSITION THE SEAL STRIPS FOR THE HP TURBINE STAGE 1 LINERS						
SB BR700-72-101960 Engine 1 SB - Open #4661	NO. 1 ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 2 ONWARD NOZZLE GUIDE VANES (NGV) AND LINERS - INTRODUCTION OF MODIFIED HP TURBINE STAGE 2 NGV ASSEMBLIES AND LINER ASSEMBLIES						
SB BR700-72-101960 Engine 2 SB - Open #4662	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 2 ONWARD NOZZLE GUIDE VANES (NGV) AND LINERS - INTRODUCTION OF MODIFIED HP TURBINE STAGE 2 NGV ASSEMBLIES AND LINER ASSEMBLIES						
SB BR700-72-101964 Engine 1 SB - Open #4663	ENGINE - HIGH PRESSURE (HP) TURBINE CASE IMPINGEMENT COOLING MANIFOLD, LOW PRESSURE (LP) TURBINE FAIRINGS AND BYPASS DUCT - INTRODUCTION OF ALTERNATIVE RIVETS FOR THE HP TURBINE COOLING MANIFOLD, THE LP TURBINE FAIRINGS AND THE INTRASCOPE BLANKS						
SB BR700-72-101964 Engine 2 SB - Open #4664	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE CASE IMPINGEMENT COOLING MANIFOLD, LOW PRESSURE (LP) TURBINE FAIRINGS AND BYPASS DUCT - INTRODUCTION OF ALTERNATIVE RIVETS FOR THE HP TURBINE COOLING MANIFOLD, THE LP TURBINE FAIRINGS AND THE INTRASCOPE BLANKS						
SB BR700-72-101971 Engine 1 SB - Open #4711	NO. 1 ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 1 LINER - INTRODUCTION OF NEW HP TURBINE STAGE 1 LINER SEGMENTS MANUFACTURED IN ACCORDANCE WITH AN UPDATED MACHINING PROCESS						

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-101971 Engine 2 SB - Open #4712	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 1 LINER - INTRODUCTION OF NEW HP TURBINE STAGE 1 LINER SEGMENTS MANUFACTURED IN ACCORDANCE WITH AN UPDATED MACHINING PROCESS						
SB BR700-72-101990 Engine 1 SB - Open #4788	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REVISED ACCESSORY GEARBOX MAIN HOUSING ASSEMBLY WITH A NEW DEFINITION FOR HOLE DIMENSIONS AND ASSOCIATED MATCHING						
SB BR700-72-101990 Engine 2 SB - Open #4789	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A REVISED ACCESSORY GEARBOX MAIN HOUSING ASSEMBLY WITH A NEW DEFINITION FOR HOLE DIMENSIONS AND ASSOCIATED MATCHING						
SB BR700-72-102102 Engine 1 SB - Open #4828	ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF AN INTERMEDIATE CASE WITH ALTERNATIVE BUSHES MADE FROM A DIFFERENT MATERIAL						
SB BR700-72-102102 Engine 2 SB - Open #4850	ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF AN INTERMEDIATE CASE WITH ALTERNATIVE BUSHES MADE FROM A DIFFERENT MATERIAL						
SB BR700-72-102169 Engine 1 SB - Open #4835	ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - INTRODUCTION OF AN ALTERNATIVE SPIRALOCK INSERT FOR THE RADIAL DRIVE SHAFT (RDS) LOWER SUPPORT HOUSING						
SB BR700-72-102169 Engine 2 SB - Open #4857	ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - INTRODUCTION OF AN ALTERNATIVE SPIRALOCK INSERT FOR THE RADIAL DRIVE SHAFT (RDS) LOWER SUPPORT HOUSING						
SB BR700-72-102187 Engine 1 SB - Open #4840	ENGINE - HIGH PRESSURE (HP) COMPRESSOR FRONT CASE - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) AND HP COMPRESSOR STAGE 1 VARIABLE STATOR VANE (VSV) BUSHES FOR THE HP COMPRESSOR FRONT SPLIT CASE ASSEMBLY						
SB BR700-72-102187 Engine 2 SB - Open #4862	ENGINE - HIGH PRESSURE (HP) COMPRESSOR FRONT CASE - INTRODUCTION OF ALTERNATIVE HP COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) AND HP COMPRESSOR STAGE 1 VARIABLE STATOR VANE (VSV) BUSHES FOR THE HP COMPRESSOR FRONT SPLIT CASE ASSEMBLY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-900229 R2 Engine 1 SB - Superseded #335	NO. 1 ENGINE - LP COMPRESSORINSPECTION OF FAN DISC, SERVICE BULLETIN	15-JAN-2010 H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-900229 R2 Engine 2 SB - Superseded #1413	NO. 2 ENGINE - LP COMPRESSORINSPECTION OF FAN DISC, SERVICE BULLETIN	15-JAN-2010 H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-900229 R4 Engine 1 SB - Superseded #121	NO. 1 ENGINE - LP COMPRESSOR-INSPECTION OF FAN DISC, SERVICE BULLETIN	15-JAN-2010 H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-900229 R4 Engine 2 SB - Superseded #2750	NO. 2 ENGINE - LP COMPRESSOR-INSPECTION OF FAN DISC, SERVICE BULLETIN	15-JAN-2010 H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-900229 R5 Engine 1 SB - Superseded #2729	NO. 1 ENGINE - LP COMPRESSOR - INSPECTION OF FAN DISC, SERVICE BULLETIN	15-JAN-2010 H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-900229 R5 Engine 2 SB - Superseded #1599	NO. 2 ENGINE - LP COMPRESSOR - INSPECTION OF FAN DISC, SERVICE BULLETIN	15-JAN-2010 H: 0.00					
	Notes NOT APPLICABLE						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-900229 R6 Engine 1 SB - N/A #1799	NO. 1 ENGINE - LP COMPRESSOR - INSPECTION OF FAN DISC, SERVICE BULLETIN.	25-FEB-2010 H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB BR700-72-900229 R6 P2 Engine 1 SB - N/A #2021	NO. 1 ENGINE - ULTRASONIC AND VISUAL INSPECTION OF THE FAN DISC, SERVICE BULLETIN	25-FEB-2010 H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB BR700-72-900229 R6 P1 Engine 1 SB - N/A #940	NO. 1 ENGINE - VISUAL ORULTRASONIC INSP OF THE FAN DISC, SERVICE BULLETIN	25-FEB-2010 H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB BR700-72-900229 R6 Engine 2 SB - N/A #88	NO. 2 ENGINE - LP COMPRESSOR - INSPECTION OF FAN DISC, SERVICE BULLETIN.	25-FEB-2010 H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB BR700-72-900229 R6 P2 Engine 2 SB - N/A #14	NO. 2 ENGINE - ULTRASONIC AND VISUAL INSPECTION OF THE FAN DISC, SERVICE BULLETIN	25-FEB-2010 H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB BR700-72-900229 R6 P1 Engine 2 SB - N/A #659	NO. 2 ENGINE - VISUAL ORULTRASONIC INSP OF THE FAN DISC, SERVICE BULLETIN	25-FEB-2010 H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-900307 R1 Engine 1 SB - Superseded #3566	NO. 1 ENGINE - INSPECTION OF TIGHT CLEARANCE ON ENGINE DRESSING, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900307 R1 Engine 2 SB - Superseded #4193	NO. 2 ENGINE - INSPECTION OF TIGHT CLEARANCE ON ENGINE DRESSING, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900307 R2 Engine 1 SB - Complied With #286	NO. 1 ENGINE - INSPECTION OF TIGHT CLEARANCE ON ENGINE DRESSING, SERVICE BULLETIN.	21-JAN-2011 H: 11.80 C: 6					
	Notes COMPLIED WITH - AT COMPLETION						
SB BR700-72-900307 R2 Engine 2 SB - Complied With #2529	NO. 2 ENGINE - INSPECTION OF TIGHT CLEARANCE ON ENGINE DRESSING, SERVICE BULLETIN.	21-JAN-2011 H: 11.80 C: 6					
	Notes COMPLIED WITH - AT COMPLETION						
SB BR700-72-900307 R3 Engine 1 SB - Complied With #2783	NO. 1 ENGINE - INSPECTION OF TIGHT CLEARANCE ON ENGINE DRESSING, SERVICE BULLETIN..	12-SEP-2012 H: 388.37 C: 190					
	Notes COMPLIED WITH						
SB BR700-72-900307 R3 Engine 2 SB - Complied With #2611	NO. 2 ENGINE - INSPECTION OF TIGHT CLEARANCE ON ENGINE DRESSING, SERVICE BULLETIN..	12-SEP-2012 H: 388.37 C: 190					
	Notes COMPLIED WITH						
SB BR700-72-900315 Engine 1 SB - Superseded #3302	NO. 1 ENGINE - ENGINE - LP COMPRESSOR- REPAIR OF THE FAN BLADE DRY FILM LUBRICANT (DFL) COATING, SERVICE BULLETIN	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-900315 Engine 2 SB - Superseded #3571	NO. 2 ENGINE - ENGINE - LP COMPRESSOR- REPAIR OF THE FAN BLADE DRY FILM LUBRICANT (DFL) COATING, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900315 R1 Engine 1 SB - Open #3425	NO. 1 ENGINE - ENGINE - LP COMPRESSOR- REPAIR OF THE FAN BLADE DRY FILM LUBRICANT (DFL) COATING, SERVICE BULLETIN.	H: 0.00					
SB BR700-72-900315 R1 Engine 2 SB - Open #3710	NO. 2 ENGINE - ENGINE - LP COMPRESSOR- REPAIR OF THE FAN BLADE DRY FILM LUBRICANT (DFL) COATING, SERVICE BULLETIN.	H: 0.00					
SB BR700-72-900341 Engine 1 SB - Open #3731	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSORBLADES - BORESCOPE BLENDING REPAIR OF THE HP COMPRESSOR STAGE 1 ROTOR BLADES, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900341 Engine 2 SB - Open #3232	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSORBLADES - BORESCOPE BLENDING REPAIR OF THE HP COMPRESSOR STAGE 1 ROTOR BLADES, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900369 R2 P1 Engine 1 SB - Superseded #3936	NO. 1 ENGINE - BORESCOPE INSPECTION OF THE HP TURBINE STAGE 1 NOZZLE GUIDE VANES (NGV), THE HP TURBINE STAGE 1 BLADES AND THE COMBUSTION REARINNER CIRCLE (CRIC), SERVICE BULLETIN	H: 0.00					
SB BR700-72-900369 R2 P2 Engine 1 SB - Superseded #3678	NO. 1 ENGINE - BORESCOPE INSPECTION OF THE HP TURBINE STAGE 1 NOZZLE GUIDE VANES (NGV), THE HP TURBINE STAGE 1 BLADES AND THE COMBUSTION REARINNER CIRCLE (CRIC), SERVICE BULLETIN.	H: 0.00					
SB BR700-72-900369 R2 P3 Engine 1 SB - Superseded #3738	NO. 1 ENGINE - BORESCOPE INSPECTION OF THE HP TURBINE STAGE 1 NOZZLE GUIDE VANES (NGV), THE HP TURBINE STAGE 1 BLADES AND THE COMBUSTION REARINNER CIRCLE (CRIC), SERVICE BULLETIN..	H: 0.00					
SB BR700-72-900369 R2 P1 Engine 2 SB - Superseded #3591	NO. 2 ENGINE - BORESCOPE INSPECTION OF THE HP TURBINE STAGE 1 NOZZLE GUIDE VANES (NGV), THE HP TURBINE STAGE 1 BLADES AND THE COMBUSTION REARINNER CIRCLE (CRIC), SERVICE BULLETIN	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-900369 R2 P2 Engine 2 SB - Superseded #3897	NO. 2 ENGINE - BORESCOPE INSPECTION OF THE HP TURBINE STAGE 1 NOZZLE GUIDE VANES (NGV), THE HP TURBINE STAGE 1 BLADES AND THE COMBUSTION REARINNER CIRCLE (CRIC), SERVICE BULLETIN.	H: 0.00					
SB BR700-72-900369 R2 P3 Engine 2 SB - Superseded #4407	NO. 2 ENGINE - BORESCOPE INSPECTION OF THE HP TURBINE STAGE 1 NOZZLE GUIDE VANES (NGV), THE HP TURBINE STAGE 1 BLADES AND THE COMBUSTION REARINNER CIRCLE (CRIC), SERVICE BULLETIN..	H: 0.00					
SB BR700-72-900369 R3 P2 Engine 1 SB - Open #4041	NO. 1 ENGINE - ENGINE - COMBUSTION AND HIGH PRESSURE (HP) TURBINE MODULE - BORESCOPE INSPECTION OF THE HP TURBINE STAGE 1 NOZZLE GUIDE VANES (NGV), THE HP TURBINE STAGE 1 BLADES AND THE COMBUSTION REARINNER CASE (CRIC), SERVICE BULLETIN	H: 0.00					
SB BR700-72-900369 R3 P3 Engine 1 SB - Open #3143	NO. 1 ENGINE - ENGINE - COMBUSTION AND HIGH PRESSURE (HP) TURBINE MODULE - BORESCOPE INSPECTION OF THE HP TURBINE STAGE 1 NOZZLE GUIDE VANES (NGV), THE HP TURBINE STAGE 1 BLADES AND THE COMBUSTION REARINNER CASE (CRIC), SERVICE BULLETIN.	H: 0.00					
SB BR700-72-900369 R3 P1 Engine 1 SB - Open #3285	NO. 1 ENGINE - ENGINE - COMBUSTION AND HIGH PRESSURE (HP) TURBINE MODULE - BORESCOPE INSPECTION OF THE HP TURBINE STAGE 1 NOZZLE GUIDE VANES (NGV), THE HP TURBINE STAGE 1 BLADES AND THE COMBUSTION REARINNER CASE (CRIC)- , SERVICE BULLETIN	H: 0.00					
SB BR700-72-900369 R3 P2 Engine 2 SB - Open #3572	NO. 2 ENGINE - ENGINE - COMBUSTION AND HIGH PRESSURE (HP) TURBINE MODULE - BORESCOPE INSPECTION OF THE HP TURBINE STAGE 1 NOZZLE GUIDE VANES (NGV), THE HP TURBINE STAGE 1 BLADES AND THE COMBUSTION REARINNER CASE (CRIC), SERVICE BULLETIN	H: 0.00					
SB BR700-72-900369 R3 P3 Engine 2 SB - Open #3810	NO. 2 ENGINE - ENGINE - COMBUSTION AND HIGH PRESSURE (HP) TURBINE MODULE - BORESCOPE INSPECTION OF THE HP TURBINE STAGE 1 NOZZLE GUIDE VANES (NGV), THE HP TURBINE STAGE 1 BLADES AND THE COMBUSTION REARINNER CASE (CRIC), SERVICE BULLETIN.	H: 0.00					
SB BR700-72-900369 R3 P1 Engine 2 SB - Open #4554	NO. 2 ENGINE - ENGINE - COMBUSTION AND HIGH PRESSURE (HP) TURBINE MODULE - BORESCOPE INSPECTION OF THE HP TURBINE STAGE 1 NOZZLE GUIDE VANES (NGV), THE HP TURBINE STAGE 1 BLADES AND THE COMBUSTION REARINNER CASE (CRIC)- , SERVICE BULLETIN	H: 0.00					
SB BR700-72-900375 Engine 1 SB - Superseded #3515	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSORVARIABLE STATOR VANE (VSV) ACTUATING MECHANISM - RE-APPLICATION OF DRIVE BRACKET BOLT TORQUE, SERVICE BULLETIN	H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-900375 Engine 2 SB - Superseded #3142	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSORVARIABLE STATOR VANE (VSV) ACTUATING MECHANISM - RE-APPLICATION OF DRIVE BRACKET BOLT TORQUE, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900375 R1 Engine 1 SB - Superseded #3527	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSORVARIABLE STATOR VANE (VSV) ACTUATING MECHANISM - RE-APPLICATION OF DRIVE BRACKET BOLT TORQUE, SERVICE BULLETIN.	H: 0.00					
SB BR700-72-900375 R1 Engine 2 SB - Superseded #4502	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSORVARIABLE STATOR VANE (VSV) ACTUATING MECHANISM - RE-APPLICATION OF DRIVE BRACKET BOLT TORQUE, SERVICE BULLETIN.	H: 0.00					
SB BR700-72-900375 R2 Engine 1 SB - Superseded #3565	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSORVARIABLE STATOR VANE (VSV) ACTUATING MECHANISM - RE-APPLICATION OF DRIVE BRACKET BOLT TORQUE, SERVICE BULLETIN..	H: 0.00					
SB BR700-72-900375 R2 Engine 2 SB - Superseded #3206	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSORVARIABLE STATOR VANE (VSV) ACTUATING MECHANISM - RE-APPLICATION OF DRIVE BRACKET BOLT TORQUE, SERVICE BULLETIN..	H: 0.00					
SB BR700-72-900375 R3 Engine 1 SB - Open #4057	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSORVARIABLE STATOR VANE (VSV) ACTUATING MECHANISM - RE-APPLICATION OF DRIVE BRACKET BOLT TORQUE, SERVICE BULLETIN...	H: 0.00					
SB BR700-72-900375 R3 Engine 2 SB - Open #3420	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSORVARIABLE STATOR VANE (VSV) ACTUATING MECHANISM - RE-APPLICATION OF DRIVE BRACKET BOLT TORQUE, SERVICE BULLETIN...	H: 0.00					
SB BR700-72-900388 R2 Engine 1 SB - Open #4370	NO. 1 ENGINE - ENGINE - HIGH PRESSURE COMPRESSORBLADES- BORESCOPE INSPECTION OF THE HP COMPRESSOR STAGE 1 BLADES FOR DEFLECTION AT THE LEADING EDGE NEAR THE SNUBBER- NON- MODIFICATION SB, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900388 R2 Engine 2 SB - Open #4210	NO. 2 ENGINE - ENGINE - HIGH PRESSURE COMPRESSORBLADES- BORESCOPE INSPECTION OF THE HP COMPRESSOR STAGE 1 BLADES FOR DEFLECTION AT THE LEADING EDGE NEAR THE SNUBBER- NON- MODIFICATION SB, SERVICE BULLETIN	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-900392 R2 Engine 1 SB - N/A #4394	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSORCASE - INSPECTION OF THE LP COMPRESSOR CASE FOR INSTALLATION OF CUT ICE IMPACT TRAY BOX ASSEMBLIES BY INCORPORATION OF THE ORIGINAL REPAIR BRG1431 - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-900392 R2 Engine 2 SB - N/A #3660	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSORCASE - INSPECTION OF THE LP COMPRESSOR CASE FOR INSTALLATION OF CUT ICE IMPACT TRAY BOX ASSEMBLIES BY INCORPORATION OF THE ORIGINAL REPAIR BRG1431 - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-900409 R1 Engine 1 SB - Open #3508	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORCASE - INSPECTION OF THE LP COMPRESSOR CASE FOR INCORPORATION OF THE REPAIR BRG1299 NON-MODIFICATION, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900409 R1 Engine 2 SB - Open #3717	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORCASE - INSPECTION OF THE LP COMPRESSOR CASE FOR INCORPORATION OF THE REPAIR BRG1299 NON-MODIFICATION, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900455 R2 PB Engine 1 SB - Superseded #2103	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN	21-MAR-2010 H: 0.00					
SB BR700-72-900455 R2 PA Engine 1 SB - Superseded #2066	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - VISUAL INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN	21-MAR-2010 H: 0.00					
SB BR700-72-900455 R2 PB Engine 2 SB - Superseded #2502	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN	21-MAR-2010 H: 0.00					
SB BR700-72-900455 R2 PA Engine 2 SB - Superseded #282	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - VISUAL INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN	21-MAR-2010 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-900455 R3 PB Engine 1 SB - Superseded #1937	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN	21-MAR-2010 H: 0.00					
SB BR700-72-900455 R3 PA Engine 1 SB - Superseded #869	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - VISUAL INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN	21-MAR-2010 H: 0.00					
SB BR700-72-900455 R3 PB Engine 2 SB - Superseded #2772	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN	21-MAR-2010 H: 0.00					
SB BR700-72-900455 R3 PA Engine 2 SB - Superseded #2111	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - VISUAL INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN	21-MAR-2010 H: 0.00					
SB BR700-72-900455 R4 PB Engine 1 SB - Superseded #871	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN.	21-MAR-2010 H: 0.00					
SB BR700-72-900455 R4 PA Engine 1 SB - Superseded #2571	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - VISUAL INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN.	21-MAR-2010 H: 0.00					
SB BR700-72-900455 R4 PB Engine 2 SB - Superseded #1381	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN.	21-MAR-2010 H: 0.00					
SB BR700-72-900455 R4 PA Engine 2 SB - Superseded #3037	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - VISUAL INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN.	21-MAR-2010 H: 0.00					
SB BR700-72-900455 R5 PB Engine 1 SB - Open #3369	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN..	H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-900455 R5 PA Engine 1 SB - Open #4038	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - VISUAL INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN..	H: 0.00					
SB BR700-72-900455 R5 PB Engine 2 SB - Open #4595	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN..	H: 0.00					
SB BR700-72-900455 R5 PA Engine 2 SB - Open #3803	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - VISUAL INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN..	H: 0.00					
SB BR700-72-900455 R6 Engine 1 SB - Open #4565	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT AND VISUAL INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900455 R6 Engine 2 SB - Open #4129	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT AND VISUAL INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900456 Engine 1 SB - Open #3638	NO. 1 ENGINE - ENGINE CONVERSION FROM A FLIGHT-TEST STANDARD ENGINE TO A PRODUCTION STANDARD ENGINE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900456 Engine 2 SB - Open #3792	NO. 2 ENGINE - ENGINE CONVERSION FROM A FLIGHT-TEST STANDARD ENGINE TO A PRODUCTION STANDARD ENGINE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900493 Engine 1 SB - Open #4613	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE RELIEF VALVE - NON-MODIFICATION, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900493 Engine 2 SB - Open #3814	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE RELIEF VALVE - NON-MODIFICATION, SERVICE BULLETIN	H: 0.00					





Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-900500 R2 Engine 1 SB - Open #4030	NO. 1 ENGINE - ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - REMOVAL AND INSTALLATION OF THE NO. 2 BEARING SUPPORT HOUSING - NON-MODIFICATION, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900500 R2 Engine 2 SB - Open #4088	NO. 2 ENGINE - ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - REMOVAL AND INSTALLATION OF THE NO. 2 BEARING SUPPORT HOUSING - NON-MODIFICATION, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900506 Engine 1 SB - Superseded #4023	NO. 1 ENGINE - ENGINE - MAINTENANCE RECOMMENDATIONS AND SAMPLING INSPECTIONS IN RESPONSE TO OPERATION IN THE VICINITY OF A VOLCANIC ASH AREA, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900506 Engine 2 SB - Superseded #3926	NO. 2 ENGINE - ENGINE - MAINTENANCE RECOMMENDATIONS AND SAMPLING INSPECTIONS IN RESPONSE TO OPERATION IN THE VICINITY OF A VOLCANIC ASH AREA, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900506 R1 Engine 1 SB - Superseded #3972	NO. 1 ENGINE - ENGINE - MAINTENANCE RECOMMENDATIONS AND SAMPLING INSPECTIONS IN RESPONSE TO OPERATION IN THE VICINITY OF A VOLCANIC ASH AREA - NON-MODIFICATION, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900506 R1 Engine 2 SB - Superseded #4468	NO. 2 ENGINE - ENGINE - MAINTENANCE RECOMMENDATIONS AND SAMPLING INSPECTIONS IN RESPONSE TO OPERATION IN THE VICINITY OF A VOLCANIC ASH AREA - NON-MODIFICATION, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900506 R2 Engine 1 SB - Open #2264	NO. 1 ENGINE - ENGINE - MAINTENANCE RECOMMENDATIONS AND SAMPLING INSPECTIONS IN RESPONSE TO OPERATION IN THE VICINITY OF A VOLCANIC ASH AREA - NON-MODIFICATION, SERVICE BULLETIN.	08-SEP-2011 H: 0.00					
	Notes DECLINED						
SB BR700-72-900506 R2 Engine 2 SB - Open #1827	NO. 2 ENGINE - ENGINE - MAINTENANCE RECOMMENDATIONS AND SAMPLING INSPECTIONS IN RESPONSE TO OPERATION IN THE VICINITY OF A VOLCANIC ASH AREA - NON-MODIFICATION, SERVICE BULLETIN.	08-SEP-2011 H: 0.00					
	Notes DECLINED						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-900510 R1 Engine 1 SB - Open #3049	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP)/HIGH PRESSURE (HP) TURBINE SUPPORT AND OUTERBEARINGS - INSPECTION AND REPAIR OF REAR BEARING SUPPORT STRUCTURES (RBSS) THAT HAVE BEEN MACHINED BY ELECTRICAL DISCHARGE MACHINING (EDM) - NON-MODIFICATION SERVI	H: 0.00					
SB BR700-72-900510 R1 Engine 2 SB - Open #3270	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP)/HIGH PRESSURE (HP) TURBINE SUPPORT AND OUTERBEARINGS - INSPECTION AND REPAIR OF REAR BEARING SUPPORT STRUCTURES (RBSS) THAT HAVE BEEN MACHINED BY ELECTRICAL DISCHARGE MACHINING (EDM) - NON-MODIFICATION SERVI	H: 0.00					
SB BR700-72-900515 Engine 1 SB - Open #4147	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR- INSPECTION POST FAN BLADE DRY FILM LUBRICANT (DFL) COATING REFURBISHMENT INTERVAL OVERSHOOT, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900515 Engine 2 SB - Open #3800	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR- INSPECTION POST FAN BLADE DRY FILM LUBRICANT (DFL) COATING REFURBISHMENT INTERVAL OVERSHOOT, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900515 R1 Engine 1 SB - Open #4856	ENGINE - LOW PRESSURE (LP) COMPRESSOR - INSPECTION POST FAN BLADE DRY FILM LUBRICANT (DFL) COATING REFURBISHMENT INTERVAL OVERSHOOT - NON-MODIFICATION SERVICE BULLETIN						
SB BR700-72-900515 R1 Engine 2 SB - Open #5144	ENGINE - LOW PRESSURE (LP) COMPRESSOR - INSPECTION POST FAN BLADE DRY FILM LUBRICANT (DFL) COATING REFURBISHMENT INTERVAL OVERSHOOT - NON-MODIFICATION SERVICE BULLETIN						
SB BR700-72-900521 PART A Engine 1 SB - Open #3252	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900521 PART B Engine 1 SB - Open #3200	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN.	H: 0.00					
SB BR700-72-900521 PART A Engine 2 SB - Open #3346	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN	H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-900521 PART B Engine 2 SB - Open #3130	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN.	H: 0.00					
SB BR700-72-900521 R1 PA Engine 1 SB - Complied With #1156	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN..	16-FEB-2012 H: 292.60 C: 134					
	Notes COMPLIED WITH						
SB BR700-72-900521 R1 PB Engine 1 SB - N/A #2780	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN...	16-FEB-2012 H: 292.60 C: 134					
	Notes NOT APPLICABLE - BY ANNULUS FILLERS S/N						
SB BR700-72-900521 R1 PA Engine 2 SB - Complied With #1486	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN..	16-FEB-2012 H: 292.60 C: 134					
	Notes COMPLIED WITH						
SB BR700-72-900521 R1 PB Engine 2 SB - N/A #1909	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN...	16-FEB-2012 H: 292.60 C: 134					
	Notes NOT APPLICABLE - BY ANNULUS FILLERS S/N						
SB BR700-72-900521 R2 PB Engine 1 SB - N/A #552	NO. 1 ENGINE - EDDY CURRENT-ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, INSPECTION OF THE AFFECTED LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS	12-SEP-2012 H: 388.37 C: 190					
	Notes NOT APPLICABLE - N/A AS PERANNULUS FILLERS S/N'S						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-900521 R2 Engine 1 SB - Open #3411	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN....	H: 0.00					
SB BR700-72-900521 R2 PA Engine 1 SB - Complied With #67	NO. 1 ENGINE - VERIFICATION-ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, OF THE SERIAL NUMBERS OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS	12-SEP-2012 H: 388.37 C: 190					
	Notes COMPLIED WITH						
SB BR700-72-900521 R2 PB Engine 2 SB - N/A #2708	NO. 2 ENGINE - EDDY CURRENT-ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, INSPECTION OF THE AFFECTED LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS	12-SEP-2012 H: 388.37 C: 190					
	Notes NOT APPLICABLE - N/A AS PERANNULUS FILLERS S/N'S						
SB BR700-72-900521 R2 Engine 2 SB - Open #3167	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN....	H: 0.00					
SB BR700-72-900521 R2 PA Engine 2 SB - Complied With #2287	NO. 2 ENGINE - VERIFICATION-ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS, OF THE SERIAL NUMBERS OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS	12-SEP-2012 H: 388.37 C: 190					
	Notes COMPLIED WITH						
SB BR700-72-900521 R3 Engine 1 SB - Complied With #1811	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, SERVICE BULLETIN	29-NOV-2012 H: 426.50 C: 209					
	Notes COMPLIED WITH						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-900521 R3 PB Engine 1 SB - N/A #2728	NO. 1 ENGINE - PERFORM-ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, EDDY CURRENT INSPECTION OF THE AFFECTED LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS	29-NOV-2012 H: 426.50 C: 209					
	Notes NOT APPLICABLE						
SB BR700-72-900521 R3 PA Engine 1 SB - N/A #50	NO. 1 ENGINE - PERFORM-ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, VERIFICATION OF THE SERIAL NUMBERS OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS	29-NOV-2012 H: 426.50 C: 209					
	Notes NOT APPLICABLE - N/A DUE TO S/N RANGE INSTALLED						
SB BR700-72-900521 R3 Engine 2 SB - Open #3059	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900521 R3 PB Engine 2 SB - Open #4152	NO. 2 ENGINE - PERFORM-ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, EDDY CURRENT INSPECTION OF THE AFFECTED LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS	H: 0.00					
SB BR700-72-900521 R3 PA Engine 2 SB - Open #4085	NO. 2 ENGINE - PERFORM-ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, VERIFICATION OF THE SERIAL NUMBERS OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS	H: 0.00					
SB BR700-72-900521 R4 PB Engine 1 SB - Open #3536	NO. 1 ENGINE - EDDY CURRENT INSPECTION-ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, OF THE AFFECTED LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS	H: 0.00					
SB BR700-72-900521 R4 Engine 1 SB - Open #3579	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, SERVICE BULLETIN.	H: 0.00					
SB BR700-72-900521 R4 PA Engine 1 SB - Open #3265	NO. 1 ENGINE - VERIFICATION-ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, OF THE SERIAL NUMBERS OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS	H: 0.00					

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-900521 R4 PB Engine 2 SB - Open #4069	NO. 2 ENGINE - EDDY CURRENT INSPECTION-ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, OF THE AFFECTED LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS	H: 0.00					
SB BR700-72-900521 R4 Engine 2 SB - Open #4009	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, SERVICE BULLETIN.	H: 0.00					
SB BR700-72-900521 R4 PA Engine 2 SB - Open #4250	NO. 2 ENGINE - VERIFICATION-ENGINE - LOW PRESSURE (LP) COMPRESSORBLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, OF THE SERIAL NUMBERS OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS	H: 0.00					
SB BR700-72-900525 Engine 1 SB - Open #4258	NO. 1 ENGINE - INSPECTION OF THE INTERMEDIATE CASE FORCORROSION DUE TO WATER ACCUMULATION IN THE ENGINE FRONT MOUNT FIREBOX, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900525 Engine 2 SB - Open #3387	NO. 2 ENGINE - INSPECTION OF THE INTERMEDIATE CASE FORCORROSION DUE TO WATER ACCUMULATION IN THE ENGINE FRONT MOUNT FIREBOX, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900525 R1 Engine 1 SB - Open #3278	NO. 1 ENGINE - ENGINE - INTERMEDIATE CASE MODULE - INSPECTION OF THE INTERMEDIATE CASE FORCORROSION DUE TO WATER ACCUMULATION IN THE ENGINE FRONT MOUNT FIREBOX - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900525 R1 Engine 2 SB - Open #3173	NO. 2 ENGINE - ENGINE - INTERMEDIATE CASE MODULE - INSPECTION OF THE INTERMEDIATE CASE FORCORROSION DUE TO WATER ACCUMULATION IN THE ENGINE FRONT MOUNT FIREBOX - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900526 Engine 1 SB - Open #4366	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INSPECTION BY CARRYING OUT A PRE-LOAD MEASUREMENT OF THE ACCESSORY GEARBOX LINE 12 - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900526 Engine 2 SB - Open #4154	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INSPECTION BY CARRYING OUT A PRE-LOAD MEASUREMENT OF THE ACCESSORY GEARBOX LINE 12 - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	H: 0.00					

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-900526 R1 Engine 1 SB - Open #3754	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - INSPECTION BY CARRYING OUT A PRE-LOAD MEASUREMENT OF THE ACCESSORY GEARBOX LINE 12 - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900526 R1 Engine 2 SB - Open #3153	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - INSPECTION BY CARRYING OUT A PRE-LOAD MEASUREMENT OF THE ACCESSORY GEARBOX LINE 12 - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	H: 0.00					
SB BR700-72-900571 Engine 1 SB - N/A #3393	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSORVIGV AND STAGES 1 TO 4 STATOR VANES - REPLACEMENT OF UNWANTED PARTS TO RECTIFY THE ENGINE CONFIGURATION IN LINE WITH THE REQUIREMENTS OF SB SB-BR700-72-101901 - NON-MODIFICATION SERVICE BULLETIN, SERVICE B	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-900571 Engine 2 SB - N/A #3798	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSORVIGV AND STAGES 1 TO 4 STATOR VANES - REPLACEMENT OF UNWANTED PARTS TO RECTIFY THE ENGINE CONFIGURATION IN LINE WITH THE REQUIREMENTS OF SB SB-BR700-72-101901 - NON-MODIFICATION SERVICE BULLETIN, SERVICE B	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-900580 Engine 1 SB - N/A #3078	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE OIL FILLERASSEMBLY - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-900580 Engine 2 SB - N/A #3079	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE OIL FILLERASSEMBLY - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-72-900580 R1 Engine 1 SB - Open #4691	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE OIL FILLER ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN (REV. 1)						

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-900580 R1 Engine 2 SB - Open #4692	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE OIL FILLER ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN (REV. 1)						
SB BR700-72-900637 Engine 1 SB - Open #4806	NO. 1 ENGINE - INTERMEDIATE CASE MODULE - INSPECTION OF THE RETENTION BOLTS OF THE NO.2/NO.3 BEARING HOUSINGS TO THE INTERMEDIATE CASE - NON-MODIFICATION SERVICE BULLETIN (REV. 1)						
SB BR700-72-900637 Engine 2 SB - Open #4828	NO. 2 ENGINE - INTERMEDIATE CASE MODULE - INSPECTION OF THE RETENTION BOLTS OF THE NO.2/NO.3 BEARING HOUSINGS TO THE INTERMEDIATE CASE - NON-MODIFICATION SERVICE BULLETIN (REV. 1)						
SB BR700-72-900668 Engine 1 SB - Open #4837	ENGINE - LOW PRESSURE (LP) COMPRESSOR CASE - INSPECTION UNDER THE FAN TRACK LINER ON LP COMPRESSOR CASES OF PRE SB-BR700-72-100981 STANDARD - NON-MODIFICATION SERVICE BULLETIN						
SB BR700-72-900668 Engine 2 SB - Open #4859	ENGINE - LOW PRESSURE (LP) COMPRESSOR CASE - INSPECTION UNDER THE FAN TRACK LINER ON LP COMPRESSOR CASES OF PRE SB-BR700-72-100981 STANDARD - NON-MODIFICATION SERVICE BULLETIN						
SB BR700-72-A900497 R1 Engine 1 SB - Open #3298	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - DECREASE OF TIME LIMITS MANUAL MAXIMUM APPROVED LIVES OF THE HP TURBINE STAGE 1 AND STAGE 2 DISCS - NON-MODIFICATION, SERVICE BULLETIN					H: 0.00	
SB BR700-72-A900497 R1 Engine 2 SB - Open #3601	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - DECREASE OF TIME LIMITS MANUAL MAXIMUM APPROVED LIVES OF THE HP TURBINE STAGE 1 AND STAGE 2 DISCS - NON-MODIFICATION, SERVICE BULLETIN.					H: 0.00	
SB BR700-72-A900509 R5 Engine 1 SB - Open #5159	ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION SERVICE BULLETIN						
SB BR700-72-A900509 R5 Engine 2 SB - Open #5150	ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION SERVICE BULLETIN						



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-72-A900584 Engine 1 SB - Open #4787	NO. 1 ENGINE - GENERAL - ENGINE INSTALLATION RESTRICTION AND CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS						
SB BR700-72-A900584 Engine 2 SB - Open #4788	NO. 2 ENGINE - GENERAL - ENGINE INSTALLATION RESTRICTION AND CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS						
SB BR700-72-A900584 R1 Engine 1 SB - Open #4798	NO. 1 ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SERVICE BULLETIN (REV. 1)						
SB BR700-72-A900584 R1 Engine 2 SB - Open #4799	NO. 2 ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SERVICE BULLETIN (REV. 1)						
SB BR700-73-100827 R1 Engine 1 SB - Complied With #1293	NO. 1 ENGINE - FUEL FLOW TRANSMITTER- INTRODUCTION OF A NEW UNIT WITH A MORE ACCURATE CALIBRATION, SERVICE BULLETIN					15-JAN-2010 H: 0.00	
Notes COMPLIED WITH - AT MANUFACTURE							
SB BR700-73-100827 R1 Engine 2 SB - Complied With #1467	NO. 2 ENGINE - FUEL FLOW TRANSMITTER- INTRODUCTION OF A NEW UNIT WITH A MORE ACCURATE CALIBRATION, SERVICE BULLETIN					15-JAN-2010 H: 0.00	
Notes COMPLIED WITH - AT MANUFACTURE							
SB BR700-73-101106 Engine 1 SB - Superseded #4317	NO. 1 ENGINE - ENGINE AND FUEL CONTROL - FUEL METERING UNIT - INTRODUCTION OF NEW FUEL METERING UNIT WITH CHANGES TO COMBINED OVERSPEED AND SHUTOFF SOLENOID, THE PRESSURE RAISING VALVE AND ELECTRO HYDRAULIC SERVO VALVE, SERVICE BULLETIN					H: 0.00	
SB BR700-73-101106 Engine 2 SB - Superseded #4165	NO. 2 ENGINE - ENGINE AND FUEL CONTROL - FUEL METERING UNIT - INTRODUCTION OF NEW FUEL METERING UNIT WITH CHANGES TO COMBINED OVERSPEED AND SHUTOFF SOLENOID, THE PRESSURE RAISING VALVE AND ELECTRO HYDRAULIC SERVO VALVE, SERVICE BULLETIN					H: 0.00	

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-73-101106 R1 Engine 1 SB - Complied With #1979	NO. 1 ENGINE - ENGINE AND FUEL CONTROL - FUEL METERING UNIT - INTRODUCTION OF A NEW FUEL METERING UNIT WITH CHANGES TO THE COMBINED OVERSPEED AND SHUT-OFF SOLENOID, THE PRESSURE RAISING VALVE AND ELECTRO HYDRAULIC SERVO VALVE, SERVICE BULLETIN Notes COMPLIED WITH - AT MANUFACTURE	15-JAN-2010 H: 0.00					
SB BR700-73-101106 R1 Engine 2 SB - Complied With #2776	NO. 2 ENGINE - ENGINE AND FUEL CONTROL - FUEL METERING UNIT - INTRODUCTION OF A NEW FUEL METERING UNIT WITH CHANGES TO THE COMBINED OVERSPEED AND SHUT-OFF SOLENOID, THE PRESSURE RAISING VALVE AND ELECTRO HYDRAULIC SERVO VALVE, SERVICE BULLETIN Notes COMPLIED WITH - AT MANUFACTURE	15-JAN-2010 H: 0.00					
SB BR700-73-101145 R3 Engine 1 SB - Open #3767	NO. 1 ENGINE - ENGINE AND FUEL CONTROL-ENGINE ELECTRIC CONTROLLER-INTRODUCTION OF C6.0 SOFTWARE STANDARD INTO AN EEC WITH 05 OR05B HARDWARE, SERVICE BULLETIN	H: 0.00					
SB BR700-73-101145 R3 Engine 2 SB - Open #3096	NO. 2 ENGINE - ENGINE AND FUEL CONTROL-ENGINE ELECTRIC CONTROLLER-INTRODUCTION OF C6.0 SOFTWARE STANDARD INTO AN EEC WITH 05 OR05B HARDWARE, SERVICE BULLETIN	H: 0.00					
SB BR700-73-101367 Engine 1 SB - Open #4408	NO. 1 ENGINE - INTRODUCTION OF AN EEC WITH A NEW HARDWARE STANDARD (08), SERVICE BULLETIN	H: 0.00					
SB BR700-73-101367 Engine 2 SB - Open #4362	NO. 2 ENGINE - INTRODUCTION OF AN EEC WITH A NEW HARDWARE STANDARD (08), SERVICE BULLETIN	H: 0.00					
SB BR700-73-101472 Engine 1 SB - Superseded #3711	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER(EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C7.0.2, SERVICE BULLETIN	H: 0.00					
SB BR700-73-101472 Engine 2 SB - Superseded #3360	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER(EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C7.0.2, SERVICE BULLETIN	H: 0.00					

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-73-101472 R1 Engine 1 SB - Complied With #775	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER(EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C7.0.2, SERVICE BULLETIN.	15-JAN-2010 H: 0.00					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB BR700-73-101472 R1 Engine 2 SB - Complied With #2203	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER(EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C7.0.2, SERVICE BULLETIN.	15-JAN-2010 H: 0.00					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB BR700-73-101504 Engine 1 SB - Open #4320	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER(EEC) - INTRODUCTION OF A NEW STANDARD OF EEC HARDWARE AND SOFTWARE, SERVICE BULLETIN	H: 0.00					
SB BR700-73-101504 Engine 2 SB - Open #3545	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER(EEC) - INTRODUCTION OF A NEW STANDARD OF EEC HARDWARE AND SOFTWARE, SERVICE BULLETIN	H: 0.00					
SB BR700-73-101504 R1 Engine 1 SB - Open #4792	NO. 1 ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW STANDARD OF EEC HARDWARE AND SOFTWARE (REV. 1)						
SB BR700-73-101504 R1 Engine 2 SB - Open #4793	NO. 2 ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW STANDARD OF EEC HARDWARE AND SOFTWARE (REV. 1)						
SB BR700-73-101509 Engine 1 SB - Open #4061	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER(EEC) - INTRODUCTION OF AN EEC WITH PRINTED CIRCUIT BOARDS FROM A NEW SOURCE, SERVICE BULLETIN	H: 0.00					
SB BR700-73-101509 Engine 2 SB - Open #3380	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER(EEC) - INTRODUCTION OF AN EEC WITH PRINTED CIRCUIT BOARDS FROM A NEW SOURCE, SERVICE BULLETIN	H: 0.00					

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-73-101547 Engine 1 SB - Open #3746	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - DATA ENTRY PLUG (DEP) - INTRODUCTION OF A DEP WITH THE APPLICABLE IDENTIFICATION SLEEVE, SERVICE BULLETIN	H: 0.00					
SB BR700-73-101547 Engine 2 SB - Open #4112	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - DATA ENTRY PLUG (DEP) - INTRODUCTION OF A DEP WITH THE APPLICABLE IDENTIFICATION SLEEVE, SERVICE BULLETIN	H: 0.00					
SB BR700-73-101558 R1 Engine 1 SB - Open #3654	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW TRANSMITTER(FFT) - INTRODUCTION OF A NEW FFT WITH IMPROVED ACCURACY LIMITS, SERVICE BULLETIN	H: 0.00					
SB BR700-73-101558 R1 Engine 2 SB - Open #3805	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW TRANSMITTER(FFT) - INTRODUCTION OF A NEW FFT WITH IMPROVED ACCURACY LIMITS, SERVICE BULLETIN	H: 0.00					
SB BR700-73-101559 Engine 1 SB - Open #3700	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIRTUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN	H: 0.00					
SB BR700-73-101559 Engine 2 SB - Open #4432	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIRTUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN	H: 0.00					
SB BR700-73-101559 R1 Engine 1 SB - Open #3197	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIRTUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN.	H: 0.00					
SB BR700-73-101559 R1 Engine 2 SB - Open #4148	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIRTUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN.	H: 0.00					
SB BR700-73-101559 R2 Engine 1 SB - Open #4794	NO. 1 ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC) (REV. 2)						



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-73-101559 R2 Engine 2 SB - Open #4795	NO. 2 ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC) (REV. 2)						
SB BR700-73-101617 R1 Engine 1 SB - Open #4388	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW TRANSMITTER(FFT) - INTRODUCTION OF A FFT WITH A NEW CALIBRATION, SERVICE BULLETIN	H: 0.00					
SB BR700-73-101617 R1 Engine 2 SB - Open #4372	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW TRANSMITTER(FFT) - INTRODUCTION OF A FFT WITH A NEW CALIBRATION, SERVICE BULLETIN	H: 0.00					
SB BR700-73-101628 Engine 1 SB - Open #4172	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER(EEC) - INTRODUCTION OF AN EEC WITH X1.1 SOFTWARE STANDARD, SERVICE BULLETIN	H: 0.00					
SB BR700-73-101628 Engine 2 SB - Open #3741	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER(EEC) - INTRODUCTION OF AN EEC WITH X1.1 SOFTWARE STANDARD, SERVICE BULLETIN	H: 0.00					
SB BR700-73-101628 R1 Engine 1 SB - Complied With #1786	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER(EEC) - INTRODUCTION OF AN EEC WITH X1.1 SOFTWARE STANDARD, SERVICE BULLETIN.	15-JAN-2010 H: 0.00					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB BR700-73-101628 R1 Engine 2 SB - Complied With #1502	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER(EEC) - INTRODUCTION OF AN EEC WITH X1.1 SOFTWARE STANDARD, SERVICE BULLETIN.	15-JAN-2010 H: 0.00					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB BR700-73-101634 Engine 1 SB - N/A #4312	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIRTUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN..	H: 0.00					
	Notes NOT APPLICABLE						





Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-73-101634 Engine 2 SB - N/A #3537	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIRTUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN..	H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-73-101634 R1 Engine 1 SB - Open #4793	NO. 1 ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC) (REV. 1)						
SB BR700-73-101634 R1 Engine 2 SB - Open #4794	NO. 2 ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC) (REV. 1)						
SB BR700-73-101761 Engine 1 SB - Open #3419	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROLLER(EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C8.0, SERVICE BULLETIN	H: 0.00					
SB BR700-73-101761 Engine 2 SB - Open #3106	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROLLER(EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C8.0, SERVICE BULLETIN	H: 0.00					
SB BR700-73-101761 R1 Engine 1 SB - Open #4786	NO. 1 ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C8.0 (REV. 1)						
SB BR700-73-101761 R1 Engine 2 SB - Open #4787	NO. 2 ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C8.0 (REV. 1)						
SB BR700-73-101806 Engine 1 SB - Open #3635	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER(EEC) - INTRODUCTION OF X1.2 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01, SERVICE BULLETIN	H: 0.00					
SB BR700-73-101806 Engine 2 SB - Open #3509	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER(EEC) - INTRODUCTION OF X1.2 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01, SERVICE BULLETIN	H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-73-101806 R1 Engine 1 SB - Open #3334	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER(EEC) - INTRODUCTION OF X1.2 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01, SERVICE BULLETIN.	H: 0.00					
SB BR700-73-101806 R1 Engine 2 SB - Open #3534	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER(EEC) - INTRODUCTION OF X1.2 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01, SERVICE BULLETIN.	H: 0.00					
SB BR700-73-101815 Engine 1 SB - Open #4026	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER(EEC) - INTRODUCTION OF MODIFIED EEC IDENTIFICATION LABELS, SERVICE BULLETIN	H: 0.00					
SB BR700-73-101815 Engine 2 SB - Open #3476	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER(EEC) - INTRODUCTION OF MODIFIED EEC IDENTIFICATION LABELS, SERVICE BULLETIN	H: 0.00					
SB BR700-73-101833 R2 Engine 1 SB - Open #3844	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL PUMP - INTRODUCTION OF A REVISED DRIVE SHAFT CONNECTION FOR THE FUEL PUMP, SERVICE BULLETIN	H: 0.00					
SB BR700-73-101833 R2 Engine 2 SB - Open #3948	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL PUMP - INTRODUCTION OF A REVISED DRIVE SHAFT CONNECTION FOR THE FUEL PUMP, SERVICE BULLETIN	H: 0.00					
SB BR700-73-101833 R3 Engine 1 SB - Open #4859	ENGINE FUEL AND CONTROL - FUEL PUMP - INTRODUCTION OF A REVISED DRIVE SHAFT CONNECTION FOR THE FUEL PUMP						
SB BR700-73-101833 R3 Engine 2 SB - Open #5147	ENGINE FUEL AND CONTROL - FUEL PUMP - INTRODUCTION OF A REVISED DRIVE SHAFT CONNECTION FOR THE FUEL PUMP						
SB BR700-73-101856 Engine 1 SB - Superseded #3848	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - DEDICATED GENERATOR- INTRODUCTION OF A NEW VARNISH FOR THE WINDINGS OF THE PERMANENT MAGNETIC ALTERNATOR (PMA), SERVICE BULLETIN	H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-73-101856 Engine 2 SB - Superseded #3891	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - DEDICATED GENERATOR- INTRODUCTION OF A NEW VARNISH FOR THE WINDINGS OF THE PERMANENT MAGNETIC ALTERNATOR (PMA), SERVICE BULLETIN	H: 0.00					
SB BR700-73-101856 R1 Engine 1 SB - Superseded #4391	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - DEDICATED GENERATOR- INTRODUCTION OF A NEW VARNISH FOR THE WINDINGS OF THE PERMANENT MAGNETIC ALTERNATOR (PMA), SERVICE BULLETIN.	H: 0.00					
SB BR700-73-101856 R1 Engine 1 SB - Superseded #4772	NO. 1 ENGINE - FUEL AND CONTROL - DEDICATED GENERATOR - INTRODUCTION OF A NEW VARNISH FOR THE WINDINGS OF THE PERMANENT MAGNETIC ALTERNATOR (PMA) (REV. 1)						
SB BR700-73-101856 R2 Engine 2 SB - Open #3976	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - DEDICATED GENERATOR- INTRODUCTION OF A NEW VARNISH FOR THE WINDINGS OF THE PERMANENT MAGNETIC ALTERNATOR (PMA), SERVICE BULLETIN.	H: 0.00					
SB BR700-73-101856 R2 Engine 2 SB - Open #4773	NO. 2 ENGINE - FUEL AND CONTROL - DEDICATED GENERATOR - INTRODUCTION OF A NEW VARNISH FOR THE WINDINGS OF THE PERMANENT MAGNETIC ALTERNATOR (PMA) (REV. 1)						
SB BR700-73-101865 Engine 1 SB - Open #3574	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL RETURN TO TANK VALVE (FRTV) - CORRECTION OF PART NUMBERS FOREXTERNAL REPLACEABLE PARTS OF THE FRTV, SERVICE BULLETIN	H: 0.00					
SB BR700-73-101865 Engine 2 SB - Open #3880	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL RETURN TO TANK VALVE (FRTV) - CORRECTION OF PART NUMBERS FOREXTERNAL REPLACEABLE PARTS OF THE FRTV, SERVICE BULLETIN	H: 0.00					
SB BR700-73-101966 R1 Engine 1 SB - Complied With #4768	NO. 1 ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF X2.0 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01 (REV. 1)	23-NOV-2016 H: 2064.80 C: 722					
SB BR700-73-101966 R1 Engine 2 SB - Complied With #4769	NO. 2 ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF X2.0 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01 (REV. 1)	23-NOV-2016 H: 2064.80 C: 722					

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-73-101966 R2 Engine 1 SB - Open #4784	NO. 1 ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF X2.0 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01 (REV. 2)						
SB BR700-73-101966 R2 Engine 2 SB - Open #4785	NO. 2 ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF X2.0 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01 (REV. 2)						
SB BR700-73-900087 Engine 1 SB - Superseded #4277	NO. 1 ENGINE - INTRODUCTION OF THE PROCEDURE FOR IDENTIFYING CORRECTLY CALIBRATED FUEL FLOW TRANSMITTERS, SERVICE BULLETIN	H: 0.00					
SB BR700-73-900087 Engine 2 SB - Superseded #4381	NO. 2 ENGINE - INTRODUCTION OF THE PROCEDURE FOR IDENTIFYING CORRECTLY CALIBRATED FUEL FLOW TRANSMITTERS, SERVICE BULLETIN	H: 0.00					
SB BR700-73-900087 R5 Engine 1 SB - Open #3857	NO. 1 ENGINE - INTRODUCTION OF THE PROCEDURE FOR IDENTIFYING CORRECTLY CALIBRATED FUEL FLOW TRANSMITTERS, SERVICE BULLETIN.	H: 0.00					
SB BR700-73-900087 R5 Engine 2 SB - Open #3050	NO. 2 ENGINE - INTRODUCTION OF THE PROCEDURE FOR IDENTIFYING CORRECTLY CALIBRATED FUEL FLOW TRANSMITTERS, SERVICE BULLETIN.	H: 0.00					
SB BR700-73-900252 Engine 1 SB - Open #3845	NO. 1 ENGINE - ENGINE AND FUEL CONTROL-AMPLITUDE MEASUREMENT OF ARINC WAVEFORM, RECOMMENDED	H: 0.00					
SB BR700-73-900252 Engine 2 SB - Open #3927	NO. 2 ENGINE - ENGINE AND FUEL CONTROL-AMPLITUDE MEASUREMENT OF ARINC WAVEFORM, RECOMMENDED	H: 0.00					
SB BR700-73-900270 Engine 1 SB - Superseded #4256	NO. 1 ENGINE - INSPECTION OF LOW PRESSURE (LP) FUEL TUBE FOR DAMAGE, SERVICE BULLETIN	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-73-900270 Engine 2 SB - Superseded #3269	NO. 2 ENGINE - INSPECTION OF LOW PRESSURE (LP) FUEL TUBE FORDAMAGE, SERVICE BULLETIN	H: 0.00					
SB BR700-73-900270 R1 Engine 1 SB - Open #3914	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INSPECTION OF THE LOW PRESSURE (LP) FUEL TUBE FORDAMAGE, SERVICE BULLETIN	H: 0.00					
SB BR700-73-900270 R1 Engine 2 SB - Open #4438	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INSPECTION OF THE LOW PRESSURE (LP) FUEL TUBE FORDAMAGE, SERVICE BULLETIN	H: 0.00					
SB BR700-73-900301 R1 Engine 1 SB - Open #4297	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL METERING UNIT (FMU) - REMOVAL/INSTALLATION OF FUEL METERING UNIT TO INSPECT COILS FORQUALITY DEFECT, SERVICE BULLETIN	H: 0.00					
SB BR700-73-900301 R1 Engine 2 SB - Open #4340	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL METERING UNIT (FMU) - REMOVAL/INSTALLATION OF FUEL METERING UNIT TO INSPECT COILS FORQUALITY DEFECT, SERVICE BULLETIN	H: 0.00					
SB BR700-73-900423 Engine 1 SB - Complied With #265	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER(EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	12-OCT-2014 H: 1015.50 C: 386					
	Notes COMPLIED WITH - REMOVED EEC FIREBOX BASE, COVERLEFT SHIELD AND RIGHT SHIELD. INSTALLED NEW EEC FIREBOX BASE, COVER, LEFT SHIELD AND RIGHT SHIELD.						
SB BR700-73-900423 Engine 2 SB - Complied With #1130	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER(EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	12-OCT-2014 H: 1015.50 C: 386					
	Notes COMPLIED WITH - REMOVED EEC FIREBOX BASE, COVERLEFT SHIELD AND RIGHT SHIELD. INSTALLED NEW EEC FIREBOX BASE, COVER, LEFT SHIELD AND RIGHT SHIELD.						
SB BR700-73-900423 R1 Engine 1 SB - Superseded #4406	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER(EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-73-900423 R1 Engine 2 SB - Superseded #4538	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER(EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	H: 0.00					
SB BR700-73-900423 R2 Engine 1 SB - Complied With #1382	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER(EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN.	13-MAR-2015 H: 0.00					
	Notes COMPLIED WITH - PCW BASIC ISSUE						
SB BR700-73-900423 R2 Engine 2 SB - Complied With #2693	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER(EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN.	13-MAR-2015 H: 0.00					
	Notes COMPLIED WITH - PCW BASIC ISSUE						
SB BR700-73-900423 R3 Engine 1 SB - Complied With #4785	NO. 1 ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN (REV. 3)	01-AUG-2013 H: 432.80 C: 211					
SB BR700-73-900423 R3 Engine 2 SB - Complied With #4786	NO. 2 ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN (REV. 3)	01-AUG-2013 H: 432.80 C: 211					
SB BR700-73-900423 R4 Engine 1 SB - Open #4853	ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN						
SB BR700-73-900423 R4 Engine 2 SB - Open #4875	ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN						
SB BR700-73-900463 Engine 1 SB - Open #3610	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER(EEC) - REMOVAL OF THE EEC FOR C15 CAPACITOR REPLACEMENT, SERVICE BULLETIN	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-73-900463 Engine 2 SB - Open #3174	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER(EEC) - REMOVAL OF THE EEC FOR C15 CAPACITOR REPLACEMENT, SERVICE BULLETIN	H: 0.00					
SB BR700-73-900494 Engine 1 SB - N/A #2650	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FULL AUTHORITY DIGITAL ENGINE CONTROL (FADEC) SYSTEM - INTERROGATION OF THE CENTRAL AIRCRAFT INFORMATION MAINTENANCE SYSTEM (CAIMS) FORFADEC SYSTEM FAULTS, SERVICE BULLETIN	25-MAR-2011 H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-73-900494 Engine 2 SB - N/A #1792	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FULL AUTHORITY DIGITAL ENGINE CONTROL (FADEC) SYSTEM - INTERROGATION OF THE CENTRAL AIRCRAFT INFORMATION MAINTENANCE SYSTEM (CAIMS) FORFADEC SYSTEM FAULTS, SERVICE BULLETIN	25-MAR-2011 H: 0.00					
	Notes NOT APPLICABLE						
SB BR700-73-900494 R1 Engine 1 SB - Open #1708	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FULL AUTHORITY DIGITAL ENGINE CONTROL (FADEC) SYSTEM - INTERROGATION OF THE CENTRAL AIRCRAFT INFORMATION MAINTENANCE SYSTEM (CAIMS) FORFADEC SYSTEM FAULTS, SERVICE BULLETIN.	25-MAR-2011 H: 0.00					
	Notes --						
SB BR700-73-900494 R1 Engine 2 SB - Open #2533	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FULL AUTHORITY DIGITAL ENGINE CONTROL (FADEC) SYSTEM - INTERROGATION OF THE CENTRAL AIRCRAFT INFORMATION MAINTENANCE SYSTEM (CAIMS) FORFADEC SYSTEM FAULTS, SERVICE BULLETIN.	25-MAR-2011 H: 0.00					
	Notes --						
SB BR700-73-900539 Engine 1 SB - Open #4433	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - HIGH PRESSURE (HP) FUEL FILTERASSEMBLY - INSPECTION OF THE HP FUEL FILTER HOUSING CAP FOR CORRECT INSTALLATION OF ITS SEAL RING AND BACKUP RING - NON-MODIFICATION, SERVICE BULLETIN	H: 0.00					
SB BR700-73-900539 Engine 2 SB - Open #3529	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - HIGH PRESSURE (HP) FUEL FILTERASSEMBLY - INSPECTION OF THE HP FUEL FILTER HOUSING CAP FOR CORRECT INSTALLATION OF ITS SEAL RING AND BACKUP RING - NON-MODIFICATION, SERVICE BULLETIN	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-73-900539 R1 Engine 1 SB - Open #4310	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - HIGH PRESSURE (HP) FUEL FILTERASSEMBLY - INSPECTION OF THE HP FUEL FILTER HOUSING CAP FOR CORRECT INSTALLATION OF ITS SEAL RING AND BACKUP RING - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	H: 0.00					
SB BR700-73-900539 R1 Engine 2 SB - Open #4363	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - HIGH PRESSURE (HP) FUEL FILTERASSEMBLY - INSPECTION OF THE HP FUEL FILTER HOUSING CAP FOR CORRECT INSTALLATION OF ITS SEAL RING AND BACKUP RING - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	H: 0.00					
SB BR700-73-A101977 R2 Engine 1 SB - Open #4790	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW EEC FIREBOX ASSEMBLY WITH A REVISED PAINT SYSTEM (REV. 2)						
SB BR700-73-A101977 R2 Engine 2 SB - Open #4791	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW EEC FIREBOX ASSEMBLY WITH A REVISED PAINT SYSTEM (REV. 2)						
SB BR700-73-A101977 R3 Engine 2 SB - Complied With #4796	NO. 2 ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW EEC FIREBOX ASSEMBLY WITH A REVISED PAINT SYSTEM (REV. 3)	28-JAN-2018					H: 2586.20 C: 898
SB BR700-73-A101977 R3 Engine 1 SB - Complied With #4795	NO. 1 ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW EEC FIREBOX ASSEMBLY WITH A REVISED PAINT SYSTEM (REV. 3)	28-JAN-2018					H: 2586.20 C: 898
SB BR700-73-A101977 R4 Engine 1 SB - Open #4839	ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW EEC FIREBOX ASSEMBLY WITH A REVISED PAINT SYSTEM						
SB BR700-73-A101977 R4 Engine 2 SB - Open #4861	ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW EEC FIREBOX ASSEMBLY WITH A REVISED PAINT SYSTEM						
SB BR700-73-A101977 R5 Engine 1 SB - Open #4852	ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW EEC FIREBOX ASSEMBLY WITH A REVISED PAINT SYSTEM						





Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-73-A101977 R5 Engine 2 SB - Open #4874	ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW EEC FIREBOX ASSEMBLY WITH A REVISED PAINT SYSTEM						
SB BR700-74-102193 R2 Engine 1 SB - Complied With #4850	IGNITION - IGNITER PLUG - INTRODUCTION OF A NEW IGNITER PLUG MANUFACTURED BY A DIFFERENT SUPPLIER	09-APR-2021					
SB BR700-74-102193 R2 Engine 2 SB - Complied With #4872	IGNITION - IGNITER PLUG - INTRODUCTION OF A NEW IGNITER PLUG MANUFACTURED BY A DIFFERENT SUPPLIER	09-APR-2021					
SB BR700-75-101130 Engine 1 SB - Superseded #3292	NO. 1 ENGINE - AIRBLEED VALVES-INTRODUCTION OF NEW IIP 8 HANDLING BLEED VALVE INNER AND OUTER ATTENUATORS TO PREVENT DAMAGE TO BYPASS DUCT, SERVICE BULLETIN	H: 0.00					
SB BR700-75-101130 Engine 2 SB - Superseded #4254	NO. 2 ENGINE - AIRBLEED VALVES-INTRODUCTION OF NEW IIP 8 HANDLING BLEED VALVE INNER AND OUTER ATTENUATORS TO PREVENT DAMAGE TO BYPASS DUCT, SERVICE BULLETIN	H: 0.00					
SB BR700-75-101130 R1 Engine 1 SB - Open #4188	NO. 1 ENGINE - AIR- BLEED VALVES - INTRODUCTION OF NEW HP 8 HANDLING BLEED VALVE INNER AND OUTER ATTENUATORS TO PREVENT DAMAGE TO BYPASS DUCT, SERVICE BULLETIN	H: 0.00					
SB BR700-75-101130 R1 Engine 2 SB - Open #4455	NO. 2 ENGINE - AIR- BLEED VALVES - INTRODUCTION OF NEW HP 8 HANDLING BLEED VALVE INNER AND OUTER ATTENUATORS TO PREVENT DAMAGE TO BYPASS DUCT, SERVICE BULLETIN	H: 0.00					
SB BR700-75-101161 R1 Engine 1 SB - Complied With #2911	NO. 1 ENGINE - AIRBLEED VALVE SOLENOID CONTROL BLOCK-INTRODUCTION OF HANDLING BLEED VALVE SOLENOID WITH SOLENOID SERVO VALVES WHICH OPERATE AT LOWER CURRENT FLOWS, SERVICE BULLETIN	15-JAN-2010					
	Notes COMPLIED WITH - AT MANUFACTURE						





Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-75-101161 R1 Engine 2 SB - Complied With #1199	NO. 2 ENGINE - AIRBLEED VALVE SOLENOID CONTROL BLOCK-INTRODUCTION OF HANDLING BLEED VALVE SOLENOID WITH SOLENOID SERVO VALVES WHICH OPERATE AT LOWER CURRENT FLOWS, SERVICE BULLETIN	15-JAN-2010 H: 0.00					
Notes COMPLIED WITH - AT MANUFACTURE							
SB BR700-75-101161 R2 Engine 1 SB - Open #4799	NO. 1 ENGINE - AIR - BLEED VALVE SOLENOID CONTROL BLOCK - INTRODUCTION OF A HANDLING BLEED VALVE SOLENOID WITH SOLENOID SERVO VALVES WHICH OPERATE AT LOWER CURRENT FLOWS (REV. 2)						
SB BR700-75-101161 R2 Engine 2 SB - Open #4800	NO. 2 ENGINE - AIR - BLEED VALVE SOLENOID CONTROL BLOCK - INTRODUCTION OF A HANDLING BLEED VALVE SOLENOID WITH SOLENOID SERVO VALVES WHICH OPERATE AT LOWER CURRENT FLOWS (REV. 2)						
SB BR700-75-101161 R3 Engine 1 SB - Open #4813	NO. 1 ENGINE - AIR - BLEED VALVE SOLENOID CONTROL BLOCK - INTRODUCTION OF A HANDLING BLEED VALVE SOLENOID WITH SOLENOID SERVO VALVES WHICH OPERATE AT LOWER CURRENT FLOWS (REV. 3)						
SB BR700-75-101161 R3 Engine 2 SB - Open #4835	NO. 2 ENGINE - AIR - BLEED VALVE SOLENOID CONTROL BLOCK - INTRODUCTION OF A HANDLING BLEED VALVE SOLENOID WITH SOLENOID SERVO VALVES WHICH OPERATE AT LOWER CURRENT FLOWS (REV. 3)						
SB BR700-75-101381 R1 Engine 1 SB - Open #4817	AIR - BLEED VALVES - INTRODUCTION OF NEW TRIPLE SEALS AND A CARBON BUSH TO REPLACE THE EXISTING STEEL COMPONENTS						
SB BR700-75-101381 R1 Engine 2 SB - Open #4839	AIR - BLEED VALVES - INTRODUCTION OF NEW TRIPLE SEALS AND A CARBON BUSH TO REPLACE THE EXISTING STEEL COMPONENTS						
SB BR700-75-101447 R1 Engine 1 SB - Open #4558	NO. 1 ENGINE - AIR- VSV ACTUATOR - INTRODUCTION OF A MODIFIED VARIABLE STATOR VANE (VSV) ACTUATOR, SERVICE BULLETIN	H: 0.00					

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-75-101447 R1 Engine 2 SB - Open #3384	NO. 2 ENGINE - AIR- VSV ACTUATOR - INTRODUCTION OF A MODIFIED VARIABLE STATOR VANE (VSV) ACTUATOR, SERVICE BULLETIN	H: 0.00					
SB BR700-75-101447 R2 Engine 1 SB - Open #3971	NO. 1 ENGINE - AIR- VSV ACTUATOR - INTRODUCTION OF A MODIFIED VARIABLE STATOR VANE (VSV) ACTUATOR, SERVICE BULLETIN.	H: 0.00					
SB BR700-75-101447 R2 Engine 2 SB - Open #3438	NO. 2 ENGINE - AIR- VSV ACTUATOR - INTRODUCTION OF A MODIFIED VARIABLE STATOR VANE (VSV) ACTUATOR, SERVICE BULLETIN.	H: 0.00					
SB BR700-75-101694 Engine 1 SB - Open #4332	NO. 1 ENGINE - AIR- AIR BLEED CONTROL SOLENOID - INTRODUCTION OF WASHERS WITH A SMALLER OUTER DIAMETER FOR THE INSTALLATION OF THE HANDLING BLEED VALVE SOLENOID CONTROL BLOCK, SERVICE BULLETIN	H: 0.00					
SB BR700-75-101694 Engine 2 SB - Open #4519	NO. 2 ENGINE - AIR- AIR BLEED CONTROL SOLENOID - INTRODUCTION OF WASHERS WITH A SMALLER OUTER DIAMETER FOR THE INSTALLATION OF THE HANDLING BLEED VALVE SOLENOID CONTROL BLOCK, SERVICE BULLETIN	H: 0.00					
SB BR700-75-900308 Engine 1 SB - Superseded #3912	NO. 1 ENGINE - AIR- VARIABLE STATOR VANE (VSV) MECHANISM LUBRICATION, SERVICE BULLETIN	H: 0.00					
SB BR700-75-900308 Engine 2 SB - Superseded #4033	NO. 2 ENGINE - AIR- VARIABLE STATOR VANE (VSV) MECHANISM LUBRICATION, SERVICE BULLETIN	H: 0.00					
SB BR700-75-900308 R1 Engine 1 SB - Superseded #4509	NO. 1 ENGINE - AIR- VARIABLE STATOR VANE (VSV) MECHANISM LUBRICATION NON-MODIFICATION SB-BR700-75-900308, SERVICE BULLETIN	H: 0.00					
SB BR700-75-900308 R1 Engine 2 SB - Superseded #3725	NO. 2 ENGINE - AIR- VARIABLE STATOR VANE (VSV) MECHANISM LUBRICATION NON-MODIFICATION SB-BR700-75-900308, SERVICE BULLETIN	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-75-900308 R2 Engine 1 SB - Open #3060	NO. 1 ENGINE - AIR- VARIABLE STATOR VANE (VSV) MECHANISM LUBRICATION NON-MODIFICATION SB-BR700-75-900308, SERVICE BULLETIN.	H: 0.00					
SB BR700-75-900308 R2 Engine 2 SB - Open #4128	NO. 2 ENGINE - AIR- VARIABLE STATOR VANE (VSV) MECHANISM LUBRICATION NON-MODIFICATION SB-BR700-75-900308, SERVICE BULLETIN.	H: 0.00					
SB BR700-75-900308 R3 Engine 1 SB - Open #3781	NO. 1 ENGINE - AIR- VARIABLE STATOR VANE (VSV) MECHANISM LUBRICATION, SERVICE BULLETIN.	H: 0.00					
SB BR700-75-900308 R3 Engine 2 SB - Open #4399	NO. 2 ENGINE - AIR- VARIABLE STATOR VANE (VSV) MECHANISM LUBRICATION, SERVICE BULLETIN.	H: 0.00					
SB BR700-75-900311 R1 Engine 1 SB - Open #4761	NO. 1 ENGINE - AIR - VARIABLE STATOR VANE (VSV) MECHANISM TORQUE CHECK - NON-MODIFICATION SERVICE BULLETIN (REV. 1)						
SB BR700-75-900311 R1 Engine 2 SB - Open #4762	NO. 2 ENGINE - AIR - VARIABLE STATOR VANE (VSV) MECHANISM TORQUE CHECK - NON-MODIFICATION SERVICE BULLETIN (REV. 1)						
SB BR700-75-900633 Engine 1 SB - Open #4810	NO. 1 ENGINE - AIR - VSV ACTUATOR - REPLACEMENT OF LUCAS VARIABLE STATOR VANE (VSV) ACTUATORS						
SB BR700-75-900633 Engine 2 SB - Open #4832	NO. 2 ENGINE - AIR - VSV ACTUATOR - REPLACEMENT OF LUCAS VARIABLE STATOR VANE (VSV) ACTUATORS						
SB BR700-77-101534 Engine 1 SB - Open #4337	NO. 1 ENGINE - ENGINE INDICATING - TURBINE GAS TEMPERATURE (TGT) THERMOCOUPLE - INTRODUCTION OF NEW TGT PROBES, SERVICE BULLETIN	H: 0.00					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-77-101534 Engine 2 SB - Open #4464	NO. 2 ENGINE - ENGINE INDICATING - TURBINE GAS TEMPERATURE (TGT) THERMOCOUPLE - INTRODUCTION OF NEW TGT PROBES, SERVICE BULLETIN	H: 0.00					
SB BR700-77-101544 Engine 1 SB - Open #3177	NO. 1 ENGINE - ENGINE INDICATING - VIBRATION TRANSDUCER AND CABLE - INTRODUCTION OF A NEW ENGINE VIBRATION MONITORING SYSTEM (EVMS) ACCELEROMETER, SERVICE BULLETIN	H: 0.00					
SB BR700-77-101544 Engine 2 SB - Open #4007	NO. 2 ENGINE - ENGINE INDICATING - VIBRATION TRANSDUCER AND CABLE - INTRODUCTION OF A NEW ENGINE VIBRATION MONITORING SYSTEM (EVMS) ACCELEROMETER, SERVICE BULLETIN	H: 0.00					
SB BR700-77-101553 Engine 1 SB - Open #3546	NO. 1 ENGINE - ENGINE INDICATING - VIBRATION TRANSDUCER AND CABLE - INTRODUCTION OF A NEW ENGINE VIBRATION MONITORING SYSTEM (EVMS) CABLE ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-77-101553 Engine 2 SB - Open #3555	NO. 2 ENGINE - ENGINE INDICATING - VIBRATION TRANSDUCER AND CABLE - INTRODUCTION OF A NEW ENGINE VIBRATION MONITORING SYSTEM (EVMS) CABLE ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-77-101560 Engine 1 SB - Open #3392	NO. 1 ENGINE - INTRODUCTION OF AN ENGINE VIBRATION MONITORING UNIT, SERVICE BULLETIN	H: 0.00					
SB BR700-77-101560 Engine 2 SB - Open #3968	NO. 2 ENGINE - INTRODUCTION OF AN ENGINE VIBRATION MONITORING UNIT, SERVICE BULLETIN	H: 0.00					
SB BR700-77-101875 Engine 1 SB - Open #4089	NO. 1 ENGINE - ENGINE INDICATING - N2 SPEED PROBES - INTRODUCTION OF NEW ATTACHING BOLTS WITH SHORTER LENGTH, SERVICE BULLETIN	H: 0.00					
SB BR700-77-101875 Engine 2 SB - Open #3349	NO. 2 ENGINE - ENGINE INDICATING - N2 SPEED PROBES - INTRODUCTION OF NEW ATTACHING BOLTS WITH SHORTER LENGTH, SERVICE BULLETIN	H: 0.00					
SB BR700-77-101875 R1 Engine 1 SB - Open #3367	NO. 1 ENGINE - ENGINE INDICATING - N2 SPEED PROBES - INTRODUCTION OF NEW ATTACHING BOLTS WITH SHORTER LENGTH, SERVICE BULLETIN.	H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-77-101875 R1 Engine 2 SB - Open #3272	NO. 2 ENGINE - ENGINE INDICATING - N2 SPEED PROBES - INTRODUCTION OF NEW ATTACHING BOLTS WITH SHORTERLENGTH, SERVICE BULLETIN.	H: 0.00					
SB BR700-77-900251 R1 Engine 1 SB - Open #3131	NO. 1 ENGINE - ENGINE INDICATING - TGT THERMOCOUPLE PROBES - ELECTRICAL RESISTANCE CHECK OF THE TGT THERMOCOUPLE PROBES, SERVICE BULLETIN	H: 0.00					
SB BR700-77-900251 R1 Engine 2 SB - Open #4289	NO. 2 ENGINE - ENGINE INDICATING - TGT THERMOCOUPLE PROBES - ELECTRICAL RESISTANCE CHECK OF THE TGT THERMOCOUPLE PROBES, SERVICE BULLETIN	H: 0.00					
SB BR700-77-900329 Engine 1 SB - Superseded #3221	NO. 1 ENGINE - ENGINE INDICATING - N2 SPEED PROBES - INSULATION RESISTANCE TEST ON N2 SPEED PROBES FORPOTENTIAL ELECTRICAL DEFECTS, SERVICE BULLETIN	H: 0.00					
SB BR700-77-900329 Engine 2 SB - Superseded #3417	NO. 2 ENGINE - ENGINE INDICATING - N2 SPEED PROBES - INSULATION RESISTANCE TEST ON N2 SPEED PROBES FORPOTENTIAL ELECTRICAL DEFECTS, SERVICE BULLETIN	H: 0.00					
SB BR700-77-900329 R1 Engine 1 SB - Complied With #2877	NO. 1 ENGINE - ENGINE INDICATING - N2 SPEED PROBES - INSULATION RESISTANCE TEST ON N2 SPEED PROBES FORPOTENTIAL ELECTRICAL DEFECTS, SERVICE BULLETIN.	06-OCT-2014 H: 1015.50 C: 386					
	Notes COMPLIED WITH						
SB BR700-77-900329 R1 Engine 2 SB - Complied With #2798	NO. 2 ENGINE - ENGINE INDICATING - N2 SPEED PROBES - INSULATION RESISTANCE TEST ON N2 SPEED PROBES FORPOTENTIAL ELECTRICAL DEFECTS, SERVICE BULLETIN.	06-OCT-2014 H: 1015.50 C: 386					
	Notes COMPLIED WITH						
SB BR700-78-100783 R6 Engine 1 SB - Open #4797	NO. 1 ENGINE - EXHAUST - LEFT AND RIGHT ENGINE THRUST REVERSER - MATERIAL CHANGE OF THE PIVOTING DOOR SEAL DEPRESSOR AND CARRIER SEGMENTS (REV. 6)						

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-78-100783 R6 Engine 2 SB - Open #4798	NO. 2 ENGINE - EXHAUST - LEFT AND RIGHT ENGINE THRUST REVERSER - MATERIAL CHANGE OF THE PIVOTING DOOR SEAL DEPRESSOR AND CARRIER SEGMENTS (REV. 6)						
SB BR700-78-101529 Engine 1 SB - Open #3400	NO. 1 ENGINE - EXHAUST - PRIMARY LOCK ACTUATOR AND MECHANISM - INTRODUCTION OF A NEW PRIMARY DOOR LOCK ACTUATOR (PDLA) SB-BR700-78-101529, SERVICE BULLETIN	H: 0.00					
SB BR700-78-101529 Engine 2 SB - Open #3233	NO. 2 ENGINE - EXHAUST - PRIMARY LOCK ACTUATOR AND MECHANISM - INTRODUCTION OF A NEW PRIMARY DOOR LOCK ACTUATOR (PDLA) SB-BR700-78-101529, SERVICE BULLETIN	H: 0.00					
SB BR700-78-101607 Engine 1 SB - Complied With #2347	NO. 1 ENGINE - EXHAUST - THRUST REVERSER- INTRODUCTION OF A NEW THRUST REVERSER UNIT (TRU), SERVICE BULLETIN					21-JAN-2010 H: 0.00	
	Notes COMPLIED WITH - AT MANUFACTURE						
SB BR700-78-101607 Engine 2 SB - Complied With #1488	NO. 2 ENGINE - EXHAUST - THRUST REVERSER- INTRODUCTION OF A NEW THRUST REVERSER UNIT (TRU), SERVICE BULLETIN					28-AUG-2009 H: 0.00	
	Notes COMPLIED WITH - AT MANUFACTURE						
SB BR700-78-101607 R1 Engine 1 SB - Open #3061	NO. 1 ENGINE - EXHAUST - THRUST REVERSER- INTRODUCTION OF A NEW THRUST REVERSER UNIT (TRU), SERVICE BULLETIN.					H: 0.00	
SB BR700-78-101607 R1 Engine 2 SB - Open #4471	NO. 2 ENGINE - EXHAUST - THRUST REVERSER- INTRODUCTION OF A NEW THRUST REVERSER UNIT (TRU), SERVICE BULLETIN.					H: 0.00	
SB BR700-78-101716 Engine 1 SB - Open #3975	NO. 1 ENGINE - THRUST REVERSER ATTACH PARTS AND FITTINGS - CLARIFICATION AND CORRECTION OF THE THRUST REVERSER UNIT (TRU) ATTACHING PART DEFINITION, SERVICE BULLETIN					H: 0.00	



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-78-101716 Engine 2 SB - Open #4550	NO. 2 ENGINE - THRUST REVERSER ATTACH PARTS AND FITTINGS - CLARIFICATION AND CORRECTION OF THE THRUST REVERSER UNIT (TRU) ATTACHING PART DEFINITION, SERVICE BULLETIN	H: 0.00					
SB BR700-78-101788 Engine 1 SB - Open #4045	NO. 1 ENGINE - EXHAUST - THRUST REVERSER- DEFINITION OF EXISTING PARTS OF THE PIVOTING DOOR ACTUATOR (PDA) ROD END ASSEMBLY AS SPAREABLE ITEMS AND CORRECTION TO THE DEFINITION OF SPAREABLE PARTS IN THE CONFIGURATION BASELINE, SERVICE BULLETIN	H: 0.00					
SB BR700-78-101788 Engine 2 SB - Open #4516	NO. 2 ENGINE - EXHAUST - THRUST REVERSER- DEFINITION OF EXISTING PARTS OF THE PIVOTING DOOR ACTUATOR (PDA) ROD END ASSEMBLY AS SPAREABLE ITEMS AND CORRECTION TO THE DEFINITION OF SPAREABLE PARTS IN THE CONFIGURATION BASELINE, SERVICE BULLETIN	H: 0.00					
SB BR700-78-101944 Engine 1 SB - Open #4303	NO. 1 ENGINE - EXHAUST - DOOR POSITION SENSOR - INTRODUCTION OF A NEW LINEAR VARIABLE TRANSMITTER (LVT) BONDING STRAP, SERVICE BULLETIN	H: 0.00					
SB BR700-78-101944 Engine 2 SB - Open #3164	NO. 2 ENGINE - EXHAUST - DOOR POSITION SENSOR - INTRODUCTION OF A NEW LINEAR VARIABLE TRANSMITTER (LVT) BONDING STRAP, SERVICE BULLETIN	H: 0.00					
SB BR700-78-101983 R1 Engine 1 SB - Open #4789	NO. 1 ENGINE - EXHAUST - THRUST REVERSER DOOR STOW SWITCH - INTRODUCTION OF A NEW DOOR STOW SWITCH WITH AN IMPROVED FUNCTIONALITY (REV. 1)						
SB BR700-78-101983 R1 Engine 2 SB - Open #4790	NO. 2 ENGINE - EXHAUST - THRUST REVERSER DOOR STOW SWITCH - INTRODUCTION OF A NEW DOOR STOW SWITCH WITH AN IMPROVED FUNCTIONALITY (REV. 1)						
SB BR700-78-101983 R2 Engine 1 SB - Open #4857	EXHAUST - THRUST REVERSER DOOR STOW SWITCH - INTRODUCTION OF A NEW DOOR STOW SWITCH WITH AN IMPROVED FUNCTIONALITY						
SB BR700-78-101983 R2 Engine 2 SB - Open #5145	EXHAUST - THRUST REVERSER DOOR STOW SWITCH - INTRODUCTION OF A NEW DOOR STOW SWITCH WITH AN IMPROVED FUNCTIONALITY						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-78-101997 Engine 1 SB - Open #4791	NO. 1 ENGINE - EXHAUST - THRUST REVERSER UNIT (TRU) VARIOUS LOCATIONS - INTRODUCTION OF NEW FASTENER DEFINITIONS WHICH ARE USED TO MOUNT THE TRU ACCESS PANELS ONTO THE TRU STRUCTURE						
SB BR700-78-101997 Engine 2 SB - Open #4792	NO. 2 ENGINE - EXHAUST - THRUST REVERSER UNIT (TRU) VARIOUS LOCATIONS - INTRODUCTION OF NEW FASTENER DEFINITIONS WHICH ARE USED TO MOUNT THE TRU ACCESS PANELS ONTO THE TRU STRUCTURE						
SB BR700-78-102008 Engine 1 SB - Open #4800	NO. 1 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - INTRODUCTION OF A DRAINAGE HOLE WITHIN THE THRUST REVERSER FIXED STRUCTURE TO PREVENT CORROSION						
SB BR700-78-102008 Engine 2 SB - Open #4822	NO. 2 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - INTRODUCTION OF A DRAINAGE HOLE WITHIN THE THRUST REVERSER FIXED STRUCTURE TO PREVENT CORROSION						
SB BR700-78-102008 R1 Engine 1 SB - Open #4803	NO. 1 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - INTRODUCTION OF A DRAINAGE HOLE WITHIN THE THRUST REVERSER FIXED STRUCTURE TO PREVENT CORROSION (REV. 1)						
SB BR700-78-102008 R1 Engine 2 SB - Open #4825	NO. 2 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - INTRODUCTION OF A DRAINAGE HOLE WITHIN THE THRUST REVERSER FIXED STRUCTURE TO PREVENT CORROSION (REV. 1)						
SB BR700-78-900350 Engine 1 SB - Superseded #3081	NO. 1 ENGINE - EXHAUST - THRUST REVERSER UNIT (TRU) - INSPECTION OF THE SPHERICAL BEARING OF THE PRIMARY DOOR LOCK ACTUATOR (PDLA) AND CLEANING OF THE S-HOOK ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-78-900350 Engine 2 SB - Superseded #3394	NO. 2 ENGINE - EXHAUST - THRUST REVERSER UNIT (TRU) - INSPECTION OF THE SPHERICAL BEARING OF THE PRIMARY DOOR LOCK ACTUATOR (PDLA) AND CLEANING OF THE S-HOOK ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-78-900350 R1 Engine 1 SB - Open #3618	NO. 1 ENGINE - EXHAUST - THRUST REVERSER UNIT (TRU) - INSPECTION OF THE SPHERICAL BEARING OF THE PRIMARY DOOR LOCK ACTUATOR (PDLA) AND CLEANING OF THE S-HOOK ASSEMBLY, SERVICE BULLETIN.	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-78-900350 R1 Engine 2 SB - Open #4220	NO. 2 ENGINE - EXHAUST - THRUST REVERSERUNIT (TRU) - INSPECTION OF THE SPHERICAL BEARING OF THE PRIMARY DOOR LOCK ACTUATOR (PDLA) AND CLEANING OF THE S-HOOK ASSEMBLY, SERVICE BULLETIN.	H: 0.00					
SB BR700-78-900474 Engine 1 SB - Open #2591	NO. 1 ENGINE - EXHAUST - THRUST REVERSER- INSPECTION OF FIXED STRUCTURE TORQUE BOX DRAINAGE HOLES, SERVICE BULLETIN	21-MAR-2010 H: 0.00					
SB BR700-78-900474 Engine 2 SB - Open #1619	NO. 2 ENGINE - EXHAUST - THRUST REVERSER- INSPECTION OF FIXED STRUCTURE TORQUE BOX DRAINAGE HOLES, SERVICE BULLETIN	21-MAR-2010 H: 0.00					
SB BR700-78-900535 R1 Engine 1 SB - Open #4232	NO. 1 ENGINE - EXHAUST - THRUST REVERSERUNIT (TRU) DOOR ACTUATOR - INSPECTION OF THE ROD END ASSEMBLY OF THE PIVOTING DOOR ACTUATOR (PDA) - NON-MODIFICATION, SERVICE BULLETIN	H: 0.00					
SB BR700-78-900535 R1 Engine 2 SB - Open #4551	NO. 2 ENGINE - EXHAUST - THRUST REVERSERUNIT (TRU) DOOR ACTUATOR - INSPECTION OF THE ROD END ASSEMBLY OF THE PIVOTING DOOR ACTUATOR (PDA) - NON-MODIFICATION, SERVICE BULLETIN	H: 0.00					
SB BR700-78-900535 R2 Engine 1 SB - Open #4499	NO. 1 ENGINE - EXHAUST - THRUST REVERSERUNIT (TRU) DOOR ACTUATOR - INSPECTION OF THE ROD END ASSEMBLY OF THE PIVOTING DOOR ACTUATOR (PDA) - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	H: 0.00					
SB BR700-78-900535 R2 Engine 2 SB - Open #3132	NO. 2 ENGINE - EXHAUST - THRUST REVERSERUNIT (TRU) DOOR ACTUATOR - INSPECTION OF THE ROD END ASSEMBLY OF THE PIVOTING DOOR ACTUATOR (PDA) - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	H: 0.00					
SB BR700-78-900547 Engine 1 SB - Open #3511	NO. 1 ENGINE - ENGINE - THRUST REVERSER- INSPECTION OF THE SEAL DEPRESSORS, SEAL SUPPORTS AND ACTUATOR FAIRINGS - NON-MODIFICATION, SERVICE BULLETIN	H: 0.00					
SB BR700-78-900547 Engine 2 SB - Open #4081	NO. 2 ENGINE - ENGINE - THRUST REVERSER- INSPECTION OF THE SEAL DEPRESSORS, SEAL SUPPORTS AND ACTUATOR FAIRINGS - NON-MODIFICATION, SERVICE BULLETIN	H: 0.00					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-78-900547 R1 Engine 1 SB - Open #4326	NO. 1 ENGINE - ENGINE - THRUST REVERSER- INSPECTION OF THE SEAL DEPRESSORS, SEAL SUPPORTS AND ACTUATOR FAIRINGS, SERVICE BULLETIN	H: 0.00					
SB BR700-78-900547 R1 Engine 2 SB - Open #3313	NO. 2 ENGINE - ENGINE - THRUST REVERSER- INSPECTION OF THE SEAL DEPRESSORS, SEAL SUPPORTS AND ACTUATOR FAIRINGS, SERVICE BULLETIN	H: 0.00					
SB BR700-78-900617 Engine 1 SB - Open #4796	NO. 1 ENGINE - EXHAUST - LEFT AND RIGHT ENGINE THRUST REVERSER - INSPECTION OF THRUST REVERSER UNIT (TRU) PIVOT DOOR INTERNAL SURFACES - NON-MODIFICATION SERVICE BULLETIN						
SB BR700-78-900617 Engine 2 SB - Open #4797	NO. 2 ENGINE - EXHAUST - LEFT AND RIGHT ENGINE THRUST REVERSER - INSPECTION OF THRUST REVERSER UNIT (TRU) PIVOT DOOR INTERNAL SURFACES - NON-MODIFICATION SERVICE BULLETIN						
SB BR700-79-100323 R1 Engine 1 SB - Open #4136	NO. 1 ENGINE - OIL - EXTERNAL OIL TUBES AND FITTINGS - INTRODUCTION OF A REVISED ANTI-SYPHON OIL TUBE ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-79-100323 R1 Engine 2 SB - Open #3851	NO. 2 ENGINE - OIL - EXTERNAL OIL TUBES AND FITTINGS - INTRODUCTION OF A REVISED ANTI-SYPHON OIL TUBE ASSEMBLY, SERVICE BULLETIN	H: 0.00					
SB BR700-79-101739 Engine 1 SB - Open #4167	NO. 1 ENGINE - OIL - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF A NEW SEALING PLATE, SERVICE BULLETIN	H: 0.00					
SB BR700-79-101739 Engine 2 SB - Open #3210	NO. 2 ENGINE - OIL - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF A NEW SEALING PLATE, SERVICE BULLETIN	H: 0.00					
SB BR700-79-101744 Engine 1 SB - Open #4238	NO. 1 ENGINE - FUEL COOLED OIL COOLER(FCOC) - INTRODUCTION OF A NEW FCOC WITH IMPROVED ICING PROTECTION CAPABILITY, SERVICE BULLETIN	H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-79-101744 Engine 2 SB - Open #3834	NO. 2 ENGINE - FUEL COOLED OIL COOLER(FCOC) - INTRODUCTION OF A NEW FCOC WITH IMPROVED ICING PROTECTION CAPABILITY, SERVICE BULLETIN	H: 0.00					
SB BR700-79-101744 R1 Engine 1 SB - Open #4158	NO. 1 ENGINE - OIL - FUEL COOLED OIL COOLER(FCOC) - INTRODUCTION OF A NEW FCOC WITH IMPROVED ICING PROTECTION CAPABILITY, SERVICE BULLETIN	H: 0.00					
SB BR700-79-101744 R1 Engine 2 SB - Open #4562	NO. 2 ENGINE - OIL - FUEL COOLED OIL COOLER(FCOC) - INTRODUCTION OF A NEW FCOC WITH IMPROVED ICING PROTECTION CAPABILITY, SERVICE BULLETIN	H: 0.00					
SB BR700-79-101803 Engine 1 SB - Open #3580	NO. 1 ENGINE - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF A NEW OIL PUMP UNIT WITH IMPROVED GEARS, SERVICE BULLETIN	H: 0.00					
SB BR700-79-101803 Engine 2 SB - Open #4542	NO. 2 ENGINE - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF A NEW OIL PUMP UNIT WITH IMPROVED GEARS, SERVICE BULLETIN	H: 0.00					
SB BR700-79-101803 R1 Engine 1 SB - Open #4604	NO. 1 ENGINE - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF A NEW OIL PUMP UNIT WITH IMPROVED GEARS, SERVICE BULLETIN.	H: 0.00					
SB BR700-79-101803 R1 Engine 2 SB - Open #3858	NO. 2 ENGINE - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF A NEW OIL PUMP UNIT WITH IMPROVED GEARS, SERVICE BULLETIN.	H: 0.00					
SB BR700-79-101885 Engine 1 SB - Open #3422	NO. 1 ENGINE - OIL - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF AN ALTERNATIVE OIL PUMP UNIT, SERVICE BULLETIN	H: 0.00					
SB BR700-79-101885 Engine 2 SB - Open #3465	NO. 2 ENGINE - OIL - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF AN ALTERNATIVE OIL PUMP UNIT, SERVICE BULLETIN	H: 0.00					





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-79-101885 R1 Engine 1 SB - Open #4624	NO. 1 ENGINE - OIL - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF AN ALTERNATIVE OIL PUMP UNIT (REV. 1)						
SB BR700-79-101885 R1 Engine 2 SB - Open #4623	NO. 2 ENGINE - OIL - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF AN ALTERNATIVE OIL PUMP UNIT (REV. 1)						
SB BR700-79-900215 R2 Engine 1 SB - N/A #2481	NO. 1 ENGINE - OIL - EXCHANGE OF OIL FILTERDIFFERENTIAL PRESSURE SWITCH, SERVICE BULLETIN	25-FEB-2010					H: 0.00
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB BR700-79-900215 R2 Engine 2 SB - N/A #1789	NO. 2 ENGINE - OIL - EXCHANGE OF OIL FILTERDIFFERENTIAL PRESSURE SWITCH, SERVICE BULLETIN	25-FEB-2010					H: 0.00
	Notes NOT APPLICABLE - BY EFFECTIVITY						
SB BR700-79-900448 PART B Engine 1 SB - Open #3090	NO. 1 ENGINE - INSTRUCTIONS-OIL - MAGNETIC CHIP DETECTORS (MCD) - REVISED INSPECTION SCHEDULE OF THE FRONT BEARING CHAMBER(FBC) MCD AND MANAGEMENT OF POTENTIAL NON-CONFORMING HIGH PRESSURE (HP) COMPRESSOR NO.3 BEARING ASSEMBLIES - NON-MODIFICATION,						H: 0.00
SB BR700-79-900448 PART A Engine 1 SB - Open #4005	NO. 1 ENGINE - INTRODUCTION-OIL - MAGNETIC CHIP DETECTORS (MCD) - REVISED INSPECTION SCHEDULE OF THE FRONT BEARING CHAMBER(FBC) MCD AND MANAGEMENT OF POTENTIAL NON-CONFORMING HIGH PRESSURE (HP) COMPRESSOR NO.3 BEARING ASSEMBLIES - NON-MODIFICATION,						H: 0.00
SB BR700-79-900448 Engine 1 SB - Open #3125	NO. 1 ENGINE - OIL - MAGNETIC CHIP DETECTORS (MCD) - REVISED INSPECTION SCHEDULE OF THE FRONT BEARING CHAMBER(FBC) MCD AND MANAGEMENT OF POTENTIAL NON-CONFORMING HIGH PRESSURE (HP) COMPRESSOR NO.3 BEARING ASSEMBLIES - NON-MODIFICATION, SERVICE BULLETIN						H: 0.00
SB BR700-79-900448 PART B Engine 2 SB - Open #3973	NO. 2 ENGINE - INSTRUCTIONS-OIL - MAGNETIC CHIP DETECTORS (MCD) - REVISED INSPECTION SCHEDULE OF THE FRONT BEARING CHAMBER(FBC) MCD AND MANAGEMENT OF POTENTIAL NON-CONFORMING HIGH PRESSURE (HP) COMPRESSOR NO.3 BEARING ASSEMBLIES - NON-MODIFICATION,						H: 0.00





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-79-900448 PART A Engine 2 SB - Open #3811	NO. 2 ENGINE - INTRODUCTION-OIL - MAGNETIC CHIP DETECTORS (MCD) - REVISED INSPECTION SCHEDULE OF THE FRONT BEARING CHAMBER(FBC) MCD AND MANAGEMENT OF POTENTIAL NON-CONFORMING HIGH PRESSURE (HP) COMPRESSOR NO.3 BEARING ASSEMBLIES - NON-MODIFICATION,	H: 0.00					
SB BR700-79-900448 Engine 2 SB - Open #3808	NO. 2 ENGINE - OIL - MAGNETIC CHIP DETECTORS (MCD) - REVISED INSPECTION SCHEDULE OF THE FRONT BEARING CHAMBER(FBC) MCD AND MANAGEMENT OF POTENTIAL NON-CONFORMING HIGH PRESSURE (HP) COMPRESSOR NO.3 BEARING ASSEMBLIES - NON-MODIFICATION, SERVICE BULLETIN	H: 0.00					
SB BR700-79-900541 Engine 1 SB - Open #3331	NO. 1 ENGINE - OIL - GENERAL - SAMPLING OF THE ENGINE OIL SYSTEM, SERVICE BULLETIN	H: 0.00					
SB BR700-79-900541 Engine 2 SB - Open #3399	NO. 2 ENGINE - OIL - GENERAL - SAMPLING OF THE ENGINE OIL SYSTEM, SERVICE BULLETIN	H: 0.00					
SB BR700-79-900541 R1 Engine 1 SB - Open #4044	NO. 1 ENGINE - OIL - GENERAL - SAMPLING OF THE ENGINE OIL SYSTEM, SERVICE BULLETIN.	H: 0.00					
SB BR700-79-900541 R1 Engine 2 SB - Open #3172	NO. 2 ENGINE - OIL - GENERAL - SAMPLING OF THE ENGINE OIL SYSTEM, SERVICE BULLETIN.	H: 0.00					
SB BR700-79-900541 R2 Engine 1 SB - Open #3990	NO. 1 ENGINE - OIL - GENERAL - SAMPLING OF THE ENGINE OIL SYSTEM - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	H: 0.00					
SB BR700-79-900541 R2 Engine 2 SB - Open #4563	NO. 2 ENGINE - OIL - GENERAL - SAMPLING OF THE ENGINE OIL SYSTEM - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN	H: 0.00					
SB BR700-80-101729 Engine 1 SB - Open #3718	NO. 1 ENGINE - STARTING - AIRTURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH MODIFIED TURBINE THRUST BEARING, SEAL AND RETAINING RING, SERVICE BULLETIN	H: 0.00					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-80-101729 Engine 2 SB - Open #4351	NO. 2 ENGINE - STARTING - AIRTURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH MODIFIED TURBINE THRUST BEARING, SEAL AND RETAINING RING, SERVICE BULLETIN	H: 0.00					
SB BR700-80-101741 Engine 1 SB - Open #4335	NO. 1 ENGINE - STARTING - AIRTURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH MODIFIED OIL FILL PORTS TO IMPROVE THE MAINTENANCE OIL FILL PROCEDURE, SERVICE BULLETIN	H: 0.00					
SB BR700-80-101741 Engine 2 SB - Open #4240	NO. 2 ENGINE - STARTING - AIRTURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH MODIFIED OIL FILL PORTS TO IMPROVE THE MAINTENANCE OIL FILL PROCEDURE, SERVICE BULLETIN	H: 0.00					
SB BR700-80-101795 Engine 1 SB - Open #4284	NO. 1 ENGINE - STARTING - AIRTURBINE STARTER - INTRODUCTION OF AN ALTERNATIVE SEAL RING FOR THE STARTER OUTPUT SHAFT, SERVICE BULLETIN	H: 0.00					
SB BR700-80-101795 Engine 2 SB - Open #3720	NO. 2 ENGINE - STARTING - AIRTURBINE STARTER - INTRODUCTION OF AN ALTERNATIVE SEAL RING FOR THE STARTER OUTPUT SHAFT, SERVICE BULLETIN	H: 0.00					
SB BR700-80-101900 PART 1 Engine 1 SB - Open #3598	NO. 1 ENGINE - ACCOMPLISH,-REPLACEMENT OF THE OLD AIRTURBINE STARTER (P/N 3505934-12) WITH A NEW PRODUCTION STANDARD AIR TURBINE STARTER (P/N 3505934-14) AND REWORK OF THE AIR TURBINE STARTER FROM THE OLD STANDARD (P/N 3505934-12) TO THE NEW STANDA	H: 0.00					
SB BR700-80-101900 PART 2 Engine 1 SB - Open #4013	NO. 1 ENGINE - ACCOMPLISH,-REWORK OF THE AIRTURBINE STARTER FROM THE OLD STANDARD (P/N 3505934-11) TO THE NEW STANDARD (P/N 3505934-13) WHICH HAVE THE SB-BR700-80-101729 STANDARD INCORPORATED	H: 0.00					
SB BR700-80-101900 Engine 1 SB - Open #4021	NO. 1 ENGINE - STARTING - AIRTURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH REVISED OIL SEAL, SERVICE BULLETIN	H: 0.00					
SB BR700-80-101900 PART 1 Engine 2 SB - Open #3675	NO. 2 ENGINE - ACCOMPLISH,-REPLACEMENT OF THE OLD AIRTURBINE STARTER (P/N 3505934-12) WITH A NEW PRODUCTION STANDARD AIR TURBINE STARTER (P/N 3505934-14) AND REWORK OF THE AIR TURBINE STARTER FROM THE OLD STANDARD (P/N 3505934-12) TO THE NEW STANDA	H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB BR700-80-101900 PART 2 Engine 2 SB - Open #3052	NO. 2 ENGINE - ACCOMPLISH,-REWORK OF THE AIRTURBINE STARTER FROM THE OLD STANDARD (P/N 3505934-11) TO THE NEW STANDARD (P/N 3505934-13) WHICH HAVE THE SB-BR700-80-101729 STANDARD INCORPORATED	H: 0.00					
SB BR700-80-101900 Engine 2 SB - Open #3524	NO. 2 ENGINE - STARTING - AIRTURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH REVISED OIL SEAL, SERVICE BULLETIN	H: 0.00					
SB BR700-80-101900 R1 Engine 1 SB - Open #4805	NO. 1 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH REVISED OIL SEAL (REV. 1)						
SB BR700-80-101900 R1 Engine 2 SB - Open #4827	NO. 2 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH REVISED OIL SEAL (REV. 1)						
SB BR700-80-900340 Engine 1 SB - Superseded #4481	NO. 1 ENGINE - INSPECTION OF THE AIRTURBINE STARTER OIL LEVEL, SERVICE BULLETIN	H: 0.00					
SB BR700-80-900340 Engine 2 SB - Superseded #3981	NO. 2 ENGINE - INSPECTION OF THE AIRTURBINE STARTER OIL LEVEL, SERVICE BULLETIN	H: 0.00					
SB BR700-80-900340 R1 Engine 1 SB - N/A #1705	NO. 1 ENGINE - INSPECTION OF THE AIRTURBINE STARTER OIL LEVEL, SERVICE BULLETIN.	21-MAR-2014 H: 735.90 C: 311					
	Notes NOT APPLICABLE - BY S/N						
SB BR700-80-900340 R1 Engine 2 SB - N/A #2704	NO. 2 ENGINE - INSPECTION OF THE AIRTURBINE STARTER OIL LEVEL, SERVICE BULLETIN.	21-MAR-2014 H: 735.90 C: 311					
	Notes NOT APPLICABLE - BY S/N						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB M-DT 700-32-022 Airframe SB - Open #4268	MESSIER DOWTY-NOSE-LANDING GEARWHEEL ASSEMBLY-REPLACE GREASE SEAL WITH A NEW - GREASE SEAL AND WATER SHIELD, SERVICE BULLETIN	H: 0.00					
SB M-DT 700-32-032 Airframe SB - Complied With #916	MESSIER DOWTY- BD700-1A10, BD700-1A11 - NLG SHOCK STRUT ASSEMBLY REMOVAL OF A SECTION OF THE SHRINKABLE TUBING, SERVICE BULLETIN	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
SB RE220-49-8085 APU SB - Open #3427	APU - AIRBORNE AUXILIARY POWER- GAS TURBINE ENGINE - REPLACE THE (RETURN) OIL TRANSFER TUBE ASSEMBLY, PN WE3881884-1 WITH OIL RETURN TUBE, PN WE70721494-1, AND (SUPPLY) OIL TRANSFER TUBE ASSEMBLY, PN WE3881884-2 WITH OIL SUPPLY TUBE, PN WE70721495-1	H: 0.00					
SB RE220-49-8085 R1 APU SB - Open #4387	APU - AIRBORNE AUXILIARY POWER- GAS TURBINE ENGINE - REPLACE THE (RETURN) OIL TRANSFER TUBE ASSEMBLY, PN WE3881884-1 WITH OIL RETURN TUBE, PN WE70721494-1, AND (SUPPLY) OIL TRANSFER TUBE ASSEMBLY, PN WE3881884-2 WITH OIL SUPPLY TUBE, PN WE70721495-1.	H: 0.00					
SB RE220-49-8169 APU SB - Open #4560	APU - AIRBORNE AUXILIARY POWER- GAS TURBINE ENGINE - SEALANT APPLICATION METHOD FOR THE EXHAUST GAS TEMPERATURE SENSOR, PN WE3876352-2, ON RE220 APUS, SERVICE BULLETIN	H: 0.00					
SB-BR700-70-900040 R15 Engine 1 SB - Open #4825	ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES - NON-MODIFICATION SERVICE BULLETIN						
SB-BR700-70-900040 R15 Engine 2 SB - Open #4847	ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES - NON-MODIFICATION SERVICE BULLETIN						
SB-BR700-70-900040 R16 Engine 1 SB - Open #4830	ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES - NON-MODIFICATION SERVICE BULLETIN						
SB-BR700-70-900040 R16 Engine 2 SB - Open #4852	ENGINE LIFE MANAGEMENT - FIXED INTERVAL REWORK ENGINES - NON-MODIFICATION SERVICE BULLETIN						



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB-BR700-70-900295 R6 Engine 1 SB - Open #4826	ENGINE LIFE MANAGEMENT - ON CONDITION OPERATION ENGINES - IN-SHOP REWORK - NON -MODIFICATION SERVICE BULLETIN						
SB-BR700-70-900295 R6 Engine 2 SB - Open #4848	ENGINE LIFE MANAGEMENT - ON CONDITION OPERATION ENGINES - IN-SHOP REWORK - NON -MODIFICATION SERVICE BULLETIN						
SB-BR700-72-101521 R1 Engine 1 SB - Open #4824	ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW METHOD OF MANUFACTURE FOR ACCESSORY GEARBOX COMPONENTS						
SB-BR700-72-101521 R1 Engine 2 SB - Open #4846	ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW METHOD OF MANUFACTURE FOR ACCESSORY GEARBOX COMPONENTS						
SB-BR700-72-101530 R1 Engine 1 SB - Open #4820	ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF NEW MANUFACTURING PROCEDURES FOR ACCESSORY GEARBOX COMPONENTS						
SB-BR700-72-101530 R1 Engine 2 SB - Open #4842	ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF NEW MANUFACTURING PROCEDURES FOR ACCESSORY GEARBOX COMPONENTS						
SB-BR700-72-101550 R1 Engine 1 SB - Open #4821	ENGINE - ACCESSORY GEARBOX MODULE - DELETION OF BREATHER FILTER AND CHANGES TO BREATHER COVER, TANK COVERS AND OBTURATOR PLATE						
SB-BR700-72-101550 R1 Engine 2 SB - Open #4843	ENGINE - ACCESSORY GEARBOX MODULE - DELETION OF BREATHER FILTER AND CHANGES TO BREATHER COVER, TANK COVERS AND OBTURATOR PLATE						
SB-BR700-72-102038 Engine 1 SB - Open #4819	ENGINE - LOW PRESSURE (LP) COMPRESSOR/INTERNAL GEARBOX AIR DISTRIBUTION TUBES - INTRODUCTION OF A NEW AIR MANIFOLD HOUSING MADE FROM A DIFFERENT MATERIAL						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB-BR700-72-102038 Engine 2 SB - Open #4841	ENGINE - LOW PRESSURE (LP) COMPRESSOR/INTERNAL GEARBOX AIR DISTRIBUTION TUBES - INTRODUCTION OF A NEW AIR MANIFOLD HOUSING MADE FROM A DIFFERENT MATERIAL						
SB-BR700-72-102070 Engine 1 SB - Open #4823	ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF ALTERNATIVE DRAIN PLUGS AT THE ENGINE OIL TANK DRAIN LOCATION OF THE ACCESSORY GEARBOX						
SB-BR700-72-102070 Engine 2 SB - Open #4845	ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF ALTERNATIVE DRAIN PLUGS AT THE ENGINE OIL TANK DRAIN LOCATION OF THE ACCESSORY GEARBOX						
SB-BR700-72-102167 Engine 1 SB - Open #4851	ENGINE - LOW PRESSURE (LP) TURBINE FUEL SHUT-OFF (FSO) CABLE AND FITTINGS INTRODUCTION OF A NEW CONDUIT ASSEMBLY FOR THE FUEL SHUT-OFF MECHANISM						
SB-BR700-72-102167 Engine 2 SB - Open #4873	ENGINE - LOW PRESSURE (LP) TURBINE FUEL SHUT-OFF (FSO) CABLE AND FITTINGS INTRODUCTION OF A NEW CONDUIT ASSEMBLY FOR THE FUEL SHUT-OFF MECHANISM						
SB-BR700-72-A900659 Engine 1 SB - Open #4832	HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN						
SB-BR700-72-A900659 Engine 2 SB - Open #4854	HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN						
SB-BR700-74-102193 Engine 1 SB - Open #4843	IGNITION - IGNITOR PLUG - INTRODUCTION OF A NEW IGNITOR PLUG MANUFACTURED BY A DIFFERENT SUPPLIER						
SB-BR700-74-102193 Engine 2 SB - Open #4865	IGNITION - IGNITOR PLUG - INTRODUCTION OF A NEW IGNITOR PLUG MANUFACTURED BY A DIFFERENT SUPPLIER						
SB-BR700-74-102193 R1 Engine 1 SB - Open #4849	IGNITION - IGNITER PLUG - INTRODUCTION OF A NEW IGNITER PLUG MANUFACTURED BY A DIFFERENT SUPPLIER						



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB-BR700-74-102193 R1 Engine 2 SB - Open #4871	IGNITION - IGNITER PLUG - INTRODUCTION OF A NEW IGNITER PLUG MANUFACTURED BY A DIFFERENT SUPPLIER						
SB-BR700-75-101381 Engine 1 SB - Open #4816	AIR - BLEED VALVES - INTRODUCTION OF NEW TRIPLE SEALS AND A CARBON BUSH TO REPLACE THE EXISTING STEEL COMPONENTS						
SB-BR700-75-101381 Engine 2 SB - Open #4838	AIR - BLEED VALVES - INTRODUCTION OF NEW TRIPLE SEALS AND A CARBON BUSH TO REPLACE THE EXISTING STEEL COMPONENTS						
SB-BR700-77-101875 R2 Engine 1 SB - Open #4822	ENGINE INDICATING - N2 SPEED PROBES - INTRODUCTION OF NEW ATTACHING BOLTS WITH SHORTER LENGTH						
SB-BR700-77-101875 R2 Engine 2 SB - Open #4844	ENGINE INDICATING - N2 SPEED PROBES - INTRODUCTION OF NEW ATTACHING BOLTS WITH SHORTER LENGTH						
SB-BR700-78-900350 Engine 1 SB - Open #4818	EXHAUST - THRUST REVERSER UNIT (TRU) - INSPECTION OF THE SPHERICAL BEARING OF THE PRIMARY DOOR LOCK ACTUATOR (PDLA) AND CLEANING OF THE S-HOOK ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN						
SB-BR700-78-900350 Engine 2 SB - Open #4840	EXHAUST - THRUST REVERSER UNIT (TRU) - INSPECTION OF THE SPHERICAL BEARING OF THE PRIMARY DOOR LOCK ACTUATOR (PDLA) AND CLEANING OF THE S-HOOK ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN						
SB-SDR-014 Airframe SB - Complied With #5148	SDR Software Release MOD P (1.12.0)					17-AUG-2021 H: 4227.30 L: 1412	
SIL APU-49 R11 APU SB - Open #4743	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSISPROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS(APUS)						





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
TV 137848 Engine 1 SB - Complied With #1906	NO. 1 ENGINE - THRUST REVERSER LEFT LOWER DOOR, TECHNICAL VARIANCE	26-JAN-2014 H: 649.70 C: 284					
	Notes COMPLIED WITH - TV NOW CLOSED - LH LOWER THRUST REVERSER DOOR REPAIRED						
VSF GG436-1055-36-01 Airframe SB - Complied With #2316	BLEED AIR SYSTEM - PRESSURE REGULATING VALVE PNR GG436-1055-1 - PRODUCT IMPROVEMENT BY SEGMENTS REPLACEMENT, VENDOR SERVICE BULLETIN	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
AD 1972-19-04 Airframe AD - N/A FAA #212	NICKEL-CADMIUM BATTERY	19-MAR-2010 H: 0.00					
	Notes NOT APPLICABLE						
AD 1974-08-09 R2 Airframe AD - Complied With FAA #839	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION (SUPERSEDED BY FAA AD 1974-08-09 R3)	03-MAR-2016 H: 1753.70 L: 622					
	Notes COMPLIED WITH - COMPLIED WITH PERMDL ML7009385-A						
AD 1974-08-09 R3 AMD 39-16951 Airframe AD - Recurring FAA #385	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION	10-OCT-2019 H: 3516.60 L: 1170	H: 1000.00			H: 4516.60	H: 60.80
	Notes COMPLIED WITH						
AD 1993-24-16 Airframe AD - N/A FAA #682	TO PREVENT FAILURE OF A PBE UNIT DUE TO DETERIORATED NECK SEAL	19-MAR-2010 H: 0.00					
	Notes NOT APPLICABLE - BY PART NUMBER NOT APPLICABLE PART NUMBER 119003-11 INSTALLED						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 1994-06-04 Airframe AD - Complied With FAA #2476	EROS FULL FACE MASK	19-MAR-2010 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION MASK P/N MF10-08-01 WITH FACE PIECE P/N MXM42 INSTALLED						
AD 1997-325 Engine 1 AD - N/A FAA #1477	NO. 1 ENGINE - ENGINE ACCESSORY GEARBOX - REMOVAL OF NON-CONFORMING PARTS FORM APT GEARBOXES	15-JAN-2010 H: 0.00					
	Notes NOT APPLICABLE						
AD 1997-325 Engine 2 AD - N/A FAA #2868	NO. 2 ENGINE - ENGINE ACCESSORY GEARBOX - REMOVAL OF NON-CONFORMING PARTS FORM APT GEARBOXES	15-JAN-2010 H: 0.00					
	Notes NOT APPLICABLE						
AD 1998-24-03 R1 Engine 1 AD - N/A FAA #1351	NO. 1 ENGINE - VISUAL INSPECTION OF ENGINE CORE FAIRING FASTENERS.	25-FEB-2010 H: 0.00					
	Notes NOT APPLICABLE - TERMINATED CANCELS 1998-467 ISSUE 03.INSPECTION REQUIREMENT TERMINATED BY MOD 72-100900.NO FURTHERACTION REQUIRED						
AD 1998-24-03 R1 Engine 2 AD - N/A FAA #933	NO. 2 ENGINE - VISUAL INSPECTION OF ENGINE CORE FAIRING FASTENERS.	25-FEB-2010 H: 0.00					
	Notes NOT APPLICABLE - TERMINATED TERMINATED BY MOD 72-100900.						
AD 1998-24-27 Airframe AD - N/A FAA #997	FIRST TECHNOLOGY FIRE & SAFETY - AUTOMATIC FIRE EXTINGUISHERS	23-JAN-2011 H: 0.00					
	Notes NOT APPLICABLE - NOT APPLICABLE BY INSTALLATION						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 1998-25-10 R1 Airframe AD - N/A FAA #665	AIRCRAFT BELTS INC. - BUCKLE ASSEMBLY LOCKING MECHANISM	23-JAN-2011 H: 0.00					
	Notes NOT APPLICABLE - NOT APPLICABLE BY SEAT BELT TYPE						
AD 1998-467 R4 Engine 1 AD - Complied With FAA #35	NO. 1 ENGINE - SEPARATION OF THE ENGINE CORE FAIRINGS DUE TO INCORRECT INSTALLATION	15-JAN-2010 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
AD 1998-467 R4 Engine 2 AD - Complied With FAA #132	NO. 2 ENGINE - SEPARATION OF THE ENGINE CORE FAIRINGS DUE TO INCORRECT INSTALLATION	15-JAN-2010 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION						
AD 2000-257 R2 Engine 1 AD - N/A FAA #1804	NO. 1 ENGINE - OIL FILTERDIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431	15-JAN-2010 H: 0.00					
	Notes NOT APPLICABLE						
AD 2000-257 R2 Engine 2 AD - N/A FAA #236	NO. 2 ENGINE - OIL FILTERDIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431	15-JAN-2010 H: 0.00					
	Notes NOT APPLICABLE						
AD 2000-348 R5 Engine 1 AD - N/A FAA #1462	NO. 1 ENGINE - LP COMPRESSORINSPECTION OF THE FAN DISK FOR CRACKS	15-JAN-2010 H: 0.00					
	Notes NOT APPLICABLE						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2000-348 R5 Engine 2 AD - N/A FAA #145	NO. 2 ENGINE - LP COMPRESSOR INSPECTION OF THE FAN DISK FOR CRACKS	15-JAN-2010 H: 0.00					
	Notes NOT APPLICABLE						
AD 2001-01-01 Engine 1 AD - N/A FAA #1939	NO. 1 ENGINE - CHECK, MARK AND REPLACE OIL FILTER DIFFERENTIAL PRESSURE SWITCH	25-FEB-2010 H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
AD 2001-01-01 Engine 2 AD - N/A FAA #2280	NO. 2 ENGINE - CHECK, MARK AND REPLACE OIL FILTER DIFFERENTIAL PRESSURE SWITCH	15-JAN-2010 H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
AD 2001-05-06 AMD 39 -12142 Engine 1 AD - Superseded FAA #912	NO. 1 ENGINE - ULTRASONIC INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS	15-JAN-2010 H: 0.00					
	Notes NOT APPLICABLE						
AD 2001-05-06 AMD 39 -12142 Engine 1 AD - Superseded FAA #2578	NO. 1 ENGINE - VISUAL INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS	15-JAN-2010 H: 0.00					
	Notes NOT APPLICABLE						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2001-05-06 AMD 39 -12142 Engine 2 AD - Superseded FAA #1214	NO. 2 ENGINE - ULTRASONIC INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS	15-JAN-2010 H: 0.00					
	Notes NOT APPLICABLE						
AD 2001-05-06 AMD 39 -12142 Engine 2 AD - Superseded FAA #2518	NO. 2 ENGINE - VISUAL INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS	15-JAN-2010 H: 0.00					
	Notes NOT APPLICABLE						
AD 2003-04-06 Airframe AD - Superseded FAA #4322	APPLIANCE AD - INSPECTION TO DETERMINE P/N INTEGRATED NAVIGATION UNIT	H: 0.00					
AD 2003-07-11 AMD PART F Engine 1 AD - Superseded FAA #26	NO. 1 ENGINE - VISUAL AND ULTRASONIC INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS	15-JAN-2010 H: 0.00					
	Notes NOT APPLICABLE						
AD 2003-07-11 AMD 39 -13107 PART B Engine 1 AD - Superseded FAA #2814	NO. 1 ENGINE - VISUAL OR ULTRASONIC INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS	15-JAN-2010 H: 0.00					
	Notes NOT APPLICABLE						
AD 2003-07-11 AMD PART F Engine 2 AD - Superseded FAA #2892	NO. 2 ENGINE - VISUAL AND ULTRASONIC INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS	15-JAN-2010 H: 0.00					
	Notes NOT APPLICABLE						





Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2003-07-11 AMD 39 -13107 PART B Engine 2 AD - Superseded FAA #1917	NO. 2 ENGINE - VISUAL OR ULTRASONIC INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS	15-JAN-2010 H: 0.00					
	Notes NOT APPLICABLE						
AD 2003-26-14 Airframe AD - N/A FAA #33	HAND HELD HALON FIRE EXTINGUISHERS	23-JAN-2011 H: 0.00					
	Notes NOT APPLICABLE - BY PART NUMBER NOT APPLICABLE BY FIRE EXTINGUISHER PART NUMBER INSTALLED (466090)						
AD 2004-494 Engine 1 AD - N/A FAA #2859	NO. 1 ENGINE - REDUCTION OF LIFE LIMITATION FOR THE HIGH PRESSURE COMPRESSOR (HPC) FRONT DRUM TO AN INADVERTENT HEAT TREATMENT.	15-JAN-2010 H: 0.00					
	Notes NOT APPLICABLE						
AD 2004-494 Engine 2 AD - N/A FAA #1437	NO. 2 ENGINE - REDUCTION OF LIFE LIMITATION FOR THE HIGH PRESSURE COMPRESSOR (HPC) FRONT DRUM TO AN INADVERTENT HEAT TREATMENT.	15-JAN-2010 H: 0.00					
	Notes NOT APPLICABLE						
AD 2005-21-05 AMD PART 2 Engine 1 AD - N/A FAA #1479	NO. 1 ENGINE - ULTRASONIC AND VISUAL INSPECTION OF THE FAN DISC	25-FEB-2010 H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2005-21-05 AMD PART L Engine 1 AD - N/A FAA #2491	NO. 1 ENGINE - VISUAL AND ULTRASONIC INSPECTION AS MANDATED IN RRD TIME LIMITS MANUAL T-710-2BR, CHAPTER05-10-01 (BR700-710A2-20).	25-FEB-2010 H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
AD 2005-21-05 AMD PART 1 Engine 1 AD - N/A FAA #321	NO. 1 ENGINE - VISUAL ORULTRASONIC INSPECTION OF THE FAN DISC	25-FEB-2010 H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
AD 2005-21-05 AMD PART 2 Engine 2 AD - N/A FAA #1721	NO. 2 ENGINE - ULTRASONIC AND VISUAL INSPECTION OF THE FAN DISC	25-FEB-2010 H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
AD 2005-21-05 AMD PART L Engine 2 AD - N/A FAA #2862	NO. 2 ENGINE - VISUAL AND ULTRASONIC INSPECTION AS MANDATED IN RRD TIME LIMITS MANUAL T-710-2BR, CHAPTER05-10-01 (BR700-710A2-20).	25-FEB-2010 H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						
AD 2005-21-05 AMD PART 1 Engine 2 AD - N/A FAA #713	NO. 2 ENGINE - VISUAL ORULTRASONIC INSPECTION OF THE FAN DISC	25-FEB-2010 H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2006-18-08 Airframe AD - N/A FAA #2218	APPLIANCE AD - GOODYEARAVIATION TIRES - PART NUMBER 217K22-1 - INSPECTION TO DETERMINE SERIAL NUMBER (S/N), AND REPLACEMENT	19-MAR-2010 H: 0.00					
	Notes NOT APPLICABLE - BY SERIAL NUMBER NOT APPLICABLE BY TIRE SERIAL NUMBERS INSTALLED IN ACCORDANCE WITH GOODYEAR AVIATION SERVICE BULLETIN SB 2005-32-004, REVISION 5						
AD 2006-19-04 AMD PART H Airframe AD - N/A FAA #459	APPLIANCE AD - HONEYWELL - COMMUNICATION (COM) UNIT / MODE S TRANSPONDERERRONEOUSLY GOING INTO STANDBY MODE - REPLACEMENT OF CERTAIN TRANSPONDERS	19-MAR-2010 H: 0.00					
	Notes NOT APPLICABLE - NOT APPLICABLE NOT INSTALLED THIS AIRCRAFT						
AD 2006-19-04 AMD PART G Airframe AD - N/A FAA #1511	APPLIANCE AD - HONEYWELL - COMMUNICATION (COM) UNIT / MODE S TRANSPONDERERRONEOUSLY GOING INTO STANDBY MODE - REPLACEMENT OF IDENTIFICATION PLATES FOR CERTAIN COM UNITS	19-MAR-2010 H: 0.00					
	Notes NOT APPLICABLE - NOT APPLICABLE NOT INSTALLED THIS AIRCRAFT						
AD 2006-19-04 AMD PART F Airframe AD - N/A FAA #2688	APPLIANCE AD - HONEYWELL - COMMUNICATION (COM) UNIT / MODE S TRANSPONDERERRONEOUSLY GOING INTO STANDBY MODE - REVISE AIRPLANE FLIGHT MANUAL (AFM)	19-MAR-2010 H: 0.00					
	Notes NOT APPLICABLE - NOT APPLICABLE NOT INSTALLED THIS AIRCRAFT						
AD 2006-22-05 Airframe AD - N/A FAA #127	APPLIANCE AD - AIRCRAFT EQUIPPED WITH HONEYWELL PRIMUS II RNZ-850()/-851() INTEGRATED NAVIGATION UNITS	19-MAR-2010 H: 0.00					
	Notes NOT APPLICABLE - NOT APPLICABLE COMPONENT P/N 7510100-631 INSTALLED						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2007-0156 Airframe AD - N/A EASA #1557	COMMUNICATION - COMM UNITS & TRANSPONDERS - MODIFICATION / REPLACEMENT	19-MAR-2010 H: 0.00					
	Notes NOT APPLICABLE - NOT APPLICABLE NOT INSTALLED THIS AIRCRAFT						
AD 2008-24-12 Airframe AD - Superseded FAA #4348	INSPECTION AND LUBRICATION OF ALL PART NUMBER(P/N) GT411-3800-5 AND GT411-3800-7 PCU ATTACHMENT JOINTS	H: 0.00					
AD 2009-0251 AMD E Airframe AD - N/A EASA #2844	EMERGENCY AD - FIRE EXTINGUISHER- PORTABLE FIRE EXTINGUISHERS IDENTIFICATION/REPLACEMENT	23-JAN-2011 H: 0.00					
	Notes NOT APPLICABLE - BY SERIAL NUMBERT NOT APPLICABLE BY FIRE EXTINGUISHER SERIAL NUMBER INSTALLED (067870 AND 068471)						
AD 2009-0262 R1 Airframe AD - N/A EASA #815	FIRE EXTINGUISHER- PORTABLE FIRE EXTINGUISHERS IDENTIFICATION/REPLACEMENT	23-JAN-2011 H: 0.00					
	Notes NOT APPLICABLE - BY SERIAL NUMBERT NOT APPLICABLE BY FIRE EXTINGUISHER SERIAL NUMBER INSTALLED (067870 AND 068471)						
AD 2009-0278 Airframe AD - N/A EASA #2530	FIRE EXTINGUISHER- PORTABLE FIRE EXTINGUISHERS IDENTIFICATION/REPLACEMENT.	23-JAN-2011 H: 0.00					
	Notes NOT APPLICABLE - NOT APPLICABLE BY FIRE EXTINGUISHERMANUFACTURER						
AD 2009-15-03 AMD (G)(1) Airframe AD - N/A FAA #2049	FOR INSPECTION AND LUBRICATION OF ALL PART NUMBER (P/N) GT411-3800-5 AND GT411-3800-7 PCU ATTACHMENT JOINTS AIRPLANES IDENTIFIED IN PARAGRAPH (F)	19-MAR-2010 H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2009-15-03 AMD (G)(2) Airframe AD - N/A FAA #900	FOR INSPECTION AND LUBRICATION OF ALL PART NUMBER (P/N) GT411-3800-5 AND GT411-3800-7 PCU ATTACHMENT JOINTS AIRPLANES NOT IDENTIFIED IN PARAGRAPH (F)	19-MAR-2010 H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER						
AD 2009-15-03 Airframe AD - N/A FAA #2909	INSPECTION AND LUBRICATION OF ALL PART NUMBER(P/N) GT411-3800-5 AND GT411-3800-7 PCU ATTACHMENT JOINTS.	19-MAR-2010 H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER						
AD 2009-21-10 R1 Airframe AD - N/A FAA #1493	INSPECT FOR AFFECTED P/N & S/N OF AVOX & BE AEROSPACE O2 BOTTLES	23-JAN-2011 H: 0.00					
	Notes NOT APPLICABLE - BY PART NUMBER NOT APPLICABLE BY OXYGEN CYLINDER PART NUMBER INSTALLED (GC481-0090-5)						
AD 2010-0062 R1 Airframe AD - N/A EASA #2171	PORTABLE HALON 1211 FIRE EXTINGUISHER- IDENTIFICATION/REPLACEMENT	23-JAN-2011 H: 0.00					
	Notes NOT APPLICABLE - BY SERIAL NUMBER NOT APPLICABLE BY FIRE EXTINGUISHER SERIAL NUMBER INSTALLED (067870 AND 068471)						
AD 2010-0075 Engine 1 AD - N/A EASA #410	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE DISCS STAGE 1 AND 2 ASSEMBLY LIFE LIMITS - MODIFICATION	21-JAN-2011 H: 11.80 C: 6					
	Notes NOT APPLICABLE - NO ACTION REQUIRED						
AD 2010-0075 Engine 2 AD - N/A EASA #1316	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE DISCS STAGE 1 AND 2 ASSEMBLY LIFE LIMITS - MODIFICATION	21-JAN-2011 H: 11.80 C: 6					
	Notes NOT APPLICABLE - NO ACTION REQUIRED						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2010-0076 Engine 1 AD - N/A EASA #977	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE DISCS STAGE 1 AND 2 ASSEMBLY LIFE LIMITS - MODIFICATION. Notes NOT APPLICABLE - BY TYPE VARIANTS	21-JAN-2011 H: 11.80 C: 6					
AD 2010-0076 Engine 2 AD - N/A EASA #38	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE DISCS STAGE 1 AND 2 ASSEMBLY LIFE LIMITS - MODIFICATION. Notes NOT APPLICABLE - BY TYPE VARIANTS	21-JAN-2011 H: 11.80 C: 6					
AD 2010-0077 Engine 1 AD - N/A EASA #1774	NO. 1 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE CYCLE COUNTING METHOD FORTOUCH-AND-GO AND OVERSHOOT Notes NOT APPLICABLE - NO ACTION REQUIRED DUE TO CYCLES WITH IN LIFE LIMITATION	21-JAN-2011 H: 11.80 C: 6					
AD 2010-0077 Engine 2 AD - N/A EASA #1106	NO. 2 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE CYCLE COUNTING METHOD FORTOUCH-AND-GO AND OVERSHOOT Notes NOT APPLICABLE - NO ACTION REQUIRED DUE TO CYCLES WITHIN LIFE LIMITATION	21-JAN-2011 H: 11.80 C: 6					
AD 2010-01-03 Airframe AD - N/A FAA #2091	FIRE FIGHTING ENTERPRISES LIMITED PORTABLE HALON 1211 FIRE EXTINGUISHERS AS INSTALLED ON VARIOUS TRANSPORT AIRPLANES, SMALL AIRPLANES, AND ROTORCRAFT Notes NOT APPLICABLE - BY SERIAL NUMBER NOT APPLICABLE BY FIRE EXTINGUISHER SERIAL NUMBER INSTALLED (067870 AND 068471)	23-JAN-2011 H: 0.00					
AD 2010-0152 Airframe AD - N/A EASA #396	OXYGEN MASK REGULATOR- MODIFICATION Notes NOT APPLICABLE - BY PART NUMBER NOT APPLICABLE BY PART NUMBER INSTALLED (MF10-08-01)	23-JAN-2011 H: 0.00					





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2010-04-16 Airframe AD - N/A FAA #1263	SICLI HALON 1211 PORTABLE FIRE EXTINGUISHERS AS INSTALLED ON VARIOUS AIRPLANES AND ROTORCRAFT	23-JAN-2011 H: 0.00					
	Notes NOT APPLICABLE - NOT APPLICABLE BY FIRE EXTINGUISHERMANUFACTURER INSTALLED (KIDDE AEROSPACE)						
AD 2010-07-02 Airframe AD - N/A FAA #1669	APPLIANCE AD - HONEYWELL - PRIMUS II RNZ-850()/-851() INTEGRATED NAVIGATION UNITS - INSPECTION TO DETERMINE P/N - MOD LEVEL - TO ENSURE ACCURATE LOCALIZER& GLIDESLOPE DEVIATION INDICATIONS	23-JAN-2011 H: 0.00					
	Notes NOT APPLICABLE - BY PART NUMBERNOT APPLICABLE INU PART NUMBER INSTALLED (7510100-631), THIS AD SUPERSEDES AD 2006-22-05						
AD 2010-07-02 AMD (L) (AMOC) Airframe AD - N/A FAA #3943	INSPECTION TO DETERMINE MOD LEVEL TO ENSURE THAT THE NRM IS AT MOD T CONFIGURATION	H: 0.00					
AD 2010-07-02 AMD (H) (AMOC) Airframe AD - N/A FAA #3676	REVISE THE LIMITATIONS SECTION OF THE AFM TO INCLUDE "FLIGHT LIMITATIONS"	H: 0.00					
AD 2010-09-04 Airframe AD - N/A FAA #4674	TO PROVIDE THE FLIGHTCREW WITH PROCEDURES TO RECOVER FROM OR WORK AROUND THESE SOFTWARE ANOMALIES DURING FLIGHT						
	Notes N/A PER EQUIPMENT INSTALLED						
AD 2010-11-05 Airframe AD - N/A FAA #728	AVOX SYSTEMS AND BIE AEROSPACE TO PREVENT AN OXYGEN CYLINDERFROM RUPTURING	12-SEP-2012 H: 0.00					
	Notes NOT APPLICABLE - N/A BY P/N						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2010-12-09 Airframe AD - N/A FAA #4675	TO PREVENT FUEL LEAKAGE IN THE APU COMPARTMENT Notes N/A BY PN INSTALLED						
AD 2010-23-08 Airframe AD - N/A FAA #2038	INSPECT TO DETERMINE THE SERIAL NUMBER OF THE INSTALLED RAM AIR TURBINE (RAT) Notes NOT APPLICABLE - BY SERIAL NUMBER NOT APPLICABLE BY RAT SERIAL NUMBER INSTALLED (0504)	23-JAN-2011				H: 0.00	
AD 2010-25-05 AMD 39 -16538 Engine 1 AD - Complied With FAA #4100	NO. 1 ENGINE - DECLARED SAFE CYCLIC LIFE FOR HPT STG 1 & 2 DISCS Notes COMPLIED WITH - AT COMPLETION			H: 14.10 C: 7			
AD 2010-25-05 AMD 39 -16538 Engine 2 AD - Complied With FAA #2979	NO. 2 ENGINE - DECLARED SAFE CYCLIC LIFE FOR HPT STG 1 & 2 DISCS Notes COMPLIED WITH - AT COMPLETION			H: 14.10 C: 7			
AD 2011-0090 R1 Airframe AD - N/A EASA #598	OXYGEN MASK REGULATOR INFLATABLE HARNESS - IDENTIFICATION/REPLACEMENT Notes NOT APPLICABLE - N/A BY S/N					12-SEP-2012 H: 0.00	
AD 2011-0098 Airframe AD - N/A EASA #935	EQUIPMENT & FURNISHINGS - PASSENGER SEAT - REPLACEMENT Notes NOT APPLICABLE - BY AIRCRAFT TYPE					12-SEP-2012 H: 0.00	





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2011-01-09 Airframe AD - N/A FAA #2903	APPLIANCE AD - B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE) PART NUMBER119003-11 INSTALLED ON VARIOUS TRANSPORT AIRPLANES	23-JAN-2011 H: 0.00					
	Notes NOT APPLICABLE - INCORPORATION OF B/E AEROSPACE SB 119003-35-5 NOT APPLICABLE BY PBE S/N INSTALLED (003-49741M)						
AD 2011-01-10 Airframe AD - Complied With FAA #2920	HYDRAULIC SYSTEM LINES - RELOCATE THE NO. 2 AND NO. 3 HYDRAULIC SYSTEM LINES IN THE WING AUXILIARY SPARAREA ON THE LEFT SIDE OF THE AIRCRAFT, AND MODIFY THE LEFT WING RIB AND LEFT AND RIGHT DEBRIS SHIELDS	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION INCORPORATION OF BOMBARDIERSB 700-29-021						
AD 2011-12-01 Airframe AD - N/A FAA #2626	PREVENT ACCELERATED FIRES AND INJURIES TO THE FLIGHTCREW AND PASSENGERS	12-SEP-2012 H: 0.00					
	Notes NOT APPLICABLE - N/A BY AIRCRAFT TYPE						
AD 2011-14-08 Airframe AD - N/A FAA #2067	B/E AEROSPACE, CONTINUOUS FLOW PASSENGEROXYGEN MASK ASSEMBLY, PART NUMBERS 174006-(), 174080-(), 174085-(), 174095-(), 174097-(), AND 174098-()	12-SEP-2012 H: 0.00					
	Notes NOT APPLICABLE - N/A BY APPROVAL HOLDER						
AD 2011-21-08 Airframe AD - N/A FAA #4676	TO IDENTIFY AND CORRECT UNSAFE CONDITION ON SICMA AERO SEAT PASSENGER SEAT ASSEMBLIES						
	Notes N/A BY PN IN STALLED						
AD 2011-22-01 AMD (E) (3) Engine 1 AD - Complied With FAA #4588	NO. 1 ENGINE - DETERMINE ROLLS-ROYCE DEUTSCHLAND LTD & CO KG (RRD) BR700-710 SERIES TURBOFAN ENGINES - LIFE CYCLE COUNTING METHOD FORTOUCH-AND-GO AND OVERSHOOT THE NUMBER OF TOUCH-AND-GO'S AND OVERSHOOTS THAT EACH INDIVIDUAL CRITICAL PART EXCEPT T	H: 292.60 C: 134					
	Notes COMPLIED WITH - BY THE OPERATOR						





Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2011-22-01 AMD (E) (1) (2) Engine 1 AD - Complied With FAA #4243	NO. 1 ENGINE - REVISE ROLLS-ROYCE DEUTSCHLAND LTD & CO KG (RRD) BR700-710 SERIES TURBOFAN ENGINES - LIFE CYCLE COUNTING METHOD FORTOUCH-AND-GO AND OVERSHOOT THE AIRWORTHINESS LIMITATIONS SECTION (ALS) OF THE OPERATORS' APPROVED MAINTENANCE PROGRAM	H: 292.60 C: 134					
	Notes COMPLIED WITH - BY THE OPERATOR						
AD 2011-22-01 Engine 1 AD - Complied With FAA #2426	NO. 1 ENGINE - ROLLS-ROYCE DEUTSCHLAND LTD & CO KG (RRD) BR700-710 SERIES TURBOFAN ENGINES - LIFE CYCLE COUNTING METHOD FORTOUCH-AND-GO AND OVERSHOOT	16-FEB-2012 H: 292.60 C: 134					
	Notes COMPLIED WITH - BY THE OPERATOR						
AD 2011-22-01 AMD (E) (3) Engine 2 AD - Complied With FAA #816	NO. 2 ENGINE - DETERMINE ROLLS-ROYCE DEUTSCHLAND LTD & CO KG (RRD) BR700-710 SERIES TURBOFAN ENGINES - LIFE CYCLE COUNTING METHOD FORTOUCH-AND-GO AND OVERSHOOT THE NUMBER OF TOUCH-AND-GO'S AND OVERSHOOTS THAT EACH INDIVIDUAL CRITICAL PART EXCEPT T	16-FEB-2012 H: 292.60 C: 134					
	Notes COMPLIED WITH - BY THE OPERATOR						
AD 2011-22-01 AMD (E) (1) (2) Engine 2 AD - Complied With FAA #1471	NO. 2 ENGINE - REVISE ROLLS-ROYCE DEUTSCHLAND LTD & CO KG (RRD) BR700-710 SERIES TURBOFAN ENGINES - LIFE CYCLE COUNTING METHOD FORTOUCH-AND-GO AND OVERSHOOT THE AIRWORTHINESS LIMITATIONS SECTION (ALS) OF THE OPERATORS' APPROVED MAINTENANCE PROGRAM	16-FEB-2012 H: 292.60 C: 134					
	Notes COMPLIED WITH - BY THE OPERATOR						
AD 2011-22-01 Engine 2 AD - Complied With FAA #1825	NO. 2 ENGINE - ROLLS-ROYCE DEUTSCHLAND LTD & CO KG (RRD) BR700-710 SERIES TURBOFAN ENGINES - LIFE CYCLE COUNTING METHOD FORTOUCH-AND-GO AND OVERSHOOT	16-FEB-2012 H: 292.60 C: 134					
	Notes COMPLIED WITH - BY THE OPERATOR						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2012-0037 Airframe AD - N/A EASA #1367	FIRE PROTECTION - HAND OPERATED FIRE EXTINGUISHER- MODIFICATION	12-SEP-2012 H: 0.00					
	Notes NOT APPLICABLE - N/A BY P/N						
AD 2012-02-08 Airframe AD - Complied With FAA #708	APPLIANCE AD - AVIATION COMMUNICATION & SURVEILLANCE SYSTEMS (ACSS) TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS	14-MAR-2013 H: 430.70					
	Notes COMPLIED WITH						
AD 2012-0254 AMD (2.2) Airframe AD - N/A EASA #1692	AMEND - OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR-IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT-AIRCRAFT FLIGHT MANUAL (AFM)	12-DEC-2012 H: 426.50 L: 209					
	Notes NOT APPLICABLE - AD 2012-0254 IS N/A DUE TO P/N AND S/N INSTALLED ON AIRCRAFT						
AD 2012-0254 AMD (1) Airframe AD - N/A EASA #327	INSPECT/CHECK - OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR-IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT-OXYGEN MASK REGULATOR TO IDENTIFY THE P/N AND S/N	12-DEC-2012 H: 426.50 L: 209					
	Notes NOT APPLICABLE - AD 2012-0254 IS N/A DUE TO P/N AND S/N INSTALLED ON AIRCRAFT						
AD 2012-0254 Airframe AD - N/A EASA #2030	OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR-IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT	12-DEC-2012 H: 426.50 L: 209					
	Notes NOT APPLICABLE - AD 2012-0254 IS N/A DUE TO P/N AND S/N INSTALLED ON AIRCRAFT						
AD 2012-0254 AMD (2.1) Airframe AD - N/A EASA #1758	REPLACE - OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR-IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT-AFFECTED OXYGEN MASK REGULATOR	12-DEC-2012 H: 426.50 L: 209					
	Notes NOT APPLICABLE - AD 2012-0254 IS N/A DUE TO P/N AND S/N INSTALLED ON AIRCRAFT						

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2012-0254 AMD (3) Airframe AD - N/A EASA #249	REPLACE - OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR-IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT-EACH AFFECTED FLIGHT CREW OXYGEN MASK REGULATOR WITH A SERVICEABLE PART	12-DEC-2012 H: 426.50 L: 209					
	Notes NOT APPLICABLE - AD 2012-0254 IS N/A DUE TO P/N AND S/N INSTALLED ON AIRCRAFT						
AD 2012-0254 R1 AMD (2.2) Airframe AD - N/A EASA #1665	AMEND - OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR- IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT-THE AIRCRAFT FLIGHT MANUAL (AFM) AND INSTALL A PLACARD	12-DEC-2012 H: 426.50 L: 209					
	Notes NOT APPLICABLE - IS N/A DUE TO P/N AND S/N INSTALLED ON AIRCRAFT						
AD 2012-0254 R1 Airframe AD - N/A EASA #2011	APPLIANCE AD - OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR- IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT	12-DEC-2012 H: 426.50 L: 209					
	Notes NOT APPLICABLE - IS N/A DUE TO P/N AND S/N INSTALLED ON AIRCRAFT						
AD 2012-0254 R1 AMD (1) Airframe AD - N/A EASA #2589	INSPECT - OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR- IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT-EACH FLIGHT CREW OXYGEN MASK REGULATOR TO IDENTIFY THE P/N AND S/N	12-DEC-2012 H: 426.50 L: 209					
	Notes NOT APPLICABLE - IS N/A DUE TO P/N AND S/N INSTALLED ON AIRCRAFT						
AD 2012-0254 R1 AMD (3) Airframe AD - N/A EASA #1894	REPLACE - OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR- IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT-EACH AFFECTED FLIGHT CREW OXYGEN MASK REGULATOR	12-DEC-2012 H: 426.50 L: 209					
	Notes NOT APPLICABLE - IS N/A DUE TO P/N AND S/N INSTALLED ON AIRCRAFT						

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2012-0254 R1 AMD (2.1) Airframe AD - N/A EASA #1897	REPLACE - OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR- IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT-EACH AFFECTED FLIGHT CREW OXYGEN MASK REGULATOR WITH A SERVICEABLE PART	12-DEC-2012 H: 426.50 L: 209					
	Notes NOT APPLICABLE - IS N/A DUE TO P/N AND S/N INSTALLED ON AIRCRAFT						
AD 2012-03-05 Airframe AD - N/A FAA #444	BOMBARDIERINC., AIRPLANES - DEFORMATION AT THE NECK OF THE PRESSURE REGULATOR BODY ON CERTAIN OXYGEN CYLINDER AND REGULATOR ASSEMBLIES (CRA)	16-FEB-2012 H: 292.60 L: 134					
	Notes NOT APPLICABLE - BY A/C S/N						
AD 2012-03-05 AMD (G) Airframe AD - N/A FAA #1036	INSPECTION BOMBARDIERINC., AIRPLANES - DEFORMATION AT THE NECK OF THE PRESSURE REGULATOR BODY ON CERTAIN OXYGEN CYLINDER AND REGULATOR ASSEMBLIES (CRA) OF OXYGEN PRESSURE REGULATORS	16-FEB-2012 H: 292.60 L: 134					
	Notes NOT APPLICABLE - BY A/C S/N						
AD 2012-03-05 AMD (G)(1) Airframe AD - N/A FAA #1875	REPLACE BOMBARDIERINC., AIRPLANES - DEFORMATION AT THE NECK OF THE PRESSURE REGULATOR BODY ON CERTAIN OXYGEN CYLINDER AND REGULATOR ASSEMBLIES (CRA) THE AFFECTED OXYGEN CRA	16-FEB-2012 H: 292.60 L: 134					
	Notes NOT APPLICABLE - BY A/C S/N						
AD 2012-05-01 Airframe AD - N/A ANAC #2372	GOODYEAR TIRES PART NUMBER 299K63-1 IDENTIFIED IN GOODYEAR AVIATION 2012-32-001, INSTALLED ON CERTAIN TRANSPORT CATEGORY AIRPLANE, INCLUDING BUT NOT LIMITED TO BOMBARDIER CL-600-2B19 AIRPLANES.	12-SEP-2012 H: 0.00					
	Notes NOT APPLICABLE - N/A AS PERINSTALLED TIRE'S P/N: MAIN: 382K03-3 NOSE: 217K03-3						

Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2012-17-01 Airframe AD - N/A FAA #4677	TO PREVENT FAILURE OF THE MAIN LANDING GEAR TIRES DURING TAKEOFF OR LANDING Notes N/A BY PART NUMBER						
AD 2013-0020 Airframe AD - Open EASA #4411	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT - SYSTEMS - INSPECTION / REPLACEMENT	H: 0.00					
AD 2013-0020 AMD (1) Airframe AD - Open EASA #3310	INSPECT - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT-SYSTEMS - INSPECTION / REPLACEMENT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN TH	H: 0.00					
AD 2013-0020 AMD (3) Airframe AD - Open EASA #3383	REMOVE - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT-SYSTEMS - INSPECTION / REPLACEMENT AND REPLACE BELTS NOT MEETING THE CERTIFICATION REQUIREMENTS OR MAKE RELEVANT SEAT INOPERATIVE	H: 0.00					
AD 2013-0020 AMD (2) Airframe AD - Open EASA #3055	VERIFY - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT-SYSTEMS - INSPECTION / REPLACEMENT IF THE ORGANISATION IS LISTED AMONG THE AUTHORIZED MAINTENANCE OR REPAIR ORGANISATION REFERENCE DOCUMENTS QUOTED IN THE REF. PUBLICATIONS SECTION O	H: 0.00					
AD 2013-0020 R1 Airframe AD - Complied With EASA #1930	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT (SUPERSEDED BY AD 2013-0020R2) Notes COMPLIED WITH	02-AUG-2013 H: 432.80 L: 211					
AD 2013-03-17 AMD 39 -17351 Engine 1 AD - N/A FAA #3886	NO. 1 ENGINE - ENGINE - HPT STAGE 1 AND STAGE 2 DISC - TO PREVENT FAILURE OF DISCS DUE TO STEEL INCLUSIONS - REPLACE AFFECTED DISCS PER AD TABLE 1 Notes N/A DUE TO HPT STAGE 1 & 2 DISCS SN'S	H: 0.00					



Maintenance Items

16-Mar-2022

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2013-03-17 AMD 39 -17351 Engine 2 AD - N/A FAA #3893	NO. 2 ENGINE - ENGINE - HPT STAGE 1 AND STAGE 2 DISC - TO PREVENT FAILURE OF DISCS DUE TO STEEL INCLUSIONS - REPLACE AFFECTED DISCS PERAD TABLE 1	H: 0.00					
	Notes N/A DUE TO HPT STAGE 1 & 2 DISCS SN'S						
AD 2013-05-13 Engine 1 AD - Recurring FAA #3951	NO. 1 ENGINE - REPLACE THE FUEL PUMP SPLINED COUPLING	31-MAR-2020 H: 3741.10 C: 1233	H: 4000.00			H: 7741.10	H: 3285.30
AD 2013-05-13 Engine 2 AD - Recurring FAA #3978	NO. 2 ENGINE - REPLACE THE FUEL PUMP SPLINED COUPLING	31-MAR-2020 H: 3741.10 C: 1233	H: 4000.00			H: 7741.10	H: 3285.30
AD 2014-03-05 Airframe AD - N/A FAA #1848	ICE AND RAIN PROTECTION - MODIFY THE AIRDATA PROBES AND SENSORS (SUPERSEDED BY FAA AD 2014-26-09)	24-SEP-2014 H: 0.00					
	Notes NOT APPLICABLE - PERAIRCRAFT S/N						
AD 2014-18-01 Airframe AD - N/A FAA #3827	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION	H: 0.00					
	Notes N/A BY EQUIPMENT INSTALLED						
AD 2014-20-03 Airframe AD - Complied With FAA #2927	DETECT & CORRECT FAULTY CHECK TEE FITTINGS USED IN FIRE EXTINGUISHING (FIREEX) LINES	04-DEC-2013 H: 561.10 L: 260					
	Notes COMPLIED WITH - C/W BY SB A700-26-010 AT STANDARD AERO						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2014-26-09 Airframe AD - N/A FAA #3510	ICE AND RAIN PROTECTION - MODIFY THE AIRDATA PROBES AND SENSORS Notes N/A PER SERVICE BULLETIN 700-30-021 R1	H: 0.00					
AD 2014-26-09 AMD PARA (H) Airframe AD - N/A FAA #3045	MODIFY THE AIRDATA PROBES AND SENSORS (NEW MODIFICATION)	H: 0.00					
AD 2014-26-09 AMD PARA (G) Airframe AD - N/A FAA #3139	MODIFY THE AIRDATA PROBES AND SENSORS (RETAINED MODIFICATION)	H: 0.00					
AD 2015-08-07 Airframe AD - N/A FAA #4496	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSSES Notes N/A BY PN /SN INSTALLED	H: 0.00					
AD 2015-08-07 AMD PARA (G) Airframe AD - N/A FAA #3368	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE MXH-35-241, REVISION 3, DATED JUNE 2	H: 0.00					
AD 2015-08-07 AMD PARA (H) Airframe AD - N/A FAA #4334	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PARAGRAPH G WITH A NEW ORRE-IDENTIFIED HARNESSSES	H: 0.00					
AD 2015-10-02 Airframe AD - N/A FAA #2831	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT Notes NOT APPLICABLE - NOT INSTALLED	22-JUL-2015 H: 0.00					



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2015-10-51 Airframe AD - N/A FAA #2436	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM ORAFMS	22-JUL-2015 H: 0.00					
	Notes NOT APPLICABLE - NOT INSTALLED						
AD 2015-16-04 Airframe AD - N/A FAA #4678	TO PREVENT FIRE EXTINGUISHERS FROM FAILING TO OPERATE IN THE EVENT OF A FIRE						
	Notes N/A BY PN INSTALLED						
AD 2015-17-05 AMD PARA (H) Airframe AD - Complied With FAA #300	ACCOMPLISH A GVI FORCORRECT CLEARANCE AND, REWORK, AS APPLICABLE	27-FEB-2014 H: 673.80 L: 291					
	Notes COMPLIED WITH - PCW SB 700-27-076 REV 1						
AD 2015-17-05 AMD PARA (I) Airframe AD - Complied With FAA #57	DO THE RE-IDENTIFICATION OF THE OVERWING PANELS	27-FEB-2014 H: 673.80 L: 291					
	Notes COMPLIED WITH - PCW SB 700-27-076 REV 1						
AD 2015-17-05 Airframe AD - Complied With FAA #2981	FLIGHT CONTROLS - INSPECTING FORCORRECT CLEARANCE AND REWORK IF NECESSARY, AND, FOR CERTAIN OTHER AIRPLANES, INSTALLING A COVER FOR THE AILERON PULLEY ASSEMBLY	27-FEB-2014 H: 673.80 L: 291					
	Notes COMPLIED WITH - PCW SB 700-27-076 REV 1						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2015-17-05 AMD PARA (G) Airframe AD - Complied With FAA #1428	INSTALL A COVERFOR THE NO. 1 AILERON PULLEY, INCLUDING DOING A GVI FOR CORRECT CLEARANCE AND REWORK AS APPLICABLE	27-FEB-2014 H: 673.80 L: 291					
	Notes COMPLIED WITH - PCW SB 700-27-076 REV 1						
AD 2015-23-09 AMD PARA (H)(2)(II) Airframe AD - N/A FAA #4110	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	H: 0.00					
	Notes N/A-AS PART NOT INSTALLED ON THIS A/C						
AD 2015-23-09 AMD PARA (G) Airframe AD - N/A FAA #3446	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER	H: 0.00					
	Notes N/A-AS PART NOT INSTALLED ON THIS A/C						
AD 2015-23-09 AMD PARA (I) Airframe AD - N/A FAA #4392	OXYGEN - ZODIAC AEROTECHNICS (FORMERLLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	H: 0.00					
	Notes N/A-AS PART NOT INSTALLED ON THIS A/C						
AD 2015-23-09 Airframe AD - N/A FAA #3935	OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	H: 0.00					
	Notes N/A-AS PART NOT INSTALLED ON THIS A/C						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2015-23-09 AMD PARA (H) (1) Airframe AD - N/A FAA #4034	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II)	H: 0.00					
	Notes N/A-AS PART NOT INSTALLED ON THIS A/C						
AD 2015-23-09 AMD PARA (H)(2)(I) Airframe AD - N/A FAA #4276	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1	H: 0.00					
	Notes N/A-AS PART NOT INSTALLED ON THIS A/C						
AD 2016-01-12 AMD 39 -18371 Airframe AD - Complied With FAA #4629	TO PREVENT EXCESSIVE QUANTITIES OF FLAMMABLE FLUID ACCUMULATION IN THE AFT EQUIPMENT BAY (EFFECTIVE 25 FEBRUARY 2016)	26-JAN-2016					
	Notes C/W BY SB 700-52-042 09/12/2012						
AD 2016-10-06 AMD 39 -18517 Airframe AD - N/A FAA #4713	TO PREVENT THE TRANSMISSION OF MISLEADING NAVIGATIONAL INFORMATION (EFFECTIVE 23 JUNE 2016)	31-MAY-2016 H: 1865.90 L: 657					
	Reference Number N/A Due Aircraft S/N Per AD						
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2016-11-20 Airframe AD - N/A FAA #4717	B/E AEROSPACE PROTECTIVE BREATING EQUIPMENT PART NUMBER 119003-11 (INSPECTION)	18-AUG-2016 H: 1948.40 L: 681					
	Notes Within 3 months after July 15, 2016 (the effective date of this AD), while still in the stowage box, physically inspect the PBE pouch to determine if it has an intact vacuum seal. P/N 119003-21 SN 004-04682M PBE INSTALLED 08/18/2016. THIS AD IS NO LONGER APPLICABLE DUE TO PN						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2016-11-20 Airframe AD - Complied With FAA #4718	B/E AEROSPACE PROTECTIVE BREATING EQUIPMENT PART NUMBER 119003-11 (REPLACEMENT)	18-AUG-2016 H: 1948.40 L: 681					
	Notes SEE TASK 25-60-00-203 (1820) UPDATE						
AD 2016-11-20 AMD 39 -18547 Airframe AD - N/A FAA #4719	TO CORRECT THE UNSAFE CONDITION ON B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE) P/N 119003-11 (EFFECTIVE 15 JULY 2016)	18-AUG-2016 H: 1948.40 L: 681					
	Notes PN 119003-21 SN 004-04682M PBE INSTALLED 08/18/2016. THIS AD IS NO LONGER APPLICABLE DUE TO PN						
AD 2016-13-12 AMD 39 -18576 Engine 1 AD - N/A FAA #4725	NO. 1 ENGINE - TO PREVENT FAILURE OF THE FUEL SHUT-OFF MECHANISM (EFFECTIVE 5 AUGUST 2016)	15-JUL-2016 H: 1924.80 C: 674					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2016-13-12 AMD 39 -18576 Engine 2 AD - N/A FAA #4726	NO. 2 ENGINE - TO PREVENT FAILURE OF THE FUEL SHUT-OFF MECHANISM (EFFECTIVE 5 AUGUST 2016)	15-JUL-2016 H: 1924.80 C: 674					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2016-15-03 AMD 39 -18594 Airframe AD - Complied With FAA #4731	TO PREVENT THERMAL EXPANSION AND PERMANENT DEFORMATION AT SEVERE HOT SOAK CONDITIONS (EFFECTIVE 31 AUGUST 2016)	05-AUG-2016 H: 1937.20 L: 678					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2016-15-06 AMD 39 -18597 Airframe AD - Complied With FAA #4733	TO PREVENT THE ACCUMULATION OF EXCESS OXYGEN IN AN ENCLOSED SPACE (EFFECTIVE 08 AUGUST 2016)	21-NOV-2016 H: 2064.80 L: 722					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2016-17-16 AMD 39 -18629 Airframe AD - Complied With FAA #4756	TO PREVENT TENSATOR SPRING FAILURE (EFFECTIVE 05 OCTOBER 2016)	01-SEP-2016 H: 1954.50 L: 682					
	Notes FOUND P/C/W IAW PARAGRAPH (j) OF THE AD BY REPLACEMENT OF DOOR TENSATOR SPRINGS WITH NEW 04-MARCH-2016 ACTT:1763.7HRS LDGS: 622						
AD 2016-25-18 AMD 39 -18744 Airframe AD - Complied With FAA #4788	TO DETECT AND CORRECT BROKEN ENGINE ATTACHMENT HARDWARE (EFFECTIVE 3 JANUARY 2017)	29-DEC-2016 H: 2101.80 L: 737					
AD 2017-04-06 AMD 39 -18801 Airframe AD - N/A FAA #4798	TO PREVENT DISPLAY OF MISLEADING ALTITUDE DATA FROM UNITED INSTRUMENTS, INC. 5934 SERIES ALTIMETERS (EFFECTIVE 07 APRIL 2017)	22-MAR-2017 H: 2216.00 L: 784					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2017-11-11 AMD 39 -18910 Airframe AD - N/A FAA #4805	THE UNSAFE CONDITION AS AN ADS-B UNIT INCORRECTLY BROADCASTING A SOURCE INTEGRITY LEVEL (SIL) OF 3 INSTEAD OF ITS AUTHORIZED SIL OF 0 (EFFECTIVE 11 JULY 2017)	16-JUL-2017 H: 2353.60 L: 823					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2017-14-15 AMD 39 -18959 Airframe AD - Complied With FAA #4811	TO DETECT AND CORRECT OUT-OF-TOLERANCE TENSION IN THE CONTROL CABLES (EFFECTIVE 31 AUGUST 2017)	29-JAN-2018 H: 2586.20 L: 898					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2017-16-01 AMD 39 -18978 Airframe AD - N/A FAA #4816	TO DETECT AND CORRECT NONFUNCTIONING AMERI-KING CORPORATION ELT MODELS AK-450 AND AK-451 (EFFECTIVE 24 OCTOBER 2017)						
	Notes ELT MODELS NOT INSTALLED ON AIRCRAFT						
AD 2017-18-12 AMD 39 -19021 Airframe AD - Complied With FAA #4814	UNSAFE CONDITION OF A B/E AEROSPACE PBE UNIT WITHIN A CERTAIN SERIAL NUMBER RANGE ARE MADE WITH CANDLE TUBE MATERIAL DETERMINED TO HAVE A LOW YIELD STRENGTH AND MAY BE VOLATILE UPON USE OR DISPOSAL (EFFECTIVE 16 OCTOBER 2017)	13-SEP-2017 H: 2422.20 L: 849					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2017-19-11 AMD 39 -19041 Airframe AD - Complied With FAA #4815	TO DETECT AND CORRECT A DORMANT FAILURE OF BOTH FCU BACK-UP MODULES (EFFECTIVE 23 OCTOBER 2017)	16-NOV-2018					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2017-22-02 AMD 39 -19082 Airframe AD - N/A FAA #4822	IPECO HOLDINGS LTD. SEATS - TO PREVENT UNEXPECTED MOVEMENT OF PILOT AND CO-PILOT SEATS ON TAKEOFF AND LANDING (EFFECTIVE 12 DECEMBER 2017)	13-DEC-2017 H: 2586.20 L: 898					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2017-22-14 Airframe AD - N/A FAA #4826	ROCKWELL COLLINS FLS - TO PREVENT ERRONEOUS EXTRAPOLATION OF POSITION/VELOCITY AND ALTITUDE DATA (EFFECTIVE 20 DECEMBER 2017)	16-JAN-2018 H: 2586.20 L: 898					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2018-03-04 AMD 39 -19177 Airframe AD - N/A FAA #4843	ROSEMOUNT AEROSPACE 851AK PITOT PROBES - TO PREVENT INCORRECT AIRSPEED INDICATIONS DURING FLIGHT (EFFECTIVE 16 MARCH 2018)	15-FEB-2018 H: 2590.30 L: 900					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2018-09-15 AMD 39 -19272 Airframe AD - Complied With FAA #4854	TO DETECT AND CORRECT BROKEN ENGINE ATTACHMENT HARDWARE (EFFECTIVE 15 JUNE 2018)	21-MAY-2018 H: 2727.40 L: 933					
AD 2018-16-01 AMD 39 -19341 Airframe AD - N/A FAA #4866	TO PREVENT MALFUNCTION OF THE EA ON THE SEAT (EFFECTIVE 31 AUGUST 2018)	20-AUG-2018 H: 2832.70 L: 977					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2018-16-13 AMD 39 -19353 Airframe AD - N/A FAA #4870	TO PREVENT FAILURE OF THESE ATTENDANT SEATS (EFFECTIVE 26 OCTOBER 2018)	08-OCT-2018 H: 2919.10 L: 1001					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2018-18-14 AMD 39 -19393 Engine 1 AD - N/A FAA #4812	TO PREVENT FAILURE OF THE EEC (EFFECTIVE 12 OCTOBER 2018)	08-OCT-2018 H: 2919.10 C: 1001					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2018-18-14 AMD 39 -19393 Engine 2 AD - N/A FAA #4834	TO PREVENT FAILURE OF THE EEC (EFFECTIVE 12 OCTOBER 2018)	08-OCT-2018 H: 2919.10 C: 1001					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2018-19-15 AMD 39 -19415 Airframe AD - N/A FAA #4877	TO PREVENT FAILURE OF THE SEATS TO PERFORM THEIR INTENDED FUNCTION GEVEN TYPE D1-02 AND D1-03 (EFFECTIVE 14 NOVEMBER 2018)	14-OCT-2018 H: 2919.10 L: 1001					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2018-20-20 AMD 39 -19454 Airframe AD - N/A FAA #4881	TO ADDRESS ANY CRACKING IN THE SUPPORT BRACKET OF THE ELEVATOR BELL CRANK (EFFECTIVE 20 NOVEMBER 2018)	16-OCT-2018 H: 2941.50 L: 1004					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2018-21-03 AMD 39 -19461 Airframe AD - Complied With FAA #4880	TO ADDRESS IN-FLIGHT DEPARTURES OF THE AFT BELLY FAIRING ACCESS PANELS (EFFECTIVE 19 NOVEMBER 2018)	23-NOV-2016 H: 2064.80 L: 722					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2018-21-14 AMD 39 -19472 Airframe AD - N/A FAA #4907	JOINT AIRCRAFT SERVICICE COMPONENT (JASC) CODE: 3510, CREW OXYGEN SYSTEM (EFFECTIVE 03-27-2019)	05-MAR-2022 H: 4446.70 L: 1492					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2018-21-14 Airframe AD - N/A FAA #4906	TO ADDRESS THE UNSAFE CONDITION OF ZODIAC AEROTECHNICS OXYGEN MASK REGULATORS	05-MAR-2022 H: 4446.70 L: 1492					
AD 2018-22-08 AMD 39 -19481 Airframe AD - Complied With FAA #4891	TO ADDRESS THIS WIRING DISCREPANCY - NON-CONFORMING FIREX SQUIB WIRE HARNESS CONNECTORS MAY HAVE BEEN INSTALLED (EFFECTIVE 10 DECEMBER 2018)	01-DEC-2018					
	Notes PCW PER SB						
AD 2018-23-01 AMD 39 -19487 Airframe AD - N/A FAA #4889	TO PREVENT FAILURE OF AFFECTED SEATS. THE UNSAFE CONDITION, IF NOT ADDRESSED, COULD RESULT IN INJURY TO THE SEAT OCCUPANTS (EFFECTIVE 28 DECEMBER 2018)	06-DEC-2018 H: 3029.90 L: 1033					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2018-23-12 AMD 39 -19499 Airframe AD - N/A FAA #4890	TO ADDRESS FUSIBLE PLUGS THAT MIGHT ACTIVATE BELOW THE RATED TEMPERATURE AND RENDER THE EVACUATION SYSTEM UNUSABLE (EFFECTIVE 28 DECEMBER 2018)	06-DEC-2018 H: 3029.90 L: 1033					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2018-25-07 AMD 39 -19518 Airframe AD - Complied With FAA #4893	TO ADDRESS FLUID LEAKAGE THAT COULD LEAD TO THE ACCUMULATION OF FLAMMABLE FLUIDS/VAPORS (EFFECTIVE 15 JANUARY 2019)	11-DEC-2018 H: 3033.70 L: 1035					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2019-01-02 AMD 39 -19541 Airframe AD - N/A FAA #4898	JOINT AIRCRAFT SYSTEM COMPONENT (JASC): 3410, FLIGHT ENVIRONMENT DATA; AND 3420, ATTITUDE AND DIRECTION DATA SYSTEM (7, FEBRUARY, 2019)	28-JAN-2019 H: 3131.30 L: 1057					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2019-03-22 AMD 39 -19574 Airframe AD - Complied With FAA #4909	TO ADDRESS THIS CONDITION, WHICH COULD LEAD TO A LOSS OF HARDWARE AND RESULT IN AN ACTUATOR DISCONNECT AND THE NLG FAILING TO RETRACT OR EXTEND (EFFECTIVE 15 APRIL 2019)	14-APR-2021 H: 3992.00 L: 1324					
AD 2019-07-03 AMD 39 -19614 Airframe AD - N/A FAA #4916	UNSAFE CONDITION, IF NOT ADDRESSED, COULD RESULT IN FAILURE OF THE SEAT OCCUPIED BY THE CABIN ATTENDANT, AND POSSIBLE INJURY TO THE CABIN ATTENDANT (EFFECTIVE 16 MAY 2019)	22-APR-2019 H: 3277.00 L: 1097					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2019-07-10 AMD 39 -19621 Airframe AD - N/A FAA #4919	NORTHROP GRUMMAN LITEF GMBH LCR-100 ATTITUDE AND HEADING REFERENCE SYSTEM (EFFECTIVE 29 MAY 2019)	26-APR-2019 H: 3286.30 L: 1099					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2019-08-01 AMD 39 -19622 Airframe AD - N/A FAA #4922	JOINT AIRCRAFT SYSTEM COMPONENT (JASC) CODE 2520, PASSENGER COMPARTMENT EQUIPMENT (EFFECTIVE 21 MAY 2019)	14-MAY-2019 H: 3296.60 L: 1105					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2019-12-02 AMD 39 -19657 Airframe AD - Complied With FAA #4930	TO ADDRESS THIS UNSAFE CONDITION, WHICH COULD RESULT IN A HYDRAULIC/FUEL LEAK AND ELECTRICAL ARCING AS AN IGNITION SOURCE (EFFECTIVE 12 AUGUST 2019)	30-JUL-2019 H: 3424.90 L: 1147					
AD 2019-12-09 AMD 39 -19664 Airframe AD - N/A FAA #4931	TO PREVENT CONFLICTING TCAS INFORMATION (EFFECTIVE 23 JULY 2019)	15-JUL-2019 H: 3387.90 L: 1137					
AD 2020-03-21 AMD 39 -19845 Airframe AD - N/A FAA #4959	TO ADDRESS POSSIBLE CORROSION ON THE INNER DIAMETER OF THE MLG TRAILING ARM ASSEMBLY AXLE BORE, WHICH, IF NOT DETECTED AND CORRECTED, COULD LEAD TO MLG COLLAPSE. (EFFECTIVE 12 MARCH 2020)	27-FEB-2020 H: 3695.30 L: 1216					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2020-05-27 AMD 39 -19877 Airframe AD - Open FAA #5005	TO ADDRESS CRACKING IN THE RUDDER QUADRANT SUPPORT STRUCTURE, WHICH CAN LEAD TO PROGRESSIVE DETERIORATION IN THE PERFORMANCE OF THE SYSTEMM (EFFECTIVE 07 MAY 2020)						
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2020-12-14 AMD 39 -19923 Airframe AD - Complied With FAA #5045	ISSUING THIS AD TO ADDRESS THIS CONDITION WHICH, IF NOT CORRECTED, COULD RESULT IN THE INABILITY TO POWER ESSENTIAL SYSTEMS IN THE EVENT THAT OTHER SOURCES OF POWER ARE ALSO LOST (EFFECTIVE 8 SEPTEMBER 2020)	21-SEP-2020 H: 3875.30 L: 1284					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2020-18-51 Airframe AD - N/A FAA #5059	ISSUING THIS EMERGENCY AD TO PREVENT AERONAUTICAL DECISION-MAKING BASED ON ERRONEOUS ATTITUDE INFORMATION, WHICH MAY RESULT IN LOSS OF CONTROL OF THE AIRCRAFT (EFFECTIVE 28 AUGUST 2020)	01-SEP-2020 H: 3844.20 L: 1271					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2021-03-17 AMD 39 -21420 Airframe AD - N/A FAA #5093	TO ADDRESS SUCH CONDITIONS, WHICH COULD CAUSE FIRE ONBOARD THE AIRPLANE. SMOKE AND SIGNS OF AN OVERHEATING CONDITION FROM THE EMERGENCY LIGHT BATTERY (ELB) DUE TO EXCESSIVE CORROSION SURROUNDING THE INTERNAL LEAD ACID BATTERIES (EFFECTIVE 30 MARCH 2021)	16-APR-2021					
	Notes NA DUE TO A/C S/N						
AD 2021-07-13 Airframe AD - N/A FAA #5100	THE FAA IS ADOPTING A NEW AIRWORTHINESS DIRECTIVE (AD) FOR CERTAIN PACIFIC SCIENTIFIC COMPANY ROTARY BUCKLE ASSEMBLIES (BUCKLES). THIS AD REQUIRES INSPECTING EACH BUCKLE INCLUDING ITS BUCKLE HANDLE VANE, AND DEPENDING ON THE RESULTS, REMOVING THE BUCKLE FROM SERVICE AND INSTALLING AN AIRWORTHY BUCKLE (11 MAY 2021).	16-APR-2021					
	Notes NA DUE TO EQUIPMENT NOT INSTALLED						
AD 2021-08-07 AMD 39 -21501 Airframe AD - N/A FAA #5101	ISSUING THIS AD TO PREVENT A MISLEADING GPS POSITION ON AN LPV APPROACH. THE UNSAFE CONDITION, IF NOT ADDRESSED, COULD RESULT IN A MISLEADING GPS POSITION ON AN LPV APPROACH RESULTING IN CONTROLLED FLIGHT INTO TERRAIN (EFFECTIVE 12 MAY 2021)	08-APR-2021 H: 3992.00 L: 1324					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ADDITIONALLY, INCLUDE ANY INSTRUCTIONS FOR THE CONTROL OF CORRELATED SUB PARTS.						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2021-08-11 AMD 39 -21505 Airframe AD - Complied With FAA #5102	AIR TRANSPORT ASSOCIATION (ATA) OF AMERICA CODE 27, FLIGHT CONTROLS. (EFFECTIVE 27 APRIL 2021)	16-APR-2021 H: 3992.00 L: 1324					
AD 2021-10-02 AMD 39 -21535 Airframe AD - Recurring FAA #5142	ELEVATOR TORQUE TUBE BEARINGS: THIS AD REQUIRES REPETITIVE GVI OF THE LEFT- AND RIGHT HAND ELEVATOR TORQUE TUBE BEARINGS FOR ANY SAND, DUST, OR CORROSION; REPETITIVE FUNCTIONAL TESTS OF ELEVATOR CONTROL SYSTEM; AND REPLACEMENT OF ELEVATOR TORQUE TUBE BEARINGS IF NECESSARY (EFFECTIVE 29 JULY 2021)	27-JUN-2021 H: 4111.10 L: 1373	M: 63			04-JUN-2026	M: 50 D: 19
Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ADDITIONALLY, INCLUDE ANY INSTRUCTIONS FOR THE CONTROL OF CORRELATED SUB PARTS.							
AD 2021-12-07 AMD 39 -21594 Engine 1 AD - N/A FAA #4855	QUALITY ESCAPE DURING THE HIGH-PRESSURE TURBINE (HPT) STAGE 1 DISK RIM COOLING AIR HOLE MANUFACTURING PROCESS. THIS AD REQUIRES REMOVING AFFECTED HPT DISKS FROM SERVICE PRIOR TO REACHING SPECIFIED COMPLIANCE TIMES OR AT THE NEXT ENGINE SHOP VISIT (EFFECTIVE 12 AUGUST 2021)	02-SEP-2021 H: 4258.30 C: 1423					
Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ADDITIONALLY, INCLUDE ANY INSTRUCTIONS FOR THE CONTROL OF CORRELATED SUB PARTS. PER THIS AD, COMPLY BY 2840 CYCLES OR WITHIN 60 DAY OF AUGUST 12, 2021.							
AD 2021-12-07 AMD 39 -21594 Engine 2 AD - N/A FAA #4877	QUALITY ESCAPE DURING THE HIGH-PRESSURE TURBINE (HPT) STAGE 1 DISK RIM COOLING AIR HOLE MANUFACTURING PROCESS. THIS AD REQUIRES REMOVING AFFECTED HPT DISKS FROM SERVICE PRIOR TO REACHING SPECIFIED COMPLIANCE TIMES OR AT THE NEXT ENGINE SHOP VISIT (EFFECTIVE 12 AUGUST 2021)	02-SEP-2021 H: 4258.30 C: 1423					
Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ADDITIONALLY, INCLUDE ANY INSTRUCTIONS FOR THE CONTROL OF CORRELATED SUB PARTS.							
AD 2021-21-04 AMD 39 -21764 Airframe AD - Complied With FAA #5152	REPORTED MISSING SLIDING BUSHINGS IN THE FORWARD ENGINE MOUNT SYSTEM. AN INSPECTION (GAP CHECK) IS REQUIRED OF THE FRONT AND AFT ENGINE MOUNTS TO VERIFY THE PROPER INSTALLATION OF THE SLIDING BUSHINGS, AND REPAIR IF NECESSARY. (EFFECTIVE 8 DECEMBER 2021)	20-DEC-2021 H: 4399.80 L: 1478					
Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ADDITIONALLY, INCLUDE ANY INSTRUCTIONS FOR THE CONTROL OF CORRELATED SUB PARTS.							



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2021-21-12 AMD 39 -21772 Engine 1 AD - N/A FAA #4858	FLIGHT DATA OBTAINED FROM AIRPLANES EQUIPPED WITH CERTAIN ROCKWELL COLLINS AVIONICS AND AUTO-THROTTLE SYSTEMS WHICH DEMONSTRATED SIGNIFICANT OSCILLATION OF THE ENGINE ROTOR REVOLUTION SPEED DURING FLIGHT. RECALCULATE THE CONSUMED AND REMAINING SERVICE LIFE OF EACH AFFECTED LLP USING ACCOMPLISHMENT INSTRUCTIONS. (EFFECTIVE 13 DECEMBER 2021)	30-NOV-2021 H: 4368.30 C: 1464					
Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ADDITIONALLY, INCLUDE ANY INSTRUCTIONS FOR THE CONTROL OF CORRELATED SUB PARTS.							
AD 2021-21-12 AMD 39 -21772 Engine 2 AD - N/A FAA #5146	FLIGHT DATA OBTAINED FROM AIRPLANES EQUIPPED WITH CERTAIN ROCKWELL COLLINS AVIONICS AND AUTO-THROTTLE SYSTEMS WHICH DEMONSTRATED SIGNIFICANT OSCILLATION OF THE ENGINE ROTOR REVOLUTION SPEED DURING FLIGHT. RECALCULATE THE CONSUMED AND REMAINING SERVICE LIFE OF EACH AFFECTED LLP USING ACCOMPLISHMENT INSTRUCTIONS. (EFFECTIVE 13 DECEMBER 2021)	30-NOV-2021 H: 4368.30 C: 1464					
Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ADDITIONALLY, INCLUDE ANY INSTRUCTIONS FOR THE CONTROL OF CORRELATED SUB PARTS.							
AD CF-1996-21 Airframe AD - N/A TCCA #2341	NICKEL CADMIUM-BATTERY.	19-MAR-2010 H: 0.00					
Notes NOT APPLICABLE							
AD CF-2008-31 Airframe AD - N/A TCCA #2383	ELEVATORPCU ATTACHMENT BOLT FRACTURE - ALL PART NUMBER (P/N) GT411-3800-5 AND GT411-3800-7 PCU ATTACHMENT JOINTS	19-MAR-2010 H: 0.00					
Notes NOT APPLICABLE - BY EFFECTIVITY NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER							
AD CF-2009-44 Airframe AD - N/A TCCA #2536	EMERGENCY LOCATORTRANSMITTER - POTENTIAL FAILURE TO TRANSMIT THE REQUIRED 406MHZ CODED SIGNAL	23-JAN-2011 H: 0.00					
Notes NOT APPLICABLE - NOT APPLICABLE BY ELT MANUFACTURER? ARTEX ELT INSTALLED							



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD CF-2010-01 AMD PART I Airframe AD - N/A TCCA #1626	IDENTIFICATION - RAM AIRTURBINE (RAT) - NON-CONFORMING BALANCE WASHER SCREWS- CHECK	19-MAR-2010 H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER						
AD CF-2010-01 Airframe AD - Complied With TCCA #1710	RAM AIRTURBINE (RAT) - NON-CONFORMING BALANCE WASHER SCREWS	19-MAR-2010 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION PART III NOT APPLICABLE BY COMPONENT SERIAL NUMBER INSTALLED						
AD CF-2010-01 AMD PART II Airframe AD - N/A TCCA #1466	REPLACEMENT - RAM AIRTURBINE (RAT) - NON-CONFORMING BALANCE WASHER SCREWS- OF THE BALANCE WASHER SCREWS AND IDENTIFICATION OF THE RAT	19-MAR-2010 H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER						
AD CF-2010-10 Airframe AD - Complied With TCCA #1923	HYDRAULIC SYSTEMS NUMBER 2 AND 3: DAMAGE CAUSED BY MAIN LANDING GEAR TIRE FAILURE	23-JAN-2011 H: 0.00					
	Notes COMPLIED WITH - AT COMPLETION INCORPORATION OF BOMBARDIER SB 700-29-021						
AD CF-2010-14 Airframe AD - N/A TCCA #1709	PASSENGER DOOR - TENSATOR SPRINGS FAILURE (SUPERSEDED BY TCCA AD CF-2014-39)	23-JAN-2011 H: 0.00					
	Notes NOT APPLICABLE - BY EFFECTIVITY NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER						
AD CF-2011-10 Airframe AD - N/A TCCA #1187	OXYGEN SUPPLY SYSTEM - DEFORMATION OF THE PRESSURE REGULATOR ON THE OXYGEN CYLINDER AND REGULATOR ASSEMBLY	22-DEC-2011 H: 253.80 L: 116					
	Notes NOT APPLICABLE						





Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD CF-2012-32 Airframe AD - Open TCCA #3355	ICE PROTECTION SYSTEM - INABILITY TO DETECT NUMBER2 PITOT STATIC PROBE HEATER FAILURE	H: 0.00					
AD D-2000-348 R6 AMD PART 5 Engine 1 AD - N/A LBA #1657	NO. 1 ENGINE - VISUAL AND ULTRASONIC INSP OF FAN DISC, ALL P/NS Notes NOT APPLICABLE - BY EFFECTIVITY	25-FEB-2010 H: 0.00					
AD D-2000-348 R6 AMD PART 4 Engine 1 AD - N/A LBA #1371	NO. 1 ENGINE - VISUAL ORULTRASONIC INSP FAN DISC, P/N BRR20791 Notes NOT APPLICABLE - BY EFFECTIVITY	25-FEB-2010 H: 0.00					
AD D-2000-348 R6 AMD PART 5 Engine 2 AD - N/A LBA #2984	NO. 2 ENGINE - VISUAL AND ULTRASONIC INSP OF FAN DISC, ALL P/NS Notes NOT APPLICABLE - BY EFFECTIVITY	25-FEB-2010 H: 0.00					
AD D-2000-348 R6 AMD PART 4 Engine 2 AD - N/A LBA #1016	NO. 2 ENGINE - VISUAL ORULTRASONIC INSP FAN DISC, P/N BRR20791 Notes NOT APPLICABLE - BY EFFECTIVITY	25-FEB-2010 H: 0.00					
AD D-2007-352 Engine 1 AD - N/A LBA #1028	NO. 1 ENGINE - REVERSE WIRED INDEPENDENT OVERSPEED PROTECTION COILS IN BR700 SERIES ENGINES - TEST OF THE OVERSPEED SHUTOFF SOLENOID VALVE IOP COIL WIRING ON FUEL METERING UNIT (FMU) OF CORRECT POLARITY.	15-JAN-2010 H: 0.00					
	Notes NOT APPLICABLE						



Maintenance Items

N393BV

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD D-2007-352 Engine 2 AD - N/A LBA #2070	NO. 2 ENGINE - REVERSE WIRED INDEPENDENT OVERSPEED PROTECTION COILS IN BR700 SERIES ENGINES - TEST OF THE OVERSPEED SHUTOFF SOLENOID VALVE IOP COIL WIRING ON FUEL METERING UNIT (FMU) OF CORRECT POLARITY.	15-JAN-2010 H: 0.00					
	Notes NOT APPLICABLE						