

Company

Owner: 2106701 Ontario Inc O/A NovaJet
Operator:

Major Assemblies

Airframe	208B Caravan	208B5277	11-Apr-2022	357.3 Hrs	620 Ldg
Eng 1	PT6A-140	PCE-VA0304	11-Apr-2022	357.3 Hrs	620 Enc
Prop 1	HC-B3TN-3AF	BUA33483	11-Apr-2022	357.3 Hrs	0 PRC

Additional Information

General Categories: RVSM,EMM,FAR 91,Typical,Severe

Cost:
Man Hrs: 3,619.6+

Analyst: Martin Lebel mlebel@traxxall.com

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time Remaining
SEQ	PN/SN	MOC Note or Component Condition							DUE	
▼ 5 - TIME LIMITS/MAINTENANCE CHECKS										
CAB11-5	New 208/208B Task-Based Inspection Program									
5 A/F								RE (-)	Optional	
Eff: 08-Jul-2011										
CAB11-5 R1	Time Limits/Maintenance Checks - New 208/208B Task-Based Inspection Program									
5 A/F								T (-)	Optional	
Eff: 16-May-2014										
CAB11-5 R2	Time Limits/Maintenance Checks - New 208/208B Task-Based Inspection Program									
5 A/F								T (A/R)	Optional	
Eff: 20-Mar-2020										
CAL-05-01	Task-Based Inspection Program - Task 0A for 14CFR Par 91.409 (A) and (B)									
5 A/F								T (-)	Informational	
Eff: 03-Oct-2014										
CAL-05-01 R1	Time Limits/Maintenance Checks - Inspection Document 0A for 14 CFR Part 91.409 (A) and (B)									
5 A/F								T (A/R)	Informational	
Eff: 17-Mar-2020										
CAL-05-02	Time Limits/Maintenance Checks - New C100490-1 Oil Cooler Check Valve (Check Valve Assembly Repair) Restoration Interval Implementation Grace Period									
5 A/F								T (A/R)	Informational, Service Letter	
Eff: 09-May-2019										
SNL00-02	Service Publications Temporary Revision Changes									
5 A/F								T (A/R)	Service Newsletter	
Eff: 17-Jan-2000										
SNL87-4	New Progressive Care Inspection Program for Caravan I Airplanes									
5 A/F								T (A/R)	Informational	
Eff: 23-Jan-1987										
SNL88-06	Revised Progressive Care Inspection Manual and Obsolete Progressive Care Inspection Operation Schedules									
5 A/F								T (A/R)	Service Newsletter	
Eff: 25-Mar-1988										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SNL90-14	New Caravan I Phasecard Inspection Program								T (A/R)	Informational
5 A/F										Mos
Eff: 28-Dec-1990										Hrs
										Ldg
SNL91-05	Temporary Revisions to Service/Maintenance Manuals and Illustrated Parts Catalogs								T (A/R)	Service Newsletter
5 A/F										Mos
Eff: 13-Dec-1991										Hrs
										Ldg
SNL94-13	Revised Progressive Care and Continuous Inspection Operations Manual								T (A/R)	Informational
5 A/F										Mos
Eff: 30-Dec-1994										Hrs
										Ldg
SNL98-08	Revised Maintenance Practices - Hazardous Air Pollutants Standard								RE (-)	Service Newsletter
5 A/F										Mos
Eff: 20-Jul-1998										Hrs
										Ldg
SNL98-08R1	Revised Maintenance Practices - Hazardous Air Pollutants Standard								T (A/R)	Service Newsletter
5 A/F										Mos
Eff: 02-Nov-1998										Hrs
										Ldg
▼ 11 - PLACARDS AND MARKINGS										
2008-10-02	Alternate Static Air Source Selector Valve - Part Number Identification Placard - Inspection								RE (-)	Mandatory
11 A/F										Mos
Eff: 12-May-2008 Not Applicable	AIRCRAFT NOT IN EFFECTIVE SERIAL RANGE.						29-Jun-2016			Hrs
(NOTE: APPLICABILITY: For static air source selector valves installed before May 12, 2008.)							0			Ldg
							0			
CAB88-25	Partition Net Placard Installation								T (A/R)	Recommended
11 A/F										Mos
Eff: 29-Jul-1988										Hrs
										Ldg
CAB96-5	Annunciator Panel Placard Installation								T (A/R)	Recommended
11 A/F										Mos
Eff: 26-Jan-1996										Hrs
										Ldg
CAL-11-01	208B EX Equipment List Correction								RE (-)	Recommended
11 A/F										Mos
Eff: 13-Aug-2013										Hrs
										Ldg
SNL06-17	New ELT Placards								T (A/R)	Informational
11 A/F										Mos
Eff: 18-Dec-2006										Hrs
										Ldg
▼ 12 - SERVICING - ROUTINE MAINTENANCE										
CAL-12-01	Transmittal of Pratt & Whitney Canada Service Information Letter S.I.L. No. PT6A-196								T (A/R)	Informational
12 A/F										Mos
Eff: 01-Nov-2012										Hrs
										Ldg
CAL-12-02	Transmittal of Pratt & Whitney Canada Service Bulletin P&WC S.B. No. 1001R29								T (A/R)	Informational
12 A/F										Mos
Eff: 04-Aug-2014										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
▼ 20 - STANDARD PRACTICES – AIRFRAME										
CAL-20-01	Listing of Nondestructive Testing Facilities						T (A/R)		Informational	
20 A/F										Mos
Eff: 09-Oct-2014										Hrs
										Ldg
▼ 21 - AIR CONDITIONING AND PRESSURIZATION										
CAB04-12	Air Conditioning Conversion From R12 to R134A Refrigerant						T (A/R)		Optional	
21 A/F										Mos
Eff: 01-Nov-2004										Hrs
(AVG MAN HRS: 4)										Ldg
CAB04-8	Air Conditioner Compressor Drive Inspection						RE (-)		Mandatory	
21 A/F										Mos
Eff: 06-Sep-2004										Hrs
(AVG MAN HRS: 6)										Ldg
CAB04-8 Rev 1	Air Conditioner Compressor Drive Inspection						T (A/R)		Mandatory	
21 A/F										Mos
Eff: 11-Jun-2007										Hrs
(AVG MAN HRS: 6)										Ldg
CAB05-11	R134A Air Conditioner System Installation						RE (-)		Optional	
21 A/F										Mos
Eff: 03-Oct-2005										Hrs
(AVG MAN HRS: 145)										Ldg
CAB05-11 Rev 1	R134A Air Conditioner System Installation						RE (-)		Optional	
21 A/F										Mos
Eff: 18-Jan-2011										Hrs
(AVG MAN HRS: 145)										Ldg
CAB09-3	Line and Tube Assemblies Inspection						T (A/R)		Mandatory	
21 A/F										Mos
Eff: 08-Jun-2009										Hrs
										Ldg
CAB-21-01	Cabin Heat Bleed Air Flow Restrictor Modification						RE (-)		Mandatory	
21 A/F										Mos
Eff: 10-Oct-2013										Hrs
(AVG MAN HRS: 1.5)										Ldg
CAB-21-03	R134A Air Conditioner System Installation for Airplanes Equipped With G1000 and 675 SHP Engine						RE (-)		Optional	
21 A/F										Mos
Eff: 31-May-2017										Hrs
										Ldg
CAB-21-04	R134A Air Conditioner System Installation for Airplanes Equipped with G1000 and 867 SHP Engine						T (A/R)		Optional	
21 A/F										Mos
Eff: 01-Jun-2017										Hrs
										Ldg
CAB-21-05	Air Conditioning - Replacement of P3 Heater (Flow) Control Valve Effectivity						T (A/R)		Optional	
21 A/F										Mos
Eff: 13-Apr-2017										Hrs
										Ldg
CAB90-9	Airborne Bleed Air Valves Retrofit Kit						RE (-)		Optional	
21 A/F										Mos
Eff: 23-Mar-1990										Hrs
(AVG MAN HRS: 6)										Ldg












Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB90-9 Rev 1	Airborne Bleed Air Valves Retrofit Kit								T (A/R)	Optional
21 A/F										Mos
Eff: 15-Jun-1990										Hrs
(AVG MAN HRS: 6)										Ldg
CAB91-12	Air Conditioner Condenser Cowl Seal Replacement								T (A/R)	Recommended
21 A/F										Mos
Eff: 26-Apr-1991										Hrs
										Ldg
CAB91-25	Air Conditioner Compressor Drive Assembly End Cap Replacement								T (A/R)	Recommended
21 A/F										Mos
Eff: 16-Aug-1991										Hrs
										Ldg
CAB91-26	Heater Valve Improvement								T (A/R)	Optional
21 A/F										Mos
Eff: 30-Aug-1991										Hrs
										Ldg
CAB92-4	Forward Fuselage Side Vent Installation Sealing								T (A/R)	Recommended
21 A/F										Mos
Eff: 14-Feb-1992										Hrs
										Ldg
ICA-208-21-00001	Air Conditioning - Heater Valve Replacement								T (A/R)	ICA Supplement
21 A/F										Mos
Eff: 13-Apr-2016										Hrs
										Ldg
▼ 22 - AUTOFLIGHT										
2001-10-09	Automatic Flight Control Systems								RE (-)	Mandatory (Appliance AD)
22 A/F										Mos
Eff: 15-Jun-2001 Not Applicable	HONEYWELL KC225 AUTOPILOT. PARTS NOT INSTALLED.F						29-Jun-2016			Hrs
										0
										Ldg
										0
2009-15-05	Yaw Bridle Cable Tension								RE (-)	Mandatory
22 A/F										Mos
Eff: 27-Jul-2009 Not Applicable	AIRCRAFT NOT IN SERIAL RANGE.						29-Jun-2016			Hrs
										0
										Ldg
										0
CAB01-14	KFC 225 Automatic Flight Control Computer System Restrictions								T (A/R)	Mandatory
22 A/F										Mos
Eff: 10-Dec-2001										Hrs
										Ldg
CAB03-12	Honeywell KC 225 Flight Control Computer Modification								T (A/R)	Recommended
22 A/F										Mos
Eff: 22-Sep-2003										Hrs
										Ldg
CAB06-5	Honeywell KS270C Pitch Servo and KS271C Roll Servo Tach Generator Modification								T (A/R)	Optional
22 A/F										Mos
Eff: 01-May-2006										Hrs
										Ldg
CAB08-9	Garmin GFC-700 Autopilot Roll and Yaw Servos Bridle Cable Clamps Inspection								T (A/R)	Mandatory
22 A/F										Mos
Eff: 24-Nov-2008										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
▼ 23 - COMMUNICATIONS										
CAB00-4	KY 196A VHF COMM Transceiver Modification								T (A/R)	Recommended
23 A/F										Mos
Eff: 17-Apr-2000										Hrs
										Ldg
CAB01-3	KMA24 Audio Panel Wiring Modification								T (A/R)	Mandatory
23 A/F										Mos
Eff: 29-Jan-2001										Hrs
										Ldg
CAB91-35	Microphone Switch Diode Installation								T (A/R)	Mandatory
23 A/F										Mos
Eff: 13-Dec-1991										Hrs
										Ldg
CAB97-11	Electrical Isolation of Pilot and Copilot Press to Talk Switches								RE (-)	Recommended
23 A/F										Mos
Eff: 22-Sep-1997										Hrs
(AVG MAN HRS: 1.5)										Ldg
CAB97-11 Rev 1	Electrical Isolation of Pilot and Copilot Press to Talk Switches								T (A/R)	Recommended
23 A/F										Mos
Eff: 27-Oct-1997										Hrs
(AVG MAN HRS: 1.5)										Ldg
▼ 24 - ELECTRICAL POWER										
2008-13-06	Right Wing Wire Bundles								RE (-)	Mandatory
24 A/F										Mos
Eff: 30-Jul-2008 Not Applicable	AIRCRAFT NOT IN EFFECTIVE SERIAL RANGE.						29-Jun-2016			Hrs
							0			Ldg
							0			
AK208-14	Ni-Cad to Sealed Lead-Acid Battery Conversion								T (A/R)	
24 A/F										Mos
Eff: 02-Feb-1996										Hrs
										Ldg
CAB00-2	Generator Contactor Transorb Installation								T (A/R)	Optional
24 A/F										Mos
Eff: 06-Mar-2000										Hrs
(AVG MAN HRS: 1)										Ldg
CAB01-15	Emergency Power Lever Shear Wire Installation								T (A/R)	Mandatory
24 A/F										Mos
Eff: 17-Dec-2001										Hrs
										Ldg
CAB02-10	KAC 501 Radar and KAC 502 Terrain Module Modification								T (A/R)	Optional
24 A/F										Mos
Eff: 12-Aug-2002										Hrs
										Ldg
CAB02-7	Concord SLA Replacement Battery Installation								RE (-)	Mandatory
24 A/F										Mos
Eff: 20-May-2002										Hrs
										Ldg
CAB02-7 Rev 1	Concord SLA Replacement Battery Installation								T (A/R)	Mandatory
24 A/F										Mos
Eff: 12-Aug-2002										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB03-3	Flight Hourmeter Electrical Wiring Modification								RE (-)	Mandatory
24 A/F										
Eff: 24-Mar-2003										
(AVG MAN HRS: 1)										
CAB03-3 Rev 1	Flight Hourmeter Electrical Wiring Modification								T (A/R)	Mandatory
24 A/F										
Eff: 02-Jun-2003										
(AVG MAN HRS: 1)										
CAB03-4	Honeywell IN 182A-16 and IN 812A-12 Radar Indicator Inspection/Modification								T (A/R)	Mandatory
24 A/F										
Eff: 19-May-2003										
CAB06-10	Electrical Ground Strap Inspection								T (A/R)	Mandatory
24 A/F										
Eff: 02-Oct-2006										
CAB07-4	12 Volt Direct Current Power Outlets Installation								T (A/R)	Optional
24 A/F										
Eff: 02-Apr-2007										
CAB08-2	Wing Electrical Wiring Harness Inspection								T (A/R)	Mandatory
24 A/F										
Eff: 04-Feb-2008										
CAB09-8	ACU Wiring Modification for STBY PWR INOP CAS Message								T (A/R)	Mandatory
24 A/F										
Eff: 22-Jun-2009										
(AVG MAN HRS: 4)										
CAB-24-01	Circuit Breaker Panel Modification								RE (-)	Mandatory
24 A/F										
Eff: 18-Sep-2013										
(AVG MAN HRS: 2.5)										
CAB-24-02	Electrical Power - Generator Control Unit (GCU) Wiring Improvements								T (A/R)	Optional
24 A/F										
Eff: 09-Aug-2018										
CAB-24-03	Electrical Power - Generator Control Unit (GCU) Circuit Breaker Addition in the Electrical J-Box								RE (-)	Recommended
24 A/F										
Eff: 30-Nov-2021										
(AVG MAN HRS: 3)										
CAB-24-04	Electrical Power - Placard Installation for Standby Alternator								T (A/R)	Recommended
24 A/F										
Eff: 01-Oct-2020										
(AVG MAN HRS: 0.5)										
CAB87-15	Circuit Breaker Inspection/Replacement								T (A/R)	Mandatory
24 A/F										
Eff: 17-Nov-1987										
CAB88-26	Circuit Breaker Panel Cover Installation								T (A/R)	Optional
24 A/F										
Eff: 29-Jul-1988										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB88-38	Flashing Beacon Circuit Breaker Inspection/Replacement								T (A/R)	Recommended
24 A/F										Mos
Eff: 09-Dec-1988										Hrs
										Ldg
CAB89-23	Lead-Acid Battery Tie Down Strap Improvement								T (A/R)	Mandatory
24 A/F										Mos
Eff: 25-Aug-1989										Hrs
										Ldg
CAB89-27	Standby Alternator Drive Pulley Inspection/Replacement								T (A/R)	Recommended
24 A/F										Mos
Eff: 22-Sep-1989										Hrs
										Ldg
CAB89-29	Power Relay Box Connector Sealing								T (A/R)	Recommended
24 A/F										Mos
Eff: 06-Oct-1989										Hrs
										Ldg
CAB90-4	Generator Field Circuit Breaker Inspection and Screw Replacement								T (A/R)	Recommended
24 A/F										Mos
Eff: 23-Feb-1990										Hrs
										Ldg
CAB90-6	Circuit Breaker Inspection/Replacement - Flap Circuit								T (A/R)	Mandatory
24 A/F										Mos
Eff: 09-Mar-1990										Hrs
										Ldg
CAB92-1	Generator Control Unit Modification								T (A/R)	Optional
24 A/F										Mos
Eff: 17-Jan-1992										Hrs
										Ldg
CAB92-17	Left Fuselage Sidewall Electrical Connectors Relocation								T (A/R)	Recommended
24 A/F										Mos
Eff: 11-Sep-1992										Hrs
										Ldg
CAB92-3	Lucas Starter/Generator Brush Inspection								T (A/R)	Recommended
24 A/F										Mos
Eff: 24-Jan-1992										Hrs
										Ldg
CAB93-16	Battery Box Latch Pivot Bolt Reversal								T (A/R)	Optional
24 A/F										Mos
Eff: 17-Sep-1993										Hrs
										Ldg
CAB94-5	Standby Alternator Output Wire Replacement								T (A/R)	Recommended
24 A/F										Mos
Eff: 11-Feb-1994										Hrs
										Ldg
CAB96-10	Avionics Cooling Fan Replacement								T (A/R)	Recommended
24 A/F										Mos
Eff: 09-Feb-1996										Hrs
										Ldg
CAB96-12	Gyro Installation Vacuum Hose Replacement								T (A/R)	Mandatory
24 A/F										Mos
Eff: 03-May-1996										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB96-23	Standby Alternator Drive Pulley Oil Drain Can Installation								T (A/R)	Optional
24 A/F										Mos
Eff: 16-Dec-1996										Hrs
										Ldg
CAB98-7	Voltage Suppression Jumper Installation								T (A/R)	Optional
24 A/F										Mos
Eff: 27-Apr-1998										Hrs
										Ldg
CAB99-9	Yaw Damper AC Inverter Wiring Fuse Installation								T (A/R)	Recommended
24 A/F										Mos
Eff: 29-Nov-1999										Hrs
										Ldg
CAL-24-01	Alternator Control Unit Inspection								RE (-)	Recommended
24 A/F										Mos
Eff: 13-May-2013										Hrs
										Ldg
CAL-24-02	Transmittal of HET Service Bulletin No. 053								RE (-)	Recommended
24 A/F										Mos
Eff: 12-Sep-2013										Hrs
										Ldg
CAL-24-03	Electrical Power - Supplements to Address Electrical Requirements for Operation of Single-Engine Passenger-Carrying Aircraft for Compensation or Hire								T (A/R)	Informational
24 A/F										Mos
Eff: 23-Dec-2015										Hrs
(NOTE: All Pre G1000-Built Caravan Airplanes used for carrying passengers for compensation or hire.)										Ldg
CAL-24-04	Electrical Power - Inspect Electrical Ground Studs in the Engine Compartment for Correct Paint and Sealant Application								RE (-)	Recommended
24 A/F										Mos
Eff: 27-Feb-2020										Hrs
(AVG MAN HRS: 3)										Ldg
CAL-24-05	Electrical Power - Wire Bundle ID Tag Inspection								T (A/R)	Recommended, Service Letter
24 A/F										Mos
Eff: 25-May-2021										Hrs
(AVG MAN HRS: 1)										Ldg
SNL00-7	Standby Alternator Drive Pulley Grease Leakage Criteria								T (A/R)	Informational
24 A/F										Mos
Eff: 12-Jun-2000										Hrs
										Ldg
SNL02-1	APC Starter-Generator Time between Overhaul Requirements								T (A/R)	Informational
24 A/F										Mos
Eff: 28-Jan-2002										Hrs
										Ldg
SNL86-47	Revised Marathon Superpower Ni-Cad Battery Charging Procedures								T (A/R)	Informational
24 A/F										Mos
Eff: 14-Nov-1986										Hrs
										Ldg
SNL87-22	Generator Control Unit Test Box and Troubleshooting Procedures								T (A/R)	Informational
24 A/F										Mos
Eff: 09-Oct-1987										Hrs
										Ldg
SNL90-9	Starter/Generator Removal and Installation Procedures								T (A/R)	Informational
24 A/F										Mos
Eff: 23-Nov-1990										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SNL92-6	Alternate Starter/Generator								T (A/R)	Informational
 24 A/F										Mos
Eff: 28-Aug-1992										Hrs
										Ldg
SNL94-11	Starter Energized Annunciator Light Operation with APC Starter-Generators								T (A/R)	Informational
 24 A/F										Mos
Eff: 09-Sep-1994										Hrs
										Ldg
SNL94-9	APC Starter-Generator Replacement Parts and Overhaul Requirements								T (A/R)	Informational
 24 A/F										Mos
Eff: 29-Jul-1994										Hrs
										Ldg
SNL95-6	Alternate Lucas Starter/Generator								T (A/R)	Informational
 24 A/F										Mos
Eff: 18-Aug-1995										Hrs
										Ldg
SNL97-5	APC Starter-Generator Time Between Overhaul Requirements								T (A/R)	Informational
 24 A/F										Mos
Eff: 08-Sep-1998										Hrs
										Ldg
SSP08-2	Circuit Breaker/Relay Box Connector Contact Inspection								T (A/R)	Mandatory
 24 A/F										Mos
Eff: 01-Dec-2008										Hrs
										Ldg
SSP09-1	Battery Shunt Replacement								T (A/R)	Mandatory
 24 A/F										Mos
Eff: 26-Jan-2009										Hrs
										Ldg
SSP11-02	Standby Alternator J-Box Diode Inspection								T (A/R)	Mandatory
 24 A/F										Mos
Eff: 26-Apr-2011										Hrs
										Ldg
▼ 25 - EQUIPMENT/FURNISHINGS										
2006-01-11	Cargo Pod and Landing Gear Fairings								RE (-)	Mandatory
 25 A/F										Mos
										Hrs
										Ldg
2006-01-11 R1	Cargo Pod and Landing Gear Fairings								RE (-)	Mandatory
 25 A/F										Mos
Eff: 22-Feb-2006 Complied	AD WAS INCORPORATED DURING PRODUCTION						29-Jun-2016			Hrs
With							0			Ldg
							0			
2021-09-09	Uninsured United Parachute Technologies, LLC Vector 3 SE Parachute Containers								RE (-)	Mandatory (Appliance AD)
 25 A/F										Mos
Eff: 07-May-2021 Not Applicable							21-Jun-2021			Hrs
							316.7			Ldg
							551			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
2021-09-09 Par. (g)(1)	Uninsured United Parachute Technologies, LLC Vector 3 SE Parachute Containers - Modify the Bottom Tuck Tab of the RPC								RE (-)	Mandatory (Appliance AD)
25 A/F	Eff: 06-May-2021 Not Applicable					Mos	21-Jun-2021			
	(NOTE: COMPLIANCE: Before the next parachute jump after the effective date of this AD, modify the bottom tuck tab of the RPC by following the Procedure in Uninsured United Parachute Technologies, LLC, INSTRUCT-064, Revision 1, dated February 10, 2021. Before the next parachute jump after the effective date of this AD, you may do the RPC replacement required by paragraph (g)(2) of this AD in lieu of doing this modification.)					Hrs	316.7			
						Ldg	551			
2021-09-09 Par. (g)(2)	Uninsured United Parachute Technologies, LLC Vector 3 SE Parachute Containers - RPC Replacement								RE (-)	Mandatory (Appliance AD)
25 A/F	Eff: 07-May-2021 Not Applicable					Mos	21-Jun-2021			
	(NOTE: COMPLIANCE: At the next reserve parachute packing after the effective date of this AD, replace the RPC by following the Procedure in Uninsured United Parachute Technologies, LLC, INSTRUCT-065, Revision 0, dated February 12, 2021.)					Hrs	316.7			
						Ldg	551			
74-08-09 R2	Equipment/furnishings - Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles								RE (-)	Mandatory
25 A/F	Eff: 06-Aug-1974					Mos				
						Hrs				
						Ldg				
74-08-09 R2 Paragraph (g)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - (1) Install a placard on each side of each lavatory door over the door knob, or on each side of each lavatory door, or adjacent to each side of each lavatory door. (2) Install a placard on or near each lavatory paper or linen waste disposal receptacle door, containing the legible words or symbology indicating "No Cigarette Disposal."								RE (-)	Mandatory
25 A/F	Eff: 06-Aug-1974					Mos				
						Hrs				
						Ldg				
74-08-09 R2 Paragraph (h)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - establish a procedure that requires that, no later than a time immediately after the "No Smoking" sign is extinguished following takeoff, an announcement be made by a crewmember to inform all aircraft occupants that smoking is prohibited in the aircraft lavatories; except that, if the aircraft is not equipped with a "No Smoking" sign, the required procedure must provide that the announcement be made prior to each takeoff.								RE (-)	Mandatory
25 A/F	Eff: 06-Aug-1974					Mos				
						Hrs				
						Ldg				
74-08-09 R2 Paragraph (i)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Install a self-contained, removable ashtray on or near the entry side of each lavatory door. One ashtray may serve more than one lavatory door if the ashtray can be seen readily from the cabin side of each lavatory door served.								RE (-)	Mandatory
25 A/F	Eff: 06-Aug-1974					Mos				
						Hrs				
						Ldg				
74-08-09 R2 Paragraph (j)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - An airplane with multiple lavatory doors may be operated with up to 50 percent of the lavatory door ashtrays missing or inoperative, provided 50 percent of the missing or inoperative ashtrays are replaced within 3 days and all remaining missing or inoperative ashtrays are replaced within 10 days. An airplane with only 1 lavatory door may be operated for a period of 10 days with the lavatory door ashtray missing or inoperative								RE (-)	Mandatory
25 A/F	Eff: 06-Aug-1974					Mos				
						Hrs				
						Ldg				
74-08-09 R2 Paragraph (k)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Inspect all lavatory paper and linen waste receptacle enclosure access doors and disposal doors for proper operation, fit, sealing, and latching for the containment of possible trash fires.								RE (-)	Mandatory
25 A/F	Eff: 06-Aug-1974					Mos				
						Hrs				
						Ldg				
74-08-09 R3	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles								RE (-)	Mandatory
25 A/F	Eff: 28-Mar-2012					Mos				
						Hrs				
						Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
74-08-09 R3 Paragraph (g)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - (1) Install a placard on each side of each lavatory door over the door knob, or on each side of each lavatory door, or adjacent to each side of each lavatory door. (2) Install a placard on or near each lavatory paper or linen waste disposal receptacle door, containing the legible words or symbology indicating "No Cigarette Disposal."						RE (-)		Mandatory	
25 A/F Eff: 06-Aug-1974										Mos Hrs Ldg
74-08-09 R3 Paragraph (h)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - establish a procedure that requires that, no later than a time immediately after the "No Smoking" sign is extinguished following takeoff, an announcement be made by a crewmember to inform all aircraft occupants that smoking is prohibited in the aircraft lavatories; except that, if the aircraft is not equipped with a "No Smoking" sign, the required procedure must provide that the announcement be made prior to each takeoff.						RE (-)		Mandatory	
25 A/F Eff: 06-Aug-1974										Mos Hrs Ldg
74-08-09 R3 Paragraph (i)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Install a self-contained, removable ashtray on or near the entry side of each lavatory door. One ashtray may serve more than one lavatory door if the ashtray can be seen readily from the cabin side of each lavatory door served.						RE (-)		Mandatory	
25 A/F Eff: 06-Aug-1974										Mos Hrs Ldg
74-08-09 R3 Paragraph (j)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - An airplane with multiple lavatory doors may be operated with up to 50 percent of the lavatory door ashtrays missing or inoperative, provided 50 percent of the missing or inoperative ashtrays are replaced within 3 days and all remaining missing or inoperative ashtrays are replaced within 10 days. An airplane with only 1 lavatory door may be operated for a period of 10 days with the lavatory door ashtray missing or inoperative						T (A/R)		Mandatory	
25 A/F Eff: 28-Mar-2012 (NOTE: Note 1 to paragraph (j) of this AD: This AD permits a lavatory door ashtray to be missing, although the FAA-approved Master Minimum Equipment List (MMEL) may not allow such provision. In any case, the provisions of this AD prevail.)										Mos Hrs Ldg
74-08-09 R3 Paragraph (k)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Inspect all lavatory paper and linen waste receptacle enclosure access doors and disposal doors for proper operation, fit, sealing, and latching for the containment of possible trash fires.						RE (-)		Mandatory	
25 A/F Eff: 28-Mar-2012										Mos Hrs Ldg
CAB00-12	Pilot and Copilot Seat Rails and Floor Structure Modification						T (A/R)		Mandatory	
25 A/F Eff: 30-Oct-2000 (AVG MAN HRS: 25)										Mos Hrs Ldg
CAB04-5	Security Lock Installation						T (A/R)		Optional	
25 A/F Eff: 20-Jun-2012										Mos Hrs Ldg
CAB05-2	ARTEX Three Frequency Emergency Locator Transmitter (ELT) Installation						T (A/R)		Optional	
25 A/F Eff: 24-Jan-2005 (AVG MAN HRS: 25)										Mos Hrs Ldg
CAB06-6	Additional Beverage Cup Holder Installation						T (A/R)		Optional	
25 A/F Eff: 01-May-2006										Mos Hrs Ldg
CAB06-7	Cargo Pod Main Landing Gear Opening Modification						T (A/R)		Optional	
25 A/F Eff: 21-Aug-2006										Mos Hrs Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB-25-01	Cargo Barrier Modification								T (A/R)	Optional
25 A/F										
Eff: 18-Oct-2013										
(AVG MAN HRS: 8)										
CAB-25-02	Field Interior Installation								RE (-)	Optional
25 A/F										
Eff: 24-Apr-2015										
CAB89-30	Enlarged Cargo Pod Heat Shield								T (A/R)	Optional
25 A/F										
Eff: 03-Nov-1989										
CAB89-4	Pointer 3000-1 ELT Installation - Superseded by CAB97-7								RE (-)	Optional
25 A/F										
Eff: 13-Jan-1989										
(AVG MAN HRS: 5)										
CAB89-4 Rev 1	Pointer 3000-1 ELT Installation - Superseded by CAB97-7								RE (-)	Optional
25 A/F										
Eff: 02-Nov-1998										
(AVG MAN HRS: 5)										
CAB91-10	Bench Seat Belt and Harness Retention								T (A/R)	Mandatory
25 A/F										
Eff: 19-Apr-1991										
CAB95-19	Cargo Pod and Landing Gear Fairing De-ice System Installation								T (A/R)	Recommended
25 A/F										
Eff: 13-Oct-1995										
CAB95-6	Crew Seat Vertical Adjust Bearing Inspection/Replacement								T (A/R)	Mandatory
25 A/F										
Eff: 26-May-1995										
CAB97-7	Pointer 3000-11 ELT Installation								T (A/R)	Recommended
25 A/F										
Eff: 28-Apr-1997										
CAB99-5	Emergency Locator Transmitter (ELT) Operational Test								T (A/R)	Mandatory
25 A/F										
Eff: 04-Oct-1999										
CAL-25-02	Equipment/Furnishings - Crew Seat Frame Inspection and Weld Repair								T	Recommended
25 A/F									24	[02-Oct-2022] 5.7 Months
Eff: 02-Oct-2020									800	[1,089.52] 732.22 Hrs
(AVG MAN HRS: 1.3) (NOTE: COMPLIANCE: This service document should be accomplished in the next 800-hours or 24-months, from date of receipt, whichever occurs first.)										
CF-48-05	Emergency Flare Installations (Previously issued as T/11/48)								T (A/R)	Mandatory
25 A/F										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
CF-59-01	Floor-Mounted Hand-Pump Type Fire Extinguishers								RE (-)	Mandatory
25 A/F	Eff: 31-Mar-1959									
CF-63-01	Carriage of External Loads - Leather Strapping								T (A/R)	Mandatory
25 A/F	Eff: 31-Jan-1963									
CF-83-31R2	Lavatory Flush Pump Motors								RE (-)	Mandatory
25 A/F	Eff: 07-Apr-1986									
SA01397NY	Erda Executive Seat, Model 3058 And Folding Tables, Supplemental Type Certificate								RE (-)	
25 A/F	Complied With									
SA02080AK-D	Exhaust Deflector - Aero Twin, Supplemental Type Certificate								RE (-)	
25 A/F	Complied With									
	INSTALLED AERO TWIN EXHAUST DEFLECTOR P/N ED8-100 PER STC SA02080AK-D. INSTALLATION WAS IN ACCORDANCE WITH AERO TWIN DRAWING NO. ED8-100. WEIGHT AND BALANCE HAS BEEN UPDATED TO REFLECT THIS INSTALLATION AND HAS BEEN INSERTED INTO THE POH. CESSNA MAINTENANCE MANUAL, CHAPTER 78 IS RECOMMENDED FOR THE CONTINUED AIRWORTHINESS REQUIREMENTS.									
SA1311GL	Installation Of Wipaire Model 8000 Amphibian/Seaplane Floats Or Wipaire Model 8750 Amphibian/Seaplane Floats, Supplemental Type Certificate								RE (-)	
25 A/F	Complied With									
SA3649NM	Fabrication And Installation Of Aero Twin, Inc. Rudder Gust Lock Kit No. At-RI-1001., Supplemental Type Certificate								RE (-)	
25 A/F	Complied With									
	STC SA3649NM, AERO TWIN RUDDER GUST LOCK KIT, P/N AT-RL-1001 WAS INCORPORATED DURING PRODUCTION.									
▼ 26 - FIRE PROTECTION										
2021-22-07	Fire Protection - Impaired Fire Extinguisher								RE	Mandatory (Appliance AD)
26 A/F	Eff: 18-Nov-2021 Not Applicable								6	14-Jul-2022 3 Months
	(UPDATE NOTE: AD Not applicable by Installed extinguisher.) (NOTE: COMPLIANCE: Par. (g)(1) Within 30 days after the effective date of this AD and thereafter at intervals not to exceed 6 months.)									
2022-01-03	Fire Bottle, Portable - HAFEX (Halon-free) Hand-Held P3HAFEX Fire Extinguisher								T	Mandatory (Appliance AD)
26 A/F	Eff: 07-Mar-2022								12	07-Mar-2023 10.9 Months
	(NOTE: Required Actions: (1) Within 12 months after the effective date of this AD, remove each fire extinguisher identified in the introductory text of paragraph (c) from service.)									
CAB06-12	Engine Fire Detector Cable Inspection								T (A/R)	Mandatory
26 A/F	Eff: 26-Dec-2006									
CAB90-25	Fire Detect Sensor Clamp Installation								T (A/R)	Optional
26 A/F	Eff: 07-Sep-1990									

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
▼ 27 - FLIGHT CONTROLS										
2004-17-01	Flap Bellcranks								RE (-)	Mandatory
27 A/F						Mos	29-Jun-2016			
Eff: 26-Sep-2004 Not Applicable	SUBJECT PARTS NOT INSTALLED.					Hrs	0			
						Ldg	0			
2004-17-01 Paragraph (e)	Flap Bellcranks, Initial Inspection								RE (-)	Mandatory
27 A/F						Mos				
Eff: 26-Sep-2004						Hrs				
						Ldg				
2004-17-01 Paragraph (f)(1)	Flap Bellcranks, Repetitive Inspections								RE (-)	Mandatory
27 A/F						Mos				
Eff: 26-Sep-2004						Hrs				
						Ldg				
2004-17-01 Paragraph (f)(2)	Flap Bellcranks, Initial Replacement								RE (-)	Mandatory
27 A/F						Mos				
Eff: 26-Sep-2004						Hrs				
						Ldg				
2009-05-12	Aileron Control System								RE (-)	Mandatory
27 A/F						Mos	29-Jun-2016			
Eff: 15-Apr-2009 Not Applicable	PER PARAGRAPH (C) OF THIS AD.					Hrs	0			
						Ldg	0			
88-19-06	Elevators								RE (-)	Mandatory
27 A/F						Mos	29-Jun-2016			
Eff: 30-Sep-1988 Not Applicable	AIRCRAFT NOT IN EFFECTIVE SERIAL RANGE.T					Hrs	0			
						Ldg	0			
90-05-01	Bellcrank Assembly								RE (-)	Mandatory
27 A/F						Mos	29-Jun-2016			
Eff: 05-Mar-1990 Not Applicable	AIRCRAFT NOT IN EFFECTIVE SERIAL RANGE.À€†					Hrs	0			
						Ldg	0			
CAB00-1	Stall Warning Ground Operations Disable Switch Installation								T (A/R)	Optional
27 A/F						Mos				
Eff: 06-Mar-2000 (AVG MAN HRS: 8)						Hrs				
						Ldg				
CAB00-5	Rudder Bar Assembly Modification and Barrel Nut Replacement								T (A/R)	Optional
27 A/F						Mos				
Eff: 17-Apr-2000						Hrs				
						Ldg				
CAB02-1	Flap System Inboard Forward Bellcrank Life Limit and Inspection								RE (-)	Mandatory
27 A/F						Mos				
Eff: 11-Feb-2002						Hrs				
						Ldg				
CAB02-1 Rev 1	Flap System Inboard Forward Bellcrank Life Limit and Inspection								RE (-)	Mandatory
27 A/F						Mos				
Eff: 11-Mar-2002						Hrs				
						Ldg				
CAB02-1 Rev 2	Flap System Inboard Forward Bellcrank Life Limit and Inspection								T (A/R)	Mandatory
27 A/F						Mos				
Eff: 27-Jan-2003						Hrs				
						Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB02-12	Flap System Inboard Forward Bellcrank Installation								RE (-)	Mandatory
27 A/F										
Eff: 21-Oct-2002										
(AVG MAN HRS: 2.9)										
CAB02-12 Rev 1	Flap System Inboard Forward Bellcrank Installation								T (A/R)	Mandatory
27 A/F										
Eff: 27-Jan-2003										
(AVG MAN HRS: 2.9)										
CAB03-11	Flap System Bell Cranks Weld Inspection								RE (-)	Mandatory
27 A/F										
Eff: 12-Sep-2003										
(AVG MAN HRS: 9)										
CAB03-11 Rev 1	Flap System Bell Cranks Weld Inspection								T (A/R)	Mandatory
27 A/F										
Eff: 24-Sep-2003										
(AVG MAN HRS: 9)										
CAB03-13	Rudder Pedal Clevis Inspection/Replacement								T (A/R)	Mandatory
27 A/F										
Eff: 03-Nov-2003										
CAB03-9	Honeywell KS 270C and 272C Servo Friction Inspection								T (A/R)	Recommended
27 A/F										
Eff: 30-Jun-2003										
CAB04-3	Aileron Bell Crank Weld Inspection								T (A/R)	Mandatory
27 A/F										
Eff: 08-Mar-2004										
CAB05-13	Right Inboard Flap Bell Crank Bearings Inspection								T (A/R)	Mandatory
27 A/F										
Eff: 31-Oct-2005										
(AVG MAN HRS: 3.5)										
CAB05-4	Flap Actuator Support Bracket Inspection/Replacement								T (A/R)	Mandatory
27 A/F										
Eff: 04-Apr-2005										
(AVG MAN HRS: 9)										
CAB06-2	Rudder Torque Tube Inspection								T (A/R)	Recommended
27 A/F										
Eff: 20-Mar-2006										
CAB06-9	Rudder Spar Inspection								T (A/R)	Mandatory
27 A/F										
Eff: 02-Oct-2006										
CAB08-6	Aileron Control Cable Attachment to Quadrant Modification								T (A/R)	Mandatory
27 A/F										
Eff: 27-Oct-2008										
(AVG MAN HRS: 22)										
CAB09-2	Elevator Pushrod Placards Installation								T (A/R)	Mandatory
27 A/F										
Eff: 11-May-2009										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB10-2	Instrument Panel Control Column Cutout Modification								T (A/R)	Mandatory
27 A/F										Mos
Eff: 12-Apr-2010										Hrs
(AVG MAN HRS: 1.5)										Ldg
CAB10-3	Wing Aileron Cable and Pulley Inspection								T (A/R)	Mandatory
27 A/F										Mos
Eff: 18-May-2010										Hrs
										Ldg
CAB10-5	Flap Pushrod Rod End Inspection								RE (-)	Mandatory
27 A/F										Mos
Eff: 18-May-2010										Hrs
(AVG MAN HRS: 1)										Ldg
CAB10-5 Rev 1	Flap Pushrod Rod End Inspection								T (A/R)	Mandatory
27 A/F										Mos
Eff: 20-Jul-2010										Hrs
(AVG MAN HRS: 1)										Ldg
CAB10-6	Right Inboard Flap Bell Crank Bearing Inspection / Replacement								T (A/R)	Mandatory
27 A/F										Mos
Eff: 20-Jul-2010										Hrs
(AVG MAN HRS: 2.3)										Ldg
CAB10-7	Elevator Hinge Bracket Inspection								T (A/R)	Mandatory
27 A/F										Mos
Eff: 20-Jul-2010										Hrs
										Ldg
CAB10-9	Roll Servo Fairlead Cover Installation								T (A/R)	Mandatory
27 A/F										Mos
Eff: 17-Sep-2010										Hrs
(AVG MAN HRS: 1.7)										Ldg
CAB-27-01	Rudder Trim Inspection								T (A/R)	Mandatory
27 A/F										Mos
Eff: 15-Feb-2029										Hrs
										Ldg
CAB-27-02	Flight Controls - Installation of Flap Cable Guards								RE (-)	Recommended
27 A/F										Mos
Eff: 16-May-2016										Hrs
										Ldg
CAB-27-03	Flight Controls - Inspection of Aileron Cable Interference								RE (-)	Mandatory
27 A/F										Mos
Eff: 04-Aug-2016										Hrs
(AVG MAN HRS: 5.8)										Ldg
CAB-27-04	Inspection/Replacement of Flap System Bell Crank								RE (-)	Mandatory
27 A/F										Mos
Eff: 24-Aug-2016										Hrs
(AVG MAN HRS: 3.7)										Ldg
CAB-27-05	Flight Controls - Flap Follow-Up Barrel Washer Installation								RE (-)	Recommended
27 A/F										Mos
Eff: 05-Jun-2018 Complied	INSPECTION COMPLETED. CONTACT NOTED, BUT NO MEASURABLE DAMAGE . WASHERS AND CLEVIS						29-Jun-2018			Hrs
With	BOLT INSTALLED IAW CAB-27-05.						114.8			Ldg
(AVG MAN HRS: 1.5)							137			

Task No		Description					CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI				DUE	Remaining
CAB-27-06		Flight Controls - Elevator Torque Tube Inspection for Loose Rivets							RE	Mandatory	≈28-Aug-2022
	27 A/F						Mos	03-May-2021			
		Eff: 14-Oct-2019 Complied With					Hrs	293.7	200	493.7	136.4 Hrs
		(AVG MAN HRS: 9) (NOTE: COMPLIANCE: The elevator torque tube attach point rivets shall be inspected every 200 flight hours until the airplane reaches 4000 flight hours or all 48 rivets have been replaced.)					Ldg	485			
CAB88-13		Flap System Adjustable Interconnect Rod Installation							T (A/R)	Optional	
	27 A/F						Mos				
		Eff: 25-Mar-1988					Hrs				
							Ldg				
CAB88-27		Elevator Balance Inspection							T (A/R)	Mandatory	
	27 A/F						Mos				
		Eff: 19-Aug-1988					Hrs				
							Ldg				
CAB88-5		Control Column Aileron Cable Guard Improvement							T (A/R)	Recommended	
	27 A/F						Mos				
		Eff: 18-Mar-1988					Hrs				
							Ldg				
CAB89-12		Control Cable Special Inspection							T (A/R)	Mandatory	
	27 A/F						Mos				
		Eff: 19-May-1989					Hrs				
							Ldg				
CAB89-25		Elevator Control Link Replacement							RE (-)	Recommended	
	27 A/F						Mos				
		Eff: 01-Sep-1989					Hrs				
		(AVG MAN HRS: 1)					Ldg				
CAB89-25 Rev 1		Elevator Control Link Replacement							T (A/R)	Recommended	
	27 A/F						Mos				
		Eff: 14-Dec-1990					Hrs				
		(AVG MAN HRS: 1)					Ldg				
CAB89-31		Inboard Flap Roller and Track Removal							T (A/R)	Optional	
	27 A/F						Mos				
		Eff: 24-Nov-1989					Hrs				
							Ldg				
CAB89-32		Flap Bellcrank Support Improvement - Superseded by CAB95-11							RE (-)	Recommended	
	27 A/F						Mos				
		Eff: 15-Dec-1989					Hrs				
							Ldg				
CAB89-32 Rev 1		Flap Bellcrank Support Improvement - Superseded by CAB95-11							RE (-)	Recommended	
	27 A/F						Mos				
		Eff: 02-Jul-1992					Hrs				
							Ldg				
CAB89-32 Rev 2		Flap Bellcrank Support Improvement - Superseded by CAB95-11							RE (-)	Recommended	
	27 A/F						Mos				
		Eff: 30-Jun-1995					Hrs				
							Ldg				
CAB89-34		Flap Bellcrank Weld Inspection							T (A/R)	Mandatory	
	27 A/F						Mos				
		Eff: 16-Nov-1990					Hrs				
							Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB90-31	Flap Bellcrank Weld Inspection								T (A/R)	Mandatory
27 A/F										Mos
Eff: 16-Nov-1990										Hrs
										Ldg
CAB91-2	Outboard Flap Pushrod Bolt and Cable Inspection								T (A/R)	Recommended
27 A/F										Mos
Eff: 22-Feb-1991										Hrs
										Ldg
CAB91-27	Control Column Bearings and Aileron Cable Guard Replacement								T (A/R)	Optional
27 A/F										Mos
Eff: 20-Sep-1991										Hrs
										Ldg
CAB91-33	Radome Sealing Procedures								T (A/R)	Optional
27 A/F										Mos
Eff: 15-Nov-1991										Hrs
										Ldg
CAB92-15	Flap Bellcrank Connecting Rod Clearance Inspection and Modification								T (A/R)	Recommended
27 A/F										Mos
Eff: 24-Jul-1992										Hrs
										Ldg
CAB92-16	Flap Support Inspection and Modification								RE (-)	Mandatory
27 A/F										Mos
Eff: 28-Aug-1992										Hrs
										Ldg
CAB92-16 Rev 1	Flap Support Inspection and Modification								RE (-)	Mandatory
27 A/F										Mos
Eff: 25-Nov-1992										Hrs
										Ldg
CAB92-16 Rev 2	Flap Support Inspection and Modification								RE (-)	Mandatory
27 A/F										Mos
Eff: 11-Dec-1992										Hrs
										Ldg
CAB92-16 Rev 3	Flap Support Inspection and Modification								RE (-)	Mandatory
27 A/F										Mos
Eff: 30-Apr-1993										Hrs
										Ldg
CAB92-18	Rudder Torque Tube Inspection and Rudder Hinge Replacement								RE (-)	Recommended
27 A/F										Mos
Eff: 16-Oct-1992										Hrs
										Ldg
CAB92-18 Rev 1	Rudder Torque Tube Inspection and Rudder Hinge Replacement								T (A/R)	Recommended
27 A/F										Mos
Eff: 30-Apr-1993										Hrs
										Ldg
CAB92-2	Vertical Stabilizer Skin Reinforcement								T (A/R)	Recommended
27 A/F										Mos
Eff: 17-Jan-1992										Hrs
										Ldg
CAB93-11	Flap Outboard Support Inspection and Modification								T (A/R)	Mandatory
27 A/F										Mos
Eff: 27-Aug-1993										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB93-12	Elevator Hinge Replacement						T (A/R)		Optional	
27 A/F					Mos					
Eff: 27-Aug-1993					Hrs					
					Ldg					
CAB93-13	Aileron Cable Seal Retainer Inspection						T (A/R)		Mandatory	
27 A/F					Mos					
Eff: 27-Aug-1993					Hrs					
					Ldg					
CAB93-14	Flap Bellcrank Safe Life Limit						T (A/R)		Mandatory	
27 A/F					Mos					
Eff: 27-Aug-1993					Hrs					
					Ldg					
CAB93-18	Aileron Outboard Hinge Bolt Inspection/Replacement						T (A/R)		Mandatory	
27 A/F					Mos					
Eff: 08-Oct-1993					Hrs					
					Ldg					
CAB93-22	Flap Support Roller Washer Installation						T (A/R)		Mandatory	
27 A/F					Mos					
Eff: 19-Nov-1993					Hrs					
					Ldg					
CAB93-6	Rudder Upper and Center Hinge Replacement						T (A/R)		Optional	
27 A/F					Mos					
Eff: 28-May-1993					Hrs					
					Ldg					
CAB94-13	Flap Support and System Inspections and Operational Check						T (A/R)		Mandatory	
27 A/F					Mos					
Eff: 01-Jul-1994					Hrs					
					Ldg					
CAB94-14	Flap Bellcrank Bolt Inspection/Replacement - Superseded by CAB95-11						RE (-)		Mandatory	
27 A/F					Mos					
Eff: 19-Jul-1994					Hrs					
(AVG MAN HRS: 1)					Ldg					
CAB94-14 Rev 1	Flap Bellcrank Bolt Inspection/Replacement - Superseded by CAB95-11						RE (-)		Mandatory	
27 A/F					Mos					
Eff: 30-Jun-1995					Hrs					
(AVG MAN HRS: 1)					Ldg					
CAB94-16	Flap Switch Guard Installation/Modification						T (A/R)		Recommended	
27 A/F					Mos					
Eff: 28-Oct-1994					Hrs					
					Ldg					
CAB94-9	Elevator Trim Chain Cover Installation						T (A/R)		Mandatory	
27 A/F					Mos					
Eff: 25-Mar-1994					Hrs					
					Ldg					
CAB95-11	Flap Bellcrank Installation Modification						RE (-)		Mandatory	
27 A/F					Mos					
Eff: 30-Jun-1995					Hrs					
(AVG MAN HRS: 6)					Ldg					
CAB95-11 Rev 1	Flap Bellcrank Installation Modification						T (A/R)		Mandatory	
27 A/F					Mos					
Eff: 18-Aug-1995					Hrs					
(AVG MAN HRS: 6)					Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time Remaining
SEQ PN/SN	MOC Note or Component Condition								DUE	
CAB97-12	Left Inboard Aft Flap Bellcrank Replacement								T (A/R)	Mandatory
27 A/F										Mos
Eff: 27-Oct-1997										Hrs
										Ldg
CAL-27-01	Rudder Cable Inspection								RE (-)	Recommended
27 A/F										Mos
Eff: 24-Feb-2012										Hrs
(AVG MAN HRS: 2)										Ldg
CAL-27-02	Flap Pushrod Rod End Inspection								T (A/R)	Mandatory
27 A/F										Mos
Eff: 20-Jul-2010										Hrs
										Ldg
CAL-27-03	Elevator Up Stop Setting Inspection								RE (-)	Mandatory
27 A/F										Mos
Eff: 07-Feb-2013										Hrs
(AVG MAN HRS: 2.5)										Ldg
CAL-27-05	Flight Controls - Elevator Pre-Flight Check for Free Play								T (A/R)	Informational, Service Letter
27 A/F										Mos
Eff: 11-Aug-2017										Hrs
										Ldg
CAL-27-06	Flight Controls - Install Missing Caterpillar Grommets in the Bulkhead Cutouts								RE (-)	Recommended, Service Letter
27 A/F										Mos
Eff: 11-Jan-2019										Hrs
(AVG MAN HRS: 1.5)										Ldg
CAL-27-07	Flight Controls - Replace Aileron Trim Tab Pushrod Assemblies								RE (-)	Mandatory, Service Letter
27 A/F							10-May-2019			Mos
Eff: 10-Jan-2019 Not Applicable	FOUND NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER.						191.3			Hrs
(AVG MAN HRS: 9) (NOTE: COMPLIANCE: Mandatory. This service document must be accomplished within 100 flight hours or three months from the date of receipt, whichever occurs first.)							274			Ldg
CAL-27-07 Rev 1	Flight Controls - Replace Aileron Trim Tab Pushrod Assemblies								RE (-)	Mandatory, Service Letter
27 A/F							10-May-2019			Mos
Eff: 08-Feb-2019 Not Applicable	FOUND TO BE NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER.						191.3			Hrs
(AVG MAN HRS: 9)							274			Ldg
CAL-27-07 Rev 1 Inspect	Flight Controls - Replace Aileron Trim Tab Pushrod Assemblies - Inspect								RE (-)	Mandatory, Service Letter
27 A/F										Mos
Eff: 08-Feb-2019										Hrs
										Ldg
CAL-27-07 Rev 1 Replace	Flight Controls - Replace Aileron Trim Tab Pushrod Assemblies - Replace								RE (-)	Mandatory, Service Letter
27 A/F										Mos
Eff: 08-Feb-2019										Hrs
										Ldg
CAL-27-09	Flight Controls - Remove and Reinstall Inverted Left Aileron Trim Tab Pushrods								RE (-)	Recommended, Service Letter
27 A/F										Mos
Eff: 17-Sep-2019										Hrs
(AVG MAN HRS: 4.7)										Ldg
CAL-27-10	Flight Controls - Inspection of the Elevator Up Travel Rigging								RE (-)	Mandatory
27 A/F										Mos
Eff: 15-Aug-2019										Hrs
(AVG MAN HRS: 2.5)										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SNL89-17	Flap and Elevator Control System Bearing Replacement								T (A/R)	Informational
27 A/F										Mos
Eff: 17-Nov-1989										Hrs
										Ldg
SNL91-1	Flap Actuator Transmission Remanufactured/Exchange Program								T (A/R)	Informational
27 A/F										Mos
Eff: 18-Jan-1991										Hrs
										Ldg
SNL94-5	Aileron and Elevator Trim Chain Connecting Link Maintenance Practices								T (A/R)	Informational
27 A/F										Mos
Eff: 29-Apr-1994										Hrs
										Ldg
SSP07-2	Horizontal Stabilizer Forward Attach Bolts Inspection								T (A/R)	Mandatory
27 A/F										Mos
Eff: 31-Aug-2007										Hrs
										Ldg
SSP97-1	Aileron Trim and Flap System Cable Inspection/Replacement								T (A/R)	Mandatory
27 A/F										Mos
Eff: 17-Nov-1997										Hrs
										Ldg
▼ 28 - FUEL										
97-01-13	Fuel, Oil and Hydraulic Hoses								RE (-)	Mandatory
28 A/F										Mos
Eff: 03-Feb-1997 Not Applicable	SUBJECT PARTS NOT INSTALLED						29-Jun-2016			Hrs
							0			Ldg
							0			
CAB00-7	Engine Fuel Pump Inspection/Replacement								T (A/R)	Mandatory
28 A/F										Mos
Eff: 17-Apr-2000										Hrs
										Ldg
CAB02-11	Fuel Vent Line Float Valves Inspection								T (A/R)	Mandatory
28 A/F										Mos
Eff: 12-Aug-2002 (AVG MAN HRS: 9)										Hrs
										Ldg
CAB02-14	Fuel Filter Element Inspection								T (A/R)	Mandatory
28 A/F										Mos
Eff: 09-Dec-2002 (AVG MAN HRS: 2.5)										Hrs
										Ldg
CAB04-1	Fuel Quantity Transmitter Inspection/Replacement								T (A/R)	Mandatory
28 A/F										Mos
Eff: 09-Feb-2004										Hrs
										Ldg
CAB07-6	Fuel Capacity Placard Replacement								T (A/R)	Mandatory
28 A/F										Mos
Eff: 25-Jun-2007										Hrs
										Ldg
CAB-28-01	Fuel Vent Line Inspection								RE (-)	Mandatory
28 A/F										Mos
Eff: 14-Jul-2015 (AVG MAN HRS: 15)										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB87-14	Fuel Reservoir Tank/Wing Bay Primer Adhesion Inspection and Repair								T (A/R)	Mandatory
28 A/F										
Eff: 16-Oct-1987										
CAB88-10	Improved Fuel Flow Transducer Electrical Connector								T (A/R)	Optional
28 A/F										
Eff: 25-Mar-1988										
CAB88-23	Wing Fuel Tanks External Sump Installation								T (A/R)	Mandatory
28 A/F										
Eff: 29-Jul-1988										
CAB89-16	Fuel Pump Drain Reservoir Installation								T (A/R)	Optional
28 A/F										
Eff: 09-Jun-1989										
CAB89-21	Fuel System Roll Pin Safetying								RE (-)	Mandatory
28 A/F										
Eff: 11-Aug-1989										
(AVG MAN HRS: 4.3)										
CAB89-21 Rev 1	Fuel System Roll Pin Safetying								T (A/R)	Mandatory
28 A/F										
Eff: 17-Nov-1989										
(AVG MAN HRS: 4.3)										
CAB89-6	Fuel Control Manual Override Arm Bushing Installation								T (A/R)	Mandatory
28 A/F										
Eff: 13-Jan-1989										
CAB92-19	Low Fuel Level Switch Cover Replacement								T (A/R)	Recommended
28 A/F										
Eff: 23-Oct-1992										
CAB94-11	Inboard Fuel Filler Installation								T (A/R)	Optional
28 A/F										
Eff: 18-Feb-1994										
CAB95-18	Auxiliary Fuel Pump Relay Replacement								T (A/R)	Optional
28 A/F										
Eff: 08-Sep-1995										
CAB96-13	Airborne Fuel Pump Inspection/Replacement								T (A/R)	Mandatory
28 A/F										
Eff: 21-Jun-1996										
CAB96-15	Fuel Hose Inspection/Replacement								RE (-)	Mandatory
28 A/F										
Eff: 19-Jul-1996										
(AVG MAN HRS: 7)										
CAB96-15 Rev 1	Fuel Hose Inspection/Replacement								T (A/R)	Mandatory
28 A/F										
Eff: 18-Oct-1996										
(AVG MAN HRS: 7)										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB98-17	Fuel Reservoir Structure Modification								T (A/R)	Recommended
28 A/F										Mos
Eff: 05-May-1999										Hrs
										Ldg
CAL-28-01	Fuel - Inspection/Replacement of Left Low Fuel Level Switch Cover Assembly								RE (-)	Mandatory
28 A/F										Mos
Eff: 12-Nov-2015										Hrs
(AVG MAN HRS: 9.8)										Ldg
CAL-28-01 Rev 1	Fuel - Inspection/Replacement of Left Low Fuel Level Switch Cover Assembly								RE (-)	Mandatory
28 A/F										Mos
Eff: 12-Jan-2016										Hrs
(AVG MAN HRS: 9.8)										Ldg
CAL-28-02	Fuel - Fuel Line Cover Assemblies Sealant Inspection								RE (-)	Mandatory
28 A/F										Mos
Eff: 12-Feb-2016										Hrs
(AVG MAN HRS: 2.2)										Ldg
ICA-208-77-00002	Check Functionality and Performance of Fuel Temperature Probe								T (A/R)	ICA Supplement
28 A/F										Mos
Eff: 16-Feb-2015										Hrs
										Ldg
SA00059WI	Wipaire Inc Single Point Fuel System, Supplemental Type Certificate								RE (A/R)	
28 A/F							25-May-2018			Mos
Complied With							93.4			Hrs
										Ldg
SIL-GEN-108	Jet Fuel Containing Fatty Acid Methyl Esters (FAME)								RE (-)	Service Information Letter
28 ENG1										Mos
										Hrs
										Enc
SIL-GEN-108 Rev 1	Jet Fuel Containing Fatty Acid Methyl Esters (FAME)								RE (-)	Service Information Letter
28 ENG1										Mos
										Hrs
										Enc
SIL-GEN-108 Rev 2	Jet Fuel Containing Fatty Acid Methyl Esters (FAME)								T (A/R)	Service Information Letter
28 ENG1										Mos
Eff: 01-Nov-2017										Hrs
										Enc
SNL84-02	Garrett TPE Fuel Manifold Tester Modification								T (A/R)	Service Newsletter
28 A/F										Mos
Eff: 27-Jan-1984										Hrs
										Ldg
SNL87-19	Fuel Flow Transmitter Seal Installation								T (A/R)	Informational
28 A/F										Mos
Eff: 21-Aug-1987										Hrs
										Ldg
SSP08-3	Wing Outboard Fuel Filler Placard Inspection								T (A/R)	Mandatory
28 A/F										Mos
Eff: 15-Dec-2008										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
▼ 30 - ICE AND RAIN PROTECTION										
2004-08-17	Upper and Lower Wing Strut Attach Fitting Nut									
30 A/F									RE (-)	Mandatory
	Eff: 17-May-2004 Not Applicable	AIRCRAFT NOT IN EFFECTIVE SERIAL RANGE.								
						Mos	29-Jun-2016			
						Hrs	0			
						Ldg	0			
2007-10-15	S1 Known Icing Equipment AFM supplements									
30 A/F									RE (-)	Mandatory
	Eff: 21-Jun-2007 Not Applicable	EQUIPMENT NOT INSTALLED ON ACFT.								
						Mos	29-Jun-2016			
						Hrs	0			
						Ldg	0			
96-09-15	Airplane Flight Manual - Icing Conditions									
30 A/F									RE (-)	Mandatory
	Eff: 11-Jun-1996 Complied With	BY AFM REVISION (SECTION 2).E.À€								
						Mos	29-Jun-2016			
						Hrs	0			
						Ldg	0			
CAB00-11	Standby Alternator and Propeller De-ice Electrical Wiring Modification									
30 A/F									T (A/R)	Recommended
	Eff: 21-Aug-2000 (AVG MAN HRS: 7)									
						Mos				
						Hrs				
						Ldg				
CAB00-13	Propeller Anti-ice Timer Inspection/Replacement									
30 A/F									T (A/R)	Recommended
	Eff: 13-Nov-2000 (AVG MAN HRS: 1.5)									
						Mos				
						Hrs				
						Ldg				
CAB04-9	Ice Protection Installation/Modification									
30 A/F									T (A/R)	Recommended
	Eff: 04-Oct-2004									
						Mos				
						Hrs				
						Ldg				
CAB06-11	Flight into Known Icing - Low Airspeed Awareness System Installation									
30 A/F									RE (-)	Mandatory
	Eff: 09-Oct-2006 (AVG MAN HRS: 36)									
						Mos				
						Hrs				
						Ldg				
CAB06-11 Rev 1	Flight into Known Icing - Low Airspeed Awareness System Installation									
30 A/F									T (A/R)	Mandatory
	Eff: 19-Feb-2007 (AVG MAN HRS: 36)									
						Mos				
						Hrs				
						Ldg				
CAB08-3	Windshield Anti-Ice Panel Seal Modification									
30 A/F									T (A/R)	Recommended
	Eff: 04-Feb-2008 (AVG MAN HRS: 4)									
						Mos				
						Hrs				
						Ldg				
CAB09-9	TKS Ice Protection System Installation									
30 A/F									RE (-)	Optional
	Eff: 10-Sep-2014 (AVG MAN HRS: 409)									
						Mos				
						Hrs				
						Ldg				
CAB-30-01	TKS Fill Cap Placard Replacement									
30 A/F									RE (-)	Mandatory
	Eff: 23-Apr-2012 (AVG MAN HRS: 0.5)									
						Mos				
						Hrs				
						Ldg				
CAB-30-02	FIKI Installation for Airplanes with Provisions									
30 A/F									RE (-)	Recommended
	Eff: 17-May-2013 (AVG MAN HRS: 55)									
						Mos				
						Hrs				
						Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB-30-03	TKS Fill Cap Placard Replacement								RE (-)	Recommended
30 A/F										Mos
Eff: 23-Apr-2012										Hrs
(AVG MAN HRS: 0.5)										Ldg
CAB-30-05	Single Filter Element for TKS Aircraft								RE (-)	Optional
30 A/F										Mos
Eff: 03-Oct-2014										Hrs
										Ldg
CAB-30-05 Rev 1	Single Filter Element for TKS Aircraft								RE (-)	Optional
30 A/F										Mos
Eff: 03-Mar-2015										Hrs
										Ldg
CAB-30-06	FIKI Installation for Airplanes with a Fairing and with Provisions								RE (-)	Recommended
30 A/F										Mos
Eff: 07-Jan-2014										Hrs
(AVG MAN HRS: 25)										Ldg
CAB-30-07	TKS Ice Warning Placard Replacement								RE (-)	Mandatory
30 A/F										Mos
Eff: 10-Sep-2014										Hrs
(AVG MAN HRS: 0.5)										Ldg
CAB87-5	Windshield Anti-ice System Improvement								T (A/R)	Recommended
30 A/F										Mos
Eff: 24-Apr-1987										Hrs
										Ldg
CAB89-26	Bleed Air Pressure Relief Valve Installation - Superseded by CAB90-14								RE (-)	Mandatory
30 A/F										Mos
Eff: 08-Sep-1989										Hrs
										Ldg
CAB89-26 Rev 1	Bleed Air Pressure Relief Valve Installation - Superseded by CAB90-14								T (A/R)	Mandatory
30 A/F										Mos
Eff: 15-Jun-1990										Hrs
										Ldg
CAB93-20	Cargo Pod and Landing Gear Fairing De-ice System Installation								RE (-)	Optional
30 A/F										Mos
Eff: 22-Oct-1993										Hrs
(AVG MAN HRS: 37)										Ldg
CAB93-20 Rev 1	Cargo Pod and Landing Gear Fairing De-ice System Installation								T (A/R)	Optional
30 A/F										Mos
Eff: 13-Oct-1995										Hrs
(AVG MAN HRS: 37)										Ldg
CAB93-21	Windshield Anti-ice Panel Upper Retention Modification								T (A/R)	Optional
30 A/F										Mos
Eff: 19-Nov-1993										Hrs
										Ldg
CAL-30-01	Transmittal of CAV Aerospace Service Letter SL 13120-10-30-001 Cessna 208B Caravan TKS Ice Protection System Filter Element Replacement								RE (-)	Informational
30 A/F										Mos
Eff: 16-Mar-2012										Hrs
(AVG MAN HRS: 4)										Ldg
CAL-30-01 Rev 1	Transmittal of CAV Aerospace Service Letter SL 13120-10-30-001 Cessna 208B Caravan TKS Ice Protection System Filter Element Replacement								RE (-)	Informational
30 A/F										Mos
										Hrs
(AVG MAN HRS: 4)										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAL-30-01 Rev 2 30 A/F Eff: 09-Sep-2013 (AVG MAN HRS: 4)	Transmittal of CAV Aerospace Service Letter SL 13120-10-30-001 Cessna 208B Caravan TKS Ice Protection System Filter Element Replacement								T (-)	Informational, Service Letter
										Mos
										Hrs
										Ldg
CAL-30-01 Rev 3 30 A/F Eff: 30-Aug-2018 (AVG MAN HRS: 4)	Transmittal of CAV Aerospace Service Letter SL 13120-10-30-001 Cessna 208B Caravan TKS Ice Protection System Filter Element Replacement								T (-)	Informational, Service Letter
										Mos
										Hrs
										Ldg
CAL-30-01 Rev 4 30 A/F Eff: 25-Sep-2018 (AVG MAN HRS: 4)	Transmittal of CAV Aerospace Service Letter SL 13120-10-30-001 Cessna 208B Caravan TKS Ice Protection System Filter Element Replacement								T (A/R)	Informational, Service Letter
										Mos
										Hrs
										Ldg
CAL-30-02 30 A/F Eff: 22-Oct-2015 (AVG MAN HRS: 6.5)	Ice and Rain Protection - Travel Tube Bracket Weldment Replacement								RE (-)	Informational
										Mos
										Hrs
										Ldg
SNL93-1 30 A/F Eff: 30-Apr-1993	Improved Surface De-Ice Boots								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL99-11 30 A/F Eff: 08-Nov-1999	Cargo Pod Optional Material De-Ice Boot Installation								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SSP08-4 30 A/F Eff: 15-Dec-2008	TKS Right Mid Wing Porous Panel Inspection								T (A/R)	Mandatory
										Mos
										Hrs
										Ldg
SSP11-01 30 A/F Eff: 18-Jan-2011 (AVG MAN HRS: 420)	TKS and Low Airspeed Awareness (LAA) System Installation for Model 208B Airplanes with Provisions								RE (-)	Optional
										Mos
										Hrs
										Ldg
SSP11-01 Rev 1 30 A/F Eff: 15-Feb-2011 (AVG MAN HRS: 420)	TKS and Low Airspeed Awareness (LAA) System Installation for Model 208B Airplanes with Provisions								RE (-)	Optional
										Mos
										Hrs
										Ldg
▼ 31 - INDICATING / RECORDING SYSTEM										
CAB-31-01 31 A/F Eff: 21-Oct-2015	Indicating/Recording Systems - CVDR Installation								T (-)	Optional
										Mos
										Hrs
										Ldg
CAB-31-01 Rev 1 31 A/F Eff: 14-Aug-2017 (NOTE: NOTE: This service bulletin is not applicable to aircraft that have the Dual GMA1347 Audio Panel Option.)	Indicating/Recording Systems - CVDR Installation								T (-)	Optional
										Mos
										Hrs
										Ldg
CAB-31-01 Rev 2 31 A/F Eff: 06-May-2019 (NOTE: NOTE: This service bulletin is not applicable to aircraft that have the Dual GMA1347 Audio Panel Option.)	Indicating/Recording Systems - CVDR Installation								T (A/R)	Optional
										Mos
										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB94-15	Right Hand Airspeed Indicator Inspection								T (A/R)	Mandatory
31 A/F										Mos
Eff: 14-Oct-1994										Hrs
										Ldg
CAB96-4	Annunciator Panel Transistor Modification								RE (-)	Optional
31 A/F										Mos
Eff: 26-Jan-1996										Hrs
										Ldg
CAB96-4 Rev 1	Annunciator Panel Transistor Modification								T (A/R)	Optional
31 A/F										Mos
Eff: 09-Aug-1996										Hrs
										Ldg
SK208-170	Interturbine Temperature Indicator Replacement								T (A/R)	
31 A/F										Mos
Eff: 30-Jun-2006										Hrs
										Ldg
SNL92-2	Improved Heated Pitot Tube								T (A/R)	Informational
31 A/F										Mos
Eff: 24-Jan-1992										Hrs
										Ldg
▼ 32 - LANDING GEAR										
CAB00-3	Main Landing Gear Axle Inspection/Replacement								T (A/R)	Mandatory
32 A/F										Mos
Eff: 06-Mar-2000										Hrs
										Ldg
CAB03-5	Main Landing Gear Brake Line and Deice Line Clamp Replacement								RE (-)	Mandatory
32 A/F										Mos
Eff: 16-Jun-2003										Hrs
(AVG MAN HRS: 1.5)										Ldg
CAB03-5 Rev 1	Main Landing Gear Brake Line and Deice Line Clamp Replacement								T (A/R)	Mandatory
32 A/F										Mos
Eff: 15-Dec-2003										Hrs
(AVG MAN HRS: 1.5)										Ldg
CAB03-6	Main Landing Gear to Fuselage Fairing Modification and Trunnion Inspection								T (A/R)	Recommended
32 A/F										Mos
Eff: 15-Jun-2003										Hrs
										Ldg
CAB03-7	Main Landing Gear Part Number and Serial Identification Placard Installation								T (A/R)	Mandatory
32 A/F										Mos
Eff: 16-Jun-2003										Hrs
(AVG MAN HRS: 2)										Ldg
CAB05-16	Nose Landing Gear Lord Shimmy Dampener Installation								T (A/R)	Optional
32 A/F										Mos
Eff: 22-Dec-2005										Hrs
(AVG MAN HRS: 2)										Ldg
CAB05-17	Main Landing Gear Trunnion and Fairing Inspection								T (A/R)	Mandatory
32 A/F										Mos
Eff: 12-Dec-2005										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB07-1	Nose Landing Gear Over Travel Indicator/LORD Shimmy Dampener Installation								T (A/R)	Recommended
32 A/F										Mos
Eff: 19-Feb-2007										Hrs
(AVG MAN HRS: 4)										Ldg
CAB-32-01	Brake System Modification and Cleansing Procedure								RE (-)	Mandatory
32 A/F										Mos
Eff: 20-Sep-2013										Hrs
										Ldg
CAB-32-01 Rev 1	Brake System Modification and Cleansing Procedure								RE (-)	Mandatory
32 A/F										Mos
Eff: 14-Mar-2014										Hrs
										Ldg
CAB-32-02	NLG Spring Forward Support Assembly Modification								RE (-)	Optional
32 A/F										Mos
Eff: 05-Nov-2014										Hrs
										Ldg
CAB-32-03	Brake System Modification								RE (-)	Mandatory
32 A/F										Mos
Eff: 17-Apr-2014										Hrs
(AVG MAN HRS: 3.5)										Ldg
CAB-32-04	Landing Gear - Main Landing Gear Trunnion and Fairing Inspection								RE (-)	Mandatory
32 A/F										Mos
Eff: 11-Jan-2016										Hrs
(AVG MAN HRS: 107)										Ldg
CAB-32-04 Rev A	Landing Gear - Main Landing Gear Trunnion and Fairing Inspection								RE (-)	Mandatory
32 A/F										Mos
Eff: 11-Jan-2016										Hrs
(AVG MAN HRS: 107)										Ldg
CAB-32-05	Landing Gear - Nose Landing Gear Fairing Inspection								RE (-)	Mandatory
32 A/F										Mos
Eff: 15-Sep-2016										Hrs
(AVG MAN HRS: 4)										Ldg
CAB88-12	Main Landing Gear Lower Fairing Improvement								RE (-)	Recommended
32 A/F										Mos
Eff: 25-Mar-1988										Hrs
										Ldg
CAB88-12 Rev 1	Main Landing Gear Lower Fairing Improvement								T (A/R)	Recommended
32 A/F										Mos
Eff: 11-Nov-1988										Hrs
										Ldg
CAB88-14	Shimmy Dampener Improvement								T (A/R)	Recommended
32 A/F										Mos
Eff: 08-Apr-1988										Hrs
										Ldg
CAB88-40	Nose Gear Steering Bushing Replacement								T (A/R)	Mandatory
32 A/F										Mos
Eff: 09-Dec-1988										Hrs
										Ldg
CAB89-13	Landing Gear Wheel Bearings Special Inspection and Lubrication								T (A/R)	Recommended
32 A/F										Mos
Eff: 19-May-1989										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB89-2 32 A/F Eff: 06-Jan-1989	Nose Landing Gear Torque Link Replacement								RE (-)	Mandatory
					Mos					
					Hrs					
					Ldg					
CAB89-2 Rev 1 32 A/F Eff: 11-May-1990	Nose Landing Gear Torque Link Replacement								RE (-)	Mandatory
					Mos					
					Hrs					
					Ldg					
CAB89-2 Rev 2 32 A/F Eff: 06-Jul-1990	Nose Landing Gear Torque Link Replacement								RE (-)	Mandatory
					Mos					
					Hrs					
					Ldg					
CAB89-8 32 A/F Eff: 17-Feb-1989	Main Gear Upper Elbow Fairing Installation								T (A/R)	Optional
					Mos					
					Hrs					
					Ldg					
CAB90-12 32 A/F Eff: 30-Mar-1990 (AVG MAN HRS: 12)	Landing Gear Springs Paint Adhesion Inspection and Repair								RE (-)	Recommended
					Mos					
					Hrs					
					Ldg					
CAB90-12 Rev 1 32 A/F Eff: 22-Jun-1990 (AVG MAN HRS: 12)	Landing Gear Springs Paint Adhesion Inspection and Repair								T (A/R)	Recommended
					Mos					
					Hrs					
					Ldg					
CAB90-26 32 A/F Eff: 12-Oct-1990	Main Landing Gear Brake Line Replacement								T (A/R)	Optional
					Mos					
					Hrs					
					Ldg					
CAB90-5 32 A/F Eff: 02-Mar-1990	Nose Gear Fork Attach Bolt Replacement								T (A/R)	Recommended
					Mos					
					Hrs					
					Ldg					
CAB91-30 32 A/F Eff: 11-Oct-1991	Nose Gear Axle Spacer Replacement								T (A/R)	Optional
					Mos					
					Hrs					
					Ldg					
CAB91-4 32 A/F Eff: 22-Mar-1991	Main Landing Gear Rubber Fairing Modification								T (A/R)	Optional
					Mos					
					Hrs					
					Ldg					
CAB94-18 32 A/F Eff: 30-Dec-1994	Main Landing Gear Fairing Baffle Modification								T (A/R)	Optional
					Mos					
					Hrs					
					Ldg					
CAB95-12 32 A/F Eff: 28-Jul-1995	Parking Brake Valve Inspection/Replacement								T (A/R)	Mandatory
					Mos					
					Hrs					
					Ldg					
CAB95-13 32 A/F Eff: 28-Jul-1995	Nose Landing Gear Spring Inspection and Identification								T (A/R)	Mandatory
					Mos					
					Hrs					
					Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB95-2 32 A/F Eff: 24-Feb-1995	Nose Landing Gear Nut Replacement								T (A/R)	Recommended
										Mos
										Hrs
										Ldg
CAB96-20 32 A/F Eff: 13-Sep-1996	Nose Landing Gear Spring Fork Attach Bolt Inspection/Modification								T (A/R)	Recommended
										Mos
										Hrs
										Ldg
CAB96-24 32 A/F Eff: 16-Dec-1996	Nose Landing Gear Drag Link Spring Inspection/Modification								T (A/R)	Mandatory
										Mos
										Hrs
										Ldg
CAB96-3 32 A/F Eff: 26-Jan-1996	Nose Landing Gear Shimmy Dampener Installation Inspection and Modification								T (A/R)	Optional
										Mos
										Hrs
										Ldg
CAB98-6 32 A/F Eff: 23-Mar-1998	Main Landing Gear Lower Fairing Baffle Replacement								T (A/R)	Optional
										Mos
										Hrs
										Ldg
CAB98-9 32 A/F Eff: 04-May-1998	Right Brake Master Cylinder Supply Hose Modification								T (A/R)	Mandatory
										Mos
										Hrs
										Ldg
CAB99-3 32 A/F Eff: 28-Jun-1999	Shimmy Dampener Modification								T (A/R)	Optional
										Mos
										Hrs
										Ldg
CAL-32-01 32 A/F Eff: 16-Apr-2014 (AVG MAN HRS: 5)	Parking Brake Inspection								RE (-)	Mandatory
										Mos
										Hrs
										Ldg
CAL-32-02 32 A/F Eff: 14-May-2015	Transmittal of Parker Service Bulletin SB7105								RE (-)	Informational
										Mos
										Hrs
										Ldg
SA39CH 32 A/F Complied With	Landing Gear Position Advisory System, Supplemental Type Certificate								RE (-)	
										Mos 07-May-2018
										Hrs 93.4
										Ldg 102
SK208-135 32 A/F Eff: 27-Apr-1998	Voltage Suppression Jumper Installation								T (A/R)	
										Mos
										Hrs
										Ldg
SK208-67 32 A/F Eff: 20-Jun-1989	Nose Gear Fork Replacement - Extended Fork								RE (-)	
										Mos
										Hrs
										Ldg
SK208-67 Rev A 32 A/F Eff: 29-Sep-1995	Nose Gear Fork Replacement - Extended Fork								T (A/R)	
										Mos
										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SK208-68	Nose Gear Fork Replacement - Standard Fork								T (A/R)	
32 A/F										
Eff: 01-May-1997										
SNL87-24	Nose Gear Shimmy Dampener Filler Plug Seal Protection								T (A/R)	Informational
32 A/F										
Eff: 30-Oct-1987										
SNL88-1	Brake Disc Heat Check/Crack Inspection Criteria								T (A/R)	Informational
32 A/F										
Eff: 08-Jan-1988										
SNL90-8	Slotted Brake Disc Availability								T (A/R)	Informational
32 A/F										
Eff: 26-Oct-1990										
SSP04-1	Main Landing Gear Part Number and Serial Identification Placard Installation								T (A/R)	Mandatory
32 A/F										
Eff: 08-Mar-2004										
SSP07-1	Nose Landing Gear - Goodyear Tire Tube Replacement								T (A/R)	Mandatory
32 A/F										
Eff: 05-Mar-2007										
WipAire Service Letter 190	Float stiffener inspection								RE (-)	
32 A/F										
On Hold										
(AVG MAN HRS: 16) (UPDATE NOTE: Initial mapping inspection completed)										
JTQ-WP-027 / JTQ-WP-027 START 03-NOV-2021										
33 - LIGHTS										
CAB05-12	Flashing Beacon Installation Inspection/Modification								T (A/R)	Recommended
33 A/F										
Eff: 31-Oct-2005										
(AVG MAN HRS: 1.5)										
CAB05-6	ALTAIR ADAS+ Annunciator Installation and Configuration File Modification								T (A/R)	Recommended
33 A/F										
Eff: 14-Mar-2005										
CAB08-7	Low Airspeed Awareness System Installation								RE (-)	Mandatory
33 A/F										
Eff: 16-Oct-2008										
(AVG MAN HRS: 21)										
CAB08-7 Rev 1	Low Airspeed Awareness System Installation								T (A/R)	Mandatory
33 A/F										
Eff: 19-Oct-2009										
(AVG MAN HRS: 21)										
CAB-33-01	Lights - LED Beacon Installation								RE (-)	Optional
33 A/F										
Eff: 15-Jan-2021										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB-33-02	Lights - Led Navigation and Anti-Collision Light Assemblies Installation								RE (-)	Optional
33 A/F										Mos
Eff: 09-Mar-2020										Hrs
										Ldg
CAB-33-02 Group A	Lights - Led Navigation and Anti-Collision Light Assemblies Installation								RE (-)	Optional
33 A/F										Mos
Eff: 09-Mar-2020										Hrs
										Ldg
CAB-33-02 Group B	Lights - Led Navigation and Anti-Collision Light Assemblies Installation								RE (-)	Optional
33 A/F										Mos
Eff: 09-Mar-2020										Hrs
										Ldg
CAB-33-02 Group C	Lights - Led Navigation and Anti-Collision Light Assemblies Installation								RE (-)	Optional
33 A/F										Mos
Eff: 09-Mar-2020										Hrs
										Ldg
CAB-33-04	Lights - LED Landing and Taxi Recognition Light Installation								RE (-)	Optional
33 A/F										Mos
Eff: 15-Jan-2021										Hrs
										Ldg
CAB-33-05	Lights - LED Courtesy Light Installation								RE (-)	Optional
33 A/F										Mos
Eff: 15-Jan-2021										Hrs
										Ldg
CAB-33-06	Lights - LED Wing Inspection Light Installation								RE (-)	Optional
33 A/F										Mos
Eff: 15-Jan-2021										Hrs
										Ldg
CAB-33-07	Lights - LED Nav/Anti-Collision Light Wiring Modification								T (A/R)	Recommended
33 A/F										Mos
Eff: 25-Mar-2020										Hrs
(AVG MAN HRS: 14) (NOTE: NOTE: The equivalent of this service bulletin has been incorporated on production airplanes 208B5604 and On.)										Ldg
CF-58-03	Emergency Lighting for Aircraft Cabin Interiors								RE (-)	Mandatory
33 A/F										Mos
Eff: 30-Jun-1959										Hrs
										Ldg
SSP05-2	Landing Light Lamp Inspection								T (A/R)	Mandatory
33 A/F										Mos
Eff: 27-Jun-2005										Hrs
										Ldg
▼ 34 - NAVIGATION										
2005-01-19	GARMIN International Inc. - Mode S Transponders								RE (-)	Mandatory (Appliance AD)
34 A/F										Mos
Eff: 23-Feb-2005 Not Applicable	DUE TO LATER REVISION OF SOFTWARE INSTALLED IN THE GTX 33 TRANSPONDER.									Hrs
Brand A:9990-2005-01-19										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time Remaining
SEQ	PN/SN	MOC Note or Component Condition							DUE	
2006-16-18 R1		Sandel Avionics Incorporated - Installing a warning placard on the TAWS/RMI							RE (-)	Mandatory (Appliance AD)
34 A/F						Mos	29-Jun-2016			
	Eff: 18-Jul-2008 Not Applicable	EQUIPMENT NOT INSTALLED ON ACFT.					Hrs	0		
	(NOTE: Any installation comprised of: ST3400 with VOR bearing pointer configured in COMPOSITE NAV - and - 3.05 or A3.05 software or earlier)					Ldg	0			
2008-26-10		Alternate Static Air Source Selector Valve - Inspection/ Replacement							RE (-)	Mandatory
34 A/F						Mos	29-Jun-2016			
	Eff: 05-Jan-2009 Not Applicable	PER PARAGRAPH (C) OF THIS AD.					Hrs	0		
						Ldg	0			
2008-26-10 Par. (e)(1)(2)(3)(4)		Alternate Static Air Source Selector Valve - Inspection							RE (-)	Mandatory
34 A/F						Mos				
	Eff: 05-Jan-2009						Hrs			
	(NOTE: APPLICABILITY: For all affected airplanes that are not equipped for flight under instrument flight rules (IFR).)					Ldg				
2008-26-10 Par. (e)(2)(i)(B)		Alternate Static Air Source Selector Valve - Install Placard							RE (-)	Mandatory
34 A/F						Mos				
	Eff: 05-Jan-2009						Hrs			
						Ldg				
2008-26-10 Par. (e)(5)		Alternate Static Air Source Selector Valve - Replacement							RE (-)	Mandatory
34 A/F						Mos				
	Eff: 05-Jan-2009						Hrs			
	(NOTE: APPLICABILITY: For all affected airplanes.)					Ldg				
2017-04-06		Altimeter - United Instruments Model 5934 Series - Slow Diaphragm Leak							RE (-)	Mandatory (Appliance AD)
34 A/F						Mos	27-Jun-2017			
	Eff: 07-Apr-2017 Not Applicable	BY S/N 510450					Hrs	59		
	(AVG MAN HRS: 1) (NOTE: APPLICABILITY: This AD applies to United Instruments, Inc. 5934 series altimeters that were manufactured between January 2015 and February 2016 and installed in airplanes and helicopters. NOTE: Refer to United Instruments, Inc. Service Bulletin No. 13, dated March 25, 2016.)					Ldg	56			
2021-08-15		Garmin International GMN-00962 GTS Processor Units							T	Mandatory (Appliance AD)
34 A/F						Mos			24	17-May-2023 1.1 Years
	Eff: 17-May-2021						Hrs			
	(NOTE: Required Action and Compliance: Within 24 months after the effective date of this AD, update the GTS processor software to a version that is not 3.13 or earlier, except 3.12.1. Software version 3.12.1 does not contain the unsafe condition.)					Ldg				
2021-23-12		Indicating/Recording System, Navigation - Radio Altimeter (Transport and Commuter Category Airplanes)							RE (-)	Mandatory (Appliance AD)
34 A/F						Mos	14-Jan-2022			
	Eff: 03-Jan-2022 Complied With						Hrs	357		
	(UPDATE NOTE: AD added to Pilot's Digital AFMs) (NOTE: COMPLIANCE: On or before January 4, 2022: Revise the Limitations Section of the existing AFM by incorporating the limitations specified in figure 1 to paragraph (g) of this AD. This may be done by inserting a copy of this AD into the existing AFM.)					Ldg	619			
98-25-02		BF Goodrich Avionics Systems, Inc. SKYWATCH SKY497 Installations with a Top-Mounted Antenna							RE (-)	Mandatory (Appliance AD)
34 A/F						Mos	29-Jun-2016			
	Eff: 22-Dec-1998 Not Applicable	AD 98-25-02 BF GOODRICH AVIONICS SYSTEMS, THIS AD IS NOT APPLICABLE DUE TO PARTS ARE NOT INSTALLED. -YS					Hrs	0		
						Ldg	0			
CAB01-10		KLN 94 GPS Navigation System Software Upgrade							T (A/R)	Mandatory
34 A/F						Mos				
	Eff: 08-Oct-2001						Hrs			
						Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB01-11 34 A/F Eff: 29-Oct-2001	KAS 297B Altitude Preselect Wiring Modification								T (A/R)	Mandatory
					Mos					
					Hrs					
					Ldg					
CAB01-16 34 A/F Eff: 24-Dec-2001	Transcal Altitude Digitizer Wiring Modification								T (A/R)	Mandatory
					Mos					
					Hrs					
					Ldg					
CAB01-2 34 A/F Eff: 15-Jan-2001 (AVG MAN HRS: 3)	Vacuum System Air Filter Element Inspection/Replacement								T (A/R)	Recommended
					Mos					
					Hrs					
					Ldg					
CAB01-4 34 A/F Eff: 12-Feb-2001	Encoding Altimeter Inspection								T (A/R)	Mandatory
					Mos					
					Hrs					
					Ldg					
CAB04-10 34 A/F Eff: 01-Nov-2004	Honeywell KGP 560 Enhanced Ground Proximity Warning System Modification								T (A/R)	Optional
					Mos					
					Hrs					
					Ldg					
CAB04-11 34 A/F Eff: 01-Nov-2004	Honeywell KMH 820 Multihazard Sensor Modification								T (A/R)	Optional
					Mos					
					Hrs					
					Ldg					
CAB04-6 34 A/F Eff: 26-Jul-2004	Pitot Tube Inspection								T (A/R)	Mandatory
					Mos					
					Hrs					
					Ldg					
CAB05-1 34 A/F Eff: 24-Jan-2005	Honeywell KLN 94 GPS Navigation System Modification								T (A/R)	Recommended
					Mos					
					Hrs					
					Ldg					
CAB05-10 34 A/F Eff: 22-Aug-2005 (AVG MAN HRS: 2)	Altair ADAS+ Processor Software Modification								RE (-)	Optional
					Mos					
					Hrs					
					Ldg					
CAB05-10 Rev 1 34 A/F Eff: 05-Sep-2005 (AVG MAN HRS: 2)	Altair ADAS+ Processor Software Modification								T (A/R)	Optional
					Mos					
					Hrs					
					Ldg					
CAB08-4 34 A/F Eff: 31-Mar-2008 (AVG MAN HRS: 0.5)	Alternate Static Source Selector Valve Inspection								RE (-)	Mandatory
					Mos					
					Hrs					
					Ldg					
CAB08-4 Rev 1 34 A/F Eff: 06-Oct-2008 (AVG MAN HRS: 0.5)	Alternate Static Source Selector Valve Inspection								T (A/R)	Mandatory
					Mos					
					Hrs					
					Ldg					
CAB-09-11 34 A/F Eff: 20-Oct-2009	Garmin G1000 Avionics Chartview Option								T (-)	Optional
					Mos					
					Hrs					
					Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB-09-11 R1	Garmin G1000 Avionics Chartview Option								T (A/R)	Optional
34 A/F										Mos
Eff: 08-Feb-2022										Hrs
(AVG MAN HRS: 1.6)										Ldg
CAB09-6	Garmin G1000 System Software Upgrade to Version 767.04								T (A/R)	Mandatory
34 A/F										Mos
Eff: 24-Aug-2009										Hrs
(AVG MAN HRS: 2)										Ldg
CAB-09-7	Garmin G1000 Synthetic Vision Installation								T (-)	Optional
34 A/F										Mos
Eff: 24-Aug-2009										Hrs
										Ldg
CAB-09-7 R1	Garmin G1000 Synthetic Vision Installation for Airplanes not Equipped with NXI								T (A/R)	Optional
34 A/F										Mos
Eff: 08-Feb-2022										Hrs
(AVG MAN HRS: 0.8)										Ldg
CAB10-8	NAV/Strobe Light Replacement								T (A/R)	Recommended
34 A/F										Mos
Eff: 20-Jul-2010										Hrs
										Ldg
CAB11-3	Garmin G1000 System Software Upgrade to Version 0767.07								T (A/R)	Mandatory
34 A/F										Mos
Eff: 26-Apr-2011										Hrs
(AVG MAN HRS: 3)										Ldg
CAB11-4	Garmin GWX 68 Weather Radar Modification								T (A/R)	Recommended
34 A/F										Mos
Eff: 24-May-2011										Hrs
										Ldg
CAB-34-01	Garmin G1000 Enhanced Search and Rescue Enablement Option								T (A/R)	Optional
34 A/F										Mos
Eff: 10-May-2012										Hrs
(AVG MAN HRS: 0.8)										Ldg
CAB-34-02	Garmin G1000 System Software Upgrade to Version 0767.13								RE (-)	Mandatory
34 A/F										Mos
Eff: 15-May-2012										Hrs
(AVG MAN HRS: 3.5)										Ldg
CAB-34-03	Navigation - Garmin G1000 System Software Upgrade to Version 0767.23								RE (-)	Recommended
34 A/F										Mos
Eff: 01-Nov-2016										Hrs
(AVG MAN HRS: 19)										Ldg
CAB-34-03 Rev 01	Navigation - Garmin G1000 System Software Upgrade to Version 0767.25								RE (-)	Recommended
34 A/F										Mos
Eff: 08-Jan-2019										Hrs
										Ldg
CAB-34-04	Garmin G1000 ADS-B Out Activation								T (-)	Optional
34 A/F										Mos
Eff: 09-Nov-2016										Hrs
(NOTE: NOTE: On airplanes that are not equipped with Garmin Software 0767.23 or later, CAB-34-03, "NAVIGATION - GARMIN G1000 SYSTEM SOFTWARE UPGRADE TO VERSION 0767.23," shall be accomplished prior to this service bulletin.)										Ldg

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
CAB-34-04 Rev 01		Garmin G1000 ADS-B Out Activation						T (A/R)		Optional	
	34 A/F										Mos
	Eff: 08-Jan-2019										Hrs
	(NOTE: NOTE: On airplanes that are not equipped with Garmin Software 0767.23 or later, the latest revision of CAB-34-03 shall be accomplished prior to this service bulletin.)										Ldg
CAB-34-06		Navigation - Install KRA-405B Radar Altimeter						T (A/R)		Optional	
	34 A/F										Mos
	Eff: 17-Nov-2016										Hrs
											Ldg
CAB-34-09		Navigation - Garmin G1000 NXI Synthetic Vision Installation						RE (-)		Optional	
	34 A/F										Mos
	Eff: 08-Feb-2022										Hrs
											Ldg
CAB-34-10		Navigation - Install Chartview on G1000 NXI Airplanes						RE (-)		Optional	
	34 A/F										Mos
	Eff: 08-Feb-2022										Hrs
											Ldg
CAB-34-11		Navigation - Stall Warning Horn Replacement						T (A/R)		Optional	
	34 A/F										Mos
	Eff: 25-May-2021										Hrs
											Ldg
CAB88-34		Static Source Selector Valve Modification						T (A/R)		Mandatory	
	34 A/F										Mos
	Eff: 11-Nov-1988										Hrs
											Ldg
CAB88-8		Radio Cover Watershield Installation and Cabin Top Sealing						T (A/R)		Recommended	
	34 A/F										Mos
	Eff: 18-Mar-1988										Hrs
											Ldg
CAB89-9		Avionics Cover Plate Modification						T (A/R)		Mandatory	
	34 A/F										Mos
	Eff: 31-Mar-1989										Hrs
											Ldg
CAB90-32		Improved Airspeed Warning Switch Installation						T (A/R)		Optional	
	34 A/F										Mos
	Eff: 07-Dec-1990										Hrs
											Ldg
CAB94-8		Avionics Wire Harness Grounding Connector Inspection						T (A/R)		Recommended	
	34 A/F										Mos
	Eff: 11-Feb-1994										Hrs
											Ldg
CAB97-1		KLN 89B GPS Navigation System Software						RE (-)		Mandatory	
	34 A/F										Mos
	Eff: 20-Jan-1997										Hrs
											Ldg
CAB97-1 Rev 1		KLN 89B GPS Navigation System Software						T (A/R)		Mandatory	
	34 A/F										Mos
	Eff: 30-Jun-1997										Hrs
											Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB97-8	Avionics Number Two Power Switch/Breaker Replacement								T (A/R)	Mandatory
34 A/F										Mos
Eff: 30-Jun-1997										Hrs
										Ldg
CAB97-9	KLN 89B GPS Navigation System Approach Restrictions								T (A/R)	Mandatory
34 A/F										Mos
Eff: 02-Jul-1997										Hrs
										Ldg
CAB98-12	KLN 89B GPS Navigation System IFR Non-Precision Approach Limitation								RE (-)	Mandatory
34 A/F										Mos
Eff: 15-Jun-1998										Hrs
(AVG MAN HRS: 2.5)										Ldg
CAB98-12 Rev 1	KLN 89B GPS Navigation System IFR Non-Precision Approach Limitation								T (A/R)	Mandatory
34 A/F										Mos
Eff: 20-Jul-1998										Hrs
(AVG MAN HRS: 2.5)										Ldg
CAB98-13	ART 2000-6 Weather Radar Modification								T (A/R)	Recommended
34 A/F										Mos
Eff: 31-Aug-1998										Hrs
										Ldg
CAB98-14	Radar Pod Drain Hole Modification and Scupper Installation								T (A/R)	Optional
34 A/F										Mos
Eff: 31-Aug-1998										Hrs
										Ldg
CAB99-2	KLN 89B GPS Navigation System Modification								T (A/R)	Mandatory
34 A/F										Mos
Eff: 28-Jun-1999										Hrs
										Ldg
CAL-34-01	Garmin G1000 Loading Updated Databases								T (A/R)	Recommended
34 A/F										Mos
Eff: 16-May-2012										Hrs
										Ldg
CAL-34-02	Navigation - Replacement of Nonconforming Diaphragm Assemblies in Affected Altimeters								RE (-)	Mandatory
34 A/F										Mos
Eff: 15-Sep-2016 Not Applicable	BY S/N 510450						27-Jun-2017			Hrs
(AVG MAN HRS: 2.5) (NOTE: EFFECTIVITY: For Group B Airplanes.)										59
										Ldg
										56
CAL-34-03	Navigation - Transmittal of Garmin Service Advisory No 1612 2015 IGRF (International Geomagnetic Reference Field) Magnetic Field Model								T (-)	Service Letter
34 A/F										Mos
Eff: 04-Aug-2016										Hrs
										Ldg
CAL-34-03 R1	Navigation - Transmittal of Garmin Service Advisory No 1612 2015 IGRF (International Geomagnetic Reference Field) Magnetic Field Model								T (-)	Service Letter
34 A/F										Mos
Eff: 26-Sep-2016										Hrs
										Ldg
CAL-34-03 R2	Navigation - Transmittal of Garmin Service Advisory No.: 1612 Revision E, 2020 IGRF (International Geomagnetic Reference Field) Magnetic Field Model								T (-)	Informational
34 A/F										Mos
Eff: 25-Jan-2021										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAL-34-03 R3 34 A/F Eff: 24-May-2021	Navigation - Transmittal of Garmin Service Advisory No.: 1612 Revision F, 2020 IGRF (International Geomagnetic Reference Field) Magnetic Field Model								T (A/R)	Informational, Service Letter
										Mos
										Hrs
										Ldg
CAL-34-04 34 A/F Eff: 19-Jan-2021 (NOTE: EFFECTIVITY: Aircraft that have not incorporated CAB-34-03 (Revision 1).)	Navigation - Transmittal of Garmin SB 2046, GRS 77 Software Version 3.04 - Pitch/Roll Offset Calibration Procedure (G1000 With Dual GRS and Three Displays)								T (A/R)	Informational
										Mos
										Hrs
										Ldg
CAL-34-05 34 A/F Eff: 01-Nov-2021	Navigation - Transmittal of Garmin SB 19102 GRS 56 MOD 1								RE (-)	Informational, Service Letter
										Mos
										Hrs
										Ldg
ICA-208-34-00001 34 A/F Eff: 18-Feb-2016	GTS 825 TAS/ADS-B Out and Phase 14 Software Update								RE (-)	ICA Supplement
										Mos
										Hrs
										Ldg
ICA-208-34-00002 34 A/F Eff: 03-May-2017	Garmin G1000 NXI Wiring Update								RE (-)	ICA Supplement
										Mos
										Hrs
										Ldg
SE-TP-007 34 A/F Complied With	Inspection Programs / Base Software Cards And Software Unlock Cards, Communique THE AIRCRAFT IS BEING MAINTAINED IAW CAR 704 OPERATIONS SMALL AIRCRAFT MAINTENANCE SCHEDULE APPROVAL/PAX 0731-C208 APPROVED BY TRANSPORT CANADA - ATTACHED.								RE (-)	
										Mos 28-May-2020
										Hrs 255.8
										Ldg 388
SNL02-2 34 A/F Eff: 11-Feb-2002	Honeywell KI 256 Attitude Indicator Special Pricing Enhancements								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL03-1 34 A/F Eff: 22-Dec-2003	Honeywell KI 256 Attitude Indicator Special Pricing Enhancements								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL03-12 34 A/F Eff: 22-Dec-2003	Altair Avionics Engine Airborne Data Acquisition System Installation								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL04-8 34 A/F Eff: 15-Nov-2004	Honeywell KI 256 Attitude Indicator Special Pricing Enhancements								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL08-18 34 A/F Eff: 25-Aug-2008	G1000 Transponder Flight Identification Operation								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL08-19 34 A/F Eff: 25-Aug-2008	Garmin G1000 Series Flight Plan Sequencing Issue								T (A/R)	Informational
										Mos
										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SNL09-1 34 A/F Eff: 09-Feb-2009	Garmin G1000 Systems LPV and LNAV/VNAV Approaches with Three-Character Airport Identifiers								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL09-2 34 A/F Eff: 09-Feb-2009	Loss of GPS/WAAS in Northern Latitudes								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL09-5 34 A/F Eff: 01-Jun-2009	DME Red X Indication During Garmin G1000 Start Up								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL11-10 34 A/F Eff: 26-Apr-2011	Garmin G1000 AOPA Database								T (A/R)	Optional
										Mos
										Hrs
										Ldg
SNL11-16 34 A/F Eff: 15-Jul-2011	Garmin SA1129A GRS77 Loss of Function								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL11-2 34 A/F Eff: 15-Mar-2011	Removal of Affected Approaches in Database Cycle 1013 for Airplanes with Garmin G1000 and WAAS								T (A/R)	
										Mos
										Hrs
										Ldg
SNL88-7 34 A/F Eff: 25-Mar-1988	Transponder Installation - Performance Troubleshooting and Repair Procedures								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL97-4 34 A/F Eff: 01-Sep-1997	Bendix/King RDR 2000 Weather Radar Modifications								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SSP02-1 34 A/F Eff: 20-May-2002	Honeywell KN 63 DME Inspection/Modification								T (A/R)	Mandatory
										Mos
										Hrs
										Ldg
SSP02-2 34 A/F Eff: 25-Nov-2002	Garmin GNS 430 and GNS 530 Modification								T (A/R)	Recommended
										Mos
										Hrs
										Ldg
SSP02-3 34 A/F Eff: 25-Nov-2002	Goodrich WX-500 Weather Mapping Sensor Modification								T (A/R)	Optional
										Mos
										Hrs
										Ldg
SSP02-4 34 A/F Eff: 25-Nov-2002	Goodrich Skywatch TRC497 Modification								T (A/R)	Optional
										Mos
										Hrs
										Ldg
SSP02-5 34 A/F Eff: 25-Nov-2002	Goodrich WX-1000 Weather Mapping System Modification								T (A/R)	Optional
										Mos
										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SSP03-1	KAC 503-1 Flight Information Services Interface Module Modification								T (A/R)	Mandatory
34 A/F										Mos
Eff: 24-Feb-2003										Hrs
										Ldg
SSP03-3	Garmin GTX 330/330D Transponder Modification								T (A/R)	Mandatory
34 A/F										Mos
Eff: 04-Oct-2004										Hrs
										Ldg
SSP04-3	Garmin GTX 330/330D Transponder Modification								T (A/R)	Recommended
34 A/F										Mos
Eff: 04-Oct-2004										Hrs
										Ldg
SSP04-4	Garmin GTX 330/330D Transponder Modification								T (A/R)	Mandatory
34 A/F										Mos
Eff: 04-Oct-2004										Hrs
										Ldg
SSP04-5	Altair ADAS+ Processor Replacement								T (A/R)	Recommended
34 A/F										Mos
Eff: 27-Dec-2004										Hrs
										Ldg
SSP04-6	Altair ADAS+ Processor Modification								T (A/R)	Recommended
34 A/F										Mos
Eff: 27-Dec-2004										Hrs
										Ldg
SSP05-1	Honeywell KRA 405B Radar Altimeter Modification								T (A/R)	Optional
34 A/F										Mos
Eff: 13-Jun-2005										Hrs
										Ldg
SSP05-3	Honeywell KI 825 Electronic Horizontal Situation Indicator (EHSI) Modification								T (A/R)	Recommended
34 A/F										Mos
Eff: 25-Jul-2005										Hrs
										Ldg
SSP05-4	Honeywell KI 825 Electronic Horizontal Situation Indicator (EHSI) Washer Installation								T (A/R)	Recommended
34 A/F										Mos
Eff: 25-Jul-2005										Hrs
										Ldg
SSP08-1	Serial Number Inspection of Garmin G1000 Line Replacement Units and Outside Air Temperature Probes								T (A/R)	Mandatory
34 A/F										Mos
Eff: 13-Oct-2008										Hrs
										Ldg
▼ 35 - OXYGEN										
2015-23-09	Oxygen - Zodiac Aerotechnics (Formerly Inter Technique Aircraft Systems) Flight Crew Oxygen Mask Regulators - Inspection / Replacement Of Oxygen Mask Regulators								RE (-)	Mandatory (Appliance AD)
35 A/F										Mos
Eff: 28-Dec-2015 Not Applicable	APPLIANCE AD-OXYGEN-ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW/OXYGEN MASK REGULATORS-INSPECTION/REPLACEMENT OF OXYGEN MASK REGULATORS. N/A SUSPECT PARTS NOT INSTALLED						29-Jun-2016			Hrs
										Ldg
										0
										0
2015-23-09 Para (g)	Oxygen - Inspect Each Flightcrew Oxygen Mask Regulator To Identify The Part Number And Serial Number								RE (-)	Mandatory (Appliance AD)
35 A/F										Mos
Eff: 28-Dec-2015 Not Applicable	INSPECT EACH FLIGHT CREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER. N/A SUSPECT PARTS NOT INSTALLED						29-Jun-2016			Hrs
										Ldg
										0
										0

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
2015-23-09 Para (h)(1)	Replace Each Affected Flightcrew Oxygen Mask With A Part Identified In Paragraph (H)(1)(I) Or (H)(1)(II).								RE (-)	Mandatory (Appliance AD)
35 A/F						Mos		29-Jun-2016		
Not Applicable	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II). N/A SUSPECT PARTS NOT INSTALLED					Hrs		0		
						Ldg		0		
2015-23-09 Para (h)(2)(i)	Revise The Emergency Procedures Section Of The Airplane Flight Manual (AFM) By Inserting The Statement Provided In Figure 1								RE (-)	Mandatory (Appliance AD)
35 A/F						Mos		29-Jun-2016		
Not Applicable	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1. N/A SUSPECT PARTS NOT INSTALLED					Hrs		0		
						Ldg		0		
2015-23-09 Para (h)(2)(ii)	Fabricate And Install A Placard On The Flightcrew Oxygen Mask Container That States: "Use Selector On 100% Or Emergency Only."								RE (-)	Mandatory (Appliance AD)
35 A/F						Mos		29-Jun-2016		
Not Applicable	FABRICATE AND INSTALL A PLACARD ON THE FLIGHT CREW OXYGEN MASK CONTAINER THAT STATES ? USE SELECTOR ON 100% OR EMERGENCY ONLY N/A SUSPECT PARTS NOT INSTALLED					Hrs		0		
						Ldg		0		
2015-23-09 Para (i)	Oxygen - Regulator Replacement								RE (-)	Mandatory (Appliance AD)
35 A/F						Mos		29-Jun-2016		
Eff: 28-Dec-2015 Not Applicable	APPLIANCE/EMERGENCY AD- AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)-INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS. N/A SUSPECT PARTS NOT INSTALLED					Hrs		0		
						Ldg		0		
2016-11-20	Oxygen - Aerospace Protective Breathing Equipment (PBE), part number (P/N) 119003-11								RE (-)	Mandatory (Appliance AD)
35 A/F						Mos		15-Feb-2017		
Eff: 15-Jul-2016 Not Applicable	THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE BY AIRCRAFT CONFIGURATION.					Hrs		46.1		
						Ldg		38		
2016-11-20 Paragraph (g)	Oxygen - Aerospace Protective Breathing Equipment (PBE), part number (P/N) 119003-11 - Inspection								RE (-)	Mandatory (Appliance AD)
35 A/F						Mos		15-Feb-2017		
Eff: 15-Jul-2016 Not Applicable	THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE BY AIRCRAFT CONFIGURATION.					Hrs		46.1		
	Brand A:9990-2016-11-20(g) (NOTE: Applicability: This AD applies to B/E Aerospace Protective Breathing Equipment (PBE), part number (P/N) 119003-11, that is installed on airplanes)					Ldg		38		
2016-11-20 Paragraph (h)	Oxygen - Aerospace Protective Breathing Equipment (PBE), part number (P/N) 119003-11 - Replacement								RE (-)	Mandatory (Appliance AD)
35 A/F						Mos		15-Feb-2017		
Eff: 15-Jul-2016 Not Applicable	THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE BY AIRCRAFT CONFIGURATION.					Hrs		46.1		
	Brand A:9990-2016-11-20(h) (NOTE: Applicability: This AD applies to B/E Aerospace Protective Breathing Equipment (PBE), part number (P/N) 119003-11, that is installed on airplanes)					Ldg		38		
2017-18-12	Oxygen - B/E Aerospace Protective Breathing Equipment (PBE) Units, P/N 119003-11 and 119003-21 - Inspect/ Replace (This AD replaces AD 2016-11-20)								RE (-)	Mandatory (Appliance AD)
35 A/F						Mos		27-Nov-2017		
Eff: 16-Oct-2017 Not Applicable (AVG MAN HRS: 2)	BY MASK PN INSTALLED					Hrs		87.8		
						Ldg		97		
2017-18-12 Par. (g)	Oxygen - B/E Aerospace Protective Breathing Equipment (PBE) Units - Inspection Retained From AD 2016-11-20 for Airplanes With PBE, P/N 119003-11, Installed								RE (-)	Mandatory (Appliance AD)
35 A/F						Mos		27-Nov-2017		
Eff: 15-Oct-2017 Not Applicable	BY MASK PN INSTALLED					Hrs		87.8		
	(AVG MAN HRS: 0.5) (NOTE: SCHEDULING/COMPLIANCE REVIEW NEEDED. This paragraph retains the requirements of AD 2016-11-20, which was due 3 months from July 15, 2016. Refer to B/E Aerospace Service Bulletin (SB) No. 119003-35-011, Rev. 000, dated February 4, 2015.)					Ldg		97		

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time Remaining
SEQ	PN/SN	MOC Note or Component Condition							DUE	
2017-18-12 Par. (h)		Oxygen - B/E Aerospace Protective Breathing Equipment (PBE) Units - Replacement Retained from AD 2016-11-20 for Airplanes with PBE, P/N 119003-11, Installed							RE (-)	Mandatory (Appliance AD)
35 A/F						Mos		27-Nov-2017		
Eff: 16-Oct-2017 Not Applicable						Hrs		87.8		
						Ldg		97		
(AVG MAN HRS: 0.5) (NOTE: APPLICABILITY: If a PBE pouch is found that does not have an intact vacuum seal. NOTE: Refer to B/E Aerospace SB No. 119003-35-009, Rev. 001, dated April 12, 2016.)										
2017-18-12 Par. (i)		Oxygen - B/E Aerospace Protective Breathing Equipment (PBE) Units - New Inspection for Airplanes With PBE, P/N 119003-21, Installed							RE (-)	Mandatory (Appliance AD)
35 A/F						Mos		27-Nov-2017		
Eff: 16-Oct-2017 Not Applicable						Hrs		87.8		
						Ldg		97		
(AVG MAN HRS: 0.5) (NOTE: NOTE: Refer to B/E Aerospace SB No. 119003-35-013, Rev. 002, dated July 19, 2017.)										
2017-18-12 Par. (j)		Oxygen - B/E Aerospace Protective Breathing Equipment (PBE) Units - New Replacement for Airplanes With PBE, P/N 119003-21, Installed							RE (-)	Mandatory (Appliance AD)
35 A/F						Mos		27-Nov-2017		
Eff: 16-Oct-2017 Not Applicable						Hrs		87.8		
						Ldg		97		
(AVG MAN HRS: 0.5) (NOTE: NOTE: Refer to B/E Aerospace SB No. 119003-35-013, Rev. 002, dated July 19, 2017.)										
2022-04-09		Valve Assembly Vent - AVOX Systems Inc. Oxygen Cylinder and Valve Assemblies							T	Mandatory (Appliance AD)
35 A/F						Days		60	03-Jun-2022	50 Days
Eff: 04-Apr-2022						Hrs				
						Ldg				
(NOTE: COMPLIANCE: Within 60 days after the effective date of this AD, inspect the oxygen valve assemblies, and oxygen cylinder and valve assemblies, to determine if the serial numbers of the valve, cylinder, and entire assembly, are listed in Appendix 1, "Affected Shipments," of the applicable service information identified in paragraphs (h)(1) through (3) of this AD. A review of airplane maintenance records is acceptable in lieu of this inspection if the serial numbers can be conclusively determined from that review. (1) AVOX Systems Inc. Alert Service Bulletin 10015804-35-01, Revision 02, dated October 16, 2019. (2) AVOX Systems Inc. Alert Service Bulletin 10015804-35-02, Revision 2, dated October 31, 2019. (3) AVOX Systems Inc. Alert Service Bulletin 10015804-35-03, Revision 02, dated October 15, 2019.)										
CAB88-33		Oxygen Gage Line Rerouting							T (A/R)	Mandatory
35 A/F						Mos				
Eff: 28-Oct-1988						Hrs				
						Ldg				
CAB93-19		Oxygen Control Lever Modification							T (A/R)	Optional
35 A/F						Mos				
Eff: 20-Jan-1995						Hrs				
						Ldg				
CAL-35-01		Altitude Compensated Regulator Inspection							RE (-)	Mandatory
35 A/F						Mos				
Eff: 16-May-2012						Hrs				
(AVG MAN HRS: 5)						Ldg				
▼ 36 - PNEUMATIC										
CAB11-1		P3 and Py Tube Inspection							T (A/R)	Recommended
36 A/F						Mos				
Eff: 15-Feb-2011						Hrs				
						Ldg				
CAB-36-01		Pneumatic - Ventilation and Drainage Improvements - Tailcone							RE (-)	Optional
36 A/F						Mos				
Eff: 15-Dec-2016						Hrs				
						Ldg				
CAB-36-01 Rev 1		Pneumatic - Ventilation and Drainage Improvements - Tailcone							T (A/R)	Optional
36 A/F						Mos				
Eff: 28-Jul-2017						Hrs				
(NOTE: NOTE: This service bulletin only applies to 208B airplanes with Cargo Pod installed.)						Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB88-11	Bleed Air Valve Pressure Regulator Poppet Nut Inspection and Modification								T (A/R)	
36 A/F										Mos
Eff: 25-Mar-1988										Hrs
										Ldg
CAB88-36	Pitot Static System Line Replacement								T (A/R)	Recommended
36 A/F										Mos
Eff: 18-Nov-1988										Hrs
										Ldg
CAB90-15	Pitot Static System Flareless Fitting Inspection								T (A/R)	Mandatory
36 A/F										Mos
Eff: 27-Apr-1990										Hrs
										Ldg
CAB93-1	Airborne Bleed Air Control Components Improvements								T (A/R)	Optional
36 A/F										Mos
Eff: 29-Jan-1993										Hrs
										Ldg
CAB93-2	Bleed Air Pressure Relief Valve Installation								T (A/R)	Mandatory
36 A/F										Mos
Eff: 12-Mar-1993										Hrs
										Ldg
▼ 37 - VACUUM										
CAB89-7	Vacuum Exhaust Ejector Fitting Improvement								T (A/R)	Optional
37 A/F										Mos
Eff: 17-Feb-1989										Hrs
										Ldg
CAB90-14	Bleed Air Pressure Relief Valve Removal								RE (-)	Mandatory
37 A/F										Mos
Eff: 13-Apr-1990										Hrs
(AVG MAN HRS: 8.5)										Ldg
CAB90-14 Rev 1	Bleed Air Pressure Relief Valve Removal								RE (-)	Mandatory
37 A/F										Mos
Eff: 15-Jun-1991										Hrs
(AVG MAN HRS: 8.5)										Ldg
CAB90-14 Rev 2	Bleed Air Pressure Relief Valve Removal								T (A/R)	Mandatory
37 A/F										Mos
Eff: 12-Mar-1993										Hrs
(AVG MAN HRS: 8.5)										Ldg
CAB91-11	Bleed Air Pressure Regulator Discharge Pressure Check (Superseded)								RE (-)	Mandatory
37 A/F										Mos
Eff: 19-Apr-1991										Hrs
(AVG MAN HRS: 0.5)										Ldg
CAB91-11 Rev 1	Bleed Air Pressure Regulator Discharge Pressure Check (Superseded)								RE (-)	Mandatory
37 A/F										Mos
Eff: 12-Mar-1993										Hrs
(AVG MAN HRS: 5)										Ldg
NL82-09	Vacuum Distribution System Troubleshooting								T (A/R)	Customer Care News Letter
37 A/F										Mos
Eff: 21-May-1982										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
▼ 51 - STANDARD PRACTICES AND STRUCTURES - GENERAL										
CAL-51-01	Structures - Use of Corrosion Inhibiting Compounds								T (A/R)	Informational
51 A/F										Mos
Eff: 13-Jan-2012										Hrs
										Ldg
▼ 52 - DOORS										
CAB88-16	Improved Door Restraint								T (A/R)	Optional
52 A/F										Mos
Eff: 15-Apr-1988										Hrs
										Ldg
CAB88-17	Cowl Door Rub Strip Improvement								T (A/R)	Optional
52 A/F										Mos
Eff: 22-Apr-1988										Hrs
										Ldg
CAB88-41	Cowl Scupper and Drain Installation								T (A/R)	Mandatory
52 A/F										Mos
Eff: 09-Dec-1988										Hrs
										Ldg
CAB89-18	Cargo Pod Door Latch Modification								T (A/R)	Optional
52 A/F										Mos
Eff: 08-Mar-1991										Hrs
										Ldg
CAB89-3	Door Lock Pin Replacement								T (A/R)	Mandatory
52 A/F										Mos
Eff: 13-Jan-1989										Hrs
										Ldg
CAB90-16	Crew Door Sill to Bulkhead Flange Gap Inspection								T (A/R)	Recommended
52 A/F										Mos
Eff: 04-May-1990										Hrs
										Ldg
CAB91-24	Door Handle Plunger Replacement								T (A/R)	Recommended
52 A/F										Mos
Eff: 02-Aug-1991										Hrs
										Ldg
CAB91-3	Cargo Pod Door Latch Modification								T (A/R)	Optional
52 A/F										Mos
Eff: 08-Mar-1991										Hrs
										Ldg
CAB93-5	Crew Door Upper and Lower Hinge Attachment Repair								T (A/R)	Optional
52 A/F										Mos
Eff: 30-Apr-1993										Hrs
										Ldg
CAB96-2	Crew and Cargo Door Hinge Pin Replacement								T (A/R)	Optional
52 A/F										Mos
Eff: 26-Jan-1996										Hrs
										Ldg
CAB97-10	Cowl Door Latch Inspection								T (A/R)	Mandatory
52 A/F										Mos
Eff: 28-Jul-1997										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB98-2	Passenger Door Step Support Modification								T (A/R)	Optional
52 A/F										Mos
Eff: 23-Feb-1998										Hrs
										Ldg
▼ 53 - FUSELAGE										
CAB02-3	Plywood Floorboard Installation - 5/8 inch								T (A/R)	Optional
53 A/F										Mos
Eff: 25-Feb-2002										Hrs
(AVG MAN HRS: 4)										Ldg
CAB87-18	Floorboard Cover Material Removal/Access Cover Replacement								T (A/R)	Mandatory
53 A/F										Mos
Eff: 18-Dec-1987										Hrs
										Ldg
CAB89-14	Crew Step Attach Area Structural Improvements								T (A/R)	Optional
53 A/F										Mos
Eff: 02-Jun-1989										Hrs
										Ldg
CAB90-21	Bulkhead Control Cable Cutout Modification								RE (-)	Recommended
53 A/F										Mos
Eff: 03-Aug-1990										Hrs
(AVG MAN HRS: 23.8)										Ldg
CAB90-21 Rev 1	Bulkhead Control Cable Cutout Modification								RE (-)	Recommended
53 A/F										Mos
Eff: 24-Sep-1990										Hrs
(AVG MAN HRS: 23.8)										Ldg
CAB90-21 Rev 2	Bulkhead Control Cable Cutout Modification								T (A/R)	Recommended
53 A/F										Mos
Eff: 21-Jun-1991										Hrs
(AVG MAN HRS: 23.8)										Ldg
CAB91-29	Nose Gear to Cargo Pod Fairing Modification								T (A/R)	Optional
53 A/F										Mos
Eff: 11-Oct-1991										Hrs
										Ldg
CAB91-9	Firewall Fitting Reinforcement Installation								RE (-)	Mandatory
53 A/F										Mos
Eff: 01-Apr-1991										Hrs
(AVG MAN HRS: 94)										Ldg
CAB91-9 Rev 1	Firewall Fitting Reinforcement Installation								RE (-)	Mandatory
53 A/F										Mos
Eff: 10-Apr-1992										Hrs
(AVG MAN HRS: 94)										Ldg
CAB91-9 Rev 2	Firewall Fitting Reinforcement Installation								T (A/R)	Mandatory
53 A/F										Mos
Eff: 02-Jul-1992										Hrs
(AVG MAN HRS: 94)										Ldg
CAB93-3	Cabin Floorboard Reinforcement Installation								RE (-)	Recommended
53 A/F										Mos
Eff: 12-Mar-1993										Hrs
(AVG MAN HRS: 13)										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB93-3 Rev 1	Cabin Floorboard Reinforcement Installation								T (A/R)	Recommended
53 A/F										Mos
Eff: 30-Apr-1993										Hrs
(AVG MAN HRS: 13)										Ldg
CAL-51-02	Structures - Drain Hole Inspection								RE (-)	Mandatory
53 A/F										Mos
Eff: 01-Feb-2012										Hrs
										Ldg
CAL-51-02 Rev 1	Structures - Drain Hole Inspection								RE (-)	Mandatory
53 A/F										Mos
Eff: 06-Nov-2014										Hrs
										Ldg
CAL-51-03	Structures - Drain Hole Inspection								RE (-)	Recommended
53 A/F										Mos
Eff: 01-Feb-2012										Hrs
										Ldg
CAL-51-03 Rev 1	Structures - Drain Hole Inspection								RE (-)	Recommended
53 A/F										Mos
Eff: 06-Nov-2014										Hrs
										Ldg
CAL-53-01	MLG Fitting Attachment Inspection								RE (-)	Mandatory
53 A/F										Mos
Eff: 18-Jul-2012										Hrs
(AVG MAN HRS: 2)										Ldg
CAL-53-02	Elevator Stop Bracket Inspection for Rivets								RE (-)	Mandatory
53 A/F										Mos
Eff: 12-Nov-2012										Hrs
(AVG MAN HRS: 5)										Ldg
CAL-53-03	Tailcone Stringer Inspection for Rivets								RE (-)	Mandatory
53 A/F										Mos
Eff: 15-Jan-2013										Hrs
(AVG MAN HRS: 1)										Ldg
CAL-53-04	Aft Elevator Bellcrank Mount Bracket and Support Doubler Inspection								RE (-)	Mandatory
53 A/F										Mos
Eff: 06-Mar-2014										Hrs
(AVG MAN HRS: 1.2)										Ldg
ICA-208-53-00001	Tailcone Ventilation and Drainage Improvements								T (A/R)	Mandatory
53 A/F										Mos
Eff: 26-Sep-2016										Hrs
(NOTE: EFFECTIVITY: Model 208B airplanes with cargo pod and incorporating CAB-01.)										Ldg
SK208-181	Installation of Bulkhead Forward of TKS Tank								T (A/R)	
53 A/F										Mos
Eff: 14-Jun-2011										Hrs
										Ldg
▼ 55 - STABILIZERS										
2021-04-10	Elevator Structure - Elevator Torque Tube Attach Fasteners								RE (-)	Mandatory
55 A/F										Mos
Eff: 12-Apr-2021 Complied With							03-May-2021			Hrs
							293.7			Ldg
							485			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
2021-04-10 Par. (1)(i)(ii)	Elevator Structure - Elevator Torque Tube Attach Fasteners - Special Detailed Inspection (Borescope)								RE (-)	Mandatory
55 A/F						Mos	03-May-2021			
	Eff: 12-Apr-2021 Complied With					Hrs	293.7			
	(NOTE: Initial Inspection within 200 hours TIS after the effective date of the AD)					Ldg	485			
2021-04-10 Par. (1)(i)(ii)(iii)	Elevator Structure - Elevator Torque Tube Attach Fasteners - Visual Inspection								RE	Mandatory ≈28-Aug-2022
55 A/F						Mos				
	(NOTE: Send report to - Wichita-COS@FAA.GOV					Hrs	200		[493.7]	136.4 Hrs
	Report to include the following;					Ldg				
	1. Name and Address of owner									
	2. Date of inspection									
	3. Name address, phone number, and email of person submitting report									
	4. Airplane serial number, registration, and Total Time									
	5. Status of fasteners. Repaired, replaced)									
2021-04-10 Par. (2)(3)	Elevator Structure - Elevator Torque Tube Attach Fasteners - Terminating Action								T	Mandatory ≈24-May-2032
55 A/F						Mos				
	(NOTE: If desired, use this requirement as a timer to shutoff recurring visual inspection.)					Hrs	4,000		4,000	3,642.7 Hrs
						Ldg				
2021-04-10 PARA (H)	Faa Reporting Requirement								RE (-)	
55 A/F						Days	03-May-2021			
	Complied With					Hrs	293.7			
	(UPDATE NOTE: To be completed 30 days after inspection.)					Ldg	485			
CAB01-8	Horizontal and Vertical Stabilizer Attach Bolt Inspection								RE (-)	Mandatory
55 A/F						Mos				
	Eff: 09-Apr-2001					Hrs				
	(AVG MAN HRS: 9)					Ldg				
CAB01-8 Rev 1	Horizontal and Vertical Stabilizer Attach Bolt Inspection								T (A/R)	Mandatory
55 A/F						Mos				
	Eff: 07-May-2001					Hrs				
	(AVG MAN HRS: 9)					Ldg				
CAB04-2	Vertical Fin Tip Inspection/Modification								T (A/R)	Mandatory
55 A/F						Mos				
	Eff: 09-Feb-2004					Hrs				
						Ldg				
CAB-55-01	Stabilizers - Inspection/Modification of Gap Between Vertical Forward Spar Caps and Canted Bulkhead								RE (-)	Mandatory
55 A/F						Mos				
	Eff: 09-Sep-2015					Hrs				
	(AVG MAN HRS: 29)					Ldg				
▼ 57 - WINGS										
CAB01-7	Airplane Hoist Ring Inspection								T (A/R)	Recommended
57 A/F						Mos				
	Eff: 26-Mar-2001					Hrs				
						Ldg				
CAB02-2	Wing Spar Inspection and Inspection Plate Modification								RE (-)	Mandatory
57 A/F						Mos				
	Eff: 25-Feb-2002					Hrs				
	(AVG MAN HRS: 3.5)					Ldg				
CAB02-2 Rev 1	Wing Spar Inspection and Inspection Plate Modification								T (A/R)	Mandatory
57 A/F						Mos				
	Eff: 16-Jun-2003					Hrs				
	(AVG MAN HRS: 3.5)					Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB09-4	Aft Wing Spar Attach Bolt Retaining Nut Torque								RE (-)	Mandatory
57 A/F										Mos
Eff: 15-Jun-2009										Hrs
(AVG MAN HRS: 1.5)										Ldg
CAB09-4 Rev 1	Aft Wing Spar Attach Bolt Retaining Nut Torque								T (A/R)	Mandatory
57 A/F										Mos
Eff: 16-Nov-2009										Hrs
(AVG MAN HRS: 1.5)										Ldg
CAB-57-01	Right Wing Repair								RE (-)	Mandatory
57 A/F										Mos
Eff: 15-Aug-2012										Hrs
(AVG MAN HRS: 8)										Ldg
CAB-57-02	Spar Fitting and Attach Bracket Inspection								RE (-)	Mandatory
57 A/F										Mos
Eff: 03-Feb-2015										Hrs
(AVG MAN HRS: 11)										Ldg
CAB88-32	Wing Skin Stiffener Installation								T (A/R)	Recommended
57 A/F										Mos
Eff: 14-Oct-1988										Hrs
										Ldg
CAB89-15	Wing Strut Cuff Fairing Anti-Chafe Methods								T (A/R)	Recommended
57 A/F										Mos
Eff: 02-Jun-1989										Hrs
										Ldg
CAL-57-01	Aft Wing Spar Attach Bolt Retaining Nut Torque								RE (-)	Mandatory
57 A/F										Mos
Eff: 18-Jun-2012										Hrs
(AVG MAN HRS: 1.5)										Ldg
CAL-57-02	Aileron Tab Hinge Pin Inspection								RE (-)	Recommended
57 A/F										Mos
Eff: 08-Nov-2012										Hrs
(AVG MAN HRS: 0.5)										Ldg
CAL-57-03	Wings - Identification Plate Inspection/Replacement								RE (-)	Mandatory
57 A/F										Mos
Eff: 23-May-2017 Complied	SCRIBED AND INSTALLED NEW PLATE P/N MS27253-1-208B COMPLETED						17-Aug-2017			Hrs
With							66.5			Ldg
							69			
CAL-57-03 Rev 1	Wings - Identification Plate Inspection/Replacement								RE (-)	Mandatory, Service Letter
57 A/F										Mos
Eff: 30-Oct-2018 Complied	INSPECTION COMPLETED. FOUND STAMPED WITH CORRECT PN 2620000-4.						10-May-2019			Hrs
With							191.3			Ldg
(AVG MAN HRS: 1) (NOTE: COMPLIANCE: MANDATORY. This service document must be accomplished within 200 flight hours or 12 months from the date of receipt, whichever occurs first.)							274			
CAL-57-04	Correct Improperly Torqued Aft Spar Attach Bolts								RE (-)	Mandatory
57 A/F										Mos
Eff: 21-May-2019										Hrs
(AVG MAN HRS: 2)										Ldg
SNL99-8	Wing Tip Installation Procedures								T (A/R)	Informational
57 A/F										Mos
Eff: 01-Jun-1999										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SSP04-2	Wing Strut Attachment Bolts Inspection								T (A/R)	Mandatory
57 A/F										Mos
Eff: 05-Apr-2004										Hrs
										Ldg
▼ 61 - PROPELLERS										
2005-14-11	Propellers returned to service by Southern California Propeller Service (USA) - Inspection								RE (-)	Mandatory
61 PROP1										Mos
Eff: 17-Aug-2005										Hrs
2005-14-12	Propeller Mounting Bolts P/N B-3339 - Inspection / Torque Check / Replacement								RE (-)	Mandatory
61 PROP1										Mos
Eff: 29-Jul-2005										Hrs
2005-14-12 (I)	Propeller Mounting Bolts P/N B-3339 - If Any Bolt Fails The Torque Check, Replace All With P/N B-3339 Bolts								T (A/R)	Mandatory
61 PROP1										Mos
Eff: 29-Jul-2005										Hrs
2009-10-14	Steel hub turbine propellers								RE (-)	Mandatory
61 PROP1										Mos
Eff: 04-Jun-2009 Not	SUBJECT PARTS NOT INSTALLED.						29-Jun-2016			Hrs
Applicable							0			
CAB89-10	Propeller Overspeed Governor Improvement								RE (-)	Optional
61 A/F										Mos
Eff: 31-Mar-1989										Hrs
										Ldg
CAB89-10 Rev 1	Propeller Overspeed Governor Improvement								T (A/R)	Optional
61 A/F										Mos
Eff: 18-Feb-1994										Hrs
										Ldg
CAB90-20	McCauley Propeller Installation								RE (-)	Optional
61 A/F										Mos
Eff: 13-Jul-1990										Hrs
(AVG MAN HRS: 3)										Ldg
CAB90-20 Rev 1	McCauley Propeller Installation								RE (-)	Optional
61 A/F										Mos
Eff: 21-Dec-1990										Hrs
(AVG MAN HRS: 3)										Ldg
CAB91-13	Hartzell Propeller Blade Inspection								RE (-)	Mandatory
61 A/F										Mos
Eff: 10-May-1991										Hrs
(AVG MAN HRS: 1)										Ldg
CAB91-13 Rev 1	Hartzell Propeller Blade Inspection								RE (-)	Mandatory
61 A/F										Mos
Eff: 06-Mar-1992										Hrs
(AVG MAN HRS: 1)										Ldg
CAB91-13 Rev 2	Hartzell Propeller Blade Inspection								T (A/R)	Mandatory
61 A/F										Mos
Eff: 20-Mar-1992										Hrs
(AVG MAN HRS: 1)										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB92-5	Hartzell Propeller Installation								T (A/R)	Optional
61 A/F										Mos
Eff: 10-Apr-1992										Hrs
										Ldg
CAB93-4	Propeller Control Cable Replacement								T (A/R)	Recommended
61 A/F										Mos
Eff: 30-Apr-1993										Hrs
										Ldg
CAL-61-01	Transmittal of McCauley SL2013-1, SB137AF, and SL1995-4C								RE (-)	Informational
61 A/F										Mos
Eff: 15-Apr-2013										Hrs
										Ldg
CAL-61-02	Propeller - Inspection								RE (-)	Mandatory
61 A/F										Mos
Eff: 18-Jun-2014										Hrs
(AVG MAN HRS: 4)										Ldg
CAL-61-03	Propeller - McCauley TKS Nozzle Bracket Inspection/Replacement								RE (-)	Mandatory, Service Letter
61 A/F										Mos
Eff: 14-Nov-2019										Hrs
(AVG MAN HRS: 2.5)										Ldg
CAL-61-04	Propeller - B-40755A Spray Head Assembly Replacement								RE (-)	Mandatory, Service Letter
61 A/F										Mos
Eff: 02-Jun-2020										Hrs
(AVG MAN HRS: 2.5)										Ldg
HC-ASB-30-358	Anti-ice - Travel Tube Bracket Weldment Replacement								RE (-)	Alert
61 PROP1										Mos
Eff: 01-Oct-2015										Hrs
(AVG MAN HRS: 6.5)										
HC-ASB-30-358 Part 1	Anti-ice - Travel Tube Bracket Weldment Replacement, Bracket Weldment Inspection								T (-)	Alert
61 PROP1										Mos
Eff: 01-Oct-2015										Hrs
(AVG MAN HRS: 1)										
HC-ASB-30-358 Part 2	Anti-ice - Travel Tube Bracket Weldment Replacement, Bracket Replacement (Terminating Action)								T (-)	Alert
61 PROP1										Mos
Eff: 01-Oct-2015										Hrs
(AVG MAN HRS: 5.5)										
HC-ASB-30-358 R1	Anti-ice - Travel Tube Bracket Weldment Replacement								RE (-)	Alert
61 PROP1										Mos
Eff: 15-Nov-2015										Hrs
(AVG MAN HRS: 6.5)										
HC-ASB-30-358 R1 Part 1	Anti-ice - Travel Tube Bracket Weldment Replacement, Bracket Weldment Inspection								T (-)	Alert
61 PROP1										Mos
Eff: 15-Nov-2015										Hrs
(AVG MAN HRS: 1)										
HC-ASB-30-358 R1 Part 2	Anti-ice - Travel Tube Bracket Weldment Replacement, Bracket Replacement (Terminating Action)								T (-)	Alert
61 PROP1										Mos
Eff: 15-Nov-2015										Hrs
(AVG MAN HRS: 5.5)										
HC-ASB-30-358 R2	Anti-ice - Travel Tube Bracket Weldment Replacement								RE (-)	Alert
61 PROP1										Mos
Eff: 01-Feb-2016										Hrs
(AVG MAN HRS: 6.5)										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
HC-ASB-30-358 R2 Part 1	Anti-ice - Travel Tube Bracket Weldment Replacement, Bracket Weldment Inspection								RE (-)	Alert
61 PROP1										Mos
Eff: 01-Feb-2016										Hrs
(AVG MAN HRS: 1)										
HC-ASB-30-358 R2 Part 2	Anti-ice - Travel Tube Bracket Weldment Replacement, Bracket Replacement (Terminating Action)								RE (-)	Alert
61 PROP1										Mos
Eff: 01-Feb-2016										Hrs
(AVG MAN HRS: 5.5)										
HC-ASB-61-313	Propeller - Counterweight Slug Bolt Inspection								RE (-)	Alert
61 PROP1										Mos
Eff: 17-Nov-2008										Hrs
(AVG MAN HRS: 2)										
HC-ASB-61-313 Rev 1	Propeller - Counterweight Slug Bolt Inspection								RE (-)	Alert
61 PROP1										Mos
Eff: 12-Dec-2008										Hrs
(AVG MAN HRS: 2)										
HC-ASB-61-313 Rev 2	Propeller - Counterweight Slug Bolt Inspection								RE (-)	Alert
61 PROP1										Mos
Eff: 27-Mar-2009										Hrs
(AVG MAN HRS: 2)										
HC-ASB-61-313 Rev 3	Propeller - Counterweight Slug Bolt Inspection								T (A/R)	Alert
61 PROP1										Mos
Eff: 15-Jul-2009										Hrs
(AVG MAN HRS: 2) (NOTE: COMPLIANCE: Completion of the one-time inspection, and replacement where required, is terminating action for this Alert Service Bulletin.)										
HC-SB-61-374 Rev 1	Blade Bearing Race Inspection Criteria								T (A/R)	
61 PROP1										Mos
Eff: 01-Aug-2017										Hrs
(NOTE: COMPLIANCE: At next propeller overhaul, inspect the blade bearing races on the affected propeller in accordance with the Accomplishment Instructions in this Service Bulletin. NOTE: Overhaul intervals are specified in Hartzell Propeller Inc. Service Letter HC-SL-61-61Y.)										
HC-SI-61-213	Uncrating Instructions for the Hartzell Propeller Inc. DT-1724-5 Automated Rolling Machine								T (-)	Service Instruction
61 PROP1										Mos
Eff: 19-Sep-2019										Hrs
HC-SI-61-213 Rev 1	DT-1724-5 Rolling Machine - Uncrating Instructions								T (A/R)	Service Instruction
61 PROP1										Mos
Eff: 17-Dec-2020										Hrs
HC-SI-61-214	DT-1724-5 Rolling Machine - Packaging Instructions								T (-)	Service Instruction
61 PROP1										Mos
Eff: 19-Sep-2019										Hrs
(NOTE: CAUTION: DO NOT USE OBSOLETE OR OUTDATED INFORMATION. PERFORM ALL INSPECTIONS OR WORK IN ACCORDANCE WITH THE MOST RECENT REVISION OF A DOCUMENT.)										
HC-SI-61-214 Rev 1	DT-1724-5 Rolling Machine - Packaging Instructions								RE (-)	Service Instruction
61 PROP1										Mos
Eff: 01-Nov-2019										Hrs
HC-SI-61-214 Rev 2	DT-1724-5 Rolling Machine - Packaging Instructions								T (A/R)	Service Instruction
61 PROP1										Mos
Eff: 17-Dec-2020										Hrs

Task No		Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition								DUE	Remaining
HC-SL-61-187 Rev 4		Propeller - Alternate Lubrication Fittings						T (A/R)		Service Letter	
	61 PROP1										Mos
	Eff: 18-Nov-2021										Hrs
HC-SL-61-277 Rev 6		Governor - Installation of Hartzell Propeller Inc. Governors						T (A/R)		Optional	
	61 PROP1										Mos
	Eff: 16-Sep-2020										Hrs
HC-SL-61-362		Propeller - A-1851-T Blade Retention Bearings						T (A/R)		Service Letter	
	61 PROP1										Mos
	Eff: 05-Sep-2018										Hrs
HC-SL-61-364		Propeller - Corrosion Inhibitor on Counterweights						T (A/R)		Service Letter	
	61 PROP1										Mos
	Eff: 03-Apr-2020										Hrs
HC-SL-61-366		Propeller - NYCO GN3058 Grease						T (A/R)		Service Letter	
	61 PROP1										Mos
	Eff: 06-Jan-2020										Hrs
	(NOTE: EFFECTIVITY: (a) All propellers manufactured by Hartzell Propeller Inc. EXCEPT, HC-E5N-3(A,B)(L)(X) propellers installed on Piaggio P-180 Avanti and Hartzell Propeller Inc. HC-E4P-5(E) propellers installed on Grob/E-Systems G520 Egrett. (b) Refer to the applicable Installation Data Sheet (IDS) in Hartzell Propeller Inc. Application Guide Manual 159 (61-02-59) for the approved grease to be used in propellers that are not affected by this Service Letter.)										
HC-SL-61-367		107995 Counterweight Mounting Bolts						T (-)		Service Letter	
	61 PROP1										Mos
	Eff: 29-May-2020										Hrs
HC-SL-61-367 Rev 1		107995 Counterweight Mounting Bolts						T (A/R)		Service Letter	
	61 PROP1										Mos
	Eff: 17-Dec-2020										Hrs
HC-SL-61-370		Beta System Cleaning Procedure						T (A/R)		Service Letter	
	61 PROP1										Mos
	Eff: 07-Jul-2021										Hrs
HC-SL-61-61Y		Propeller - Overhaul Periods and Service Life Limits For Hartzell Propeller Inc. Aviation Components - Propellers, Governors, And Propeller Damper Assemblies						RE (-)			
	61 PROP1										Mos
											Hrs
HC-SL-61-61Y Rev 1		Propeller - Overhaul Periods and Service Life Limits For Hartzell Propeller Inc. Aviation Components - Propellers, Governors, And Propeller Damper Assemblies						RE (-)			
	61 PROP1										Mos
											Hrs
HC-SL-61-61Y Rev 10		Propeller - Overhaul Periods And Service Life Limits For Hartzell Propeller Inc. Aviation Components - Propellers, Governors, Accumulators, And Propeller Damper Assemblies, Service Letter (Recommended)						RE (-)			
	61 PROP1										Mos
											Hrs
HC-SL-61-61Y Rev 12		Propeller - Overhaul Periods and Service Life Limits for Hartzell Propeller Inc. Aviation Components - Propellers, Governors, Accumulators, and Propeller Damper Assemblies						T (-)		Service Letter	
	61 PROP1										Mos
	Eff: 16-Aug-2018										Hrs

Task No		Description					CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI				DUE	Remaining
HC-SL-61-61Y Rev 13		Propeller - Overhaul Periods and Service Life Limits for Hartzell Propeller Inc. Aviation Components - Propellers, Governors, Accumulators, and Propeller Damper Assemblies								T (-)	Service Letter
	61 PROP1 Eff: 04-Mar-2021										Mos Hrs
HC-SL-61-61Y Rev 14		Propeller - Overhaul Periods and Service Life Limits for Hartzell Propeller Inc. Aviation Components - Propellers, Governors, Accumulators, and Propeller Damper Assemblies								T (A/R)	Service Letter
	61 PROP1 Eff: 07-Jul-2021										Mos Hrs
HC-SL-61-61Y Rev 2		Propeller - Overhaul Periods and Service Life Limits For Hartzell Propeller Inc. Aviation Components - Propellers, Governors, And Propeller Damper Assemblies								RE (-)	
	61 PROP1										Mos Hrs
HC-SL-61-61Y Rev 3		Propeller - Overhaul Periods and Service Life Limits For Hartzell Propeller Inc. Aviation Components - Propellers, Governors, And Propeller Damper Assemblies								RE (-)	
	61 PROP1										Mos Hrs
HC-SL-61-61Y Rev 4		Propeller - Overhaul Periods and Service Life Limits For Hartzell Propeller Inc. Aviation Components - Propellers, Governors, And Propeller Damper Assemblies								RE (-)	
	61 PROP1										Mos Hrs
HC-SL-61-61Y Rev 5		Propeller - Overhaul Periods and Service Life Limits For Hartzell Propeller Inc. Aviation Components - Propellers, Governors, And Propeller Damper Assemblies								RE (-)	
	61 PROP1										Mos Hrs
HC-SL-61-61Y Rev 6		Propeller - Overhaul Periods and Service Life Limits For Hartzell Propeller Inc. Aviation Components - Propellers, Governors, And Propeller Damper Assemblies								RE (-)	
	61 PROP1										Mos Hrs
HC-SL-61-61Y Rev 7		Propeller - Overhaul Periods and Service Life Limits For Hartzell Propeller Inc. Aviation Components - Propellers, Governors, And Propeller Damper Assemblies								T (A/R)	
	61 PROP1										Mos Hrs
HC-SL-61-61Y Rev 8		Propeller - Overhaul Periods and Service Life Limits For Hartzell Propeller Inc. Aviation Components - Propellers, Governors, And Propeller Damper Assemblies								T (A/R)	
	61 PROP1 Eff: 03-Aug-2015										Mos Hrs
HC-SL-61-61Y Rev 9		Propeller - Overhaul Periods and Service Life Limits For Hartzell Propeller Inc. Aviation Components - Propellers, Governors, And Propeller Damper Assemblies								T (A/R)	
	61 PROP1 Eff: 03-Aug-2015										Mos Hrs
SB119A		Proper Usage of Split Retainers P/N C- 3903 Matching Serial Numbers								T (A/R)	Optional
	61 PROP1 Eff: 01-Mar-1999										Mos Hrs

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SEL-61-01	Propeller - Propeller Governor Inspection in Accordance with McCauley ASB273								RE (-)	Mandatory, Service Letter
61 PROP1	BY MODEL					Mos	20-Dec-2018			
Eff: 16-Nov-2018 Not Applicable						Hrs	191.3			
SI 140	Propellers - Installation of Mounting Bolts								RE (-)	Service Instruction
61 PROP1						Mos				
Eff: 15-Mar-1982						Hrs				
SI 140A	Propellers - Installation of Mounting Bolts								RE (-)	Service Instruction
61 PROP1						Mos				
Eff: 04-Oct-1982						Hrs				
SI 140A Rev 1	Propellers - Installation of Mounting Bolts								RE (-)	Service Instruction
61 PROP1						Mos				
Eff: 29-Apr-1982						Hrs				
SI 140A Rev 2	Propellers - Installation of Mounting Bolts								RE (-)	Service Instruction
61 PROP1						Mos				
Eff: 20-Jun-1983						Hrs				
SI 140A Rev 3	Propellers - Installation of Mounting Bolts								RE (-)	Service Instruction
61 PROP1						Mos				
Eff: 15-Mar-1984						Hrs				
SI 140A Rev 4	Propellers - Installation of Mounting Bolts								RE (-)	Service Instruction
61 PROP1						Mos				
Eff: 15-Nov-1984						Hrs				
SI 140A Rev 5	Propellers - Installation of Mounting Bolts								RE (-)	Service Instruction
61 PROP1						Mos				
Eff: 28-Jan-1986						Hrs				
SI 140A Rev 6	Propellers - Installation of Mounting Bolts								RE (-)	Service Instruction
61 PROP1						Mos				
Eff: 18-Aug-1986						Hrs				
SI 140A Rev 7	Propellers - Installation of Mounting Bolts								RE (-)	Service Instruction
61 PROP1						Mos				
Eff: 18-Aug-2003						Hrs				
SI 140A Rev 8	Propellers - Installation of Mounting Bolts								RE (-)	Service Instruction
61 PROP1						Mos				
Eff: 06-Apr-2004						Hrs				
SI 140A Rev 9	Propellers - Installation of Mounting Bolts								T (A/R)	Service Instruction
61 PROP1						Mos				
Eff: 30-Mar-2005						Hrs				
SNL06-8	Propeller Blade Leak Troubleshooting Instructions								T (A/R)	Informational
61 A/F						Mos				
Eff: 10-Apr-2006						Hrs				
						Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SNL87-12	Dynamic Propeller Balancing Procedures								T (A/R)	Informational
61 A/F										Mos
Eff: 01-May-1987										Hrs
										Ldg
SNL87-15	Hartzell Composite Propeller Blade Instruction Manual								T (A/R)	Informational
61 A/F										Mos
Eff: 22-May-1987										Hrs
										Ldg
SNL88-5	Propeller Tie Down Improvement								T (A/R)	Informational
61 A/F										Mos
Eff: 04-Mar-1988										Hrs
										Ldg
SNL89-05	Propeller Aircraft Special Tools Catalog								T (A/R)	Service Newsletter
61 A/F										Mos
Eff: 31-Mar-1989										Hrs
										Ldg
SNL93-09	Field Inspection and Repair of McCauley Propeller Blades								RE (-)	Service Newsletter
61 A/F										Mos
Eff: 10-Dec-1993										Hrs
										Ldg
SNL94-04	Cessna Service Information for Propeller Model Airplanes								T (A/R)	Service Newsletter
61 A/F										Mos
Eff: 29-Apr-1994										Hrs
										Ldg
SNL94-06	Propeller Airplanes Serial Number Listing								T (A/R)	Service Newsletter
61 A/F										Mos
Eff: 20-May-1994										Hrs
										Ldg
SNL94-6	Propeller Airplanes Serial Number Listing								T (A/R)	Informational
61 A/F										Mos
Eff: 20-May-1994										Hrs
										Ldg
▼ 70 - STANDARD PRACTICES - ENGINES										
SNL93-06	Maintenance Practices for Pressure Cylinders								T (A/R)	Service Newsletter
70 A/F										Mos
Eff: 17-Sep-1993										Hrs
										Ldg
▼ 71 - POWER PLANT										
90-05-04	Engine Mount Ring								RE (-)	Mandatory
71 A/F										Mos
Eff: 23-Mar-1990 Not Applicable	AIRCRAFT NOT IN EFFECTIVE SERIAL RANGE.Á€†						29-Jun-2016			Hrs
							0			Ldg
							0			
CAB00-9	Engine Secondary Exhaust Duct Hanger Modification								RE (-)	Mandatory
71 A/F										Mos
Eff: 29-May-2000										Hrs
(AVG MAN HRS: 4.1)										Ldg
CAB00-9 Rev 1	Engine Secondary Exhaust Duct Hanger Modification								T (A/R)	Mandatory
71 A/F										Mos
Eff: 30-Jul-2001										Hrs
(AVG MAN HRS: 4.1)										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB02-13	Engine Mount Bolts and Washers Inspection								RE (-)	Mandatory
71 A/F										
Eff: 09-Dec-2002										
(AVG MAN HRS: 3.7)										
CAB02-13 Rev 1	Engine Mount Bolts and Washers Inspection								T (A/R)	Mandatory
71 A/F										
Eff: 24-Mar-2003										
(AVG MAN HRS: 3.7)										
CAB05-7	Engine Shroud Segment Inspection								T (A/R)	Mandatory
71 A/F										
Eff: 02-May-2005										
CAB06-4	Engine Compressor Vane Ring Damping Strap Inspection								T (A/R)	Mandatory
71 A/F										
Eff: 15-May-2006										
CAB07-2	Engine Primary Exhaust Duct Inspection								T (A/R)	Mandatory
71 A/F										
Eff: 19-Feb-2007										
CAB09-1	Engine Inlet Inertial Separator Drain Hole Inspection								T (A/R)	Mandatory
71 A/F										
Eff: 11-May-2009										
(AVG MAN HRS: 1)										
CAB09-5	Engine Compressor Turbine Blades Replacement								T (A/R)	Mandatory
71 A/F										
Eff: 22-Jun-2009										
CAB10-4	Pratt & Whitney ADASd Software Upgrade								T (A/R)	Recommended
71 A/F										
Eff: 18-May-2010										
CAB11-7	Engine Mount Inspection for Sufficient Paint Coverage								T (A/R)	Recommended
71 A/F										
Eff: 13-Sep-2011										
CAB11-7	Engine Mount Inspection for Sufficient Paint Coverage								RE (-)	Recommended
71 A/F										
Eff: 13-Sep-2011										
CAB-71-01	Cowl Lock Modification								RE (-)	Recommended
71 A/F										
Eff: 07-Aug-2013										
(AVG MAN HRS: 1)										
CAB-71-02	Engine Truss Inspection at Fuel Ecology Tank Bracket and Induction Air Plenum								RE (-)	Mandatory
71 A/F										
Eff: 18-Sep-2014										
(AVG MAN HRS: 8.5)										
CAB86-12	Inertial Separator Forward and Aft Vane Rivet Inspection								RE (-)	Mandatory
71 A/F										
Eff: 23-May-1986										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB86-12 Rev 1 71 A/F Eff: 10-Apr-1987	Inertial Separator Forward and Aft Vane Rivet Inspection								RE (-)	Mandatory
										Mos
										Hrs
										Ldg
CAB86-12 Rev 2 71 A/F Eff: 08-Apr-1988	Inertial Separator Forward and Aft Vane Rivet Inspection								RE (-)	Mandatory
										Mos
										Hrs
										Ldg
CAB88-15 71 A/F Eff: 18-Jul-1988	Inertial Separator Vane Improvements								T (A/R)	Recommended
										Mos
										Hrs
										Ldg
CAB88-20 71 A/F Eff: 31-May-1988	Aft Exhaust Duct Hanger Modification								T (A/R)	Recommended
										Mos
										Hrs
										Ldg
CAB89-20 71 A/F Eff: 14-Jul-1989	Inertial Separator Drain Installation								T (A/R)	Mandatory
										Mos
										Hrs
										Ldg
CAB90-7 71 A/F Eff: 16-Mar-1990 (AVG MAN HRS: 8)	Engine Mount Bracket Drainage and Bolt Lubrication								RE (-)	Optional
										Mos
										Hrs
										Ldg
CAB90-7 Rev 1 71 A/F Eff: 01-Jun-1990 (AVG MAN HRS: 8)	Engine Mount Bracket Drainage and Bolt Lubrication								T (A/R)	Optional
										Mos
										Hrs
										Ldg
CAB91-34 71 A/F Eff: 22-Nov-1991	Engine Power Control Cable Replacement								T (A/R)	Mandatory
										Mos
										Hrs
										Ldg
CAB92-14 71 A/F Eff: 17-Jul-1992	PT6A-114/-114A Engine Compressor Turbine Blade Inspection (Cancelled)								RE (-)	Mandatory
										Mos
										Hrs
										Ldg
CAB92-14 Rev 1 71 A/F Eff: 31-Dec-1992	PT6A-114/-114A Engine Compressor Turbine Blade Inspection (Cancelled)								RE (-)	Mandatory
										Mos
										Hrs
										Ldg
CAB94-17 71 A/F Eff: 30-Dec-1994 (AVG MAN HRS: 15)	PT6A-114A Engine Vane Ring Damping Strap Installation								RE (-)	Recommended
										Mos
										Hrs
										Ldg
CAB94-17 Rev 1 71 A/F Eff: 18-Aug-1995 (AVG MAN HRS: 15)	PT6A-114A Engine Vane Ring Damping Strap Installation								T (A/R)	Recommended
										Mos
										Hrs
										Ldg
CAB95-1 71 A/F Eff: 17-Feb-1995	Nose Cap/Induction Inlet Support and Engine Flange Guard Installation								T (A/R)	Recommended
										Mos
										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB95-14	PT6A-114A Engine Third Stage Compressor Stator Assembly Replacement								T (A/R)	Recommended
71 A/F										Mos
Eff: 18-Aug-1995										Hrs
										Ldg
CAB97-2	Engine Power Control Cable Umbrella Seal Installation								T (A/R)	Recommended
71 A/F										Mos
Eff: 24-Feb-1997										Hrs
										Ldg
CAB98-15	Engine Bleed Off Valve Diaphragm Inspection (Cancelled)								RE (-)	Recommended
71 A/F										Mos
Eff: 05-Oct-1998										Hrs
(AVG MAN HRS: 8)										Ldg
CAB98-15 Rev 1	Engine Bleed Off Valve Diaphragm Inspection (Cancelled)								RE (-)	Recommended
71 A/F										Mos
Eff: 15-Mar-1999										Hrs
(AVG MAN HRS: 8)										Ldg
CAB98-18	PT6A Engine No. 1 Bearing Outer Housing Inspection								T (A/R)	Mandatory
71 A/F										Mos
Eff: 30-Nov-1998										Hrs
										Ldg
CAB99-1	Engine Bleed Off Valve Cover and Diaphragm Inspection								RE (-)	Mandatory
71 A/F										Mos
Eff: 15-Mar-1999										Hrs
										Ldg
CAB99-1 Rev 1	Engine Bleed Off Valve Cover and Diaphragm Inspection								T (A/R)	Mandatory
71 A/F										Mos
Eff: 27-Dec-1999										Hrs
										Ldg
CAB99-6	Engine Bleed Off Valve Replacement								RE (-)	Recommended
71 A/F										Mos
Eff: 08-Nov-1999										Hrs
(AVG MAN HRS: 8)										Ldg
CAB99-6 Rev 1	Engine Bleed Off Valve Replacement								T (A/R)	Recommended
71 A/F										Mos
Eff: 29-May-2000										Hrs
(AVG MAN HRS: 8)										Ldg
CAL-71-01	Transmittal of Pratt & Whitney Canada S.I.L. No. GEN-119								T (A/R)	Informational
71 A/F										Mos
Eff: 12-Apr-2012										Hrs
										Ldg
CAL-71-02	Transmittal of Pratt & Whitney Canada P&WC: 66-2011 PT6A-114A & PT6A-34 Inspect Bleed Off Valve								RE (-)	Recommended
71 A/F										Mos
Eff: 18-Sep-2014										Hrs
										Ldg
CAL-71-03	Transmittal of Pratt & Whitney Canada S.B. No. A1427R3								T (A/R)	Recommended
71 A/F										Mos
Eff: 19-Apr-2012										Hrs
										Ldg
CAL-71-04	Transmittal of Pratt & Whitney Canada S.I.L. No. PT6A-195								T (A/R)	Informational
71 A/F										Mos
Eff: 20-Jun-2012										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAL-71-05	Engine Oil Breather-Hose Life Limit								T (A/R)	Informational
71 A/F Eff: 13-Aug-2012										
CAL-71-06	Transmittal of Pratt & Whitney Canada S.I.L. GEN-110R1								T (A/R)	Informational
71 A/F Eff: 10-Oct-2012										
CAL-71-07	Transmittal of Pratt & Whitney Canada S.I.L. No. PT6A-199, S.I.L. No. GEN-031R1, S.I.L. No. GEN-034R3, and S.I.L. No. GEN-038R3								T (A/R)	Informational
71 A/F Eff: 19-Dec-2012										
CAL-71-08	Transmittal of P&WC S.I.L. No. PT6A-204, S.I.L. No. GEN-125, PT6A SPB No. 34R1, S.I.L. No. GEN-116R1, and S.I.L. No. GEN-123								T (A/R)	Informational
71 A/F Eff: 15-Apr-2013										
CAL-71-09	Transmittal of P&WC S.B. No. 1669R9								RE (-)	Recommended
71 A/F Eff: 01-Aug-2013										
CAL-71-10	Transmittal of P&WC S.B. No. 1638R2, S.B. No.1714, S.I.L. No. PT6A-041R6, S.I.L. No. PT6A-107R1, S.I.L. No.PT6A-149R4, S.I.L. No. PT6A-201, S.I.L. No. PT6A-208								T (A/R)	Informational
71 A/F Eff: 17-Jul-2013										
CAL-71-11	Transmittal of P&WC S.B. No. 1703R9, S.B. No. 1717, S.B. No. 1381R5, S.B. No. 1721, S.B. No. 1722, S.B. No. 1002R28, S.B. No. 1244R26, S.B. No. 1727, S.I.L. No. PT6A-211, S.I.L. No. PT6A-208R1, S.I.L. No. PT6A-160R2, S.I.L. No. PT6A-146R1, S.I.L. No. PT6A-116R3, S.I.L. No. GEN-123R1, S.I.L. No. GEN-127, S.I.L. GEN-027R4								T (A/R)	Informational
71 A/F Eff: 23-Oct-2013										
CAL-71-12	Transmittal of P&WC S.I.L. No. PT6A-196R1, S.I.L. No. GEN-123-R2, S.I.L. No. GEN-134, PT6A SPB No. 185, PT6A SPB No. 186, S.B. No. 1002R29, S.B. No. 1455R3, S.B. No. 1521R5, S.B. No. 1568R7, S.B. No. 1588R2, S.B. No. 1731, S.B. No. 1733								T (A/R)	Informational
71 A/F Eff: 26-Mar-2014										
CAL-71-13	Transmittal of P&WC S.I.L. No. GEN-PT6-034, S.B. No. 1447R4, S.B. No. 1703R10, S.B. No. 1705R1, S.B. No. 1722R1, S.B. No. 1729, S.B. No. 1737								T (A/R)	Informational
71 A/F Eff: 09-Jun-2012										
CAL-71-14	Transmittal of P&WC S.I.L. No. PT6A-221								RE (-)	Informational
71 A/F Eff: 15-Sep-2014										
CAL-71-15	Engine Mount Inspection for Sufficient Paint Coverage								RE (-)	Recommended
71 A/F Eff: 06-Mar-2015 (AVG MAN HRS: 1.5)										
CAL-71-15 Rev 1	Engine Mount Inspection for Sufficient Paint Coverage								RE (-)	Recommended
71 A/F Eff: 16-Sep-2015 (AVG MAN HRS: 1.5)										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAL-71-16	Inspect the Inertial Separator Rod for Proper Clearance and Replace the Spacer if Chafing is Found								RE (-)	Recommended
71 A/F										Mos
Eff: 21-May-2019										Hrs
(AVG MAN HRS: 4)										Ldg
CAL-71-17	Inspect for Proper Clearance Between the Engine Mount and the Right Firewall Flange								RE (-)	Recommended
71 A/F										Mos
Eff: 10-Apr-2019										Hrs
(AVG MAN HRS: 4)										Ldg
SK208-141	Secondary Exhaust Duct Installation								T (A/R)	
71 A/F										Mos
Eff: 18-Aug-2000										Hrs
										Ldg
SNL00-12	Engine Operational Procedures - Emergency Power Lever (EPL)/Fuel Control Manual Override System								T (A/R)	Informational
71 A/F										Mos
Eff: 13-Nov-2000										Hrs
										Ldg
SNL04-1	Pratt & Whitney Canada PT6A Compressor Turbine (CT) BLADE Fractures								T (A/R)	Informational
71 A/F										Mos
Eff: 22-Mar-2004										Hrs
										Ldg
SNL04-4	Emergency Power Lever (EPL) Fuel Control Manual Override System								T (A/R)	Informational
71 A/F										Mos
Eff: 17-May-2004										Hrs
										Ldg
SNL06-10	Pratt & Whitney Canada PT6A Borescope Inspection During Fuel Nozzle Check								T (A/R)	Informational
71 A/F										Mos
Eff: 07-Aug-2006										Hrs
										Ldg
SNL06-14	Pratt & Whitney Canada PT6A Compressor and Turbine Wash								T (A/R)	Informational
71 A/F										Mos
Eff: 02-Oct-2006										Hrs
										Ldg
SNL06-16	Pratt & Whitney Canada PT6A Web-Based Engine Condition Trend Monitoring (WebECTM) Services								T (A/R)	
71 A/F										Mos
Eff: 27-Nov-2006										Hrs
										Ldg
SNL07-16	Pratt & Whitney Canada PT6A #1 Bearing Electrical Discharge Damage (EDD)								T (A/R)	Informational
71 A/F										Mos
Eff: 21-Nov-2007										Hrs
										Ldg
SNL07-17	Pratt & Whitney Canada Cleanable Filters Part Marked "Noncleanable"								T (A/R)	Informational
71 A/F										Mos
Eff: 21-Nov-2007										Hrs
										Ldg
SNL07-8	Pratt & Whitney Canada PT6A Compressor Turbine Blade Maintenance								T (A/R)	Informational
71 A/F										Mos
Eff: 02-Apr-2007										Hrs
										Ldg
SNL09-8	Pratt & Whitney Canada Operation and Maintenance 2009 Conferences for PT6A Engines								T (A/R)	Informational
71 A/F										Mos
Eff: 10-Aug-2009										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SNL10-7 71 A/F Eff: 10-Jul-2010	Pratt & Whitney Canada PT6A Compressor and Turbine Wash								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL10-9 71 A/F Eff: 20-Jul-2010	PT6A Power Management								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL11-20 71 A/F Eff: 17-Aug-2011	Engine Performance Checking Curves								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL11-22 71 A/F Eff: 08-Sep-2011	Subscription to and Use of Pratt & Whitney Canada Internet-Based Engine Condition Trend Monitoring WebECTM(R) Services								T (A/R)	
										Mos
										Hrs
										Ldg
SNL11-23 71 A/F Eff: 08-Sep-2011	P&WC Propeller-Shaft Oil Seal Modification								T (A/R)	
										Mos
										Hrs
										Ldg
SNL11-25 71 A/F Eff: 29-Sep-2011	P&WC Engine Operation in Volcanic Ash Conditions								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL11-26 71 A/F Eff: 29-Sep-2011	P&WC Operation Into Radioactive Environments								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL11-27 71 A/F Eff: 29-Sep-2011	P&WC Proper Positioning of Locking Devices at Assembly								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL88-14 71 A/F Eff: 26-Aug-1988	Engine Inlet Cover Improvement								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL88-4 71 A/F Eff: 29-Jan-1988	PT6A Engine Sulphidation Information								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL90-4 71 A/F Eff: 09-Feb-1990	Engine Accessory Gearbox Coupling Shaft Ball Lock Replacement								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL92-5 71 A/F Eff: 21-Aug-1992	PT6A-114/-114A Engine Power Turbine Blade Improvement								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL92-9 71 A/F Eff: 31-Dec-1992	PT6A-114/-114A Engine Compressor Turbine Blade Inspection Findings								T (A/R)	Informational
										Mos
										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SNL93-7	Temporary Replacement of a PT6A-114 Engine with a PT6A-114A Engine								T (A/R)	Informational
71 A/F										Mos
Eff: 22-Oct-1993										Hrs
										Ldg
SNL94-12	PT6A-114A Engine Third Stage Compressor Stator Airfoil Fractures								RE (-)	Informational
71 A/F										Mos
Eff: 11-Nov-1994										Hrs
										Ldg
SNL94-12 Rev 1	PT6A-114A Engine Third Stage Compressor Stator Airfoil Fractures								RE (-)	Informational
71 A/F										Mos
Eff: 30-Dec-1994										Hrs
										Ldg
SNL94-12 Rev 2	PT6A-114A Engine Third Stage Compressor Stator Airfoil Fractures								T (A/R)	Informational
71 A/F										Mos
Eff: 09-Jun-1995										Hrs
										Ldg
SNL96-4	Engine Combustion Chamber Liner Dome Bulging								T (A/R)	Informational
71 A/F										Mos
Eff: 23-Dec-1996										Hrs
										Ldg
▼ 72 - ENGINE										
1000	Omnibus Service Bulletin								T (A/R)	Category 11
72 ENG1										Mos
Eff: 07-Dec-2012										Hrs
										Enc
1002	Rotor Components - Service Life								RE (-)	
72 ENG1										Mos
Eff: 01-Dec-1973										Hrs
										Enc
1002 Rev 1	Rotor Components - Service Life								RE (-)	
72 ENG1										Mos
										Hrs
										Enc
1002 Rev 10	Rotor Components - Service Life								RE (-)	
72 ENG1										Mos
										Hrs
										Enc
1002 Rev 11	Rotor Components - Service Life								RE (-)	
72 ENG1										Mos
										Hrs
										Enc
1002 Rev 12	Rotor Components - Service Life								RE (-)	
72 ENG1										Mos
										Hrs
										Enc
1002 Rev 13	Rotor Components - Service Life								RE (-)	
72 ENG1										Mos
										Hrs
										Enc

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
1002 Rev 14 72 ENG1	Rotor Components - Service Life								RE (-)	
1002 Rev 15 72 ENG1	Rotor Components - Service Life								RE (-)	
1002 Rev 16 72 ENG1	Rotor Components - Service Life								RE (-)	
1002 Rev 17 72 ENG1	Rotor Components - Service Life								RE (-)	
1002 Rev 18 72 ENG1	Rotor Components - Service Life								RE (-)	
1002 Rev 19 72 ENG1	Rotor Components - Service Life								RE (-)	
1002 Rev 2 72 ENG1	Rotor Components - Service Life								RE (-)	
1002 Rev 20 72 ENG1	Rotor Components - Service Life								RE (-)	
1002 Rev 21 72 ENG1	Rotor Components - Service Life								RE (-)	
1002 Rev 22 72 ENG1	Rotor Components - Service Life								RE (-)	
1002 Rev 23 72 ENG1	Rotor Components - Service Life								RE (-)	
1002 Rev 24 72 ENG1	Rotor Components - Service Life								RE (-)	
1002 Rev 25 72 ENG1	Rotor Components - Service Life								RE (-)	

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
1002 Rev 26 72 ENG1	Rotor Components - Service Life								RE (-)	
										Mos
										Hrs
										Enc
1002 Rev 27 72 ENG1	Rotor Components - Service Life								RE (-)	
										Mos
										Hrs
										Enc
1002 Rev 28 72 ENG1	Rotor Components - Service Life								RE (-)	
										Mos
										Hrs
										Enc
1002 Rev 3 72 ENG1	Rotor Components - Service Life								RE (-)	
										Mos
										Hrs
										Enc
1002 Rev 4 72 ENG1	Rotor Components - Service Life								RE (-)	
										Mos
										Hrs
										Enc
1002 Rev 5 72 ENG1	Rotor Components - Service Life								RE (-)	
										Mos
										Hrs
										Enc
1002 Rev 6 72 ENG1	Rotor Components - Service Life								RE (-)	
										Mos
										Hrs
										Enc
1002 Rev 7 72 ENG1	Rotor Components - Service Life								RE (-)	
										Mos
										Hrs
										Enc
1002 Rev 8 72 ENG1	Rotor Components - Service Life								RE (-)	
										Mos
										Hrs
										Enc
1002 Rev 9 72 ENG1	Rotor Components - Service Life								RE (-)	
										Mos
										Hrs
										Enc
1003 72 ENG1	Operating Time Between Overhauls and Hot Section Inspection Frequency (This service bulletin is superseded by P&WC S.B. No. 1703)								RE (-)	
										Mos
										Hrs
										Enc
1244 72 ENG1 Eff: 24-Jul-1975	Engine Fuels And Additives - Requirements And Approved Listing								RE (-)	Recommended
										Mos
										Hrs
										Enc
1244 Rev 1 72 ENG1	Engine Fuels And Additives - Requirements And Approved Listing								RE (-)	Recommended
										Mos
										Hrs
										Enc

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
1244 Rev 10 72 ENG1	Engine Fuels And Additives - Requirements And Approved Listing								RE (-)	Recommended
										Mos
										Hrs
										Enc
1244 Rev 11 72 ENG1	Engine Fuels And Additives - Requirements And Approved Listing								RE (-)	Recommended
										Mos
										Hrs
										Enc
1244 Rev 12 72 ENG1	Engine Fuels And Additives - Requirements And Approved Listing								RE (-)	Recommended
										Mos
										Hrs
										Enc
1244 Rev 13 72 ENG1	Engine Fuels And Additives - Requirements And Approved Listing								RE (-)	Recommended
										Mos
										Hrs
										Enc
1244 Rev 14 72 ENG1	Engine Fuels And Additives - Requirements And Approved Listing								RE (-)	Recommended
										Mos
										Hrs
										Enc
1244 Rev 15 72 ENG1	Engine Fuels And Additives - Requirements And Approved Listing								RE (-)	Recommended
										Mos
										Hrs
										Enc
1244 Rev 16 72 ENG1	Engine Fuels And Additives - Requirements And Approved Listing								RE (-)	Recommended
										Mos
										Hrs
										Enc
1244 Rev 17 72 ENG1	Engine Fuels And Additives - Requirements And Approved Listing								RE (-)	Recommended
										Mos
										Hrs
										Enc
1244 Rev 18 72 ENG1	Engine Fuels And Additives - Requirements And Approved Listing								RE (-)	Recommended
										Mos
										Hrs
										Enc
1244 Rev 19 72 ENG1	Engine Fuels And Additives - Requirements And Approved Listing								RE (-)	Recommended
										Mos
										Hrs
										Enc
1244 Rev 2 72 ENG1	Engine Fuels And Additives - Requirements And Approved Listing								RE (-)	Recommended
										Mos
										Hrs
										Enc
1244 Rev 20 72 ENG1	Engine Fuels And Additives - Requirements And Approved Listing								RE (-)	Recommended
										Mos
										Hrs
										Enc
1244 Rev 21 72 ENG1	Engine Fuels And Additives - Requirements And Approved Listing								RE (-)	Recommended
										Mos
										Hrs
										Enc

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
1244 Rev 22 72 ENG1	Engine Fuels And Additives - Requirements And Approved Listing								RE (-)	Recommended
1244 Rev 23 72 ENG1	Engine Fuels And Additives - Requirements And Approved Listing								RE (-)	Recommended
1244 Rev 24 72 ENG1	Engine Fuels And Additives - Requirements And Approved Listing								RE (-)	Recommended
1244 Rev 25 72 ENG1	Engine Fuels And Additives - Requirements And Approved Listing								RE (-)	Recommended
1244 Rev 26 72 ENG1 Eff: 26-Sep-2013	Engine Fuels And Additives - Requirements And Approved Listing								T (-)	Recommended
1244 Rev 27 72 ENG1 Eff: 30-Dec-2016	Engine Fuels And Additives - Requirements And Approved Listing								T (-)	Recommended
1244 Rev 3 72 ENG1	Engine Fuels And Additives - Requirements And Approved Listing								RE (-)	Recommended
1244 Rev 4 72 ENG1	Engine Fuels And Additives - Requirements And Approved Listing								RE (-)	Recommended
1244 Rev 5 72 ENG1	Engine Fuels And Additives - Requirements And Approved Listing								RE (-)	Recommended
1244 Rev 6 72 ENG1	Engine Fuels And Additives - Requirements And Approved Listing								RE (-)	Recommended
1244 Rev 7 72 ENG1	Engine Fuels And Additives - Requirements And Approved Listing								RE (-)	Recommended
1244 Rev 8 72 ENG1	Engine Fuels And Additives - Requirements And Approved Listing								RE (-)	Recommended
1244 Rev 9 72 ENG1	Engine Fuels And Additives - Requirements And Approved Listing								RE (-)	Recommended

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
1447		Tachometer Drive Bevel Gearshaft - Modification Of							RE (-)	Category 8
	72 ENG1									Mos
	Eff: 25-Jul-1989									Hrs
	(AVG MAN HRS: 2.5)									Enc
1447 R1		Tachometer Drive Bevel Gearshaft - Modification Of							RE (-)	Category 8
	72 ENG1									Mos
										Hrs
	(AVG MAN HRS: 2.5)									Enc
1447 R2		Tachometer Drive Bevel Gearshaft - Modification Of							RE (-)	Category 8
	72 ENG1									Mos
										Hrs
	(AVG MAN HRS: 2.5)									Enc
1447 R3		Tachometer Drive Bevel Gearshaft - Modification Of							RE (-)	Category 8
	72 ENG1									Mos
										Hrs
	(AVG MAN HRS: 2.5)									Enc
1447 R4		Tachometer Drive Bevel Gearshaft - Modification Of							T (-)	Category 8
	72 ENG1									Mos
	Eff: 21-Feb-2014									Hrs
	(AVG MAN HRS: 2.5)									Enc
1447 R5		Tachometer Drive Bevel Gearshaft - Modification Of							T (-)	Cat. 7 - Optional
	72 ENG1									Mos
	Eff: 23-Dec-2014									Hrs
	(AVG MAN HRS: 2.5) (NOTE: An improved square drive for the tachometer bevel gearshaft is introduced)									Enc
1447 R6		Tachometer Drive Bevel Gearshaft - Modification Of							T (A/R)	Category 8
	72 ENG1									Mos
	Eff: 27-May-2016									Hrs
	(AVG MAN HRS: 2.5)									Enc
1511 R2		Modification/Replacement of Fuel Nozzle Adapter Assembly Bolts, Removal of Gas Generator Case Assembly							RE (-)	Category 8
	72 ENG1									Mos
	Eff: 31-Jul-2018									Hrs
										Enc
1669 R11		Inspection/Replacement of Compressor Turbine Blades							RE (-)	Category 3
	72 ENG1									Mos
	Eff: 17-Jan-2017									Hrs
	(AVG MAN HRS: 17)									Enc
1703 R12		Operating Time Between Overhauls and Hot Section Inspection Frequency (This service bulletin supersedes P&WC S.B. No. 1003)							T (-)	
	72 ENG1									Mos
	Eff: 20-Mar-2018									Hrs
										Enc
1703 R13		Operating Time Between Overhauls and Hot Section Inspection Frequency (This SB supersedes SB 1003)							T (A/R)	
	72 ENG1									Mos
	Eff: 04-Oct-2018									Hrs
										Enc
1710		Single Port Turbine Exhaust Duct Assembly - Replacement of							T (A/R)	Category 7
	72 ENG1									Mos
	Eff: 14-Feb-2017									Hrs
										Enc

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
1715		Fuel/Oil Heat Exchanger (Fohe) - Replacement of							RE (-)	Category 7
	72 ENG1					Mos	29-Jun-2016			
	Eff: 03-May-2013 Complied	AT MANUFACTURE				Hrs	0			
	With					Enc	0			
1717		First Stage Carrier Balancing Assembly - Modification/ Replacement of							RE (-)	Category 7
	72 ENG1					Mos	29-Jun-2016			
	Eff: 25-Sep-2013 Complied	AT MANUFACTURE				Hrs	0			
	With					Enc	0			
1718		Fuel/Oil Heat Exchanger (Fohe) - Replacement of							RE (-)	Category 6
	72 ENG1					Mos	29-Jun-2016			
	Eff: 12-Jul-2013 Complied	AT MANUFACTURE				Hrs	0			
	With					Enc	0			
1719		Fuel/Oil Heat Exchanger (Fohe) - Inspection of							T (A/R)	Category 3
	72 ENG1					Mos				
	Eff: 25-Jun-2013					Hrs				
						Enc				
1720		Motive Flow Solenoid Valve - Replacement of							RE (-)	Category 3
	72 ENG1					Mos				
						Hrs				
						Enc				
1720 R1		Motive Flow Solenoid Valve - Replacement of							RE (-)	Category 3
	72 ENG1					Mos				
						Hrs				
						Enc				
1720 R2		Motive Flow Solenoid Valve - Replacement of							RE (-)	Category 3
	72 ENG1					Mos	29-Jun-2016			
	Eff: 22-Dec-2015 Complied	AT MANUFACTURE				Hrs	0			
	With					Enc	0			
1721		Replacement of Power Turbine Disk							RE (-)	Category 3
	72 ENG1					Mos				
	Eff: 02-Jul-2013					Hrs				
						Enc				
1721 R1		Replacement of Power Turbine Disk							RE (-)	Category 3
	72 ENG1					Mos				
	Eff: 02-Jul-2013					Hrs				
	(AVG MAN HRS: 3)					Enc				
1722		Propeller Reduction Gearbox Front Housing Assembly - Replacement of							RE (-)	Category 7
	72 ENG1					Mos				
						Hrs				
						Enc				
1722 R1		Propeller Reduction Gearbox Front Housing Assembly - Replacement of							T (A/R)	Category 7
	72 ENG1					Mos				
	Eff: 04-Feb-2014					Hrs				
						Enc				
1723		Compressor Stator Assembly - Replacement of							RE (-)	Category 7
	72 ENG1					Mos	29-Jun-2016			
	Eff: 15-Oct-2014 Complied	AT MANUFACTURE				Hrs	0			
	With					Enc	0			













Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time Remaining
SEQ PN/SN	MOC Note or Component Condition								DUE	
1724	Fuel/Oil Heat Exchanger (Fohe) - Replacement / Modification of								RE (-)	Category 5
72 ENG1										
1724 R1	Fuel/Oil Heat Exchanger (Fohe) - Replacement / Modification of								RE (-)	Category 5
72 ENG1										
1724 R2	Fuel/Oil Heat Exchanger (Fohe) - Replacement / Modification of								RE (-)	Category 5
72 ENG1										
Complied With	AT MANUFACTURE									
1724 R3	Fuel/Oil Heat Exchanger (Fohe) - Replacement / Modification of								T (-)	Category 5
72 ENG1										
Eff: 18-Aug-2016										
1724 R4	Replacement / Modification of Fuel/Oil Heat Exchanger (FOHE)								RE (-)	Category 5
72 ENG1										
Eff: 13-Nov-2017										
(AVG MAN HRS: 1.5)										
1725	Fuel Filter Impending Bypass Indicator- Replacement of								RE (-)	Category 6
72 ENG1										
1725 R1	Fuel Filter Impending Bypass Indicator- Replacement of								RE (-)	Category 6
72 ENG1										
Eff: 06-Nov-2013	Complied AT MANUFACTURE									
With										
1727 R1	Replacement of Compressor Turbine Blades								RE (-)	Category 7
72 ENG1										
Eff: 30-Mar-2016										
(AVG MAN HRS: 9)										
1729	Accessory Gearbox Housing Assembly - Modification / Replacement of								RE (-)	Category 6, Category 7
72 ENG1										
Eff: 27-Jan-2014	Complied AT MANUFACTURE									
With										
1730	Compressor Turbine Shroud Housing - Replacement of								RE (-)	Category 7
72 ENG1										
Eff: 17-Apr-2015	Complied AT MANUFACTURE									
With										
1731	Accessory Gearbox (Agb) Housing Assembly - Replacement of								T (A/R)	Category 10
72 ENG1										
Eff: 12-Dec-2013										
1733	Torque Limiter - Inspection of								RE (-)	Category 3
72 ENG1										













Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
1733 R1	Torque Limiter - Inspection of								T (A/R)	Category 3
72 ENG1										Mos
Eff: 27-Jan-2015										Hrs
										Enc
1735	Rear Reduction Gearbox Housing - Replacement of								RE (-)	Category 7
72 ENG1										Mos
Eff: 24-Apr-2014 Complied With	AT MANUFACTURE					29-Jun-2016	0			Hrs
							0			Enc
1736	Introduction of Fuel and Oil Temperature Sensor								RE (-)	Category 5
72 ENG1										Mos
Complied With	AT MANUFACTURE					29-Jun-2016	0			Hrs
							0			Enc
1736 R1	Introduction of Fuel and Oil Temperature Sensor								RE (-)	Category 5
72 ENG1										Mos
										Hrs
										Enc
1736 R2	Introduction of Fuel and Oil Temperature Sensor								T (-)	Category 5
72 ENG1										Mos
Eff: 05-Sep-2017										Hrs
										Enc
1737	Single Port Turbine Exhaust Duct Assembly - Replacement/Modification of								RE (-)	Category 3, Category 6
72 ENG1										Mos
Complied With	AT MANUFACTURE					29-Jun-2016	0			Hrs
							0			Enc
1737 R1	Single Port Turbine Exhaust Duct Assembly - Replacement/Modification of								T (-)	Category 3, Category 6
72 ENG1										Mos
Eff: 07-Sep-2017										Hrs
										Enc
1737 R2	Single Port Turbine Exhaust Duct Assembly - Replacement/Modification of								RE (-)	Category 3, Category 6
72 ENG1										Mos
Eff: 05-Jan-2018 (AVG MAN HRS: 1)										Hrs
										Enc
1740	Propeller Overspeed Governor - Replacement of								RE (-)	Category 7
72 ENG1										Mos
Eff: 24-Apr-2014 Complied With	AT MANUFACTURE					29-Jun-2016	0			Hrs
							0			Enc
1743	PT6A-140 Engine to PT6A-140 Engine - Conversion of								T (A/R)	Category 8
72 ENG1										Mos
Eff: 23-Dec-2014										Hrs
										Enc
1749 R1	Replacement of Compressor Turbine Blades								RE (-)	Category 7
72 ENG1										Mos
Eff: 18-Nov-2016 (AVG MAN HRS: 1.5)										Hrs
										Enc
1750	Fuel Filter Impending Bypass Indicator Preformed Packings - Replacement of								RE (-)	Category 6
72 ENG1										Mos
Eff: 12-Nov-2014 Complied With	AT MANUFACTURE					29-Jun-2016	0			Hrs
							0			Enc

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time Remaining
SEQ	PN/SN	MOC Note or Component Condition							DUE	
1751		Straight Headed Pin - Reorientation of							RE (-)	Category 6
	72 ENG1					Mos	29-Jun-2016			
	Eff: 25-Mar-2015 Complied With					Hrs	0			
						Enc	0			
1752		Fuel Nozzle Tips - Inspection of							RE (-)	Category 3
	72 ENG1					Mos				
						Hrs				
						Enc				
1752 R1		Fuel Nozzle Tips - Inspection of							RE (-)	Category 3
	72 ENG1					Mos				
						Hrs				
						Enc				
1752 R2		Fuel Nozzle Tips - Inspection of							T (A/R)	Category 3
	72 ENG1					Mos				
	Eff: 28-Oct-2016					Hrs				
						Enc				
1753		Compressor Turbine Air Baffle - Replacement of							RE (-)	Category 5
	72 ENG1					Mos	29-Jun-2016			
	Eff: 26-Jun-2015 Complied With					Hrs	0			
						Enc	0			
1755		Replacement of Power Turbine Shaft Housing Assembly Power Turbine Stator Air Seal And Retaining Ring							RE (-)	Category 6
	72 ENG1					Mos	29-Jun-2016			
	Eff: 13-Apr-2015 Complied With					Hrs	0			
						Enc	0			
1755 Rev 1		Replacement of Power Turbine Shaft Housing Assembly Power Turbine Stator Air Seal And Retaining Ring							RE (-)	Category 7
	72 ENG1					Mos				
	Eff: 22-Oct-2019					Hrs				
						Enc				
1756		Reduction Gearbox Tachometer Pad Washer - Removal of							RE (-)	Category 6
	72 ENG1					Mos	29-Jun-2016			
	Eff: 25-Feb-2015 Complied With					Hrs	0			
						Enc	0			
1757		1St And 2Nd Stage Reduction Carrier Set - Replacement/Modification of							RE (-)	Category 7
	72 ENG1					Mos	29-Jun-2016			
	Eff: 26-Mar-2015 Complied With					Hrs	0			
						Enc	0			
1765		Oil Filter Oil Filler Neck And Rgb Strainer - Preformed Packings - Replacement of							RE (-)	Category 9
	72 ENG1					Mos				
						Hrs				
						Enc				
1765 R1		Oil Filter Oil Filler Neck And Rgb Strainer - Preformed Packings - Replacement of							T (A/R)	Category 9
	72 ENG1					Mos				
	Eff: 15-Aug-2016					Hrs				
						Enc				
1769		Turboprop Engine - Replacement/Modification Of Compressor Disk Balancing Assembly							RE (-)	Category 6
	72 ENG1					Mos				
	Eff: 21-Dec-2015					Hrs				
	(AVG MAN HRS: 1.5)					Enc				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
1771		Propeller Reduction Gearbox Front And Rear Housing Assembly - Replacement of							RE (-)	Category 7
	72 ENG1					Mos	29-Jun-2016			
	Eff: 30-Jul-2015 Complied With					Hrs	0			
						Enc	0			
1775		Conversion of PT6A-140 Engine to PT6A-140 Engine							T (-)	Category 8
	72 ENG1					Mos				
	Eff: 17-Sep-2015					Hrs				
						Enc				
1775 Rev 1		Conversion of PT6A-140 Engine (Bs1294) to PT6A-140 Engine (Bs1341)							T (A/R)	Category 8
	72 ENG1					Mos				
	Eff: 19-Oct-2018					Hrs				
	(AVG MAN HRS: 1.5) (NOTE: CONCURRENT REQUIREMENTS: P&WC Special Instruction (SI) 71-2014 must be done in conjunction with this Service Bulletin (SB).)					Enc				
1776		PT6A-140 Engine to PT6A-140 Engine - Conversion of							RE (-)	Category 8
	72 ENG1					Mos				
						Hrs				
						Enc				
1776 R1		PT6A-140 Engine to PT6A-140 Engine - Conversion of							T (A/R)	Category 8
	72 ENG1					Mos				
	Eff: 16-Sep-2015					Hrs				
						Enc				
1777		Engine Shipping Container Assembly - Replacement of							T (A/R)	Category 10
	72 ENG1					Mos				
	Eff: 08-Feb-2016					Hrs				
						Enc				
1778		Carrier Balancing Assembly First-Stage - Replacement / Modification of							RE (-)	Category 8
	72 ENG1					Mos	29-Jun-2016			
	Eff: 17-Dec-2015 Complied With					Hrs	0			
						Enc	0			
1779		Replacement of Combustion Chamber Liner							T (-)	Category 7
	72 ENG1					Mos				
	Eff: 18-Oct-2016					Hrs				
						Enc				
1779 Rev 1		Replacement of Combustion Chamber Liner							T (A/R)	Category 7
	72 ENG1					Mos				
	Eff: 13-Nov-2020					Hrs				
	(AVG MAN HRS: 1.5)					Enc				
1783		Power Turbine Stator Air Seal - Replacement/Modification of							RE (-)	Category 6
	72 ENG1					Mos	29-Jun-2016			
	Eff: 11-Dec-2015 Complied With					Hrs	0			
						Enc	0			
1785		Power Turbine Stator Air Seal - Replacement of							RE (-)	Category 6
	72 ENG1					Mos				
						Hrs				
						Enc				
1785 R1		Power Turbine Stator Air Seal - Replacement of							T (A/R)	Category 6
	72 ENG1					Mos				
	Eff: 11-Feb-2016					Hrs				
						Enc				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
1788	Accessory Gearbox Housing Assembly - Replacement of						T (A/R)		Category 7	
72 ENG1										
Eff: 18-Jan-2016										
1790	Gas Generator Case Assembly - Replacement of						RE (-)		Category 7	
72 ENG1										
1790 Rev 1	Replacement of Gas Generator Case Assembly						T (-)		Category 7	
72 ENG1										
Eff: 07-Jul-2017										
1790 Rev 2	Replacement of Gas Generator Case Assembly						T (A/R)		Category 7	
72 ENG1										
Eff: 13-Nov-2020										
1791	Replacement of Compressor Center Top Fireseal						RE (-)		Category 7	
72 ENG1										
Eff: 01-Dec-2017										
1791 Rev 1	Replacement of Compressor Center Top Fireseal						T (A/R)		Category 7	
72 ENG1										
Eff: 16-Sep-2019										
1796	Replacement of Scavenge Pump Housing						T (-)		Category 7	
72 ENG1										
Eff: 02-Mar-2018										
1796 Rev 1	Replacement/Modification of Scavenge Pump Housing						T (A/R)		Category 7	≈03-Nov-2026
72 ENG1										
Eff: 04-May-2019									[2,000]	1,642.7 Hrs
1800	Replacement of Nut Option (IC)						T (-)		Category 9	
72 ENG1										
Eff: 24-Aug-2018										
1800 R1	Replacement of Nut Option (IC)						T (A/R)		Category 9	
72 ENG1										
Eff: 03-Oct-2018										
1804	Replacement/Modification of Centrifugal Impeller						T (A/R)		Category 7	
72 ENG1										
Eff: 23-Mar-2019										
1807	Replacement of Ignition Exciter						T (-)		Category 7	
72 ENG1										
Eff: 13-Mar-2019										
(AVG MAN HRS: 1.5)										
1807 Rev 1	Replacement of Ignition Exciter						T (A/R)		Category 7	
72 ENG1										
Eff: 15-Sep-2020										
(AVG MAN HRS: 1.5)										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
1808		Introduction of T5 Trim-Wiring-Harness Classifications							T (-)	Category 9
	72 ENG1 Eff: 19-Feb-2020									Mos Hrs Enc
1811		Introduction of Scavenge-Pump Drive-Shaft Plug							T (-)	Category 5
	72 ENG1 Eff: 05-Dec-2019 (AVG MAN HRS: 0.5)									Mos Hrs Enc
1811 R1		Introduction of Scavenge-Pump Drive Shaft Plug							T	Category 3
	72 ENG1 Eff: 05-Dec-2019 (AVG MAN HRS: 0.5) (NOTE: COMPLIANCE: CATEGORY 3 - P&WC recommends to do this service bulletin within 36 months from the initial release of this SB.)						36		05-Dec-2022	7.8 Months
1824		Replacement of Reduction Gearbox First Stage Ring Gear and Planet Gear Set							T (A/R)	Category 7
	72 ENG1 Eff: 09-Sep-2021									Mos Hrs Enc
1903		Operating Time Between Overhauls And Hot Section Inspection Frequency							RE (-)	Category 10
	72 ENG1									Mos Hrs Enc
1903 R1		Operating Time Between Overhauls And Hot Section Inspection Frequency							RE (-)	Category 10
	72 ENG1									Mos Hrs Enc
1903 R2		Operating Time Between Overhauls And Hot Section Inspection Frequency							RE (-)	Category 10
	72 ENG1									Mos Hrs Enc
1903 R3		Operating Time Between Overhauls And Hot Section Inspection Frequency							T (A/R)	Category 10
	72 ENG1 Eff: 27-Nov-2015									Mos Hrs Enc
2014-11-05		Reinforcement liner to the power turbine (PT) containment ring and, for certain PT containment rings, adding scallops							RE (-)	Mandatory
	72 ENG1 Eff: 05-Aug-2014									Mos Hrs Enc
3482		Replacement/Modification of Fuel Control Unit							RE (-)	Category 6
	72 ENG1 Eff: 02-Oct-2015									Mos Hrs Enc
3482 Rev 1		Replacement/Modification of Fuel Control Unit							RE (-)	Category 6
	72 ENG1 Eff: 19-Nov-2015									Mos Hrs Enc
3482 Rev 2		Replacement/Modification of Fuel Control Unit							RE (-)	Category 6
	72 ENG1 Eff: 07-Mar-2016									Mos Hrs Enc

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
3482 Rev 3	Replacement/Modification of Fuel Control Unit						RE (-)		Category 6	
 72 ENG1										Mos
Eff: 04-Apr-2016										Hrs
										Enc
3482 Rev 4	Replacement/Modification of Fuel Control Unit						RE (-)		Category 6	
 72 ENG1										Mos
Eff: 09-Jan-2017										Hrs
										Enc
3506	Conversion of PT6A-42A (BS1192) Engine to PT6A-42A (BS1181) Engine						T (A/R)		Category 8	
 72 ENG1										Mos
Eff: 05-May-2020										Hrs
(AVG MAN HRS: 1.5)										Enc
56-06-02	Cylinder Flange Attaching Stud						T (A/R)		Mandatory	
 72 ENG1										Mos
										Hrs
										Enc
A1713	Bracket Assembly Motive Flow Shut off Valve - Inspection of						T (A/R)		Category 3	
 72 ENG1										Mos
Eff: 28-Jan-2013										Hrs
										Enc
CAL-72-01	Transmittal of P&WC S.B. No. 1903R2						T (A/R)		Informational	
 72 A/F										Mos
Eff: 14-Mar-2013										Hrs
										Ldg
CAL-72-02	Transmittal of Pratt & Whitney Canada S.I.L. No. PT6A-206						T (A/R)		Informational	
 72 A/F										Mos
Eff: 05-Apr-2013										Hrs
										Ldg
CAL-72-03	Transmittal of P&WC S.B. No. 1703R7						RE (-)		Informational	
 72 A/F										Mos
Eff: 16-May-2013										Hrs
										Ldg
CAL-72-04	Transmittal of P&WC S.B. No. 1657R1						RE (-)		Informational	
 72 A/F										Mos
Eff: 12-Dec-2013										Hrs
										Ldg
CF-1996-24	Compressor Bleed-off Valve Cover Assembly Inspection/Replacement (Cancelled by AD CF-1996-24R1)						RE (-)		Mandatory	
 72 ENG1										Mos
Eff: 23-Dec-1996										Hrs
										Enc
PWC-79388-Y2D8	Inspection - Chip Detector And Oil Filter Patch Check - [Per Pwc Requirements] - Report Finding To Pwc.						RE (-)			
 72 ENG1								20-Jul-2018		Mos
Complied With								125.3		Hrs
								155		Enc
SIL No. GEN-143	P&WC Oil Analysis Technology Trial Program						T (-)		Service Information Letter	
 72 ENG1										Mos
Eff: 18-Aug-2016										Hrs
(NOTE: NOTE: The purpose of this Service Information Letter is to introduce P&WC operators to the new Oil Analysis Technology Trial program currently in progress for the next 18 to 24 months at P&WC.)										Enc

Task No		Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition								DUE	Remaining
SIL-GEN-143 Rev 1		P&WC Oil Analysis Technology Trial Program						T (A/R)		Service Information Letter	
	72 ENG1										Mos
	Eff: 02-Feb-2017										Hrs
	(NOTE: NOTE: It is recommended that this procedure be accomplished by the operator as soon as practicable upon first oil sampling kit reception and during scheduled maintenance.)										Enc
SIL-GEN-015 R2		Shipment Discrepancies, New Non-Conforming Material and Material Returns						T (A/R)		Service Information Letter	
	72 ENG1										Mos
	Eff: 23-Nov-2020										Hrs
											Enc
SIL-GEN-020 Rev 6		Vane Rings Airflow Rig Correlation and Calibration with P&WC						T (A/R)		Service Information Letter	
	72 ENG1										Mos
	Eff: 27-Sep-2021										Hrs
											Enc
SIL-GEN-022 R10		P&WC Service Tool Procurement						T (-)		Service Information Letter	
	72 ENG1										Mos
	Eff: 27-Apr-2020										Hrs
											Enc
SIL-GEN-022 R11		P&WC Service Tool Procurement						T (A/R)		Service Information Letter	
	72 ENG1										Mos
	Eff: 27-Apr-2020										Hrs
											Enc
SIL-GEN-044		Return of Engine Parts to Pratt & Whitney Canada Inc. (P&WC) for Investigation - Evaluation						RE (-)		Service Information Letter	
	72 ENG1										Mos
	Eff: 03-Jun-1998										Hrs
											Enc
SIL-GEN-044 R1		Return of Engine Parts to Pratt & Whitney Canada Inc. (P&WC) for Investigation - Evaluation						T (A/R)		Service Information Letter	
	72 ENG1										Mos
	Eff: 16-Oct-2017										Hrs
											Enc
SIL-GEN-049		Warranty Coverage Minimum Service Bulletin Lists and Service Bulletin (SB) Compliance Code						RE (-)		Service Information Letter	
	72 ENG1										Mos
											Hrs
											Enc
SIL-GEN-049 R1		Warranty Coverage Minimum Service Bulletin Lists and Service Bulletin (SB) Compliance Code						T (-)		Service Information Letter	
	72 ENG1										Mos
	Eff: 02-Nov-2012										Hrs
											Enc
SIL-GEN-049 R2		Warranty Coverage Minimum Service Bulletin Lists and Service Bulletin (SB) Compliance Code						T (A/R)		Service Information Letter	
	72 ENG1										Mos
	Eff: 13-Sep-2019										Hrs
											Enc
SIL-GEN-055		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
	72 ENG1										Mos
											Hrs
											Enc
SIL-GEN-055 R1		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
	72 ENG1										Mos
											Hrs
											Enc

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SIL-GEN-055 R10 72 ENG1 Eff: 13-Nov-2018	Guidelines and Standards for Subscribing and Utilizing the Internet-Based Engine Condition Trend Monitoring EHM Services								T (A/R)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-GEN-055 R2 72 ENG1	Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon								RE (-)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-GEN-055 R3 72 ENG1	Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon								RE (-)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-GEN-055 R4 72 ENG1	Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon								RE (-)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-GEN-055 R5 72 ENG1	Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon								RE (-)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-GEN-055 R6 72 ENG1	Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon								RE (-)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-GEN-055 R8 72 ENG1 Eff: 06-Nov-2018	Guidelines and Standards for Subscribing and Utilizing the Internet-based Engine Condition Trend Monitoring EHM Services								T (-)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-GEN-055 R9 72 ENG1 Eff: 08-Nov-2018	Guidelines and Standards for Subscribing and Utilizing the Internet-based Engine Condition Trend Monitoring EHM Services								T (-)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-GEN-061 72 ENG1	Engine Related Requests								RE (-)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-GEN-061 Rev 1 72 ENG1	Engine Related Requests								RE (-)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-GEN-061 Rev 10 72 ENG1 Eff: 25-Jan-2021	Engine Related Requests								T (A/R)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-GEN-061 Rev 2 72 ENG1	Engine Related Requests								RE (-)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-GEN-061 Rev 3 72 ENG1	Engine Related Requests								RE (-)	Service Information Letter
										Mos
										Hrs
										Enc

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SIL-GEN-061 Rev 4 72 ENG1	Engine Related Requests						RE (-)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-061 Rev 5 72 ENG1	Engine Related Requests						RE (-)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-061 Rev 6 72 ENG1	Engine Related Requests						RE (-)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-061 Rev 7 72 ENG1	Engine Related Requests						RE (-)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-061 Rev 8 72 ENG1 Eff: 10-Apr-2018	Engine Related Requests						T (-)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-061 Rev 9 72 ENG1 Eff: 21-Mar-2019	Engine Related Requests						T (-)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-093 72 ENG1 Eff: 20-Mar-2009	Engine Preservation and Storage						RE (-)		Informational	
										Mos
										Hrs
										Enc
SIL-GEN-093 R1 72 ENG1 Eff: 14-Apr-2016	Engine Preservation and Storage						T (-)		Informational	
										Mos
										Hrs
										Enc
SIL-GEN-093 R2 72 ENG1 Eff: 22-Oct-2021	Engine Preservation and Storage						T (A/R)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-105 72 ENG1	Diagnostics, Prognostics And Health Management ("DPHM") Package						RE (-)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-105 R1 72 ENG1	Diagnostics, Prognostics And Health Management ("DPHM") Package						RE (-)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-105 R2 72 ENG1	Diagnostics, Prognostics And Health Management ("DPHM") Package						RE (-)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-105 R3 72 ENG1	Diagnostics, Prognostics And Health Management ("DPHM") Package						RE (-)		Service Information Letter	
										Mos
										Hrs
										Enc

Task No		Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition								DUE	Remaining
SIL-GEN-105 R5		Diagnostics, Prognostics and Health Management ("DPHM") Package						T (A/R)		Service Information Letter	
	72 ENG1										Mos
	Eff: 14-Jun-2018										Hrs
											Enc
SIL-GEN-110		Pratt & Whitney Canada Corp. (P&WC) Customer Training Collaborative Agreement with FlightSafety International (FSI)						RE (-)		Service Information Letter	
	72 ENG1										Mos
											Hrs
											Enc
SIL-GEN-110 Rev 1		Pratt & Whitney Canada Corp. (P&WC) Customer Training Collaborative Agreement with FlightSafety International (FSI)						RE (-)		Service Information Letter	
	72 ENG1										Mos
											Hrs
											Enc
SIL-GEN-110 Rev 3		Pratt & Whitney Canada Corp. (P&WC) Customer Training Collaborative Agreement with FlightSafety International (FSI)						T (A/R)		Service Information Letter	
	72 ENG1										Mos
	Eff: 19-Dec-2018										Hrs
											Enc
SIL-GEN-122		Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
	72 ENG1										Mos
											Hrs
											Enc
SIL-GEN-122 R1		Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
	72 ENG1										Mos
											Hrs
											Enc
SIL-GEN-122 R2		Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
	72 ENG1										Mos
											Hrs
											Enc
SIL-GEN-122 R3		Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
	72 ENG1										Mos
											Hrs
											Enc
SIL-GEN-122 R4		Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
	72 ENG1										Mos
											Hrs
											Enc
SIL-GEN-122 R5		Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
	72 ENG1										Mos
											Hrs
											Enc
SIL-GEN-122 R6		Recovery Fee For Maintenance Deviation Letters						T (-)		Service Information Letter	
	72 ENG1										Mos
	Eff: 29-Dec-2017										Hrs
											Enc
SIL-GEN-122 R7		Recovery Fee For Maintenance Deviation Letters						T (-)		Service Information Letter	
	72 ENG1										Mos
	Eff: 19-Dec-2018										Hrs
											Enc
SIL-GEN-122 R8		Recovery Fee for Maintenance Deviation Letters						T (-)		Service Information Letter	
	72 ENG1										Mos
	Eff: 20-Dec-2019										Hrs
											Enc














Task No		Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition								DUE	Remaining
SIL-GEN-122 R9		Recovery Fee for Maintenance Deviation Letters						T (A/R)		Service Information Letter	
	72 ENG1										Mos
	Eff: 18-Dec-2020										Hrs
											Enc
SIL-GEN-123		Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
	72 ENG1										Mos
	Eff: 21-Jan-2013										Hrs
											Enc
SIL-GEN-123 R1		Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
	72 ENG1										Mos
											Hrs
											Enc
SIL-GEN-123 R2		Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
	72 ENG1										Mos
											Hrs
											Enc
SIL-GEN-123 R3		Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
	72 ENG1										Mos
											Hrs
											Enc
SIL-GEN-123 R4		Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
	72 ENG1										Mos
											Hrs
											Enc
SIL-GEN-123 R5		Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
	72 ENG1										Mos
											Hrs
											Enc
SIL-GEN-123 R6		Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
	72 ENG1										Mos
											Hrs
											Enc
SIL-GEN-123 R7		Qualified Engine Oil Analysis Laboratory List						T (-)		Service Information Letter	
	72 ENG1										Mos
	Eff: 10-Jul-2018										Hrs
											Enc
SIL-GEN-123 R8		Qualified Engine Oil Analysis Laboratory List						T (A/R)		Service Information Letter	
	72 ENG1										Mos
	Eff: 25-Jul-2018										Hrs
											Enc
SIL-GEN-128 Rev 1		Limited Time Offer for P&WC Engine Diagnostic System for Applicable P&WC Turbofan Powered Aircraft						T (A/R)		Service Information Letter	
	72 ENG1										Mos
	Eff: 15-Jul-2013										Hrs
											Enc
SIL-GEN-135		Aviation Accidents / Incidents - Return to Service of Affected P&WC Products and the Effect on Engine Warranty and Service Policies Status (This Service Information Letter (SIL) supersedes SIL GEN-039)						T (-)		Service Information Letter	
	72 ENG1										Mos
	Eff: 21-Feb-2017										Hrs
	(NOTE: APPLICABILITY: All P&WC engines.)										Enc

Task No		Description					CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI				DUE	Remaining
SIL-GEN-135 Rev 1		Aviation Accidents / Incidents - Return to Service of Affected P&WC Products and the Effect on Engine Warranty and Service Policies Status							T (A/R)	Service Information Letter	
	72 ENG1										Mos
	Eff: 03-Jun-2021										Hrs
											Enc
SIL-GEN-143		P&WC'S Oil Analysis Technology Trial Program							RE (-)	Service Information Letter	
	72 ENG1										Mos
	Eff: 18-Aug-2016										Hrs
											Enc
SIL-GEN-143 R1		P&WC'S Oil Analysis Technology Trial Program							RE (-)	Service Information Letter	
	72 ENG1										Mos
											Hrs
											Enc
SIL-GEN-143 R2		P&WC'S Oil Analysis Technology Trial Program							T (A/R)	Service Information Letter	
	72 ENG1										Mos
	Eff: 09-Jul-2018										Hrs
											Enc
SIL-GEN-153		P&WC's Oil Analysis Technology Program Logistics Information							T (-)	Service Information Letter	
	72 ENG1										Mos
	Eff: 17-Jul-2018										Hrs
											Enc
SIL-GEN-153 R7		P&WC's Oil Analysis Technology Service Logistics Information							T (A/R)	Service Information Letter	
	72 ENG1										Mos
	Eff: 05-Jan-2021										Hrs
											Enc
SIL-GEN-153 Rev 1		P&WC's Oil Analysis Technology Program Logistics Information							T (-)	Service Information Letter	
	72 ENG1										Mos
	Eff: 10-Mar-2019										Hrs
											Enc
SIL-GEN-153 Rev 2		P&WC's Oil Analysis Technology Service Logistics Information							T (-)	Service Information Letter	
	72 ENG1										Mos
	Eff: 20-Jun-2019										Hrs
											Enc
SIL-GEN-153 Rev 3		P&WC's Oil Analysis Technology Service Logistics Information							T (-)	Service Information Letter	
	72 ENG1										Mos
	Eff: 26-Sep-2019										Hrs
											Enc
SIL-GEN-153 Rev 4		P&WC's Oil Analysis Technology Service Logistics Information							T (-)	Service Information Letter	
	72 ENG1										Mos
	Eff: 05-May-2020										Hrs
											Enc
SIL-GEN-153 Rev 5		P&WC's Oil Analysis Technology Service Logistics Information							T (-)	Service Information Letter	
	72 ENG1										Mos
	Eff: 28-Sep-2020										Hrs
											Enc
SIL-GEN-153 Rev 6		P&WC's Oil Analysis Technology Service Logistics Information							T (-)	Service Information Letter	
	72 ENG1										Mos
	Eff: 30-Oct-2020										Hrs
											Enc
SIL-GEN-153 Rev 9		P&WC's Oil Analysis Technology Service Logistics Information							T (A/R)	Service Information Letter	
	72 ENG1										Mos
	Eff: 18-Jan-2022										Hrs
											Enc

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SIL-GEN-155 72 ENG1 Eff: 14-Jun-2019	Introduction of Hyperlinks in P&WC Service Bulletins								T (A/R)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-GEN-156 R1 72 ENG1 Eff: 02-Apr-2020	DUPONT KATHON™ FP 1.5 Fuel Biocide Product Discontinuation								T (-)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-GEN-156 R2 72 ENG1 Eff: 07-Apr-2020	DUPONT KATHON™ FP 1.5 Fuel Biocide Product Discontinuation								T (A/R)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-GEN-157 72 ENG1 Eff: 18-Mar-2020	Preservation - Engines Removed from Service on Temporary Basis								T (A/R)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-GEN-158 72 ENG1 Eff: 20-Jul-2020	Handling of Suspected Hexavalent Chromium Residue on Engine Parts During Maintenance, Repair and Overhaul								T (A/R)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-GEN-159 72 ENG1 Eff: 08-Jul-2020	Environmentally Assisted Cracking in Certain Aluminium Alloys								T (A/R)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-GEN-160 72 ENG1 Eff: 30-Jun-2020	Occasional Dust Plume Exposure								T (A/R)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-GEN-161 72 ENG1 Eff: 19-Oct-2020	Operations in Environments Affected by Wildfires, Bushfires and Forest Fires								T (A/R)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-GEN-166 72 ENG1 Eff: 23-Jun-2021	Critical Component Accumulated Cycle Counting								T (A/R)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-GEN-PT6-036 72 ENG1 Eff: 15-Jun-2016	Limited Time Offer for Data Transmission Unit (DtU) 3G Upgrade								T (-)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-GEN-PT6-036 Rev 1 72 ENG1 Eff: 24-Jul-2019	Limited Time Offer for Data Transmission Unit (DTU) 3G Upgrade								T (A/R)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-GEN-PT6-037 72 ENG1 Eff: 02-Oct-2018	ACES Viper II Analyzer Introduction								T (A/R)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-PT6A-135 72 ENG1 Eff: 01-Jan-2006	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)								RE (-)	Service Information Letter
										Mos
										Hrs
										Enc

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SIL-PT6A-135 R1 72 ENG1	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)								RE (-)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-PT6A-135 R2 72 ENG1 Eff: 03-Dec-2018	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)								T (-)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-PT6A-135 R3 72 ENG1 Eff: 17-Sep-2019	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)								T (A/R)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-PT6A-186 72 ENG1 Eff: 14-Apr-2011	Uncommanded on Ground Power Reduction PT6A-42A								RE (-)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-PT6A-186 Rev 1 72 ENG1	Uncommanded on Ground Power Reduction PT6A-42A								RE (-)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-PT6A-186 Rev 2 72 ENG1	Uncommanded on Ground Power Reduction PT6A-42A								RE (-)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-PT6A-233 72 ENG1 Eff: 08-Dec-2015	Fleet Time Between Overhaul Read-Across Harmonization								T (A/R)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-PT6A-239 72 ENG1 Eff: 09-Mar-2016	Reversing Lever Guide Pin Bracket Assembly								RE (-)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-PT6A-239 R1 72 ENG1 Eff: 15-Mar-2016	Reversing Lever Guide Pin Bracket Assembly								T (A/R)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-PT6A-245 72 ENG1 Eff: 23-Jun-2016 (NOTE: Note: Refer to Airworthiness Directive CF-2013-21R1.)	Alternative Means of Compliance For PT6A-114 and PT6A-114A CT Blades - Airworthiness Directive - Engines With Low Utilization								T (A/R)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-PT6A-251 72 ENG1 Eff: 27-Jan-2017	2017 PT6A Customer Days								RE (-)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-PT6A-251 Rev 1 72 ENG1	2017 PT6A Customer Days								RE (-)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-PT6A-251 Rev 2 72 ENG1 Eff: 09-Jan-2018	2017 PT6A Customer Days (This Service Information Letter is Cancelled)								RE (-)	Service Information Letter
										Mos
										Hrs
										Enc

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SIL-PT6A-254	Engine Starting Issues and/or Acceleration Issues from Ground Idle (GI)								T (A/R)	Service Information Letter
72 ENG1										Mos
Eff: 31-Mar-2017										Hrs
(NOTE: APPLICABILITY: All PT6A Engine models with DPF2 (Honeywell) FCU's.)										Enc
SIL-PT6A-268	P/N: 3032623 (IC PN 3073901-01) Number 4 Bearing Serial Number Misprint								T (A/R)	Service Information Letter
72 ENG1										Mos
Eff: 20-Jan-2020										Hrs
										Enc
SIL-PW200-004	New Engine Serial Numbering Methodology								RE (-)	Service Information Letter
72 ENG1										Mos
Eff: 20-Jun-1996										Hrs
										Enc
SIL-PW200-004 R1	New Engine Serial Numbering Methodology								RE (-)	Service Information Letter
72 ENG1										Mos
Eff: 23-Sep-1998										Hrs
										Enc
SIL-PW200-004 R2	New Engine Serial Numbering Methodology								T (A/R)	Service Information Letter
72 ENG1										Mos
Eff: 12-Mar-2004										Hrs
										Enc
SIL-PW300-007	New Engine Serial Numbering Methodology								RE (-)	Service Information Letter
72 ENG1										Mos
Eff: 20-Jun-1996										Hrs
										Enc
SIL-PW300-007 Rev 1	New Engine Serial Numbering Methodology								T (A/R)	Service Information Letter
72 ENG1										Mos
Eff: 23-Sep-1998										Hrs
										Enc
▼ 73 - ENGINE - FUEL AND CONTROL										
1701	Replacement of Turboprop Engine Fuel Nozzle Sheath								T (-)	Category 9
73 ENG1										Mos
Eff: 08-Feb-2017										Hrs
										Enc
1701 Rev 1	Replacement of Turboprop Engine Fuel Nozzle Sheath								T (-)	Category 9
73 ENG1										Mos
Eff: 06-Mar-2017										Hrs
										Enc
1701 Rev 2	Replacement of Turboprop Engine Fuel Nozzle Sheath								T (A/R)	Category 9
73 ENG1										Mos
Eff: 29-Dec-2021										Hrs
										Enc
1736 R3	Introduction of Fuel and Oil Temperature Sensor (Superseded by SB 1806)								RE (-)	Category 5
73 ENG1										Mos
Eff: 09-Jan-2019										Hrs
(AVG MAN HRS: 1.5)										Enc
1805	Inspection of Fuel Oil Heat Exchanger (FOHE) Preformed Packing								RE (-)	Category 3
73 ENG1										Mos
Eff: 21-Jan-2019										Hrs
(AVG MAN HRS: 1.5)										Enc














Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining	
1806		Removal of Fuel Oil Heat Exchanger (FOHE) Temperature Sensor (Supersedes SB 1736)							RE (-)	Category 7	≈03-Nov-2026
	73 ENG1										
	Eff: 09-Jan-2019										
	(AVG MAN HRS: 1.5)										
3482 Rev 5		Replacement/Modification of Fuel Control Unit							RE (-)	Category 6	
	73 ENG1										
	Eff: 09-Jul-2019										
	(AVG MAN HRS: 1.5)										
3501		Replacement/Modification of Oil to Fuel Heater							RE (-)	Category 3	
	73 ENG1										
	Eff: 14-Jun-2019										
	(AVG MAN HRS: 1.5)										
3501 Rev 1		Replacement/Modification of Oil to Fuel Heater							RE (-)	Category 3	
	73 ENG1										
	Eff: 14-Jun-2019										
	(AVG MAN HRS: 1.5)										
CAB05-18		Engine Fuel Pump Coupling Inspection							T (A/R)	Mandatory	
	73 A/F										
	Eff: 23-Dec-2005										
CAB08-1		Fuel Control Unit Rod End Hardware Replacement							T (A/R)	Recommended	
	73 A/F										
	Eff: 21-Jan-2008										
	(AVG MAN HRS: 1)										
CAB89-33		Engine Fuel Nozzle Inspection (Cancelled)							RE (-)	Recommended	
	73 A/F										
	Eff: 22-Dec-1989										
	(AVG MAN HRS: 0.5)										
CAB89-33 Rev 1		Engine Fuel Nozzle Inspection (Cancelled)							RE (-)	Recommended	
	73 A/F										
	Eff: 12-Mar-1993										
	(AVG MAN HRS: 0.5)										
CAB90-2		Inspection and Lubrication of Engine Fuel Control Rod Ends and Linkage - Cancelled							RE (-)		
	73 A/F										
	Eff: 22-Dec-1989										
CAB90-2 Rev 1		Inspection and Lubrication of Engine Fuel Control Rod Ends and Linkage - Cancelled							T (A/R)		
	73 A/F										
	Eff: 12-Mar-1993										
CAB90-24		Engine Fuel Control Actuating Lever Improvement							T (A/R)	Mandatory	
	73 A/F										
	Eff: 24-Aug-1990										
CAB91-22		Engine Fuel Condition Control Lever Replacement							T (A/R)	Mandatory	
	73 A/F										
	Eff: 05-Jul-1991										
CAB98-11		Engine Fuel Manifold Adapter Assembly Inspection							RE (-)	Recommended	
	73 A/F										
	Eff: 15-Jun-1998										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB98-11 Rev 1 73 A/F Eff: 28-Jun-1999	Engine Fuel Manifold Adapter Assembly Inspection								T (A/R)	Recommended
										Mos
										Hrs
										Ldg
CAB98-4 73 A/F Eff: 02-Mar-1998	Engine Fuel Manifold Adapter Assembly Inspection								RE (-)	Recommended
										Mos
										Hrs
										Ldg
CAB98-4 Rev 1 73 A/F Eff: 15-Jun-1998	Engine Fuel Manifold Adapter Assembly Inspection								T (A/R)	Recommended
										Mos
										Hrs
										Ldg
CAL-73-01 73 A/F Eff: 13-Sep-2012	Transmittal of P&WC S.B. No. 1705								T (A/R)	Mandatory
										Mos
										Hrs
										Ldg
CAL-73-02 73 A/F Eff: 17-Jul-2013	Transmittal of P&WC S.B. No. 1720								RE (-)	Recommended
										Mos
										Hrs
										Ldg
CAL-73-03 73 A/F Eff: 18-Jul-2013 (AVG MAN HRS: 1)	Transmittal of P&WC S.B. No. 1719								RE (-)	Recommended
										Mos
										Hrs
										Ldg
CAL-73-04 73 A/F Eff: 06-Dec-2013	Transmittal of P&WC S.B. No. 1725R1								RE (-)	Informational
										Mos
										Hrs
										Ldg
CAL-73-05 73 A/F Eff: 13-Aug-2014	Transmittal of P&WC S.B. No. 1748								T (A/R)	Informational
										Mos
										Hrs
										Ldg
CAL-73-06 73 A/F Eff: 22-May-2015	Fuel Nozzle Tip Assembly Replacement								RE (-)	Recommended
										Mos
										Hrs
										Ldg
SIL-PT6A-229 Rev 1 73 ENG1 Eff: 20-Oct-2021	PT6A Fuel Control Unit Improvement Package								T (A/R)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-PT6A-246 73 ENG1 Eff: 22-Jul-2016 (NOTE: NOTE: This Service Information Letter is valid until superseded or cancelled by revision.)	Preventive Maintenance on Fuel Tubes								T (A/R)	Service Information Letter
										Mos
										Hrs
										Enc
SNL89-7 73 A/F Eff: 12-May-1989	PT6 Engine Fuel Pump Inspection								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL93-8 73 A/F Eff: 10-Dec-1993	PT6A Engine Fuel Control Maintenance Practices								T (A/R)	Informational
										Mos
										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SNL94-7	Pratt and Whitney Engine Fuel Nozzle In Situ Cleaning								T (A/R)	Informational
73 A/F										Mos
Eff: 24-Jun-1994										Hrs
										Ldg
▼ 74 - IGNITION										
1819	Replacement of Ignition Exciter								T (-)	Category 7
74 ENG1										Mos
Eff: 18-Feb-2021										Hrs
(AVG MAN HRS: 1)										Enc
1819 Rev 1	Replacement of Ignition Exciter								RE (-)	Category 7
74 ENG1										Mos
Eff: 26-Mar-2021 Not Applicable										Hrs
(AVG MAN HRS: 1)										Enc
										21-Jun-2021
										316.7
										551
1819 Rev 2	Replacement of Ignition Exciter								RE (-)	Category 7
74 ENG1										Mos
Eff: 29-Apr-2021 Not Applicable										Hrs
(AVG MAN HRS: 1)										Enc
										21-Jun-2021
										316.7
										551
1819 Rev 3	Replacement of Ignition Exciter								RE (-)	Category 7
74 ENG1										Mos
Eff: 19-May-2021 Complied With										Hrs
(AVG MAN HRS: 1)										Enc
										21-Jun-2021
										316.7
										551
CAB07-7	Engine Spark Igniters Inspection								T (A/R)	Mandatory
74 A/F										Mos
Eff: 18-Sep-2007										Hrs
										Ldg
CAB94-6	Engine Igniter Inspection								T (A/R)	Recommended
74 A/F										Mos
Eff: 11-Feb-1994										Hrs
										Ldg
CAB96-11	Engine Igniter Lead Cable Routing Modification								T (A/R)	Optional
74 A/F										Mos
Eff: 01-Mar-1996										Hrs
										Ldg
▼ 75 - BLEED AIR										
CAB96-22	PT6A-114/-114A Engine Bleed Off Valve Cover Inspection/Replacement								T (A/R)	Mandatory
75 A/F										Mos
Eff: 06-Dec-1996										Hrs
										Ldg
SNL95-7	Clarification of Compressor Bleed Valves Installed on PT6A-114 and PT6A-114A Engines								T (A/R)	Informational
75 A/F										Mos
Eff: 18-Aug-1995										Hrs
										Ldg
SNL99-2	Engine Bleed Off Valve (BOV) Installation on PT6A-114 and PT6A-114A Engines								T (A/R)	Mandatory
75 A/F										Mos
Eff: 29-Mar-1999										Hrs
										Ldg
▼ 76 - ENGINE CONTROLS										
1766	Inspection of Turboprop Engine Interconnect Rod								RE (-)	Category 3
76 ENG1										Mos
Eff: 13-Jul-2015										Hrs
(AVG MAN HRS: 1.5)										Enc

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
97-25-04	Airplane Flight Manual (AFM) - Limitations - Power Levers								RE (-)	Mandatory
76 A/F	COMPLIED WITH BY AFM REVISION (SECTION 2),E.Á€±					Mos	29-Jun-2016			
Eff: 21-Jan-1998 Not Applicable						Hrs	0			
							Ldg	0		
CAB02-4	Emergency Power Lever Control Cable Bracket Replacement								T (A/R)	Recommended
76 A/F						Mos				
Eff: 22-Apr-2002						Hrs				
(AVG MAN HRS: 1)							Ldg			
CAB06-3	Control Quadrant Modification								T (A/R)	Recommended
76 A/F						Mos				
Eff: 20-Mar-2006						Hrs				
							Ldg			
CAB93-9	Throttle Quadrant Cover Tab Modification								T (A/R)	Recommended
76 A/F						Mos				
Eff: 12-Aug-1993						Hrs				
							Ldg			
▼ 77 - ENGINE INDICATING										
1808 Rev 1	Introduction of T5 Trim-Wiring-Harness Classifications								T (A/R)	Category 9
77 ENG1						Mos				
Eff: 01-Apr-2020						Hrs				
							Enc			
1820	Replacement of Torque Pressure Transducer								T (A/R)	Category 7
77 ENG1						Mos				
Eff: 08-Nov-2021						Hrs				
(AVG MAN HRS: 1)							Enc			
CAB05-3	Torque Transducer Replacement								T (A/R)	Optional
77 A/F						Mos				
Eff: 21-Feb-2005						Hrs				
							Ldg			
CAB10-1	Pratt & Whitney Engine Services ADAS+ ETM Torque Transducer Replacement and Software Update								RE (-)	Optional
77 A/F						Mos				
Eff: 18-Jan-2010						Hrs				
(AVG MAN HRS: 2)							Ldg			
CAB10-1 Rev 1	Pratt & Whitney Engine Services ADAS+ ETM Torque Transducer Replacement and Software Update								RE (-)	Optional
77 A/F						Mos				
Eff: 15-Mar-2010						Hrs				
(AVG MAN HRS: 2)							Ldg			
CAB-77-01	Fast Engine Trend Monitoring Installation for Airplanes with Provisions								RE (-)	Recommended
77 A/F						Mos				
Eff: 09-Jun-2014						Hrs				
(AVG MAN HRS: 6)							Ldg			
CAB-77-01 Rev 1	Engine Indicating - Fast Engine Trend Monitoring Installation for Airplanes with Provisions								RE (-)	Recommended
77 A/F						Mos				
Eff: 01-Jun-2018						Hrs				
(AVG MAN HRS: 6)							Ldg			
CAB-77-02	Engine Indicating - New Configuration File for ADAS Systems								RE (-)	Optional
77 A/F						Mos				
Eff: 18-Feb-2016						Hrs				
							Ldg			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time Remaining
SEQ	PN/SN	MOC Note or Component Condition							DUE	
CAL-77-01	Inspection of the Pressure Line and Vent Line for the Torque Indicator Gauge								RE (-)	Mandatory
77 A/F										Mos
Eff: 04-Dec-2014										Hrs
(AVG MAN HRS: 2.3)										Ldg
CAL-77-02	Engine Indicating - Fast Hardware and Software Update Available for 3G Network Connectivity								T (A/R)	Optional, Service Letter
77 A/F										Mos
Eff: 04-Jun-2018										Hrs
(NOTE: NOTE: Airplanes -5001 thru -5120 that have not incorporated CAB-77-01 must accomplish CAB-77-01R1 instead of CAL-77-02.)										Ldg
▼ 78 - EXHAUST										
CAB00-8	Engine Secondary Exhaust Duct Hanger Modification and Cowling Inspection								T (A/R)	Recommended
78 A/F										Mos
Eff: 29-May-2000										Hrs
(AVG MAN HRS: 8)										Ldg
CAB04-4	Engine Primary Exhaust Duct Replacement								T (A/R)	Optional
78 A/F										Mos
Eff: 08-Mar-2004										Hrs
(AVG MAN HRS: 3.5)										Ldg
CAB-78-02	Exhaust - Hanger Bracket Locations								RE (-)	Recommended
78 A/F										Mos
Eff: 17-Oct-2017 Not Applicable	BY AC SN						27-Nov-2017			Hrs
(AVG MAN HRS: 6)							87.8			Ldg
							97			
CAB90-27	Secondary Exhaust Duct Mid Support Removal								T (A/R)	Recommended
78 A/F										Mos
Eff: 26-Oct-1990										Hrs
										Ldg
▼ 79 - OIL										
CAB01-13	Engine Oil Tube Clamp Modification								T (A/R)	Recommended
79 A/F										Mos
Eff: 30-Nov-2001										Hrs
										Ldg
CAB03-2	Engine Oil Pressure/Oil Temperature Indicator Installation								T (A/R)	Optional
79 A/F										Mos
Eff: 24-Feb-2003										Hrs
(AVG MAN HRS: 2)										Ldg
CAB05-9	Engine Oil Tank Filler Cap Inspection								T (A/R)	Mandatory
79 A/F										Mos
Eff: 27-Jun-2005										Hrs
										Ldg
CAB11-2	Oil Pressure Transducer and Connector Inspection								T (A/R)	Recommended
79 A/F										Mos
Eff: 15-Feb-2011										Hrs
										Ldg
CAB11-6	Oil Scavenge Hose Inspection								T (A/R)	Recommended
79 A/F										Mos
Eff: 23-Aug-2011										Hrs
										Ldg
CAB87-17	Large Engine Oil Cooler Installation								T (A/R)	Optional
79 A/F										Mos
Eff: 18-Dec-1987										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB87-20	Engine Oil Scavenge Pump Retaining Nut Lockwasher Replacement								T (A/R)	Mandatory
 79 A/F										Mos
Eff: 19-Dec-1987										Hrs
										Ldg
CAB89-1	Engine Oil Hose Replacement								T (A/R)	Recommended
 79 A/F										Mos
Eff: 06-Jan-1989										Hrs
										Ldg
CAB90-19	Engine Oil Filler Cap Security								T (A/R)	Mandatory
 79 A/F										Mos
Eff: 22-Jun-1990										Hrs
										Ldg
CAB90-34	Engine Oil Filler Cap Security Warning Placard Installation								T (A/R)	Mandatory
 79 A/F										Mos
Eff: 21-Dec-1990										Hrs
										Ldg
CAB90-8	Large Engine Oil Cooler Hose Replacement								T (A/R)	Recommended
 79 A/F										Mos
Eff: 23-Mar-1990										Hrs
										Ldg
CAB91-1	Engine Oil Filler Tube Modification								T (A/R)	Recommended
 79 A/F										Mos
Eff: 25-Jan-1991										Hrs
										Ldg
CAB91-32	Engine Chip Detector Inspection and Replacement								T (A/R)	Recommended
 79 A/F										Mos
Eff: 01-Nov-1991										Hrs
										Ldg
CAB96-9	Engine Oil Filler Placard Installation Modification								T (A/R)	Recommended
 79 A/F										Mos
Eff: 09-Feb-1996										Hrs
										Ldg
CAL-79-01	Oil - C100490-1 Oil Cooler System Check Valve Assembly Repair Kit Installation								T (A/R)	Optional, Service Letter
 79 A/F										Mos
Eff: 09-May-2019										Hrs
										Ldg
CAL-79-02	Oil - Transmittal of Pratt & Whitney Canada Service Bulletin PT6A-72-1811 - Turboprop Engine - Introduction of Scavenge-Pump Drive-Shaft Plug								T (A/R)	Recommended
 79 A/F										Mos
Eff: 14-Jul-2020										Hrs
(AVG MAN HRS: 0.5)										Ldg
SIL-PT6A-226	Oil Filler Ball Valve Field Incorporation								RE (-)	Recommended
 79 ENG1										Mos
Eff: 17-Jul-2016										Hrs
										Enc
SIL-PT6A-226 R1	Oil Filler Ball Valve Field Incorporation								T (-)	Recommended
 79 ENG1										Mos
Eff: 08-Nov-2016										Hrs
										Enc
SIL-PT6A-226 R2	Oil Filler Ball Valve Field Incorporation								T (-)	Service Information Letter
 79 ENG1										Mos
Eff: 11-Nov-2016										Hrs
										Enc

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time Remaining
SEQ PN/SN	MOC Note or Component Condition								DUE	
SIL-PT6A-226 R3 79 ENG1 Eff: 11-Nov-2017	Oil Filler Ball Valve Field Incorporation								RE (-)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-PT6A-226 R4 79 ENG1 Eff: 18-Apr-2018	Oil Filler Ball Valve Field Incorporation								T (-)	Service Information Letter
										Mos
										Hrs
										Enc
SIL-PT6A-226 R5 79 ENG1 Eff: 29-Jun-2018	Oil Filler Ball Valve Field Incorporation								T (A/R)	Service Information Letter
										Mos
										Hrs
										Enc
SNL85-08 79 A/F Eff: 15-Feb-1985	Oil Leak Troubleshooting Maintenance Tip								T (A/R)	Service Newsletter
										Mos
										Hrs
										Ldg
SNL89-13 79 A/F Eff: 08-Sep-1989	Engine Chip Detector Functional Test								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SSP03-4 79 A/F Eff: 15-Dec-2003	Engine Oil Pressure and Torque Indicating Systems O-Ring Replacement								T (A/R)	Mandatory
										Mos
										Hrs
										Ldg
▼ 80 - STARTING										
CAB05-15 80 A/F Eff: 12-Dec-2005 (AVG MAN HRS: 144)	300 Ampere Starter-Generator Installation								RE (-)	Optional
										Mos
										Hrs
										Ldg
CAB05-15 Rev 1 80 A/F Eff: 22-Mar-2011 (AVG MAN HRS: 144)	300 Ampere Starter-Generator Installation								RE (-)	Optional
										Mos
										Hrs
										Ldg
CAB09-10 80 A/F Eff: 19-Oct-2009	Generator Field Circuit Breaker Inspection								T (A/R)	Recommended
										Mos
										Hrs
										Ldg
CAB-80-01 80 A/F Eff: 27-Oct-2014	300 Ampere Starter/Generator Installation for 208B EX (867SHP) Airplanes								T (A/R)	Optional
										Mos
										Hrs
										Ldg
CAL-80-01 80 A/F Eff: 16-Jan-2013	200-AMP Starter Generator Modification at Overhaul								T (A/R)	Informational
										Mos
										Hrs
										Ldg
CAL-80-02 80 A/F Eff: 01-Aug-2013	Transmittal of Skurka Aerospace Inc. Service Letter #231 Rev. A								T (A/R)	Informational
										Mos
										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time Remaining
SEQ PN/SN	MOC Note or Component Condition								DUE	
▼ 90 - GENERAL - SUPPLEMENTAL TYPE CERTIFICATE (STC)										
SNL04-5	FAA Approved Supplemental Type Certificates (STC's) and FAA-PMA Approved Parts								T (A/R)	Informational
90 A/F										Mos
Eff: 31-May-2004										Hrs
										Ldg
SNL06-6	FAA Approved Supplemental Type Certificates (STC's) and FAA-PMA Approved Parts								T (A/R)	Informational
90 A/F										Mos
Eff: 20-Mar-2006										Hrs
										Ldg
SNL95-9	FAA Approved Supplemental Type Certificates (STC's) and FAA-PMA Approved Parts								T (A/R)	Informational
90 A/F										Mos
Eff: 17-Nov-1995										Hrs
										Ldg
▼ 99 - --										
CAB01-1	Pilot's Operating Handbook and Pilot's Checklist Revisions								T (A/R)	Mandatory
99 A/F										Mos
Eff: 15-Jan-2001										Hrs
										Ldg
CAB01-12	Pilot's Operating Handbook and Pilot's Checklist Revisions								T (A/R)	Mandatory
99 A/F										Mos
Eff: 03-Dec-2001										Hrs
										Ldg
CAB02-6	Brazilian Airplane Flight Manual and Pilot's Checklist Revisions								T (A/R)	Mandatory
99 A/F										Mos
Eff: 17-Jun-2002										Hrs
										Ldg
CAB02-9	Pilot's Operating Handbook and Pilot's Checklist Revisions								T (A/R)	Mandatory
99 A/F										Mos
Eff: 17-Jun-2002										Hrs
										Ldg
CAB03-1	Pilot's Operating Handbook Revision								RE (-)	Mandatory
99 A/F										Mos
Eff: 10-Feb-2003										Hrs
										Ldg
CAB03-1 Rev 1	Pilot's Operating Handbook Revision								T (A/R)	Mandatory
99 A/F										Mos
Eff: 14-Feb-2003										Hrs
										Ldg
CAB03-10	Brazilian Airplane Flight Manual and Pilot's Checklist Revision								T (A/R)	Mandatory
99 A/F										Mos
Eff: 28-Jul-2003										Hrs
										Ldg
CAB03-14	Argentine Airplane Flight Manual Revisions								T (A/R)	Mandatory
99 A/F										Mos
Eff: 15-Dec-2003										Hrs
										Ldg
CAB03-8	British Aeroplane Flight Manual Revision								T (A/R)	Mandatory
99 A/F										Mos
Eff: 16-Jun-2003										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB04-7	Pilot's Operating Handbook Supplement S1 Revisions								T (A/R)	Mandatory
99 A/F										
Eff: 23-Aug-2004										
CAB05-14	Pilot's Operating Handbook Supplement S1 Revision								T (A/R)	Mandatory
99 A/F										
Eff: 12-Dec-2005										
CAB05-5	Pilot's Operating Handbook Temporary Revision and Supplement S1 Revisions								T (A/R)	Mandatory
99 A/F										
Eff: 14-Mar-2005										
CAB05-8	Pilot's Operating Handbook Temporary Revision and Supplement S1 Revision								T (A/R)	Mandatory
99 A/F										
Eff: 25-Jul-2005										
CAB06-1	Pilot's Operating Handbook Supplement S1 Revision								T (A/R)	Mandatory
99 A/F										
Eff: 12-Dec-2005										
CAB06-8	Pilot's Operating Handbook Supplement S1 Revision and Operational Limitation Placards Installation								T (A/R)	Mandatory
99 A/F										
Eff: 18-Sep-2006										
(AVG MAN HRS: 1)										
CAB07-3	Pilot's Operating Handbook Supplement S1 Revision and Operational Limitation Placard Installation								T (A/R)	Mandatory
99 A/F										
Eff: 05-Mar-2007										
(AVG MAN HRS: 0.2)										
CAB07-5	Pilot's Operating Handbook Revision								T (A/R)	Mandatory
99 A/F										
Eff: 25-Jun-2007										
CAB08-5	Pilot's Abbreviated Checklist Revision								T (A/R)	Recommended
99 A/F										
Eff: 12-May-2008										
CAB08-8	Stall Warning Margin Adjustment/Reset								T (A/R)	Mandatory
99 A/F										
Eff: 15-Dec-2008										
CAB87-19	Pilot's Operating Handbook and Checklist Revision								T (A/R)	Mandatory
99 A/F										
Eff: 29-Nov-1999										
CAB88-31	Pilot's Operating Handbook and Checklist Revision								T (A/R)	Mandatory
99 A/F										
Eff: 29-Nov-1999										
CAB88-4	Pilot's Operating Handbook and Checklist Revision								T (A/R)	Mandatory
99 A/F										
Eff: 29-Nov-1999										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB88-9	Tow Limit Modification								T (A/R)	Recommended
99 A/F										
Eff: 18-Mar-1988										
CAB89-22	Pilot's Operating Handbook and Checklist Revision								T (A/R)	Mandatory
99 A/F										
Eff: 29-Nov-1999										
CAB90-1	Pilot's Operating Handbook and Checklist Revisions								T (A/R)	Mandatory
99 A/F										
Eff: 19-Jan-1990										
CAB90-10	Cargo Loading Manual Revision								T (A/R)	Mandatory
99 A/F										
Eff: 23-Mar-1990										
CAB90-17	Pilot's Operating Handbook Revision								T (A/R)	Mandatory
99 A/F										
Eff: 25-Jun-2007										
CAB90-29	Pilot's Operating Handbook and Checklist Revisions								T (A/R)	Mandatory
99 A/F										
Eff: 02-Nov-1990										
CAB90-30	Pilot's Operating Handbook and Checklist Revisions								T (A/R)	Mandatory
99 A/F										
Eff: 02-Nov-1990										
CAB91-20	Pilot's Operating Handbook and Checklist Revisions								T (A/R)	Mandatory
99 A/F										
Eff: 28-Jun-1991										
CAB91-21	Pilot's Operating Handbook and Checklist Revisions								T (A/R)	Mandatory
99 A/F										
Eff: 28-Jun-1991										
CAB91-7	Pilot's Operating Handbook and Checklist Revisions								T (A/R)	Mandatory
99 A/F										
Eff: 22-Mar-1991										
CAB91-8	Pilot's Operating Handbook and Checklist Revisions								T (A/R)	Mandatory
99 A/F										
Eff: 22-Mar-1991										
CAB92-12	Pilot's Operating Handbook Revision								T (A/R)	Mandatory
99 A/F										
Eff: 25-Jun-2007										
CAB92-13	Pilot's Operating Handbook Revision								T (A/R)	Mandatory
99 A/F										
Eff: 25-Jun-2007										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB95-5	Pilot's Operating Handbook Revision								T (A/R)	Mandatory
99 A/F										
Eff: 25-Jun-2007										
CAB95-9	Pilot's Operating Handbook and Checklist Revisions								T (A/R)	Mandatory
99 A/F										
Eff: 23-Jun-1995										
CAB96-1	Cargo Loading Placard Modification								T (A/R)	Mandatory
99 A/F										
Eff: 26-Jan-1996										
CAB96-16	AN3-5A Bolt Inspection/Replacement								T (A/R)	Recommended
99 A/F										
Eff: 19-Jul-1996										
CAB96-18	Pilot's Operating Handbook and Checklist Revisions								T (A/R)	Mandatory
99 A/F										
Eff: 09-Aug-1996										
CAB96-19	Pilot's Operating Handbook and Checklist Revisions								T (A/R)	Mandatory
99 A/F										
Eff: 09-Aug-1996										
CAB96-7	Pilot's Operating Handbook Revision								T (A/R)	Mandatory
99 A/F										
Eff: 25-Jun-2007										
CAB96-8	Pilot's Operating Handbook Revision								T (A/R)	Mandatory
99 A/F										
Eff: 25-Jun-2007										
CAB97-4	Pilot's Operating Handbook and Checklist Revisions								T (A/R)	Mandatory
99 A/F										
Eff: 03-Mar-1997										
CAB97-5	Pilot's Operating Handbook and Checklist Revisions								T (A/R)	Mandatory
99 A/F										
Eff: 03-Mar-1997										
CAB98-1	Pilot's Operating Handbook Revisions								T (A/R)	Mandatory
99 A/F										
Eff: 19-Jan-1998										
CAB98-19	Pilot's Operating Handbook and Pilot's Checklist Revisions								T (A/R)	Mandatory
99 A/F										
Eff: 21-Dec-1998										
CAB98-3	Pilot's Checklist Revisions								T (A/R)	Mandatory
99 A/F										
Eff: 23-Feb-1998										

[]: Manual entry, (): Package, #: Masked Due, ≈: Estimated, Δ: Deficient, OVD: Overdue, Tol: Tolerance



Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CAB99-4	Pilot's Operating Handbook and Pilot's Checklist Revisions								T (A/R)	Mandatory
99 A/F										
Eff: 23-Aug-1999										
CAB99-8	Pilot's Operating Handbook and Pilot's Checklist Revisions								T (A/R)	Mandatory
99 A/F										
Eff: 29-Nov-1999										
CAL-99-01	Miscellaneous - Incremental Library Updates for CESVIEW								T (A/R)	Informational
99 A/F										
Eff: 29-Jan-2016										
SK421-68 Rev D	Hydro Modification (Model SE589, and Model SE588 Modified with Service Kit SK210-38)								T (A/R)	
99 A/F										
Eff: 07-May-1976										
SNL00-14	Cessna Service Information for All Propeller Model Airplanes								T (A/R)	Optional
99 A/F										
Eff: 26-Dec-2000										
SNL00-2	Service Publications Temporary Revision Numbering Change								T (A/R)	Informational
99 A/F										
Eff: 17-Jan-2000										
SNL00-3	Pilot's Operating Handbook - Log of Approved Supplements								T (A/R)	Informational
99 A/F										
Eff: 17-Jan-2000										
SNL01-2	New Cessna 2001 Service Directory								T (A/R)	Informational
99 A/F										
Eff: 17-Apr-2001										
SNL01-5	Air BP Purchase of Exxon Turbo Oil								T (A/R)	Informational
99 A/F										
Eff: 13-Aug-2001										
SNL03-10	Maintenance Practices - Handling of Airplane Gyro Instruments								T (A/R)	Informational
99 A/F										
Eff: 27-Oct-2003										
SNL04-6	Caravan II F406 Service Support								T (A/R)	Informational
99 A/F										
Eff: 28-Jun-2004										
SNL05-16	FAA - Approved Deicing Program Update - Winter 2005/2006								T (A/R)	Informational
99 A/F										
Eff: 21-Nov-2005										
SNL05-2	Handling of Airplane Gyro Instruments								T (A/R)	Informational
99 A/F										
Eff: 27-Oct-2003										














Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SNL05-4	FAA - Approved Deicing Program Update - Winter 2004/2005								T (A/R)	Informational
99 A/F										Mos
Eff: 31-Jan-2005										Hrs
										Ldg
SNL05-6	2005 Cessna Caravan Support Team Brochure								RE (-)	Informational
99 A/F										Mos
Eff: 21-Mar-2005										Hrs
										Ldg
SNL05-6 Rev 1	2005 Cessna Caravan Support Team Brochure								T (A/R)	Informational
99 A/F										Mos
Eff: 02-May-2005										Hrs
										Ldg
SNL05-8	New Cessna 2005 Service Directory								RE (-)	Informational
99 A/F										Mos
Eff: 25-Apr-2005										Hrs
										Ldg
SNL05-8 Rev 1	New Cessna 2005 Service Directory								T (A/R)	Informational
99 A/F										Mos
Eff: 23-May-2005										Hrs
										Ldg
SNL06-12	Caravan I Flight in Icing - Safety Awareness								RE (-)	Informational
99 A/F										Mos
Eff: 18-Sep-2006										Hrs
										Ldg
SNL06-12 Rev 1	Caravan I Flight in Icing - Safety Awareness								T (A/R)	Informational
99 A/F										Mos
Eff: 19-Feb-2007										Hrs
										Ldg
SNL06-15	Caravan I Cold Weather Operations - On-Line Safety Awareness Training Seminars								T (A/R)	Informational
99 A/F										Mos
Eff: 06-Oct-2006										Hrs
										Ldg
SNL06-18	Approved Deicing Program Updates - Winter 2006/2007								T (A/R)	Informational
99 A/F										Mos
Eff: 26-Dec-2006										Hrs
										Ldg
SNL06-3	New Cessna 2006 Service Directory								T (A/R)	Informational
99 A/F										Mos
Eff: 20-Mar-2006										Hrs
										Ldg
SNL06-4	2006 Cessna Caravan Support Team Brochure								T (A/R)	Informational
99 A/F										Mos
Eff: 20-Mar-2006										Hrs
										Ldg
SNL06-5	Maintaining Current Service and Operational Information for Propeller Airplanes								T (A/R)	Informational
99 A/F										Mos
Eff: 20-Mar-2006										Hrs
										Ldg
SNL07-15	Caravan I Flight in Icing - Safety Awareness Seminars								T (A/R)	Informational
99 A/F										Mos
Eff: 15-Oct-2007										Hrs
										Ldg














Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SNL07-4	New Cessna 2007 Service Directory								T (A/R)	Informational
99 A/F										Mos
Eff: 05-Feb-2007										Hrs
										Ldg
SNL07-7	2007 Cessna Caravan Support Team Brochure								T (A/R)	Informational
99 A/F										Mos
Eff: 02-Apr-2007										Hrs
										Ldg
SNL07-9	Maintaining Current Service and Operational Information for Propeller Airplanes								T (A/R)	Informational
99 A/F										Mos
Eff: 16-Apr-2007										Hrs
										Ldg
SNL08-1	FAA Approved Deicing Program Update Winter 2007-2008								T (A/R)	Informational
99 A/F										Mos
Eff: 21-Jan-2008										Hrs
										Ldg
SNL08-14	Main Landing Gear Inspection Interval Audit								RE (-)	Informational
99 A/F										Mos
Eff: 14-Jul-2008										Hrs
										Ldg
SNL08-14 Rev 1	Main Landing Gear Inspection Interval Audit								T (A/R)	Informational
99 A/F										Mos
Eff: 18-Jan-2011										Hrs
										Ldg
SNL08-21	FAA Approved Deicing Program Update Winter 2008-2009								T (A/R)	Informational
99 A/F										Mos
Eff: 15-Dec-2008										Hrs
										Ldg
SNL08-9	New Cessna 2008 Service Directory								T (A/R)	Informational
99 A/F										Mos
Eff: 05-May-2008										Hrs
										Ldg
SNL10-1	FAA Approved Deicing Program Update Winter 2009-2010								T (A/R)	Informational
99 A/F										Mos
Eff: 11-Jan-2010										Hrs
										Ldg
SNL10-5	Ethanol Based Fuel Not Approved for Use in Cessna Airplanes								T (A/R)	Informational
99 A/F										Mos
Eff: 18-May-2010										Hrs
										Ldg
SNL11-29	Cessna Service Document Change Notification								T (A/R)	Informational
99 A/F										Mos
Eff: 22-Nov-2011										Hrs
										Ldg
SNL11-3	2010 IGRF (International Geomagnetic Reference Field) Magnetic Field Model								T (A/R)	
99 A/F										Mos
Eff: 15-Mar-2011										Hrs
										Ldg
SNL11-30	FAA Approved Deicing Program Update Winter 2011-2012								T (A/R)	Informational
99 A/F										Mos
Eff: 04-Nov-2011										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SNL11-5	PT6A Value Overhaul Program and Hot Section Refresh Kits								T (A/R)	
99 A/F										Mos
Eff: 22-Mar-2011										Hrs
										Ldg
SNL85-1	New Cessna Service Information System								T (A/R)	Informational
99 A/F										Mos
Eff: 18-Jan-1985										Hrs
										Ldg
SNL85-45	Cessna Owner Advisory Service								T (A/R)	Informational
99 A/F										Mos
Eff: 11-Oct-1985										Hrs
										Ldg
SNL85-51	New Cessna Aircraft Condition Report Form								T (A/R)	Informational
99 A/F										Mos
Eff: 15-Nov-1985										Hrs
										Ldg
SNL85-53	Cessna Pilot Safety and Warning Supplements								T (A/R)	Informational
99 A/F										Mos
Eff: 27-Nov-1985										Hrs
										Ldg
SNL85-8	Oil Leak Troubleshooting Maintenance Tip								T (A/R)	Informational
99 A/F										Mos
Eff: 15-Feb-1985										Hrs
										Ldg
SNL86-29	Serial Number Requirements, Customer Care Quick Claims								T (A/R)	Informational
99 A/F										Mos
Eff: 03-Jul-1986										Hrs
										Ldg
SNL86-30	Reminder on Stored Airplane Criteria								T (A/R)	Informational
99 A/F										Mos
Eff: 03-Jul-1986										Hrs
										Ldg
SNL86-44	Flight Control Surface Balancing Information								T (A/R)	Informational
99 A/F										Mos
Eff: 12-Sep-1986										Hrs
										Ldg
SNL86-46	Service Bulletin Credit Cutoff Dates								T (A/R)	Informational
99 A/F										Mos
Eff: 24-Oct-1986										Hrs
										Ldg
SNL87-10	Cessna Propeller Aircraft Technical Support								T (A/R)	Informational
99 A/F										Mos
Eff: 13-Mar-1987										Hrs
										Ldg
SNL87-27	Revision Status Checklists for Technical Publications and Pilot's Operating Handbooks								T (A/R)	Informational
99 A/F										Mos
Eff: 13-Nov-1987										Hrs
										Ldg
SNL87-7	Warranty Policy Clarification - Exchange Parts								RE (-)	Informational
99 A/F										Mos
Eff: 13-Feb-1987										Hrs
										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SNL87-7 Rev 1 99 A/F Eff: 30-Oct-1987	Warranty Policy Clarification - Exchange Parts								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL87-9 99 A/F Eff: 06-Mar-1987	Avionics Warranty Registration								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL88-11 99 A/F Eff: 26-Jul-1991	New Cessna Sales and Service Directory								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL88-6 99 A/F Eff: 25-Mar-1988	Revised Progressive Care Inspection Manual and Obsolete Progressive Care Inspection Operation Schedules								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL89-11 99 A/F Eff: 08-Sep-1989	Proper Lubrication Practices for Hartzell Propeller Assemblies								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL89-14 99 A/F Eff: 15-Sep-1989	Revised Progressive Care and Continuous Inspection Operations Manual								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL89-15 99 A/F Eff: 22-Sep-1989	Production Change for Aerofiche Publications								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL89-16 99 A/F Eff: 29-Dec-1989	Customized Service Bulletin Listing Program								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL89-18 99 A/F Eff: 24-Nov-1989	Eaton Consolidated Controls Bleed Air Components Maintenance Information								RE (-)	Informational
										Mos
										Hrs
										Ldg
SNL89-18 Rev 1 99 A/F Eff: 15-Jun-1990	Eaton Consolidated Controls Bleed Air Components Maintenance Information								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL89-19 99 A/F Eff: 08-Dec-1989	Cessna Customer Care Supplies and Publications Catalog								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL89-5 99 A/F Eff: 31-Mar-1989	Propeller Aircraft Special Tools Catalog								T (A/R)	Informational
										Mos
										Hrs
										Ldg
SNL89-6 99 A/F Eff: 07-Apr-1989	Customized Service Bulletin Listing Program for Propjet Airplanes								T (A/R)	Informational
										Mos
										Hrs
										Ldg








Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SNL90-1	Improved Shockmounts for KG 102A and KSG 105 Directional Gyros								T (A/R)	Informational
99 A/F										Mos
Eff: 05-Jan-1990										Hrs
										Ldg
SNL90-13	Cessna Customer Care Supplies and Publications Catalog								T (A/R)	Informational
99 A/F										Mos
Eff: 21-Dec-1990										Hrs
										Ldg
SNL90-5	New Cessna Sales and Service Directory								T (A/R)	Informational
99 A/F										Mos
Eff: 26-Jul-1991										Hrs
										Ldg
SNL90-7	PT6A-114/-114A Engine Interchangeability								RE (-)	Informational
99 A/F										Mos
Eff: 12-Oct-1990										Hrs
										Ldg
SNL90-7 Rev 1	PT6A-114/-114A Engine Interchangeability								T (A/R)	Informational
99 A/F										Mos
Eff: 24-Sep-1993										Hrs
										Ldg
SNL91-2	Control Wheel Cap and Press-to-Talk Switch Improvements								RE (-)	Informational
99 A/F										Mos
Eff: 22-Mar-1991										Hrs
										Ldg
SNL91-2 Rev 1	Control Wheel Cap and Press-to-Talk Switch Improvements								T (A/R)	Informational
99 A/F										Mos
Eff: 13-Dec-1991										Hrs
										Ldg
SNL91-3	New Cessna Sales and Service Directory								T (A/R)	Informational
99 A/F										Mos
Eff: 26-Jul-1991										Hrs
										Ldg
SNL91-4	Improved Fuel Tank Access Cover Sealant								T (A/R)	Informational
99 A/F										Mos
Eff: 15-Nov-1991										Hrs
										Ldg
SNL91-5	Temporary Revisions to Service/Maintenance Manuals and Illustrated Parts Catalogs								T (A/R)	Informational
99 A/F										Mos
Eff: 13-Dec-1991										Hrs
										Ldg
SNL91-6	Radar Pod Abrasion Boot Installation								T (A/R)	Informational
99 A/F										Mos
Eff: 20-Dec-1991										Hrs
										Ldg
SNL92-1	Cessna Customer Care Supplies and Publications Catalog								T (A/R)	Informational
99 A/F										Mos
Eff: 17-Jan-1992										Hrs
										Ldg
SNL92-4	New Cessna Service Directory								T (A/R)	Informational
99 A/F										Mos
Eff: 10-Jul-1992										Hrs
										Ldg

Task No		Description					CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI				DUE	Remaining
SNL92-8		Cessna Customer Care Supplies and Publications Catalog							T (A/R)	Informational	
	99 A/F										
	Eff: 31-Dec-1992										
SNL93-10		Cessna Customer Care Supplies and Publications Catalog							T (A/R)	Informational	
	99 A/F										
	Eff: 30-Dec-1993										
SNL93-4		New Cessna Service Station Directory							T (A/R)	Informational	
	99 A/F										
	Eff: 18-Apr-1997										
SNL93-6		Maintenance Practices for Pressure Cylinders							T (A/R)	Informational	
	99 A/F										
	Eff: 17-Sep-1993										
SNL93-9		Field Inspection and Repair of McCauley Propeller Blades							RE (-)	Informational	
	99 A/F										
	Eff: 10-Dec-1993										
SNL94-2		Improved O-Rings for Airborne Bleed Air Pressure Valve Installation							RE (-)	Informational	
	99 A/F										
	Eff: 25-Feb-1994										
SNL94-2 Rev 1		Improved O-Rings for Airborne Bleed Air Pressure Valve Installation							T (A/R)	Informational	
	99 A/F										
	Eff: 25-Mar-1994										
SNL94-4		Cessna Service Information for Propeller Model Airplanes							T (A/R)	Informational	
	99 A/F										
	Eff: 29-Apr-1994										
SNL94-8		New Cessna Service Station Directory							T (A/R)	Informational	
	99 A/F										
	Eff: 18-Apr-1997										
SNL95-1		Cessna Customer Care Supplies and Publications Catalog							T (A/R)	Informational	
	99 A/F										
	Eff: 20-Jan-1995										
SNL95-10		Cessna Customer Care Supplies and Publications Catalog							T (A/R)	Informational	
	99 A/F										
	Eff: 29-Dec-1995										
SNL95-4		New Cessna Service Station Directory							T (A/R)	Informational	
	99 A/F										
	Eff: 18-Apr-1997										
SNL95-8		Approved Nondestructive Testing Facilities - Superseded by SNL98-7							T (A/R)	Informational	
	99 A/F										
	Eff: 01-Sep-1995										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SNL96-1	Caravan I Technical Information on CD-ROM								T (A/R)	Informational
 99 A/F Eff: 02-Feb-1996										
SNL96-2	Cessna Propeller Aircraft Product Support Brochure								T (A/R)	Informational
 99 A/F Eff: 19-Apr-1996										
SNL96-3	New Cessna Service Station Directory								T (A/R)	Informational
 99 A/F Eff: 18-Apr-1997										
SNL97-2	Cessna Customer Care Supplies and Publications Catalog								T (A/R)	Informational
 99 A/F Eff: 17-Mar-1997										
SNL97-3	New Cessna Service Station Directory								T (A/R)	Informational
 99 A/F Eff: 18-Apr-1997										
SNL98-10	Cessna Service Information for All Propeller Model Airplanes								T (A/R)	Informational
 99 A/F Eff: 14-Sep-1998										
SNL98-11	Year 2000 Readiness Disclosure								T (A/R)	Informational
 99 A/F Eff: 21-Dec-1998										
SNL98-12	Year 2000 Calendar Preparation								T (A/R)	Informational
 99 A/F Eff: 21-Dec-1998										
SNL98-3	Cessna Customer Care Supplies and Publications Catalog								T (A/R)	Informational
 99 A/F Eff: 27-Sep-1998										
SNL98-5	New Cessna 1998 Service Directory								T (A/R)	Informational
 99 A/F Eff: 18-May-1998										
SNL98-7	Approved Nondestructive Testing Facilities - Superseded by SNL00-11								T (A/R)	Informational
 99 A/F Eff: 29-Jun-1998										
SNL98-8	Revised Maintenance Practices - Hazardous Air Pollutants Standard								RE (-)	Informational
 99 A/F Eff: 20-Jul-1998										
SNL98-8 Rev 1	Revised Maintenance Practices - Hazardous Air Pollutants Standard								T (A/R)	Informational
 99 A/F Eff: 02-Nov-1998										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SNL98-9	New Pilot Safety and Warning Supplements								RE (-)	Informational
99 A/F										Mos
Eff: 17-Aug-1998										Hrs
										Ldg
SNL98-9 Rev 1	New Pilot Safety and Warning Supplements								T (A/R)	Informational
99 A/F										Mos
Eff: 26-Oct-1998										Hrs
										Ldg
SSP03-2	Pilot's Instrument Panel Floodlight Wiring Modification - CAA Certified Airplanes								T (A/R)	Recommended
99 A/F										Mos
Eff: 11-Aug-2003										Hrs
										Ldg
▼ 100 - GENERAL										
CF-58-02	Radio Equipment Installed Directly Under an Engine Fuel Primer in Aircraft Must Be Relocated Owing to Fire Hazard (This cancels Airworthiness Directive 51-4)								T (A/R)	Mandatory
100 A/F										Mos
	(NOTE: COMPLIANCE: Compliance with this Directive is effective immediately for all aircraft affected by this order.)									Hrs
										Ldg
SIL-GEN-156	DUPONT KATHON™ FP 1.5 Fuel Biocide Product Discontinuation								T (-)	Service Information Letter
100 ENG1										Mos
Eff: 06-Aug-2019										Hrs
										Enc
SIL-GEN-163	Removal of AWL Requirement to Mark Parts with Accumulated Cycles and/or Time								T (A/R)	Service Information Letter
100 ENG1										Mos
Eff: 03-Mar-2021										Hrs
										Enc
SIL-GEN-PT6-038	United States Parts Distribution								T (A/R)	Service Information Letter
100 ENG1										Mos
Eff: 02-Jun-2021										Hrs
										Enc
SIL-PT6A-276	P&WC's Oil Analysis Technology Solution Now Available for Cessna Caravan and Grand Caravan Ex Aircraft Models								T (A/R)	Service Information Letter
100 ENG1										Mos
Eff: 04-Jan-2021										Hrs
										Enc
SNL00-11	Approved Nondestructive Testing Facilities (Superseded by MEL-20-01)								T (-)	Service Newsletter
100 A/F										Mos
Eff: 28-Aug-2000										Hrs
										Ldg
SNL85-35	Use of Airplane Lights for Daytime Recognition								T (-)	Service Newsletter
100 A/F										Mos
Eff: 09-Aug-1985										Hrs
										Ldg
SNL85-35R1	Use of Airplane Lights for Daytime Recognition								T (A/R)	Service Newsletter
100 A/F										Mos
Eff: 23-Aug-1985										Hrs
										Ldg
SNL87-07	Warranty Policy Clarification - Exchange Parts								T (-)	Service Newsletter
100 A/F										Mos
Eff: 13-Feb-1987										Hrs
(AVG MAN HRS: 0)										Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SNL87-07R1	Warranty Policy Clarification - Exchange Parts								T (A/R)	Service Newsletter
100 A/F										
Eff: 30-Oct-1987										
(AVG MAN HRS: 0)										
SNL90-05	New Cessna Sales and Service Directory								T (A/R)	Service Newsletter
100 A/F										
Eff: 22-Jun-1990										
SNL91-03	New Cessna Sales and Service Directory								T (A/R)	Service Newsletter
100 A/F										
Eff: 26-Jul-1991										
SNL92-01	Cessna Customer Care Supplies and Publications Catalog								T (A/R)	Service Newsletter
100 A/F										
Eff: 17-Jan-1992										
SNL92-04	New Cessna Service Directory								T (A/R)	Service Newsletter
100 A/F										
Eff: 10-Jul-1992										
SNL92-08	Cessna Customer Care Supplies and Publications Catalog								T (A/R)	Service Newsletter
100 A/F										
Eff: 31-Dec-1992										
SNL93-04	New Cessna Service Station Directory								T (A/R)	Service Newsletter
100 A/F										
Eff: 16-Jul-1993										
SNL94-08	New Cessna Service Station Directory								T (A/R)	Service Newsletter
100 A/F										
Eff: 01-Jul-1994										
SNL95-01	Cessna Customer Care Supplies and Publications Catalog								T (A/R)	Service Newsletter
100 A/F										
Eff: 20-Jan-1995										
SNL95-04	New Cessna Service Station Directory								T (A/R)	Service Newsletter
100 A/F										
Eff: 14-Jul-1995										
SNL95-08	Approved Nondestructive Testing Facilities								T (A/R)	Service Newsletter
100 A/F										
Eff: 01-Sep-1995										
SNL95-09	FAA Approved Supplemental Type Certificates (STC's) and FAA-PMA Approved Parts								T (A/R)	Service Newsletter
100 A/F										
Eff: 17-Nov-1995										
SNL96-02	Cessna Propeller Aircraft Product Support Brochure								T (A/R)	Service Newsletter
100 A/F										
Eff: 19-Apr-1996										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SNL96-03	New Cessna Service Station Directory								T (A/R)	Service Newsletter
 100 A/F										Mos
Eff: 09-Aug-1996										Hrs
										Ldg
SNL97-02	Cessna Customer Care Supplies and Publications Catalog								T (A/R)	Service Newsletter
 100 A/F										Mos
Eff: 17-Mar-1997										Hrs
										Ldg
SNL97-03	New Cessna Service Station Directory								T (A/R)	Service Newsletter
 100 A/F										Mos
Eff: 18-Apr-1997										Hrs
										Ldg
SNL98-03	Cessna Customer Care Supplies And Publication Catalog								T (A/R)	Service Newsletter
 100 A/F										Mos
Eff: 27-Apr-1998										Hrs
										Ldg
SNL98-07	Approved Nondestructive Testing Facilities								T (A/R)	Service Newsletter
 100 A/F										Mos
Eff: 29-Jun-1998										Hrs
										Ldg
SNL98-09	New Pilot Safety And Warning Supplements								RE (-)	Service Newsletter
 100 A/F										Mos
Eff: 17-Aug-1998										Hrs
										Ldg
SNL98-09R1	New Pilot Safety And Warning Supplements								T (A/R)	Service Newsletter
 100 A/F										Mos
Eff: 26-Oct-1998										Hrs
										Ldg