

Repair Order Review

Recon Repairs

Mountain View Meridian - Loc1

73-749-1

HEADER INFORMATION

Repair Order #	Date	Time	Tag #		
340924M	02/20/20	0850	737491		
Srv Writer	Cust #	MOP	Stock #	Vin/Serial #	Unit Description
001403	00004	INT	737491	42901547	2000 CLA PU380 HAY HEAD
RO Note			Meter In	Meter Out	Promise Date
			0.000	0.000	

CUSTOMER INFO

Purchase Order # :

Bill To :

Name	: INTERNAL RECONDITIONING
Address	:
Address 2	:
City	:
State	:
Zip	:
Phone	:
Fax	:
Cell	:

Ship To :

Ship Name	:
Ship Address	:
Ship Address 2	:
Ship City	:
Ship State	:
Ship Zip	:
Ship Phone	:
Ship Fax	:
Ship Cell	:
Ship Contact	:
Ship Via	:

INVOICE INFORMATION

Misc Charge Settings	: 1
Misc Override Charge	: 0

CONDITION INFORMATION

Cond	Type	Labor	Parts
001		1183.19	899.97
Sublet	Other	Total	
0.00	0.00	2083.16	

CONDITION NOTES

Description :
W/JOHN C
COMPLETE DRIVELINE YES

Cause :

Fix :
HAS DRIVELINE AT THIS TIME. REPLACED STRIPPERS AS NEEDED. REPLACED BUSHINGS ON C
ROP ROLLERS. HAD TIRE REPAIRED AND REINSTALLED ONTO UNIT. REPLACED INPUT SEAL AN
D SHIMED GEAR BOX. CHECKED GEARBOX FOR OIL HAS GREASE IN IT. REPLACED BUSHINGS I
N REAR GAUGE ROLLERS. PUT UNIT BACK ON LOWER LOT. RAN HEAD AND REPAIRED TINES AS
NEEDED.

GENERAL INFORMATION