

INSPECTION

1974

MAKE / MODEL / YEAR:

John Deere 4400

CUSTOMER / LOCATION:

19997 Louis Noll
Canby Rd. 517 Vidua, MO 65580

DATE:

07/01/18

Category Specifics

Category Specifics	Comments
Unloading Auger Length	12ft
Grain Tank Size	
Crop Type	<input checked="" type="checkbox"/> Corn/Beans <input checked="" type="checkbox"/> Grain <input type="checkbox"/> Rice
Separator Type	<input type="checkbox"/> Rotor <input checked="" type="checkbox"/> Walker
Terrain Type	<input type="checkbox"/> Conventional <input type="checkbox"/> Sidehill
Rear Attachment	<input type="checkbox"/> Straw Chopper <input type="checkbox"/> Straw Spreader <input type="checkbox"/> Chaff Spreader
Fore/Aft Reel	<input type="checkbox"/> Yes <input type="checkbox"/> No
Auto Reel Speed	<input type="checkbox"/> Yes <input type="checkbox"/> No
GPS	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
GPS Ready	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
GPS Monitor	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Grain Loss Monitor	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Yield Monitor	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Contour FeederHouse	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Warranty	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No

Hours: ~~2222~~ N/A

N/A

General Appearance

General Appearance	Comments
Guards/Covers/Steps	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair
Hoods/Grill/Fenders	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair
Glass/Mirrors	<input type="checkbox"/> New <input checked="" type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair
Doors	<input type="checkbox"/> New <input checked="" type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair
Cab Condition	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair
Paint	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair
Seat	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair
Radio	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Air	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Heat	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Steering Wheel Play	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No

Engine		Comments
Engine Manufacturer	Deere	Hours: 2,375
Engine Model		
Engine Serial Number		
Coolant Level	<input type="checkbox"/> Low <input checked="" type="checkbox"/> Good <input type="checkbox"/> High	
Coolant Leaks	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Blow-By	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Oil Leaks?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Smokes?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Turbocharger	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Powertrain		Comments
Transmission Type	<input type="checkbox"/> 2 Spd <input type="checkbox"/> 3 Spd <input checked="" type="checkbox"/> 4 Spd <input type="checkbox"/> 5 Spd <input type="checkbox"/> ProDrive	
Forward Speed		
Reverse Speed		
Transmission Condition	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair	
Torque Converter	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair	
Linkage	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair	
Brakes	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair	
Emergency Brake Works?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Will Pull Through Brakes?	<input type="checkbox"/> Yes <input type="checkbox"/> No	
Chassis		Comments
Tire Brand	Goodyear	
Steering Tire Size		
Steering Tire % Remaining	50%	
Drive Tire Size		
Drive Tire % Remaining	75%	
Track % Remaining	NA	
Steering Linkage	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair	
Duals	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Electrical		Comments
Batteries	<input type="checkbox"/> New <input checked="" type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair	
Warning Lights Work	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Gauges Work	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Lights Work	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Hydraulics		Comments
Hoses	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair	
Cylinder Rods	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair	
Pump	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair	
Hydraulics Leak	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	