



Custom Track Service  
Summary

LOUISIANA MACHINERY  
CO. L.L.C. (D241)

Prepared By: Neil Whitam

<b>Model</b>	320EL	<b>Job Site</b>	--		<b>Inspection Date</b>	20Aug19
<b>Manufacturer</b>	Caterpillar		<u>Left</u>	<u>Right</u>	<b>Next Inspection Date</b>	--
<b>Serial Number</b>	WBK03207	<b>Track Sag</b>	--	--	<b>Next Inspection Hours</b>	--
<b>Reference Number</b>	--	<b>Frame Extension</b>	--	--	<b>Underfoot Conditions</b>	
<b>Hour Meter Reading</b>	6,666	<b>Maximum</b>	--	--	<b>Impact</b>	Moderate
<b>Hours Per Week</b>	--	<b>Dry Joints</b>	--	--	<b>Abrasion</b>	Moderate
<b>Total Odometer Reading</b>	--	<b>Internal Wear</b>	--	--	<b>Moisture</b>	Moderate
<b>Forward Odometer</b>	--		--	--	<b>Packing</b>	Moderate
<b>Reverse Odometer</b>	--	<b>Track Shoe Width</b>	33"	33"	<b>Bushing Allowable Wear</b>	Greater
					<b>Link Allowable Wear</b>	Greater

GROUP	RECOMMENDATION	% WORN	PROJECTED SMU AT 100% PROJECTED SMU AT 120%			PROJECTED DATE AT 100%	PROJECTED DATE AT 120%
TRACK LINK	Good	37% (1.13 in)	28% (1.15 in)	--	--	--	--
TRACK BUSHING	Good	13% (0.43 in)	20% (0.42 in)	--	--	--	--
TRACK SHOE	Good	17% (1.3 in)	21% (1.27 in)	--	--	--	--
FRONT IDLER	Good	24% (0.78 in)	12% (0.76 in)	--	--	--	--
CARRIER ROLLER	Good	33% (4.5 in)	34% (4.49 in)	--	--	--	--
	Good	38% (4.47 in)	46% (4.41 in)	--	--	--	--
TRACK ROLLER	Good	-- --	18% (1.64 in)	--	--	--	--
	Good	18% (1.64 in)	35% (1.59 in)	--	--	--	--
	Good	11% (1.66 in)	4% (1.68 in)	--	--	--	--
	Good	4% (1.68 in)	--	--	--	--	--
	--	--	--	--	--	--	--
	--	--	--	--	--	--	--
	--	--	--	--	--	--	--
	Good	11% (1.66 in)	11% (1.66 in)	--	--	--	--
SPROCKET	--	--	--	--	--	--	--

#### General Recommendations

--

Photos

---

Pre-Inspect



Pre-Inspect

---