

Condition Report - Offer ID: 1107597

General Information			
Date Inspected:	11/09/2018	Make:	CASE IH
Inspected By:	Asset Appraisal Services	Model:	Steiger 580Q
Anticipated Availability Date:	N/A	Serial Number:	ZFF304240
Hour Meter:	2732	Year:	2015
Horsepower:	N/A	Specifications of Machine:	N/A

INSPECTION RATING KEY			
Excellent:	Outstanding Quality	Very Good:	New or Near New
Good:	Functions Within the Anticipated Wear	Fair:	Although Functioning, Needs Repair

General Appearance			
Paint:	Good	Radiator Grill/Shroud:	Good
Sheet Metal/Fiberglass:	Good	Fuel Tank:	Good
Grab Irons:	Good	Pre-Cleaner Bowl:	Good
Steps/Ladders:	Good	Battery Box:	Good
Cab/ROPS:	Good	Main Frame:	Good
Fenders:	Good	Differential Supports:	Good
Engine Enclosure/Hood:	Good	Number of Front Weights:	N/A
Stack/Exhaust Pipe:	Good		
Comments:	N/A		

Gauges/Operator Station/Console			
Dash/Console:	Good	Windows:	Good
Gauges:	N/A	Mirror:	Good
Switches:	Good	Air Conditioner:	Good
Interior Lights:	Fair	Heater:	Good
EMS Panel/Warning Lights:	Good	Windshield Wipers:	Good
Floor Boards:	Good	Horn:	Good
Seat Cushion:	Good	Back Up Alarm:	N/A
Arm Rests:	Good	Seat Belt:	Good
Doors:	Good	Manuals:	N/A
Door Latches:	Good		
Comments:	Dome Light Inop - HVAC Vents Right Of Dash Console Taped Over		

Engine/Cooling System/Electrical System			
Engine Make:	FPT	Water Pump:	Good
Serial Number:	00007113	Fan:	Good
Blow By:	No	Fan Drive:	Good
Leaks:	No	Radiator:	Fair
Excessive Smoke:	No	Coolers:	Fair
Turbocharger:	Good	Hoses:	Good
Intake:	Good	Batteries/Cables:	Good
Exhaust/Muffler:	Good	Starter:	Good
Air Cleaner:	Fair	Alternator:	Good
Fuel Injection System:	Good	Pre-Heater:	Good
Governor:	Good	Lights-External:	Fair
Belts/Pulleys:	Good	Wiring:	Good
Engine Supports:	Good	Engine Operating Condition:	Good
Comments:	Has 2 Beacon Lights; Left Broken Off, Right Lights Up But Does Not Rotate - Air Cleaner Dirty - Radiator, Coolers Dirty - 5 Rear Work Lights Inop		

Steering			
Operating Condition:	Good	Lines/Hoses:	Good
Steering Linkage:	Good	Kingpins:	N/A
Pump:	Good	Tie Rods/Rod Ends:	N/A

Articulating Tractor

Articulation P&B:	Good	Steering Cylinder P &B:	Good
Steering Cylinders:	Good	Lines/Hoses:	N/A
Comments:	N/A		

Hydraulics

Operating Condition:	Good	Pumps and Valves:	Good
Controls Levers:	Good	Hoses/Lines:	Good
Control Linkage:	Good	Leaks:	No
Tank:	Good	Number of Remote Circuits:	N/A
Comments:	N/A		

Transmission

Operating Condition:	Good	Pump:	Good
Type of Transmission:	Power Shift	Leaks:	No
Torque Converter:	N/A	Lines/Hoses:	Good
Case:	Good	Forward Shift:	Good
Drive Shaft:	Good	Reverse Shift:	Good
Universal Joints:	Good	Number of Speeds:	N/A
Comments:	2 Reverse Speeds		

Final Drives/Brakes			
Front Axle:	Good	Brake Operating Condition:	Good
Front Final Drives:	Good	Brake Drum/Rotors:	N/A
Front Differential:	Good	Lines:	Good
Rear Axle:	Good	Leaks:	No
Rear Final Drives:	Good	Brake Linkage:	N/A
Rear Differential:	Good	Parking Brake:	Good
Clutch:	Good	Wheel Lugs/Rims:	Good
Comments:	N/A		

Rear			
3 Point Hitch:	N/A	PTO Operational:	Yes
Top Link:	N/A	Drawbar:	N/A
Quick Coupler:	N/A	Hammerstrap:	Yes
Comments:	1000 PTO		

Loader			
Make:	N/A	Tilt Cylinder:	N/A
Model:	N/A	Bucket Size:	N/A
Serial Number:	N/A	Bucket Condition:	N/A
Loader Arms:	N/A	Cutting Edge:	N/A
Loader Arm P&B:	N/A	Loader Controls:	N/A
Lift Cylinders:	N/A	Quick Coupler:	N/A
Comments:	N/A		

Attachment			
Make:	Case IH	Serial Number:	14491256
Model:	AFS Pro 700	Lines/Hoses:	N/A
General Description:	Monitor	Pump/Motor:	N/A
Operating Condition:	N/A	Controls:	N/A
Cylinders:	N/A	Hi Flow/Standard Flow:	N/A
Pins & Bushings:	N/A	Electrical Connection:	N/A
Comments:	N/A		

Attachment			
Make:	Case IH	Serial Number:	5437501365
Model:	372	Lines/Hoses:	N/A
General Description:	Antenna	Pump/Motor:	N/A
Operating Condition:	N/A	Controls:	N/A
Cylinders:	N/A	Hi Flow/Standard Flow:	N/A
Pins & Bushings:	N/A	Electrical Connection:	N/A
Comments:	N/A		

Tires				
	Model/Make	Tire Size	Measurement 32nds Inside	Measurement 32nds Outside
Right Front	N/A	N/A	N/A	N/A
Right Rear	N/A	N/A	N/A	N/A
Left Front	N/A	N/A	N/A	N/A
Left Rear	N/A	N/A	N/A	N/A

Tires				
	% Wear Remaining Inside	% Wear Remaining Outside	Cuts/Chunks	Recaps
Right Front	N/A	N/A	N/A	N/A
Right Rear	N/A	N/A	N/A	N/A
Left Front	N/A	N/A	N/A	N/A
Left Rear	N/A	N/A	N/A	N/A
Comments :		N/A		

Tracks				
	Make/Width	Drive Lugs	% Wear Remaining	Cuts/Chunks
Right Front	Continental	44	N/A	No
Right Rear	Continental	58	N/A	No
Left Front	Continental	38	N/A	No
Left Rear	Continental	45	N/A	No
Idlers	Good			
Rollers/Bogies	Fair			
Comments :	Width: 30 Inches Each -- Right Front Track Drive Lugs Cracking Around Base - Left Rear Track Drive Lugs Cracking Around Base - Right Front Roller Rubber Edge Chipping - Right Rear Track Listed As Agricultural Use Only, Other 3 Tracks Listed As Scraper Use Only			