



315 Bewley Building,
Lockport, NY 14094
p. 716.995.7400 f. 716.995.7401

Date: 12/03/2019
From: Todd Destro
Email: tdestro@glassettllc.com

Delivery / Condition Report

Customer Name: WILSON VALERA
Year / Make / Model: 2006 MACK CXN613 VIN #: 1M1AK06YX6N010560

	GOOD	FAIR	POOR	N/A
FRONT BUMPER	✓			
HEAD LIGHTS	✓			
HOOD	✓			
TURN SIGNALS				
GRILL			✓	
LEFT FRT FENDER	✓			
LEFT DOOR	✓			
LEFT SLEEPER				✓
REAR BUMPER				✓
TAIL LIGHTS	✓			
REAR CAB PANEL	✓			
RIGHT FRT FENDER	✓			
RIGHT DOOR	✓			
RIGHT SLEEPER				✓
TOP	✓			

Scatched
CRACKED

	GOOD	FAIR	POOR	N/A
WINDSHIELD	✓			
LEFT DOOR	✓			
LEFT SLEEPER				✓
REAR WINDOW	✓			
RIGHT DOOR	✓			
RIGHT SLEEPER				
MIRRORS	✓			

	YES	NO
SLIDING 5th WHEEL		✓
DUAL FUEL TANKS		
MUD FLAPS	✓	
1/4 FENDERS		✓
1/2 FENDERS		✓
FULL FENDERS		✓

	GOOD	FAIR	POOR	N/A
LEFT STEER				
LEFT FRT OUTSIDE	✓			
LEFT FRT INSIDE	✓			
LEFT CENTER OUTSIDE	✓			
LEFT CENTER INSIDE	✓			
LEFT REAR OUTSIDE				
LEFT REAR INSIDE				✓

	GOOD	FAIR	POOR	N/A
RIGHT STEER				
RIGHT FRT OUTSIDE	✓			
RIGHT FRT INSIDE	✓			
RIGHT CENTER OUTSIDE	✓			
RIGHT CENTER INSIDE	✓			
RIGHT REAR OUTSIDE	✓			
RIGHT REAR INSIDE				✓

Odometer: 748,242 Color: BLUE

Keys: (Yes) / No (circle one) Starts: (Yes) / No (circle one) Needs Tow: Yes (No) (circle one)

Notes: PASS SIDE MIRROR CRACKED. FRONT GRILL CRACKED.
VARIOUS SCRATCHES ALL OVER

Delivery Location: Quality first 359 NJ-35, CLIFFWOOD, NJ 07721

Print Name: SAP

Signature: [Signature]

Date: 12/09/201

I represent to Great Lakes Asset Solutions by my signature / stamp below that I am authorized to immediately take possession of said unit in the represented condition as expressed. Furthermore, I take responsibility for the finance company of having this unit in my possession for them.