

INSPECTION

2017 John Deere S670 Sn: 1H05670SCH0795564

MAKE / MODEL / YEAR:

Marysville, Kansas

CUSTOMER / LOCATION:

8-19-2020

DATE:

One Owner Combine

Category Specifics		Comments
Grain Tank Size		
GPS Ready	☒ Yes ☐ No	
Unloading Auger Length	26ft	
GPS Monitor	☐ Yes ☐ No	
Crop Type	☒ Corn/Beans ☐ Grain ☐ Rice	Does have small grain grates
Separator Type	☒ Rotor ☐ Walker	
Warranty	☐ Yes ☒ No	
Terrain Type	☒ Conventional ☐ Sidehill	
Rear Attachment	☐ Straw Chopper ☐ Straw Spreader ☐ Chaff Spreader ☒ Straw Chopper / Spreader Combo	
Fore / Aft Reel	☒ Yes ☐ No	
Auto Reel Speed	☐ Yes ☐ No	
GPS	☐ Yes ☐ No	
Grain Loss Monitor	☒ Yes ☐ No	
Yield Monitor	☒ Yes ☐ No	
Contour Feederhouse	☒ Yes ☐ No	

General Appearance		Comments
Guards/Covers/Steps	☐ New ☒ Excellent ☐ Good ☐ Fair ☐ Poor	
Hoods/Grill/Fenders	☐ New ☒ Excellent ☐ Good ☐ Fair ☐ Poor	
Glass/Mirrors	☐ New ☒ Excellent ☐ Good ☐ Fair ☐ Poor	
Doors	☐ New ☒ Excellent ☐ Good ☐ Fair ☐ Poor	
Cab Condition	☐ New ☒ Excellent ☐ Good ☐ Fair ☐ Poor	
Paint	☐ New ☒ Excellent ☐ Good ☐ Fair ☐ Poor	
Seat	☐ New ☒ Excellent ☐ Good ☐ Fair ☐ Poor	still has plastic
Radio	☒ Yes ☐ No	
Air	☒ Yes ☐ No	
Heat	☒ Yes ☐ No	
Steering Wheel Play	☐ Yes ☒ No	

Engine		Comments
Engine Serial Number		
Coolant Level	☐ Low ☒ Good ☐ High	
Coolant Leaks	☐ Yes ☒ No	
Blow-By	☐ Yes ☒ No	
Oil Leaks?	☐ Yes ☒ No	
Smokes?	☐ Yes ☒ No	
Turbocharger	☒ Yes ☐ No	

Powertrain		Comments
Transmission Type	☐ IVT ☒ 2 Spd ☐ 3 Spd ☐ 4 Spd ☐ 5 Spd ☒ ProDrive	
Forward Speed		
Reverse Speed		
Transmission Condition	☐ New ☐ Excellent ☐ Good ☐ Fair ☐ Poor	
Torque Converter	☐ New ☐ Excellent ☐ Good ☐ Fair ☐ Poor	
Linkage	☐ New ☐ Excellent ☐ Good ☐ Fair ☐ Poor	
Brakes	☐ New ☐ Excellent ☐ Good ☐ Fair ☐ Poor	
Emergency Brake Works?	☐ Yes ☐ No	
Will Pull Through Brakes?	☐ Yes ☐ No	

Chassis		Comments
Tire Brand	Goodyear	
Steering Tire Size	600/70R28	
Steering Tire % Remaining		
Drive Tire Size	20/85R42	
Drive Tire % Remaining		
Track % Remaining		
Steering Linkage	☐ New ☐ Excellent ☐ Good ☐ Fair ☐ Poor	
Duals	☒ Yes ☐ No	
Electrical		Comments
Batteries	☐ New ☐ Excellent ☒ Good ☐ Fair ☐ Poor	
Warning Lights Work	☒ Yes ☐ No	
Gauges Work	☒ Yes ☐ No	
Lights Work	☒ Yes ☐ No	
Hydraulics		Comments
Hoses	☐ New ☒ Excellent ☐ Good ☐ Fair ☐ Poor	
Cylinder Rods	☐ New ☒ Excellent ☐ Good ☐ Fair ☐ Poor	
Pump	☐ New ☒ Excellent ☐ Good ☐ Fair ☐ Poor	
Hydraulics Leak	☐ Yes ☒ No	

Combine is in excellent condition. If you would like to view this machine in person please don't hesitate to contact us. Combine has been fully serviced and is ready to go to the field.