Inspection Report

			Make	Model	Year
Asset Description			Volvo	EC480EL	2016
Vin Number	VCEC480EC0031	0522			_
Hours/Milage	1522				
General Appearance					
	Excellent Good F	air Poor	Comments		
Paint			Normal wear		
Panels					
Glass					
Steps					
Guards		✓ □	One handrail l	pent	
Lights					
Mirrors					
Additional comments					
Safety					
-	Excellent Good F	air Poor	Comments		
Travel Alarm					
Horn					
Seat belts					
Safety lockout/Stop					
Additional comments					
Control Station					
	Excellent Good F	air Poor	Comments		
Mirrors					
Seat/ Armrests					
Hydraulics Controls					
Drivetrain Controls					
Dash					
Gauges					
Hours			1522 hours		
AC			too cold to che	eck	
Heater			wasn't tested		

Additional comments	
Engine	
	Excellent Good Fair Poor Comments
Oil level	
Oil leaks	
Air filters	
Coolant level	
coolant leaks	
Exhaust System	
Radiator	
Power steering fluid level	
transmission fluid level	
Def fluid	
Additional comments	
	
Drivetrain	E will of Oxyd Edy Bray Oxygoda
the decree 400 cm	Excellent Good Fair Poor Comments
track condition	
Left Drive Motor	
Right Drive Motor	
Left Final Drive	
Right Final Drive	
Additional comments	Drivetrain operational
, taditional commonte	Bittotiani oporational
Hydraulic system	
•	Excellent Good Fair Poor Comments
Hydraulic level	
Pumps	
Valves	
Tank	
Hoses	
Swing Motor	
Hydraulic Center Swivel	
Boom Lift Cylinders	
Stick Cylinder	
Bucket Clyinder	

Additional comments	
Chassis	
5 6 1111	Excellent Good Fair Poor Comments
Boom Condition	
Stick Condition	
Boom Base Pin and Bushings	
Pin and Bushings Boom to Stick	
Pin and Bushings Boom to Bucket	
Turntable Bearing	
Bottom Covers	
Additional comments	
Undercarriage	
	Excellent Good Fair Poor Comments
Roller Frame	
Track Tensioner	
Track Pads	
Grouser Height	
Track Links	
Track Bushings	
Carrier Rollers	
Track Rollers	
Idler	
Sprocket	
Additional comments	