

#### **Section 1**

Heavy Highway Tractor Options/Specifications	
Options/Specifications	
Date/Time	04-04-2020
IRC#	B8011
Customer#	201008011
Unit Make	Peterbilt
Model	379
Year	2000
Vehicle Type	Day cab highway tractor
VIN#	1NP5L09X8YD537726

**VIN/Dataplate Photos** 





**Left Front Corner Shot** 



**Left Rear Corner Shot** 





#### **Right Rear Corner Shot**



#### **Right Front Corner Shot**



	AND
Shipping Length (Ft') (In.")	25'
Shipping Width (Ft.') (In")	8' 6"
Shipping Height (Ft') (In")	11'
Weight	NA
Oil Samples	None
Odometer Reading	713095



#### **Odometer Photo**



Hour Meter reading	8097
Hour Meter Photo	
Cab Heat	Yes
A/C	Yes
Air Ride Drivers Seat	Yes
High Back Drivers seat	Yes
Air Ride Passenger Seat	No
High Back Passenger Seat	No
Heated Seats	No
Tilt Steering Wheel	No
Telescopic Steering Wheel	No
Power Drivers Window	No
Power Passenger Window	No
Power Mirrors	No
Heated Mirrors	Yes
Cab Suspension	No
Engine Make/Model	Cummins ISM
Engine Displacement	NA
Engine Horsepower	335@2100
Engine Brake	Yes



Transmission Make/Model	Spicer
Transmission Speeds	10
Differential Lock	No
РТО	Yes
Wet Kit	Yes
Hydraulic Pump	Yes
Rear Axle Ratio	411
Wheelbase (In.)	214"
Drive Type (Wheel Positions X Driven Positions)	6x4
Front Axle Weight Rating (Lbs.)	12000
Rear Axle Weight Rating*(Combined) (Lbs.)	40000
GVWR	52000
Front Suspension Type	Spring
Rear Suspension Type	Air ride
Steer Tire Size	11R22.5
Pusher/Tag Axle	No
Pusher/Tag Information	NA
Drive Tire Size	11R22.5
Fixed Fifth Wheel	No
Sliding Fifth Wheel	Yes
Box/Bed Deminsions	NA
Bed/Box,Misc. Options/Information	
Bed/Box,Misc. Data Photos	
Sleeper	No
Sleeper Size (inches)	
Flat Top Sleeper	N/A
Raised Roof Sleeper	N/A
Headache Rack	Yes
Accessory Power Unit	NA
OPERATIONAL CHECKS	
Engine Operational?	Yes
Steering/Brakes Operational?	Yes



Transmission/Drivetrain Operational?	Yes
Hydraulic System Operational	Not operationally checked
Additional information/Noticable Damage	NA
Additional Axle Tire Size	NA