

Inspection Report Highway Truck



IRC# B8009

CO# 201008009

Pre-Inspection DATE: 4/8/2020

Vin # 1np5lt9x0xd485685 Make- Peterbilt Model- 379 Year- 1999
 Hours- NA Miles- 914907 Equipment Location- Thief River Falls MN

Seller Information- Bluebill Auctions

*Please review all photos and videos along with report

Iron Ridge Co. Building A Mountain Of Integrity

1: General Condition Operational/Average wear for type, operating hours, and age *Heavy wear, leaks, and major damage as well as unit highlights are photographed and/or noted in comments

ITEM	<input type="checkbox"/>	COMMENT
*Start Odometer		914908.1
*Start Hour Meter		29898.6
Lights	<input checked="" type="checkbox"/>	
Paint/Main Body/Sheet Metal	<input checked="" type="checkbox"/>	
Cab External Condition	<input checked="" type="checkbox"/>	Dent behind drivers door
Steps/Ladder/Catwalks	<input checked="" type="checkbox"/>	
Handrails/Grab Irons	<input checked="" type="checkbox"/>	
Cab Door	<input checked="" type="checkbox"/>	Drivers door handle loose but operational
Fuel Tank	<input checked="" type="checkbox"/>	
Exhaust Stack/Air Inlet	<input checked="" type="checkbox"/>	
Batteries/Battery Box	<input checked="" type="checkbox"/>	

Additional Notes-

2: Operator Station

ITEM	<input type="checkbox"/>	COMMENT
Windows/Glass	<input checked="" type="checkbox"/>	
Mirrors	<input checked="" type="checkbox"/>	
Seat Belts	<input checked="" type="checkbox"/>	
Back Up Alarm	<input checked="" type="checkbox"/>	
Horn	<input checked="" type="checkbox"/>	
Dash Console	<input checked="" type="checkbox"/>	
Engine Oil Pressure		PSI 30
Warning Lights	<input checked="" type="checkbox"/>	
Gauges	<input checked="" type="checkbox"/>	

Windshield Wipers	✓	
Steering Controls	✓	
Engine Controls	✓	
Drive Train Controls	✓	
Hydraulic Controls	✓	Not operationally checked
PTO Controls	✓	Not operationally checked
Service/Park Brakes	✓	
Heater	✓	
A/C		Not operationally checked
Ceiling/Roof	✓	
Seat/Armrests	✓	
Floor Boards/Mats	✓	
Doors/Latches	✓	

Additional Notes-

3: Drive Train/Transmission

ITEM	<input type="checkbox"/>	COMMENT
Trans. Make/Model		Spicer
*Transmission Type		Manual
*Transmission Speeds		10
Transmission Forward	✓	
Transmission Reverse	✓	
Drive Shafts	✓	
Steer Axle	✓	
Middle Drive Axle	✓	
Rear Drive Axle	✓	
Additional Axles	✓	
Steering System	✓	
PTO	✓	Not operationally checked

Additional Notes-

4: Engine

ITEM	<input type="checkbox"/>	COMMENT
*Engine Make/Model	<input type="checkbox"/>	Cat C10
Emissions Control Label	<input type="checkbox"/>	None Found

Engine Operation	✓	
Oil Leaks		None seen
Engine Blow-by Video	✓	
Engine Run Video	✓	
Exhaust System/Turbo	✓	
Fuel System	✓	
Fuel Leaks		None seen
Radiator	✓	
Coolant Leaks		None seen
Coolant Condition/Level	✓	
Belts/Accessory Drive	✓	

Additional Notes-

5: Tires/Brakes

BRAKE TYPE		Drum				
BRAKE CONDITION		Operational, see photos for wear				
TIRE CONDITION		See photos				
Position	SIZE	BRAND	REMAINING TREAD-32nds.	Wheel Type	Recap Y/N	
LF	11R22.5	Goodyear	14	AL	N	
LMO	11R22.5	Cachland	18	AL	N	
LMI	11R22.5	Cachland	19	S	N	
LRO	11R22.5	Firestone	26	AL	N	
LRI	11R22.5	Firestone	25	S	N	
RF	11R22.5	Goodyear	14	AL	N	
RMO	11R22.5	Cachland	16	AL	N	
RMI	11R22.5	Cachland	19	S	N	
RRO	11R22.5	Firestone	27	AL	N	
RRI	11R22.5	Firestone	27	S	N	
R						
L						
R						
L						

Additional Notes-

6:Hydraulic

N/A

ITEM	<input type="checkbox"/>	COMMENT
Pump	<input checked="" type="checkbox"/>	
Hydraulic Lines/Hoses	<input checked="" type="checkbox"/>	
Valves	<input type="checkbox"/>	NA
Reservoir/Tank	<input checked="" type="checkbox"/>	
Cylinders	<input type="checkbox"/>	NA
Leaks	<input type="checkbox"/>	None seen

Additional Notes-

7: Chassis

ITEM	<input type="checkbox"/>	COMMENT
Main Frame Condition	<input checked="" type="checkbox"/>	
Wheel Base	<input type="checkbox"/>	215"
Suspension Bushings	<input checked="" type="checkbox"/>	
Suspension Springs	<input checked="" type="checkbox"/>	
Suspension Air Bags	<input checked="" type="checkbox"/>	
Cab Air Suspension	<input type="checkbox"/>	NA
Fifth Wheel	<input checked="" type="checkbox"/>	
Sliding Fifth Wheel	<input checked="" type="checkbox"/>	
Fifth Wheel Remaining	<input type="checkbox"/>	5/32
Dump Box/Bed Dimensions	<input type="checkbox"/>	NA
Dump Box/Bed Condition	<input type="checkbox"/>	NA
Tail Gate	<input type="checkbox"/>	NA
Sleeper	<input type="checkbox"/>	NA
Aux. Power Unit	<input type="checkbox"/>	NA
Start Up Video	<input checked="" type="checkbox"/>	
*End Hour Meter	<input type="checkbox"/>	NA
*End Odometer	<input type="checkbox"/>	914907.3

Additional Notes-

*Notice: We CAN NOT and DO NOT offer any warranty or guarantee on the inspections from Iron Ridge Co.
We are an independent company, we do our best to represent equipment as it is.