## INSPECTION

2013 Dee	re 328D	
MAKE / MODEL	YEAR:	
Marysville, 1	K3	
CUSTOMER / LO	CATION:	
8-26-202	9	
DATE:		
Category Specific	STANTANTANTANTANTANTANTANTANTANTANTANTANT	Comments
Category operation	☐ 4-in-1 ☐ Clamshell ☐ Ditch Cleaning ☐ Frost ☐ General Purpose ☐ Light Material	
Bucket Type	☐ Multi-Purpose ☐ Other ☐ Rock   ☐ Screen ☐ Severe-Duty ☐ Side Dump   ☐ Skeleton ☐ Spade Nose ☐ Trenching	
Bucket Size		
Bucket Condition	☐ New ☐ Excellent ☐ Good ☐ Fair ☐ Poor	
Emergency Shut Off	☐ New ☐ Excellent ☐ Good ☐ Fair ☐ Poor	
Other Attachments		
Operating Weight	8,408	
Operating Capacity		
General Appearar	nce	Comments
ROPS	Enclosed Open None	and the state has
Guards/Covers/Steps	☐ New ☐ Excellent ☑ Good ☐ Fair ☐ Poor	Right Side Ergine Chiefel has been straightened.
Hood/Grill/Fenders	☐ New ☐ Excellent ☐ Good ☐ Fair ☐ Poor	
Glass/Mirrors	☐ New ☐ Excellent ☑ Good ☐ Fair ☐ Poor	
Doors	☐ New ☐ Excellent ☐ Good ☐ Fair ☐ Poor	
Cab	☐ New ☐ Excellent ☐ Good ☐ Fair ☐ Poor	
Paint	☐ New ☐ Excellent ☑ Good ☐ Fair ☐ Poor	
Seat	□ New □ Excellent □ Good □ Fair □ Poor	
Steering Wheel Play	☐ Yes ☑ No	
General Appeara	nce Interior	Comments
A/C	¥Yes □ No	
Heater	Yes No	11 4.
A/C Condition	□ New □ Excellent □ Good □ Fair AC	blower wars on all setting
	15 r	blower works on all setting not currently colding may need raed.

Engine		Comments
	John Deere	New Engine Recently.
Engine Model	Jakn Dede	installed. Please review vicker
Engine Serial Number		engine idles sounds rough.
Horsepower		J
Blow-By	Yes No None Observed	
Oil Leaks?	Type WNo	
Smokes	Yes No Engine will smoke	while all idling up.
Turbocharger	☐ Yes ☐ No	0.7.
Coolant Leaks	☐ Yes ☑ No	
Coolant Levels	☐ Low ☐ Good ☐ Hìgh	
Powertrain		Comments
Transmission Type		
Travel Speed		
Travel Speed - 2-Speed		
Option		
Forward Speed		
Reverse Speed	□ Now □ Excellent □ Good □ Fair	
Transmission Condition	Poor	
Torque Converter	☐ New ☐ Excellent ☐ Good ☐ Fair ☐ Poor —	
Linkage	☐ New ☐ Excellent ☐ Good ☐ Fair ☐ Poor	
Final Drives	☐ New ☐ Excellent ☐ Good ☐ Fair ☐ Poor	
Brake Type		
Brakes	☐ New ☐ Excellent ☐ Good ☐ Fair ☐ Poor	
Emergency Brake works?	Yes No	
Pull Through Brakes?	☐ Yes ☐ No	
Chassis		Comments
Tire Brand		
Tire Size		
Tire Type		
LF % Remaining		
LR % Remaining		
RF % Remaining		
RR % Remaining		
Steering Linkage	☐ New ☐ Excellent ☐ Good ☐ Fair ☐ Poor	
Ground Clearance		
Wheelbase		Comments
Electrical		Collinents
Batteries	☐ New ☐ Excellent ☑ Good ☐ Fair ☐ Poor	
Warning Lights Work	☐ Yes ☐ No	
Gauges Work	V Yes □ No	
Lights Work	Yes No	

31/2020 https://dealer	s.sandhills.com/Inspections/SpecSheet.aspx?ocid=1073&catName=Skid+Steers+-+Wheel&companyID=61038&template	∍Na…
Hydraulics	Comments	
Hoses	□ New □ Excellent □ Good □ Fair □ Poor	
Cylinder Rods	□ New □ Excellent ☑ Good □ Fair □ Poor	
Pumps	□ New □ Excellent □ Good □ Fair □ Poor	
Hydraulics Leak	Yes No Small normal Leaks	