

INSPECTION

1998 Komatsu WA320-3L

MAKE / MODEL / YEAR:

Washington, Ks

CUSTOMER / LOCATION:

9-17-2020

DATE:

Category Specifics		Comments
Emergency Shut Off	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	
General Appearance		Comments
Guards/Covers/Steps	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	Some rust as shown in pictures
Hood/Grill/Fenders	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	
Glass/Mirrors	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	
Doors	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	
Cab Condition	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	
Cab Type		
Paint	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	Normal wear for age
Seat	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	
Heater	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Steering Wheel Play	<input type="checkbox"/> Yes <input type="checkbox"/> No	
Engine		Comments
Engine Manufacturer	Komatsu	
Engine Model		
Engine Serial Number		
Blow-By	<input type="checkbox"/> Yes <input type="checkbox"/> No None Observed	
Oil Leaks?	<input type="checkbox"/> Yes <input type="checkbox"/> No Small normal leaks	
Smokes	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No See Video	
Turbocharger	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Coolant Leaks	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Coolant Levels	<input type="checkbox"/> Low <input checked="" type="checkbox"/> Good <input type="checkbox"/> High	

Powertrain		Comments
Transmission Type		
Forward Speed	4	
Reverse Speed	4	
Transmission Condition	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	Shifted properly during inspection
Torque Converter	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	
Linkage	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	
Final Drives	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	
Brakes	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	Park Brake does not work
Brake Type		
Emergency Brake works?	<input type="checkbox"/> Yes <input type="checkbox"/> No	
Pull Through Brakes?	<input type="checkbox"/> Yes <input type="checkbox"/> No	
Chassis		Comments
Tire Brand		
Tire Size	20.5 R25	
Tire Type		
LF % Remaining		
LC % Remaining		
LR % Remaining		
RF % Remaining		
RC % Remaining		
RR % Remaining		
Steering Linkage	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	
Articulating Center Pins	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	
Electrical		Comments
Batteries	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	
Warning Lights Work	<input type="checkbox"/> Yes <input type="checkbox"/> No	
Gauges Work	<input type="checkbox"/> Yes <input type="checkbox"/> No	
Lights Work	<input type="checkbox"/> Yes <input type="checkbox"/> No	
Hydraulics		Comments
Hoses	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	
Cylinder Rods	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	
Pumps	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	Hydraulics were responsive during inspection.
Hydraulics Leak	<input type="checkbox"/> Yes <input type="checkbox"/> No	Small normal leaks for age and hours