

INSPECTION

Caterpillar 977K

MAKE / MODEL / YEAR:

Washington, Ks

CUSTOMER / LOCATION:

9-17-2020

DATE:

Category Specifics		Comments
Bucket Type	Tooth Bucket	
Bucket Size	8ft	
Bucket Condition	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	
Loader Linkage	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	Normal wear for age
Pins/Bushings	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	" "
Emergency Shut Off	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	
General Appearance		Comments
Guards/Covers/Steps	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	
Hood/Grill/Fenders	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	
Glass/Mirrors	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor N/A	
Doors	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor N/A	
Cab Condition	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor N/A	
Cab Type	Open	
Paint	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor	
Seat	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor	
Heater	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Steering Wheel Play	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	

Engine		Comments
Engine Manufacturer	Caterpillar	
Engine Model		
Engine Serial Number		
Blow-By	<input type="checkbox"/> Yes <input type="checkbox"/> No	
Oil Leaks?	<input type="checkbox"/> Yes <input type="checkbox"/> No	
Smokes	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No See Video	
Turbocharger	<input type="checkbox"/> Yes <input type="checkbox"/> No	
Coolant Leaks	<input type="checkbox"/> Yes <input type="checkbox"/> No None Observed	
Coolant Levels	<input type="checkbox"/> Low <input type="checkbox"/> Good <input type="checkbox"/> High	
Powertrain		Comments
Transmission Type		
Forward Speed		
Reverse Speed		
Transmission Condition	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	Shifted properly during inspection
Torque Converter	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	
Linkage	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	
Final Drives	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	
Brake Type		
Brakes	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	
Emergency Brake works?	<input type="checkbox"/> Yes <input type="checkbox"/> No	
Pull Through Brakes?	<input type="checkbox"/> Yes <input type="checkbox"/> No	
Chassis		Comments
Pad Type		
Pad Size	18in	
Pads % Remaining		
Link Height % Remaining	See Pictures	
Rollers % Remaining		
Sprockets % Remaining		
Idlers % Remaining		
Bushings % Remaining		
Steering Linkage	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	
Electrical		Comments
Batteries	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	
Warning Lights Work	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Gauges Work	<input type="checkbox"/> Yes <input type="checkbox"/> No	
Lights Work	<input type="checkbox"/> Yes <input type="checkbox"/> No	

Hydraulics		Comments
Hoses	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	Hydraulics do have leaks.
Cylinder Rods	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	
Pumps	<input type="checkbox"/> New <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor	Was low on hydraulic oil during inspection. Seller stated hydraulic do function properly when oil is full.
Hydraulics Leak	<input type="checkbox"/> Yes <input type="checkbox"/> No	